



# AIA® Document A101® – 2017

## **Standard Form of Agreement Between Owner and Contractor where the basis of payment is a Stipulated Sum**

**AGREEMENT** made as of the Twenty-seventh day of June in the year Two Thousand Twenty-two  
*(In words, indicate day, month and year.)*

**BETWEEN** the Owner:  
*(Name, legal status, address and other information)*

Saulet Apts LLC  
780 Third Ave 25<sup>th</sup> Fl  
New York, N.Y. 10017

and the Contractor:  
*(Name, legal status, address and other information)*

Camp Roofing LTD dba Camp Construction Services  
15139 South Post Oak Road  
Houston, Texas 77053

for the following Project:  
*(Name, location and detailed description)*

The Saulet  
1420 Annunciation Street  
New Orleans, LA 70130  
Interior and Exterir Building Repairs

The Architect:  
*(Name, legal status, address and other information)*

N/A

The Owner and Contractor agree as follows.

### **ADDITIONS AND DELETIONS:**

The author of this document has added information needed for its completion. The author may also have revised the text of the original AIA standard form. An *Additions and Deletions Report* that notes added information as well as revisions to the standard form text is available from the author and should be reviewed. A vertical line in the left margin of this document indicates where the author has added necessary information and where the author has added to or deleted from the original AIA text.

This document has important legal consequences. Consultation with an attorney is encouraged with respect to its completion or modification.

The parties should complete A101®–2017, Exhibit A, Insurance and Bonds, contemporaneously with this Agreement. AIA Document A201®–2017, General Conditions of the Contract for Construction, is adopted in this document by reference. Do not use with other general conditions unless this document is modified.

Init.

**TABLE OF ARTICLES**

<b>1</b>	<b>THE CONTRACT DOCUMENTS</b>
<b>2</b>	<b>THE WORK OF THIS CONTRACT</b>
<b>3</b>	<b>DATE OF COMMENCEMENT AND SUBSTANTIAL COMPLETION</b>
<b>4</b>	<b>CONTRACT SUM</b>
<b>5</b>	<b>PAYMENTS</b>
<b>6</b>	<b>DISPUTE RESOLUTION</b>
<b>7</b>	<b>TERMINATION OR SUSPENSION</b>
<b>8</b>	<b>MISCELLANEOUS PROVISIONS</b>
<b>9</b>	<b>ENUMERATION OF CONTRACT DOCUMENTS</b>

**EXHIBIT A INSURANCE AND BONDS****ARTICLE 1 THE CONTRACT DOCUMENTS**

The Contract Documents consist of this Agreement, Conditions of the Contract (General, Supplementary, and other Conditions), Drawings, Specifications, Addenda issued prior to execution of this Agreement, other documents listed in this Agreement, and Modifications issued after execution of this Agreement, all of which form the Contract, and are as fully a part of the Contract as if attached to this Agreement or repeated herein. The Contract represents the entire and integrated agreement between the parties hereto and supersedes prior negotiations, representations, or agreements, either written or oral. An enumeration of the Contract Documents, other than a Modification, appears in Article 9.

**ARTICLE 2 THE WORK OF THIS CONTRACT**

The Contractor shall fully execute the Work described in the Contract Documents, except as specifically indicated in the Contract Documents to be the responsibility of others.

**ARTICLE 3 DATE OF COMMENCEMENT AND SUBSTANTIAL COMPLETION**

**§ 3.1** The date of commencement of the Work shall be:

*(Check one of the following boxes.)*

- The date of this Agreement.
- A date set forth in a notice to proceed issued by the Owner.
- Established as follows:  
*(Insert a date or a means to determine the date of commencement of the Work.)*
- July 11, 2022

If a date of commencement of the Work is not selected, then the date of commencement shall be the date of this Agreement.

**§ 3.2** The Contract Time shall be measured from the date of commencement of the Work.

**§ 3.3 Substantial Completion**

**§ 3.3.1** Subject to adjustments of the Contract Time as provided in the Contract Documents, the Contractor shall achieve Substantial Completion of the entire Work:

*(Check one of the following boxes and complete the necessary information.)*

Init.

/

Not later than ( ) calendar days from the date of commencement of the Work.

By the following date: October 14, 2022

§ 3.3.2 Subject to adjustments of the Contract Time as provided in the Contract Documents, if portions of the Work are to be completed prior to Substantial Completion of the entire Work, the Contractor shall achieve Substantial Completion of such portions by the following dates:

Portion of Work	Substantial Completion Date
-----------------	-----------------------------

§ 3.3.3 If the Contractor fails to achieve Substantial Completion as provided in this Section 3.3, liquidated damages, if any, shall be assessed as set forth in Section 4.5.

**ARTICLE 4 CONTRACT SUM**

§ 4.1 The Owner shall pay the Contractor the Contract Sum in current funds for the Contractor’s performance of the Contract. The Contract Sum shall be Six Million Two Thousand Three Hundred Fifty-one Dollars and Forty-nine Cents (\$ 6,002,351.49 ), subject to additions and deductions as provided in the Contract Documents.

**§ 4.2 Alternates**

§ 4.2.1 Alternates, if any, included in the Contract Sum:

Item	Price
------	-------

§ 4.2.2 Subject to the conditions noted below, the following alternates may be accepted by the Owner following execution of this Agreement. Upon acceptance, the Owner shall issue a Modification to this Agreement. *(Insert below each alternate and the conditions that must be met for the Owner to accept the alternate.)*

Item	Price	Conditions for Acceptance
------	-------	---------------------------

§ 4.3 Allowances, if any, included in the Contract Sum: *(Identify each allowance.)*

Item	Price
------	-------

§ 4.4 Unit prices, if any: *(Identify the item and state the unit price and quantity limitations, if any, to which the unit price will be applicable.)*

Item	Units and Limitations	Price per Unit (\$0.00)
------	-----------------------	-------------------------

§ 4.5 Liquidated damages, if any: *(Insert terms and conditions for liquidated damages, if any.)*

§ 4.6 Other: *(Insert provisions for bonus or other incentives, if any, that might result in a change to the Contract Sum.)*

**ARTICLE 5 PAYMENTS****§ 5.1 Progress Payments**

**§ 5.1.1** Based upon Applications for Payment submitted to the Architect by the Contractor and Certificates for Payment issued by the Architect, the Owner shall make progress payments on account of the Contract Sum to the Contractor as provided below and elsewhere in the Contract Documents.

**§ 5.1.2** The period covered by each Application for Payment shall be one calendar month ending on the last day of the month, or as follows:

**§ 5.1.3** Provided that an Application for Payment is received by the Architect not later than the 20th day of a month, the Owner shall make payment of the amount certified to the Contractor not later than the 20th day of the following month. If an Application for Payment is received by the Architect after the application date fixed above, payment of the amount certified shall be made by the Owner not later than Thirty ( 30 ) days after the Architect receives the Application for Payment.

*(Federal, state or local laws may require payment within a certain period of time.)*

**§ 5.1.4** Each Application for Payment shall be based on the most recent schedule of values submitted by the Contractor in accordance with the Contract Documents. The schedule of values shall allocate the entire Contract Sum among the various portions of the Work. The schedule of values shall be prepared in such form, and supported by such data to substantiate its accuracy, as the Architect may require. This schedule of values shall be used as a basis for reviewing the Contractor's Applications for Payment.

**§ 5.1.5** Applications for Payment shall show the percentage of completion of each portion of the Work as of the end of the period covered by the Application for Payment.

**§ 5.1.6** In accordance with AIA Document A201™–2017, General Conditions of the Contract for Construction, and subject to other provisions of the Contract Documents, the amount of each progress payment shall be computed as follows:

**§ 5.1.6.1** The amount of each progress payment shall first include:

- .1 That portion of the Contract Sum properly allocable to completed Work;
- .2 That portion of the Contract Sum properly allocable to materials and equipment delivered and suitably stored at the site for subsequent incorporation in the completed construction, or, if approved in advance by the Owner, suitably stored off the site at a location agreed upon in writing; and
- .3 That portion of Construction Change Directives that the Architect determines, in the Architect's professional judgment, to be reasonably justified.

**§ 5.1.6.2** The amount of each progress payment shall then be reduced by:

- .1 The aggregate of any amounts previously paid by the Owner;
- .2 The amount, if any, for Work that remains uncorrected and for which the Architect has previously withheld a Certificate for Payment as provided in Article 9 of AIA Document A201–2017;
- .3 Any amount for which the Contractor does not intend to pay a Subcontractor or material supplier, unless the Work has been performed by others the Contractor intends to pay;
- .4 For Work performed or defects discovered since the last payment application, any amount for which the Architect may withhold payment, or nullify a Certificate of Payment in whole or in part, as provided in Article 9 of AIA Document A201–2017; and
- .5 Retainage withheld pursuant to Section 5.1.7.

**§ 5.1.7 Retainage**

**§ 5.1.7.1** For each progress payment made prior to Substantial Completion of the Work, the Owner may withhold the following amount, as retainage, from the payment otherwise due:

*(Insert a percentage or amount to be withheld as retainage from each Application for Payment. The amount of retainage may be limited by governing law.)*

Init.

/

§ 5.1.7.1.1 The following items are not subject to retainage:  
*(Insert any items not subject to the withholding of retainage, such as general conditions, insurance, etc.)*

§ 5.1.7.2 Reduction or limitation of retainage, if any, shall be as follows:  
*(If the retainage established in Section 5.1.7.1 is to be modified prior to Substantial Completion of the entire Work, including modifications for Substantial Completion of portions of the Work as provided in Section 3.3.2, insert provisions for such modifications.)*

§ 5.1.7.3 Except as set forth in this Section 5.1.7.3, upon Substantial Completion of the Work, the Contractor may submit an Application for Payment that includes the retainage withheld from prior Applications for Payment pursuant to this Section 5.1.7. The Application for Payment submitted at Substantial Completion shall not include retainage as follows:  
*(Insert any other conditions for release of retainage upon Substantial Completion.)*

§ 5.1.8 If final completion of the Work is materially delayed through no fault of the Contractor, the Owner shall pay the Contractor any additional amounts in accordance with Article 9 of AIA Document A201–2017.

§ 5.1.9 Except with the Owner’s prior approval, the Contractor shall not make advance payments to suppliers for materials or equipment which have not been delivered and stored at the site.

**§ 5.2 Final Payment**

§ 5.2.1 Final payment, constituting the entire unpaid balance of the Contract Sum, shall be made by the Owner to the Contractor when

- .1 the Contractor has fully performed the Contract except for the Contractor’s responsibility to correct Work as provided in Article 12 of AIA Document A201–2017, and to satisfy other requirements, if any, which extend beyond final payment; and
- .2 a final Certificate for Payment has been issued by the Architect.

§ 5.2.2 The Owner’s final payment to the Contractor shall be made no later than 30 days after the issuance of the Architect’s final Certificate for Payment, or as follows:

**§ 5.3 Interest**

Payments due and unpaid under the Contract shall bear interest from the date payment is due at the rate stated below, or in the absence thereof, at the legal rate prevailing from time to time at the place where the Project is located.  
*(Insert rate of interest agreed upon, if any.)*

%

**ARTICLE 6 DISPUTE RESOLUTION**

**§ 6.1 Initial Decision Maker**

The Architect will serve as the Initial Decision Maker pursuant to Article 15 of AIA Document A201–2017, unless the parties appoint below another individual, not a party to this Agreement, to serve as the Initial Decision Maker.  
*(If the parties mutually agree, insert the name, address and other contact information of the Initial Decision Maker, if other than the Architect.)*

**§ 6.2 Binding Dispute Resolution**

For any Claim subject to, but not resolved by, mediation pursuant to Article 15 of AIA Document A201–2017, the method of binding dispute resolution shall be as follows:

*(Check the appropriate box.)*

Arbitration pursuant to Section 15.4 of AIA Document A201–2017

Litigation in a court of competent jurisdiction

Other *(Specify)*

If the Owner and Contractor do not select a method of binding dispute resolution, or do not subsequently agree in writing to a binding dispute resolution method other than litigation, Claims will be resolved by litigation in a court of competent jurisdiction.

**ARTICLE 7 TERMINATION OR SUSPENSION**

**§ 7.1** The Contract may be terminated by the Owner or the Contractor as provided in Article 14 of AIA Document A201–2017.

**§ 7.1.1** If the Contract is terminated for the Owner’s convenience in accordance with Article 14 of AIA Document A201–2017, then the Owner shall pay the Contractor a termination fee as follows:

*(Insert the amount of, or method for determining, the fee, if any, payable to the Contractor following a termination for the Owner’s convenience.)*

**§ 7.2** The Work may be suspended by the Owner as provided in Article 14 of AIA Document A201–2017.

**ARTICLE 8 MISCELLANEOUS PROVISIONS**

**§ 8.1** Where reference is made in this Agreement to a provision of AIA Document A201–2017 or another Contract Document, the reference refers to that provision as amended or supplemented by other provisions of the Contract Documents.

**§ 8.2** The Owner’s representative:

*(Name, address, email address, and other information)*

Jeremy Rieder, President and Chief Executive Officer  
Sauler Apts LLC  
1770 W. County Line Rd., Suite 201  
Lakewood, N.J. 10017  
jr@onyxp.com  
732-886-6787 ext 114

**§ 8.3** The Contractor’s representative:

*(Name, address, email address, and other information)*

Jeff Blevins, President  
Camp Construction Services

Init.

15139 South Post Oak Road  
 Houston, Texas 77053  
 jblevins@campconstruction.com  
 713-413-2267

§ 8.4 Neither the Owner’s nor the Contractor’s representative shall be changed without ten days’ prior notice to the other party.

**§ 8.5 Insurance and Bonds**

§ 8.5.1 The Owner and the Contractor shall purchase and maintain insurance as set forth in AIA Document A101™–2017, Standard Form of Agreement Between Owner and Contractor where the basis of payment is a Stipulated Sum, Exhibit A, Insurance and Bonds, and elsewhere in the Contract Documents.

§ 8.5.2 The Contractor shall provide bonds as set forth in AIA Document A101™–2017 Exhibit A, and elsewhere in the Contract Documents.

§ 8.6 Notice in electronic format, pursuant to Article 1 of AIA Document A201–2017, may be given in accordance with AIA Document E203™–2013, Building Information Modeling and Digital Data Exhibit, if completed, or as otherwise set forth below:

*(If other than in accordance with AIA Document E203–2013, insert requirements for delivering notice in electronic format such as name, title, and email address of the recipient and whether and how the system will be required to generate a read receipt for the transmission.)*

§ 8.7 Other provisions:

**ARTICLE 9 ENUMERATION OF CONTRACT DOCUMENTS**

§ 9.1 This Agreement is comprised of the following documents:

- .1 AIA Document A101™–2017, Standard Form of Agreement Between Owner and Contractor
- .2 AIA Document A101™–2017, Exhibit A, Insurance and Bonds
- .3 AIA Document A201™–2017, General Conditions of the Contract for Construction
- .4 AIA Document E203™–2013, Building Information Modeling and Digital Data Exhibit, dated as indicated below:  
*(Insert the date of the E203-2013 incorporated into this Agreement.)*

.5 Drawings

Number	Title	Date
--------	-------	------

.6 Specifications

Section	Title	Date	Pages
---------	-------	------	-------

.7 Addenda, if any:

Init.

/

Number Date Pages

Portions of Addenda relating to bidding or proposal requirements are not part of the Contract Documents unless the bidding or proposal requirements are also enumerated in this Article 9.

.8 Other Exhibits:
(Check all boxes that apply and include appropriate information identifying the exhibit where required.)

[ ] AIA Document E204™-2017, Sustainable Projects Exhibit, dated as indicated below:
(Insert the date of the E204-2017 incorporated into this Agreement.)

[ ] The Sustainability Plan:

Title Date Pages

[ ] Supplementary and other Conditions of the Contract:

Document Title Date Pages

.9 Other documents, if any, listed below:
(List here any additional documents that are intended to form part of the Contract Documents. AIA Document A201™-2017 provides that the advertisement or invitation to bid, Instructions to Bidders, sample forms, the Contractor's bid or proposal, portions of Addenda relating to bidding or proposal requirements, and other information furnished by the Owner in anticipation of receiving bids or proposals, are not part of the Contract Documents unless enumerated in this Agreement. Any such documents should be listed here only if intended to be part of the Contract Documents.)

Exhibit B - Xactimate

This Agreement entered into as of the day and year first written above.

OWNER (Signature) [Handwritten Signature]

Jeremy Rieder President and Chief Executive Officer
(Printed name and title)

DocuSigned by: Jeff Blevins 7/17/2022 | 10:15 CDT

CONTRACTOR (Signature)

Camp Roofing, Ltd.
By: Camp GP, LLC, its general partner
By: Jeff Blevins, President
(Printed name and title)

Init.

# Additions and Deletions Report for AIA® Document A101® – 2017

This Additions and Deletions Report, as defined on page 1 of the associated document, reproduces below all text the author has added to the standard form AIA document in order to complete it, as well as any text the author may have added to or deleted from the original AIA text. Added text is shown underlined. Deleted text is indicated with a horizontal line through the original AIA text.

Note: This Additions and Deletions Report is provided for information purposes only and is not incorporated into or constitute any part of the associated AIA document. This Additions and Deletions Report and its associated document were generated simultaneously by AIA software at 11:06:48 CT on 06/27/2022.

## PAGE 1

**AGREEMENT** made as of the Twenty-seventh day of June in the year Two Thousand Twenty-two

...

Saulet Apts LLC  
780 Third Ave 25<sup>th</sup> Fl  
New York, N.Y. 10017

...

*(Name, legal status, address and other information)*

Camp Roofing LTD dba Camp Construction Services  
15139 South Post Oak Road  
Houston, Texas 77053

...

The Saulet  
1420 Annunciation Street  
New Orleans, LA 70130  
Interior and Exterir Building Repairs

...

N/A  
**PAGE 2**

Established as follows:

...

July 11, 2022

## PAGE 3

By the following date: October 14, 2022

...

§ 4.1 The Owner shall pay the Contractor the Contract Sum in current funds for the Contractor’s performance of the Contract. The Contract Sum shall be Six Million Two Thousand Three Hundred Fifty-one Dollars and Forty-nine Cents (\$ 6,002,351.49), subject to additions and deductions as provided in the Contract Documents.

PAGE 4

§ 5.1.3 Provided that an Application for Payment is received by the Architect not later than the 20th day of a month, the Owner shall make payment of the amount certified to the Contractor not later than the 20th day of the following month. If an Application for Payment is received by the Architect after the application date fixed above, payment of the amount certified shall be made by the Owner not later than Thirty ( 30 ) days after the Architect receives the Application for Payment.

PAGE 6

[ X ] Litigation in a court of competent jurisdiction

...

Jeremy Rieder, President and Chief Executive Officer  
Saulet Apts LLC  
1770 W. County Line Rd., Suite 201  
Lakewood, N.J. 10017  
jr@onyxp.com  
732-886-6787 ext 114

...

Jeff Blevins, President  
Camp Construction Services  
15139 South Post Oak Road  
Houston, Texas 77053  
jblevins@campconstruction.com  
713-413-2267

PAGE 8

Exhibit B - Xactimate

...

Jeremy Rieder President and Chief Executive Officer

Camp Roofing, Ltd.  
By: Camp GP, LLC, its general partner  
By: Jeff Blevins, President

## **Certification of Document's Authenticity** **AIA® Document D401™ – 2003**

I, \_\_\_\_\_, hereby certify, to the best of my knowledge, information and belief, that I created the attached final document simultaneously with its associated Additions and Deletions Report and this certification at 11:06:48 CT on 06/27/2022 under Order No. 2114259654 from AIA Contract Documents software and that in preparing the attached final document I made no changes to the original text of AIA® Document A101™ – 2017, Standard Form of Agreement Between Owner and Contractor where the basis of payment is a Stipulated Sum, as published by the AIA in its software, other than those additions and deletions shown in the associated Additions and Deletions Report.

DocuSigned by:

*Diane Suits*

(Signed) 76EB496EC0D04FC...

Executive Administrative Assistant

(Title)

7/17/2022 | 12:37 CDT

(Dated)

# Exhibit B



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Insured: Saulet - Building 1-11 and office - V5.23  
Property: 1420 Annunciation Street  
New Orleans, LA 70130

Business: (832) 309-9126

Claim Rep.: Mr. Mark Graves  
Company: Zurich North America  
Business: 1299 Zurich Way  
Schaumburg, IL 60196

Business: (920) 457-2257  
E-mail: mark.graves@zurichna.com

Contractor:  
Company: Camp Construction Services  
Business: 15139 S. Post Oak Road  
Houston, TX 77053

**Claim Number:** 5630071243

**Policy Number:** 0190484

**Type of Loss:** Hurricane

Date Contacted: 9/10/2021 12:00 AM

Date of Loss: 8/30/2021 12:00 AM

Date Inspected: 9/10/2021 12:00 AM

Date Received: 9/10/2021 12:00 AM

Date Entered: 9/10/2021 12:00 AM

Date Est. Completed: 1/5/2022 11:34 PM

Price List: LANO8X\_OCT21  
Restoration/Service/Remodel  
Estimate: SAULET-RECON-V5\_23-B



**Camp Construction Services**


15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**SAULET-B01-OFFICE-V5\_23**

**SAULET-BLDG-01-V5\_23**

**Building 1 Interiors**

**1108**



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	


- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
2. Paint the walls and ceiling - two coats	472.34 SF		0.00	1.36	10.44	128.48	781.30
3. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
4. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
<b>Totals: Kitchen</b>					<b>11.60</b>	<b>168.06</b>	<b>1,019.87</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Living / Dining Room**

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

- Missing Wall** **12' 7" X 9'** **Opens into KITCHEN**
- Missing Wall** **4' 1" X 9'** **Opens into ENTRY**
- Window** **4' X 4'** **Opens into Exterior**
- Door** **4' X 6' 8"** **Opens into Exterior**
- Window** **4' X 4'** **Opens into Exterior**
- Missing Wall** **1' 1" X 9'** **Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5. 5/8" - drywall per LF - up to 2' tall	20.00 LF		0.00	11.45	2.85	45.80	277.65
<i>Walls</i>							
6. Baseboard - 2 1/4"	20.00 LF		0.00	2.90	1.89	11.60	71.49
7. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
<i>Walls</i>							
8. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
9. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
10. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>26.56</b>	<b>378.28</b>	<b>2,296.17</b>



**Bedroom**

**Height: 9'**

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

- Window** **4' X 4'** **Opens into Exterior**
- Door** **2' 8" X 6' 8"** **Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
11. 5/8" - drywall per LF - up to 2' tall	10.00 LF		0.00	11.45	1.43	22.90	138.83




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
12. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
13. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
14. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
15. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
16. Seal & paint base shoe or quarter round	42.83 LF		0.00	1.19	0.47	10.20	61.64
17. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
18. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
19. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
20. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
Totals: Bedroom					21.08	279.92	1,700.59



### Closet

Height: 9'

198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
21. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint and blend (ceiling)</i>	235.72 SF		0.00	1.84	6.63	86.74	527.09
22. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
23. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
24. Clean and deodorize carpet	36.97 SF		0.00	0.57	0.00	4.22	25.29
25. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
26. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet					7.52	114.78	696.22



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 1108

66.76

941.04

5,712.85

1109



**Kitchen**


**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling **2' 6" X 5'** **Opens into KITCHEN**
- Door **1' 6" X 6' 8"** **Opens into PANTRY**
- Missing Wall **2' 4" X 9'** **Opens into HALLWAY**
- Missing Wall **12' 7" X 9'** **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling **2' 6" X 5'** **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling **7' 7" X 5'** **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
27. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
28. Paint the walls and ceiling - two coats	472.34 SF		0.00	1.36	10.44	128.48	781.30
29. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
30. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57

Totals: Kitchen 11.60      168.06      1,019.87



**Living / Dining Room**

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

- Missing Wall **12' 7" X 9'** **Opens into KITCHEN**
- Missing Wall **4' 1" X 9'** **Opens into ENTRY**
- Window **4' X 4'** **Opens into Exterior**
- Door **4' X 6' 8"** **Opens into Exterior**
- Window **4' X 4'** **Opens into Exterior**
- Missing Wall **1' 1" X 9'** **Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
31. 5/8" - drywall per LF - up to 2' tall <i>Walls</i>	20.00 LF		0.00	11.45	2.85	45.80	277.65
32. Baseboard - 2 1/4"	20.00 LF		0.00	2.90	1.89	11.60	71.49
33. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
34. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
35. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
36. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>26.56</b>	<b>378.28</b>	<b>2,296.17</b>



### Bedroom

**Height: 9'**

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
37. 5/8" - drywall per LF - up to 2' tall	10.00 LF		0.00	11.45	1.43	22.90	138.83
38. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
39. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
40. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
41. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
42. Seal & paint base shoe or quarter round	42.83 LF		0.00	1.19	0.47	10.20	61.64
43. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
44. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
45. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
46. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Bedroom					21.08	279.92	1,700.59



### Closet


Height: 9'

198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
47. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint and blend (ceiling)</i>	235.72 SF		0.00	1.84	6.63	86.74	527.09
48. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
49. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
50. Clean and deodorize carpet	36.97 SF		0.00	0.57	0.00	4.22	25.29
51. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
52. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet					7.52	114.78	696.22

Total: 1109 **66.76    941.04    5,712.85**

### 1110



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
53. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
54. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
55. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
56. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					6.89	98.08	595.42



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
57. 5/8" drywall - hung, taped, floated, ready for paint Walls	5.00 SF		0.00	2.87	0.34	2.88	17.57
58. Batt insulation - 6" - R19 - unfaced batt Walls	5.00 SF		0.00	1.07	0.32	1.08	6.75
59. Seal/prime then paint the walls and ceiling twice (3 coats) Walls	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
60. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
61. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
62. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
63. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
64. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					18.18	268.88	1,631.45



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 1110

25.07

366.96

2,226.87

1111



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
65. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	179.00 SF		0.00	2.87	12.05	102.74	628.52
66. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	54.00 SF		0.00	1.07	3.47	11.56	72.81
67. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	40.83 SF		0.00	1.12	3.08	9.14	57.95
68. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
69. Casing - 2 1/4"	42.00 LF		0.00	2.23	4.90	18.74	117.30
70. Paint casing - one coat	42.00 LF		0.00	1.44	0.42	12.10	73.00
71. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
72. Seal & paint baseboard - two coats	10.00 LF		0.00	2.24	0.11	4.48	26.99
73. Base shoe	6.00 LF		0.00	1.41	0.30	1.70	10.46
74. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
75. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
76. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
77. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
78. Light fixture - Standard grade	1.00 EA		0.00	53.27	1.72	10.66	65.65
79. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
80. Detach & Reset Thermostat	1.00 EA	62.84	0.00	0.00	0.00	12.56	75.40
81. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
82. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					34.19	306.78	1,874.83



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
83. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
84. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	97.00 SF		0.00	2.87	6.53	55.68	340.60
85. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	282.90 SF		0.00	1.84	7.96	104.10	632.60
86. Light fixture <i>Walls</i> <i>Walls</i>	1.00 EA		0.00	69.13	3.32	13.82	86.27
87. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
88. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
89. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
90. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					29.85	241.94	1,481.55



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
91. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	54.00 SF		0.00	2.87	3.64	31.00	189.62
92. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	14.00 SF		0.00	1.07	0.90	3.00	18.88
93. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
94. Baseboard - 4 1/4"	28.00 LF		0.00	4.14	5.68	23.18	144.78
95. Base shoe	27.00 LF		0.00	1.41	1.36	7.62	47.05
96. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
97. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
98. Casing - 2 1/4"	20.00 LF		0.00	2.23	2.33	8.92	55.85
99. Paint casing - one coat	20.00 LF		0.00	1.44	0.20	5.76	34.76
100. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
101. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					30.85	333.58	2,032.33
Total: 1111					<b>94.89</b>	<b>882.30</b>	<b>5,388.71</b>

1112



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen


**Height: 8'**

369.67 SF Walls	157.60 SF Ceiling
527.26 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	55.42 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>7' 6" X 4'</b>	<b>Opens into KITCHEN2</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 11" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Missing Wall</b>	<b>14' 2 1/16" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 4'</b>	<b>Opens into KITCHEN2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
102. Seal & paint baseboard - two coats	55.42 LF		0.00	2.24	0.61	24.82	149.57
103. Paint the walls and ceiling - two coats	527.26 SF		0.00	1.36	11.66	143.42	872.15
104. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
105. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89

Totals: Kitchen 13.04      189.52      1,150.13



### Living / Dining Room

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN2</b>




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
106. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	5.00 SF		0.00	2.87	0.34	2.88	17.57
107. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	5.00 SF		0.00	1.07	0.32	1.08	6.75
108. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	875.58 SF		0.00	1.84	24.64	322.22	1,957.93
109. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
110. Seal & paint base shoe or quarter round	63.08 LF		0.00	1.19	0.70	15.02	90.79
111. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
112. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
113. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>29.50</b>	<b>439.72</b>	<b>2,667.69</b>
<b>Total: 1112</b>					<b>42.54</b>	<b>629.24</b>	<b>3,817.82</b>

**1113**



**Kitchen**

**Height: 8'**

369.67 SF Walls	157.60 SF Ceiling
527.26 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	55.42 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **2' 6" X 4'**      **Opens into KITCHEN2**
- Door**      **3' X 6' 8"**      **Opens into Exterior**
- Door**      **1' 11" X 6' 8"**      **Opens into PANTRY**
- Door**      **1' 10" X 6' 8"**      **Opens into CLOSET**
- Missing Wall**      **14' 2 1/16" X 8'**      **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling**      **7' 6" X 4'**      **Opens into KITCHEN2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
114. 5/8" drywall - hung, taped, floated, ready for paint	177.00 SF		0.00	2.87	11.92	101.60	621.51




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
115. Blown-in insulation - 10" depth - R26	157.60 SF		0.00	1.12	11.88	35.30	223.69
<i>Ceiling</i>							
116. Seal/prime then paint the walls and ceiling twice (3 coats)	527.26 SF		0.00	1.84	14.84	194.04	1,179.04
117. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
118. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
119. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
120. Cabinetry - lower (base) units	10.00 LF		0.00	219.33	179.12	438.66	2,811.08
121. Countertop - solid surface	25.50 SF		0.00	64.30	114.55	327.94	2,082.14
122. Backsplash - solid surface - Unattached	14.00 LF		0.00	14.91	14.94	41.74	265.42
123. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
124. Detach & Reset Range - freestanding - gas	1.00 EA	171.46	0.00	0.00	0.00	34.30	205.76
125. Detach & Reset Dishwasher	1.00 EA	250.12	0.00	0.00	0.00	50.02	300.14
126. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
127. Sink - single - Detach & reset	1.00 EA		0.00	160.49	0.05	32.10	192.64
128. Detach & Reset Sink faucet - Kitchen	1.00 EA	128.34	0.00	0.00	0.00	25.66	154.00
129. Install Plumbing fixture supply line	1.00 EA		0.00	14.53	0.00	2.90	17.43
130. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
131. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
Totals: Kitchen					358.83	1,414.30	8,844.54



### Hall Bathroom

Height: 8'

240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

**Door** 1' 6" X 6' 8"

**Opens into LINEN\_CLOSET**

**Door** 2' 8" X 6' 8"

**Opens into LIVING\_\_DIN**




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Hall Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
132. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
133. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	57.36 SF		0.00	1.12	4.32	12.84	81.40
134. Paint the walls and ceiling - two coats	297.58 SF		0.00	1.36	6.58	80.94	492.23
135. Drywall patch / small repair, ready for paint <i>Wall (patch)</i>	1.00 EA		0.00	89.02	0.33	17.80	107.15
136. Clean floor	57.36 SF		0.00	0.54	0.06	6.20	37.23
137. Mask the floor per square foot - plastic and tape - 4 mil	57.36 SF		0.00	0.35	0.29	4.02	24.39
Totals: Hall Bathroom					12.93	133.28	812.63



### Living / Dining Room

Height: 8'

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
138. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	30.00 SF		0.00	2.87	2.02	17.22	105.34
139. Seal/prime then paint the walls and ceiling twice (3 coats)	875.58 SF		0.00	1.84	24.64	322.22	1,957.93




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
140. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
141. Paint door/window trim & jamb - Large - 2 coats (per side)	2.00 EA		0.00	53.78	1.07	21.52	130.15
142. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
143. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
144. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
Totals: Living / Dining Room					31.69	468.62	2,843.38
Total: 1113					<b>403.45</b>	<b>2,016.20</b>	<b>12,500.55</b>

### 1119



#### Kitchen

Height: 9'

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
145. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
146. Paint the walls and ceiling - two coats	522.56 SF		0.00	1.36	11.55	142.14	864.37
147. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
148. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					12.85	185.98	1,128.65



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
149. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	55.00 SF		0.00	2.87	3.70	31.58	193.13
150. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	55.00 SF		0.00	1.07	3.54	11.78	74.17
151. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
152. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
153. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
154. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
155. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
156. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living / Dining Room					40.86	544.34	3,306.74



### Bathroom

Height: 9'

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

**Door** 3' 3" X 6' 8"

**Opens into ROOM2**

**Door** 2' 8" X 6' 8"

**Opens into MASTER\_BEDRO**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
157. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11
158. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	10.00 SF		0.00	1.12	0.75	2.24	14.19
159. Seal/prime then paint the ceiling twice (3 coats) <i>Walls</i>	66.75 SF		0.00	1.84	1.88	24.56	149.26
160. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
161. Seal & paint baseboard - two coats	31.08 LF		0.00	2.24	0.34	13.92	83.88
162. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
163. Mask the floor per square foot - plastic and tape - 4 mil	66.75 SF		0.00	0.35	0.34	4.68	28.38
164. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24
Totals: Bathroom					10.93	144.66	878.94
Total: 1119					<b>64.64</b>	<b>874.98</b>	<b>5,314.33</b>

1202



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom

**Height: 9'**

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 3" X 6' 8"</b>	<b>Opens into ROOM2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
165. 1/2" water rock - hung, taped, floated, ready for paint	10.00 SF		0.00	2.88	0.70	5.76	35.26
166. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
167. Seal/prime then paint the ceiling twice (3 coats)	66.75 SF		0.00	1.84	1.88	24.56	149.26
<b>Ceiling</b>							
168. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
169. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
170. Detach & Reset Towel bar	1.00 EA	16.99	0.00	0.00	0.00	3.40	20.39
171. Detach & Reset Mirror - 1/4" plate glass	25.00 SF	6.20	0.00	0.00	0.00	31.00	186.00
172. Mask the floor per square foot - plastic and tape - 4 mil	66.75 SF		0.00	0.35	0.34	4.68	28.38
173. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24
<b>Totals: Bathroom</b>					<b>10.05</b>	<b>166.10</b>	<b>1,006.61</b>
<b>Total: 1202</b>					<b>10.05</b>	<b>166.10</b>	<b>1,006.61</b>

1207



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
174. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
175. Paint the ceiling - two coats	384.72 SF		0.00	1.36	8.51	104.64	636.37
176. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>10.44</b>	<b>157.74</b>	<b>956.85</b>



### Bathroom

**Height: 9'**

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 3" X 6' 8"</b>	<b>Opens into ROOM2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
177. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
178. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	10.00 SF		0.00	1.12	0.75	2.24	14.19
179. Seal/prime then paint the ceiling twice (3 coats) <i>Walls</i>	66.75 SF		0.00	1.84	1.88	24.56	149.26
180. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
181. Seal & paint baseboard - two coats	31.08 LF		0.00	2.24	0.34	13.92	83.88
182. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
183. Mask the floor per square foot - plastic and tape - 4 mil	66.75 SF		0.00	0.35	0.34	4.68	28.38
184. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24
<b>Totals: Bathroom</b>					<b>10.93</b>	<b>144.66</b>	<b>878.94</b>
<b>Total: 1207</b>					<b>21.37</b>	<b>302.40</b>	<b>1,835.79</b>

### 1208



#### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
185. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	36.00 SF		0.00	1.12	2.71	8.06	51.09
186. 5/8" drywall - hung, taped, floated, ready for paint	48.00 SF		0.00	2.87	3.23	27.56	168.55




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
187. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
<i>Ceiling</i>							
188. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
189. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
190. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
191. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					20.39	259.20	1,575.46



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
192. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
193. Paint the walls and ceiling - two coats	704.18 SF		0.00	1.36	15.57	191.54	1,164.79
194. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
195. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
196. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					18.48	271.56	1,647.78



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 1208

38.87

530.76

3,223.24

**1209**



**Living / Dining Room**


**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
197. Seal/prime then paint the walls twice (3 coats)	414.58 SF		0.00	1.84	11.67	152.56	927.06
198. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
199. Track for track lighting - Detach & reset	3.00 LF		0.00	9.84	0.00	5.90	35.42
200. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
201. In-wall / In-ceiling speaker - Detach & reset	2.00 EA		0.00	18.44	0.00	7.38	44.26
202. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
203. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
204. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16

Totals: Living / Dining Room 13.13      255.64      1,546.97



**Closet**

**Height: 9'**

198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
-------------	----------------------	----------------------------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
205. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
206. Detach & Reset Shelving - wire (vinyl coated)	21.39 LF	9.66	0.00	0.00	0.00	41.32	247.95
207. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
208. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
209. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet					6.82	136.92	828.40
Total: 1209					19.95	392.56	2,375.37

### 1211



#### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
210. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	70.00 SF		0.00	2.87	4.71	40.18	245.79
211. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	158.83 SF		0.00	1.84	4.47	58.46	355.18
212. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
213. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
214. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
215. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					9.97	118.42	720.44



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
216. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
217. 5/8" drywall - hung, taped, floated, ready for paint	114.74 SF		0.00	2.87	7.73	65.86	402.89
218. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	282.90 SF		0.00	1.84	7.96	104.10	632.60
219. Detach & Reset Light fixture	3.00 EA	50.85	0.00	0.00	0.00	30.52	183.07
220. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
221. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
222. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					21.20	236.12	1,437.93



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bathroom

Height: 9'

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into ENTRY
Door	2' 8" X 6' 8"	Opens into WALKIN_CLOS
Door	2' 8" X 6' 8"	Opens into BEDROOM



### Subroom: Utility Room (1)

Height: 9'

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
223. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	30.00 SF		0.00	2.87	2.02	17.22	105.34
224. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	30.00 SF		0.00	1.12	2.26	6.72	42.58
225. Seal/prime then paint the ceiling twice (3 coats) <i>Walls</i>	96.03 SF		0.00	1.84	2.70	35.34	214.74
226. Paint the walls - two coats	509.17 SF		0.00	1.36	11.26	138.50	842.23
227. Seal & paint baseboard - two coats	54.50 LF		0.00	2.24	0.60	24.42	147.10
228. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
229. Mask the floor per square foot - plastic and tape - 4 mil	96.03 SF		0.00	0.35	0.48	6.72	40.81
230. Final cleaning - construction - Residential	96.03 SF		0.00	0.34	0.00	6.54	39.19
Totals: Bathroom					19.78	244.60	1,487.30



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
231. 5/8" drywall - hung, taped, floated, ready for paint	30.00 SF		0.00	2.87	2.02	17.22	105.34
<i>Walls</i>							
232. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
<i>Walls</i>							
233. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
234. 5/8" - drywall per LF - up to 2' tall	86.00 LF		0.00	11.45	12.27	196.94	1,193.91
235. Seal/prime then paint the surface area twice (3 coats)	688.00 SF		0.00	1.84	19.36	253.18	1,538.46
236. Light fixture	5.00 EA		0.00	69.13	16.58	69.14	431.37
237. Ceiling fan & light	2.00 EA		0.00	324.26	25.63	129.70	803.85
238. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
239. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					91.96	901.86	5,503.14
<b>Total: 1211</b>					<b>142.91</b>	<b>1,501.00</b>	<b>9,148.81</b>

1213



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom 2**


**Height: 8'**

420.05 SF Walls  
571.57 SF Walls & Ceiling  
16.84 SY Flooring  
59.01 LF Ceil. Perimeter

151.52 SF Ceiling  
151.52 SF Floor  
56.01 LF Floor Perimeter

**Door** 3' X 6' 8" Opens into LIVING\_\_DIN  
**Window** 4' X 4' Opens into Exterior  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
240. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
241. Seal/prime then paint the ceiling twice (3 coats)	151.52 SF		0.00	1.84	4.26	55.76	338.82
242. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
243. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
244. Mask the floor per square foot - plastic and tape - 4 mil	151.52 SF		0.00	0.35	0.76	10.60	64.39
245. Final cleaning - construction - Residential	151.52 SF		0.00	0.34	0.00	10.30	61.82
<b>Totals: Bedroom 2</b>					5.35	134.44	812.07



**Kitchen**

**Height: 8'**

369.67 SF Walls  
527.26 SF Walls & Ceiling  
17.13 SY Flooring  
41.50 LF Ceil. Perimeter

157.60 SF Ceiling  
154.15 SF Floor  
55.42 LF Floor Perimeter

**Missing Wall - Goes to Ceiling** 7' 6" X 4' Opens into KITCHEN2  
**Door** 3' X 6' 8" Opens into Exterior  
**Door** 1' 11" X 6' 8" Opens into PANTRY  
**Door** 1' 10" X 6' 8" Opens into CLOSET  
**Missing Wall** 14' 2 1/16" X 8' Opens into LIVING\_\_DIN  
**Missing Wall - Goes to Ceiling** 2' 6" X 4' Opens into KITCHEN2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
246. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
247. Seal/prime then paint the walls and ceiling twice (3 coats)	527.26 SF		0.00	1.84	14.84	194.04	1,179.04
248. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
249. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
250. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
251. Mask the walls per square foot - plastic and tape - 4 mil	369.67 SF		0.00	0.35	1.86	25.88	157.12
252. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
<b>Totals: Kitchen</b>					<b>17.03</b>	<b>283.86</b>	<b>1,720.09</b>
<b>Total: 1213</b>					<b>22.38</b>	<b>418.30</b>	<b>2,532.16</b>

1214



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
253. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
<i>Ceiling</i>							
254. Seal/prime then paint the ceiling twice (3 coats)	64.74 SF		0.00	1.84	1.82	23.82	144.76
255. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
<i>Ceiling</i>							
256. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
257. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
258. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
259. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
260. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					7.81	155.30	939.57



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
261. 5/8" drywall - hung, taped, floated, ready for paint	45.00 SF		0.00	2.87	3.03	25.84	158.02
<i>Ceiling</i>							
262. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
<i>Walls</i>							
263. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
264. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
265. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
266. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					20.04	279.80	1,698.84
Total: 1214					27.85	435.10	2,638.41

1219



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Master Bedroom**

**Height: 9'**

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
267. Seal/prime then paint the ceiling twice (3 coats)	161.67 SF		0.00	1.84	4.55	59.50	361.52
<i>Ceiling</i>							
268. Paint the walls - two coats	450.94 SF		0.00	1.36	9.97	122.66	745.91
269. Seal & paint baseboard - two coats	50.50 LF		0.00	2.24	0.56	22.62	136.30
270. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
271. Mask the floor per square foot - plastic and tape - 4 mil	161.67 SF		0.00	0.35	0.81	11.32	68.71
272. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
<b>Totals: Master Bedroom</b>					<b>16.80</b>	<b>245.38</b>	<b>1,489.02</b>
<b>Total: 1219</b>					<b>16.80</b>	<b>245.38</b>	<b>1,489.02</b>

1301



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room/Kitchen**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM_</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM_</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM_</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
273. 5/8" drywall - hung, taped, floated, ready for paint	4.00 SF		0.00	2.87	0.27	2.30	14.05
274. Baseboard - 3 1/4"	5.00 LF		0.00	3.49	0.73	3.50	21.68
275. Paint the walls and ceiling - two coats	1,310.03 SF		0.00	1.36	28.97	356.32	2,166.93
276. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
277. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
278. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
279. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39


Totals: Living Room/Kitchen 34.50 495.42 3,006.88

Total: 1301 **34.50 495.42 3,006.88**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into LIVING_DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
280. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57
281. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
282. Baseboard - 3 1/4"	2.00 LF		0.00	3.49	0.29	1.40	8.67
283. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
284. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
285. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
<b>Totals: Kitchen</b>					<b>15.08</b>	<b>217.68</b>	<b>1,321.03</b>



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
286. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
287. Paint the walls and ceiling - two coats	704.18 SF		0.00	1.36	15.57	191.54	1,164.79
288. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
289. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
290. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					18.48	271.56	1,647.78
Total: 1308					<b>33.56</b>	<b>489.24</b>	<b>2,968.81</b>

### 1310



### Bedroom

Height: 9'

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
291. 5/8" drywall - hung, taped, floated, ready for paint	15.00 SF		0.00	2.87	1.01	8.62	52.68
292. Seal/prime then paint the walls and ceiling twice (3 coats)	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
293. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
294. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
295. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
296. Mask the walls per square foot - plastic and tape - 4 mil	362.22 SF		0.00	0.35	1.82	25.36	153.96
297. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					18.81	261.66	1,588.75

Door 2' 8" X 6' 8"

Opens into BATHROOM

Window 4' X 4'

Opens into Exterior



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 1310

18.81

261.66

1,588.75

1311



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET2

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
298. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	48.00 SF		0.00	2.87	3.23	27.56	168.55
299. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
300. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
301. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
302. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
303. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
304. Floor preparation for resilient flooring	40.83 SF		0.00	0.71	0.41	5.80	35.20
305. Vinyl plank flooring	40.83 SF		0.00	5.74	12.27	46.88	293.51
306. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
307. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					23.30	185.20	1,134.46



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
308. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
309. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	129.00 SF		0.00	2.87	8.69	74.04	452.96
310. Seal/prime then paint the ceiling twice (3 coats) <i>Ceiling</i>	64.74 SF		0.00	1.84	1.82	23.82	144.76
311. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
312. Hanging light fixture <i>Wall</i>	2.00 EA		0.00	81.74	6.53	32.70	202.71
313. Cabinetry - lower (base) units	10.00 LF		0.00	219.33	179.12	438.66	2,811.08
314. R&R Cabinetry - upper (wall) units	18.00 LF		9.45	152.53	201.58	583.12	3,700.34
315. Detach & Reset Countertop - post formed plastic laminate	12.75 LF	19.74	0.00	0.00	0.18	50.34	302.21
316. Sink - single - Detach & reset	1.00 EA		0.00	160.49	0.05	32.10	192.64
317. Detach & Reset Sink faucet - Kitchen	1.00 EA	128.34	0.00	0.00	0.00	25.66	154.00
318. Range - electric - Reset	1.00 EA		0.00	18.11	0.00	3.62	21.73
319. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
320. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
321. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
322. Floor preparation for resilient flooring	64.74 SF		0.00	0.71	0.65	9.20	55.82
323. Vinyl plank flooring	64.74 SF		0.00	5.74	19.45	74.32	465.38
324. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					426.60	1,442.92	9,084.17




**Bedroom**

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" **Opens into BATHROOM**  
**Window** 4' X 4' **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
325. Carpet - Standard grade	139.02 SF		0.00	2.82	25.71	78.40	496.15
15 % waste added for Carpet - Standard grade.							
326. Carpet pad	120.89 SF		0.00	0.63	5.95	15.24	97.35
327. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					31.66	101.86	642.82



**Walk-in Closet**

**Height: 9'**

181.72 SF Walls	22.92 SF Ceiling
204.64 SF Walls & Ceiling	22.92 SF Floor
2.55 SY Flooring	19.50 LF Floor Perimeter
22.17 LF Ceil. Perimeter	


**Door** 2' 8" X 6' 8" **Opens into BATHROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
328. Carpet - Standard grade	26.35 SF		0.00	2.82	4.87	14.86	94.04
15 % waste added for Carpet - Standard grade.							
329. Carpet pad	22.92 SF		0.00	0.63	1.13	2.88	18.45
330. Final cleaning - construction - Residential	22.92 SF		0.00	0.34	0.00	1.56	9.35
Totals: Walk-in Closet					6.00	19.30	121.84



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bathroom

Height: 9'

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into ENTRY
Door	2' 8" X 6' 8"	Opens into WALKIN_CLOS
Door	2' 8" X 6' 8"	Opens into BEDROOM



### Subroom: Utility Room (1)

Height: 9'

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
331. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	21.00 SF		0.00	2.87	1.41	12.06	73.74
332. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	96.03 SF		0.00	1.12	7.24	21.52	136.31
333. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64
334. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	605.19 SF		0.00	1.84	17.03	222.72	1,353.30
335. Seal & paint baseboard - two coats	54.50 LF		0.00	2.24	0.60	24.42	147.10
336. Detach & Reset Washer/Washing Machine - Front-loading	1.00 EA	46.97	0.00	0.00	0.00	9.40	56.37
337. Detach & Reset Dryer - Electric	1.00 EA	36.21	0.00	0.00	0.00	7.24	43.45
338. Floor preparation for resilient flooring	96.03 SF		0.00	0.71	0.96	13.64	82.78
339. Vinyl plank flooring	96.03 SF		0.00	5.74	28.86	110.24	690.31
340. Vinyl - metal transition strip	54.50 LF		0.00	3.02	7.12	32.92	204.63
341. Mask the floor per square foot - plastic and tape - 4 mil	96.03 SF		0.00	0.35	0.48	6.72	40.81
342. Final cleaning - construction - Residential	96.03 SF		0.00	0.34	0.00	6.54	39.19



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Bathroom					64.35	519.42	3,180.63



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
343. 5/8" drywall - hung, taped, floated, ready for paint	30.00 SF		0.00	2.87	2.02	17.22	105.34
<i>Walls</i>							
344. Baseboard - 4 1/4"	7.00 LF		0.00	4.14	1.42	5.80	36.20
345. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
<i>Walls</i>							
346. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
347. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
348. Vinyl - metal transition strip	3.00 LF		0.00	3.02	0.39	1.82	11.27
349. Carpet pad	154.68 SF		0.00	0.63	7.62	19.50	124.57
350. Carpet - Standard grade	177.88 SF		0.00	2.82	32.89	100.32	634.83
15 % waste added for Carpet - Standard grade.							
351. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
352. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					61.35	398.62	2,453.03
Total: 1311					613.26	2,667.32	16,616.95



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Walk-in Closet

Height: 8'

236.67 SF Walls	46.13 SF Ceiling
282.79 SF Walls & Ceiling	46.13 SF Floor
5.13 SY Flooring	29.17 LF Floor Perimeter
31.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	2' 6" X 6' 8"			Opens into MASTER_BATH			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
353. Seal/prime then paint the ceiling twice (3 coats)	46.13 SF		0.00	1.84	1.30	16.98	103.16	
354. Detach & Reset Shelving - wire (vinyl coated)	29.17 LF	9.66	0.00	0.00	0.00	56.36	338.14	
355. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56	
356. Mask the floor per square foot - plastic and tape - 4 mil	46.13 SF		0.00	0.35	0.23	3.24	19.62	
357. Final cleaning - construction - Residential	46.13 SF		0.00	0.34	0.00	3.14	18.82	
<b>Totals: Master Walk-in Closet</b>						1.53	83.48	502.30



### Bedroom 1 Walk-In Closet

Height: 8'


154.67 SF Walls	29.60 SF Ceiling
184.27 SF Walls & Ceiling	29.60 SF Floor
3.29 SY Flooring	18.67 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	4' X 6' 8"			Opens into BEDROOM_1			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
358. Seal/prime then paint the ceiling twice (3 coats)	29.60 SF		0.00	1.84	0.83	10.90	66.19	
359. Detach & Reset Shelving - wire (vinyl coated)	18.67 LF	9.66	0.00	0.00	0.00	36.08	216.43	
360. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56	
361. Mask the floor per square foot - plastic and tape - 4 mil	29.60 SF		0.00	0.35	0.15	2.08	12.59	
362. Final cleaning - construction - Residential	29.60 SF		0.00	0.34	0.00	2.02	12.08	
<b>Totals: Bedroom 1 Walk-In Closet</b>						0.98	54.84	329.85



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 8'**

369.67 SF Walls	157.60 SF Ceiling
527.26 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	55.42 LF Floor Perimeter
41.50 LF Ceil. Perimeter	


- Missing Wall - Goes to Ceiling**      **7' 6" X 4'**      **Opens into KITCHEN2**
- Door**      **3' X 6' 8"**      **Opens into Exterior**
- Door**      **1' 11" X 6' 8"**      **Opens into PANTRY**
- Door**      **1' 10" X 6' 8"**      **Opens into CLOSET**
- Missing Wall**      **14' 2 1/16" X 8'**      **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling**      **2' 6" X 4'**      **Opens into KITCHEN2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
363. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
364. Seal/prime then paint the walls and ceiling twice (3 coats)	527.26 SF		0.00	1.84	14.84	194.04	1,179.04
365. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
366. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
367. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
368. Mask the walls per square foot - plastic and tape - 4 mil	369.67 SF		0.00	0.35	1.86	25.88	157.12
369. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
<b>Totals: Kitchen</b>					<b>17.03</b>	<b>283.86</b>	<b>1,720.09</b>
<b>Total: 1312</b>					<b>19.54</b>	<b>422.18</b>	<b>2,552.24</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**


201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**
- Door**
- Door**
- Missing Wall**

- 6' 4" X 5'**
- 1' 8" X 6' 8"**
- 3' X 6' 8"**
- 4' 5" X 9'**

- Opens into LIVING\_ROOM**
- Opens into PANTRY**
- Opens into UTILITY\_ROOM**
- Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
370. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
371. Paint the walls and ceiling - two coats	267.13 SF		0.00	1.36	5.91	72.66	441.87
372. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
373. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>6.51</b>	<b>92.74</b>	<b>562.94</b>



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

- Missing Wall**
- Missing Wall - Goes to Ceiling**
- Window**
- Window**
- Missing Wall**

- 1' 5" X 9'**
- 6' 10" X 5'**
- 4' X 4'**
- 4' X 4'**
- 4' 6" X 9'**

- Opens into ENTRY**
- Opens into KITCHEN**
- Opens into Exterior**
- Opens into Exterior**
- Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
374. Seal/prime then paint the ceiling twice (3 coats)	215.36 SF		0.00	1.84	6.06	79.26	481.58
375. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
376. Paint the walls - two coats	425.08 SF		0.00	1.36	9.40	115.62	703.13




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
377. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
378. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
379. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>18.05</b>	<b>267.34</b>	<b>1,622.04</b>

**1317**



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
380. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
381. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
<i>Ceiling</i>							
382. Casing - 2 1/4"	7.00 LF		0.00	2.23	0.82	3.12	19.55
383. Seal/prime then paint the walls and ceiling twice (3 coats)	522.56 SF		0.00	1.84	14.71	192.30	1,168.52
<i>Walls</i>							
384. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
385. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
386. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					18.42	239.94	1,458.07



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
387. 5/8" drywall - hung, taped, floated, ready for paint	29.00 SF		0.00	2.87	1.95	16.64	101.82
388. Batt insulation - 6" - R19 - unfaced batt	25.00 SF		0.00	1.07	1.61	5.36	33.72
<i>Walls</i>							
389. Casing - 2 1/4"	7.00 LF		0.00	2.23	0.82	3.12	19.55
390. Paint casing - one coat	7.00 LF		0.00	1.44	0.07	2.02	12.17
391. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
<i>Walls</i>							
392. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
393. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
394. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
395. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
396. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					38.07	528.12	3,206.70



### Bathroom

Height: 9'

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

Door 3' 3" X 6' 8" Opens into ROOM2

Door 2' 8" X 6' 8" Opens into MASTER\_BEDRO


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
397. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11
398. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	10.00 SF		0.00	1.12	0.75	2.24	14.19
399. Seal/prime then paint the ceiling twice (3 coats) <i>Walls</i>	66.75 SF		0.00	1.84	1.88	24.56	149.26
400. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
401. Seal & paint baseboard - two coats	31.08 LF		0.00	2.24	0.34	13.92	83.88
402. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
403. Mask the floor per square foot - plastic and tape - 4 mil	66.75 SF		0.00	0.35	0.34	4.68	28.38
404. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24
Totals: Bathroom					10.93	144.66	878.94
Total: 1317					67.42	912.72	5,543.71
Total: 1316					91.98	1,272.80	7,728.69



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

1319



### Bedroom 1

Height: 9'

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	


Door 2' 8" X 6' 8" Opens into WALKIN\_CLOS  
Door 3' X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
405. 5/8" drywall - hung, taped, floated, ready for paint	219.97 SF		0.00	2.87	14.81	126.26	772.38
406. Batt insulation - 6" - R19 - unfaced batt	219.97 SF		0.00	1.07	14.15	47.08	296.60
<i>Ceiling</i>							
407. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
408. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
409. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
<i>Walls</i>							
410. Seal & paint baseboard - two coats	41.67 LF		0.00	2.24	0.46	18.66	112.46
411. Seal & paint base shoe or quarter round	41.67 LF		0.00	1.19	0.46	9.92	59.97
412. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
413. Clean and deodorize carpet	139.97 SF		0.00	0.57	0.00	15.96	95.74
414. Mask the walls per square foot - plastic and tape - 4 mil	388.22 SF		0.00	0.35	1.95	27.18	165.01
415. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
Totals: Bedroom 1					49.35	511.84	3,120.33



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
416. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48	
417. Paint the walls and ceiling - two coats	522.56 SF		0.00	1.36	11.55	142.14	864.37	
418. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54	
419. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26	
<b>Totals: Kitchen</b>						<b>12.85</b>	<b>185.98</b>	<b>1,128.65</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
420. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45
421. Batt insulation - 6" - R19 - unfaced batt	16.00 SF		0.00	1.07	1.03	3.42	21.57
<i>Ceiling</i>							
422. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
<i>Walls</i>							
423. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
424. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
425. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
426. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
427. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>37.34</b>	<b>527.36</b>	<b>3,201.46</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bathroom**

**Height: 9'**

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

**Door** **3' 3" X 6' 8"** **Opens into ROOM2**  
**Door** **2' 8" X 6' 8"** **Opens into MASTER\_BEDRO**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
428. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
<i>Ceiling</i>							
429. Blown-in insulation - 10" depth - R26	10.00 SF		0.00	1.12	0.75	2.24	14.19
<i>Ceiling</i>							
430. Seal/prime then paint the ceiling twice (3 coats)	66.75 SF		0.00	1.84	1.88	24.56	149.26
<i>Walls</i>							
431. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
432. Seal & paint baseboard - two coats	31.08 LF		0.00	2.24	0.34	13.92	83.88
433. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
434. Mask the floor per square foot - plastic and tape - 4 mil	66.75 SF		0.00	0.35	0.34	4.68	28.38
435. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24


Totals: Bathroom 10.93 144.66 878.94

Total: 1319 **110.47 1,369.84 8,329.38**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

375.72 SF Walls  
505.07 SF Walls & Ceiling  
14.37 SY Flooring  
45.50 LF Ceil. Perimeter

129.35 SF Ceiling  
129.35 SF Floor  
42.83 LF Floor Perimeter

**Window**

**4' X 4'**

**Opens into Exterior**


**Door**

**2' 8" X 6' 8"**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
436. Paint the walls and ceiling - two coats	505.07 SF		0.00	1.36	11.17	137.38	835.45
<i>Paint and blend (ceiling)</i>							
437. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
438. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
439. Clean and deodorize carpet	129.35 SF		0.00	0.57	0.00	14.74	88.47
440. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
441. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78

Totals: Bedroom 13.20      207.44      1,257.88



**Closet**

**Height: 9'**

198.76 SF Walls  
235.72 SF Walls & Ceiling  
4.11 SY Flooring  
24.06 LF Ceil. Perimeter

36.97 SF Ceiling  
36.97 SF Floor  
21.39 LF Floor Perimeter

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
442. Paint the walls and ceiling - two coats	235.72 SF		0.00	1.36	5.21	64.12	389.91
<i>Paint and blend (ceiling)</i>							
443. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
444. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
445. Clean and deodorize carpet	36.97 SF		0.00	0.57	0.00	4.22	25.29




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
446. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
447. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet					6.10	92.16	559.04
Total: 1409					<b>19.30</b>	<b>299.60</b>	<b>1,816.92</b>

### 1410



### Bedroom

Height: 9'

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
448. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16
449. Batt insulation - 6" - R19 - unfaced batt	14.00 SF		0.00	1.07	0.90	3.00	18.88
450. Seal/prime then paint the walls and ceiling twice (3 coats)	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
451. Base shoe	11.00 LF		0.00	1.41	0.55	3.10	19.16
452. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
453. Seal & paint base shoe or quarter round	41.33 LF		0.00	1.19	0.46	9.84	59.48
454. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
455. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
456. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
457. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					19.57	253.78	1,542.21

2' 8" X 6' 8"

Opens into BATHROOM

Window

4' X 4'

Opens into Exterior



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 1410

19.57

253.78

1,542.21

**1412**



**Bedroom 1**

**Height: 8'**

373.33 SF Walls  
507.23 SF Walls & Ceiling  
14.88 SY Flooring  
52.50 LF Ceil. Perimeter

133.90 SF Ceiling  
133.90 SF Floor  
45.50 LF Floor Perimeter

**Door** **4' X 6' 8"** **Opens into BEDROOM\_1\_WA**  
**Door** **3' X 6' 8"** **Opens into LIVING\_\_DIN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
458. R&R Vinyl window - double hung, 9-12 sf	1.00 EA		28.41	327.83	25.48	71.24	452.96
459. Paint door or window opening - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
460. Paint the walls - two coats	373.33 SF		0.00	1.36	8.25	101.54	617.52
461. Seal & paint baseboard - two coats	45.50 LF		0.00	2.24	0.50	20.38	122.80
462. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
463. Detach & Reset Window blind - PVC - 2" - 7.1 to 14 SF - High grade	1.00 EA	34.54	0.00	0.00	0.00	6.90	41.44
464. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
<b>Totals: Bedroom 1</b>					<b>35.60</b>	<b>236.58</b>	<b>1,455.27</b>



**Master Bedroom**

**Height: 8'**

353.33 SF Walls  
516.19 SF Walls & Ceiling  
18.10 SY Flooring  
51.17 LF Ceil. Perimeter

162.86 SF Ceiling  
162.86 SF Floor  
45.17 LF Floor Perimeter

**Door** **3' X 6' 8"** **Opens into LIVING\_\_DIN**  
**Door** **3' X 6' 8"** **Opens into MASTER\_BATH**  
**Window** **4' X 4'** **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
465. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Master Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
466. Seal/prime then paint the ceiling twice (3 coats)	162.86 SF		0.00	1.84	4.58	59.94	364.18
467. Paint the walls - two coats	353.33 SF		0.00	1.36	7.81	96.10	584.44
468. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
469. Mask the floor per square foot - plastic and tape - 4 mil	162.86 SF		0.00	0.35	0.82	11.40	69.22
470. Final cleaning - construction - Residential	162.86 SF		0.00	0.34	0.00	11.08	66.45
<b>Totals: Master Bedroom</b>					<b>14.46</b>	<b>199.68</b>	<b>1,212.47</b>



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
471. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	5.00 SF		0.00	2.87	0.34	2.88	17.57
472. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	5.00 SF		0.00	1.07	0.32	1.08	6.75
473. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
474. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	875.58 SF		0.00	1.84	24.64	322.22	1,957.93



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
475. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
476. Seal & paint base shoe or quarter round	63.08 LF		0.00	1.19	0.70	15.02	90.79
477. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
478. Mask the walls per square foot - plastic and tape - 4 mil	498.90 SF		0.00	0.35	2.51	34.92	212.05
479. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
Totals: Living / Dining Room					30.70	451.08	2,736.99
Total: 1412					<b>80.76</b>	<b>887.34</b>	<b>5,404.73</b>

### 1413



### Master Bath

Height: 8'

308.67 SF Walls	84.51 SF Ceiling
393.18 SF Walls & Ceiling	84.51 SF Floor
9.39 SY Flooring	37.67 LF Floor Perimeter
43.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
480. Seal/prime then paint the ceiling twice (3 coats)	84.51 SF		0.00	1.84	2.38	31.10	188.98
481. Paint the walls - two coats	308.67 SF		0.00	1.36	6.82	83.96	510.57
482. Seal & paint baseboard - two coats	37.67 LF		0.00	2.24	0.42	16.88	101.68
483. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
484. Mask the floor per square foot - plastic and tape - 4 mil	84.51 SF		0.00	0.35	0.43	5.92	35.93
485. Final cleaning - construction - Residential	84.51 SF		0.00	0.34	0.00	5.74	34.47
Totals: Master Bath					10.51	152.74	926.94
Total: 1413					<b>10.51</b>	<b>152.74</b>	<b>926.94</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Total: Building 1 Interiors 2,116.55    19,215.28    117,405.89

### Gym/Clubhouse

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
486. Paint the surface area - two coats <i>Entry</i>	429.00 SF		0.00	1.36	9.49	116.68	709.61
487. Drywall patch / small repair, ready for paint <i>Entry</i>	1.00 EA		0.00	89.02	0.33	17.80	107.15
488. Paint the surface area - two coats <i>Cardio Room</i>	1,196.00 SF		0.00	1.36	26.44	325.32	1,978.32
489. Paint baseboard, oversized - two coats <i>Cardio Room</i>	90.00 LF		0.00	2.29	1.72	41.22	249.04
490. Paint the surface area - two coats <i>Cardio Room</i>	80.00 SF		0.00	1.36	1.77	21.76	132.33
491. Carpet Installer - per hour <i>Cardio Room</i>	2.00 HR		0.00	90.00	0.00	36.00	216.00
492. 5/8" drywall - hung, taped, floated, ready for paint <i>Pedicure Room</i>	460.00 SF		0.00	2.87	30.97	264.04	1,615.21
493. In-wall / In-ceiling speaker <i>Pedicure Room</i>	1.00 EA		0.00	237.59	18.09	47.52	303.20
494. Recessed light fixture <i>Pedicure Room</i>	2.00 EA		0.00	121.50	7.07	48.60	298.67
495. Paint the surface area - two coats <i>Pedicure Room</i>	576.00 SF		0.00	1.36	12.74	156.68	952.78
496. Seal the surface area w/latex based stain blocker - one coat <i>Pedicure Room</i>	144.00 SF		0.00	0.91	1.01	26.20	158.25
497. Cleaning Technician - per hour <i>Final construction cleaning.</i>	10.00 HR		0.00	53.50	0.00	107.00	642.00
Totals: Gym/Clubhouse					109.63	1,208.82	7,362.56

### Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
498. 5/8" - drywall per LF - up to 2' tall	216.00 LF		0.00	11.45	30.83	494.64	2,998.67
499. 5/8" drywall - hung, taped, floated, ready for paint	902.00 SF		0.00	2.87	60.74	517.74	3,167.22
<i>Ceiling</i>							
500. Seal/prime then paint the surface area twice (3 coats)	45,816.00 SF		0.00	1.84	1,289.26	16,860.28	102,450.98
<i>Estimated allowance</i>							
501. Electrician - per hour	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
<i>Labor to detach and reset misc. to prep for painting.</i>							
502. Painter - per hour	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
<i>Misc labor to prep for paint.</i>							
503. Carpenter - General Framer - per hour	20.00 HR		0.00	72.00	0.00	288.00	1,728.00
<i>Labor to install drywall nailers.</i>							
Totals: Corridors/Hallways					1,380.83	19,427.10	117,943.55

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
504. Clean with pressure/chemical spray	43,760.00 SF		0.00	0.43	43.98	3,763.36	22,624.14
505. Exterior - paint two coats	43,760.00 SF		0.00	1.58	1,407.32	13,828.16	84,376.28
506. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
507. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
508. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
509. R&R Fascia - metal - 8"	374.00 LF		0.42	6.08	80.81	486.20	2,998.01
510. R&R Wall/roof panel - ribbed - 24 gauge - up to 1"	1,122.00 SF		0.63	5.38	332.64	1,348.66	8,424.52
<i>Allowance for parapet siding for flat roof replacement due to tie-in.</i>							
511. R&R Outside/Inside corner - 26 gauge	96.00 LF		1.72	6.04	29.14	148.98	923.08
512. R&R Window screen, 1 - 9 SF	48.00 EA		4.74	36.30	151.23	393.98	2,515.13
513. Reglaze window, 1 - 9 sf	3.00 EA		0.00	78.39	11.93	47.04	294.14



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
514. R&R Exterior post light fixture - High grade	2.00 EA		47.46	258.57	29.55	122.40	764.01
515. Paint casing - one coat	20.00 LF		0.00	1.44	0.20	5.76	34.76
516. R&R Gutter / downspout - aluminum - 7" to 8"	140.00 LF		0.63	17.54	184.60	508.76	3,237.16
<b>120 LF Downspout</b>							
<b>20 LF Gutters</b>							
517. R&R Light fixture - wall sconce - High grade	2.00 EA		10.49	155.78	24.12	66.52	423.18
518. R&R Shutters - wood - louvered or paneled - Large	5.00 EA		7.86	358.97	131.66	366.84	2,332.65
<b>5 sets. Line item description states "Shutter set and installation labor. Labor cost to remove shutters and to discard in a job-site waste receptacle."</b>							
519. Seal & paint window shutters - per set	5.00 EA		0.00	46.58	2.72	46.58	282.20
520. Clean with pressure/chemical spray	112.00 SF		0.00	0.43	0.11	9.64	57.91
<b>Powerwash two (2) double doors.</b>							
521. R&R Soffit - vinyl	20.00 SF		0.38	5.81	4.36	24.76	152.92
Totals: Exteriors					2,578.59	25,075.48	153,031.35

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
567. Crane and operator - 14 ton capacity - 65' extension boom	80.00 HR						AS INCURRED
568. Telehandler/forklift and operator	80.00 HR						AS INCURRED
569. Scaffolding	43,760.00 SF		0.00	0.50	879.58	4,376.00	27,135.58
570. Commercial Supervision / Project Management - per hour	232.00 HR		0.00	68.91	0.00	3,197.42	19,184.54
571. General Laborer - per hour	560.00 HR		0.00	37.61	0.00	4,212.32	25,273.92
572. Temporary toilet (per month)	8.00 MO						AS INCURRED
573. Temporary power usage (per month) - Commercial	2.00 MO		0.00	197.34	39.67	78.94	513.29
574. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
575. Light bulb - Incand. standard bulb - 1000 hr - mat. only	45.00 EA		0.00	0.79	3.57	7.12	46.24
<b>Assuming three (3) lights per fixture.</b>							
576. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - GENERAL CONDITIONS


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
577. OSHA compliance safety monitor- per hour	HR						AS INCURRED
578. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
579. Overhead safety monitor - per hour	HR						AS INCURRED
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
580. Taxes, insurance, permits & fees (Bid Item)	1.00 EA						AS INCURRED
Totals: GENERAL CONDITIONS					923.32	11,987.14	72,846.09
Total: SAULET-BLDG-01-V5_23					<b>7,108.92</b>	<b>76,913.82</b>	<b>468,589.44</b>

### SAULET-BLDG-02-V5\_23

#### Building 2 Interiors

#### Main Level

#### 2102



#### Kitchen

Height: 9'

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
581. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
582. Paint the walls and ceiling - two coats	522.56 SF		0.00	1.36	11.55	142.14	864.37
583. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
584. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					12.85	185.98	1,128.65



**Living / Dining Room**

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
585. 5/8" drywall - hung, taped, floated, ready for paint <i>Double Layer</i>	120.00 SF		0.00	2.87	8.08	68.88	421.36
586. Blown-in insulation - 10" depth - R26	384.72 SF		0.00	1.12	29.00	86.18	546.07
587. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
588. Paint the walls - two coats	655.11 SF		0.00	1.36	14.48	178.20	1,083.63
589. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
590. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
591. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
592. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living / Dining Room					84.42	817.96	4,992.04



**Utility Room**

**Height: 9'**

216.22 SF Walls	40.89 SF Ceiling
257.11 SF Walls & Ceiling	40.89 SF Floor
4.54 SY Flooring	23.33 LF Floor Perimeter
26.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>							
				<b>2' 8" X 6' 8"</b>			
							<b>Opens into LIVING__DIN</b>
593. 5/8" drywall - hung, taped, floated, ready for paint <i>Double Layer</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
594. Seal/prime then paint the surface area twice (3 coats)	45.00 SF		0.00	1.84	1.27	16.56	100.63
595. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	40.89 SF		0.00	1.12	3.08	9.16	58.04
596. Mask the floor per square foot - plastic and tape - 4 mil	40.89 SF		0.00	0.35	0.21	2.86	17.38
597. Final cleaning - construction - Residential	40.89 SF		0.00	0.34	0.00	2.78	16.68
Totals: Utility Room					5.37	38.24	234.86

**2103**



**Bedroom**

**Height: 8'**

316.11 SF Walls	138.06 SF Ceiling
454.17 SF Walls & Ceiling	138.06 SF Floor
15.34 SY Flooring	40.42 LF Floor Perimeter
47.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>							
				<b>3' 8" X 6' 8"</b>			
							<b>Opens into WALKIN_CLOS</b>
<b>Door</b>							
				<b>2' 11" X 6' 8"</b>			
							<b>Opens into LIVING__DIN</b>
<b>Window</b>							
				<b>4' X 4'</b>			
							<b>Opens into Exterior</b>




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
598. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	144.00 SF		0.00	2.87	9.70	82.66	505.64
599. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	138.06 SF		0.00	1.12	10.41	30.92	195.96
600. Seal/prime then paint the ceiling twice (3 coats)	138.06 SF		0.00	1.84	3.89	50.80	308.72
601. Mask the floor per square foot - plastic and tape - 4 mil	138.06 SF		0.00	0.35	0.69	9.66	58.67
602. Final cleaning - construction - Residential	138.06 SF		0.00	0.34	0.00	9.38	56.32
<b>Totals: Bedroom</b>					<b>24.69</b>	<b>183.42</b>	<b>1,125.31</b>



### Kitchen

**Height: 8'**

230.00 SF Walls	80.06 SF Ceiling
310.06 SF Walls & Ceiling	80.06 SF Floor
8.90 SY Flooring	26.33 LF Floor Perimeter
40.83 LF Ceil. Perimeter	


<b>Door</b>	<b>4' 2" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into WORKSPACE__</b>
<b>Door</b>	<b>1' 9" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
603. Paint the walls and ceiling - two coats	310.06 SF		0.00	1.36	6.86	84.34	512.88
604. Seal & paint baseboard - two coats	26.33 LF		0.00	2.24	0.29	11.80	71.07
605. Mask the floor per square foot - plastic and tape - 4 mil	80.06 SF		0.00	0.35	0.40	5.60	34.02
606. Final cleaning - construction - Residential	80.06 SF		0.00	0.34	0.00	5.44	32.66
<b>Totals: Kitchen</b>					<b>7.55</b>	<b>107.18</b>	<b>650.63</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 8'**

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
607. Paint the walls and ceiling - two coats	743.06 SF		0.00	1.36	16.43	202.12	1,229.11
608. Seal & paint baseboard - two coats	62.17 LF		0.00	2.24	0.69	27.86	167.81
609. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
610. Mask the floor per square foot - plastic and tape - 4 mil	276.89 SF		0.00	0.35	1.39	19.38	117.68
611. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
<b>Totals: Living / Dining Room</b>					<b>19.42</b>	<b>286.46</b>	<b>1,738.17</b>
<b>Total: 2103</b>					<b>51.66</b>	<b>577.06</b>	<b>3,514.11</b>
<b>Total: 2102</b>					<b>154.30</b>	<b>1,619.24</b>	<b>9,869.66</b>

2107



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
612. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	56.00 SF		0.00	2.87	3.77	32.14	196.63
613. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	136.58 SF		0.00	1.12	10.30	30.60	193.87
614. Seal/prime then paint the ceiling twice (3 coats)	136.58 SF		0.00	1.84	3.84	50.26	305.41
615. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
616. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
617. Seal/prime then paint the ceiling twice (3 coats) <i>Ceiling</i>	136.58 SF		0.00	1.84	3.84	50.26	305.41
618. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
619. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>30.95</b>	<b>306.94</b>	<b>1,872.60</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
620. 5/8" drywall - hung, taped, floated, ready for paint	4.00 SF		0.00	2.87	0.27	2.30	14.05
<i>Walls</i>							
621. Batt insulation - 6" - R19 - unfaced batt	4.00 SF		0.00	1.07	0.26	0.86	5.40
<i>Walls</i>							
622. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
<i>Paint and blend (walls).</i>							
623. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
624. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
625. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
626. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>33.39</b>	<b>487.86</b>	<b>2,960.43</b>

2108



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	


- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN2**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DIN**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN2**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
627. 5/8" drywall - hung, taped, floated, ready for paint	24.00 SF		0.00	2.87	1.62	13.78	84.28
<i>Island</i>							
628. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
<i>Walls</i>							
629. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
630. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
631. Base shoe	12.00 LF		0.00	1.41	0.60	3.38	20.90
632. Seal & paint base shoe or quarter round	53.92 LF		0.00	1.19	0.60	12.84	77.60
633. Toe kick - pre-finished wood - 1/2"	6.00 LF		0.00	9.57	2.57	11.48	71.47
634. Mask the walls per square foot - plastic and tape - 4 mil	356.25 SF		0.00	0.35	1.79	24.94	151.42
635. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
<b>Totals: Kitchen</b>					<b>22.82</b>	<b>280.38</b>	<b>1,705.01</b>
<b>Total: 2108</b>					<b>22.82</b>	<b>280.38</b>	<b>1,705.01</b>
<b>Total: 2107</b>					<b>87.16</b>	<b>1,075.18</b>	<b>6,538.04</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
636. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
637. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	150.00 SF		0.00	2.87	10.10	86.10	526.70
638. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	282.90 SF		0.00	1.84	7.96	104.10	632.60
639. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
640. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
641. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					23.57	225.84	1,378.67



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
642. Blown-in insulation - 10" depth - R26	154.68 SF		0.00	1.12	11.66	34.64	219.54




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
643. 5/8" drywall - hung, taped, floated, ready for paint	122.00 SF		0.00	2.87	8.21	70.02	428.37
<i>Ceiling</i>							
644. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
<i>Ceiling</i>							
<i>Wall</i>							
645. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
646. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
647. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
648. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>36.88</b>	<b>358.62</b>	<b>2,188.73</b>



**Entry**

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
649. Batt insulation - 8" - R25 - unfaced batt	40.00 SF		0.00	1.43	3.26	11.44	71.90
<i>Ceiling</i>							
650. 5/8" drywall - hung, taped, floated, ready for paint	85.00 SF		0.00	2.87	5.72	48.80	298.47
<i>Ceiling</i>							
651. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Entry**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
<i>Wall</i>							
652. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
653. Base shoe	6.00 LF		0.00	1.41	0.30	1.70	10.46
654. Seal & paint baseboard - two coats	6.00 LF		0.00	2.24	0.07	2.68	16.19
655. Seal & paint base shoe or quarter round	6.00 LF		0.00	1.19	0.07	1.42	8.63
656. Casing - 2 1/4"	20.00 LF		0.00	2.23	2.33	8.92	55.85
657. Seal & paint casing - two coats	20.00 LF		0.00	2.26	0.26	9.04	54.50
658. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
659. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
660. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>20.88</b>	<b>166.10</b>	<b>1,017.46</b>

**2112**



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
661. 5/8" drywall - hung, taped, floated, ready for paint	24.00 SF		0.00	2.87	1.62	13.78	84.28




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Walls</i>							
662. Seal/prime then paint the walls twice (3 coats)	498.90 SF		0.00	1.84	14.04	183.60	1,115.62
<i>Walls</i>							
663. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
664. Base shoe	6.00 LF		0.00	1.41	0.30	1.70	10.46
665. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
666. Seal & paint base shoe or quarter round	63.08 LF		0.00	1.19	0.70	15.02	90.79
667. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
668. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
669. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>21.03</b>	<b>316.80</b>	<b>1,921.79</b>



**Kitchen**

**Height: 8'**

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **2' 3" X 4'**      **Opens into KITCHEN**
- Missing Wall**      **14' 2 1/16" X 8'**      **Opens into LIVING\_\_DIN**
- Door**      **1' 10" X 6' 8"**      **Opens into CLOSET**
- Door**      **1' 11" X 6' 8"**      **Opens into PANTRY**
- Door**      **3' X 6' 8"**      **Opens into Exterior**
- Missing Wall - Goes to Ceiling**      **7' 6" X 4'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
670. Seal/prime then paint the walls twice (3 coats)	367.67 SF		0.00	1.84	10.35	135.30	822.16
671. Seal & paint baseboard - two coats	54.92 LF		0.00	2.24	0.61	24.60	148.23
672. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
673. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					11.73	181.18	1,098.80



### Hall Bathroom

Height: 8'

240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

**Door** 1' 6" X 6' 8" Opens into LINEN\_CLOSET  
**Door** 2' 8" X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
674. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	24.00 SF		0.00	2.87	1.62	13.78	84.28
675. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	57.36 SF		0.00	1.12	4.32	12.84	81.40
676. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	297.58 SF		0.00	1.84	8.37	109.52	665.44
677. Mask the floor per square foot - plastic and tape - 4 mil	57.36 SF		0.00	0.35	0.29	4.02	24.39
678. Final cleaning - construction - Residential	57.36 SF		0.00	0.34	0.00	3.90	23.40

Totals: Hall Bathroom 14.60 144.06 878.91

Total: 2112 47.36 642.04 3,899.50


Total: 2111 128.69 1,392.60 8,484.36

2115



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bathroom**

**Height: 9'**

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	

**Door** 1' 5" X 6' 8" Opens into LINEN\_CLOSET  
**Door** 2' 8" X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
679. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling above shower</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
680. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	53.06 SF		0.00	1.12	4.00	11.88	75.31
681. Seal/prime then paint the walls and ceiling twice (3 coats)	319.83 SF		0.00	1.84	9.00	117.70	715.19
682. Mask the floor per square foot - plastic and tape - 4 mil	53.06 SF		0.00	0.35	0.27	3.72	22.56
683. Seal & paint baseboard - two coats	28.58 LF		0.00	2.24	0.32	12.80	77.14
684. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
685. Final cleaning - construction - Residential	53.06 SF		0.00	0.34	0.00	3.60	21.64
<b>Totals: Bathroom</b>					<b>14.86</b>	<b>165.72</b>	<b>1,009.28</b>
<b>Total: 2115</b>					<b>14.86</b>	<b>165.72</b>	<b>1,009.28</b>
<b>Total: Main Level</b>					<b>385.01</b>	<b>4,252.74</b>	<b>25,901.34</b>

2106



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**


**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
686. Paint the walls - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79
687. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					8.22	111.62	677.90



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
688. 5/8" - drywall per LF - up to 2' tall	11.17 LF		0.00	11.45	1.59	25.58	155.07
689. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
690. Seal/prime then paint the walls twice (3 coats)	118.00 SF		0.00	1.84	3.32	43.42	263.86
691. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
692. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
693. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Entry**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
694. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
695. Batt insulation - 4" - R13 - unfaced batt	6.00 SF		0.00	0.83	0.29	1.00	6.27
696. Baseboard - 4 1/4"	3.25 LF		0.00	4.14	0.66	2.70	16.82
697. Casing - 2 1/4"	7.00 LF		0.00	2.23	0.82	3.12	19.55
698. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>8.17</b>	<b>138.90</b>	<b>841.54</b>
<b>Total: 2106</b>					<b>16.39</b>	<b>250.52</b>	<b>1,519.44</b>

**2202**



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
699. Paint the ceiling - two coats	136.58 SF		0.00	1.36	3.02	37.16	225.93
<i>Paint and blend</i>							
700. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
701. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>3.69</b>	<b>55.52</b>	<b>336.73</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
702. Paint the ceiling - two coats <i>Paint and blend</i>	384.72 SF		0.00	1.36	8.51	104.64	636.37
703. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
704. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96

Totals: Living / Dining Room 10.44    157.74    956.85


Total: 2202 **14.13    213.26    1,293.58**

**2209**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>17' X 9'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
705. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	2.00 SF		0.00	2.87	0.13	1.14	7.01
706. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint &amp; blend</i>	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
707. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
708. Base shoe	6.00 LF		0.00	1.41	0.30	1.70	10.46
709. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
710. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
711. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
712. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
713. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>24.57</b>	<b>357.74</b>	<b>2,171.01</b>
<b>Total: 2209</b>					<b>24.57</b>	<b>357.74</b>	<b>2,171.01</b>

2211



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**


**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
714. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
715. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	91.00 SF		0.00	2.87	6.13	52.24	319.54
716. Seal/prime then paint the ceiling twice (3 coats) <i>Ceiling</i>	64.74 SF		0.00	1.84	1.82	23.82	144.76
717. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
718. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
719. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
720. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>13.16</b>	<b>130.02</b>	<b>793.20</b>



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Entry**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
721. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	6.00 SF		0.00	2.87	0.40	3.44	21.06
722. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
723. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
724. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
725. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
726. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>5.66</b>	<b>81.68</b>	<b>495.71</b>
<b>Total: 2211</b>					<b>18.82</b>	<b>211.70</b>	<b>1,288.91</b>

**2213**



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
727. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
728. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	376.68 SF		0.00	1.12	28.39	84.38	534.65
729. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	875.58 SF		0.00	1.84	24.64	322.22	1,957.93
730. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
731. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>55.73</b>	<b>465.46</b>	<b>2,848.49</b>



**Kitchen**

**Height: 8'**

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>2' 3" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 11" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Missing Wall</b>	<b>14' 2 1/16" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 6" X 4'</b>	<b>Opens into KITCHEN</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
732. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	525.18 SF		0.00	1.84	14.78	193.26	1,174.37
733. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
734. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
<b>Totals: Kitchen</b>					<b>15.55</b>	<b>214.54</b>	<b>1,302.78</b>

<b>Total: 2213</b>					<b>71.28</b>	<b>680.00</b>	<b>4,151.27</b>
--------------------	--	--	--	--	--------------	---------------	-----------------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 9'**

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
735. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint and blend</i>	612.61 SF		0.00	1.84	17.24	225.44	1,369.88
736. Seal & paint baseboard - two coats	50.50 LF		0.00	2.24	0.56	22.62	136.30
737. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
738. Mask the floor per square foot - plastic and tape - 4 mil	161.67 SF		0.00	0.35	0.81	11.32	68.71
739. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
<b>Totals: Master Bedroom</b>					<b>19.52</b>	<b>288.66</b>	<b>1,751.47</b>
<b>Total: 2307</b>					<b>19.52</b>	<b>288.66</b>	<b>1,751.47</b>

**2308**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

369.50 SF Walls	146.76 SF Ceiling
516.26 SF Walls & Ceiling	142.34 SF Floor
15.82 SY Flooring	53.83 LF Floor Perimeter
34.83 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Missing Wall</b>	<b>17' X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
740. Detach & Reset Door lockset - exterior	1.00 EA	23.06	0.00	0.00	0.00	4.62	27.68
741. Steel door, 3' x 7' - fire rated	1.00 EA		0.00	567.29	51.51	113.46	732.26
742. Steel door frame - 8' opening	1.00 EA		0.00	313.62	24.64	62.72	400.98
743. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
744. Paint door or window opening - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
745. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
746. Seal/prime then paint the walls and ceiling twice (3 coats)	516.26 SF		0.00	1.84	14.53	189.98	1,154.43
747. Seal & paint baseboard - two coats	53.83 LF		0.00	2.24	0.59	24.12	145.29
748. Mask the floor per square foot - plastic and tape - 4 mil	142.34 SF		0.00	0.35	0.72	9.96	60.50
749. Final cleaning - construction - Residential	142.34 SF		0.00	0.34	0.00	9.68	58.08
<b>Totals: Kitchen</b>					<b>94.52</b>	<b>455.22</b>	<b>2,825.89</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall

17' X 9'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Door

4' X 6' 8"

Opens into Exterior

Window

4' X 4'

Opens into Exterior

Missing Wall

1' 1" X 9'

Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
750. Paint the walls and ceiling - two coats	704.18 SF		0.00	1.36	15.57	191.54	1,164.79
751. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
752. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
753. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
754. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16


Totals: Living / Dining Room

18.48 271.56 1,647.78

Total: 2308

113.00 726.78 4,473.67

2310



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
755. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
756. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
757. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
758. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
759. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					7.35	107.22	650.73



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
760. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	60.00 SF		0.00	2.87	4.04	34.44	210.68
761. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
762. Crown molding - 2 1/4"	11.00 LF		0.00	3.77	1.30	8.30	51.07
763. Seal & paint crown molding - two coats	40.67 LF		0.00	2.24	0.57	18.22	109.89
764. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
765. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	36.00 SF		0.00	1.07	2.32	7.70	48.54
766. Base shoe	11.00 LF		0.00	1.41	0.55	3.10	19.16
767. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
768. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
769. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
770. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
771. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
772. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					39.56	379.00	2,313.68
Total: 2310					<b>46.91</b>	<b>486.22</b>	<b>2,964.41</b>

2311



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
773. Paint the ceiling - two coats	64.74 SF		0.00	1.36	1.43	17.62	107.10
774. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
775. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					1.76	26.56	161.04



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**


**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
776. Detach & Reset Hanging light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03	
777. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	32.00 SF		0.00	2.87	2.15	18.36	112.35	
778. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54	
779. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99	
780. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74	
781. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11	
<b>Totals: Living Room</b>						29.40	278.22	1,698.76



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
782. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
783. Detach & Reset Exhaust fan	1.00 EA	184.31	0.00	0.00	0.00	36.86	221.17
784. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	28.00 SF		0.00	2.87	1.89	16.08	98.33
785. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	40.83 SF		0.00	1.12	3.08	9.14	57.95
786. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
787. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
788. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
789. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					10.56	154.64	938.29
Total: 2311					<b>41.72</b>	<b>459.42</b>	<b>2,798.09</b>

2312



### Bedroom 1

Height: 8'

373.33 SF Walls	133.90 SF Ceiling
507.23 SF Walls & Ceiling	133.90 SF Floor
14.88 SY Flooring	45.50 LF Floor Perimeter
52.50 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into BEDROOM_1_WA</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
790. 5/8" drywall - hung, taped, floated, ready for paint <i>Double Layer</i>	154.00 SF		0.00	2.87	10.37	88.40	540.75
791. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	133.90 SF		0.00	1.12	10.09	30.00	190.06
792. Seal/prime then paint the walls and ceiling twice (3 coats)	507.23 SF		0.00	1.84	14.27	186.66	1,134.23




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom 1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
793. Mask the floor per square foot - plastic and tape - 4 mil	133.90 SF		0.00	0.35	0.67	9.38	56.92
794. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
Totals: Bedroom 1					35.40	323.54	1,976.59



**Hall Bathroom**

**Height: 8'**

240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
795. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
796. Seal/prime then paint the walls twice (3 coats)	240.22 SF		0.00	1.84	6.76	88.40	537.16
797. Seal & paint baseboard - two coats	29.33 LF		0.00	2.24	0.32	13.14	79.16
798. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
799. Final cleaning - construction - Residential	57.36 SF		0.00	0.34	0.00	3.90	23.40
Totals: Hall Bathroom					7.99	133.90	811.36


Total: 2312					<b>43.39</b>	<b>457.44</b>	<b>2,787.95</b>
-------------	--	--	--	--	--------------	---------------	-----------------

2313



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 8'**


498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
800. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	4.00 SF		0.00	2.87	0.27	2.30	14.05
801. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint &amp; blend</i>	875.58 SF		0.00	1.84	24.64	322.22	1,957.93
802. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
803. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>26.80</b>	<b>376.50</b>	<b>2,285.76</b>

### Hall Bathroom

**Height: 8'**



240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Hall Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
804. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	18.00 SF		0.00	2.87	1.21	10.34	63.21
805. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	57.36 SF		0.00	1.12	4.32	12.84	81.40
806. Seal/prime then paint the walls and ceiling twice (3 coats)	297.58 SF		0.00	1.84	8.37	109.52	665.44
807. Mask the floor per square foot - plastic and tape - 4 mil	57.36 SF		0.00	0.35	0.29	4.02	24.39
808. Final cleaning - construction - Residential	57.36 SF		0.00	0.34	0.00	3.90	23.40
Totals: Hall Bathroom					14.19	140.62	857.84
Total: 2313					<b>40.99</b>	<b>517.12</b>	<b>3,143.60</b>

2410



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
809. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
810. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
811. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
812. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					6.89	98.08	595.42



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
813. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	162.00 SF		0.00	2.87	10.91	92.98	568.83	
814. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54	
815. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Walls</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99	
816. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	60.00 SF		0.00	1.07	3.86	12.84	80.90	
817. Baseboard - 3 1/4"	46.08 LF		0.00	3.49	6.72	32.16	199.70	
818. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37	
819. Clean and deodorize carpet	154.68 SF		0.00	0.57	0.00	17.64	105.81	
820. Chair rail - 2 1/2"	26.00 LF		0.00	3.05	3.37	15.86	98.53	
821. Seal & paint chair rail - two coats	46.08 LF		0.00	2.16	0.60	19.90	120.03	
822. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74	
823. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11	
<b>Totals: Living Room</b>						53.22	461.70	2,823.55
<b>Total: 2410</b>						<b>60.11</b>	<b>559.78</b>	<b>3,418.97</b>

**2412**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom 1

**Height: 8'**

373.33 SF Walls  
507.23 SF Walls & Ceiling  
14.88 SY Flooring  
52.50 LF Ceil. Perimeter

133.90 SF Ceiling  
133.90 SF Floor  
45.50 LF Floor Perimeter


**Door** 4' X 6' 8" Opens into BEDROOM\_1\_WA  
**Door** 3' X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
824. 5/8" drywall - hung, taped, floated, ready for paint	442.00 SF		0.00	2.87	29.76	253.70	1,552.00
825. Batt insulation - 6" - R19 - unfaced batt	184.00 SF		0.00	1.07	11.83	39.38	248.09
<i>Walls</i>							
826. Seal/prime then paint the walls and ceiling twice (3 coats)	507.23 SF		0.00	1.84	14.27	186.66	1,134.23
<i>Walls</i>							
<i>Double layer</i>							
827. Blown-in insulation - 10" depth - R26	133.90 SF		0.00	1.12	10.09	30.00	190.06
<i>Ceiling</i>							
828. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
<i>Ceiling</i>							
829. Seal & paint baseboard - two coats	45.50 LF		0.00	2.24	0.50	20.38	122.80
830. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
831. Mask the floor per square foot - plastic and tape - 4 mil	133.90 SF		0.00	0.35	0.67	9.38	56.92
832. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
<b>Totals: Bedroom 1</b>					<b>68.03</b>	<b>603.10</b>	<b>3,686.67</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom 2

**Height: 8'**

420.05 SF Walls	151.52 SF Ceiling
571.57 SF Walls & Ceiling	151.52 SF Floor
16.84 SY Flooring	56.01 LF Floor Perimeter
59.01 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
833. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	144.00 SF		0.00	2.87	9.70	82.66	505.64
834. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	36.00 SF		0.00	1.07	2.32	7.70	48.54
835. Seal/prime then paint the walls and ceiling twice (3 coats)	571.57 SF		0.00	1.84	16.08	210.34	1,278.11
836. Seal & paint baseboard - two coats	56.01 LF		0.00	2.24	0.62	25.10	151.18
837. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
838. Mask the floor per square foot - plastic and tape - 4 mil	151.52 SF		0.00	0.35	0.76	10.60	64.39
839. Final cleaning - construction - Residential	151.52 SF		0.00	0.34	0.00	10.30	61.82
<b>Totals: Bedroom 2</b>					<b>30.39</b>	<b>364.98</b>	<b>2,220.29</b>
<b>Total: 2412</b>					<b>98.42</b>	<b>968.08</b>	<b>5,906.96</b>
<b>Total: Building 2 Interiors</b>					<b>994.26</b>	<b>10,429.46</b>	<b>63,570.67</b>

### Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
840. 5/8" - drywall per LF - up to 2' tall	216.00 LF		0.00	11.45	30.83	494.64	2,998.67
841. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	451.00 SF		0.00	2.87	30.37	258.88	1,583.62
842. Seal/prime then paint the surface area twice (3 coats)	45,816.00 SF		0.00	1.84	1,289.26	16,860.28	102,450.98



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Estimated allowance</i>							
843. Electrician - per hour	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
<i>Labor to detach and reset misc to prep for paint.</i>							
844. Painter - per hour	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
<i>Misc labor to prep for paint.</i>							
845. Carpenter - General Framer - per hour	30.00 HR		0.00	72.00	0.00	432.00	2,592.00
<i>Labor to install drywall nailers.</i>							
Totals: Corridors/Hallways					1,350.46	19,312.24	117,223.95

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
846. Clean with pressure/chemical spray	43,760. SF 00		0.00	0.43	43.98	3,763.36	22,624.14
847. Exterior - paint two coats	43,760. SF 00		0.00	1.58	1,407.32	13,828.16	84,376.28
848. Electrician - per hour	100.00 HR		0.00	95.03	0.00	1,900.60	11,403.60
<i>Labor to detach and reset misc to prep for paint. Includes time to service distressed light post.</i>							
849. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
850. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
851. R&R Window screen, 1 - 9 SF	31.00 EA		4.74	36.30	97.67	254.44	1,624.35
852. R&R Gutter / downspout - aluminum - 7" to 8"	180.00 LF		0.63	17.54	237.34	654.12	4,162.06
<b>130 LF Downspout</b>							
<b>50 LF Gutters</b>							
853. R&R Light fixture - wall sconce - High grade	2.00 EA		10.49	155.78	24.12	66.52	423.18
854. R&R Shutters - wood - louvered or paneled - Large	2.00 EA		7.86	358.97	52.66	146.72	933.04
<b>2 sets. Line item description states "Shutter set and installation labor. Labor cost to remove shutters and to discard in a job-site waste receptacle."</b>							
855. Seal & paint window shutters - per set	2.00 EA		0.00	46.58	1.09	18.64	112.89
856. Clean with pressure/chemical spray	168.00 SF		0.00	0.43	0.17	14.44	86.85
<b>Powerwash three (3) double doors.</b>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Exteriors					2,008.57	23,034.36	140,214.77

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
898. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR					AS INCURRED	
899. Telehandler/forklift and operator	160.00 HR					AS INCURRED	
900. Scaffold -	43,760. SF 00		0.00	0.50	0.00	4,376.00	26,256.00
901. Commercial Supervision / Project Management - per hour	192.00 HR		0.00	68.91	0.00	2,646.14	15,876.86
902. General Laborer - per hour	512.00 HR		0.00	37.61	0.00	3,851.26	23,107.58
903. Temporary toilet (per month)	12.00 MO					AS INCURRED	
904. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
905. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
906. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
907. OSHA compliance safety monitor- per hour	HR					AS INCURRED	
908. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
909. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs. Eight (8) hours per day, five (5) days a week during the eight (8) week repair schedule for these trades.</i>							
910. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
911. Light bulb - Incand. standard bulb - 1000 hr - mat. only	1.00 EA		0.00	0.79	0.08	0.16	1.03
Totals: GENERAL CONDITIONS					60.08	11,107.30	66,703.91
Total: SAULET-BLDG-02-V5_23					4,413.37	63,883.36	387,713.30

### SAULET-BLDG-03-V5\_23


#### Building 3 Interiors

3103



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 8'**

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN2</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM2</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DI2</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
912. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
913. Seal/prime then paint the ceiling twice (3 coats)	277.94 SF		0.00	1.84	7.82	102.28	621.51
914. In-wall / In-ceiling speaker - Detach & reset	2.00 EA		0.00	18.44	0.00	7.38	44.26
915. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
916. Smoke detector - Detach & reset	2.00 EA		0.00	49.24	0.00	19.70	118.18
917. Seal & paint crown molding - two coats	74.00 LF		0.00	2.24	1.04	33.16	199.96
918. Detach & Reset Track lighting - track only	3.00 LF	9.84	0.00	0.00	0.00	5.90	35.42
919. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
920. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
921. Paint door/window trim & jamb - 2 coats (per side)	6.00 EA		0.00	45.71	2.74	54.86	331.86
922. Mask the floor per square foot - plastic and tape - 4 mil	276.89 SF		0.00	0.35	1.39	19.38	117.68
923. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
<b>Totals: Living / Dining Room</b>					<b>13.32</b>	<b>315.94</b>	<b>1,908.98</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Walk-in Closet

Height: 8'

130.22 SF Walls	22.36 SF Ceiling
152.58 SF Walls & Ceiling	22.36 SF Floor
2.48 SY Flooring	15.67 LF Floor Perimeter
19.33 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
924. 5/8" drywall - hung, taped, ready for texture	16.00 SF		0.00	2.53	1.06	8.10	49.64
925. Seal/prime then paint the ceiling twice (3 coats)	22.36 SF		0.00	1.84	0.63	8.22	49.99
926. Paint the walls - two coats	130.22 SF		0.00	1.36	2.88	35.42	215.40
927. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
928. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
929. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
930. Shelving - wire (vinyl coated) - Detach & reset	16.00 LF		0.00	9.66	0.00	30.92	185.48
931. Mask French door lites (per side of slab)	1.00 EA		0.00	77.74	0.10	15.54	93.38
932. Final cleaning - construction - Residential	22.36 SF		0.00	0.34	0.00	1.52	9.12
Totals: Walk-in Closet					8.11	161.56	977.45

Door

3' 8" X 6' 8"

Opens into BEDROOM2

DESCRIPTION

QTY

RESET

REMOVE

REPLACE

TAX

O&P

TOTAL

924. 5/8" drywall - hung, taped, ready for texture

16.00 SF

0.00

2.53

1.06

8.10

49.64

925. Seal/prime then paint the ceiling twice (3 coats)

22.36 SF

0.00

1.84

0.63

8.22

49.99

926. Paint the walls - two coats

130.22 SF

0.00

1.36

2.88

35.42

215.40

927. Light fixture - Detach & reset

1.00 EA

0.00

50.85

0.00

10.18

61.03

928. Paint door slab only - 2 coats (per side)

4.00 EA

0.00

53.15

2.98

42.52

258.10

929. Paint door/window trim & jamb - 2 coats (per side)

1.00 EA

0.00

45.71

0.46

9.14

55.31

930. Shelving - wire (vinyl coated) - Detach & reset

16.00 LF

0.00

9.66

0.00

30.92

185.48

931. Mask French door lites (per side of slab)

1.00 EA

0.00

77.74

0.10

15.54

93.38

932. Final cleaning - construction - Residential

22.36 SF

0.00

0.34

0.00

1.52

9.12

Totals: Walk-in Closet

8.11

161.56

977.45



### Bedroom

Height: 8'

316.11 SF Walls	138.06 SF Ceiling
454.17 SF Walls & Ceiling	138.06 SF Floor
15.34 SY Flooring	40.42 LF Floor Perimeter
47.00 LF Ceil. Perimeter	

Door

3' 8" X 6' 8"

Opens into WALKIN\_CLOS

Door

2' 11" X 6' 8"

Opens into LIVING\_\_DI2

Window

4' X 4'

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
933. 5/8" drywall - hung, taped, ready for texture	16.00 SF		0.00	2.53	1.06	8.10	49.64




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
934. Batt insulation - 4" - R13 - paper / foil faced	16.00 SF		0.00	1.07	1.16	3.42	21.70
935. Seal/prime then paint the walls and ceiling twice (3 coats)	454.17 SF		0.00	1.84	12.78	167.14	1,015.59
936. Baseboard - 4 1/4"	11.67 LF		0.00	4.14	2.37	9.66	60.34
937. Paint baseboard - two coats	40.42 LF		0.00	2.16	0.53	17.46	105.30
938. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
939. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
940. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	34.54	0.00	6.90	41.44
941. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
942. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
943. Mask the walls per square foot - plastic and tape - 4 mil	316.11 SF		0.00	0.35	1.59	22.12	134.35
944. Final cleaning - construction - Residential	138.06 SF		0.00	0.34	0.00	9.38	56.32
Totals: Bedroom					21.89	323.70	1,964.23



### Kitchen

Height: 8'

230.00 SF Walls	80.06 SF Ceiling
310.06 SF Walls & Ceiling	80.06 SF Floor
8.90 SY Flooring	26.33 LF Floor Perimeter
40.83 LF Ceil. Perimeter	

<b>Door</b>	<b>4' 2" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 9" X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into LIVING_DI2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
945. Seal/prime then paint the ceiling twice (3 coats)	80.06 SF		0.00	1.84	2.25	29.46	179.02
946. Mask the floor per square foot - plastic and tape - 4 mil	80.06 SF		0.00	0.35	0.40	5.60	34.02
947. Final cleaning - construction - Residential	80.06 SF		0.00	0.34	0.00	5.44	32.66




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					2.65	40.50	245.70



### Bathroom

Height: 8'

229.78 SF Walls	52.50 SF Ceiling
282.28 SF Walls & Ceiling	52.50 SF Floor
5.83 SY Flooring	28.00 LF Floor Perimeter
32.33 LF Ceil. Perimeter	


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>				<b>1' 6" X 6' 8"</b>			
<b>Door</b>				<b>2' 10" X 6' 8"</b>			
							<b>Opens into LINEN_CLOSET</b>
							<b>Opens into LIVING__DI2</b>
948. 1/2" water rock - hung, taped, floated, ready for paint	20.00 SF		0.00	2.88	1.41	11.52	70.53
949. Seal/prime then paint the walls and ceiling twice (3 coats)	282.28 SF		0.00	1.84	7.94	103.88	631.22
950. Baseboard - 4 1/4"	8.00 LF		0.00	4.14	1.62	6.62	41.36
951. Paint baseboard - two coats	28.00 LF		0.00	2.16	0.37	12.10	72.95
952. Casing - 2 1/4"	7.00 LF		0.00	2.23	0.82	3.12	19.55
953. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
954. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
955. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
956. Bathroom mirror - Detach & reset	20.00 SF		0.00	9.37	0.00	37.48	224.88
957. Towel bar - Detach & reset	1.00 EA		0.00	16.99	0.00	3.40	20.39
958. Bathroom ventilation fan - Detach & reset	1.00 EA		0.00	73.14	0.00	14.62	87.76
959. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
960. Final cleaning - construction - Residential	52.50 SF		0.00	0.34	0.00	3.58	21.43
Totals: Bathroom					16.05	271.06	1,642.37
Total: 3103					<b>62.02</b>	<b>1,112.76</b>	<b>6,738.73</b>

3107



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

Height: 9'

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
961. Paint the ceiling - two coats	161.67 SF		0.00	1.36	3.57	43.98	267.42
962. Mask the floor per square foot - plastic and tape - 4 mil	161.67 SF		0.00	0.35	0.81	11.32	68.71
963. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97

Totals: Master Bedroom 4.38      66.30      402.10

Total: 3107 **4.38      66.30      402.10**

**3109**



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
964. 5/8" drywall - hung, taped, floated, ready for paint	505.07 SF		0.00	2.87	34.01	289.92	1,773.48
965. Batt insulation - 6" - R19 - unfaced batt	375.72 SF		0.00	1.07	24.17	80.40	506.59
966. Blown-in insulation - 10" depth - R26	129.35 SF		0.00	1.12	9.75	28.98	183.60
967. Carpet	148.75 SF		0.00	3.67	40.21	109.18	695.30

*15 % waste added for Carpet.*

968. Carpet pad 129.35 SF      0.00      0.63      6.37      16.30      104.16




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
969. Baseboard - 3 1/4"	42.83 LF		0.00	3.49	6.24	29.90	185.62
970. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
971. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
972. Window sill	3.00 LF		0.00	3.12	0.27	1.88	11.51
973. Seal & paint window sill	4.00 LF		0.00	3.82	0.10	3.06	18.44
974. Outlet or switch cover	4.00 EA		0.00	3.06	0.35	2.44	15.03
975. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
976. Door knob/lockset - Detach & reset	1.00 EA		0.00	23.06	0.00	4.62	27.68
977. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
978. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
979. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
980. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
981. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					<b>172.95</b>	<b>947.82</b>	<b>5,859.72</b>



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN2**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DIN**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN2**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
982. 5/8" drywall - hung, taped, floated, ready for paint	326.00 SF		0.00	2.87	21.95	187.12	1,144.69



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
983. Blown-in insulation - 10" depth - R26	116.09 SF		0.00	1.12	8.75	26.00	164.77
<i>Ceiling</i>							
984. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
<i>Walls (fur down)</i>							
985. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
986. Cabinetry - upper (wall) units	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
987. Cabinetry - lower (base) units	10.00 LF		0.00	219.33	179.12	438.66	2,811.08
988. Batt insulation - 6" - R19 - unfaced batt	244.00 SF		0.00	1.07	15.69	52.22	328.99
<i>Walls</i>							
989. Baseboard - 3 1/4"	53.92 LF		0.00	3.49	7.86	37.64	233.68
990. Seal & paint baseboard - two coats	23.00 LF		0.00	2.24	0.25	10.30	62.07
991. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
992. Detach & Reset Range - freestanding - gas	1.00 EA	171.46	0.00	0.00	0.00	34.30	205.76
993. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
994. Countertop subdeck - plywood	25.00 SF		0.00	3.70	4.37	18.50	115.37
995. Install Sink - single - Detach & reset	1.00 EA		0.00	160.01	0.00	32.00	192.01
996. Detach & Reset Sink faucet - Kitchen	1.00 EA	128.34	0.00	0.00	0.00	25.66	154.00
997. Install Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
998. Countertop - solid surface	25.00 SF		0.00	64.30	112.31	321.50	2,041.31
999. Seal & paint base shoe or quarter round	53.92 LF		0.00	1.19	0.60	12.84	77.60
1,000. Base shoe	53.92 LF		0.00	1.41	2.71	15.20	93.94
1,001. Floor preparation for resilient flooring	111.67 SF		0.00	0.71	1.12	15.86	96.27
1,002. Vinyl plank flooring	111.67 SF		0.00	5.74	33.56	128.20	802.75
1,003. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
1,004. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					517.45	1,958.10	12,265.99



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Pantry

**Height: 9'**


63.50 SF Walls	4.17 SF Ceiling
67.67 SF Walls & Ceiling	4.17 SF Floor
0.46 SY Flooring	6.67 LF Floor Perimeter
8.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 6" X 6' 8"			Opens into KITCHEN2			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
1,005. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45	
<i>Ceiling</i>								
1,006. Blown-in insulation - 10" depth - R26	4.00 SF		0.00	1.12	0.30	0.90	5.68	
<i>Ceiling</i>								
<i>Walls</i>								
1,007. Batt insulation - 6" - R19 - unfaced batt	36.00 SF		0.00	1.07	2.32	7.70	48.54	
<i>Walls</i>								
1,008. Seal/prime then paint the walls and ceiling twice (3 coats)	67.67 SF		0.00	1.84	1.90	24.90	151.31	
1,009. Vinyl plank flooring	4.17 SF		0.00	5.74	1.25	4.78	29.97	
1,010. Floor preparation for resilient flooring	4.17 SF		0.00	0.71	0.04	0.60	3.60	
1,011. Base shoe	6.67 LF		0.00	1.41	0.34	1.88	11.62	
1,012. Seal & paint base shoe or quarter round	6.67 LF		0.00	1.19	0.07	1.58	9.59	
1,013. Seal & paint baseboard - two coats	6.67 LF		0.00	2.24	0.07	2.98	17.99	
1,014. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
1,015. Mask the floor per square foot - plastic and tape - 4 mil	4.17 SF		0.00	0.35	0.02	0.30	1.78	
1,016. Final cleaning - construction - Residential	4.17 SF		0.00	0.34	0.00	0.28	1.70	
<b>Totals: Pantry</b>					9.46	78.00	477.54	



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Closet

**Height: 9'**


198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"			Opens into BATHROOM				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	1,017. 5/8" drywall - hung, taped, floated, ready for paint	235.72 SF		0.00	2.87	15.87	135.30	827.69
	1,018. Batt insulation - 6" - R19 - unfaced batt	198.76 SF		0.00	1.07	12.78	42.54	267.99
	1,019. Blown-in insulation - 10" depth - R26	36.97 SF		0.00	1.12	2.79	8.28	52.48
	1,020. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
	1,021. Door knob/lockset - Detach & reset	1.00 EA		0.00	23.06	0.00	4.62	27.68
	1,022. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
	1,023. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
	1,024. Shelving - wire (vinyl coated)	25.00 LF		0.00	10.99	9.65	54.96	339.36
	1,025. Baseboard - 3 1/4"	21.39 LF		0.00	3.49	3.12	14.94	92.71
	1,026. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
	1,027. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
	1,028. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
	1,029. Floor preparation for resilient flooring	36.97 SF		0.00	0.71	0.37	5.26	31.88
	1,030. Vinyl plank flooring	36.97 SF		0.00	5.74	11.11	42.44	265.76
	1,031. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet						86.09	503.14	3,104.80



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom

**Height: 9'**

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	Door	2' 8" X 6' 8"	Opens into CLOSET
								Door	2' 8" X 6' 8"	Opens into HALLWAY
1,032. 5/8" drywall - hung, taped, floated, ready for paint	335.92 SF		0.00	2.87	22.62	192.82	1,179.53			
<i>Walls</i>										
1,033. Batt insulation - 6" - R19 - unfaced batt	271.97 SF		0.00	1.07	17.49	58.20	366.70			
<i>Walls</i>										
1,034. Baseboard - 3 1/4"	28.84 LF		0.00	3.49	4.20	20.14	124.99			
1,035. Seal & paint baseboard - two coats	28.84 LF		0.00	2.24	0.32	12.92	77.84			
1,036. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16			
1,037. Vinyl plank flooring	63.94 SF		0.00	5.74	19.21	73.40	459.63			
1,038. Base shoe	5.00 LF		0.00	1.41	0.25	1.42	8.72			
1,039. Seal & paint base shoe or quarter round	28.84 LF		0.00	1.19	0.32	6.86	41.50			
1,040. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64			
1,041. Vanity	4.00 LF		0.00	211.87	68.65	169.50	1,085.63			
1,042. Countertop - solid surface	8.00 SF		0.00	64.30	35.94	102.88	653.22			
1,043. Bath accessory	3.00 EA		0.00	28.55	4.55	17.14	107.34			
1,044. Fiberglass tub & shower combination	1.00 EA		0.00	1,109.55	56.90	221.92	1,388.37			
1,045. Mirror - 1/4" plate glass	9.00 SF		0.00	16.85	10.67	30.34	192.66			
1,046. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56			
1,047. Bathroom ventilation fan	1.00 EA		0.00	101.10	5.87	20.22	127.19			
1,048. Door knob/lockset - Detach & reset	2.00 EA		0.00	23.06	0.00	9.22	55.34			
1,049. Interior door unit	2.00 EA		0.00	269.19	41.87	107.68	687.93			
1,050. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05			



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,051. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,052. Angle stop valve	1.00 EA		0.00	36.26	0.72	7.26	44.24
<i>Ceiling</i>							
1,053. Blown-in insulation - 10" depth - R26	63.94 SF		0.00	1.12	4.82	14.32	90.75
<i>Ceiling</i>							
1,054. Sink - single	1.00 EA		0.00	274.65	15.92	54.94	345.51
1,055. Tub/shower faucet	1.00 EA		0.00	315.61	14.07	63.12	392.80
1,056. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
1,057. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
1,058. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
1,059. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,060. Outlet or switch - Detach & reset	4.00 EA		0.00	18.23	0.00	14.58	87.50
1,061. Bathroom ventilation fan - Detach & reset	1.00 EA		0.00	55.29	0.00	11.06	66.35
1,062. Floor preparation for resilient flooring	63.94 SF		0.00	0.71	0.64	9.08	55.12
1,063. Mask the floor per square foot - plastic and tape - 4 mil	63.94 SF		0.00	0.35	0.32	4.48	27.18
1,064. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
<b>Totals: Bathroom</b>					<b>357.91</b>	<b>1,532.06</b>	<b>9,550.05</b>

Entry	Height: 9'
124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	
<b>Door</b>	<b>3' X 6' 8"</b>
<b>Door</b>	<b>3' X 6' 8"</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>
	<b>Opens into Exterior</b>
	<b>Opens into UTILITY_ROOM</b>
	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,065. 5/8" drywall - hung, taped, floated, ready for paint	73.00 SF		0.00	2.87	4.92	41.90	256.33




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
1,066. Blown-in insulation - 10" depth - R26	28.58 SF		0.00	1.12	2.15	6.40	40.56
<i>Ceiling</i>							
1,067. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,068. Outlet or switch - Detach & reset	4.00 EA		0.00	18.23	0.00	14.58	87.50
<i>Walls</i>							
1,069. Batt insulation - 6" - R19 - unfaced batt	50.00 SF		0.00	1.07	3.22	10.70	67.42
<i>Walls</i>							
1,070. Seal/prime then paint the walls and ceiling twice (3 coats)	152.83 SF		0.00	1.84	4.30	56.24	341.75
<i>Walls</i>							
1,071. Casing - 2 1/4"	40.00 LF		0.00	2.23	4.66	17.84	111.70
1,072. Paint door/window trim & jamb - 1 coat (per side)	40.00 EA		0.00	30.78	13.39	246.24	1,490.83
1,073. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
1,074. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,075. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					37.01	433.42	2,637.69



### Utility Room

Height: 9'

322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

Door	3' X 6' 8"	Opens into ENTRY					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,076. 5/8" drywall - hung, taped, floated, ready for paint	68.00 SF		0.00	2.87	4.58	39.04	238.78
1,077. Baseboard - 3 1/4"	33.00 LF		0.00	3.49	4.81	23.04	143.02
1,078. Seal & paint baseboard - two coats	33.00 LF		0.00	2.24	0.36	14.78	89.06




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,079. Seal/prime then paint the walls and ceiling twice (3 coats)	368.15 SF		0.00	1.84	10.36	135.48	823.24
1,080. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,081. Mask the floor per square foot - plastic and tape - 4 mil	46.15 SF		0.00	0.35	0.23	3.24	19.62
1,082. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83
Totals: Utility Room					20.80	227.86	1,387.86



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall	12' 7" X 9'	Opens into KITCHEN2
Missing Wall	4' 1" X 9'	Opens into ENTRY
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	1' 1" X 9'	Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,083. 5/8" drywall - hung, taped, floated, ready for paint	499.00 SF		0.00	2.87	33.60	286.42	1,752.15
<i>Ceiling</i>							
1,084. Blown-in insulation - 10" depth - R26	78.00 SF		0.00	1.12	5.88	17.48	110.72
<i>Ceiling</i>							
1,085. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,086. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
1,087. Seal & Paint cove molding - three coats	53.00 LF		0.00	2.20	0.69	23.32	140.61
1,088. Baseboard - 3 1/4"	48.58 LF		0.00	3.49	7.08	33.90	210.52
1,089. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
1,090. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,091. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
1,092. Batt insulation - 6" - R19 - unfaced batt	119.00 SF		0.00	1.07	7.65	25.46	160.44
<i>Wall</i>							
1,093. Outlet or switch - Detach & reset	13.00 EA		0.00	18.23	0.00	47.40	284.39
1,094. Vinyl plank flooring	289.60 SF		0.00	5.74	87.02	332.46	2,081.78
1,095. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
<b>Totals: Living / Dining Room</b>					<b>174.03</b>	<b>1,129.06</b>	<b>6,948.36</b>
<b>Total: 3109</b>					<b>1,375.70</b>	<b>6,809.46</b>	<b>42,232.01</b>

**3112**



**Entry**

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,096. 5/8" drywall - hung, taped, floated, ready for paint	3.00 SF		0.00	2.87	0.20	1.72	10.53
<i>Ceiling</i>							
1,097. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							
1,098. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16
<i>Walls</i>							
1,099. Batt insulation - 6" - R19 - unfaced batt	14.00 SF		0.00	1.07	0.90	3.00	18.88




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Walls</i>							
1,100. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
<i>Walls</i>							
1,101. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
1,102. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
1,103. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,104. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
1,105. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					10.89	98.90	604.34



### Bedroom

**Height: 9'**


362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>					
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,106. Seal/prime then paint the walls and ceiling twice (3 coats)	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
1,107. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
1,108. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
Totals: Bedroom					14.20	186.30	1,132.07



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Bathroom**

**Height: 9'**

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>



**Subroom: Utility Room (1)**

**Height: 9'**


145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,109. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	18.00 SF		0.00	2.87	1.21	10.34	63.21
1,110. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	96.03 SF		0.00	1.12	7.24	21.52	136.31
1,111. Paint the walls and ceiling - two coats <i>Ceiling</i>	605.19 SF		0.00	1.36	13.38	164.62	1,001.06
1,112. Seal & paint baseboard - two coats	54.50 LF		0.00	2.24	0.60	24.42	147.10
1,113. Seal & paint base shoe or quarter round	54.50 LF		0.00	1.19	0.60	12.98	78.44
1,114. Mask the floor per square foot - plastic and tape - 4 mil	96.03 SF		0.00	0.35	0.48	6.72	40.81
1,115. Final cleaning - construction - Residential	96.03 SF		0.00	0.34	0.00	6.54	39.19
<b>Totals: Bathroom</b>					<b>23.51</b>	<b>247.14</b>	<b>1,506.12</b>
<b>Total: 3112</b>					<b>48.60</b>	<b>532.34</b>	<b>3,242.53</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,116. 5/8" drywall - hung, taped, floated, ready for paint	70.00 SF		0.00	2.87	4.71	40.18	245.79
<i>Ceiling</i>							
1,117. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
1,118. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
<i>Ceiling</i>							
1,119. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,120. Detach & Reset Cabinetry - lower (base) units	3.00 LF	69.68	0.00	0.00	0.00	41.80	250.84
1,121. Detach & Reset Countertop - post formed plastic laminate	6.00 LF	19.74	0.00	0.00	0.08	23.68	142.20
1,122. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
1,123. 5/8" drywall - hung, taped, floated, ready for paint	27.00 SF		0.00	2.87	1.82	15.50	94.81
<i>Walls</i>							
1,124. Batt insulation - 4" - R11- unfaced batt	15.00 SF		0.00	0.70	0.56	2.10	13.16
1,125. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
<i>Walls</i>							
1,126. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
1,127. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
1,128. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>38.48</b>	<b>419.22</b>	<b>2,553.96</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,129. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls and ceiling.</i>	180.00 SF		0.00	2.87	12.12	103.32	632.04
1,130. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
1,131. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	12.00 SF		0.00	1.07	0.77	2.56	16.17
1,132. Trim board - 1"x 8" to 1"x 12" - Detach & reset	46.08 LF		0.00	3.88	0.14	35.76	214.69
1,133. Base shoe	27.00 LF		0.00	1.41	1.36	7.62	47.05
1,134. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
1,135. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
1,136. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
1,137. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,138. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,139. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					43.57	448.82	2,736.62



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,140. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	44.00 SF		0.00	2.87	2.96	25.26	154.50
1,141. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	40.83 SF		0.00	1.12	3.08	9.14	57.95
1,142. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,143. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
1,144. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	158.83 SF		0.00	1.84	4.47	58.46	355.18
1,145. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	50.00 SF		0.00	2.87	3.37	28.70	175.57
1,146. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	3.00 SF		0.00	1.07	0.19	0.64	4.04
1,147. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	158.83 SF		0.00	1.84	4.47	58.46	355.18
1,148. Baseboard - 3 1/4"	9.00 LF		0.00	3.49	1.31	6.28	39.00
1,149. Base shoe	9.00 LF		0.00	1.41	0.45	2.54	15.68
1,150. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
1,151. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
1,152. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,153. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
1,154. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					24.98	238.64	1,456.77



### Closet

Height: 9'


76.28 SF Walls	6.03 SF Ceiling
82.31 SF Walls & Ceiling	6.03 SF Floor
0.67 SY Flooring	8.00 LF Floor Perimeter
9.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,155. Baseboard - 3 1/4"	8.00 LF		0.00	3.49	1.17	5.58	34.67
1,156. Seal & paint baseboard - two coats	8.00 LF		0.00	2.24	0.09	3.58	21.59
1,157. 5/8" drywall - hung, taped, floated, ready for paint	38.00 SF		0.00	2.87	2.56	21.82	133.44
<i>Walls</i>							
1,158. Seal/prime then paint the walls and ceiling twice (3 coats)	82.31 SF		0.00	1.84	2.32	30.30	184.07
1,159. Mask the floor per square foot - plastic and tape - 4 mil	6.03 SF		0.00	0.35	0.03	0.42	2.56
1,160. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,161. Final cleaning - construction - Residential	6.03 SF		0.00	0.34	0.00	0.42	2.47
Totals: Closet					6.63	71.26	434.11



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>				<b>2' 8" X 6' 8"</b>			
<b>Window</b>				<b>4' X 4'</b>			
							<b>Opens into BATHROOM</b>
							<b>Opens into Exterior</b>
1,162. 5/8" drywall - hung, taped, floated, ready for paint	86.00 SF		0.00	2.87	5.79	49.36	301.97
<i>Walls</i>							
1,163. Batt insulation - 6" - R19 - unfaced batt	22.00 SF		0.00	1.07	1.42	4.70	29.66
<i>Walls</i>							
1,164. Seal/prime then paint the walls twice (3 coats)	362.22 SF		0.00	1.84	10.19	133.30	809.97
<i>Walls</i>							
1,165. Paint the ceiling - two coats	120.89 SF		0.00	1.36	2.67	32.88	199.96
1,166. Baseboard - 3 1/4"	41.33 LF		0.00	3.49	6.02	28.84	179.10
1,167. Detach & Reset Casing - 2 1/4"	28.00 LF	2.04	0.00	0.00	0.06	11.42	68.60
1,168. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
1,169. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,170. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
1,171. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
<b>Totals: Bedroom</b>					28.13	313.98	1,912.13



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bathroom**


**Height: 9'**

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,172. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
<i>Walls</i>							
1,173. Baseboard - 3 1/4"	9.00 LF		0.00	3.49	1.31	6.28	39.00
1,174. Seal & paint baseboard - two coats	38.33 LF		0.00	2.24	0.42	17.18	103.46
1,175. Seal/prime then paint the walls and ceiling twice (3 coats)	444.82 SF		0.00	1.84	12.52	163.70	994.69
1,176. R&R Vanity	6.00 LF		9.45	211.87	102.97	265.58	1,696.47
1,177. Detach & Reset Toilet paper holder	1.00 EA	17.94	0.00	0.00	0.00	3.58	21.52
1,178. Seal & paint base shoe or quarter round	38.33 LF		0.00	1.19	0.42	9.12	55.15
1,179. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,180. Mask the floor per square foot - plastic and tape - 4 mil	81.15 SF		0.00	0.35	0.41	5.68	34.49
1,181. Final cleaning - construction - Residential	81.15 SF		0.00	0.34	0.00	5.52	33.11

Totals: Bathroom 119.86    497.26    3,103.43



**Utility Room**

**Height: 9'**

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,182. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,183. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
1,184. Seal/prime then paint the walls and ceiling twice (3 coats)	160.38 SF		0.00	1.84	4.51	59.02	358.63
1,185. Seal & paint baseboard - two coats	10.00 LF		0.00	2.24	0.11	4.48	26.99
1,186. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,187. Mask the floor per square foot - plastic and tape - 4 mil	14.88 SF		0.00	0.35	0.07	1.04	6.32
1,188. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
<b>Totals: Utility Room</b>					<b>7.96</b>	<b>93.16</b>	<b>566.90</b>
<b>Total: 3113</b>					<b>269.61</b>	<b>2,082.34</b>	<b>12,763.92</b>

### 3119



### Living / Dining Room

**Height: 8'**

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DI2</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,189. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
1,190. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
1,191. Paint the walls - two coats	465.11 SF		0.00	1.36	10.28	126.52	769.35




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,192. Seal & paint baseboard - two coats	62.17 LF		0.00	2.24	0.69	27.86	167.81
1,193. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,194. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
Totals: Living / Dining Room					12.93	197.80	1,199.62
Total: 3119					<b>12.93</b>	<b>197.80</b>	<b>1,199.62</b>

### 3203



#### Master Walk-in Closet

Height: 9'

216.67 SF Walls	36.80 SF Ceiling
253.47 SF Walls & Ceiling	36.80 SF Floor
4.09 SY Flooring	23.17 LF Floor Perimeter
26.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,195. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
1,196. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	253.47 SF		0.00	1.84	7.13	93.28	566.79
1,197. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
1,198. Seal & paint baseboard - two coats	23.17 LF		0.00	2.24	0.26	10.38	62.54
1,199. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,200. Mask the floor per square foot - plastic and tape - 4 mil	36.80 SF		0.00	0.35	0.18	2.58	15.64
1,201. Final cleaning - construction - Residential	36.80 SF		0.00	0.34	0.00	2.50	15.01
Totals: Master Walk-in Closet					9.96	132.16	802.86


3' 6" X 6' 8"

Opens into MASTER\_BATHR



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Utility Room

Height: 9'

184.94 SF Walls	24.32 SF Ceiling
209.26 SF Walls & Ceiling	24.32 SF Floor
2.70 SY Flooring	19.75 LF Floor Perimeter
22.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' 1" X 6' 8"			Opens into LIVING_ROOM			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
1,202. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34	
1,203. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42	
1,204. Seal & paint baseboard - two coats	19.75 LF		0.00	2.24	0.22	8.84	53.30	
1,205. Seal & paint base shoe or quarter round	10.00 LF		0.00	1.19	0.11	2.38	14.39	
1,206. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23	
<i>Wall</i>								
1,207. Seal/prime then paint the walls and ceiling twice (3 coats)	209.26 SF		0.00	1.84	5.89	77.00	467.93	
1,208. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
1,209. Mask the floor per square foot - plastic and tape - 4 mil	24.32 SF		0.00	0.35	0.12	1.70	10.33	
1,210. Final cleaning - construction - Residential	24.32 SF		0.00	0.34	0.00	1.66	9.93	
<b>Totals: Utility Room</b>					<b>10.11</b>	<b>122.00</b>	<b>742.18</b>	



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 8" X 6' 8"			Opens into LINEN_CLOSET			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
1,211. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13	
<i>Ceiling</i>								




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bathroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,212. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	79.85 SF		0.00	1.12	6.02	17.88	113.33
1,213. Seal/prime then paint the ceiling twice (3 coats) <i>Ceiling</i>	79.85 SF		0.00	1.84	2.25	29.38	178.55
1,214. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
1,215. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
<b>Totals: Bathroom</b>					<b>9.48</b>	<b>65.18</b>	<b>400.55</b>



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,216. R&R Cabinetry - lower (base) units <i>Kitchen</i>	9.00 LF		9.45	219.33	161.21	411.82	2,632.05
1,217. R&R Countertop - solid surface <i>Kitchen</i>	19.50 SF		5.43	64.30	87.60	271.96	1,719.30



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,218. R&R Cabinetry - upper (wall) units <i>Kitchen</i>	9.00 LF		9.45	152.53	100.79	291.58	1,850.19
1,219. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
1,220. 5/8" drywall - hung, taped, floated, ready for paint <i>Kitchen (Fur down)</i>	154.00 SF		0.00	2.87	10.37	88.40	540.75
1,221. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Kitchen (fur down)</i> <i>Wall (living room)</i>	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
1,222. Batt insulation - 6" - R19 - unfaced batt <i>Wall (living room)</i>	23.00 SF		0.00	1.07	1.48	4.92	31.01
1,223. Baseboard - 3 1/4"	22.00 LF		0.00	3.49	3.21	15.36	95.35
1,224. Seal & paint baseboard - two coats <i>Ceiling (Living Room)</i>	216.83 LF		0.00	2.24	2.40	97.14	585.24
1,225. Blown-in insulation - 10" depth - R26 <i>Ceiling (Living Room)</i>	486.47 SF		0.00	1.12	36.67	108.98	690.50
1,226. Base shoe	22.00 LF		0.00	1.41	1.11	6.20	38.33
1,227. Seal & paint base shoe or quarter round	216.83 LF		0.00	1.19	2.40	51.60	312.03
1,228. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
1,229. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,230. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>447.43</b>	<b>1,964.80</b>	<b>12,235.89</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Entry**

**Height: 9'**

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,231. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	2.00 SF		0.00	2.87	0.13	1.14	7.01
1,232. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint and blend (wall)</i>	82.01 SF		0.00	1.84	2.31	30.18	183.39
1,233. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
1,234. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,235. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
1,236. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
<b>Totals: Entry</b>					<b>3.52</b>	<b>55.04</b>	<b>333.90</b>
<b>Total: 3203</b>					<b>480.50</b>	<b>2,339.18</b>	<b>14,515.38</b>

**3205**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,237. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	60.00 SF		0.00	2.87	4.04	34.44	210.68
1,238. Batt insulation - 4" - R11-unfaced batt <i>Wall</i>	60.00 SF		0.00	0.70	2.23	8.40	52.63
1,239. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
1,240. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
1,241. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
1,242. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
1,243. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	522.56 SF		0.00	1.84	14.71	192.30	1,168.52
1,244. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
1,245. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>24.87</b>	<b>302.32</b>	<b>1,838.70</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bathroom

Height: 9'

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	

Door 1' 5" X 6' 8" Opens into LINEN\_CLOSET  
Door 2' 8" X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,246. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
1,247. Paint the ceiling - two coats	53.06 SF		0.00	1.36	1.17	14.44	87.77
1,248. Bathroom ventilation fan - Detach & reset	1.00 EA		0.00	73.14	0.00	14.62	87.76
1,249. Mask the walls per square foot - plastic and tape - 4 mil	266.78 SF		0.00	0.35	1.34	18.68	113.39
1,250. Final cleaning - construction - Residential	53.06 SF		0.00	0.34	0.00	3.60	21.64
Totals: Bathroom					2.84	69.14	417.71



### Bedroom 1

Height: 9'

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

Door 2' 8" X 6' 8" Opens into WALKIN\_CLOS  
Door 3' X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,251. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
<i>Ceiling</i>							
1,252. Blown-in insulation - 10" depth - R26	139.97 SF		0.00	1.12	10.55	31.36	198.68
<i>Ceiling</i>							
1,253. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
<i>Ceiling</i>							



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom 1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Wall</i>							
1,254. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
<i>Wall</i>							
1,255. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,256. Seal & paint baseboard - two coats	41.67 LF		0.00	2.24	0.46	18.66	112.46
1,257. Clean and deodorize carpet	139.97 SF		0.00	0.57	0.00	15.96	95.74
1,258. Mask the floor per square foot - plastic and tape - 4 mil	139.97 SF		0.00	0.35	0.70	9.80	59.49
1,259. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
<b>Totals: Bedroom 1</b>					29.34	311.16	1,896.22



**Living / Dining Room**

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,260. Seal/prime then paint the ceiling twice (3 coats)	384.72 SF		0.00	1.84	10.83	141.58	860.29
1,261. Detach & Reset Fluorescent light fixture	1.00 EA	73.82	0.00	0.00	0.00	14.76	88.58
1,262. Detach & Reset Hanging light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,263. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
1,264. Mask the walls per square foot - plastic and tape - 4 mil	655.11 SF		0.00	0.35	3.29	45.86	278.44
1,265. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					14.12	245.52	1,487.16
Total: 3205					<b>71.17</b>	<b>928.14</b>	<b>5,639.79</b>

**3208**

Kitchen		Height: 9'
	369.50 SF Walls	146.76 SF Ceiling
	516.26 SF Walls & Ceiling	142.34 SF Floor
	15.82 SY Flooring	53.83 LF Floor Perimeter
	34.83 LF Ceil. Perimeter	
Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN
Door	3' X 6' 8"	Opens into UTILITY_ROOM
Door	3' X 6' 8"	Opens into Exterior
Door	1' 6" X 6' 8"	Opens into PANTRY
Missing Wall	2' 4" X 9'	Opens into HALLWAY
Missing Wall	17' X 9'	Opens into LIVING__DIN
Missing Wall - Goes to Ceiling	7' 7" X 5'	Opens into KITCHEN
Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,266. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	53.00 SF		0.00	2.87	3.57	30.42	186.10
1,267. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	23.00 SF		0.00	1.12	1.73	5.16	32.65
1,268. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,269. Heat/AC register - Mechanically attached - Detach & reset <i>Walls</i>	1.00 EA		0.00	18.80	0.00	3.76	22.56




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,270. Base shoe	1.00 LF		0.00	1.41	0.05	0.28	1.74
1,271. Seal & paint baseboard - two coats	53.83 LF		0.00	2.24	0.59	24.12	145.29
1,272. Seal & paint base shoe or quarter round	53.83 LF		0.00	1.19	0.59	12.82	77.47
1,273. Seal/prime then paint the walls and ceiling twice (3 coats)	516.26 SF		0.00	1.84	14.53	189.98	1,154.43
1,274. Baseboard - 3 1/4"	1.00 LF		0.00	3.49	0.15	0.70	4.34
1,275. Seal & paint baseboard - two coats	53.83 LF		0.00	2.24	0.59	24.12	145.29
1,276. Mask the floor per square foot - plastic and tape - 4 mil	142.34 SF		0.00	0.35	0.72	9.96	60.50
1,277. Final cleaning - construction - Residential	142.34 SF		0.00	0.34	0.00	9.68	58.08
Totals: Kitchen					25.84	324.82	1,974.72
Total: 3208					<b>25.84</b>	<b>324.82</b>	<b>1,974.72</b>

**3209**



### Closet

**Height: 9'**

198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,278. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16
<i>Walls</i>							
1,279. Batt insulation - 6" - R19 - unfaced batt	14.00 SF		0.00	1.07	0.90	3.00	18.88
<i>Walls</i>							
1,280. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
1,281. Base shoe	7.00 LF		0.00	1.41	0.35	1.98	12.20
1,282. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,283. Seal & paint base shoe or quarter round	21.39 LF		0.00	1.19	0.24	5.10	30.79
1,284. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
1,285. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,286. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
1,287. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet					10.97	133.56	812.29



### Bedroom

Height: 9'

375.72 SF Walls  
505.07 SF Walls & Ceiling  
14.37 SY Flooring  
45.50 LF Ceil. Perimeter

129.35 SF Ceiling  
129.35 SF Floor  
42.83 LF Floor Perimeter

Window

4' X 4'

Opens into Exterior

Door

2' 8" X 6' 8"

Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,288. 5/8" drywall - hung, taped, floated, ready for paint	34.00 SF		0.00	2.87	2.29	19.52	119.39
<i>Walls</i>							
1,289. Baseboard - 3 1/4"	42.83 LF		0.00	3.49	6.24	29.90	185.62
1,290. Seal & paint baseboard - two coats	31.00 LF		0.00	2.24	0.34	13.88	83.66
1,291. Batt insulation - 6" - R19 - unfaced batt	14.00 SF		0.00	1.07	0.90	3.00	18.88
1,292. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
<i>Walls</i>							
1,293. Outlet or switch - Detach & reset	2.00 EA		0.00	18.23	0.00	7.30	43.76
1,294. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,295. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
1,296. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Bedroom					25.54	295.60	1,799.08



### Bathroom

Height: 9'

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	


Door	2' 8" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,297. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
<i>Walls</i>							
1,298. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
<i>Walls</i>							
1,299. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
1,300. Seal & paint baseboard - two coats	10.00 LF		0.00	2.24	0.11	4.48	26.99
1,301. Seal & paint base shoe or quarter round	10.00 LF		0.00	1.19	0.11	2.38	14.39
1,302. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16
<i>Walls</i>							
1,303. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
1,304. Mask the floor per square foot - plastic and tape - 4 mil	63.94 SF		0.00	0.35	0.32	4.48	27.18
1,305. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
Totals: Bathroom					14.59	164.86	1,003.76



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

369.50 SF Walls	146.76 SF Ceiling
516.26 SF Walls & Ceiling	142.34 SF Floor
15.82 SY Flooring	53.83 LF Floor Perimeter
34.83 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>17' X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,306. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	141.00 SF		0.00	2.87	9.49	80.94	495.10
1,307. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
1,308. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,309. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	516.26 SF		0.00	1.84	14.53	189.98	1,154.43
<i>Walls</i>							
1,310. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	29.00 SF		0.00	1.07	1.87	6.20	39.10
<i>Paint and blend (walls)</i>							
1,311. Seal & paint baseboard - two coats	53.83 LF		0.00	2.24	0.59	24.12	145.29
1,312. Mask the floor per square foot - plastic and tape - 4 mil	142.34 SF		0.00	0.35	0.72	9.96	60.50
1,313. Final cleaning - construction - Residential	142.34 SF		0.00	0.34	0.00	9.68	58.08
<b>Totals: Kitchen</b>					<b>27.20</b>	<b>351.40</b>	<b>2,135.57</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>17' X 9'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,314. 5/8" drywall - hung, taped, floated, ready for paint	120.00 SF		0.00	2.87	8.08	68.88	421.36
<i>Walls</i>							
1,315. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
1,316. Seal & paint baseboard - two coats	61.00 LF		0.00	2.24	0.67	27.32	164.63
1,317. Seal & paint base shoe or quarter round	61.00 LF		0.00	1.19	0.67	14.52	87.78
1,318. Batt insulation - 6" - R19 - unfaced batt	36.00 SF		0.00	1.07	2.32	7.70	48.54
1,319. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
<i>Walls</i>							
1,320. Outlet or switch - Detach & reset	1.00 EA		0.00	18.23	0.00	3.64	21.87
1,321. Baseboard - 3 1/4"	48.58 LF		0.00	3.49	7.08	33.90	210.52
1,322. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
1,323. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>42.54</b>	<b>468.78</b>	<b>2,855.25</b>
<b>Total: 3209</b>					<b>120.84</b>	<b>1,414.20</b>	<b>8,605.95</b>

**3210**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,324. 5/8" drywall - hung, taped, floated, ready for paint <i>Countertop column</i>	15.00 SF		0.00	2.87	1.01	8.62	52.68
1,325. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Countertop column</i>	282.90 SF		0.00	1.84	7.96	104.10	632.60
1,326. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
1,327. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
1,328. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
1,329. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41

Totals: Kitchen 9.90 140.34 851.97



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,330. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	112.00 SF		0.00	2.87	7.54	64.28	393.26




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,331. Blown-in insulation - 10" depth - R26	154.68 SF		0.00	1.12	11.66	34.64	219.54
<i>Ceiling</i>							
1,332. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
1,333. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,334. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
1,335. Paint the walls - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79
1,336. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
1,337. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,338. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,339. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					44.43	484.50	2,951.48



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,340. 5/8" drywall - hung, taped, floated, ready for paint	28.00 SF		0.00	2.87	1.89	16.08	98.33
<i>Ceiling</i>							
1,341. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,342. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	158.83 SF		0.00	1.84	4.47	58.46	355.18
1,343. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,344. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	45.00 SF		0.00	2.87	3.03	25.84	158.02
1,345. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	45.00 SF		0.00	1.07	2.89	9.64	60.68
1,346. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
1,347. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	158.83 SF		0.00	1.84	4.47	58.46	355.18
1,348. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
1,349. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,350. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
1,351. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					21.07	229.28	1,396.54
Total: 3210					<b>75.40</b>	<b>854.12</b>	<b>5,199.99</b>

3213



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,352. 5/8" drywall - hung, taped, floated, ready for paint	267.00 SF		0.00	2.87	17.98	153.26	937.53



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,353. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
1,354. Batt insulation - 6" - R19 - unfaced batt	67.00 SF		0.00	1.07	4.31	14.34	90.34
<i>Walls</i>							
1,355. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,356. Detach & Reset Cabinetry - lower (base) units	2.00 LF	69.68	0.00	0.00	0.00	27.88	167.24
1,357. R&R Countertop - post formed plastic laminate	25.00 LF		5.22	50.41	87.28	278.16	1,756.19
1,358. R&R Cabinet refacing	65.04 SF		3.78	28.62	112.43	421.46	2,641.18
1,359. Detach & Reset Kitchen Sink - single basin	1.00 EA	160.49	0.00	0.00	0.05	32.10	192.64
1,360. Sink strainer and drain assembly	1.00 EA		0.00	51.35	1.81	10.28	63.44
1,361. Detach & Reset Sink faucet - Kitchen	1.00 EA	128.34	0.00	0.00	0.00	25.66	154.00
1,362. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
<i>Walls</i>							
1,363. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
1,364. Floor preparation for resilient flooring	64.74 SF		0.00	0.71	0.65	9.20	55.82
1,365. Vinyl plank flooring	64.74 SF		0.00	5.74	19.45	74.32	465.38
1,366. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>260.45</b>	<b>1,188.02</b>	<b>7,388.46</b>



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,367. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
1,368. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
1,369. R&R Baseboard - 3 1/4"	12.00 LF		0.57	3.49	1.75	9.74	60.21
1,370. Base shoe	12.00 LF		0.00	1.41	0.60	3.38	20.90
1,371. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
1,372. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
1,373. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,374. Clean and deodorize carpet	154.68 SF		0.00	0.57	0.00	17.64	105.81
1,375. Seal/prime then paint the walls twice (3 coats)	371.67 SF		0.00	1.84	10.46	136.78	831.11
1,376. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,377. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					17.10	248.20	1,506.47



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,378. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	52.00 SF		0.00	2.87	3.50	29.84	182.58
1,379. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Entry**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
1,380. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
1,381. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,382. 5/8" drywall - hung, taped, floated, ready for paint	4.00 SF		0.00	2.87	0.27	2.30	14.05
1,383. Batt insulation - 6" - R19 - unfaced batt	3.00 SF		0.00	1.07	0.19	0.64	4.04
<i>Walls</i>							
1,384. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
1,385. Base shoe	11.17 LF		0.00	1.41	0.56	3.16	19.47
1,386. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
1,387. Baseboard - 3 1/4"	11.17 LF		0.00	3.49	1.63	7.80	48.41
1,388. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
1,389. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
1,390. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,391. Floor preparation for resilient flooring	40.83 SF		0.00	0.71	0.41	5.80	35.20
1,392. Vinyl plank flooring	40.83 SF		0.00	5.74	12.27	46.88	293.51
1,393. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>27.29</b>	<b>200.40</b>	<b>1,229.52</b>



**Bedroom**

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" **Opens into BATHROOM**  
**Window** 4' X 4' **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,394. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	45.00 SF		0.00	2.87	3.03	25.84	158.02
1,395. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	45.00 SF		0.00	1.07	2.89	9.64	60.68
1,396. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
1,397. Seal/prime then paint the walls and ceiling twice (3 coats)	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
1,398. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
1,399. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
1,400. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,401. Clean and deodorize carpet	120.89 SF		0.00	0.57	0.00	13.78	82.69
1,402. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
<b>Totals: Bedroom</b>					22.07	283.32	1,721.89



### Bathroom


**Height: 9'**

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" **Opens into ENTRY**

**Door** 2' 8" X 6' 8" **Opens into WALKIN\_CLOS**

**Door** 2' 8" X 6' 8" **Opens into BEDROOM**



### Subroom: Utility Room (1)

**Height: 9'**

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,403. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57
1,404. Seal/prime then paint the walls twice (3 coats)	509.17 SF		0.00	1.84	14.33	187.38	1,138.58
1,405. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
1,406. Seal & paint baseboard - two coats	54.50 LF		0.00	2.24	0.60	24.42	147.10
1,407. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
1,408. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
<b>Totals: Bathroom</b>					<b>18.40</b>	<b>257.82</b>	<b>1,565.27</b>
<b>Total: 3213</b>					<b>345.31</b>	<b>2,177.76</b>	<b>13,411.61</b>

### 3215



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,409. Outlet or switch - Detach & reset	1.00 EA		0.00	18.23	0.00	3.64	21.87
1,410. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11
1,411. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,412. Seal/prime then paint the walls and ceiling twice (3 coats)	522.56 SF		0.00	1.84	14.71	192.30	1,168.52
1,413. Base shoe	4.00 LF		0.00	1.41	0.20	1.12	6.96
1,414. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
1,415. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
1,416. Baseboard - 2 1/4"	4.00 LF		0.00	2.90	0.38	2.32	14.30
1,417. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
1,418. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>18.53</b>	<b>264.64</b>	<b>1,606.35</b>



### Bathroom

Height: 9'

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b> 1' 5" X 6' 8" Opens into LINEN_CLOSET							
<b>Door</b> 2' 8" X 6' 8" Opens into LIVING__DIN							
1,419. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	24.00 SF		0.00	2.87	1.62	13.78	84.28
1,420. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	53.06 SF		0.00	1.12	4.00	11.88	75.31
1,421. Seal/prime then paint the walls and ceiling twice (3 coats)	319.83 SF		0.00	1.84	9.00	117.70	715.19
1,422. Mask the floor per square foot - plastic and tape - 4 mil	53.06 SF		0.00	0.35	0.27	3.72	22.56
1,423. Final cleaning - construction - Residential	53.06 SF		0.00	0.34	0.00	3.60	21.64
<b>Totals: Bathroom</b>					<b>14.89</b>	<b>150.68</b>	<b>918.98</b>
<b>Total: 3215</b>					<b>33.42</b>	<b>415.32</b>	<b>2,525.33</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

3218



### Kitchen

Height: 9'

291.33 SF Walls	86.14 SF Ceiling
377.47 SF Walls & Ceiling	86.14 SF Floor
9.57 SY Flooring	29.58 LF Floor Perimeter
40.33 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

4' 1" X 6' 8"

Opens into LIVING\_ROOM

Door

1' 8" X 6' 8"

Opens into ENTRY\_CLOSET

Door

3' X 6' 8"

Opens into UTILITY\_ROOM

Door

2' X 6' 8"

Opens into PANTRY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,424. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	126.00 SF		0.00	2.87	8.48	72.32	442.42
1,425. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	86.14 SF		0.00	1.12	6.49	19.30	122.27
1,426. Seal/prime then paint the ceiling twice (3 coats)	86.14 SF		0.00	1.84	2.42	31.70	192.62
1,427. Detach & Reset Light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
1,428. Mask the floor per square foot - plastic and tape - 4 mil	86.14 SF		0.00	0.35	0.43	6.04	36.62
1,429. Final cleaning - construction - Residential	86.14 SF		0.00	0.34	0.00	5.86	35.15
Totals: Kitchen					17.82	155.56	951.12
Total: 3218					17.82	155.56	951.12

3219



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bedroom

**Height: 8'**

316.11 SF Walls	138.06 SF Ceiling
454.17 SF Walls & Ceiling	138.06 SF Floor
15.34 SY Flooring	40.42 LF Floor Perimeter
47.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,430. Seal/prime then paint the walls and ceiling twice (3 coats)	454.17 SF		0.00	1.84	12.78	167.14	1,015.59
1,431. Seal & paint baseboard - two coats	40.42 LF		0.00	2.24	0.45	18.10	109.09
1,432. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,433. Mask the floor per square foot - plastic and tape - 4 mil	138.06 SF		0.00	0.35	0.69	9.66	58.67
1,434. Final cleaning - construction - Residential	138.06 SF		0.00	0.34	0.00	9.38	56.32
<b>Totals: Bedroom</b>					<b>14.83</b>	<b>222.56</b>	<b>1,350.28</b>



### Living / Dining Room

**Height: 8'**

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,435. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	42.00 SF		0.00	2.87	2.83	24.10	147.47
1,436. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	277.94 SF		0.00	1.12	20.95	62.26	394.50
1,437. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Wall</i>	743.06 SF		0.00	1.84	20.91	273.44	1,661.58
1,438. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	30.00 SF		0.00	1.07	1.93	6.42	40.45
1,439. Crown molding - 3 1/4"	10.00 LF		0.00	4.40	1.67	8.80	54.47
1,440. Seal & paint crown molding - two coats	74.00 LF		0.00	2.24	1.04	33.16	199.96
1,441. Seal & paint baseboard - two coats	62.17 LF		0.00	2.24	0.69	27.86	167.81
1,442. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,443. Mask the floor per square foot - plastic and tape - 4 mil	276.89 SF		0.00	0.35	1.39	19.38	117.68
1,444. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
Totals: Living / Dining Room					52.32	492.52	3,007.49



### Kitchen

Height: 8'

230.00 SF Walls	80.06 SF Ceiling
310.06 SF Walls & Ceiling	80.06 SF Floor
8.90 SY Flooring	26.33 LF Floor Perimeter
40.83 LF Ceil. Perimeter	

<b>Door</b>	<b>4' 2" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into WORKSPACE___</b>
<b>Door</b>	<b>1' 9" X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into LIVING___DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,445. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	90.00 SF		0.00	2.87	6.06	51.66	316.02
1,446. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	80.06 SF		0.00	1.12	6.04	17.94	113.65
1,447. Seal/prime then paint the walls and ceiling twice (3 coats)	310.06 SF		0.00	1.84	8.73	114.10	693.34
1,448. Seal & paint base shoe or quarter round	26.33 LF		0.00	1.19	0.29	6.26	37.88
1,449. Mask the floor per square foot - plastic and tape - 4 mil	80.06 SF		0.00	0.35	0.40	5.60	34.02
1,450. Final cleaning - construction - Residential	80.06 SF		0.00	0.34	0.00	5.44	32.66
Totals: Kitchen					21.52	201.00	1,227.57
Total: 3219					<b>88.67</b>	<b>916.08</b>	<b>5,585.34</b>

3303



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>					
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,451. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	8.00 SF		0.00	2.87	0.54	4.60	28.10
1,452. Batt insulation - 6" - R19 - unfaced batt <i>Ceiling</i>	4.00 SF		0.00	1.07	0.26	0.86	5.40
1,453. Seal/prime then paint the walls and ceiling twice (3 coats)	390.74 SF		0.00	1.84	11.00	143.80	873.76
1,454. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,455. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
Totals: Bathroom					12.20	160.30	973.80



### Living Room

Height: 9'

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into BEDROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,456. 5/8" drywall - hung, taped, floated, ready for paint Walls	4.00 SF		0.00	2.87	0.27	2.30	14.05
1,457. Batt insulation - 6" - R19 - unfaced batt Walls	4.00 SF		0.00	1.07	0.26	0.86	5.40
1,458. Seal/prime then paint the walls twice (3 coats)	892.06 SF		0.00	1.84	25.10	328.28	1,994.77
1,459. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
1,460. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,461. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
1,462. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living Room					30.33	470.44	2,852.96
Total: 3303					<b>42.53</b>	<b>630.74</b>	<b>3,826.76</b>

**3305**



### Bathroom

**Height: 9'**

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,463. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
<i>Ceiling</i>							
1,464. Blown-in insulation - 10" depth - R26	53.06 SF		0.00	1.12	4.00	11.88	75.31
<i>Ceiling</i>							
1,465. Seal/prime then paint the ceiling twice (3 coats)	53.06 SF		0.00	1.84	1.49	19.52	118.64
1,466. Mask the floor per square foot - plastic and tape - 4 mil	53.06 SF		0.00	0.35	0.27	3.72	22.56
1,467. Final cleaning - construction - Residential	53.06 SF		0.00	0.34	0.00	3.60	21.64
Totals: Bathroom					6.16	42.16	259.21



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,468. 5/8" drywall - hung, taped, floated, ready for paint	24.00 SF		0.00	2.87	1.62	13.78	84.28
<i>Walls</i>							
1,469. Batt insulation - 6" - R19 - unfaced batt	4.00 SF		0.00	1.07	0.26	0.86	5.40
<i>Walls</i>							
1,470. Base shoe	4.00 LF		0.00	1.41	0.20	1.12	6.96
1,471. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
1,472. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
<i>Ceiling</i>							
1,473. Blown-in insulation - 10" depth - R26	384.72 SF		0.00	1.12	29.00	86.18	546.07
<i>Ceiling</i>							
1,474. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
<i>Ceiling</i>							
<i>Paint and blend (walls)</i>							
1,475. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
1,476. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
1,477. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,478. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,479. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					65.28	641.94	3,916.82
Total: 3305					<b>71.44</b>	<b>684.10</b>	<b>4,176.03</b>

**3306**



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

Missing Wall - Goes to Floor

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,480. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	27.00 SF		0.00	2.87	1.82	15.50	94.81
1,481. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	27.00 SF		0.00	1.07	1.74	5.78	36.41
1,482. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	218.17 SF		0.00	1.84	6.14	80.28	487.85
1,483. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
1,484. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
1,485. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					10.33	122.70	746.55



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**


**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,486. R&R 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	27.00 SF		0.53	2.87	1.82	18.36	111.98
1,487. R&R Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	27.00 SF		0.36	1.07	1.74	7.72	48.07
1,488. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
1,489. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
1,490. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,491. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,492. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11

Totals: Living Room 20.57    280.04    1,700.87



**Bedroom**

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Window**

**4' X 4'**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,493. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	51.00 SF		0.00	2.87	3.43	29.28	179.08
1,494. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	51.00 SF		0.00	1.07	3.28	10.92	68.77
1,495. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
1,496. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer</i>	24.00 SF		0.00	2.87	1.62	13.78	84.28
1,497. Baseboard - 3 1/4" <i>Ceiling</i>	11.00 LF		0.00	3.49	1.60	7.68	47.67
1,498. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
1,499. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
1,500. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,501. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
1,502. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					39.09	470.70	2,863.25
Total: 3306					<b>69.99</b>	<b>873.44</b>	<b>5,310.67</b>

**3310**



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

Missing Wall - Goes to Floor

**5' 7" X 9'**

**Opens into ENTRY**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,503. Hat channel, 16" OC	64.74 SF		0.00	1.53	2.47	19.82	121.34
1,504. 5/8" drywall - hung, taped, floated, ready for paint	150.00 SF		0.00	2.87	10.10	86.10	526.70
1,505. Batt insulation - 4" - R11-unfaced batt	150.00 SF		0.00	0.70	5.58	21.00	131.58
1,506. 5/8" drywall - hung, taped, floated, ready for paint	64.74 SF		0.00	2.87	4.36	37.16	227.32
1,507. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
1,508. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
<i>Ceiling</i>							
1,509. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,510. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
1,511. Detach & Reset Cabinetry - upper (wall) units	7.00 LF	59.59	0.00	0.00	0.00	83.42	500.55
1,512. Detach & Reset Cabinetry - lower (base) units	3.00 LF	69.68	0.00	0.00	0.00	41.80	250.84
1,513. Detach & Reset Countertop - post formed plastic laminate	6.00 LF	19.74	0.00	0.00	0.08	23.68	142.20
1,514. Baseboard - 4 1/4"	7.00 LF		0.00	4.14	1.42	5.80	36.20
1,515. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
1,516. Base shoe	27.25 LF		0.00	1.41	1.37	7.68	47.47
1,517. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
1,518. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
1,519. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
1,520. Floor preparation for resilient flooring	64.74 SF		0.00	0.71	0.65	9.20	55.82
1,521. R&R Vinyl plank flooring	64.74 SF		1.48	5.74	19.45	93.48	580.36
1,522. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					59.82	613.24	3,739.34



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,523. Hat channel, 16" OC	371.67 SF		0.00	1.53	14.19	113.74	696.59
1,524. 5/8" drywall - hung, taped, floated, ready for paint	309.36 SF		0.00	2.87	20.83	177.58	1,086.27
<i>Double layer</i>							
1,525. Blown-in insulation - 10" depth - R26	154.68 SF		0.00	1.12	11.66	34.64	219.54
<i>Ceiling</i>							
1,526. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
<i>Walls</i>							
1,527. Crown molding - 3 1/4"	40.67 LF		0.00	4.40	6.78	35.80	221.53
1,528. Seal & paint crown molding - two coats	40.67 LF		0.00	2.24	0.57	18.22	109.89
1,529. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
1,530. 5/8" drywall - hung, taped, floated, ready for paint	394.00 SF		0.00	2.87	26.53	226.16	1,383.47
<i>Walls</i>							
1,531. Batt insulation - 6" - R19 - unfaced batt	82.00 SF		0.00	1.07	5.27	17.54	110.55
<i>Walls</i>							
1,532. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
<i>Walls</i>							
1,533. Baseboard - 3 1/4"	34.00 LF		0.00	3.49	4.95	23.74	147.35
1,534. Window sill	3.34 LF		0.00	3.12	0.31	2.08	12.81
1,535. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,536. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,537. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living Room					122.91	1,097.16	6,705.81



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,538. 5/8" drywall - hung, taped, floated, ready for paint	56.00 SF		0.00	2.87	3.77	32.14	196.63
1,539. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							
1,540. Seal/prime then paint the ceiling twice (3 coats)	40.83 SF		0.00	1.84	1.15	15.02	91.30
<i>Ceiling</i>							
1,541. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
1,542. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
1,543. 5/8" drywall - hung, taped, floated, ready for paint	42.00 SF		0.00	2.87	2.83	24.10	147.47
<i>Walls</i>							
1,544. Batt insulation - 6" - R19 - unfaced batt	42.00 SF		0.00	1.07	2.70	8.98	56.62
<i>Walls</i>							
1,545. Casing - 2 1/4"	21.00 LF		0.00	2.23	2.45	9.36	58.64
1,546. Base shoe	7.00 LF		0.00	1.41	0.35	1.98	12.20
1,547. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
1,548. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,549. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
1,550. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,551. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
1,552. Vinyl floor covering (sheet goods)	46.96 SF		0.00	3.35	8.21	31.46	196.99
15 % waste added for Vinyl floor covering (sheet goods).							
1,553. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>30.24</b>	<b>186.22</b>	<b>1,147.80</b>



### Bedroom

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,554. Remove Carpet	120.89 SF		0.34	0.00	0.00	8.22	49.32
1,555. Carpet	139.02 SF		0.00	3.67	37.58	102.04	649.82
15 % waste added for Carpet.							
1,556. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
<b>Totals: Bedroom</b>					<b>37.58</b>	<b>118.48</b>	<b>748.46</b>

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Window**

**4' X 4'**

**Opens into Exterior**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bathroom

Height: 9'

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into ENTRY
Door	2' 8" X 6' 8"	Opens into WALKIN_CLOS
Door	2' 8" X 6' 8"	Opens into BEDROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,557. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64
1,558. Base shoe	38.33 LF		0.00	1.41	1.93	10.82	66.80
1,559. Seal & paint baseboard - two coats	38.33 LF		0.00	2.24	0.42	17.18	103.46
1,560. Seal & paint base shoe or quarter round	38.33 LF		0.00	1.19	0.42	9.12	55.15
1,561. Final cleaning - construction - Residential	81.15 SF		0.00	0.34	0.00	5.52	33.11
Totals: Bathroom					3.42	94.64	571.16



### Utility Room

Height: 9'

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,562. Detach & Reset Washer/Washing Machine - Front-loading	1.00 EA	46.97	0.00	0.00	0.00	9.40	56.37
1,563. Detach & Reset Dryer - Electric	1.00 EA	36.21	0.00	0.00	0.00	7.24	43.45
1,564. Seal & paint baseboard - two coats	16.17 LF		0.00	2.24	0.18	7.24	43.64
1,565. Seal & paint base shoe or quarter round	16.17 LF		0.00	1.19	0.18	3.84	23.26
1,566. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
Totals: Utility Room					0.36	28.74	172.80



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 3310

254.33

2,138.48

13,085.37

3313



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,567. Hat channel, 16" OC	64.74 SF		0.00	1.53	2.47	19.82	121.34
1,568. 5/8" drywall - hung, taped, floated, ready for paint	150.00 SF		0.00	2.87	10.10	86.10	526.70
1,569. Batt insulation - 4" - R11-unfaced batt	150.00 SF		0.00	0.70	5.58	21.00	131.58
1,570. 5/8" drywall - hung, taped, floated, ready for paint	64.74 SF		0.00	2.87	4.36	37.16	227.32
1,571. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
1,572. Seal/prime then paint the ceiling twice (3 coats)	64.74 SF		0.00	1.84	1.82	23.82	144.76
<i>Ceiling</i>							
1,573. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,574. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
1,575. Detach & Reset Cabinetry - upper (wall) units	7.00 LF	59.59	0.00	0.00	0.00	83.42	500.55
1,576. Detach & Reset Cabinetry - lower (base) units	3.00 LF	69.68	0.00	0.00	0.00	41.80	250.84
1,577. Detach & Reset Countertop - post formed plastic laminate	6.00 LF	19.74	0.00	0.00	0.08	23.68	142.20
1,578. Baseboard - 4 1/4"	7.00 LF		0.00	4.14	1.42	5.80	36.20
1,579. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
<i>Walls</i>							
1,580. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
1,581. Base shoe	27.25 LF		0.00	1.41	1.37	7.68	47.47
1,582. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,583. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
1,584. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
1,585. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>41.54</b>	<b>534.38</b>	<b>3,247.92</b>



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling
- Window
- Missing Wall

- 5' 5" X 5'
- 4' X 4'
- 4' 1" X 9'


- Opens into KITCHEN
- Opens into Exterior
- Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,586. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
1,587. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
1,588. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,589. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,590. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>13.84</b>	<b>203.42</b>	<b>1,234.47</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,591. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	15.00 SF		0.00	2.87	1.01	8.62	52.68
1,592. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	40.83 SF		0.00	1.12	3.08	9.14	57.95
1,593. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,594. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	30.00 SF		0.00	2.87	2.02	17.22	105.34
1,595. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	30.00 SF		0.00	1.07	1.93	6.42	40.45
1,596. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
1,597. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
1,598. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
1,599. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
1,600. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
1,601. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,602. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
1,603. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>15.83</b>	<b>151.42</b>	<b>924.23</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 3313

71.21

889.22

5,406.62

3317




### Utility Room

Height: 9'

216.22 SF Walls	40.89 SF Ceiling
257.11 SF Walls & Ceiling	40.89 SF Floor
4.54 SY Flooring	23.33 LF Floor Perimeter
26.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,604. Seal/prime then paint the ceiling twice (3 coats)	40.89 SF		0.00	1.84	1.15	15.04	91.43
1,605. Mask the floor per square foot - plastic and tape - 4 mil	40.89 SF		0.00	0.35	0.21	2.86	17.38
1,606. Final cleaning - construction - Residential	40.89 SF		0.00	0.34	0.00	2.78	16.68
Totals: Utility Room					1.36	20.68	125.49
Total: 3317					1.36	20.68	125.49

3409



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,607. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (Ceiling)</i>	112.00 SF		0.00	2.87	7.54	64.28	393.26
1,608. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	129.35 SF		0.00	1.12	9.75	28.98	183.60
1,609. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
<i>Walls</i>							
1,610. Batt insulation - 6" - R19 - unfaced batt	88.00 SF		0.00	1.07	5.66	18.84	118.66
<i>Walls</i>							
1,611. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
1,612. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
<i>Walls</i>							
1,613. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,614. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
1,615. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					<b>40.94</b>	<b>361.66</b>	<b>2,210.89</b>
<b>Total: 3409</b>					<b>40.94</b>	<b>361.66</b>	<b>2,210.89</b>

### 3411



#### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,616. 5/8" drywall - hung, taped, floated, ready for paint	60.00 SF		0.00	2.87	4.04	34.44	210.68
<i>Double layer (Ceiling)</i>							
1,617. Blown-in insulation - 10" depth - R26	154.68 SF		0.00	1.12	11.66	34.64	219.54
<i>Ceiling</i>							
1,618. Seal/prime then paint the ceiling twice (3 coats)	154.68 SF		0.00	1.84	4.35	56.92	345.88




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
1,619. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
1,620. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					20.83	147.34	904.95



### Bedroom

Height: 9'

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,621. 5/8" drywall - hung, taped, floated, ready for paint	241.78 SF		0.00	2.87	16.28	138.78	848.97
<i>Double layer (Ceiling)</i>							
1,622. Blown-in insulation - 10" depth - R26	120.89 SF		0.00	1.12	9.11	27.08	171.59
<i>Ceiling</i>							
1,623. Seal/prime then paint the walls and ceiling twice (3 coats)	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
1,624. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
1,625. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
1,626. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					39.59	396.54	2,418.88

Total: 3411 **60.42** **543.88** **3,323.83**

Total: Building 3 Interiors **3,644.43** **26,468.38** **162,453.80**

### Corridors/Hallways



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,627. 5/8" - drywall per LF - up to 2' tall	216.00 LF		0.00	11.45	30.83	494.64	2,998.67
1,628. 5/8" drywall - hung, taped, floated, ready for paint	451.00 SF		0.00	2.87	30.37	258.88	1,583.62
<i>Ceiling</i>							
1,629. Seal/prime then paint the surface area twice (3 coats)	43,792.00 SF		0.00	1.84	1,232.31	16,115.46	97,925.05
<i>Estimated allowance</i>							
1,630. Electrician - per hour	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
<i>Labor to detach and reset misc to prep for paint.</i>							
1,631. Painter - per hour	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
<i>Misc labor to prep for paint.</i>							
1,632. Carpenter - General Framer - per hour	30.00 HR		0.00	72.00	0.00	432.00	2,592.00
<i>Labor to install drywall nailers.</i>							
Totals: Corridors/Hallways					1,293.51	18,567.42	112,698.02

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,633. Clean with pressure/chemical spray	35,760.00 SF		0.00	0.43	35.94	3,075.36	18,488.10
1,634. Exterior - paint two coats	35,760.00 SF		0.00	1.58	1,150.04	11,300.16	68,951.00
1,635. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
1,636. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
1,637. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
1,638. R&R Window screen, 1 - 9 SF	41.00 EA		4.74	36.30	129.18	336.52	2,148.34
1,639. R&R Exterior post light fixture - High grade	1.00 EA		47.46	258.57	14.77	61.22	382.02
<i>Gate light fixture.</i>							
1,640. R&R Gutter / downspout - aluminum - 7" to 8"	150.00 LF		0.63	17.54	197.78	545.10	3,468.38
<i>50 LF Downspout 100 LF Gutters</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,641. Gutter / downspout - Detach & reset	50.00 LF		0.00	4.85	0.00	48.50	291.00
1,642. R&R Light fixture - wall sconce - High grade	2.00 EA		10.49	155.78	24.12	66.52	423.18
1,643. R&R Shutters - wood - louvered or paneled - Large	4.00 EA		7.86	358.97	105.32	293.46	1,866.10
<i>4 sets. Line item description states "Shutter set and installation labor. Labor cost to remove shutters and to discard in a job-site waste receptacle."</i>							
1,644. Seal & paint window shutters - per set	4.00 EA		0.00	46.58	2.17	37.26	225.75
1,645. Clean with pressure/chemical spray	112.00 SF		0.00	0.43	0.11	9.64	57.91
<i>Powerwash two (2) double doors.</i>							
1,646. R&R Commercial sign face	10.00 SF		1.89	28.88	25.13	61.54	394.37
<i>Building number sign.</i>							
1,647. R&R Fascia - fiber cement - 8"	50.00 LF		0.42	8.92	13.07	93.40	573.47
1,648. Prime & paint exterior fascia - wood, 6" - 8" wide	50.00 LF		0.00	3.15	0.95	31.50	189.95
Totals: Exteriors					1,842.80	19,868.02	121,050.83

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,690. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR						AS INCURRED
1,691. Telehandler/forklift and operator	160.00 HR						AS INCURRED
1,692. Scaffold	35,760. SF 00		0.00	0.50	0.00	3,576.00	21,456.00
1,693. Commercial Supervision / Project Management - per hour	224.00 HR		0.00	68.91	0.00	3,087.16	18,523.00
1,694. General Laborer - per hour	512.00 HR		0.00	37.61	0.00	3,851.26	23,107.58
1,695. Temporary toilet (per month)	12.00 MO						AS INCURRED
1,696. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
1,697. Hand wash station	6.00 MO						AS INCURRED
1,698. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
1,699. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
1,700. OSHA compliance safety monitor- per hour	HR						AS INCURRED



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,701. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
1,702. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
1,703. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
1,704. Light bulb - Incand. standard bulb - 1000 hr - mat. only	18.00 EA		0.00	0.79	1.43	2.84	18.49
Assuming three (3) bulbs per fixture.							
Totals: GENERAL CONDITIONS					61.43	10,751.00	64,567.51
Total: SAULET-BLDG-03-V5_23					<b>6,842.17</b>	<b>75,654.82</b>	<b>460,770.16</b>

### SAULET-BLDG-04-V5\_23

#### Building 4 Interiors

4101



#### Bedroom

Height: 9'

373.11 SF Walls	128.44 SF Ceiling
501.56 SF Walls & Ceiling	128.44 SF Floor
14.27 SY Flooring	42.50 LF Floor Perimeter
45.33 LF Ceil. Perimeter	

#### Window

4' X 4'

Opens into Exterior

#### Door

2' 10" X 6' 8"

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,705. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
1,706. 5/8" drywall - hung, taped, floated, ready for paint	501.56 SF		0.00	2.87	33.77	287.90	1,761.15
1,707. Batt insulation - 6" - R19 - unfaced batt	373.11 SF		0.00	1.07	24.00	79.84	503.07
<i>Walls</i>							
1,708. Blown-in insulation - 10" depth - R26	128.44 SF		0.00	1.12	9.68	28.78	182.31
<i>Ceiling</i>							
1,709. Baseboard - 3 1/4"	42.50 LF		0.00	3.49	6.19	29.66	184.18
1,710. Seal & paint baseboard - two coats	42.50 LF		0.00	2.24	0.47	19.04	114.71



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,711. Seal/prime then paint the walls and ceiling twice (3 coats)	501.56 SF		0.00	1.84	14.11	184.58	1,121.56
1,712. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
1,713. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
1,714. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
1,715. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
1,716. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,717. Window blind - PVC - 1" - 14.1 to 20 SF	2.00 EA		0.00	71.68	5.39	28.68	177.43
1,718. Carpet	147.71 SF		0.00	3.67	39.93	108.42	690.45
<i>15 % waste added for Carpet.</i>							
1,719. Carpet pad	128.44 SF		0.00	0.63	6.33	16.18	103.43
1,720. Mask the floor per square foot - plastic and tape - 4 mil	128.44 SF		0.00	0.35	0.65	9.00	54.60
1,721. Final cleaning - construction - Residential	128.44 SF		0.00	0.34	0.00	8.74	52.41
<b>Totals: Bedroom</b>					<b>178.82</b>	<b>971.14</b>	<b>6,005.47</b>



### Bathroom

**Height: 9'**

256.03 SF Walls	62.14 SF Ceiling
318.17 SF Walls & Ceiling	62.14 SF Floor
6.90 SY Flooring	26.98 LF Floor Perimeter
32.64 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" Opens into ENTRY  
**Door** 3' X 6' 8" Opens into WALKIN\_CLOS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,722. 5/8" drywall - hung, taped, floated, ready for paint	380.30 SF		0.00	2.87	25.61	218.30	1,335.37
1,723. Seal/prime then paint the walls and ceiling twice (3 coats)	318.17 SF		0.00	1.84	8.95	117.08	711.46
1,724. Batt insulation - 6" - R19 - unfaced batt	256.03 SF		0.00	1.07	16.47	54.80	345.22
1,725. Blown-in insulation - 10" depth - R26	62.14 SF		0.00	1.12	4.68	13.92	88.20



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,726. Fiberglass tub & shower combination	1.00 EA		0.00	1,109.55	56.90	221.92	1,388.37
1,727. Vanity	4.00 LF		0.00	211.87	68.65	169.50	1,085.63
1,728. Countertop - solid surface	9.50 SF		0.00	64.30	42.68	122.18	775.71
1,729. Baseboard - 3 1/4"	26.98 LF		0.00	3.49	3.93	18.84	116.93
1,730. Base shoe	26.98 LF		0.00	1.41	1.36	7.60	47.00
1,731. Seal & paint baseboard - two coats	26.98 LF		0.00	2.24	0.30	12.08	72.82
1,732. Seal & paint base shoe or quarter round	26.98 LF		0.00	1.19	0.30	6.42	38.83
1,733. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
1,734. Sink - single	1.00 EA		0.00	274.65	15.92	54.94	345.51
1,735. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
1,736. Tub/shower faucet	1.00 EA		0.00	315.61	14.07	63.12	392.80
1,737. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
1,738. Mirror - 1/4" plate glass	9.00 SF		0.00	16.85	10.67	30.34	192.66
1,739. Bath accessory	2.00 EA		0.00	28.55	3.04	11.42	71.56
1,740. Exhaust fan	1.00 EA		0.00	197.85	5.11	39.58	242.54
1,741. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
1,742. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,743. Door knob/lockset - Detach & reset	2.00 EA		0.00	23.06	0.00	9.22	55.34
1,744. Interior door unit	2.00 EA		0.00	269.19	41.87	107.68	687.93
1,745. Vinyl tile	62.14 SF		0.00	3.93	13.61	48.84	306.66
1,746. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
1,747. Floor preparation for resilient flooring	62.14 SF		0.00	0.71	0.62	8.82	53.56
1,748. Mask the walls per square foot - plastic and tape - 4 mil	256.03 SF		0.00	0.35	1.29	17.92	108.82
1,749. Final cleaning - construction - Residential	62.14 SF		0.00	0.34	0.00	4.22	25.35
<b>Totals: Bathroom</b>					<b>355.13</b>	<b>1,512.52</b>	<b>9,430.04</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Walk-in Closet

**Height: 9'**


179.77 SF Walls	31.46 SF Ceiling
211.23 SF Walls & Ceiling	31.46 SF Floor
3.50 SY Flooring	19.20 LF Floor Perimeter
22.20 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' X 6' 8"			Opens into BATHROOM			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
1,750. Carpet	36.18 SF		0.00	3.67	9.78	26.56	169.12	
<i>% waste added for Carpet.</i>								
1,751. Carpet pad	31.46 SF		0.00	0.63	1.55	3.96	25.33	
1,752. 5/8" drywall - hung, taped, floated, ready for paint	211.23 SF		0.00	2.87	14.22	121.24	741.69	
1,753. Paint the walls and ceiling - two coats	211.23 SF		0.00	1.36	4.67	57.46	349.40	
1,754. Baseboard - 3 1/4"	19.20 LF		0.00	3.49	2.80	13.40	83.21	
1,755. Seal & paint baseboard - two coats	19.20 LF		0.00	2.24	0.21	8.60	51.82	
1,756. Shelving - wire (vinyl coated) - Detach & reset	19.20 LF		0.00	9.66	0.00	37.10	222.57	
1,757. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56	
1,758. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27	
1,759. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97	
1,760. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05	
1,761. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61	
1,762. Door knob/lockset - Detach & reset	1.00 EA		0.00	23.06	0.00	4.62	27.68	
1,763. Mask the floor per square foot - plastic and tape - 4 mil	31.46 SF		0.00	0.35	0.16	2.20	13.37	
1,764. Final cleaning - construction - Residential	31.46 SF		0.00	0.34	0.00	2.14	12.84	
<b>Totals: Walk-in Closet</b>					<b>60.05</b>	<b>388.24</b>	<b>2,389.49</b>	



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Utility Room**

**Height: 9'**

185.50 SF Walls	26.94 SF Ceiling
212.44 SF Walls & Ceiling	26.94 SF Floor
2.99 SY Flooring	19.83 LF Floor Perimeter
22.83 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into KITCHEN</b>					
<b>DESCRIPTION</b>	<b>QTY</b>	<b>RESET</b>	<b>REMOVE</b>	<b>REPLACE</b>	<b>TAX</b>	<b>O&amp;P</b>	<b>TOTAL</b>
1,765. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
1,766. Baseboard - 3 1/4"	8.00 LF		0.00	3.49	1.17	5.58	34.67
1,767. Seal & paint baseboard - two coats	19.83 LF		0.00	2.24	0.22	8.88	53.52
1,768. Seal/prime then paint the walls twice (3 coats)	185.50 SF		0.00	1.84	5.22	68.26	414.80
1,769. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,770. Mask the floor per square foot - plastic and tape - 4 mil	26.94 SF		0.00	0.35	0.14	1.88	11.45
1,771. Final cleaning - construction - Residential	26.94 SF		0.00	0.34	0.00	1.84	11.00
Totals: Utility Room					8.29	104.76	636.93



**Kitchen**

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>6' 4" X 5'</b>	<b>Opens into LIVING_ROOM</b>					
<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>					
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>					
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>					
<b>DESCRIPTION</b>	<b>QTY</b>	<b>RESET</b>	<b>REMOVE</b>	<b>REPLACE</b>	<b>TAX</b>	<b>O&amp;P</b>	<b>TOTAL</b>
1,772. Detach & Reset Cabinetry - lower (base) units	10.00 LF	69.68	0.00	0.00	0.00	139.36	836.16
1,773. Cabinetry - upper (wall) units	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
1,774. Detach & Reset Countertop - solid surface	25.50 SF	34.74	0.00	0.00	0.18	177.18	1,063.23



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,775. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
1,776. Detach & Reset Range - freestanding - gas	1.00 EA	171.46	0.00	0.00	0.00	34.30	205.76
1,777. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
1,778. 5/8" drywall - hung, taped, floated, ready for paint	48.00 SF		0.00	2.87	3.23	27.56	168.55
<i>Walls</i>							
1,779. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
<i>Walls</i>							
1,780. Sink - single - Detach & reset	1.00 EA		0.00	160.49	0.05	32.10	192.64
1,781. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
1,782. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
1,783. P-trap assembly - Detach & reset	1.00 EA		0.00	63.96	0.00	12.80	76.76
1,784. Seal/prime then paint the walls and ceiling twice (3 coats)	267.13 SF		0.00	1.84	7.52	98.30	597.34
1,785. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
1,786. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
1,787. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
1,788. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>126.61</b>	<b>970.06</b>	<b>5,946.77</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Entry**

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	


<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,789. 5/8" drywall - hung, taped, floated, ready for paint	62.00 SF		0.00	2.87	4.17	35.58	217.69
<i>Ceiling</i>							
1,790. Blown-in insulation - 10" depth - R26	48.39 SF		0.00	1.12	3.65	10.84	68.69
<i>Ceiling</i>							
1,791. Seal/prime then paint the walls and ceiling twice (3 coats)	195.72 SF		0.00	1.84	5.51	72.02	437.65
1,792. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
1,793. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
<i>Walls</i>							
1,794. Batt insulation - 6" - R19 - unfaced batt	4.00 SF		0.00	1.07	0.26	0.86	5.40
<i>Walls</i>							
1,795. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
1,796. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,797. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
1,798. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					<b>14.45</b>	<b>164.20</b>	<b>999.72</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

**Missing Wall**

**1' 5" X 9'**

**Opens into ENTRY**

**Missing Wall - Goes to Ceiling**

**6' 10" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 6" X 9'**

**Opens into ENTRY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,799. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	139.00 SF		0.00	2.87	9.36	79.78	488.07
1,800. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	26.00 SF		0.00	1.07	1.67	5.56	35.05
1,801. Paint the walls and ceiling - two coats	640.44 SF		0.00	1.36	14.16	174.20	1,059.36
1,802. Baseboard - 3 1/4"	31.00 LF		0.00	3.49	4.52	21.64	134.35
1,803. Base shoe	31.00 LF		0.00	1.41	1.56	8.74	54.01
1,804. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
1,805. Seal & paint base shoe or quarter round	54.58 LF		0.00	1.19	0.60	13.00	78.55
1,806. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,807. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
1,808. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>34.46</b>	<b>375.38</b>	<b>2,286.72</b>
<b>Total: 4101</b>					<b>777.81</b>	<b>4,486.30</b>	<b>27,695.14</b>

4106



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

2' 6" X 5'

Opens into KITCHEN

Missing Wall

12' 7" X 9'

Opens into LIVING\_\_DIN

Missing Wall

2' 4" X 9'

Opens into HALLWAY

Door

1' 6" X 6' 8"

Opens into PANTRY

Missing Wall - Goes to Ceiling

7' 7" X 5'


Opens into KITCHEN

Missing Wall - Goes to Ceiling

2' 6" X 5'

Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,809. Paint the walls - two coats	356.25 SF		0.00	1.36	7.88	96.90	589.28
1,810. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
1,811. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,812. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
1,813. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					9.95	154.76	938.46



### Entry

Height: 9'

124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	

Door

3' X 6' 8"

Opens into Exterior

Door

3' X 6' 8"

Opens into UTILITY\_ROOM

Missing Wall

4' 1" X 9'

Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,814. Baseboard - 3 1/4"	2.00 LF		0.00	3.49	0.29	1.40	8.67
1,815. Casing - 3 1/4"	40.00 LF		0.00	3.19	8.52	25.52	161.64

Entry and laundry room.




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,816. Paint casing - one coat	40.00 LF		0.00	1.44	0.40	11.52	69.52
1,817. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
<i>Walls</i>							
1,818. Batt insulation - 6" - R19 - unfaced batt	2.00 SF		0.00	1.07	0.13	0.42	2.69
<i>Walls</i>							
1,819. Paint the walls - two coats	124.25 SF		0.00	1.36	2.75	33.80	205.53
1,820. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
1,821. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,822. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
1,823. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					12.96	92.36	567.23



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall	12' 7" X 9'	Opens into KITCHEN
Missing Wall	4' 1" X 9'	Opens into ENTRY
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	1' 1" X 9'	Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,824. Paint the walls - two coats	414.58 SF		0.00	1.36	9.17	112.76	685.76
1,825. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
1,826. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,827. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living / Dining Room					10.62	172.50	1,045.65
Total: 4106					33.53	419.62	2,551.34

4107



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,828. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
1,829. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
1,830. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	18.80	0.00	7.52	45.12
1,831. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
1,832. In-wall / In-ceiling speaker - Detach & reset	3.00 EA		0.00	18.44	0.00	11.06	66.38
1,833. Seal/prime then paint the walls twice (3 coats)	655.11 SF		0.00	1.84	18.43	241.08	1,464.91
1,834. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,835. Baseboard - 4 1/4"	14.00 LF		0.00	4.14	2.84	11.60	72.40
1,836. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,837. Casing - 2 1/4"	8.00 LF		0.00	2.23	0.93	3.56	22.33
1,838. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>23.75</b>	<b>376.28</b>	<b>2,281.46</b>



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,839. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
1,840. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
1,841. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>9.16</b>	<b>139.50</b>	<b>846.18</b>

Total: 4107 **32.91    515.78    3,127.64**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,842. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	14.00 SF		0.00	2.87	0.94	8.04	49.16
1,843. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	14.00 SF		0.00	1.07	0.90	3.00	18.88
1,844. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
1,845. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling fur down.</i>	26.00 SF		0.00	2.87	1.75	14.92	91.29
1,846. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling fur down</i>	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
1,847. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall above cabinets.</i>	13.00 SF		0.00	2.87	0.88	7.46	45.65
1,848. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
1,849. Vinyl plank flooring	481.31 SF		0.00	5.74	144.63	552.54	3,459.89
1,850. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,851. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
1,852. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
Totals: Living Room					191.51	1,206.24	7,428.84



#### Entry

Height: 9'

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

Door

3' X 6' 8"

Opens into Exterior

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,853. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
1,854. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
1,855. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,856. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
1,857. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
Totals: Entry					2.44	36.88	223.84
Total: 4110					193.95	1,243.12	7,652.68

4209



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bathroom

Height: 9'

295.00 SF Walls	69.45 SF Ceiling
364.45 SF Walls & Ceiling	69.45 SF Floor
7.72 SY Flooring	32.00 LF Floor Perimeter
35.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' X 6' 8"			Opens into ROOM2			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
1,858. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15	
1,859. Seal/prime then paint the walls and ceiling twice (3 coats)	364.45 SF		0.00	1.84	10.26	134.12	814.97	
1,860. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03	
1,861. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92	
1,862. Mask the walls per square foot - plastic and tape - 4 mil	295.00 SF		0.00	0.35	1.48	20.66	125.39	
1,863. Final cleaning - construction - Residential	69.45 SF		0.00	0.34	0.00	4.72	28.33	
Totals: Bathroom					12.07	190.96	1,157.79	
Total: 4209					12.07	190.96	1,157.79	

4301



### Pantry

Height: 9'

66.89 SF Walls	4.69 SF Ceiling
71.58 SF Walls & Ceiling	4.69 SF Floor
0.52 SY Flooring	7.00 LF Floor Perimeter
8.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 8" X 6' 8"			Opens into KITCHEN			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
1,864. Vinyl plank flooring	4.69 SF		0.00	5.74	1.41	5.38	33.71	
1,865. Floor preparation for resilient flooring	4.69 SF		0.00	0.71	0.05	0.66	4.04	
1,866. Base shoe	7.00 LF		0.00	1.41	0.35	1.98	12.20	
1,867. Seal & paint baseboard - two coats	7.00 LF		0.00	2.24	0.08	3.14	18.90	




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Pantry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,868. Seal & paint base shoe or quarter round	7.00 LF		0.00	1.19	0.08	1.66	10.07
1,869. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,870. Final cleaning - construction - Residential	4.69 SF		0.00	0.34	0.00	0.32	1.91
Totals: Pantry					2.43	22.28	136.14



### Kitchen

Height: 9'

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

6' 4" X 5'

Opens into LIVING\_ROOM

Door

1' 8" X 6' 8"

Opens into PANTRY

Door

3' X 6' 8"

Opens into UTILITY\_ROOM

Missing Wall

4' 5" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,871. Baseboard - 3 1/4"	24.75 LF		0.00	3.49	3.61	17.28	107.27
1,872. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
1,873. Base shoe	24.75 LF		0.00	1.41	1.24	6.98	43.12
1,874. Floor preparation for resilient flooring	65.15 SF		0.00	0.71	0.66	9.26	56.18
1,875. Vinyl plank flooring	65.15 SF		0.00	5.74	19.58	74.80	468.34
1,876. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
1,877. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
Totals: Kitchen					25.63	129.74	803.91

Total: 4301

28.06

152.02

940.05

4308



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 8'**

316.11 SF Walls	138.06 SF Ceiling
454.17 SF Walls & Ceiling	138.06 SF Floor
15.34 SY Flooring	40.42 LF Floor Perimeter
47.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,878. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
1,879. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	12.00 SF		0.00	1.07	0.77	2.56	16.17
1,880. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	316.11 SF		0.00	1.84	8.90	116.32	706.86
1,881. Seal & paint baseboard - two coats	40.42 LF		0.00	2.24	0.45	18.10	109.09
1,882. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,883. Final cleaning - construction - Residential	138.06 SF		0.00	0.34	0.00	9.38	56.32
<b>Totals: Bedroom</b>					<b>11.84</b>	<b>171.52</b>	<b>1,041.18</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 8'**

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,884. 5/8" drywall - hung, taped, floated, ready for paint	1.00 SF		0.00	2.87	0.07	0.58	3.52
<i>Walls</i>							
1,885. Batt insulation - 6" - R19 - unfaced batt	1.00 SF		0.00	1.07	0.06	0.22	1.35
<i>Walls</i>							
1,886. Paint the walls - two coats	465.11 SF		0.00	1.36	10.28	126.52	769.35
1,887. Seal & paint baseboard - two coats	62.17 LF		0.00	2.24	0.69	27.86	167.81
1,888. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
<b>Totals: Living / Dining Room</b>					<b>11.10</b>	<b>174.00</b>	<b>1,054.99</b>



### Kitchen

**Height: 8'**

230.00 SF Walls	80.06 SF Ceiling
310.06 SF Walls & Ceiling	80.06 SF Floor
8.90 SY Flooring	26.33 LF Floor Perimeter
40.83 LF Ceil. Perimeter	

<b>Door</b>	<b>4' 2" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 9" X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,889. Paint the walls - two coats	230.00 SF		0.00	1.36	5.09	62.56	380.45
1,890. Seal & paint baseboard - two coats	26.33 LF		0.00	2.24	0.29	11.80	71.07
1,891. Mask the floor per square foot - plastic and tape - 4 mil	80.06 SF		0.00	0.35	0.40	5.60	34.02
1,892. Final cleaning - construction - Residential	80.06 SF		0.00	0.34	0.00	5.44	32.66
<b>Totals: Kitchen</b>					<b>5.78</b>	<b>85.40</b>	<b>518.20</b>
<b>Total: 4308</b>					<b>28.72</b>	<b>430.92</b>	<b>2,614.37</b>

**4309**



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,893. Floor preparation for resilient flooring	481.31 SF		0.00	0.71	4.84	68.34	414.91
1,894. Vinyl plank flooring	481.31 SF		0.00	5.74	144.63	552.54	3,459.89
<i>Kitchen flooring.</i>							
1,895. Baseboard - 3 1/4"	108.42 LF		0.00	3.49	15.80	75.68	469.87




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,896. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
1,897. Base shoe	108.42 LF		0.00	1.41	5.45	30.58	188.90
1,898. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
1,899. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>173.12</b>	<b>834.26</b>	<b>5,178.62</b>
<b>Total: 4309</b>					<b>173.12</b>	<b>834.26</b>	<b>5,178.62</b>

**4310**



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,900. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer ceiling</i>	54.00 SF		0.00	2.87	3.64	31.00	189.62
1,901. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	486.47 SF		0.00	1.12	36.67	108.98	690.50




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,902. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
<i>Ceiling</i>							
1,903. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
1,904. Track for track lighting - Detach & reset	8.00 LF		0.00	9.84	0.00	15.74	94.46
1,905. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
1,906. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,907. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
1,908. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>81.70</b>	<b>807.34</b>	<b>4,925.55</b>



### Entry

**Height: 9'**

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,909. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
1,910. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
1,911. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,912. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
1,913. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
<b>Totals: Entry</b>					<b>2.44</b>	<b>36.88</b>	<b>223.84</b>

Total: 4310


**84.14      844.22      5,149.39**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

4312



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	


Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,914. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
<i>Walls</i>							
1,915. Blown-in insulation - 10" depth - R26	486.47 SF		0.00	1.12	36.67	108.98	690.50
<i>Walls</i>							
1,916. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
<i>Walls</i>							
1,917. Baseboard - 3 1/4"	17.00 LF		0.00	3.49	2.48	11.86	73.67
1,918. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
1,919. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,920. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
1,921. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					81.62	745.42	4,553.99



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Entry**


**Height: 9'**

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

- Missing Wall** **4' 5" X 9'** **Opens into LIVING\_ROOM**
- Door** **3' X 6' 8"** **Opens into Exterior**
- Missing Wall** **4' 5" X 9'** **Opens into LIVING\_ROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,922. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
1,923. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
1,924. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
1,925. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,926. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
<b>Totals: Entry</b>					<b>2.44</b>	<b>36.88</b>	<b>223.84</b>
<b>Total: 4312</b>					<b>84.06</b>	<b>782.30</b>	<b>4,777.83</b>

4402



**Kitchen**

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling** **6' 4" X 5'** **Opens into LIVING\_ROOM**
- Door** **1' 8" X 6' 8"** **Opens into PANTRY**
- Door** **3' X 6' 8"** **Opens into UTILITY\_ROOM**
- Missing Wall** **4' 5" X 9'** **Opens into ENTRY2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,927. Paint the walls - two coats	201.97 SF		0.00	1.36	4.47	54.94	334.09




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,928. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
1,929. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
Totals: Kitchen					4.74	70.46	427.47



**Entry**

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	


<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,930. Paint the walls - two coats	147.33 SF		0.00	1.36	3.26	40.08	243.71
1,931. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
1,932. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					3.42	49.72	301.70



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY2</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,933. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	6.00 SF		0.00	2.87	0.40	3.44	21.06
1,934. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	6.00 SF		0.00	1.07	0.39	1.28	8.09
1,935. Paint the walls - two coats <i>Walls</i>	425.08 SF		0.00	1.36	9.40	115.62	703.13
1,936. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
1,937. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
1,938. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,939. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
1,940. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>13.22</b>	<b>194.90</b>	<b>1,182.62</b>
<b>Total: 4402</b>					<b>21.38</b>	<b>315.08</b>	<b>1,911.79</b>

4403



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,941. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	1.00 SF		0.00	2.87	0.07	0.58	3.52
1,942. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	1.00 SF		0.00	1.07	0.06	0.22	1.35
1,943. Paint the walls - two coats <i>Walls</i>	823.56 SF		0.00	1.36	18.21	224.00	1,362.25
1,944. Baseboard - 3 1/4"	1.00 LF		0.00	3.49	0.15	0.70	4.34
1,945. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
1,946. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
1,947. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
1,948. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39

Totals: Living Room 23.02    358.80    2,175.68

Total: 4403 23.02    358.80    2,175.68



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

4406



### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

3' X 6' 8"

Opens into LIVING\_ROOM

Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,949. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	93.00 SF		0.00	2.87	6.26	53.38	326.55
1,950. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	93.00 SF		0.00	1.07	5.98	19.90	125.39
1,951. Paint the walls and ceiling - two coats <i>Walls</i>	502.33 SF		0.00	1.36	11.11	136.64	830.92
1,952. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	91.00 SF		0.00	2.87	6.13	52.24	319.54
1,953. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	136.10 SF		0.00	1.12	10.26	30.48	193.17
1,954. Baseboard - 3 1/4"	13.00 LF		0.00	3.49	1.89	9.08	56.34
1,955. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
Totals: Bedroom					42.08	320.08	1,962.56
Total: 4406					42.08	320.08	1,962.56

4407



### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



#### Master Bedroom

Height: 9'

450.94 SF Walls  
612.61 SF Walls & Ceiling  
17.96 SY Flooring  
55.83 LF Ceil. Perimeter

161.67 SF Ceiling  
161.67 SF Floor  
50.50 LF Floor Perimeter

**Door** 2' 8" X 6' 8" Opens into BATHROOM1  
**Door** 2' 8" X 6' 8" Opens into LIVING\_\_DIN  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
1,956. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45	
<i>Ceiling</i>								
1,957. Batt insulation - 8" - R25 - unfaced batt	40.00 SF		0.00	1.43	3.26	11.44	71.90	
<i>Ceiling</i>								
1,958. Paint the ceiling - two coats	161.67 SF		0.00	1.36	3.57	43.98	267.42	
<i>Ceiling</i>								
1,959. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33	
1,960. Mask the floor per square foot - plastic and tape - 4 mil	161.67 SF		0.00	0.35	0.81	11.32	68.71	
1,961. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97	
Totals: Master Bedroom						10.33	136.92	831.78
Total: 4407						<b>10.33</b>	<b>136.92</b>	<b>831.78</b>

4410



#### Master Bedroom

Height: 9'

446.61 SF Walls  
624.04 SF Walls & Ceiling  
19.71 SY Flooring  
53.50 LF Ceil. Perimeter

177.43 SF Ceiling  
177.43 SF Floor  
50.67 LF Floor Perimeter

**Door** 2' 10" X 6' 8" Opens into MASTER\_BATHR  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,962. 5/8" drywall - hung, taped, floated, ready for paint	128.00 SF		0.00	2.87	8.62	73.48	449.46
1,963. Batt insulation - 4" - R11-unfaced batt	83.00 SF		0.00	0.70	3.09	11.62	72.81
<i>Walls</i>							
1,964. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
1,965. Paint the walls and ceiling - two coats	624.04 SF		0.00	1.36	13.80	169.74	1,032.23
<i>Walls</i>							
1,966. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
1,967. Paint the walls and ceiling - two coats	624.04 SF		0.00	1.36	13.80	169.74	1,032.23
1,968. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
<b>Totals: Master Bedroom</b>					<b>53.46</b>	<b>507.16</b>	<b>3,096.37</b>



### Bedroom

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**3' X 6' 8"**

**Opens into LIVING\_ROOM**

**Door**

**2' 8" X 6' 8"**

**Opens into WALKIN\_CLOS1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,969. 5/8" drywall - hung, taped, floated, ready for paint	176.00 SF		0.00	2.87	11.85	101.02	617.99
1,970. Batt insulation - 4" - R11-unfaced batt	83.00 SF		0.00	0.70	3.09	11.62	72.81
<i>Walls</i>							
1,971. Blown-in insulation - 10" depth - R26	136.10 SF		0.00	1.12	10.26	30.48	193.17
<i>Ceiling</i>							
1,972. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
1,973. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,974. Paint the walls and ceiling - two coats <i>Walls</i>	502.33 SF		0.00	1.36	11.11	136.64	830.92
1,975. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
1,976. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
1,977. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					52.66	386.28	2,370.33



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM2
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,978. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	180.00 SF		0.00	2.87	12.12	103.32	632.04
1,979. Batt insulation - 10" - R30 - unfaced batt <i>Walls</i>	180.00 SF		0.00	1.57	18.63	56.52	357.75
1,980. Crown molding - 3 1/4"	22.00 LF		0.00	4.40	3.67	19.36	119.83
1,981. Paint crown molding - one coat	123.33 LF		0.00	1.48	1.36	36.50	220.39




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,982. Baseboard - 3 1/4"	18.00 LF		0.00	3.49	2.62	12.56	78.00
1,983. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
1,984. Trim board - 1" x 2" - installed (pine)	108.42 LF		0.00	2.96	12.31	64.18	397.41
1,985. Casing - 2 1/4"	21.00 LF		0.00	2.23	2.45	9.36	58.64
1,986. Seal & paint base shoe or quarter round	15.00 LF		0.00	1.19	0.17	3.58	21.60
1,987. Paint casing - one coat	LF		0.00	1.44	0.00	0.00	0.00
1,988. Seal/prime then paint the walls twice (3 coats)	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
1,989. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
1,990. Paint the ceiling - two coats	486.47 SF		0.00	1.36	10.76	132.32	804.68
1,991. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
Totals: Living Room					90.89	855.80	5,225.56



### Entry

Height: 9'

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

Door

3' X 6' 8"

Opens into Exterior

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,992. Paint the walls - two coats	62.50 SF		0.00	1.36	1.38	17.00	103.38
1,993. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
1,994. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
1,995. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
1,996. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
Totals: Entry					2.01	31.58	191.58



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 4410

199.02

1,780.82

10,883.84

### 4411



### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
1,997. Paint the walls and ceiling - two coats	624.04 SF		0.00	1.36	13.80	169.74	1,032.23	
1,998. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33	
1,999. Detach & Reset In-wall / In-ceiling speaker	1.00 EA	18.44	0.00	0.00	0.00	3.68	22.12	
2,000. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41	
2,001. Final cleaning - construction - Commercial	177.43 SF		0.00	0.27	0.00	9.58	57.49	
<b>Totals: Master Bedroom</b>						14.69	231.64	1,404.58

Door

2' 10" X 6' 8"

Opens into MASTER\_BATHR

Window


4' X 4'

Opens into Exterior



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM2
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,002. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,003. Paint the walls - two coats	823.56 SF		0.00	1.36	18.21	224.00	1,362.25
2,004. Final cleaning - construction - Commercial	481.31 SF		0.00	0.27	0.00	26.00	155.95
Totals: Living Room					18.54	267.80	1,625.35
Total: 4411					33.23	499.44	3,029.93

4412



**Master Bedroom**

**Height: 9'**

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

Door	2' 10" X 6' 8"	Opens into MASTER_BATHR
Window	4' X 4'	Opens into Exterior



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,005. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	93.00 SF		0.00	2.87	6.26	53.38	326.55
2,006. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	93.00 SF		0.00	1.07	5.98	19.90	125.39
2,007. Paint the walls - two coats <i>walls</i>	446.61 SF		0.00	1.36	9.87	121.48	738.74
2,008. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
2,009. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,010. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
2,011. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	19.00 SF		0.00	2.87	1.28	10.90	66.71
2,012. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	177.43 SF		0.00	1.12	13.37	39.74	251.83
2,013. Paint the ceiling - two coats <i>Ceiling</i>	177.43 SF		0.00	1.36	3.92	48.26	293.48
2,014. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,015. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
2,016. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,017. Clean and deodorize carpet	177.43 SF		0.00	0.57	0.00	20.22	121.36
2,018. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
Totals: Master Bedroom					46.13	417.60	2,551.90



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**3' X 6' 8"**

**Opens into LIVING\_ROOM2**

**Door**

**2' 8" X 6' 8"**


**Opens into WALKIN\_CLOS1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,019. 5/8" drywall - hung, taped, floated, ready for paint	161.05 SF		0.00	2.87	10.84	92.44	565.49
<i>Ceiling and walls</i>							
2,020. Batt insulation - 4" - R11- unfaced batt	366.22 SF		0.00	0.70	13.62	51.28	321.25
<i>Walls</i>							
2,021. Blown-in insulation - 10" depth - R26	161.05 SF		0.00	1.12	12.14	36.08	228.60
<i>Ceiling</i>							
2,022. Seal/prime then paint the walls and ceiling twice (3 coats)	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
<i>Ceiling</i>							
2,023. Baseboard - 4 1/4"	4.00 LF		0.00	4.14	0.81	3.32	20.69
2,024. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
2,025. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,026. Seal the walls and ceiling w/latex based stain blocker - one coat	502.33 SF		0.00	0.91	3.53	91.42	552.07
2,027. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
2,028. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,029. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
2,030. Clean and deodorize carpet	136.10 SF		0.00	0.57	0.00	15.52	93.10
2,031. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
2,032. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
<b>Totals: Bedroom</b>					<b>58.46</b>	<b>575.70</b>	<b>3,512.69</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom

**Height: 9'**

310.89 SF Walls  
390.74 SF Walls & Ceiling  
8.87 SY Flooring  
38.00 LF Ceil. Perimeter

79.85 SF Ceiling  
79.85 SF Floor  
33.33 LF Floor Perimeter


**Door** **1' 8" X 6' 8"** **Opens into LINEN\_CLOSET**  
**Door** **3' X 6' 8"** **Opens into LIVING\_ROOM2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,033. Detach & Reset Shower door	1.00 EA	99.01	0.00	0.00	0.00	19.80	118.81
2,034. Waterproof panel shower surround w/trim - up to 98 SF	1.00 EA		0.00	444.31	12.64	88.86	545.81
2,035. Detach & Reset Shower faucet	1.00 EA	83.42	0.00	0.00	0.00	16.68	100.10
2,036. 1/2" water rock - hung, taped, floated, ready for paint	88.00 SF		0.00	2.88	6.19	50.68	310.31
<i>Walls</i>							
2,037. Batt insulation - 6" - R19 - unfaced batt	88.00 SF		0.00	1.07	5.66	18.84	118.66
<i>Walls</i>							
2,038. Bathroom mirror - Detach & reset	22.00 SF		0.00	9.37	0.00	41.22	247.36
2,039. Seal/prime then paint the walls twice (3 coats)	310.89 SF		0.00	1.84	8.75	114.40	695.19
<i>Walls</i>							
2,040. Seal & paint baseboard - two coats	33.33 LF		0.00	2.24	0.37	14.94	89.97
2,041. Seal & paint base shoe or quarter round	33.33 LF		0.00	1.19	0.37	7.94	47.97
2,042. Paint the ceiling - two coats	79.85 SF		0.00	1.36	1.77	21.72	132.09
2,043. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,044. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64
2,045. Detach & Reset Towel bar	1.00 EA	16.99	0.00	0.00	0.00	3.40	20.39
2,046. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
2,047. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
2,048. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
2,049. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
<b>Totals: Bathroom</b>					<b>39.95</b>	<b>492.84</b>	<b>2,996.89</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM2
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,050. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	82.00 SF		0.00	2.87	5.52	47.06	287.92
2,051. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	82.00 SF		0.00	1.07	5.27	17.54	110.55
2,052. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
2,053. Paint the ceiling - two coats	486.47 SF		0.00	1.36	10.76	132.32	804.68
2,054. Baseboard - 4 1/4" Kitchen and living room.	108.42 LF		0.00	4.14	22.01	89.78	560.65
2,055. Casing - 2 1/4"	LF		0.00	2.23	0.00	0.00	0.00
2,056. Crown molding - 3 1/4"	22.00 LF		0.00	4.40	3.67	19.36	119.83
2,057. Trim board - 1" x 2" - installed (pine)	22.00 LF		0.00	2.96	2.50	13.02	80.64
2,058. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
2,059. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,060. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
Kitchen and Living Room.							
2,061. Paint door/window trim & jamb - 2 coats (per side)	4.00 EA		0.00	45.71	1.83	36.56	221.23
2,062. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
2,063. Floor preparation for resilient flooring	481.31 SF		0.00	0.71	4.84	68.34	414.91
2,064. Vinyl plank flooring	481.31 SF		0.00	5.74	144.63	552.54	3,459.89
2,065. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
Totals: Living Room					227.83	1,411.44	8,696.46



### Entry

Height: 9'

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM2

Door

3' X 6' 8"

Opens into Exterior

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,066. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
2,067. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
2,068. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,069. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
2,070. Floor preparation for resilient flooring	19.51 SF		0.00	0.71	0.20	2.78	16.83
2,071. Vinyl plank flooring	19.51 SF		0.00	5.74	5.86	22.40	140.25
2,072. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
Totals: Entry					8.50	62.06	380.92



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 4412

**380.87      2,959.64      18,138.86**

### Garage/Storage

#### B04G1

**LxWxH 22' x 10' x 9'**




576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,073. Door knob - interior	2.00 EA		0.00	41.58	4.30	16.64	104.10
2,074. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
2,075. Paint the walls - two coats	576.00 SF		0.00	1.36	12.74	156.68	952.78
2,076. Interior door unit	2.00 EA		0.00	269.19	41.87	107.68	687.93
2,077. Paint the ceiling - two coats	220.00 SF		0.00	1.36	4.86	59.84	363.90
2,078. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
2,079. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
<b>Totals: B04G1</b>					<b>66.88</b>	<b>399.46</b>	<b>2,463.58</b>

#### B451

**LxWxH 22' x 10' x 9'**




576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,080. 5/8" drywall - hung, taped, floated, ready for paint	125.00 SF		0.00	2.87	8.42	71.76	438.93
2,081. Fluorescent - four tube - 4' - strip light	1.00 EA		0.00	113.24	6.43	22.64	142.31
2,082. Sprinkler head with escutcheon	2.00 EA		0.00	32.27	4.89	12.90	82.33
2,083. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
<b>Totals: B451</b>					<b>19.74</b>	<b>122.26</b>	<b>753.33</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### B452

LxWxH 22' x 10' x 9'

576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,084. Paint the walls and ceiling - two coats	796.00 SF		0.00	1.36	17.60	216.52	1,316.68
2,085. Fluorescent - four tube - 4' - strip light	1.00 EA		0.00	113.24	6.43	22.64	142.31
2,086. Mask the walls per square foot - plastic and tape - 4 mil	576.00 SF		0.00	0.35	2.89	40.32	244.81
2,087. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B452					26.92	294.44	1,793.56



### B04G3

LxWxH 22' x 10' x 9'


576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,088. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,089. Paint the walls and ceiling - two coats	796.00 SF		0.00	1.36	17.60	216.52	1,316.68
2,090. Fluorescent - four tube - 4' - strip light	1.00 EA		0.00	113.24	6.43	22.64	142.31
2,091. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B04G3					24.36	271.92	1,655.90



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### B04G4

LxWxH 22' x 10' x 9'

576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,092. 5/8" drywall - hung, taped, floated, ready for paint	110.00 SF		0.00	2.87	7.41	63.14	386.25
2,093. Batt insulation - 6" - R19 - unfaced batt	576.00 SF		0.00	1.07	37.05	123.26	776.63
2,094. Fluorescent - four tube - 4' - strip light	1.00 EA		0.00	113.24	6.43	22.64	142.31
2,095. Smoke detector	1.00 EA		0.00	60.60	2.82	12.12	75.54
2,096. Overhead (garage) door opener	1.00 EA		0.00	449.61	23.93	89.92	563.46
2,097. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B04G4					77.64	326.04	2,033.95
Total: Garage/Storage					<b>215.54</b>	<b>1,414.12</b>	<b>8,700.32</b>
Total: Building 4 Interiors					<b>2,373.84</b>	<b>17,684.40</b>	<b>108,479.61</b>

### Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,098. 5/8" - drywall per LF - up to 2' tall	216.00 LF		0.00	11.45	30.83	494.64	2,998.67
2,099. 5/8" drywall - hung, taped, floated, ready for paint	451.00 SF		0.00	2.87	30.37	258.88	1,583.62
<i>Ceiling</i>							
2,100. Seal/prime then paint the surface area twice (3 coats)	25,116.00 SF		0.00	1.84	706.76	9,242.68	56,162.88
<i>Estimated allowance</i>							
2,101. Electrician - per hour	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
<i>Labor to detach and reset misc to prep for paint.</i>							
2,102. Painter - per hour	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
<i>Misc labor to prep for paint.</i>							
2,103. Carpenter - General Framing - per hour	30.00 HR		0.00	72.00	0.00	432.00	2,592.00



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Labor to install drywall nailers.</i>							
Totals: Corridors/Hallways					767.96	11,694.64	70,935.85

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,104. Clean with pressure/chemical spray	25,080. SF 00		0.00	0.43	25.21	2,156.88	12,966.49
2,105. Exterior - paint two coats	25,080. SF 00		0.00	1.58	806.57	7,925.28	48,358.25
2,106. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
2,107. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
2,108. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
2,109. R&R Window screen, 1 - 9 SF	32.00 EA		4.74	36.30	100.82	262.66	1,676.76
2,110. Reglaze window, 1 - 9 sf	2.00 EA		0.00	78.39	7.96	31.36	196.10
2,111. R&R Gutter / downspout - aluminum - 7" to 8"	473.00 LF		0.63	17.54	623.68	1,718.88	10,936.97
<b>299 LF Downspout 174 LF Gutters</b>							
2,112. R&R Light fixture - wall sconce - High grade	2.00 EA		10.49	155.78	24.12	66.52	423.18
2,113. R&R Overhead door & hardware - 9' x 7'	1.00 EA		82.04	934.67	65.56	203.34	1,285.61
Totals: Exteriors					1,798.14	16,272.76	99,434.62

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,158. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR						AS INCURRED
2,159. Telehandler/forklift and operator	160.00 HR						AS INCURRED
2,160. Scaffolding	25,080. EA 00		0.00	0.50	504.11	2,508.00	15,552.11



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,161. Commercial Supervision / Project Management - per hour	182.00 HR		0.00	68.91	0.00	2,508.32	15,049.94
2,162. General Laborer - per hour	1,120.00 HR		0.00	37.61	0.00	8,424.64	50,547.84
2,163. Temporary toilet (per month)	12.00 MO						AS INCURRED
2,164. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
2,165. Hand wash station	6.00 MO						AS INCURRED
2,166. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
2,167. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
2,168. OSHA compliance safety monitor- per hour	HR						AS INCURRED
2,169. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
2,170. Overhead safety monitor - per hour	HR						AS INCURRED
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
2,171. Taxes, insurance, permits & fees (Bid Item)	1.00 EA						AS INCURRED
2,172. Light bulb - Incand. standard bulb - 1000 hr - mat. only	21.00 EA		0.00	0.79	1.67	3.32	21.58
2,173. Light bulb - Compact Fluorescent twist - mat. only	6.00 EA		0.00	4.58	2.76	5.50	35.74
Totals: GENERAL CONDITIONS					568.54	13,683.52	82,669.65
Total: SAULET-BLDG-04-V5_23					<b>5,508.48</b>	<b>59,335.32</b>	<b>361,519.73</b>

### SAULET-BLDG-05-V5\_23

#### Building 5 Interiors

5101



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Master Bedroom**

**Height: 8'**

296.67 SF Walls	133.13 SF Ceiling
429.79 SF Walls & Ceiling	133.13 SF Floor
14.79 SY Flooring	37.67 LF Floor Perimeter
46.17 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into MASTER_WALK</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BATHR</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,174. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,175. Seal/prime then paint the walls and ceiling twice (3 coats)	429.79 SF		0.00	1.84	12.09	158.16	961.06
2,176. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,177. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,178. Mask the floor per square foot - plastic and tape - 4 mil	133.13 SF		0.00	0.35	0.67	9.32	56.59
2,179. Final cleaning - construction - Residential	133.13 SF		0.00	0.34	0.00	9.06	54.32

Totals: Master Bedroom 13.09    234.32    1,419.01

Total: 5101 **13.09    234.32    1,419.01**

**5102**



**Bedroom**

**Height: 8'**

278.00 SF Walls	110.63 SF Ceiling
388.63 SF Walls & Ceiling	110.63 SF Floor
12.29 SY Flooring	35.67 LF Floor Perimeter
42.17 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into BEDROOM_CLOS</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,180. 5/8" drywall - hung, taped, floated, ready for paint	30.00 SF		0.00	2.87	2.02	17.22	105.34
2,181. Batt insulation - 6" - R19 - unfaced batt	30.00 SF		0.00	1.07	1.93	6.42	40.45
2,182. Baseboard - 3 1/4"	35.67 LF		0.00	3.49	5.20	24.90	154.59
2,183. Seal & paint baseboard - two coats	35.67 LF		0.00	2.24	0.39	15.98	96.27
2,184. Paint the walls - two coats	278.00 SF		0.00	1.36	6.15	75.62	459.85
2,185. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,186. Mask the floor per square foot - plastic and tape - 4 mil	110.63 SF		0.00	0.35	0.56	7.74	47.02
2,187. Final cleaning - construction - Residential	110.63 SF		0.00	0.34	0.00	7.52	45.13
Totals: Bedroom					17.16	173.68	1,059.26



### Bathroom

Height: 8'

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	

Door 2' 4" X 6' 8"

Opens into LINEN\_CLOSET

Door 2' 5" X 6' 8"

Opens into KITCHEN\_\_DI

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,188. 5/8" drywall - hung, taped, floated, ready for paint	4.00 SF		0.00	2.87	0.27	2.30	14.05
2,189. Batt insulation - 6" - R19 - unfaced batt	4.00 SF		0.00	1.07	0.26	0.86	5.40
2,190. Paint the walls - two coats	287.00 SF		0.00	1.36	6.35	78.06	474.73
2,191. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,192. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,193. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
2,194. Seal & paint baseboard - two coats	35.08 LF		0.00	2.24	0.39	15.72	94.69
2,195. Seal & paint base shoe or quarter round	35.08 LF		0.00	1.19	0.39	8.36	50.50




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,196. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
Totals: Bathroom					22.55	198.74	1,214.90
Total: 5102					<b>39.71</b>	<b>372.42</b>	<b>2,274.16</b>

### 5110



#### Master Bedroom

**Height: 8'**

296.67 SF Walls	133.13 SF Ceiling
429.79 SF Walls & Ceiling	133.13 SF Floor
14.79 SY Flooring	37.67 LF Floor Perimeter
46.17 LF Ceil. Perimeter	

#### Window

4' X 4'

Opens into Exterior

#### Door

3' X 6' 8"

Opens into LIVING\_ROOM

#### Door

2' 6" X 6' 8"

Opens into MASTER\_WALK

#### Door

3' X 6' 8"

Opens into MASTER\_BATHR

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,197. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45
2,198. Batt insulation - 8" - R25 - unfaced batt	40.00 SF		0.00	1.43	3.26	11.44	71.90
2,199. Seal/prime then paint the ceiling twice (3 coats)	133.13 SF		0.00	1.84	3.75	49.00	297.71
2,200. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,201. Mask the floor per square foot - plastic and tape - 4 mil	133.13 SF		0.00	0.35	0.67	9.32	56.59
2,202. Final cleaning - construction - Residential	133.13 SF		0.00	0.34	0.00	9.06	54.32
Totals: Master Bedroom					10.37	138.00	838.30



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Master Bathroom

Height: 8'

258.44 SF Walls	70.83 SF Ceiling
329.28 SF Walls & Ceiling	70.83 SF Floor
7.87 SY Flooring	31.50 LF Floor Perimeter
36.33 LF Ceil. Perimeter	

Door	1' 10" X 6' 8"	Opens into LINEN_CLOSE1
Door	3' X 6' 8"	Opens into MASTER_BEDRO

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,203. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
2,204. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
2,205. Paint the walls - two coats	258.44 SF		0.00	1.36	5.71	70.30	427.49
2,206. Baseboard - 3 1/4"	31.50 LF		0.00	3.49	4.59	21.98	136.51
2,207. Seal & paint baseboard - two coats	31.50 LF		0.00	2.24	0.35	14.12	85.03
2,208. Seal & paint base shoe or quarter round	31.50 LF		0.00	1.19	0.35	7.50	45.34
2,209. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,210. Mask the floor per square foot - plastic and tape - 4 mil	70.83 SF		0.00	0.35	0.36	4.96	30.11
2,211. Final cleaning - construction - Residential	70.83 SF		0.00	0.34	0.00	4.82	28.90
Totals: Master Bathroom					13.13	140.70	857.28



### Living Room

Height: 8'

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

Door	2' 6" X 6' 8"	Opens into BEDROOM
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into MASTER_BEDRO
Missing Wall	15' X 8'	Opens into KITCHEN_DI




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,212. Paint the ceiling - two coats	141.03 SF		0.00	1.36	3.12	38.36	233.28
2,213. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
2,214. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
Totals: Living Room					3.83	57.84	350.78



### Kitchen / Dining

Height: 8'

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

Missing Wall	15' X 8'	Opens into LIVING_ROOM
Door	2' 5" X 6' 8"	Opens into BATHROOM
Door	2' 4" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	6' 11" X 4'	Opens into KITCHEN__DI
Missing Wall - Goes to Ceiling	2' 7" X 4'	Opens into KITCHEN__DI
Door	1' 5" X 6' 8"	Opens into CLOSET
Door	3' X 6' 8"	Opens into Exterior
Door	4' X 6' 8"	Opens into UTILITY_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,215. 5/8" drywall - hung, taped, floated, ready for paint	17.00 SF		0.00	2.87	1.14	9.76	59.69
2,216. Batt insulation - 8" - R25 - unfaced batt	17.00 SF		0.00	1.43	1.38	4.86	30.55
2,217. Paint the ceiling - two coats	217.96 SF		0.00	1.36	4.82	59.28	360.53
2,218. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
2,219. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
Totals: Kitchen / Dining					8.42	103.56	629.80
Total: 5110					35.75	440.10	2,676.16

5210



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Master Bathroom**

**Height: 8'**

258.44 SF Walls	70.83 SF Ceiling
329.28 SF Walls & Ceiling	70.83 SF Floor
7.87 SY Flooring	31.50 LF Floor Perimeter
36.33 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into LINEN_CLOSE1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,220. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
2,221. Batt insulation - 8" - R25 - unfaced batt	2.00 SF		0.00	1.43	0.16	0.58	3.60
2,222. Paint the ceiling - two coats	70.83 SF		0.00	1.36	1.57	19.26	117.16
2,223. Mask the floor per square foot - plastic and tape - 4 mil	70.83 SF		0.00	0.35	0.36	4.96	30.11
2,224. Final cleaning - construction - Residential	70.83 SF		0.00	0.34	0.00	4.82	28.90
<b>Totals: Master Bathroom</b>					<b>2.22</b>	<b>30.76</b>	<b>186.78</b>



**Living Room**

**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,225. Paint the walls and ceiling - two coats	373.69 SF		0.00	1.36	8.26	101.64	618.12
2,226. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
2,227. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,228. Detach & Reset Chandelier	1.00 EA	132.21	0.00	0.00	0.00	26.44	158.65
2,229. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
2,230. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
Totals: Living Room					10.21	179.06	1,084.51



### Kitchen / Dining

Height: 8'

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

Missing Wall	15' X 8'	Opens into LIVING_ROOM
Door	2' 5" X 6' 8"	Opens into BATHROOM
Door	2' 4" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	6' 11" X 4'	Opens into KITCHEN__DI
Missing Wall - Goes to Ceiling	2' 7" X 4'	Opens into KITCHEN__DI
Door	1' 5" X 6' 8"	Opens into CLOSET
Door	3' X 6' 8"	Opens into Exterior
Door	4' X 6' 8"	Opens into UTILITY_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,231. 5/8" drywall - hung, taped, floated, ready for paint	45.00 SF		0.00	2.87	3.03	25.84	158.02
2,232. Batt insulation - 8" - R25 - unfaced batt	30.00 SF		0.00	1.43	2.44	8.58	53.92
2,233. Paint the walls and ceiling - two coats	631.29 SF		0.00	1.36	13.96	171.72	1,044.23
2,234. Batt insulation - 6" - R19 - unfaced batt	15.00 SF		0.00	1.07	0.96	3.22	20.23
2,235. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,236. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,237. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,238. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen / Dining

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,239. Seal & paint base shoe or quarter round	58.56 LF		0.00	1.19	0.65	13.94	84.28
2,240. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
2,241. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
Totals: Kitchen / Dining					37.66	341.94	2,089.11
Total: 5210					<b>50.09</b>	<b>551.76</b>	<b>3,360.40</b>

### 5301



### Living Room

Height: 8'

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,242. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
2,243. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
2,244. Baseboard - 3 1/4"	29.50 LF		0.00	3.49	4.30	20.60	127.86
2,245. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
2,246. Paint the walls - two coats	232.67 SF		0.00	1.36	5.14	63.28	384.85
2,247. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,248. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
2,249. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
Totals: Living Room					14.03	150.62	917.65



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen / Dining


**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,250. Paint the walls - two coats	413.33 SF		0.00	1.36	9.14	112.42	683.69
2,251. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06
2,252. Seal & paint base shoe or quarter round	58.56 LF		0.00	1.19	0.65	13.94	84.28
2,253. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
2,254. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
<b>Totals: Kitchen / Dining</b>					<b>11.52</b>	<b>182.26</b>	<b>1,105.06</b>
<b>Total: 5301</b>					<b>25.55</b>	<b>332.88</b>	<b>2,022.71</b>

5302



### Bathroom

**Height: 8'**

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,255. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
2,256. Batt insulation - 8" - R25 - unfaced batt	12.00 SF		0.00	1.43	0.98	3.44	21.58
2,257. Paint the ceiling - two coats	65.56 SF		0.00	1.36	1.45	17.84	108.45
2,258. Mask the floor per square foot - plastic and tape - 4 mil	65.56 SF		0.00	0.35	0.33	4.60	27.88
2,259. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
<b>Totals: Bathroom</b>					<b>3.57</b>	<b>37.22</b>	<b>226.79</b>
<b>Total: 5302</b>					<b>3.57</b>	<b>37.22</b>	<b>226.79</b>

5303



### Kitchen

Height: 9'

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,260. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
2,261. Paint the ceiling - two coats	136.58 SF		0.00	1.36	3.02	37.16	225.93
2,262. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
<b>Totals: Kitchen</b>					<b>3.69</b>	<b>46.54</b>	<b>282.87</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,263. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
2,264. Paint the ceiling - two coats	384.72 SF		0.00	1.36	8.51	104.64	636.37
2,265. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
<b>Totals: Living / Dining Room</b>					<b>10.44</b>	<b>131.64</b>	<b>800.29</b>
<b>Total: 5303</b>					<b>14.13</b>	<b>178.18</b>	<b>1,083.16</b>

5304



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,266. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
2,267. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
2,268. Seal/prime then paint the walls twice (3 coats)	232.67 SF		0.00	1.84	6.55	85.62	520.28
2,269. Baseboard - 4 1/4"	18.00 LF		0.00	4.14	3.65	14.90	93.07
2,270. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
2,271. Base shoe	18.00 LF		0.00	1.41	0.90	5.08	31.36
2,272. Seal & paint base shoe or quarter round	29.50 LF		0.00	1.19	0.33	7.02	42.46
2,273. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,274. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
<b>Totals: Living Room</b>					<b>15.31</b>	<b>169.48</b>	<b>1,032.16</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen / Dining

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,275. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,276. Batt insulation - 4" - R11- unfaced batt	8.00 SF		0.00	0.70	0.30	1.12	7.02
2,277. Paint the walls - two coats	413.33 SF		0.00	1.36	9.14	112.42	683.69
2,278. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06
2,279. Seal & paint base shoe or quarter round	58.56 LF		0.00	1.19	0.65	13.94	84.28
2,280. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69

Totals: Kitchen / Dining 11.07    186.14    1,127.89


Total: 5304 **26.38    355.62    2,160.05**

5309



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,281. Paint the walls and ceiling - two coats	522.56 SF		0.00	1.36	11.55	142.14	864.37
2,282. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
2,283. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
2,284. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
2,285. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					13.48	199.52	1,210.48



### Bedroom 1

**Height: 9'**

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,286. 5/8" drywall - hung, taped, ready for texture	48.00 SF		0.00	2.53	3.18	24.28	148.90



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,287. Batt insulation - 4" - R13 - paper / foil faced	48.00 SF		0.00	1.07	3.47	10.28	65.11
2,288. Baseboard - 4 1/4"	12.00 LF		0.00	4.14	2.44	9.94	62.06
2,289. Seal & paint baseboard - two coats	41.67 LF		0.00	2.24	0.46	18.66	112.46
2,290. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
2,291. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
2,292. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84
2,293. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,294. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,295. Mask the walls per square foot - plastic and tape - 4 mil	388.22 SF		0.00	0.35	1.95	27.18	165.01
2,296. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
Totals: Bedroom 1					27.51	339.90	2,066.84



### Master Bedroom

Height: 9'

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,297. 5/8" drywall - hung, taped, ready for texture	48.00 SF		0.00	2.53	3.18	24.28	148.90
2,298. Batt insulation - 4" - R13 - paper / foil faced	48.00 SF		0.00	1.07	3.47	10.28	65.11
2,299. Baseboard - 4 1/4"	11.33 LF		0.00	4.14	2.30	9.38	58.59
2,300. Paint baseboard - two coats	50.50 LF		0.00	2.16	0.66	21.82	131.56
2,301. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
2,302. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,303. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,304. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,305. Mask the floor per square foot - plastic and tape - 4 mil	161.67 SF		0.00	0.35	0.81	11.32	68.71
2,306. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
Totals: Master Bedroom					11.57	133.74	813.92



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,307. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,308. Batt insulation - 4" - R13 - paper / foil faced	8.00 SF		0.00	1.07	0.58	1.72	10.86
2,309. Baseboard - 4 1/4"	18.00 LF		0.00	4.14	3.65	14.90	93.07
2,310. Casing - 2 1/4"	16.00 LF		0.00	2.23	1.87	7.14	44.69
2,311. Quarter round - 3/4"	68.42 LF		0.00	1.65	5.09	22.58	140.56
2,312. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84
2,313. Seal/prime then paint the walls twice (3 coats)	655.11 SF		0.00	1.84	18.43	241.08	1,464.91




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,314. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,315. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
2,316. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
2,317. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
2,318. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	18.80	0.00	7.52	45.12
2,319. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
2,320. In-wall / In-ceiling speaker - Detach & reset	3.00 EA		0.00	18.44	0.00	11.06	66.38
2,321. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
2,322. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
2,323. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>35.46</b>	<b>465.50</b>	<b>2,828.38</b>
<b>Total: 5309</b>					<b>88.02</b>	<b>1,138.66</b>	<b>6,919.62</b>

**5311**



**Kitchen / Dining**

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

Missing Wall	15' X 8'	Opens into LIVING_ROOM
Door	2' 5" X 6' 8"	Opens into BATHROOM2
Door	2' 4" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	6' 11" X 4'	Opens into KITCHEN__DI
Missing Wall - Goes to Ceiling	2' 7" X 4'	Opens into KITCHEN__DI
Door	1' 5" X 6' 8"	Opens into CLOSET
Door	3' X 6' 8"	Opens into Exterior
Door	4' X 6' 8"	Opens into UTILITY_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen / Dining

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,324. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,325. Paint the walls - two coats	413.33 SF		0.00	1.36	9.14	112.42	683.69
2,326. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
Totals: Kitchen / Dining					9.47	144.84	878.53



### Bathroom

Height: 8'

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	

**Door** 2' 4" X 6' 8" Opens into LINEN\_CLOSET

**Door** 2' 5" X 6' 8" Opens into KITCHEN\_DI


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,327. Paint the walls - two coats	287.00 SF		0.00	1.36	6.35	78.06	474.73
2,328. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
Totals: Bathroom					6.35	82.52	501.48
Total: 5311					15.82	227.36	1,380.01

5312



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen / Dining

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM2</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,329. Paint the ceiling - two coats	217.96 SF		0.00	1.36	4.82	59.28	360.53
2,330. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
2,331. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
<b>Totals: Kitchen / Dining</b>					<b>5.90</b>	<b>88.94</b>	<b>539.56</b>



### Bathroom

**Height: 8'**

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,332. Mask the floor per square foot - plastic and tape - 4 mil	65.56 SF		0.00	0.35	0.33	4.60	27.88
2,333. Paint the walls - two coats	287.00 SF		0.00	1.36	6.35	78.06	474.73
2,334. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
<b>Totals: Bathroom</b>					<b>6.68</b>	<b>87.12</b>	<b>529.36</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room


**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,335. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
2,336. Paint the ceiling - two coats	141.03 SF		0.00	1.36	3.12	38.36	233.28
2,337. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
<b>Totals: Living Room</b>					<b>3.83</b>	<b>57.84</b>	<b>350.78</b>
<b>Total: 5312</b>					<b>16.41</b>	<b>233.90</b>	<b>1,419.70</b>

5403



### Utility Room

**Height: 8'**

88.00 SF Walls	11.67 SF Ceiling
99.67 SF Walls & Ceiling	11.67 SF Floor
1.30 SY Flooring	10.33 LF Floor Perimeter
14.33 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into KITCHEN__DI</b>
-------------	-------------------	-------------------------------

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,338. Mask the floor per square foot - plastic and tape - 4 mil	11.67 SF		0.00	0.35	0.06	0.82	4.96
2,339. Paint the ceiling - two coats	11.67 SF		0.00	1.36	0.26	3.18	19.31
2,340. Final cleaning - construction - Residential	11.67 SF		0.00	0.34	0.00	0.80	4.77
<b>Totals: Utility Room</b>					<b>0.32</b>	<b>4.80</b>	<b>29.04</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 5403

0.32

4.80

29.04

5404



### Bedroom 1

Height: 9'

388.22 SF Walls  
528.19 SF Walls & Ceiling  
15.55 SY Flooring  
47.33 LF Ceil. Perimeter

139.97 SF Ceiling  
139.97 SF Floor  
41.67 LF Floor Perimeter

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,341. 5/8" drywall - hung, taped, floated, ready for paint	30.00 SF		0.00	2.87	2.02	17.22	105.34
2,342. Batt insulation - 8" - R25 - unfaced batt	30.00 SF		0.00	1.43	2.44	8.58	53.92
2,343. Paint the ceiling - two coats	139.97 SF		0.00	1.36	3.09	38.08	231.53
2,344. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,345. Mask the floor per square foot - plastic and tape - 4 mil	139.97 SF		0.00	0.35	0.70	9.80	59.49
2,346. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
<b>Totals: Bedroom 1</b>					8.25	119.42	724.72

Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS

Door

3' X 6' 8"

Opens into LIVING\_\_DI2



### Master Bedroom

Height: 9'

450.94 SF Walls  
612.61 SF Walls & Ceiling  
17.96 SY Flooring  
55.83 LF Ceil. Perimeter

161.67 SF Ceiling  
161.67 SF Floor  
50.50 LF Floor Perimeter

Door

2' 8" X 6' 8"

Opens into BATHROOM1

Door

2' 8" X 6' 8"

Opens into LIVING\_\_DI2

Window

4' X 4'

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,347. 5/8" drywall - hung, taped, floated, ready for paint	100.00 SF		0.00	2.87	6.73	57.40	351.13
2,348. Batt insulation - 10" - R30 - unfaced batt	50.00 SF		0.00	1.57	5.18	15.70	99.38




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,349. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,350. Seal/prime then paint the ceiling twice (3 coats)	161.67 SF		0.00	1.84	4.55	59.50	361.52
2,351. Paint the walls - two coats	450.94 SF		0.00	1.36	9.97	122.66	745.91
2,352. Clean and deodorize carpet	161.67 SF		0.00	0.57	0.00	18.44	110.59
2,353. Mask the walls per square foot - plastic and tape - 4 mil	450.94 SF		0.00	0.35	2.27	31.56	191.66
2,354. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
<b>Totals: Master Bedroom</b>					<b>28.70</b>	<b>352.48</b>	<b>2,143.49</b>



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,355. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,356. Seal/prime then paint the ceiling twice (3 coats)	136.58 SF		0.00	1.84	3.84	50.26	305.41
2,357. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
2,358. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
2,359. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>13.37</b>	<b>191.40</b>	<b>1,161.80</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,360. 5/8" drywall - hung, taped, floated, ready for paint	120.00 SF		0.00	2.87	8.08	68.88	421.36
2,361. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
Drywall patch for entry.							
2,362. Batt insulation - 8" - R25 - unfaced batt	40.00 SF		0.00	1.43	3.26	11.44	71.90
2,363. Batt insulation - 10" - R30 - unfaced batt	60.00 SF		0.00	1.57	6.21	18.84	119.25
2,364. Crown molding - 4 1/4"	56.00 LF		0.00	4.86	11.26	54.44	337.86
2,365. Trim board - 1" x 2" - installed (pine)	15.00 LF		0.00	2.96	1.70	8.88	54.98
2,366. Seal & paint trim - two coats	15.00 LF		0.00	2.15	0.18	6.46	38.89
2,367. Paint crown molding - one coat	56.00 LF		0.00	1.48	0.62	16.58	100.08
2,368. Paint the walls - two coats	655.11 SF		0.00	1.36	14.48	178.20	1,083.63
2,369. Seal/prime then paint the ceiling twice (3 coats)	384.72 SF		0.00	1.84	10.83	141.58	860.29
2,370. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
2,371. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>58.88</b>	<b>576.20</b>	<b>3,515.87</b>




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Total: 5404

109.20 1,239.50 7,545.88

5405




**Bathroom**

**Height: 9'**

439.50 SF Walls	109.08 SF Ceiling
548.58 SF Walls & Ceiling	109.08 SF Floor
12.12 SY Flooring	45.33 LF Floor Perimeter
58.83 LF Ceil. Perimeter	

- Door** 3' X 6' 8" Opens into ENTRY\_HALL
- Door** 3' X 6' 8" Opens into BEDROOM
- Door** 4' 10" X 6' 8" Opens into CLOSET



**Subroom: Water Closet (1)**

**Height: 9'**

175.72 SF Walls	27.00 SF Ceiling
202.72 SF Walls & Ceiling	27.00 SF Floor
3.00 SY Flooring	18.83 LF Floor Perimeter
21.50 LF Ceil. Perimeter	


- Door** 2' 8" X 6' 8" Opens into BATHROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,372. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
2,373. Paint the walls and ceiling - two coats	751.31 SF		0.00	1.36	16.61	204.36	1,242.75
2,374. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
2,375. Mask the floor per square foot - plastic and tape - 4 mil	136.03 SF		0.00	0.35	0.68	9.52	57.81
2,376. Final cleaning - construction - Residential	136.03 SF		0.00	0.34	0.00	9.26	55.51
<b>Totals: Bathroom</b>					17.29	240.30	1,458.96



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

Height: 9'

397.83 SF Walls	196.81 SF Ceiling
594.64 SF Walls & Ceiling	196.81 SF Floor
21.87 SY Flooring	43.17 LF Floor Perimeter
47.17 LF Ceil. Perimeter	

Door

4' X 6' 8"

Opens into Exterior

Missing Wall

12' 4" X 9'

Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,377. 5/8" drywall - hung, taped, floated, ready for paint	24.00 SF		0.00	2.87	1.62	13.78	84.28
2,378. Batt insulation - 8" - R25 - unfaced batt	24.00 SF		0.00	1.43	1.95	6.86	43.13
2,379. Paint the ceiling - two coats	196.81 SF		0.00	1.36	4.35	53.54	325.55
2,380. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
2,381. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
2,382. Mask the floor per square foot - plastic and tape - 4 mil	196.81 SF		0.00	0.35	0.99	13.78	83.65
2,383. Final cleaning - construction - Residential	196.81 SF		0.00	0.34	0.00	13.38	80.30
Totals: Living / Dining Room					25.04	180.02	1,105.11
Total: 5405					<b>42.33</b>	<b>420.32</b>	<b>2,564.07</b>

5406



### Bedroom

Height: 9'

478.33 SF Walls	190.08 SF Ceiling
668.42 SF Walls & Ceiling	190.08 SF Floor
21.12 SY Flooring	51.33 LF Floor Perimeter
58.33 LF Ceil. Perimeter	

Door

4' X 6' 8"

Opens into Exterior

Door

3' X 6' 8"

Opens into BATHROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,384. In-wall / In-ceiling speaker	1.00 EA		0.00	237.59	18.09	47.52	303.20
2,385. Paint the ceiling - two coats	190.08 SF		0.00	1.36	4.20	51.70	314.41
2,386. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,387. Mask the ceiling per square foot - plastic and tape - 4 mil	190.08 SF		0.00	0.35	0.95	13.30	80.78
2,388. Final cleaning - construction - Commercial	190.08 SF		0.00	0.27	0.00	10.26	61.58
Totals: Bedroom					23.24	132.96	821.00



### Living / Dining Room

Height: 9'


397.83 SF Walls	196.81 SF Ceiling
594.64 SF Walls & Ceiling	196.81 SF Floor
21.87 SY Flooring	43.17 LF Floor Perimeter
47.17 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>12' 4" X 9'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,389. Paint the ceiling - two coats	196.81 SF		0.00	1.36	4.35	53.54	325.55
2,390. Mask the floor per square foot - plastic and tape - 4 mil	196.81 SF		0.00	0.35	0.99	13.78	83.65
2,391. Final cleaning - construction - Residential	196.81 SF		0.00	0.34	0.00	13.38	80.30
Totals: Living / Dining Room					5.34	80.70	489.50

Total: 5406 28.58 213.66 1,310.50

### 5408



### Bathroom

Height: 9'

439.50 SF Walls	109.08 SF Ceiling
548.58 SF Walls & Ceiling	109.08 SF Floor
12.12 SY Flooring	45.33 LF Floor Perimeter
58.83 LF Ceil. Perimeter	


<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into ENTRY_HALL2</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' 10" X 6' 8"</b>	<b>Opens into CLOSET</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom



#### Subroom: Water Closet (1)

Height: 9'


175.72 SF Walls	27.00 SF Ceiling
202.72 SF Walls & Ceiling	27.00 SF Floor
3.00 SY Flooring	18.83 LF Floor Perimeter
21.50 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"			Opens into BATHROOM				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	2,392. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
	2,393. Paint the walls and ceiling - two coats	751.31 SF		0.00	1.36	16.61	204.36	1,242.75
	2,394. Detach & Reset Light bar - 3 lights	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
	2,395. Vinyl tile	136.03 SF		0.00	3.93	29.80	106.92	671.32
	2,396. Baseboard - 4 1/4"	64.17 LF		0.00	4.14	13.03	53.14	331.83
	2,397. Seal & paint baseboard - two coats	64.17 LF		0.00	2.24	0.71	28.74	173.19
	2,398. Base shoe	64.17 LF		0.00	1.41	3.23	18.10	111.81
	2,399. Seal & paint base shoe or quarter round	64.17 LF		0.00	1.19	0.71	15.28	92.35
	2,400. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
	2,401. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
	2,402. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
	2,403. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64
	2,404. Final cleaning - construction - Residential	136.03 SF		0.00	0.34	0.00	9.26	55.51
Totals: Bathroom						66.56	564.36	3,452.53



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry Hall


Height: 9'

205.44 SF Walls	46.14 SF Ceiling
251.58 SF Walls & Ceiling	46.14 SF Floor
5.13 SY Flooring	20.67 LF Floor Perimeter
29.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into ENTRY_CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall</b>	<b>3' 8" X 9'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,405. 5/8" drywall - hung, taped, floated, ready for paint	64.00 SF		0.00	2.87	4.31	36.74	224.73
2,406. Paint the ceiling - two coats	46.14 SF		0.00	1.36	1.02	12.56	76.33
2,407. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
2,408. Mask the floor per square foot - plastic and tape - 4 mil	46.14 SF		0.00	0.35	0.23	3.24	19.62
2,409. Final cleaning - construction - Residential	46.14 SF		0.00	0.34	0.00	3.14	18.83

Totals: Entry Hall 5.56      65.86      400.54



### Kitchen

Height: 9'

397.78 SF Walls	118.44 SF Ceiling
516.22 SF Walls & Ceiling	115.42 SF Floor
12.82 SY Flooring	53.17 LF Floor Perimeter
39.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>3' 8" X 9'</b>	<b>Opens into ENTRY_HALL2</b>
<b>Missing Wall</b>	<b>12' 4" X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1' 9" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,410. Paint the ceiling - two coats	118.44 SF		0.00	1.36	2.62	32.22	195.92
2,411. Mask the floor per square foot - plastic and tape - 4 mil	115.42 SF		0.00	0.35	0.58	8.08	49.06



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,412. Final cleaning - construction - Residential	115.42 SF		0.00	0.34	0.00	7.84	47.08
Totals: Kitchen					3.20	48.14	292.06



### Living / Dining Room

Height: 9'

397.83 SF Walls	196.81 SF Ceiling
594.64 SF Walls & Ceiling	196.81 SF Floor
21.87 SY Flooring	43.17 LF Floor Perimeter
47.17 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>12' 4" X 9'</b>	<b>Opens into KITCHEN</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,413. 5/8" drywall - hung, taped, floated, ready for paint	24.00 SF		0.00	2.87	1.62	13.78	84.28
2,414. Batt insulation - 8" - R25 - unfaced batt	24.00 SF		0.00	1.43	1.95	6.86	43.13
2,415. Paint the ceiling - two coats	196.81 SF		0.00	1.36	4.35	53.54	325.55
2,416. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
2,417. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
2,418. Mask the floor per square foot - plastic and tape - 4 mil	196.81 SF		0.00	0.35	0.99	13.78	83.65
2,419. Final cleaning - construction - Residential	196.81 SF		0.00	0.34	0.00	13.38	80.30
Totals: Living / Dining Room					25.04	180.02	1,105.11
Total: 5408					<b>100.36</b>	<b>858.38</b>	<b>5,250.24</b>

5409



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 9'**

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,420. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45
2,421. Batt insulation - 8" - R25 - unfaced batt	30.00 SF		0.00	1.43	2.44	8.58	53.92
2,422. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
2,423. Baseboard - 3 1/4"	50.50 LF		0.00	3.49	7.36	35.26	218.87
2,424. Seal & paint baseboard - two coats	50.50 LF		0.00	2.24	0.56	22.62	136.30
2,425. Paint the walls and ceiling - two coats	612.61 SF		0.00	1.36	13.54	166.64	1,013.33
2,426. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,427. Detach & Reset Window blind - PVC - 1" - 7.1 to 14 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,428. Mask the floor per square foot - plastic and tape - 4 mil	161.67 SF		0.00	0.35	0.81	11.32	68.71
2,429. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
<b>Totals: Master Bedroom</b>					<b>28.95</b>	<b>312.62</b>	<b>1,904.54</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,430. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
2,431. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
2,432. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
2,433. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
2,434. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
2,435. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
2,436. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,437. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>12.50</b>	<b>180.94</b>	<b>1,098.16</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,438. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
2,439. Batt insulation - 6" - R19 - unfaced batt	6.00 SF		0.00	1.07	0.39	1.28	8.09
2,440. Baseboard - 3 1/4"	68.42 LF		0.00	3.49	9.97	47.76	296.52
2,441. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
2,442. Paint the walls - two coats	655.11 SF		0.00	1.36	14.48	178.20	1,083.63
2,443. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,444. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
2,445. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>28.84</b>	<b>332.72</b>	<b>2,025.07</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom


**Height: 9'**

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 3" X 6' 8"</b>	<b>Opens into ROOM2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,446. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57
2,447. Batt insulation - 6" - R19 - unfaced batt	5.00 SF		0.00	1.07	0.32	1.08	6.75
2,448. Baseboard - 3 1/4"	31.08 LF		0.00	3.49	4.53	21.70	134.70
2,449. Seal & paint baseboard - two coats	31.08 LF		0.00	2.24	0.34	13.92	83.88
2,450. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
2,451. Mask the floor per square foot - plastic and tape - 4 mil	66.75 SF		0.00	0.35	0.34	4.68	28.38
2,452. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
2,453. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24
Totals: Bathroom					13.01	180.64	1,096.73
Total: 5409					<b>83.30</b>	<b>1,006.92</b>	<b>6,124.50</b>

**5410**



### Living Room

**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>




### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

#### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,454. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57
2,455. Batt insulation - 6" - R19 - unfaced batt	5.00 SF		0.00	1.07	0.32	1.08	6.75
2,456. Paint the walls - two coats	232.67 SF		0.00	1.36	5.14	63.28	384.85
2,457. Baseboard - 3 1/4"	29.50 LF		0.00	3.49	4.30	20.60	127.86
2,458. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
2,459. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,460. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,461. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
2,462. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
<b>Totals: Living Room</b>					<b>26.48</b>	<b>188.66</b>	<b>1,158.24</b>



#### Kitchen / Dining

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,463. Paint the walls - two coats	413.33 SF		0.00	1.36	9.14	112.42	683.69
2,464. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06
2,465. Seal & paint base shoe or quarter round	58.56 LF		0.00	1.19	0.65	13.94	84.28




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen / Dining

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,466. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,467. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
2,468. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
Totals: Kitchen / Dining					12.43	200.54	1,215.67
Total: 5410					<b>38.91</b>	<b>389.20</b>	<b>2,373.91</b>

5412



### Kitchen / Dining

Height: 8'

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

Missing Wall	15' X 8'	Opens into LIVING_ROOM
Door	2' 5" X 6' 8"	Opens into BATHROOM
Door	2' 4" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	6' 11" X 4'	Opens into KITCHEN__DI
Missing Wall - Goes to Ceiling	2' 7" X 4'	Opens into KITCHEN__DI
Door	1' 5" X 6' 8"	Opens into CLOSET
Door	3' X 6' 8"	Opens into Exterior
Door	4' X 6' 8"	Opens into UTILITY_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,469. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,470. Seal/prime then paint the ceiling twice (3 coats)	217.96 SF		0.00	1.84	6.13	80.22	487.40
2,471. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,472. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,473. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
2,474. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen / Dining

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen / Dining					7.54	167.66	1,013.47



### Living Room

Height: 8'

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,475. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,476. Seal/prime then paint the ceiling twice (3 coats)	141.03 SF		0.00	1.84	3.97	51.90	315.37
2,477. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,478. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,479. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
2,480. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
Totals: Living Room					5.01	129.16	779.91
Total: 5412					<b>12.55</b>	<b>296.82</b>	<b>1,793.38</b>
Total: Building 5 Interiors					<b>744.07</b>	<b>8,532.02</b>	<b>51,933.29</b>

### Corridors/Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,481. 5/8" drywall - hung, taped, floated, ready for paint	81,512. SF 00		0.00	2.87	5,488.61	46,787.88	286,215.93
<i>Ceiling</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridors/Breezways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,482. Seal/prime then paint the surface area twice (3 coats)	40,756. SF 00		0.00	1.84	1,146.87	14,998.20	91,136.11
<i>Estimated allowance</i>							
2,483. Electrician - per hour	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
<i>Labor to detach and reset misc to prep for paint.</i>							
2,484. Painter - per hour	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
<i>Misc labor to prep for paint.</i>							
2,485. Carpenter - General Framer - per hour	60.00 HR		0.00	72.00	0.00	864.00	5,184.00
<i>Labor to install drywall nailers.</i>							
Totals: Corridors/Breezways					6,635.48	63,916.52	390,134.72

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,486. Clean with pressure/chemical spray	35,080. SF 00		0.00	0.43	35.26	3,016.88	18,136.54
2,487. Exterior - paint two coats	35,080. SF 00		0.00	1.58	1,128.17	11,085.28	67,639.85
2,488. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
2,489. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
2,490. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
2,491. R&R Window screen, 1 - 9 SF	21.00 EA		4.74	36.30	66.16	172.36	1,100.36
2,492. R&R Gutter / downspout - aluminum - 7" to 8"	313.00 LF		0.63	17.54	412.71	1,137.44	7,237.36
<b>80 LF Downspout</b>							
<b>233 LF Gutters</b>							
2,493. R&R Light fixture - wall sconce - High grade	3.00 EA		10.49	155.78	36.18	99.76	634.75
2,494. R&R Clothes dryer vent cover	2.00 EA		4.72	41.86	1.38	18.62	113.16
2,495. Clean with pressure/chemical spray	168.00 SF		0.00	0.43	0.17	14.44	86.85
<b>Three (3) sets of doors.</b>							
Totals: Exteriors					1,824.25	19,452.62	118,540.13



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,537. Crane and operator - 14 ton capacity - 65' extension boom	8.00 HR					AS INCURRED	
2,538. Telehandler/forklift and operator	8.00 HR					AS INCURRED	
2,539. Scaffold - per section (per month)	1.00 MO		0.00	112.88	0.00	22.58	135.46
2,540. Commercial Supervision / Project Management - per hour	288.00 HR		0.00	68.91	0.00	3,969.22	23,815.30
2,541. General Laborer - per hour	80.00 HR		0.00	37.61	0.00	601.76	3,610.56
2,542. Temporary toilet (per month)	4.00 MO					AS INCURRED	
2,543. Temporary power usage (per month) - Commercial	1.00 MO		0.00	197.34	19.83	39.46	256.63
2,544. Hand wash station	4.00 MO					AS INCURRED	
2,545. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
2,546. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
2,547. OSHA compliance safety monitor- per hour	HR					AS INCURRED	
2,548. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
2,549. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
2,550. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
<b>Totals: GENERAL CONDITIONS</b>					<b>20.33</b>	<b>4,748.36</b>	<b>28,510.47</b>
<b>Total: SAULET-BLDG-05-V5_23</b>					<b>9,224.13</b>	<b>96,649.52</b>	<b>589,118.61</b>

### SAULET-BLDG-06-V5\_23

#### Building 6 Interiors

6101



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Entry

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,551. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
2,552. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
2,553. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					<b>4.33</b>	<b>61.68</b>	<b>374.32</b>



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>6' 4" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,554. Paint the walls and ceiling - two coats	267.13 SF		0.00	1.36	5.91	72.66	441.87
2,555. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
2,556. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					5.91	82.24	499.28



### Living Room

Height: 9'

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

Missing Wall	1' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to Ceiling	6' 10" X 5'	Opens into KITCHEN
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	4' 6" X 9'	Opens into ENTRY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,557. 5/8" - drywall per LF - up to 2' tall	9.00 LF		0.00	11.45	1.28	20.62	124.95
2,558. Batt insulation - 4" - R13 - paper / foil faced	18.00 SF		0.00	1.07	1.30	3.86	24.42
2,559. Baseboard - 4 1/4"	17.17 LF		0.00	4.14	3.49	14.22	88.79
2,560. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
2,561. Seal/prime then paint the walls twice (3 coats)	425.08 SF		0.00	1.84	11.96	156.44	950.55
2,562. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
2,563. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
2,564. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,565. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
2,566. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84
2,567. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					20.69	275.90	1,675.91
Total: 6101					30.93	419.82	2,549.51

6103



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

3' X 6' 8"

Opens into LIVING\_ROOM2

Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS1


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,568. 5/8" drywall - hung, taped, floated, ready for paint	120.00 SF		0.00	2.87	8.08	68.88	421.36
2,569. Batt insulation - 6" - R19 - unfaced batt	70.00 SF		0.00	1.07	4.50	14.98	94.38
2,570. Batt insulation - 8" - R25 - unfaced batt	50.00 SF		0.00	1.43	4.07	14.30	89.87
2,571. Seal/prime then paint the walls and ceiling twice (3 coats)	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
2,572. Baseboard - 3 1/4"	41.00 LF		0.00	3.49	5.97	28.62	177.68
2,573. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
2,574. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,575. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,576. Detach & Reset Window blind - PVC - 1" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,577. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,578. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
2,579. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					53.23	466.94	2,854.91
Total: 6103					<b>53.23</b>	<b>466.94</b>	<b>2,854.91</b>

6107



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,580. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
<i>Walls</i>							
2,581. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
<i>Walls</i>							
2,582. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
2,583. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
2,584. Seal/prime then paint the walls twice (3 coats)	385.98 SF		0.00	1.84	10.86	142.04	863.10
<i>Walls</i>							
2,585. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,586. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
2,587. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
2,588. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					17.35	231.30	1,405.06



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,589. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
<i>Walls</i>							
2,590. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
<i>Walls</i>							
2,591. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
2,592. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
2,593. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
2,594. Seal & paint casing - two coats	20.00 LF		0.00	2.26	0.26	9.04	54.50
2,595. Seal/prime then paint the walls twice (3 coats)	655.11 SF		0.00	1.84	18.43	241.08	1,464.91
<i>Walls</i>							
2,596. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,597. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
2,598. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>29.88</b>	<b>382.74</b>	<b>2,326.31</b>
<b>Total: 6107</b>					<b>47.23</b>	<b>614.04</b>	<b>3,731.37</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

6108



### Bedroom

Height: 8'

345.33 SF Walls	127.65 SF Ceiling
472.99 SF Walls & Ceiling	127.65 SF Floor
14.18 SY Flooring	44.67 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

Door

3' X 6' 8"

Opens into LIVING\_\_DIN

Window

4' X 4'


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,599. 5/8" drywall - hung, taped, floated, ready for paint	55.00 SF		0.00	2.87	3.70	31.58	193.13
2,600. Batt insulation - 6" - R19 - unfaced batt	50.00 SF		0.00	1.07	3.22	10.70	67.42
2,601. Batt insulation - 8" - R25 - unfaced batt	5.00 SF		0.00	1.43	0.41	1.44	9.00
2,602. Seal/prime then paint the walls and ceiling twice (3 coats)	472.99 SF		0.00	1.84	13.31	174.06	1,057.67
2,603. Baseboard - 3 1/4"	44.67 LF		0.00	3.49	6.51	31.18	193.59
2,604. Seal & paint baseboard - two coats	44.67 LF		0.00	2.24	0.49	20.02	120.57
2,605. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,606. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,607. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,608. Detach & Reset Window blind - PVC - 1" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,609. Mask the floor per square foot - plastic and tape - 4 mil	127.65 SF		0.00	0.35	0.64	8.94	54.26
2,610. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
Totals: Bedroom					43.62	396.14	2,420.35



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen / Dining

**Height: 8'**

366.78 SF Walls	146.51 SF Ceiling
513.29 SF Walls & Ceiling	144.57 SF Floor
16.06 SY Flooring	52.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>3' 2" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 10" X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>11' 7" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>1' 7" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,611. Paint the walls - two coats	366.78 SF		0.00	1.36	8.11	99.76	606.69
2,612. Seal & paint baseboard - two coats	52.92 LF		0.00	2.24	0.58	23.70	142.82
2,613. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,614. Final cleaning - construction - Residential	144.57 SF		0.00	0.34	0.00	9.84	58.99
Totals: Kitchen / Dining					9.60	151.58	919.11



### Utility Room

**Height: 8'**

156.67 SF Walls	29.17 SF Ceiling
185.83 SF Walls & Ceiling	29.17 SF Floor
3.24 SY Flooring	19.17 LF Floor Perimeter
21.67 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into KITCHEN__DI</b>
-------------	----------------------	-------------------------------

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,615. 5/8" drywall - hung, taped, floated, ready for paint	81.00 SF		0.00	2.87	5.45	46.50	284.42
2,616. Batt insulation - 6" - R19 - unfaced batt	75.00 SF		0.00	1.07	4.82	16.06	101.13
2,617. Batt insulation - 8" - R25 - unfaced batt	6.00 SF		0.00	1.43	0.49	1.72	10.79
2,618. Seal/prime then paint the walls and ceiling twice (3 coats)	185.83 SF		0.00	1.84	5.23	68.38	415.54




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,619. Mask French door lites (per side of slab)	1.00 EA		0.00	77.74	0.10	15.54	93.38
2,620. Final cleaning - construction - Residential	29.17 SF		0.00	0.34	0.00	1.98	11.90
Totals: Utility Room					16.09	150.18	917.16



### Living / Dining

Height: 8'

395.33 SF Walls	237.02 SF Ceiling
632.35 SF Walls & Ceiling	237.02 SF Floor
26.34 SY Flooring	50.67 LF Floor Perimeter
62.83 LF Ceil. Perimeter	

Missing Wall	11' 11" X 8'	Opens into KITCHEN__DI
Door	3' X 6' 8"	Opens into STUDY1
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into Exterior
Missing Wall - Goes to Ceiling	3' 10" X 4'	Opens into KITCHEN__DI

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,621. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
2,622. Batt insulation - 6" - R19 - unfaced batt	16.00 SF		0.00	1.07	1.03	3.42	21.57
2,623. Paint the walls - two coats	395.33 SF		0.00	1.36	8.74	107.54	653.93
2,624. Baseboard - 3 1/4"	50.67 LF		0.00	3.49	7.38	35.36	219.58
2,625. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,626. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,627. Mask the floor per square foot - plastic and tape - 4 mil	237.02 SF		0.00	0.35	1.19	16.60	100.75
2,628. Final cleaning - construction - Residential	237.02 SF		0.00	0.34	0.00	16.12	96.71
Totals: Living / Dining					20.89	229.20	1,396.09



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 6108

90.20

927.10

5,652.71

**6112**



**Walk-in Closet**

**Height: 9'**

159.22 SF Walls	23.92 SF Ceiling
183.15 SF Walls & Ceiling	23.92 SF Floor
2.66 SY Flooring	17.00 LF Floor Perimeter
19.67 LF Ceil. Perimeter	

**Door**

**2' 8" X 6' 8"**

**Opens into BEDROOM**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,629. 5/8" drywall - hung, taped, floated, ready for paint	22.00 SF		0.00	2.87	1.48	12.62	77.24
2,630. Baseboard - 3 1/4"	17.00 LF		0.00	3.49	2.48	11.86	73.67
2,631. Seal/prime then paint the walls twice (3 coats)	159.22 SF		0.00	1.84	4.48	58.60	356.04
2,632. Seal & paint baseboard - two coats	17.00 LF		0.00	2.24	0.19	7.62	45.89
2,633. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,634. Final cleaning - construction - Residential	23.92 SF		0.00	0.34	0.00	1.62	9.75

Totals: Walk-in Closet

9.09

101.46

617.90



**Master Linen Closet**

**Height: 9'**

50.00 SF Walls	2.75 SF Ceiling
52.75 SF Walls & Ceiling	2.75 SF Floor
0.31 SY Flooring	5.17 LF Floor Perimeter
6.67 LF Ceil. Perimeter	

**Door**

**1' 6" X 6' 8"**

**Opens into MASTER\_BATHR**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,635. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
<i>Walls</i>							
2,636. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
2,637. Seal & paint baseboard - two coats	5.17 LF		0.00	2.24	0.06	2.32	13.96




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Linen Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,638. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	50.00 SF		0.00	1.84	1.41	18.40	111.81
2,639. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
2,640. Final cleaning - construction - Residential	2.75 SF		0.00	0.34	0.00	0.18	1.12
Totals: Master Linen Closet					2.59	58.30	352.33



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM_</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,641. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
2,642. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
2,643. Sink - single	2.00 EA		0.00	274.65	31.83	109.86	690.99
2,644. Sink faucet - Bathroom	2.00 EA		0.00	216.39	26.73	86.56	546.07
2,645. P-trap assembly - Detach & reset	1.00 EA		0.00	63.96	0.00	12.80	76.76
2,646. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
2,647. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	48.00 SF		0.00	2.87	3.23	27.56	168.55
2,648. Batt insulation - 6" - R19 - unfaced batt <i>Ceiling</i>	36.00 SF		0.00	1.07	2.32	7.70	48.54
2,649. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
2,650. Seal & paint baseboard - two coats	33.33 LF		0.00	2.24	0.37	14.94	89.97
2,651. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	390.74 SF		0.00	1.84	11.00	143.80	873.76




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,652. Blown-in insulation - 10" depth - R26	79.85 SF		0.00	1.12	6.02	17.88	113.33
<i>Ceiling</i>							
2,653. Seal & paint base shoe or quarter round	33.33 LF		0.00	1.19	0.37	7.94	47.97
2,654. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
2,655. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
<b>Totals: Bathroom</b>					<b>248.14</b>	<b>927.62</b>	<b>5,813.54</b>



### Utility Room

**Height: 9'**


184.94 SF Walls	24.32 SF Ceiling
209.26 SF Walls & Ceiling	24.32 SF Floor
2.70 SY Flooring	19.75 LF Floor Perimeter
22.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>		<b>3' 1" X 6' 8"</b>		<b>Opens into LIVING_ROOM_</b>			
2,656. 5/8" drywall - hung, taped, floated, ready for paint	50.00 SF		0.00	2.87	3.37	28.70	175.57
<i>Walls</i>							
2,657. Baseboard - 3 1/4"	19.75 LF		0.00	3.49	2.88	13.78	85.59
2,658. Seal & paint baseboard - two coats	19.75 LF		0.00	2.24	0.22	8.84	53.30
2,659. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,660. Seal/prime then paint the walls twice (3 coats)	184.94 SF		0.00	1.84	5.20	68.06	413.55
<i>Walls</i>							
2,661. Final cleaning - construction - Residential	24.32 SF		0.00	0.34	0.00	1.66	9.93
<b>Totals: Utility Room</b>					<b>12.13</b>	<b>130.18</b>	<b>793.25</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Linen Closet

Height: 9'

68.39 SF Walls	4.83 SF Ceiling
73.22 SF Walls & Ceiling	4.83 SF Floor
0.54 SY Flooring	7.17 LF Floor Perimeter
8.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,662. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
<i>Walls</i>							
2,663. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
2,664. Seal/prime then paint the walls twice (3 coats)	68.39 SF		0.00	1.84	1.92	25.16	152.92
<i>Walls</i>							
2,665. Seal & paint baseboard - two coats	7.17 LF		0.00	2.24	0.08	3.22	19.36
2,666. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,667. Final cleaning - construction - Residential	4.83 SF		0.00	0.34	0.00	0.32	1.96
<b>Totals: Linen Closet</b>					4.41	51.20	311.72



### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,668. 5/8" drywall - hung, taped, floated, ready for paint	98.00 SF		0.00	2.87	6.60	56.26	344.12
<i>Walls</i>							
2,669. Batt insulation - 6" - R19 - unfaced batt	84.00 SF		0.00	1.07	5.40	17.98	113.26




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Walls</i>							
2,670. Baseboard - 3 1/4"	28.00 LF		0.00	3.49	4.08	19.54	121.34
2,671. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
<i>Bedroom hall (walls)</i>							
2,672. Seal/prime then paint the walls twice (3 coats)	366.22 SF		0.00	1.84	10.31	134.76	818.91
<i>Bedroom hall (walls)</i>							
2,673. Detach & Reset Window blind - PVC - 1" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,674. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,675. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					27.75	288.26	1,757.32



### Master Walk-in Closet

Height: 9'

216.67 SF Walls	36.80 SF Ceiling
253.47 SF Walls & Ceiling	36.80 SF Floor
4.09 SY Flooring	23.17 LF Floor Perimeter
26.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>							
<b>3' 6" X 6' 8"</b>							
<b>Opens into MASTER_BATHR</b>							
2,676. 5/8" drywall - hung, taped, floated, ready for paint	22.00 SF		0.00	2.87	1.48	12.62	77.24
<i>Walls</i>							
2,677. Baseboard - 3 1/4"	17.00 LF		0.00	3.49	2.48	11.86	73.67
2,678. Seal & paint baseboard - two coats	23.17 LF		0.00	2.24	0.26	10.38	62.54
2,679. Seal/prime then paint the walls twice (3 coats)	216.67 SF		0.00	1.84	6.10	79.74	484.51
2,680. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,681. Final cleaning - construction - Residential	36.80 SF		0.00	0.34	0.00	2.50	15.01
Totals: Master Walk-in Closet					10.78	126.24	768.28



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

**Door** 2' 10" X 6' 8" Opens into MASTER\_BATHR  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,682. 5/8" drywall - hung, taped, floated, ready for paint	52.00 SF		0.00	2.87	3.50	29.84	182.58
<i>Walls</i>							
2,683. Batt insulation - 6" - R19 - unfaced batt	52.00 SF		0.00	1.07	3.34	11.12	70.10
<i>Walls</i>							
2,684. Baseboard - 3 1/4"	39.00 LF		0.00	3.49	5.68	27.22	169.01
2,685. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,686. Seal/prime then paint the walls twice (3 coats)	446.61 SF		0.00	1.84	12.57	164.36	998.69
<i>Walls</i>							
2,687. Detach & Reset Window blind - PVC - 1" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,688. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,689. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
<b>Totals: Master Bedroom</b>					26.56	299.40	1,823.04



### Master Bathroom

Height: 9'

325.78 SF Walls	73.08 SF Ceiling
398.86 SF Walls & Ceiling	73.08 SF Floor
8.12 SY Flooring	34.17 LF Floor Perimeter
42.00 LF Ceil. Perimeter	

**Door** 2' 10" X 6' 8" Opens into MASTER\_BEDRO  
**Door** 1' 6" X 6' 8" Opens into MASTER\_LINEN  
**Door** 3' 6" X 6' 8" Opens into MASTER\_WALK



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Master Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,690. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
2,691. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
2,692. Sink - single	2.00 EA		0.00	274.65	31.83	109.86	690.99
2,693. Sink faucet - Bathroom	2.00 EA		0.00	216.39	26.73	86.56	546.07
2,694. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
<i>Walls</i>							
2,695. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
2,696. Seal & paint baseboard - two coats	34.17 LF		0.00	2.24	0.38	15.30	92.22
2,697. Seal/prime then paint the walls twice (3 coats)	325.78 SF		0.00	1.84	9.17	119.88	728.49
2,698. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
2,699. Seal & paint base shoe or quarter round	34.17 LF		0.00	1.19	0.38	8.14	49.18
2,700. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,701. Final cleaning - construction - Residential	73.08 SF		0.00	0.34	0.00	4.98	29.83
Totals: Master Bathroom					234.47	842.26	5,287.93



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room/kitchen**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM_</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM_</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM_</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,702. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	242.00 SF		0.00	2.87	16.30	138.90	849.74
2,703. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	486.47 SF		0.00	1.12	36.67	108.98	690.50
2,704. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
2,705. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	141.00 SF		0.00	1.07	9.07	30.18	190.12
2,706. Baseboard - 3 1/4"	48.00 LF		0.00	3.49	6.99	33.50	208.01
2,707. Base shoe	48.00 LF		0.00	1.41	2.41	13.54	83.63
2,708. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
2,709. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
2,710. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room/kitchen


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,711. Detach & Reset Range - freestanding - gas	1.00 EA	171.46	0.00	0.00	0.00	34.30	205.76
2,712. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
2,713. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
2,714. Detach & Reset Cabinetry - upper (wall) units	10.00 LF	59.59	0.00	0.00	0.00	119.18	715.08
2,715. Detach & Reset Cabinetry - lower (base) units	10.00 LF	69.68	0.00	0.00	0.00	139.36	836.16
2,716. Detach & Reset Countertop - solid surface	25.50 SF	34.74	0.00	0.00	0.18	177.18	1,063.23
2,717. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
2,718. Sink - single - Detach & reset	1.00 EA		0.00	160.49	0.05	32.10	192.64
2,719. Install Sink faucet - Detach & reset	1.00 EA		0.00	128.34	0.00	25.66	154.00
2,720. Detach & Reset P-trap assembly - ABS (plastic)	1.00 EA	63.96	0.00	0.00	0.00	12.80	76.76
2,721. Vinyl plank flooring	30.00 SF		0.00	5.74	9.01	34.44	215.65
2,722. Drywall patch / small repair, ready for paint	2.00 EA		0.00	89.02	0.67	35.60	214.31
<i>Paint and blend patch.</i>							
2,723. Floor preparation for resilient flooring	3.00 SF		0.00	0.71	0.03	0.42	2.58
2,724. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
2,725. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room/kitchen</b>					<b>123.06</b>	<b>1,689.26</b>	<b>10,258.38</b>
<b>Total: 6112</b>					<b>698.98</b>	<b>4,514.18</b>	<b>27,783.69</b>

6203



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Entry

**Height: 9'**

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,726. Seal/prime then paint the walls and ceiling twice (3 coats)	82.01 SF		0.00	1.84	2.31	30.18	183.39
2,727. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
2,728. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,729. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
<b>Totals: Entry</b>					<b>2.84</b>	<b>43.40</b>	<b>263.30</b>



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,730. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
2,731. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	12.00 SF		0.00	1.07	0.77	2.56	16.17
2,732. Baseboard - 3 1/4"	15.00 LF		0.00	3.49	2.19	10.48	65.02
2,733. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
2,734. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
2,735. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,736. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>29.06</b>	<b>422.60</b>	<b>2,564.57</b>

### 6210



### Bathroom

**Height: 9'**

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into ROOM2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,737. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
2,738. Batt insulation - 6" - R19 - unfaced batt	6.00 SF		0.00	1.07	0.39	1.28	8.09
2,739. Batt insulation - 8" - R25 - unfaced batt	12.00 SF		0.00	1.43	0.98	3.44	21.58
2,740. Seal/prime then paint the walls and ceiling twice (3 coats)	390.74 SF		0.00	1.84	11.00	143.80	873.76
2,741. Seal & paint baseboard - two coats	33.33 LF		0.00	2.24	0.37	14.94	89.97



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,742. Seal & paint base shoe or quarter round	33.33 LF		0.00	1.19	0.37	7.94	47.97
2,743. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
2,744. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,745. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
2,746. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
<b>Totals: Bathroom</b>					<b>15.70</b>	<b>247.38</b>	<b>1,499.85</b>



### Master Bedroom

**Height: 9'**

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into MASTER_BATHR</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,747. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57
2,748. Batt insulation - 6" - R19 - unfaced batt	5.00 SF		0.00	1.07	0.32	1.08	6.75
2,749. Seal/prime then paint the walls twice (3 coats)	446.61 SF		0.00	1.84	12.57	164.36	998.69
2,750. Baseboard - 3 1/4"	50.67 LF		0.00	3.49	7.38	35.36	219.58
2,751. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,752. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,753. Detach & Reset Window blind - PVC - 1" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,754. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
<b>Totals: Master Bedroom</b>					<b>22.08</b>	<b>270.54</b>	<b>1,645.25</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Room2

**Height: 9'**

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

- |   |                       |                                |
|---|-----------------------|--------------------------------|
| <b>Missing Wall - Goes to neither Floor/Ceiling</b> | <b>10' 2" X 5'</b>    | <b>Opens into ROOM2</b>        |
| <b>Window</b>                                       | <b>4' X 4'</b>        | <b>Opens into Exterior</b>     |
| <b>Door</b>   | <b>4' X 6' 8"</b>     | <b>Opens into Exterior</b>     |
| <b>Window</b>                                       | <b>4' X 4'</b>        | <b>Opens into Exterior</b>     |
| <b>Door</b>   | <b>3' X 6' 8"</b>     | <b>Opens into BEDROOM</b>      |
| <b>Door</b>   | <b>3' X 6' 8"</b>     | <b>Opens into BATHROOM1</b>    |
| <b>Door</b>   | <b>3' X 6' 8"</b>     | <b>Opens into Exterior</b>     |
| <b>Door</b>   | <b>1' 10" X 6' 8"</b> | <b>Opens into PANTRY</b>       |
| <b>Door</b>   | <b>3' 1" X 6' 8"</b>  | <b>Opens into UTILITY_ROOM</b> |
| <b>Missing Wall - Goes to neither Floor/Ceiling</b> | <b>3' X 5'</b>        | <b>Opens into ROOM2</b>        |
| <b>Missing Wall - Goes to neither Floor/Ceiling</b> | <b>3' X 5'</b>        | <b>Opens into ROOM2</b>        |


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,755. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
2,756. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
2,757. Seal/prime then paint the walls twice (3 coats)	892.06 SF		0.00	1.84	25.10	328.28	1,994.77
2,758. Baseboard - 3 1/4"	115.25 LF		0.00	3.49	16.79	80.44	499.45
2,759. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
2,760. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
2,761. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,762. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27
<b>Totals: Room2</b>					<b>47.72</b>	<b>548.02</b>	<b>3,335.96</b>
<b>Total: 6210</b>					<b>85.50</b>	<b>1,065.94</b>	<b>6,481.06</b>
<b>Total: 6203</b>					<b>117.40</b>	<b>1,531.94</b>	<b>9,308.93</b>

6301



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Ceiling</b>	<b>6' 4" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,763. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16
2,764. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
2,765. Batt insulation - 8" - R25 - unfaced batt	4.00 SF		0.00	1.43	0.33	1.14	7.19
2,766. Seal/prime then paint the walls and ceiling twice (3 coats)	267.13 SF		0.00	1.84	7.52	98.30	597.34
2,767. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,768. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,769. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
2,770. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
2,771. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
2,772. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>25.64</b>	<b>203.72</b>	<b>1,247.94</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Entry

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,773. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,774. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
2,775. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
2,776. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
2,777. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
2,778. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					<b>5.35</b>	<b>78.78</b>	<b>478.01</b>



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,779. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,780. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
2,781. Paint the walls and ceiling - two coats	640.44 SF		0.00	1.36	14.16	174.20	1,059.36
2,782. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
2,783. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,784. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					16.75	282.88	1,714.02
Total: 6301					<b>47.74</b>	<b>565.38</b>	<b>3,439.97</b>

### 6310



#### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

3' X 6' 8"

Opens into LIVING\_ROOM2

Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,785. 5/8" drywall - hung, taped, floated, ready for paint	26.00 SF		0.00	2.87	1.75	14.92	91.29
2,786. Batt insulation - 6" - R19 - unfaced batt	26.00 SF		0.00	1.07	1.67	5.56	35.05
2,787. Seal/prime then paint the walls twice (3 coats)	366.22 SF		0.00	1.84	10.31	134.76	818.91
2,788. Baseboard - 3 1/4"	41.00 LF		0.00	3.49	5.97	28.62	177.68
2,789. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
2,790. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
2,791. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,792. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,793. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					21.74	253.10	1,540.46



### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into MASTER_BATHR</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,794. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
2,795. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
2,796. Seal/prime then paint the walls twice (3 coats)	446.61 SF		0.00	1.84	12.57	164.36	998.69
2,797. Baseboard - 3 1/4"	50.67 LF		0.00	3.49	7.38	35.36	219.58
2,798. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,799. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
2,800. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,801. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,802. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
Totals: Master Bedroom					23.62	286.88	1,744.93
Total: 6310					<b>45.36</b>	<b>539.98</b>	<b>3,285.39</b>

6312



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**3' X 6' 8"**

**Opens into ROOM2**

**Door**

**2' 8" X 6' 8"**

**Opens into WALKIN\_CLOS1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,803. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,804. Seal/prime then paint the walls and ceiling twice (3 coats)	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
2,805. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
2,806. Clean and deodorize carpet	136.10 SF		0.00	0.57	0.00	15.52	93.10
2,807. Seal & paint window sill	3.60 LF		0.00	3.82	0.09	2.76	16.60
2,808. 5/8" drywall - hung, taped, floated, ready for paint	414.22 SF		0.00	2.87	27.89	237.76	1,454.46
2,809. Batt insulation - 6" - R19 - unfaced batt	366.22 SF		0.00	1.07	23.56	78.38	493.80
2,810. Batt insulation - 8" - R25 - unfaced batt	48.00 SF		0.00	1.43	3.91	13.72	86.27
2,811. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,812. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,813. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,814. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
2,815. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
<b>Totals: Bedroom</b>					<b>71.63</b>	<b>674.68</b>	<b>4,119.71</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 9'**


446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,816. 5/8" drywall - hung, taped, floated, ready for paint	506.61 SF		0.00	2.87	34.11	290.80	1,778.88
2,817. Batt insulation - 6" - R19 - unfaced batt	446.61 SF		0.00	1.07	28.73	95.58	602.18
2,818. Batt insulation - 8" - R25 - unfaced batt	60.00 SF		0.00	1.43	4.88	17.16	107.84
2,819. Paint the walls and ceiling - two coats	624.04 SF		0.00	1.36	13.80	169.74	1,032.23
2,820. Baseboard - 3 1/4"	50.67 LF		0.00	3.49	7.38	35.36	219.58
2,821. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,822. Window sill	3.60 LF		0.00	3.12	0.33	2.24	13.80
2,823. Seal & paint window sill	3.60 LF		0.00	3.82	0.09	2.76	16.60
2,824. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	34.54	0.00	6.90	41.44
2,825. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,826. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,827. Clean and deodorize carpet	177.43 SF		0.00	0.57	0.00	20.22	121.36
2,828. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,829. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
2,830. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
<b>Totals: Master Bedroom</b>					91.68	756.26	4,629.31



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Room2

**Height: 9'**

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

- |   |                       |                                |
|---|-----------------------|--------------------------------|
| <b>Missing Wall - Goes to neither Floor/Ceiling</b> | <b>10' 2" X 5'</b>    | <b>Opens into ROOM2</b>        |
| <b>Door</b>   | <b>3' 1" X 6' 8"</b>  | <b>Opens into UTILITY_ROOM</b> |
| <b>Door</b>   | <b>1' 10" X 6' 8"</b> | <b>Opens into PANTRY</b>       |
| <b>Door</b>   | <b>3' X 6' 8"</b>     | <b>Opens into Exterior</b>     |
| <b>Door</b>   | <b>3' X 6' 8"</b>     | <b>Opens into BATHROOM1</b>    |
| <b>Door</b>   | <b>3' X 6' 8"</b>     | <b>Opens into BEDROOM</b>      |
| <b>Window</b>                                       | <b>4' X 4'</b>        | <b>Opens into Exterior</b>     |
| <b>Door</b>   | <b>4' X 6' 8"</b>     | <b>Opens into Exterior</b>     |
| <b>Window</b>                                       | <b>4' X 4'</b>        | <b>Opens into Exterior</b>     |
| <b>Missing Wall - Goes to neither Floor/Ceiling</b> | <b>3' X 5'</b>        | <b>Opens into ROOM2</b>        |
| <b>Missing Wall - Goes to neither Floor/Ceiling</b> | <b>3' X 5'</b>        | <b>Opens into ROOM2</b>        |

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,831. 5/8" drywall - hung, taped, floated, ready for paint	605.84 SF		0.00	2.87	40.79	347.76	2,127.31
2,832. Batt insulation - 6" - R19 - unfaced batt	100.00 SF		0.00	1.07	6.43	21.40	134.83
2,833. Batt insulation - 8" - R25 - unfaced batt	505.84 SF		0.00	1.43	41.18	144.68	909.21
2,834. Seal/prime then paint the walls and ceiling twice (3 coats)	1,397.90 SF		0.00	1.84	39.34	514.42	3,125.90
2,835. Baseboard - 3 1/4"	115.25 LF		0.00	3.49	16.79	80.44	499.45
2,836. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
2,837. Crown molding - 3 1/4"	133.17 LF		0.00	4.40	22.22	117.20	725.37
2,838. Paint crown molding - two coats	133.17 LF		0.00	2.24	2.01	59.66	359.97
2,839. Base shoe	115.25 LF		0.00	1.41	5.79	32.50	200.79
2,840. Seal & paint base shoe or quarter round	115.25 LF		0.00	1.19	1.27	27.44	165.86
2,841. Track for track lighting - Detach & reset	8.00 LF		0.00	9.84	0.00	15.74	94.46
2,842. Clean and deodorize carpet	500.67 SF		0.00	0.57	0.00	57.08	342.46
2,843. Seal & paint base shoe or quarter round	1.00 LF		0.00	1.19	0.01	0.24	1.44
2,844. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Room2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,845. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
2,846. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27
Totals: Room2					180.08	1,548.42	9,470.49
Total: 6312					<b>343.39</b>	<b>2,979.36</b>	<b>18,219.51</b>

### 6401



#### Entry

Height: 9'

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	


Missing Wall	1' 5" X 9'	Opens into LIVING_ROOM
Missing Wall	4' 5" X 9'	Opens into KITCHEN
Door	3' X 6' 8"	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	2' 10" X 6' 8"	Opens into BEDROOM
Missing Wall	4' 6" X 9'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,847. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,848. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
2,849. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
2,850. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
2,851. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
2,852. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					5.35	78.78	478.01



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**6' 4" X 5'**

**Opens into LIVING\_ROOM**

**Door**

**1' 8" X 6' 8"**

**Opens into PANTRY**

**Door**

**3' X 6' 8"**

**Opens into UTILITY\_ROOM**

**Missing Wall**

**4' 5" X 9'**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,853. 5/8" drywall - hung, taped, floated, ready for paint	4.00 SF		0.00	2.87	0.27	2.30	14.05
2,854. Batt insulation - 6" - R19 - unfaced batt	4.00 SF		0.00	1.07	0.26	0.86	5.40
2,855. Seal/prime then paint the walls twice (3 coats)	201.97 SF		0.00	1.84	5.68	74.32	451.62
2,856. Baseboard - 3 1/4"	24.75 LF		0.00	3.49	3.61	17.28	107.27
2,857. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
2,858. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,859. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,860. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
2,861. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>25.70</b>	<b>184.30</b>	<b>1,131.42</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,862. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,863. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
2,864. Paint the walls - two coats	425.08 SF		0.00	1.36	9.40	115.62	703.13
2,865. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
2,866. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>11.54</b>	<b>178.94</b>	<b>1,085.16</b>
<b>Total: 6401</b>					<b>42.59</b>	<b>442.02</b>	<b>2,694.59</b>

6403



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Room2**

**Height: 9'**

892.06 SF Walls  
1,397.90 SF Walls & Ceiling  
55.63 SY Flooring  
133.17 LF Ceil. Perimeter

505.84 SF Ceiling  
500.67 SF Floor  
115.25 LF Floor Perimeter

- Missing Wall - Goes to neither Floor/Ceiling** 10' 2" X 5' **Opens into ROOM2**
- Door** 3' 1" X 6' 8" **Opens into UTILITY\_ROOM**
- Door** 1' 10" X 6' 8" **Opens into PANTRY**
- Door** 3' X 6' 8" **Opens into Exterior**
- Door** 3' X 6' 8" **Opens into BATHROOM1**
- Door** 3' X 6' 8" **Opens into BEDROOM**
- Window** 4' X 4' **Opens into Exterior**
- Door** 4' X 6' 8" **Opens into Exterior**
- Window** 4' X 4' **Opens into Exterior**
- Missing Wall - Goes to neither Floor/Ceiling** 3' X 5' **Opens into ROOM2**
- Missing Wall - Goes to neither Floor/Ceiling** 3' X 5' **Opens into ROOM2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,867. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
2,868. Batt insulation - 6" - R19 - unfaced batt	6.00 SF		0.00	1.07	0.39	1.28	8.09
2,869. Paint the walls - two coats	892.06 SF		0.00	1.36	19.72	242.64	1,475.56
2,870. Baseboard - 3 1/4"	115.25 LF		0.00	3.49	16.79	80.44	499.45
2,871. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
2,872. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,873. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
2,874. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27

Totals: Room2 41.55 457.66 2,787.60


Total: 6403 **41.55 457.66 2,787.60**

**6404**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

**Missing Wall**

**4' 5" X 9'**


**Opens into LIVING\_ROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,875. Paint the walls - two coats	62.50 SF		0.00	1.36	1.38	17.00	103.38
2,876. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
2,877. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,878. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
2,879. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
<b>Totals: Entry</b>					<b>2.01</b>	<b>31.58</b>	<b>191.58</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,880. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls (kitchen)</i>	60.00 SF		0.00	2.87	4.04	34.44	210.68
2,881. Batt insulation - 6" - R19 - unfaced batt <i>Walls (kitchen)</i>	60.00 SF		0.00	1.07	3.86	12.84	80.90
2,882. Cabinetry - lower (base) units <i>Kitchen</i>	10.00 LF		0.00	219.33	179.12	438.66	2,811.08
2,883. Cabinetry - upper (wall) units <i>Kitchen</i>	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
2,884. Countertop - solid surface <i>Kitchen</i>	25.50 SF		0.00	64.30	114.55	327.94	2,082.14
2,885. Seal/prime then paint the walls twice (3 coats) <i>Walls (kitchen)</i>	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
2,886. Floor preparation for resilient flooring	130.00 SF		0.00	0.71	1.31	18.46	112.07
2,887. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
2,888. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,889. Vinyl plank flooring	130.00 SF		0.00	5.74	39.06	149.24	934.50
2,890. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
2,891. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>481.64</b>	<b>1,723.02</b>	<b>10,819.55</b>
<b>Total: 6404</b>					<b>483.65</b>	<b>1,754.60</b>	<b>11,011.13</b>

### 6407



#### Bedroom 1

Height: 9'

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>				<b>2' 8" X 6' 8"</b>			
							<b>Opens into WALKIN_CLOS</b>
<b>Door</b>				<b>3' X 6' 8"</b>			
							<b>Opens into LIVING__DIN</b>
2,892. 5/8" drywall - hung, taped, floated, ready for paint	189.00 SF		0.00	2.87	12.73	108.48	663.64
2,893. Batt insulation - 6" - R19 - unfaced batt	45.00 SF		0.00	1.07	2.89	9.64	60.68
2,894. Batt insulation - 8" - R25 - unfaced batt	144.00 SF		0.00	1.43	11.72	41.18	258.82
2,895. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
2,896. Baseboard - 3 1/4"	41.67 LF		0.00	3.49	6.07	29.08	180.58
2,897. Seal & paint baseboard - two coats	41.67 LF		0.00	2.24	0.46	18.66	112.46
2,898. Outlet or switch cover	1.00 EA		0.00	3.06	0.09	0.62	3.77
2,899. Detach & Reset Window blind - PVC - 2" - 7.1 to 14 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,900. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,901. Mask the floor per square foot - plastic and tape - 4 mil	139.97 SF		0.00	0.35	0.70	9.80	59.49
2,902. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom 1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Bedroom 1					50.43	453.46	2,771.17



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,903. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
2,904. Batt insulation - 6" - R19 - unfaced batt	6.00 SF		0.00	1.07	0.39	1.28	8.09
2,905. Batt insulation - 8" - R25 - unfaced batt	4.00 SF		0.00	1.43	0.33	1.14	7.19
2,906. Paint the walls and ceiling - two coats	522.56 SF		0.00	1.36	11.55	142.14	864.37
2,907. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
2,908. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
2,909. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,910. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>14.70</b>	<b>191.34</b>	<b>1,162.70</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,911. 5/8" drywall - hung, taped, floated, ready for paint	75.00 SF		0.00	2.87	5.05	43.06	263.36
2,912. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
2,913. Batt insulation - 8" - R25 - unfaced batt	65.00 SF		0.00	1.43	5.29	18.60	116.84
2,914. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
2,915. Baseboard - 3 1/4"	68.42 LF		0.00	3.49	9.97	47.76	296.52
2,916. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
2,917. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
2,918. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,919. Mask the floor per square foot - plastic and tape - 4 mil	384.72 SF		0.00	0.35	1.93	26.94	163.52
2,920. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>68.24</b>	<b>646.10</b>	<b>3,944.65</b>
<b>Total: 6407</b>					<b>133.37</b>	<b>1,290.90</b>	<b>7,878.52</b>

6408

6408




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - 6408

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,921. Final cleaning - construction - Residential	752.89 SF		0.00	0.34	0.00	51.20	307.18
Total: 6408					0.00	51.20	307.18



### Bedroom

Height: 8'

345.33 SF Walls	127.65 SF Ceiling
472.99 SF Walls & Ceiling	127.65 SF Floor
14.18 SY Flooring	44.67 LF Floor Perimeter
47.67 LF Ceil. Perimeter	


**Door** 3' X 6' 8" Opens into LIVING\_\_DIN  
**Window** 4' X 4" Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,922. 5/8" drywall - hung, taped, floated, ready for paint	160.00 SF		0.00	2.87	10.77	91.84	561.81
2,923. Batt insulation - 4" - R13 - paper / foil faced	122.00 SF		0.00	1.07	8.83	26.10	165.47
2,924. Paint baseboard - two coats	44.67 LF		0.00	2.16	0.58	19.30	116.37
2,925. Baseboard - 4 1/4"	11.67 LF		0.00	4.14	2.37	9.66	60.34
2,926. Seal/prime then paint the walls and ceiling twice (3 coats)	472.99 SF		0.00	1.84	13.31	174.06	1,057.67
2,927. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
2,928. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,929. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,930. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
2,931. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84
2,932. Texture drywall - light hand texture	122.00 SF		0.00	0.72	0.61	17.56	106.01
2,933. Remove Carpet	127.65 SF		0.34	0.00	0.00	8.68	52.08
2,934. Carpet	146.80 SF		0.00	3.67	39.69	107.76	686.21
15 % waste added for Carpet.							
2,935. Carpet pad	127.65 SF		0.00	0.63	6.29	16.08	102.79
Totals: Bedroom					84.06	525.84	3,239.14



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Study

**Height: 8'**

272.78 SF Walls	92.60 SF Ceiling
365.38 SF Walls & Ceiling	92.60 SF Floor
10.29 SY Flooring	34.92 LF Floor Perimeter
42.00 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 1" X 6' 8"</b>	<b>Opens into STUDY_CLOSE2</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>2' X 6' 8"</b>	<b>Opens into STUDY_CLOSET</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,936. 5/8" drywall - hung, taped, floated, ready for paint	128.00 SF		0.00	2.87	8.62	73.48	449.46
2,937. Batt insulation - 4" - R13 - paper / foil faced	96.00 SF		0.00	1.07	6.95	20.54	130.21
2,938. Paint baseboard - two coats	34.92 LF		0.00	2.16	0.46	15.08	90.97
2,939. Seal/prime then paint the walls and ceiling twice (3 coats)	365.38 SF		0.00	1.84	10.28	134.46	817.04
2,940. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
2,941. Paint door/window trim & jamb - 2 coats (per side)	4.00 EA		0.00	45.71	1.83	36.56	221.23
2,942. Paint door slab only - 2 coats (per side)	3.00 EA		0.00	53.15	2.24	31.90	193.59
2,943. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,944. Baseboard - 4 1/4"	10.00 LF		0.00	4.14	2.03	8.28	51.71
2,945. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
2,946. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84
2,947. Remove Carpet	92.60 SF		0.34	0.00	0.00	6.30	37.78
2,948. Carpet	106.49 SF		0.00	3.67	28.79	78.16	497.77
15 % waste added for Carpet.							
2,949. Carpet pad	92.60 SF		0.00	0.63	4.56	11.66	74.56
<b>Totals: Study</b>					<b>66.91</b>	<b>446.20</b>	<b>2,744.11</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Walk-in Closet**

**Height: 8'**

192.00 SF Walls	42.43 SF Ceiling
234.43 SF Walls & Ceiling	42.43 SF Floor
4.71 SY Flooring	23.50 LF Floor Perimeter
26.50 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM</b>				
-------------	-------------------	----------------------------	--	--	--	--

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,950. Remove Carpet	42.43 SF		0.34	0.00	0.00	2.88	17.31
2,951. Carpet	48.80 SF		0.00	3.67	13.19	35.82	228.11
15 % waste added for Carpet.							
2,952. R&R Carpet pad	42.43 SF		0.14	0.63	2.09	6.52	41.28
2,953. Paint baseboard - two coats	23.50 LF		0.00	2.16	0.31	10.16	61.23
<b>Totals: Walk-in Closet</b>					<b>15.59</b>	<b>55.38</b>	<b>347.93</b>



**Study Closet 1**

**Height: 8'**

62.67 SF Walls	5.60 SF Ceiling
68.26 SF Walls & Ceiling	5.60 SF Floor
0.62 SY Flooring	7.50 LF Floor Perimeter
9.50 LF Ceil. Perimeter	


<b>Door</b>	<b>2' X 6' 8"</b>	<b>Opens into STUDY</b>				
-------------	-------------------	-------------------------	--	--	--	--

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,954. Paint baseboard - two coats	7.50 LF		0.00	2.16	0.10	3.24	19.54
2,955. Remove Carpet	5.60 SF		0.34	0.00	0.00	0.38	2.28
2,956. Carpet	6.44 SF		0.00	3.67	1.74	4.72	30.09
15 % waste added for Carpet.							
2,957. R&R Carpet pad	5.60 SF		0.14	0.63	0.28	0.86	5.45
<b>Totals: Study Closet 1</b>					<b>2.12</b>	<b>9.20</b>	<b>57.36</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Bathroom**

**Height: 8'**

228.00 SF Walls	59.31 SF Ceiling
287.31 SF Walls & Ceiling	59.31 SF Floor
6.59 SY Flooring	27.50 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

**Door** **3' X 6' 8"** **Opens into LIVING\_\_DIN**  
**Door** **3' X 6' 8"** **Opens into WALKIN\_CLOS**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,958. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
2,959. Batt insulation - 4" - R13 - paper / foil faced	4.00 SF		0.00	1.07	0.29	0.86	5.43
2,960. Baseboard - 4 1/4"	4.00 LF		0.00	4.14	0.81	3.32	20.69
2,961. Paint baseboard - two coats	27.50 LF		0.00	2.16	0.36	11.88	71.64
2,962. Quarter round - 3/4"	27.50 LF		0.00	1.65	2.05	9.08	56.51
2,963. Seal & paint base shoe or quarter round	27.50 LF		0.00	1.19	0.30	6.54	39.57
2,964. Seal/prime then paint the walls and ceiling twice (3 coats)	287.31 SF		0.00	1.84	8.09	105.74	642.48
2,965. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
2,966. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,967. Bathroom ventilation fan - Detach & reset	1.00 EA		0.00	73.14	0.00	14.62	87.76
2,968. Bathroom mirror - Detach & reset	20.00 SF		0.00	9.37	0.00	37.48	224.88
2,969. Towel bar - Detach & reset	1.00 EA		0.00	16.99	0.00	3.40	20.39
<b>Totals: Bathroom</b>					<b>12.23</b>	<b>224.66</b>	<b>1,360.09</b>



**Study Closet 2**

**Height: 8'**

62.11 SF Walls	5.60 SF Ceiling
67.71 SF Walls & Ceiling	5.60 SF Floor
0.62 SY Flooring	7.42 LF Floor Perimeter
9.50 LF Ceil. Perimeter	

**Door** **2' 1" X 6' 8"** **Opens into STUDY**



## Camp Construction Services


15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Study Closet 2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,970. Remove Carpet	5.60 SF		0.34	0.00	0.00	0.38	2.28
2,971. Carpet	6.44 SF		0.00	3.67	1.74	4.72	30.09
15 % waste added for Carpet.							
2,972. Carpet pad	5.60 SF		0.00	0.63	0.28	0.70	4.51
2,973. Paint baseboard - two coats	7.42 LF		0.00	2.16	0.10	3.20	19.33
Totals: Study Closet 2					2.12	9.00	56.21

### Kitchen / Dining

Height: 8'



366.78 SF Walls	146.51 SF Ceiling
513.29 SF Walls & Ceiling	144.57 SF Floor
16.06 SY Flooring	52.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	


Missing Wall - Goes to Ceiling	3' X 4'	Opens into KITCHEN__DI
Door	2' 6" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 7" X 6' 8"	Opens into PANTRY
Missing Wall	11' 7" X 8'	Opens into LIVING__DIN
Missing Wall - Goes to Ceiling	3' 10" X 4'	Opens into LIVING__DIN
Missing Wall - Goes to Ceiling	3' 2" X 4'	Opens into KITCHEN__DI

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,974. Seal & paint baseboard - two coats	52.92 LF		0.00	2.24	0.58	23.70	142.82
2,975. Seal/prime then paint the walls twice (3 coats)	366.78 SF		0.00	1.84	10.32	134.98	820.18
2,976. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,977. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
2,978. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
Totals: Kitchen / Dining					10.90	180.14	1,091.78



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining

**Height: 8'**

395.33 SF Walls	237.02 SF Ceiling
632.35 SF Walls & Ceiling	237.02 SF Floor
26.34 SY Flooring	50.67 LF Floor Perimeter
62.83 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 11" X 8'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 10" X 4'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,979. 5/8" drywall - hung, taped, floated, ready for paint	48.00 SF		0.00	2.87	3.23	27.56	168.55
2,980. Batt insulation - 4" - R13 - paper / foil faced	48.00 SF		0.00	1.07	3.47	10.28	65.11
2,981. Baseboard - 4 1/4"	24.00 LF		0.00	4.14	4.87	19.88	124.11
2,982. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,983. Seal/prime then paint the walls twice (3 coats)	395.33 SF		0.00	1.84	11.12	145.48	884.01
2,984. Casing - 2 1/4"	30.00 LF		0.00	2.23	3.50	13.38	83.78
2,985. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
2,986. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
2,987. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
2,988. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
<b>Totals: Living / Dining</b>					<b>27.21</b>	<b>269.88</b>	<b>1,646.41</b>
<b>Total: 6408</b>					<b>221.14</b>	<b>1,771.50</b>	<b>10,850.21</b>

6410



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

**Door** 2' 10" X 6' 8" Opens into MASTER\_BATHR  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,989. Paint the walls and ceiling - two coats	624.04 SF		0.00	1.36	13.80	169.74	1,032.23
2,990. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
2,991. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
2,992. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
2,993. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
2,994. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
2,995. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
<b>Totals: Master Bedroom</b>					<b>16.16</b>	<b>285.24</b>	<b>1,727.63</b>
<b>Total: 6410</b>					<b>16.16</b>	<b>285.24</b>	<b>1,727.63</b>

6411



### Master Bathroom

Height: 9'

325.78 SF Walls	73.08 SF Ceiling
398.86 SF Walls & Ceiling	73.08 SF Floor
8.12 SY Flooring	34.17 LF Floor Perimeter
42.00 LF Ceil. Perimeter	

**Door** 2' 10" X 6' 8" Opens into MASTER\_BEDRO  
**Door** 1' 6" X 6' 8" Opens into MASTER\_LINEN  
**Door** 3' 6" X 6' 8" Opens into MASTER\_WALK

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
2,996. Paint the walls and ceiling - two coats	398.86 SF		0.00	1.36	8.82	108.50	659.77
2,997. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
2,998. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
2,999. Batt insulation - 8" - R25 - unfaced batt	12.00 SF		0.00	1.43	0.98	3.44	21.58
3,000. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47
3,001. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,002. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
3,003. Seal & paint base shoe or quarter round	34.17 LF		0.00	1.19	0.38	8.14	49.18
3,004. Seal & paint baseboard - two coats	34.17 LF		0.00	2.24	0.38	15.30	92.22
3,005. Mask the floor per square foot - plastic and tape - 4 mil	73.08 SF		0.00	0.35	0.37	5.12	31.07
3,006. Final cleaning - construction - Residential	73.08 SF		0.00	0.34	0.00	4.98	29.83
Totals: Master Bathroom					28.78	278.80	1,701.39
Total: 6411					<b>28.78</b>	<b>278.80</b>	<b>1,701.39</b>

### 6412



#### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

#### Window

4' X 4'

Opens into Exterior

#### Door

3' X 6' 8"

Opens into ROOM2

#### Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,007. 5/8" drywall - hung, taped, floated, ready for paint	55.00 SF		0.00	2.87	3.70	31.58	193.13
3,008. Batt insulation - 6" - R19 - unfaced batt	55.00 SF		0.00	1.07	3.54	11.78	74.17



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,009. Seal/prime then paint the walls twice (3 coats)	366.22 SF		0.00	1.84	10.31	134.76	818.91
3,010. Baseboard - 3 1/4"	41.00 LF		0.00	3.49	5.97	28.62	177.68
3,011. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
3,012. Base shoe	41.00 LF		0.00	1.41	2.06	11.56	71.43
3,013. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,014. Seal & paint base shoe or quarter round	41.00 LF		0.00	1.19	0.45	9.76	59.00
3,015. Vinyl plank flooring	136.10 SF		0.00	5.74	40.90	156.24	978.35
3,016. Floor preparation for resilient flooring	136.10 SF		0.00	0.71	1.37	19.32	117.32
3,017. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
<b>Totals: Bedroom</b>					<b>69.66</b>	<b>449.52</b>	<b>2,766.78</b>



### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into MASTER_BATHR</b>					
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,018. Paint the walls - two coats	446.61 SF		0.00	1.36	9.87	121.48	738.74
3,019. 5/8" drywall - hung, taped, floated, ready for paint	100.00 SF		0.00	2.87	6.73	57.40	351.13
3,020. Batt insulation - 6" - R19 - unfaced batt	100.00 SF		0.00	1.07	6.43	21.40	134.83
3,021. Baseboard - 3 1/4"	50.67 LF		0.00	3.49	7.38	35.36	219.58
3,022. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
3,023. Vinyl plank flooring	177.43 SF		0.00	5.74	53.32	203.70	1,275.47
3,024. Floor preparation for resilient flooring	177.43 SF		0.00	0.71	1.78	25.20	152.96
3,025. Base shoe	50.67 LF		0.00	1.41	2.55	14.28	88.27




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,026. Seal & paint base shoe or quarter round	50.67 LF		0.00	1.19	0.56	12.06	72.92
3,027. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,028. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
3,029. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
Totals: Master Bedroom					90.98	556.34	3,429.07



### Room2

Height: 9'

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into ROOM2
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into Exterior
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into ROOM2
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,030. 5/8" drywall - hung, taped, floated, ready for paint	200.00 SF		0.00	2.87	13.47	114.80	702.27
3,031. Batt insulation - 6" - R19 - unfaced batt	120.00 SF		0.00	1.07	7.72	25.68	161.80
3,032. Batt insulation - 8" - R25 - unfaced batt	80.00 SF		0.00	1.43	6.51	22.88	143.79
3,033. Seal/prime then paint the walls and ceiling twice (3 coats)	1,397.90 SF		0.00	1.84	39.34	514.42	3,125.90
3,034. Baseboard - 3 1/4"	115.25 LF		0.00	3.49	16.79	80.44	499.45



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Room2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,035. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
3,036. Crown molding - 3 1/4"	133.17 LF		0.00	4.40	22.22	117.20	725.37
3,037. Paint crown molding - two coats	133.17 LF		0.00	2.24	2.01	59.66	359.97
3,038. Vinyl plank flooring	500.67 SF		0.00	5.74	150.45	574.78	3,599.08
3,039. Floor preparation for resilient flooring	500.67 SF		0.00	0.71	5.03	71.10	431.61
3,040. Base shoe	115.25 LF		0.00	1.41	5.79	32.50	200.79
3,041. Seal & paint base shoe or quarter round	115.25 LF		0.00	1.19	1.27	27.44	165.86
3,042. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
3,043. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,044. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27
Totals: Room2					275.30	1,779.90	10,954.63
Total: 6412					<b>435.94</b>	<b>2,785.76</b>	<b>17,150.48</b>
Total: Building 6 Interiors					<b>2,877.64</b>	<b>21,625.22</b>	<b>132,627.54</b>

### Corridors/Breezways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,045. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	72,680. SF 00		0.00	2.87	4,893.91	41,718.32	255,203.83
3,046. Exterior - paint two coats <i>Estimated allowance</i>	36,340. SF 00		0.00	1.58	1,168.69	11,483.44	70,069.33
3,047. Electrician - per hour <i>Labor to detach and reset misc to prep for paint.</i>	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
3,048. Painter - per hour <i>Misc labor to prep for paint.</i>	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
3,049. Carpenter - General Framer - per hour <i>Labor to install drywall nailers.</i>	60.00 HR		0.00	72.00	0.00	864.00	5,184.00



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridors/Breezways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Corridors/Breezways					6,062.60	55,332.20	338,055.84

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,050. Clean with pressure/chemical spray	21,760. SF 00		0.00	0.43	21.87	1,871.36	11,250.03
3,051. Exterior - paint two coats	21,760. SF 00		0.00	1.58	699.80	6,876.16	41,956.76
3,052. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
3,053. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
3,054. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
3,055. R&R Window screen, 1 - 9 SF	26.00 EA		4.74	36.30	81.92	213.40	1,362.36
3,056. R&R Gutter / downspout - aluminum - 7" to 8"	603.00 LF		0.63	17.54	795.09	2,191.30	13,942.90
<i>200 LF Downspout 403 LF Gutters</i>							
3,057. R&R Light fixture - wall sconce - High grade	2.00 EA		10.49	155.78	24.12	66.52	423.18
3,058. R&R Overhead door & hardware - 9' x 7'	1.00 EA		82.04	934.67	65.56	203.34	1,285.61
3,059. R&R Exterior post light fixture - High grade	2.00 EA		47.46	258.57	29.55	122.40	764.01
<i>Gate light fixture.</i>							
Totals: Exteriors					1,862.13	15,452.32	94,576.11

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,101. Crane and operator - 14 ton capacity - 65' extension boom	8.00 HR						AS INCURRED
3,102. Telehandler/forklift and operator	8.00 HR						AS INCURRED
3,103. Scaffolding	21,760. EA 00		0.00	0.50	437.38	2,176.00	13,493.38



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,104. Commercial Supervision / Project Management - per hour	336.00 HR		0.00	68.91	0.00	4,630.76	27,784.52
3,105. General Laborer - per hour	120.00 HR		0.00	37.61	0.00	902.64	5,415.84
3,106. Temporary toilet (per month)	4.00 MO					AS INCURRED	
3,107. Temporary power usage (per month) - Commercial	1.00 MO		0.00	197.34	19.83	39.46	256.63
3,108. Hand wash station	4.00 MO					AS INCURRED	
3,109. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
3,110. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
3,111. OSHA compliance safety monitor- per hour	HR					AS INCURRED	
3,112. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
3,113. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
3,114. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
3,115. Light bulb - Incand. standard bulb - 1000 hr - mat. only	6.00 EA		0.00	0.79	0.48	0.94	6.16
Totals: GENERAL CONDITIONS					458.19	7,865.14	47,649.05
Total: SAULET-BLDG-06-V5_23					<b>11,260.56</b>	<b>100,274.88</b>	<b>612,908.54</b>

### SAULET-BLDG-07-V5\_23

#### Building 7 Interiors

#### 7102

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,116. Drywall patch / small repair, ready for paint	2.00 EA		0.00	89.02	0.67	35.60	214.31
3,117. Seal/prime then paint the walls twice (3 coats)	287.00 SF		0.00	1.84	8.08	105.62	641.78
3,118. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
3,119. Paint baseboard - two coats	35.08 LF		0.00	2.16	0.46	15.16	91.39
3,120. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,121. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,122. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,123. Towel bar - Detach & reset	1.00 EA		0.00	16.99	0.00	3.40	20.39
3,124. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
Totals: Bathroom					10.89	192.28	1,164.54
Total: 7102					<b>10.89</b>	<b>192.28</b>	<b>1,164.54</b>

7104



### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	


Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN2
Missing Wall	12' 7" X 9'	Opens into LIVING__DI2
Missing Wall	2' 4" X 9'	Opens into HALLWAY
Door	1' 6" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN2
Missing Wall - Goes to Ceiling	7' 7" X 5'	Opens into KITCHEN2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,125. Paint baseboard - two coats	53.92 LF		0.00	2.16	0.70	23.30	140.47
3,126. Seal/prime then paint the walls twice (3 coats)	356.25 SF		0.00	1.84	10.02	131.10	796.62
3,127. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,128. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
3,129. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					10.72	170.90	1,036.04



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Hallway

Height: 9'

61.19 SF Walls	11.96 SF Ceiling
73.15 SF Walls & Ceiling	11.96 SF Floor
1.33 SY Flooring	5.42 LF Floor Perimeter
10.75 LF Ceil. Perimeter	

Missing Wall

1' 1" X 9'

Opens into LIVING\_\_DI2

Missing Wall

2' 4" X 9'

Opens into KITCHEN2

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

2' 8" X 6' 8"

Opens into BEDROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,130. Paint baseboard - two coats	5.42 LF		0.00	2.16	0.07	2.34	14.12
3,131. Seal/prime then paint the walls twice (3 coats)	61.19 SF		0.00	1.84	1.72	22.52	136.83
3,132. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,133. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
3,134. Final cleaning - construction - Residential	11.96 SF		0.00	0.34	0.00	0.82	4.89
Totals: Hallway					1.79	34.58	209.22



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall

12' 7" X 9'

Opens into KITCHEN2

Missing Wall

4' 1" X 9'

Opens into ENTRY

Window

4' X 4'

Opens into Exterior

Door

4' X 6' 8"

Opens into Exterior

Window

4' X 4'

Opens into Exterior

Missing Wall

1' 1" X 9'

Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,135. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,136. Batt insulation - 4" - R13 - paper / foil faced	20.00 SF		0.00	1.07	1.45	4.28	27.13
3,137. Baseboard - 4 1/4"	10.00 LF		0.00	4.14	2.03	8.28	51.71
3,138. Paint baseboard - two coats	48.58 LF		0.00	2.16	0.64	20.98	126.55
3,139. Seal/prime then paint the walls twice (3 coats)	414.58 SF		0.00	1.84	11.67	152.56	927.06
3,140. Window sill	4.00 LF		0.00	3.12	0.37	2.50	15.35
3,141. Trim board - 1" x 4" - installed (pine)	4.00 LF		0.00	3.97	0.78	3.18	19.84
3,142. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,143. In-wall / In-ceiling speaker - Detach & reset	2.00 EA		0.00	18.44	0.00	7.38	44.26
3,144. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
3,145. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,146. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
3,147. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					18.29	261.98	1,590.10
Total: 7104					<b>30.80</b>	<b>467.46</b>	<b>2,835.36</b>

### 7105



#### Entry

Height: 9'

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

Door

3' X 6' 8"

Opens into Exterior

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,148. Paint the walls - two coats	62.50 SF		0.00	1.36	1.38	17.00	103.38
3,149. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,150. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
Totals: Entry					1.45	21.08	127.98



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into BEDROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,151. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
3,152. Batt insulation - 4" - R11-unfaced batt	16.00 SF		0.00	0.70	0.59	2.24	14.03
3,153. Baseboard - 2 1/4"	12.34 LF		0.00	2.90	1.17	7.16	44.12
3,154. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
3,155. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
3,156. Seal/prime then paint the walls twice (3 coats)	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
3,157. Paint the ceiling - two coats	486.47 SF		0.00	1.36	10.76	132.32	804.68
3,158. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,159. Mask the walls per square foot - plastic and tape - 4 mil	823.56 SF		0.00	0.35	4.14	57.66	350.05
3,160. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
Totals: Living Room					43.58	602.78	3,660.06
Total: 7105					<b>45.03</b>	<b>623.86</b>	<b>3,788.04</b>

7109



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into BEDROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM2
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,161. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
3,162. Batt insulation - 4" - R11- unfaced batt	20.00 SF		0.00	0.70	0.74	2.80	17.54
3,163. Baseboard - 4 1/4"	10.00 LF		0.00	4.14	2.03	8.28	51.71
3,164. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
3,165. Seal/prime then paint the walls twice (3 coats)	823.56 SF		0.00	1.84	23.18	303.08	1,841.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,166. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,167. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,168. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
3,169. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
3,170. Mask and cover light fixture Cover Breaker Panel	1.00 EA		0.00	21.63	0.06	4.32	26.01
3,171. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
Totals: Living Room					29.47	451.02	2,735.52
Total: 7109					<b>29.47</b>	<b>451.02</b>	<b>2,735.52</b>

### 7114



#### Bedroom Closet

Height: 8'


88.00 SF Walls	9.17 SF Ceiling
97.17 SF Walls & Ceiling	9.17 SF Floor
1.02 SY Flooring	10.33 LF Floor Perimeter
14.33 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,172. 5/8" - drywall per LF - up to 2' tall	10.33 LF		0.00	11.45	1.47	23.66	143.41
3,173. Batt insulation - 4" - R13 - paper / foil faced	6.00 SF		0.00	1.07	0.43	1.28	8.13
3,174. Seal/prime then paint the walls twice (3 coats)	88.00 SF		0.00	1.84	2.48	32.38	196.78
3,175. Baseboard - 4 1/4"	10.33 LF		0.00	4.14	2.10	8.56	53.43
3,176. Seal & paint baseboard - two coats	10.33 LF		0.00	2.24	0.11	4.62	27.87
3,177. Shelving - wire (vinyl coated) - Detach & reset	6.42 LF		0.00	9.66	0.00	12.40	74.42
3,178. Final cleaning - construction - Residential	9.17 SF		0.00	0.34	0.00	0.62	3.74
Totals: Bedroom Closet					6.59	83.52	507.78



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bathroom**

**Height: 8'**

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	

**Door** **2' 4" X 6' 8"** **Opens into LINEN\_CLOSET**  
**Door** **2' 5" X 6' 8"** **Opens into KITCHEN\_DI**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,179. 5/8" - drywall per LF - up to 2' tall	17.00 LF		0.00	11.45	2.43	38.94	236.02
3,180. Seal/prime then paint the walls twice (3 coats)	287.00 SF		0.00	1.84	8.08	105.62	641.78
3,181. Baseboard - 4 1/4"	17.00 LF		0.00	4.14	3.45	14.08	87.91
3,182. Seal & paint baseboard - two coats	35.08 LF		0.00	2.24	0.39	15.72	94.69
3,183. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,184. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,185. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
3,186. Towel bar - Detach & reset	1.00 EA		0.00	16.99	0.00	3.40	20.39
3,187. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
<b>Totals: Bathroom</b>					<b>15.26</b>	<b>214.44</b>	<b>1,301.74</b>



**Bedroom**

**Height: 8'**

278.00 SF Walls	110.63 SF Ceiling
388.63 SF Walls & Ceiling	110.63 SF Floor
12.29 SY Flooring	35.67 LF Floor Perimeter
42.17 LF Ceil. Perimeter	

**Door** **4' X 6' 8"** **Opens into BEDROOM\_CLOS**  
**Door** **2' 6" X 6' 8"** **Opens into LIVING\_ROOM**  
**Window** **4' X 4'** **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


**CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,188. 5/8" - drywall per LF - up to 2' tall	35.67 LF		0.00	11.45	5.09	81.68	495.19
3,189. Batt insulation - 4" - R11- unfaced batt	17.83 SF		0.00	0.70	0.66	2.50	15.64
3,190. Seal/prime then paint the walls twice (3 coats)	278.00 SF		0.00	1.84	7.82	102.30	621.64
3,191. Baseboard - 4 1/4"	18.00 LF		0.00	4.14	3.65	14.90	93.07
3,192. Seal & paint baseboard - two coats	35.67 LF		0.00	2.24	0.39	15.98	96.27
3,193. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,194. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
3,195. Final cleaning - construction - Residential	110.63 SF		0.00	0.34	0.00	7.52	45.13
<b>Totals: Bedroom</b>					<b>18.98</b>	<b>256.06</b>	<b>1,555.42</b>
<b>Total: 7114</b>					<b>40.83</b>	<b>554.02</b>	<b>3,364.94</b>

7203

**Kitchen**

**Height: 8'**



293.44 SF Walls	107.91 SF Ceiling
401.35 SF Walls & Ceiling	107.91 SF Floor
11.99 SY Flooring	40.17 LF Floor Perimeter
40.42 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>2' 2" X 4'</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall</b>	<b>8' 2" X 8'</b>	<b>Opens into LIVING__DI2</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into CLOSET2</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall</b>	<b>2' X 8'</b>	<b>Opens into ROOM1</b>
<b>Door</b>	<b>2' 2" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>8' 5" X 4'</b>	<b>Opens into LIVING__DI2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,196. Seal/prime then paint the walls and ceiling twice (3 coats)	401.35 SF		0.00	1.84	11.29	147.70	897.47




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,197. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,198. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
3,199. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,200. Mask the floor per square foot - plastic and tape - 4 mil	107.91 SF		0.00	0.35	0.54	7.56	45.87
3,201. Final cleaning - construction - Residential	107.91 SF		0.00	0.34	0.00	7.34	44.03
<b>Totals: Kitchen</b>					<b>11.83</b>	<b>196.88</b>	<b>1,193.00</b>



**Living / Dining Room**


**Height: 8'**

394.22 SF Walls	294.17 SF Ceiling
688.39 SF Walls & Ceiling	294.17 SF Floor
32.69 SY Flooring	60.08 LF Floor Perimeter
50.08 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 4" X 8'</b>	<b>Opens into ROOM3</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 9" X 4'</b>	<b>Opens into ROOM3</b>
<b>Missing Wall</b>	<b>8' 2" X 8'</b>	<b>Opens into KITCHEN2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 4'</b>	<b>Opens into KITCHEN2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>8' 11" X 4'</b>	<b>Opens into KITCHEN2</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>3' 9" X 8'</b>	<b>Opens into ROOM3</b>

**Subroom: Room3 (1)**

**Height: 8'**



49.33 SF Walls	4.33 SF Ceiling
53.67 SF Walls & Ceiling	4.33 SF Floor
0.48 SY Flooring	6.17 LF Floor Perimeter
6.17 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>5' 8" X 8'</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall</b>	<b>2' X 8'</b>	<b>Opens into KITCHEN2</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,202. 5/8" drywall - hung, taped, floated, ready for paint	96.00 SF		0.00	2.87	6.46	55.10	337.08
3,203. Batt insulation - 6" - R19 - unfaced batt	96.00 SF		0.00	1.07	6.17	20.54	129.43
3,204. Seal/prime then paint the walls and ceiling twice (3 coats)	742.06 SF		0.00	1.84	20.88	273.08	1,659.35
3,205. Paint baseboard - two coats	66.25 LF		0.00	2.16	0.87	28.62	172.59
3,206. Seal & paint base shoe or quarter round	66.25 LF		0.00	1.19	0.73	15.76	95.33
3,207. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,208. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,209. Batt insulation - 4" - R13 - paper / foil faced	96.00 SF		0.00	1.07	6.95	20.54	130.21
3,210. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
3,211. Mask the floor per square foot - plastic and tape - 4 mil	298.50 SF		0.00	0.35	1.50	20.90	126.88
3,212. Final cleaning - construction - Residential	298.50 SF		0.00	0.34	0.00	20.30	121.79
<b>Totals: Living / Dining Room</b>					<b>43.56</b>	<b>504.66</b>	<b>3,071.63</b>
<b>Total: 7203</b>					<b>55.39</b>	<b>701.54</b>	<b>4,264.63</b>

7206



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen / Dining

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	


<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,213. 5/8" drywall - hung, taped, floated, ready for paint	413.33 SF		0.00	2.87	27.83	237.26	1,451.35
3,214. Batt insulation - 6" - R19 - unfaced batt	413.33 SF		0.00	1.07	26.59	88.46	557.31
3,215. Seal/prime then paint the walls twice (3 coats)	413.33 SF		0.00	1.84	11.63	152.10	924.26
3,216. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06
3,217. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,218. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
<b>Totals: Kitchen / Dining</b>					<b>67.61</b>	<b>536.96</b>	<b>3,289.28</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,219. Paint the walls - two coats	232.67 SF		0.00	1.36	5.14	63.28	384.85
3,220. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
3,221. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,222. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
3,223. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55

Totals: Living Room 7.09 114.26 692.59


Total: 7206 **74.70 651.22 3,981.87**

7211



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**


**Height: 8'**

394.22 SF Walls	294.17 SF Ceiling
688.39 SF Walls & Ceiling	294.17 SF Floor
32.69 SY Flooring	60.08 LF Floor Perimeter
50.08 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 4" X 8'</b>	<b>Opens into ROOM3</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 9" X 4'</b>	<b>Opens into ROOM3</b>
<b>Missing Wall</b>	<b>8' 2" X 8'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>8' 11" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>3' 9" X 8'</b>	<b>Opens into ROOM3</b>

**Subroom: Room3 (1)**

**Height: 8'**



49.33 SF Walls	4.33 SF Ceiling
53.67 SF Walls & Ceiling	4.33 SF Floor
0.48 SY Flooring	6.17 LF Floor Perimeter
6.17 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>5' 8" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>2' X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,224. 5/8" drywall - hung, taped, floated, ready for paint	15.00 SF		0.00	2.87	1.01	8.62	52.68
3,225. R&R Batt insulation - 4" - R11-unfaced batt	15.00 SF		0.30	0.70	0.56	3.00	18.56
3,226. R&R Baseboard - 4 1/4"	7.00 LF		0.57	4.14	1.42	6.60	40.99
3,227. Seal & paint baseboard - two coats	66.25 LF		0.00	2.24	0.73	29.68	178.81
3,228. Seal/prime then paint the walls and ceiling twice (3 coats)	742.06 SF		0.00	1.84	20.88	273.08	1,659.35
3,229. Mask the walls per square foot - plastic and tape - 4 mil	443.56 SF		0.00	0.35	2.23	31.06	188.54
3,230. Final cleaning - construction - Residential	298.50 SF		0.00	0.34	0.00	20.30	121.79



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living / Dining Room					26.83	372.34	2,260.72
Total: 7211					<b>26.83</b>	<b>372.34</b>	<b>2,260.72</b>

**7213**

Room2	Height: 9'
380.72 SF Walls	132.66 SF Ceiling
513.38 SF Walls & Ceiling	128.94 SF Floor
14.33 SY Flooring	50.92 LF Floor Perimeter
42.83 LF Ceil. Perimeter	

- Missing Wall** 16' 11" X 9' Opens into LIVING\_\_DIN
- Missing Wall - Goes to Ceiling** 9' 5" X 5' Opens into ROOM2
- Missing Wall - Goes to Ceiling** 1' 11" X 5' Opens into ROOM2
- Door** 3' X 6' 8" Opens into UTILITY\_ROOM
- Door** 1' 11" X 6' 8" Opens into PANTRY
- Door** 3' X 6' 8" Opens into Exterior
- Door** 3' X 6' 8" Opens into BATHROOM1
- Door** 3' X 6' 8" Opens into BEDROOM
- Missing Wall** 1' 1" X 9' Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,231. 5/8" drywall - hung, taped, floated, ready for paint	380.72 SF		0.00	2.87	25.64	218.54	1,336.85
3,232. Batt insulation - 6" - R19 - unfaced batt	380.72 SF		0.00	1.07	24.49	81.48	513.34
3,233. Seal/prime then paint the walls twice (3 coats)	380.72 SF		0.00	1.84	10.71	140.10	851.33
3,234. Seal & paint baseboard - two coats	50.92 LF		0.00	2.24	0.56	22.82	137.44
3,235. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,236. Mask the floor per square foot - plastic and tape - 4 mil	128.94 SF		0.00	0.35	0.65	9.02	54.80
3,237. Final cleaning - construction - Residential	128.94 SF		0.00	0.34	0.00	8.76	52.60

Totals: Room2					62.96	499.00	3,056.97
---------------	--	--	--	--	-------	--------	----------


Total: 7213					<b>62.96</b>	<b>499.00</b>	<b>3,056.97</b>
-------------	--	--	--	--	--------------	---------------	-----------------



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

7304



**Entry**

**Height: 9'**

124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	


- Door** 3' X 6' 8" **Opens into Exterior**
- Door** 3' X 6' 8" **Opens into UTILITY\_ROOM**
- Missing Wall** 4' 1" X 9' **Opens into LIVING\_\_DIN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,238. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
<i>Walls</i>							
3,239. Paint the walls - two coats	124.25 SF		0.00	1.36	2.75	33.80	205.53
<i>Paint and blend (walls)</i>							
3,240. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
3,241. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
3,242. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,243. Seal & paint base shoe or quarter round	12.25 LF		0.00	1.19	0.14	2.92	17.64
3,244. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
3,245. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
<b>Totals: Entry</b>					<b>3.76</b>	<b>86.42</b>	<b>522.35</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,246. Paint the walls - two coats	414.58 SF		0.00	1.36	9.17	112.76	685.76
3,247. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
3,248. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,249. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>10.62</b>	<b>172.50</b>	<b>1,045.65</b>
<b>Total: 7304</b>					<b>14.38</b>	<b>258.92</b>	<b>1,568.00</b>

7306



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM2
Door	1' 10" X 6' 8"	Opens into PANTRY1
Door	3' 1" X 6' 8"	Opens into UTILITY_ROO1
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM1
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,250. 5/8" drywall - hung, taped, floated, ready for paint	150.00 SF		0.00	2.87	10.10	86.10	526.70
3,251. Batt insulation - 4" - R11-unfaced batt	100.00 SF		0.00	0.70	3.72	14.00	87.72
3,252. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
3,253. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
3,254. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
3,255. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
3,256. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
3,257. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,258. Baseboard - 4 1/4"	9.00 LF		0.00	4.14	1.83	7.46	46.55
3,259. Casing - 2 1/4"	16.00 LF		0.00	2.23	1.87	7.14	44.69
3,260. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,261. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,262. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
3,263. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
Totals: Living Room					61.15	812.46	4,935.71
Total: 7306					<b>61.15</b>	<b>812.46</b>	<b>4,935.71</b>

### 7313



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,264. 1/2" water rock - hung, taped, floated, ready for paint	32.00 SF		0.00	2.88	2.25	18.44	112.85
3,265. Batt insulation - 4" - R13 - paper / foil faced	32.00 SF		0.00	1.07	2.32	6.84	43.40
3,266. Seal/prime then paint the walls and ceiling twice (3 coats)	390.74 SF		0.00	1.84	11.00	143.80	873.76
3,267. Detach & Reset Light bar - 3 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
3,268. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,269. Bathroom ventilation fan - Detach & reset	1.00 EA		0.00	73.14	0.00	14.62	87.76
3,270. Towel bar - Detach & reset	1.00 EA		0.00	16.99	0.00	3.40	20.39
3,271. Bathroom mirror - Detach & reset	20.00 SF		0.00	9.37	0.00	37.48	224.88
3,272. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
3,273. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
Totals: Bathroom					15.97	249.56	1,513.17

1' 8" X 6' 8"

Opens into LINEN\_CLOSET

Door


3' X 6' 8"

Opens into LIVING\_ROOM2



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room/Dining/Kitchen

Height: 9'

878.32 SF Walls	505.70 SF Ceiling
1,384.02 SF Walls & Ceiling	500.53 SF Floor
55.61 SY Flooring	112.95 LF Floor Perimeter
133.86 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2
Door	3' X 6' 8"	Opens into MASTER_BEDRO
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into Exterior
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM2
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,274. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
3,275. Batt insulation - 4" - R13 - paper / foil faced	6.00 SF		0.00	1.07	0.43	1.28	8.13
3,276. Casing - 2 1/4"	8.00 LF		0.00	2.23	0.93	3.56	22.33
3,277. Baseboard - 4 1/4"	4.00 LF		0.00	4.14	0.81	3.32	20.69
3,278. Paint baseboard - two coats	225.89 LF		0.00	2.16	2.95	97.58	588.45
3,279. Seal/prime then paint the walls twice (3 coats)	878.32 SF		0.00	1.84	24.72	323.22	1,964.05
3,280. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
3,281. Heat/AC register - Mechanically attached - Detach & reset	3.00 EA		0.00	18.80	0.00	11.28	67.68
3,282. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
3,283. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,284. Final cleaning - construction - Residential	500.53 SF		0.00	0.34	0.00	34.04	204.22

Totals: Living Room/Dining/Kitchen 30.63 518.92 3,144.23

Total: 7313 46.60 768.48 4,657.40



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

7402



**Bedroom**

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**3' X 6' 8"**

**Opens into LIVING\_ROOM**

**Door**

**2' 8" X 6' 8"**


**Opens into WALKIN\_CLOS1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,285. 5/8" drywall - hung, taped, floated, ready for paint	128.00 SF		0.00	2.87	8.62	73.48	449.46
3,286. Batt insulation - 4" - R13 - paper / foil faced	96.00 SF		0.00	1.07	6.95	20.54	130.21
3,287. Blown-in insulation - 10" depth - R26	32.00 SF		0.00	1.12	2.41	7.16	45.41
3,288. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
3,289. Baseboard - 4 1/4"	10.00 LF		0.00	4.14	2.03	8.28	51.71
3,290. Paint baseboard - two coats	41.00 LF		0.00	2.16	0.54	17.72	106.82
3,291. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,292. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
3,293. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,294. Mask the ceiling per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
3,295. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
<b>Totals: Bedroom</b>					23.05	231.72	1,413.44



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY1</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM1</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,296. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
3,297. Batt insulation - 4" - R13 - paper / foil faced	16.00 SF		0.00	1.07	1.16	3.42	21.70
3,298. Seal/prime then paint the walls twice (3 coats)	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
3,299. Baseboard - 4 1/4"	8.00 LF		0.00	4.14	1.62	6.62	41.36
3,300. Base shoe	8.00 LF		0.00	1.41	0.40	2.26	13.94
3,301. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
3,302. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
3,303. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,304. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
3,305. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,306. Mask the ceiling per square foot - plastic and tape - 4 mil	486.47 SF		0.00	0.35	2.44	34.06	206.76
3,307. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living Room					33.65	533.14	3,232.41
Total: 7402					<b>56.70</b>	<b>764.86</b>	<b>4,645.85</b>

### 7403



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

2' 8" X 6' 8"

Opens into HALLWAY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,308. 5/8" drywall - hung, taped, floated, ready for paint	64.00 SF		0.00	2.87	4.31	36.74	224.73
3,309. Blown-in insulation - 12" depth - R30	64.00 SF		0.00	1.27	5.60	16.26	103.14
3,310. Seal/prime then paint the ceiling twice (3 coats)	129.35 SF		0.00	1.84	3.64	47.60	289.24
3,311. Paint the walls - two coats	375.72 SF		0.00	1.36	8.31	102.20	621.49
3,312. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,313. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,314. Mask the walls per square foot - plastic and tape - 4 mil	375.72 SF		0.00	0.35	1.89	26.30	159.69
3,315. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
Totals: Bedroom					23.75	277.88	1,690.96
Total: 7403					<b>23.75</b>	<b>277.88</b>	<b>1,690.96</b>

### 7405



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Utility Room**

**Height: 9'**

184.94 SF Walls	24.32 SF Ceiling
209.26 SF Walls & Ceiling	24.32 SF Floor
2.70 SY Flooring	19.75 LF Floor Perimeter
22.83 LF Ceil. Perimeter	

DOOR	3' 1" X 6' 8"			Opens into LIVING_ROOM2				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	3,316. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
	3,317. Batt insulation - 10" - R30 - unfaced batt	6.00 SF		0.00	1.57	0.62	1.88	11.92
	3,318. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
	3,319. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
	3,320. Detach & Reset Washer/Washing Machine - Front-loading	1.00 EA	46.97	0.00	0.00	0.00	9.40	56.37
	3,321. Detach & Reset Dryer - Electric	1.00 EA	36.21	0.00	0.00	0.00	7.24	43.45
	3,322. Detach & Reset Shelving - wire (vinyl coated)	4.00 LF	9.66	0.00	0.00	0.00	7.72	46.36
	3,323. Seal/prime then paint the walls and ceiling twice (3 coats)	209.26 SF		0.00	1.84	5.89	77.00	467.93
	3,324. Mask the walls per square foot - plastic and tape - 4 mil	184.94 SF		0.00	0.35	0.93	12.94	78.60
	3,325. Final cleaning - construction - Residential	24.32 SF		0.00	0.34	0.00	1.66	9.93
Totals: Utility Room						7.84	134.94	817.57



**Bedroom**

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

DOOR	4' X 4'			Opens into Exterior				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	3' X 6' 8"							
	2' 8" X 6' 8"							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,326. 5/8" drywall - hung, taped, floated, ready for paint	110.00 SF		0.00	2.87	7.41	63.14	386.25
3,327. Batt insulation - 10" - R30 - unfaced batt	26.00 SF		0.00	1.57	2.69	8.16	51.67
3,328. Batt insulation - 4" - R11- unfaced batt	14.00 SF		0.00	0.70	0.52	1.96	12.28
3,329. Baseboard - 2 1/4"	19.00 LF		0.00	2.90	1.79	11.02	67.91
3,330. Casing - 2 1/4"	7.00 LF		0.00	2.23	0.82	3.12	19.55
3,331. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
3,332. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
3,333. Seal/prime then paint the walls and ceiling twice (3 coats)	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
3,334. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
3,335. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,336. Clean and deodorize carpet	136.10 SF		0.00	0.57	0.00	15.52	93.10
3,337. Mask the ceiling per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
3,338. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					30.42	343.88	2,093.74



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,339. 5/8" drywall - hung, taped, floated, ready for paint	102.00 SF		0.00	2.87	6.87	58.54	358.15
3,340. Batt insulation - 4" - R11-unfaced batt	6.00 SF		0.00	0.70	0.22	0.84	5.26
3,341. Baseboard - 2 1/4"	25.34 LF		0.00	2.90	2.39	14.70	90.58
3,342. Casing - 2 1/4"	17.00 LF		0.00	2.23	1.98	7.58	47.47
3,343. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
3,344. Window blind - aluminum - 1" - 7.1 to 14 SF	1.00 EA		0.00	85.47	4.32	17.10	106.89
3,345. Crown molding - 3 1/4"	9.34 LF		0.00	4.40	1.56	8.22	50.88
3,346. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
3,347. Paint crown molding - one coat	123.33 LF		0.00	1.48	1.36	36.50	220.39
3,348. Seal & paint trim - two coats	108.42 LF		0.00	2.15	1.31	46.62	281.03
3,349. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
3,350. Mask the walls per square foot - plastic and tape - 4 mil	823.56 SF		0.00	0.35	4.14	57.66	350.05
3,351. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living Room					62.75	821.94	4,994.23
Total: 7405					<b>101.01</b>	<b>1,300.76</b>	<b>7,905.54</b>

**7406**



**Master Walk-in Closet**

**Height: 8'**

174.90 SF Walls	32.11 SF Ceiling
207.01 SF Walls & Ceiling	32.11 SF Floor
3.57 SY Flooring	21.45 LF Floor Perimeter
23.95 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
				<b>2' 6" X 6' 8"</b>			
				<b>Opens into MASTER_BEDRO</b>			
3,352. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
3,353. Seal/prime then paint the walls twice (3 coats)	174.90 SF		0.00	1.84	4.92	64.36	391.10
3,354. Baseboard - 4 1/4"	8.00 LF		0.00	4.14	1.62	6.62	41.36
3,355. Quarter round - 3/4"	8.00 LF		0.00	1.65	0.59	2.64	16.43
3,356. Seal & paint base shoe or quarter round	21.45 LF		0.00	1.19	0.24	5.10	30.87
3,357. Seal & paint baseboard - two coats	21.45 LF		0.00	2.24	0.24	9.62	57.91
3,358. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,359. Final cleaning - construction - Commercial	32.11 SF		0.00	0.27	0.00	1.74	10.41
Totals: Master Walk-in Closet					8.69	103.02	626.82



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**


**Height: 8'**

278.00 SF Walls	110.63 SF Ceiling
388.63 SF Walls & Ceiling	110.63 SF Floor
12.29 SY Flooring	35.67 LF Floor Perimeter
42.17 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into BEDROOM_CLOS</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,360. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
3,361. Seal/prime then paint the walls and ceiling twice (3 coats)	388.63 SF		0.00	1.84	10.94	143.02	869.04
3,362. Baseboard - 4 1/4"	8.00 LF		0.00	4.14	1.62	6.62	41.36
3,363. Quarter round - 3/4"	8.00 LF		0.00	1.65	0.59	2.64	16.43
3,364. Seal & paint base shoe or quarter round	35.67 LF		0.00	1.19	0.39	8.50	51.34
3,365. Seal & paint baseboard - two coats	35.67 LF		0.00	2.24	0.39	15.98	96.27
3,366. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,367. Mask the walls per square foot - plastic and tape - 4 mil	278.00 SF		0.00	0.35	1.40	19.46	118.16
3,368. Final cleaning - construction - Commercial	110.63 SF		0.00	0.27	0.00	5.98	35.85

Totals: Bedroom 16.41      215.14      1,307.19



**Bathroom**

**Height: 8'**

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into KITCHEN_DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,369. Seal/prime then paint the ceiling twice (3 coats)	65.56 SF		0.00	1.84	1.85	24.12	146.60
3,370. Exhaust fan - Detach & reset	1.00 EA		0.00	184.31	0.00	36.86	221.17
3,371. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,372. Final cleaning - construction - Commercial	65.56 SF		0.00	0.27	0.00	3.54	21.24
3,373. Mask the walls per square foot - plastic and tape - 4 mil	287.00 SF		0.00	0.35	1.44	20.10	121.99
3,374. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
Totals: Bathroom					3.29	92.84	560.31



### Kitchen / Dining

Height: 8'

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

Missing Wall	15' X 8'	Opens into LIVING_ROOM
Door	2' 5" X 6' 8"	Opens into BATHROOM
Door	2' 4" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	6' 11" X 4'	Opens into KITCHEN__DI
Missing Wall - Goes to Ceiling	2' 7" X 4'	Opens into KITCHEN__DI
Door	1' 5" X 6' 8"	Opens into CLOSET
Door	3' X 6' 8"	Opens into Exterior
Door	4' X 6' 8"	Opens into UTILITY_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,375. Seal/prime then paint the walls twice (3 coats)	413.33 SF		0.00	1.84	11.63	152.10	924.26
3,376. Seal & paint base shoe or quarter round	58.56 LF		0.00	1.19	0.65	13.94	84.28
3,377. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06
3,378. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen / Dining

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,379. Final cleaning - construction - Commercial	214.90 SF		0.00	0.27	0.00	11.60	69.62
Totals: Kitchen / Dining					12.93	207.64	1,258.78



### Living Room

Height: 8'

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,380. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
3,381. Seal/prime then paint the walls twice (3 coats)	232.67 SF		0.00	1.84	6.55	85.62	520.28
3,382. Baseboard - 4 1/4"	8.00 LF		0.00	4.14	1.62	6.62	41.36
3,383. Quarter round - 3/4"	8.00 LF		0.00	1.65	0.59	2.64	16.43
3,384. Seal & paint base shoe or quarter round	29.50 LF		0.00	1.19	0.33	7.02	42.46
3,385. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
3,386. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,387. Final cleaning - construction - Commercial	141.03 SF		0.00	0.27	0.00	7.62	45.70
Totals: Living Room					10.50	135.68	824.60
Total: 7406					<b>51.82</b>	<b>754.32</b>	<b>4,577.70</b>

7407



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Entry**

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

- Missing Wall** **1' 5" X 9'** **Opens into LIVING\_ROOM**
- Missing Wall** **4' 5" X 9'** **Opens into KITCHEN**
- Door** **3' X 6' 8"** **Opens into Exterior**
- Door** **2' 8" X 6' 8"** **Opens into BATHROOM**
- Door** **2' 10" X 6' 8"** **Opens into BEDROOM**
- Missing Wall** **4' 6" X 9'** **Opens into LIVING\_ROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,388. Seal/prime then paint the ceiling twice (3 coats)	48.39 SF		0.00	1.84	1.36	17.80	108.20
3,389. Mask the walls per square foot - plastic and tape - 4 mil	147.33 SF		0.00	0.35	0.74	10.32	62.63
3,390. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					2.10	31.42	190.58



**Kitchen**

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling** **6' 4" X 5'** **Opens into LIVING\_ROOM**
- Door** **1' 8" X 6' 8"** **Opens into PANTRY**
- Door** **3' X 6' 8"** **Opens into UTILITY\_ROOM**
- Missing Wall** **4' 5" X 9'** **Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,391. Seal/prime then paint the ceiling twice (3 coats)	65.15 SF		0.00	1.84	1.83	23.98	145.69
3,392. Detach & Reset Track lighting - track only	3.00 LF	9.84	0.00	0.00	0.00	5.90	35.42
3,393. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,394. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,395. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,396. Mask the walls per square foot - plastic and tape - 4 mil	201.97 SF		0.00	0.35	1.02	14.14	85.85
3,397. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>2.85</b>	<b>104.70</b>	<b>630.99</b>



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,398. Seal/prime then paint the ceiling twice (3 coats)	215.36 SF		0.00	1.84	6.06	79.26	481.58
3,399. Detach & Reset Track lighting - track only	3.00 LF	9.84	0.00	0.00	0.00	5.90	35.42
3,400. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
3,401. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,402. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,403. Mask the walls per square foot - plastic and tape - 4 mil	425.08 SF		0.00	0.35	2.14	29.76	180.68
3,404. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>8.20</b>	<b>185.80</b>	<b>1,122.98</b>
<b>Total: 7407</b>					<b>13.15</b>	<b>321.92</b>	<b>1,944.55</b>

7408



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom


Height: 9'

363.67 SF Walls	81.15 SF Ceiling
444.82 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	38.33 LF Floor Perimeter
46.33 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,405. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
<i>Walls</i>							
3,406. Paint the walls - two coats	363.67 SF		0.00	1.36	8.04	98.92	601.55
3,407. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
3,408. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
3,409. Seal & paint baseboard - two coats	38.33 LF		0.00	2.24	0.42	17.18	103.46
3,410. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,411. Seal & paint base shoe or quarter round	38.33 LF		0.00	1.19	0.42	9.12	55.15
3,412. Final cleaning - construction - Residential	81.15 SF		0.00	0.34	0.00	5.52	33.11
<b>Totals: Bathroom</b>					<b>10.12</b>	<b>223.02</b>	<b>1,348.23</b>

7409



### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS1</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,413. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
3,414. Batt insulation - 4" - R13 - paper / foil faced	6.00 SF		0.00	1.07	0.43	1.28	8.13
3,415. Seal/prime then paint the walls twice (3 coats)	366.22 SF		0.00	1.84	10.31	134.76	818.91
3,416. Baseboard - 4 1/4"	9.00 LF		0.00	4.14	1.83	7.46	46.55
3,417. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
3,418. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,419. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					13.81	198.06	1,202.23
Total: 7409					13.81	198.06	1,202.23
Total: 7408					23.93	421.08	2,550.46

7411



### Living / Dining Room

Height: 8'

394.22 SF Walls	294.17 SF Ceiling
688.39 SF Walls & Ceiling	294.17 SF Floor
32.69 SY Flooring	60.08 LF Floor Perimeter
50.08 LF Ceil. Perimeter	

Missing Wall	11' 4" X 8'	Opens into ROOM3
Missing Wall - Goes to Ceiling	3' 9" X 4'	Opens into ROOM3
Missing Wall	8' 2" X 8'	Opens into KITCHEN
Missing Wall - Goes to Ceiling	2' 6" X 4'	Opens into KITCHEN
Missing Wall - Goes to Ceiling	8' 11" X 4'	Opens into KITCHEN
Door	2' 6" X 6' 8"	Opens into BATHROOM
Door	2' 8" X 6' 8"	Opens into BEDROOM
Window	4' 1" X 4'	Opens into Exterior
Window	4' 1" X 4'	Opens into Exterior
Missing Wall	3' 9" X 8'	Opens into ROOM3




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

#### Subroom: Room3 (1)

Height: 8'



49.33 SF Walls  
53.67 SF Walls & Ceiling  
0.48 SY Flooring  
6.17 LF Ceil. Perimeter

4.33 SF Ceiling  
4.33 SF Floor  
6.17 LF Floor Perimeter

Missing Wall

5' 8" X 8'

Opens into LIVING\_\_DI2

Missing Wall

2' X 8'

Opens into KITCHEN


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,420. 5/8" drywall - hung, taped, floated, ready for paint	45.00 SF		0.00	2.87	3.03	25.84	158.02
3,421. Seal/prime then paint the walls twice (3 coats)	443.56 SF		0.00	1.84	12.48	163.24	991.87
3,422. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,423. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,424. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,425. Baseboard - 4 1/4"	5.00 LF		0.00	4.14	1.02	4.14	25.86
3,426. Seal & paint baseboard - two coats	66.25 LF		0.00	2.24	0.73	29.68	178.81
3,427. Seal & paint base shoe or quarter round	66.25 LF		0.00	1.19	0.73	15.76	95.33
3,428. Shelving - 12" - in place	40.00 LF		0.00	10.47	16.32	83.76	518.88
3,429. Seal & paint wood shelving, 12"- 24" width	40.00 LF		0.00	6.68	1.93	53.44	322.57
3,430. Paint crown molding, oversized - one coat	56.25 LF		0.00	1.58	0.68	17.78	107.34
3,431. Final cleaning - construction - Residential	298.50 SF		0.00	0.34	0.00	20.30	121.79
Totals: Living / Dining Room					36.92	464.10	2,821.39
Total: 7411					<b>36.92</b>	<b>464.10</b>	<b>2,821.39</b>

7412



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN2
Missing Wall	12' 7" X 9'	Opens into LIVING__DIN
Missing Wall	2' 4" X 9'	Opens into HALLWAY
Door	1' 6" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	7' 7" X 5'	Opens into KITCHEN2
Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,432. Paint the ceiling - two coats	116.09 SF		0.00	1.36	2.57	31.58	192.03
3,433. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
3,434. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					3.13	47.00	285.06



### Entry

Height: 9'

124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	


Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into UTILITY_ROOM
Missing Wall	4' 1" X 9'	Opens into LIVING__DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,435. Paint the ceiling - two coats	28.58 SF		0.00	1.36	0.63	7.78	47.28
3,436. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
3,437. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					0.77	11.72	71.08



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall	12' 7" X 9'	Opens into KITCHEN2
Missing Wall	4' 1" X 9'	Opens into ENTRY
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	1' 1" X 9'	Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,438. 5/8" drywall - hung, taped, floated, ready for paint	289.60 SF		0.00	2.87	19.50	166.24	1,016.89
<i>Ceiling</i>							
3,439. Blown-in insulation - 10" depth - R26	289.60 SF		0.00	1.12	21.83	64.88	411.06
<i>Ceiling</i>							
3,440. Seal/prime then paint the ceiling twice (3 coats)	289.60 SF		0.00	1.84	8.15	106.58	647.59
<i>Ceiling</i>							
3,441. Crown molding - 3 1/4"	42.00 LF		0.00	4.40	7.01	36.96	228.77
3,442. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
3,443. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
3,444. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>58.74</b>	<b>438.20</b>	<b>2,687.70</b>
<b>Total: 7412</b>					<b>62.64</b>	<b>496.92</b>	<b>3,043.84</b>

7413



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

**Door** 1' 8" X 6' 8" Opens into LINEN\_CLOSET  
**Door** 3' X 6' 8" Opens into LIVING\_ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,445. Seal/prime then paint the walls and ceiling twice (3 coats)	390.74 SF		0.00	1.84	11.00	143.80	873.76
3,446. Mask the walls per square foot - plastic and tape - 4 mil	310.89 SF		0.00	0.35	1.56	21.76	132.13
3,447. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
Totals: Bathroom					12.56	171.00	1,038.48
Total: 7413					<b>12.56</b>	<b>171.00</b>	<b>1,038.48</b>
Total: Building 7 Interiors					<b>881.51</b>	<b>11,325.44</b>	<b>68,832.47</b>

### Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
***Ceiling***							
3,448. 5/8" drywall - hung, taped, heavy texture, ready for paint	356.26 SF		0.00	3.35	29.36	238.70	1,461.53
<i>First Floor</i>							
3,449. Blown-in insulation - 14" depth - R38	178.13 SF		0.00	1.50	19.69	53.44	340.33
<i>First Floor</i>							
3,450. Paint - two coats	178.13 SF		0.00	1.35	3.76	48.10	292.34
<i>First Floor</i>							
3,451. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
<i>First Floor</i>							
3,452. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
<i>First Floor</i>							
***Ceiling***							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,453. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>First Floor</i>	78.00 SF		0.00	3.35	6.43	52.26	319.99
3,454. Blown-in insulation - 14" depth - R38 <i>First Floor</i>	856.00 SF		0.00	1.50	94.63	256.80	1,635.43
3,455. Paint - two coats <i>First Floor</i>	1,250.00 SF		0.00	1.35	26.38	337.50	2,051.38
3,456. Sprinkler head/escutcheon - Detach & reset <i>First Floor</i>	16.00 EA		0.00	17.44	0.00	55.80	334.84
3,457. Light fixture - Detach & reset <i>First Floor</i>	17.00 EA		0.00	50.85	0.00	172.90	1,037.35
3,458. Ceiling fan - Detach & reset <i>First Floor</i>	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
3,459. Exit sign - Detach & reset <i>First Floor</i>	6.00 EA		0.00	66.10	0.00	79.32	475.92
3,460. Heat/AC register - Mechanically attached - Detach & reset <i>First Floor</i>	16.00 EA		0.00	18.80	0.00	60.16	360.96
3,461. Batt insulation - 4" - R15 - paper / foil faced <i>First Floor</i>	27.00 SF		0.00	1.32	2.25	7.12	45.01
3,462. Paint door or window opening - 1 coat (per side) <i>First Floor</i> ***Ceiling***	1.00 EA		0.00	30.60	0.32	6.12	37.04
3,463. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Second Floor</i>	544.00 SF		0.00	3.35	44.83	364.48	2,231.71
3,464. Blown-in insulation - 14" depth - R38 <i>Second Floor</i>	60.00 SF		0.00	1.50	6.63	18.00	114.63
3,465. Sprinkler head/escutcheon - Detach & reset <i>Second Floor</i>	17.00 EA		0.00	17.44	0.00	59.30	355.78
3,466. Light fixture - Detach & reset <i>Second Floor</i>	21.00 EA		0.00	50.85	0.00	213.58	1,281.43



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,467. Ceiling fan - Detach & reset <i>Second Floor</i>	4.00 EA		0.00	181.09	0.00	144.88	869.24
3,468. Exit sign - Detach & reset <i>Second Floor</i>	5.00 EA		0.00	66.10	0.00	66.10	396.60
3,469. Heat/AC register - Mechanically attached - Detach & reset <i>Second Floor</i>	19.00 EA		0.00	18.80	0.00	71.44	428.64
3,470. Batt insulation - 4" - R15 - paper / foil faced <i>Second Floor</i>	212.00 SF		0.00	1.32	17.68	55.96	353.48
3,471. Paint the surface area - two coats - 2 colors <i>Second Floor</i>	2,655.04 SF		0.00	1.72	56.03	913.34	5,536.04
3,472. Paint door or window opening - 1 coat (per side) <i>Line item to detach and reset wall sconce emergency lights..</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
3,473. Paint the surface area - two coats <i>Second Floor</i> ***Ceiling***	969.30 SF		0.00	1.36	21.43	263.66	1,603.34
3,474. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Third Floor</i>	634.00 SF		0.00	3.35	52.25	424.78	2,600.93
3,475. Blown-in insulation - 14" depth - R38 <i>Third Floor</i>	60.00 SF		0.00	1.50	6.63	18.00	114.63
3,476. Sprinkler head/escutcheon - Detach & reset <i>Third Floor</i>	17.00 EA		0.00	17.44	0.00	59.30	355.78
3,477. Light fixture - Detach & reset <i>Third Floor</i>	19.00 EA		0.00	50.85	0.00	193.24	1,159.39
3,478. Ceiling fan - Detach & reset <i>Third Floor</i>	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
3,479. Exit sign - Detach & reset <i>Third Floor</i>	5.00 EA		0.00	66.10	0.00	66.10	396.60
3,480. Heat/AC register - Mechanically attached - Detach & reset <i>Third Floor</i>	19.00 EA		0.00	18.80	0.00	71.44	428.64



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,481. Batt insulation - 4" - R15 - paper / foil faced <i>Third Floor</i>	257.00 SF		0.00	1.32	21.44	67.84	428.52
3,482. Paint door or window opening - 1 coat (per side) <i>Third Floor</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
3,483. Paint the surface area - two coats <i>Third Floor</i>	1,256.00 SF		0.00	1.36	27.77	341.64	2,077.57
***Ceiling***							
3,484. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Fourth Floor</i>	634.00 SF		0.00	3.35	52.25	424.78	2,600.93
3,485. Blown-in insulation - 14" depth - R38 <i>Fourth Floor</i>	60.00 SF		0.00	1.50	6.63	18.00	114.63
3,486. Sprinkler head/escutcheon - Detach & reset <i>Fourth Floor</i>	17.00 EA		0.00	17.44	0.00	59.30	355.78
3,487. Light fixture - Detach & reset <i>Fourth Floor</i>	19.00 EA		0.00	50.85	0.00	193.24	1,159.39
3,488. Ceiling fan - Detach & reset <i>Fourth Floor</i>	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
3,489. Exit sign - Detach & reset <i>Fourth Floor</i>	5.00 EA		0.00	66.10	0.00	66.10	396.60
3,490. Heat/AC register - Mechanically attached - Detach & reset <i>Fourth Floor</i>	19.00 EA		0.00	18.80	0.00	71.44	428.64
3,491. Batt insulation - 4" - R15 - paper / foil faced <i>Fourth Floor</i>	257.00 SF		0.00	1.32	21.44	67.84	428.52
3,492. Paint the surface area - two coats <i>Fourth Floor</i>	969.30 SF		0.00	1.36	21.43	263.66	1,603.34
3,493. Paint door or window opening - 1 coat (per side) <i>Fourth Floor</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
3,494. Carpenter - General Framer - per hour	30.00 HR		0.00	72.00	0.00	432.00	2,592.00



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Labor to install drywall nailers.</i>							
Totals: Corridor/Breezeway					540.22	6,966.64	42,339.57

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,495. Clean with pressure/chemical spray	21,760. SF 00		0.00	0.43	21.87	1,871.36	11,250.03
3,496. Exterior - paint two coats	21,760. SF 00		0.00	1.58	699.80	6,876.16	41,956.76
3,497. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
3,498. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
3,499. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
3,500. R&R Window screen, 1 - 9 SF	29.00 EA		4.74	36.30	91.37	238.04	1,519.57
3,501. R&R Soffit - vinyl	20.00 SF		0.38	5.81	4.36	24.76	152.92
3,502. Clean with pressure/chemical spray	56.00 SF		0.00	0.43	0.06	4.82	28.96
<i>One (1) set of double doors.</i>							
Totals: Exteriors					961.68	12,922.98	78,499.50

### Garage/Storage



#### B07G1

LxWxH 22' x 10' x 9'

576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,503. Paint the walls and ceiling - two coats	796.00 SF		0.00	1.36	17.60	216.52	1,316.68
3,504. Mask the walls per square foot - plastic and tape - 4 mil	576.00 SF		0.00	0.35	2.89	40.32	244.81



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - B07G1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,505. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B07G1					20.49	271.80	1,651.25
Total: Garage/Storage					<b>20.49</b>	<b>271.80</b>	<b>1,651.25</b>

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,547. Crane and operator - 14 ton capacity - 65' extension boom	8.00 HR					AS INCURRED	
3,548. Telehandler/forklift and operator	8.00 HR					AS INCURRED	
3,549. Scaffolding	21,760. EA 00		0.00	0.50	437.38	2,176.00	13,493.38
3,550. Commercial Supervision / Project Management - per hour	56.00 HR		0.00	68.91	0.00	771.80	4,630.76
3,551. General Laborer - per hour	150.00 HR		0.00	37.61	0.00	1,128.30	6,769.80
3,552. Temporary toilet (per month)	4.00 MO					AS INCURRED	
3,553. Temporary power usage (per month) - Commercial	1.00 MO		0.00	197.34	19.83	39.46	256.63
3,554. Hand wash station	4.00 MO					AS INCURRED	
3,555. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
3,556. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
3,557. OSHA compliance safety monitor- per hour	HR					AS INCURRED	
3,558. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
3,559. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
3,560. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
Totals: GENERAL CONDITIONS					457.71	4,230.90	25,843.09
Total: SAULET-BLDG-07-V5_23					<b>2,861.61</b>	<b>35,717.76</b>	<b>217,165.88</b>

### SAULET-BLDG-08-V5\_23


#### Building 8 Interiors

#### Main Level



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Master Walk-in Closet

Height: 9'

220.39 SF Walls	37.49 SF Ceiling
257.88 SF Walls & Ceiling	37.49 SF Floor
4.17 SY Flooring	23.67 LF Floor Perimeter
26.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' 2" X 6' 8"			Opens into MASTER_BATHR			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
3,561. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	80.00 SF		0.00	2.87	5.39	45.92	280.91	
3,562. Baseboard - 3 1/4"	20.00 LF		0.00	3.49	2.91	13.96	86.67	
3,563. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	257.88 SF		0.00	1.84	7.26	94.90	576.66	
3,564. Seal & paint baseboard - two coats	23.67 LF		0.00	2.24	0.26	10.60	63.88	
3,565. Shelving - wire (vinyl coated) - Detach & reset	16.67 LF		0.00	9.66	0.00	32.20	193.23	
3,566. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
3,567. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03	
3,568. Mask the floor per square foot - plastic and tape - 4 mil	37.49 SF		0.00	0.35	0.19	2.62	15.93	
3,569. Final cleaning - construction - Residential	37.49 SF		0.00	0.34	0.00	2.56	15.31	
<b>Totals: Master Walk-in Closet</b>						16.47	222.08	1,348.93



### Bathroom

Height: 9'

295.00 SF Walls	69.45 SF Ceiling
364.45 SF Walls & Ceiling	69.45 SF Floor
7.72 SY Flooring	32.00 LF Floor Perimeter
35.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' X 6' 8"			Opens into ROOM2			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
3,570. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls (bathroom hall)</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11	



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,571. Baseboard - 3 1/4"	32.00 LF		0.00	3.49	4.66	22.34	138.68
3,572. Seal & paint baseboard - two coats	32.00 LF		0.00	2.24	0.35	14.34	86.37
3,573. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
3,574. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
<i>Wall bathroom</i>							
3,575. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
<i>Wall bathroom</i>							
3,576. Seal/prime then paint the walls and ceiling twice (3 coats)	364.45 SF		0.00	1.84	10.26	134.12	814.97
3,577. Seal & paint base shoe or quarter round	32.00 LF		0.00	1.19	0.35	7.62	46.05
3,578. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,579. Mask the floor per square foot - plastic and tape - 4 mil	69.45 SF		0.00	0.35	0.35	4.86	29.52
3,580. Final cleaning - construction - Residential	69.45 SF		0.00	0.34	0.00	4.72	28.33
Totals: Bathroom					20.39	270.64	1,644.18



### Bedroom

Height: 9'

359.56 SF Walls	136.05 SF Ceiling
495.60 SF Walls & Ceiling	136.05 SF Floor
15.12 SY Flooring	40.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

Door	3' X 6' 8"	Opens into ROOM2
Door	3' 8" X 6' 8"	Opens into WALKIN_CLOS
Window	4' X 4'	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,581. 5/8" drywall - hung, taped, floated, ready for paint	72.00 SF		0.00	2.87	4.85	41.32	252.81
3,582. Batt insulation - 6" - R19 - unfaced batt	72.00 SF		0.00	1.07	4.63	15.40	97.07
3,583. Paint - two coats	359.56 SF		0.00	1.36	7.95	97.80	594.75
3,584. Baseboard - 3 1/4"	8.00 LF		0.00	3.49	1.17	5.58	34.67




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,585. Seal & paint baseboard - two coats	40.00 LF		0.00	2.24	0.44	17.92	107.96
3,586. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,587. Mask the floor per square foot - plastic and tape - 4 mil	136.05 SF		0.00	0.35	0.68	9.52	57.82
3,588. Final cleaning - construction - Residential	136.05 SF		0.00	0.34	0.00	9.26	55.52
Totals: Bedroom					20.63	215.08	1,311.21



### Living / Dining Room

Height: 9'

255.33 SF Walls	236.06 SF Ceiling
491.40 SF Walls & Ceiling	236.06 SF Floor
26.23 SY Flooring	30.42 LF Floor Perimeter
33.67 LF Ceil. Perimeter	

Missing Wall	2' 4" X 9'	Opens into STAIRCASE
Missing Wall	8' 10" X 9'	Opens into STAIRCASE
Missing Wall - Goes to Ceiling	3' 9" X 5'	Opens into STAIRCASE
Missing Wall	1' 1" X 9'	Opens into ROOM2
Missing Wall	16' 11" X 9'	Opens into ROOM2
Door	3' X 6' 8"	Opens into MASTER_BEDRO
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	3' 1" X 9'	Opens into STAIRCASE

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,589. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	58.00 SF		0.00	2.87	3.91	33.30	203.67
3,590. Baseboard - 3 1/4"	29.00 LF		0.00	3.49	4.23	20.24	125.68
3,591. Seal & paint baseboard - two coats	30.42 LF		0.00	2.24	0.34	13.62	82.10
3,592. Seal/prime then paint the walls twice (3 coats) <i>Wall</i>	255.33 SF		0.00	1.84	7.18	93.96	570.95
3,593. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	234.00 SF		0.00	2.87	15.76	134.32	821.66




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,594. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	236.06 SF		0.00	1.12	17.79	52.88	335.06
3,595. Seal/prime then paint the walls twice (3 coats) <i>Ceiling</i>	255.33 SF		0.00	1.84	7.18	93.96	570.95
3,596. Crown molding - 3 1/4"	13.00 LF		0.00	4.40	2.17	11.44	70.81
3,597. Paint crown molding - two coats	33.67 LF		0.00	2.24	0.51	15.08	91.01
3,598. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
3,599. Seal & paint base shoe or quarter round	30.42 LF		0.00	1.19	0.34	7.24	43.78
3,600. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,601. Mask the floor per square foot - plastic and tape - 4 mil	236.06 SF		0.00	0.35	1.19	16.52	100.33
3,602. Final cleaning - construction - Residential	236.06 SF		0.00	0.34	0.00	16.06	96.32
Totals: Living / Dining Room					61.51	537.08	3,283.96
Total: Main Level					<b>119.00</b>	<b>1,244.88</b>	<b>7,588.28</b>

8111



### Kitchen

Height: 9'

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

6' 4" X 5'

Opens into LIVING\_ROOM2

Door

1' 8" X 6' 8"

Opens into PANTRY

Door

3' X 6' 8"

Opens into UTILITY\_ROOM

Missing Wall

4' 5" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,603. Seal/prime then paint the ceiling twice (3 coats)	65.15 SF		0.00	1.84	1.83	23.98	145.69
3,604. Paint the walls - two coats	201.97 SF		0.00	1.36	4.47	54.94	334.09



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,605. Mask the walls per square foot - plastic and tape - 4 mil	201.97 SF		0.00	0.35	1.02	14.14	85.85
3,606. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
Totals: Kitchen					7.32	97.50	592.22



### Living Room

Height: 9'

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

Missing Wall

1' 5" X 9'

Opens into ENTRY

Missing Wall - Goes to Ceiling

6' 10" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 6" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,607. 5/8" drywall - hung, taped, floated, ready for paint	64.00 SF		0.00	2.87	4.31	36.74	224.73
3,608. Batt insulation - 6" - R19 - unfaced batt	64.00 SF		0.00	1.07	4.12	13.70	86.30
3,609. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
3,610. Seal/prime then paint the ceiling twice (3 coats)	215.36 SF		0.00	1.84	6.06	79.26	481.58
3,611. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
3,612. Paint the walls - two coats	425.08 SF		0.00	1.36	9.40	115.62	703.13
3,613. Mask the walls per square foot - plastic and tape - 4 mil	425.08 SF		0.00	0.35	2.14	29.76	180.68
3,614. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					26.03	338.50	2,057.01



### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



#### Entry


**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,615. Seal/prime then paint the ceiling twice (3 coats)	48.39 SF		0.00	1.84	1.36	17.80	108.20
3,616. Paint the walls - two coats	147.33 SF		0.00	1.36	3.26	40.08	243.71
3,617. Mask the walls per square foot - plastic and tape - 4 mil	147.33 SF		0.00	0.35	0.74	10.32	62.63
3,618. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					<b>5.36</b>	<b>71.50</b>	<b>434.29</b>
<b>Total: 8111</b>					<b>38.71</b>	<b>507.50</b>	<b>3,083.52</b>

### 8113



#### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>5' 5" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to Floor</b>	<b>5' 7" X 9'</b>	<b>Opens into ENTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,619. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
<i>Walls</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,620. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
3,621. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
3,622. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,623. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					5.88	91.56	555.34



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,624. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
3,625. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
3,626. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
<i>Walls</i>							
3,627. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
<i>Walls</i>							
3,628. Baseboard - 3 1/4"	4.00 LF		0.00	3.49	0.58	2.80	17.34
3,629. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
3,630. Seal/prime then paint the walls twice (3 coats)	371.67 SF		0.00	1.84	10.46	136.78	831.11
3,631. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,632. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					18.07	216.82	1,318.87



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

Height: 9'

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

Door

2' 8" X 6' 8"

Opens into BATHROOM


Window

4' X 4'

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,633. Seal/prime then paint the walls twice (3 coats)	362.22 SF		0.00	1.84	10.19	133.30	809.97
3,634. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
3,635. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,636. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,637. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					11.56	192.14	1,164.36
Total: 8113					35.51	500.52	3,038.57

8115



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM2

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,638. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
3,639. Seal/prime then paint the walls twice (3 coats)	218.17 SF		0.00	1.84	6.14	80.28	487.85
3,640. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					6.44	96.88	587.80



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,641. 5/8" drywall - hung, taped, floated, ready for paint	18.00 SF		0.00	2.87	1.21	10.34	63.21
<i>Walls</i>							
3,642. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
<i>Walls</i>							
3,643. Baseboard - 3 1/4"	14.00 LF		0.00	3.49	2.04	9.78	60.68
3,644. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
3,645. Paint - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79
<i>Walls</i>							
3,646. Casing - 3 1/4"	8.00 LF		0.00	3.19	1.70	5.10	32.32
3,647. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
3,648. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,649. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
3,650. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					16.44	197.86	1,203.62
Total: 8115					22.88	294.74	1,791.42

8126



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'


Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,651. 5/8" - drywall per LF - up to 2' tall	7.00 LF		0.00	11.45	1.00	16.04	97.19
3,652. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
3,653. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,654. Baseboard - 4 1/4"	7.00 LF		0.00	4.14	1.42	5.80	36.20
3,655. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
3,656. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
3,657. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,658. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
Totals: Kitchen					16.94	249.36	1,513.10



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,659. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
3,660. Install Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
3,661. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
3,662. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
3,663. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,664. Casing - 2 1/4"	7.00 LF		0.00	2.23	0.82	3.12	19.55
3,665. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
3,666. Baseboard - 4 1/4"	4.00 LF		0.00	4.14	0.81	3.32	20.69
3,667. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,668. Batt insulation - 4" - R13 - paper / foil faced	6.00 SF		0.00	1.07	0.43	1.28	8.13
3,669. Floor protection - self-adhesive plastic film	40.83 SF		0.56	0.00	0.57	4.58	28.01
Totals: Entry					8.01	130.58	791.41



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,670. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,671. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
3,672. Paint baseboard - two coats	46.08 LF		0.00	2.16	0.60	19.90	120.03
3,673. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
3,674. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,675. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,676. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,677. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
3,678. Floor protection - self-adhesive plastic film	154.68 SF		0.56	0.00	2.18	17.32	106.12
3,679. Mask the walls per square foot - plastic and tape - 4 mil	371.67 SF		0.00	0.35	1.87	26.02	157.97
3,680. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>21.86</b>	<b>367.00</b>	<b>2,223.88</b>
<b>Total: 8126</b>					<b>46.81</b>	<b>746.94</b>	<b>4,528.39</b>

8128



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" **Opens into ENTRY**

**Door** 2' 8" X 6' 8" **Opens into WALKIN\_CLOS**

**Missing Wall** 4' 11" X 9' **Opens into BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,681. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
<i>Ceiling</i>							
3,682. Blown-in insulation - 10" depth - R26	81.97 SF		0.00	1.12	6.18	18.36	116.35
<i>Ceiling</i>							
3,683. Paint - two coats	423.67 SF		0.00	1.36	9.37	115.24	700.80
3,684. Seal/prime then paint the ceiling twice (3 coats)	81.97 SF		0.00	1.84	2.31	30.16	183.29
3,685. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,686. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
3,687. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,688. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
3,689. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					20.61	218.48	1,331.57
Total: 8128					<b>20.61</b>	<b>218.48</b>	<b>1,331.57</b>

8129



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Missing Wall</b>	<b>4' 11" X 9'</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,690. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
<i>Ceiling</i>							
3,691. Blown-in insulation - 10" depth - R26	81.97 SF		0.00	1.12	6.18	18.36	116.35
<i>Ceiling</i>							
3,692. Paint the walls - two coats	341.69 SF		0.00	1.36	7.55	92.94	565.19
3,693. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
3,694. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72
3,695. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
3,696. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,697. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
3,698. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					28.40	321.94	1,960.06
Total: 8129					<b>28.40</b>	<b>321.94</b>	<b>1,960.06</b>

### 8202



#### Master Bath

Height: 8'

308.67 SF Walls	84.51 SF Ceiling
393.18 SF Walls & Ceiling	84.51 SF Floor
9.39 SY Flooring	37.67 LF Floor Perimeter
43.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b> 3' X 6' 8" Opens into MASTER_BEDRO							
<b>Door</b> 2' 6" X 6' 8" Opens into MASTER_WALK							
3,699. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
<i>Ceiling</i>							
3,700. Blown-in insulation - 10" depth - R26	84.51 SF		0.00	1.12	6.37	18.94	119.96
<i>Ceiling</i>							
3,701. Seal/prime then paint the walls and ceiling twice (3 coats)	393.18 SF		0.00	1.84	11.06	144.70	879.21
3,702. Seal the ceiling w/latex based stain blocker - one coat	84.51 SF		0.00	0.91	0.59	15.38	92.87
3,703. Seal & paint baseboard - two coats	37.67 LF		0.00	2.24	0.42	16.88	101.68
3,704. Seal & paint base shoe or quarter round	37.67 LF		0.00	1.19	0.42	8.96	54.21
3,705. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,706. Mask the floor per square foot - plastic and tape - 4 mil	84.51 SF		0.00	0.35	0.43	5.92	35.93
3,707. Final cleaning - construction - Residential	84.51 SF		0.00	0.34	0.00	5.74	34.47
Totals: Master Bath					20.56	232.54	1,415.77



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Master Bedroom**

**Height: 8'**

353.33 SF Walls  
516.19 SF Walls & Ceiling  
18.10 SY Flooring  
51.17 LF Ceil. Perimeter

162.86 SF Ceiling  
162.86 SF Floor  
45.17 LF Floor Perimeter


**Door** 3' X 6' 8" Opens into LIVING\_\_DIN  
**Door** 3' X 6' 8" Opens into MASTER\_BATH  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,708. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	135.00 SF		0.00	2.87	9.09	77.50	474.04
3,709. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	85.00 SF		0.00	1.07	5.47	18.20	114.62
3,710. Baseboard - 3 1/4"	15.00 LF		0.00	3.49	2.19	10.48	65.02
3,711. Seal & paint baseboard - two coats	45.17 LF		0.00	2.24	0.50	20.24	121.92
3,712. Paint - two coats <i>Walls</i>	353.33 SF		0.00	1.36	7.81	96.10	584.44
3,713. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,714. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,715. Final cleaning - construction - Residential	162.86 SF		0.00	0.34	0.00	11.08	66.45
<b>Totals: Master Bedroom</b>					25.97	265.70	1,620.00



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	


<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,716. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
3,717. Paint the walls and ceiling - two coats	875.58 SF		0.00	1.36	19.36	238.16	1,448.31
3,718. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
3,719. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,720. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
3,721. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>26.18</b>	<b>350.50</b>	<b>2,129.23</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen


Height: 8'

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling	2' 3" X 4'	Opens into KITCHEN2
Missing Wall	14' 2 1/16" X 8"	Opens into LIVING__DIN
Door	1' 10" X 6' 8"	Opens into CLOSET
Door	1' 11" X 6' 8"	Opens into PANTRY
Door	3' X 6' 8"	Opens into Exterior
Missing Wall - Goes to Ceiling	7' 6" X 4'	Opens into KITCHEN2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,722. Paint the walls and ceiling - two coats	525.18 SF		0.00	1.36	11.61	142.84	868.69
3,723. Seal & paint baseboard - two coats	54.92 LF		0.00	2.24	0.61	24.60	148.23
3,724. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,725. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
3,726. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89

Totals: Kitchen 13.90      207.00      1,255.94



### Hall Bathroom

Height: 8'

240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

Door	1' 6" X 6' 8"	Opens into LINEN_CLOSET
Door	2' 8" X 6' 8"	Opens into LIVING__DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,727. 5/8" drywall - hung, taped, floated, ready for paint Ceiling	16.00 SF		0.00	2.87	1.08	9.18	56.18
3,728. Blown-in insulation - 10" depth - R26	57.36 SF		0.00	1.12	4.32	12.84	81.40



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Hall Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
3,729. Paint - two coats	297.58 SF		0.00	1.36	6.58	80.94	492.23
3,730. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,731. Seal & paint baseboard - two coats	29.33 LF		0.00	2.24	0.32	13.14	79.16
3,732. Seal & paint base shoe or quarter round	29.33 LF		0.00	1.19	0.32	6.98	42.20
3,733. Mask the floor per square foot - plastic and tape - 4 mil	57.36 SF		0.00	0.35	0.29	4.02	24.39
3,734. Final cleaning - construction - Residential	57.36 SF		0.00	0.34	0.00	3.90	23.40
<b>Totals: Hall Bathroom</b>					<b>13.37</b>	<b>140.14</b>	<b>854.27</b>
<b>Total: 8202</b>					<b>99.98</b>	<b>1,195.88</b>	<b>7,275.21</b>

8203

### Kitchen

Height: 8'



293.44 SF Walls	107.91 SF Ceiling
401.35 SF Walls & Ceiling	107.91 SF Floor
11.99 SY Flooring	40.17 LF Floor Perimeter
40.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling	2' 2" X 4'	Opens into LIVING__DI2
Missing Wall	8' 2" X 8'	Opens into LIVING__DI2
Door	3' X 6' 8"	Opens into Exterior
Door	1' 8" X 6' 8"	Opens into CLOSET
Door	4' X 6' 8"	Opens into UTILITY_ROOM
Missing Wall	2' X 8'	Opens into ROOM3
Door	2' 2" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	8' 5" X 4'	Opens into LIVING__DI2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,735. 5/8" drywall - hung, taped, floated, ready for paint	46.00 SF		0.00	2.87	3.10	26.40	161.52
<i>Walls</i>							
3,736. Seal/prime then paint the walls twice (3 coats)	293.44 SF		0.00	1.84	8.26	107.98	656.17




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,737. Seal & paint baseboard - two coats Includes entry.	40.17 LF		0.00	2.24	0.44	18.00	108.42
3,738. Seal & paint base shoe or quarter round	40.17 LF		0.00	1.19	0.44	9.56	57.80
3,739. Mask the floor per square foot - plastic and tape - 4 mil	107.91 SF		0.00	0.35	0.54	7.56	45.87
3,740. Final cleaning - construction - Residential	107.91 SF		0.00	0.34	0.00	7.34	44.03
<b>Totals: Kitchen</b>					<b>12.78</b>	<b>176.84</b>	<b>1,073.81</b>



**Living / Dining Room**


**Height: 8'**

394.22 SF Walls	294.17 SF Ceiling
688.39 SF Walls & Ceiling	294.17 SF Floor
32.69 SY Flooring	60.08 LF Floor Perimeter
50.08 LF Ceil. Perimeter	

Missing Wall	11' 4" X 8'	Opens into ROOM2
Missing Wall - Goes to Ceiling	3' 9" X 4'	Opens into ROOM2
Missing Wall	8' 2" X 8'	Opens into KITCHEN2
Missing Wall - Goes to Ceiling	2' 6" X 4'	Opens into KITCHEN2
Missing Wall - Goes to Ceiling	8' 11" X 4'	Opens into KITCHEN2
Door	2' 6" X 6' 8"	Opens into BATHROOM
Door	2' 8" X 6' 8"	Opens into BEDROOM
Window	4' 1" X 4'	Opens into Exterior
Window	4' 1" X 4'	Opens into Exterior
Missing Wall	3' 9" X 8'	Opens into ROOM2

**Subroom: Room3 (1)**

**Height: 8'**



49.33 SF Walls	4.33 SF Ceiling
53.67 SF Walls & Ceiling	4.33 SF Floor
0.48 SY Flooring	6.17 LF Floor Perimeter
6.17 LF Ceil. Perimeter	

Missing Wall	5' 8" X 8'	Opens into LIVING__DI2
Missing Wall	2' X 8'	Opens into KITCHEN2




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,741. Paint the walls - two coats	443.56 SF		0.00	1.36	9.81	120.64	733.69
3,742. Final cleaning - construction - Residential	298.50 SF		0.00	0.34	0.00	20.30	121.79
Totals: Living / Dining Room					9.81	140.94	855.48
Total: 8203					<b>22.59</b>	<b>317.78</b>	<b>1,929.29</b>

**8204**



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,743. 5/8" drywall - hung, taped, floated, ready for paint	15.00 SF		0.00	2.87	1.01	8.62	52.68
<i>Ceiling</i>							
3,744. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
3,745. Paint - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
3,746. Hanging light fixture	1.00 EA		0.00	81.74	3.27	16.34	101.35
3,747. Seal the ceiling w/latex based stain blocker - one coat	64.74 SF		0.00	0.91	0.46	11.78	71.15
3,748. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
3,749. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
3,750. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
3,751. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					16.81	155.80	951.70



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,752. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	75.00 SF		0.00	2.87	5.05	43.06	263.36
3,753. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	40.83 SF		0.00	1.12	3.08	9.14	57.95
3,754. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Walls</i>	158.83 SF		0.00	1.84	4.47	58.46	355.18
3,755. Baseboard - 3 1/4"	11.17 LF		0.00	3.49	1.63	7.80	48.41
3,756. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
3,757. Light fixture <i>Walls</i>	1.00 EA		0.00	69.13	3.32	13.82	86.27
3,758. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,759. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
3,760. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
3,761. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>18.46</b>	<b>154.72</b>	<b>946.71</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**


**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,762. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
<i>Ceiling</i>							
<i>Walls</i>							
3,763. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
3,764. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,765. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
3,766. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
3,767. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>13.90</b>	<b>205.24</b>	<b>1,245.48</b>
<b>Total: 8204</b>					<b>49.17</b>	<b>515.76</b>	<b>3,143.89</b>

**8210**



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM2**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,768. Paint - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
3,769. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
3,770. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
3,771. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
3,772. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
3,773. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>7.19</b>	<b>114.74</b>	<b>695.66</b>



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM2**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,774. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
3,775. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
3,776. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
3,777. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
3,778. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
3,779. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>3.96</b>	<b>66.68</b>	<b>403.98</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**  
**Window**  
**Missing Wall**

**5' 5" X 5'**  
**4' X 4'**  
**4' 1" X 9'**

**Opens into KITCHEN**  
**Opens into Exterior**  
**Opens into ENTRY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,780. Drywall patch / small repair, ready for paint <i>Wall</i>	1.00 EA		0.00	89.02	0.33	17.80	107.15
3,781. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
3,782. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
3,783. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,784. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,785. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
3,786. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>17.34</b>	<b>285.58</b>	<b>1,730.87</b>
<b>Total: 8210</b>					<b>28.49</b>	<b>467.00</b>	<b>2,830.51</b>

**8212**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	


<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,787. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Wall</i>							
3,788. Seal/prime then paint the walls twice (3 coats)	498.90 SF		0.00	1.84	14.04	183.60	1,115.62
3,789. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
3,790. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,791. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,792. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>15.98</b>	<b>287.38</b>	<b>1,740.23</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 8'**

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling **2' 3" X 4'** **Opens into KITCHEN**
- Door **3' X 6' 8"** **Opens into Exterior**
- Door **1' 11" X 6' 8"** **Opens into PANTRY**
- Door **1' 10" X 6' 8"** **Opens into CLOSET**
- Missing Wall **14' 2 1/16" X 8'** **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling **7' 6" X 4'** **Opens into KITCHEN**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,793. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	14.00 SF		0.00	2.87	0.94	8.04	49.16
3,794. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	14.00 SF		0.00	1.07	0.90	3.00	18.88
3,795. Paint - two coats <i>Walls</i>	367.67 SF		0.00	1.36	8.13	100.00	608.16
3,796. Casing - 3 1/4"	32.00 LF		0.00	3.19	6.82	20.42	129.32
3,797. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
3,798. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,799. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
3,800. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
<b>Totals: Kitchen</b>					<b>18.32</b>	<b>170.60</b>	<b>1,041.86</b>
<b>Total: 8212</b>					<b>34.30</b>	<b>457.98</b>	<b>2,782.09</b>

8213



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Utility Room

Height: 9'

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,801. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Wall</i>							
3,802. Seal/prime then paint the walls twice (3 coats)	145.50 SF		0.00	1.84	4.09	53.54	325.35
3,803. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
3,804. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,805. Mask the floor per square foot - plastic and tape - 4 mil	14.88 SF		0.00	0.35	0.07	1.04	6.32
3,806. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
Totals: Utility Room					4.95	112.54	680.21



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Missing Wall</b>	<b>4' 11" X 9'</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,807. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Ceiling</i>							
3,808. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
3,809. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,810. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
3,811. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72
3,812. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
3,813. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,814. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
3,815. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
<b>Totals: Bathroom</b>					<b>14.57</b>	<b>301.26</b>	<b>1,822.13</b>
<b>Total: 8213</b>					<b>19.52</b>	<b>413.80</b>	<b>2,502.34</b>

8222



### Living / Dining Room

Height: 9'

255.33 SF Walls	236.06 SF Ceiling
491.40 SF Walls & Ceiling	236.06 SF Floor
26.23 SY Flooring	30.42 LF Floor Perimeter
33.67 LF Ceil. Perimeter	

Missing Wall	2' 4" X 9'	Opens into STAIRCASE
Missing Wall	8' 10" X 9'	Opens into STAIRCASE
Missing Wall - Goes to Ceiling	3' 9" X 5'	Opens into STAIRCASE
Missing Wall	1' 1" X 9'	Opens into ROOM2
Missing Wall	16' 11" X 9'	Opens into ROOM2
Door	3' X 6' 8"	Opens into MASTER_BEDRO
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	3' 1" X 9'	Opens into STAIRCASE

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,816. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
3,817. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	20.00 SF		0.00	1.07	1.29	4.28	26.97



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,818. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
3,819. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	255.33 SF		0.00	1.84	7.18	93.96	570.95
3,820. Seal & paint baseboard - two coats	30.42 LF		0.00	2.24	0.34	13.62	82.10
3,821. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
3,822. Seal & paint base shoe or quarter round	30.42 LF		0.00	1.19	0.34	7.24	43.78
3,823. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,824. Final cleaning - construction - Residential	236.06 SF		0.00	0.34	0.00	16.06	96.32
<b>Totals: Living / Dining Room</b>					<b>13.37</b>	<b>174.72</b>	<b>1,061.72</b>
<b>Total: 8222</b>					<b>13.37</b>	<b>174.72</b>	<b>1,061.72</b>

8224

### Kitchen

Height: 8'



293.44 SF Walls	107.91 SF Ceiling
401.35 SF Walls & Ceiling	107.91 SF Floor
11.99 SY Flooring	40.17 LF Floor Perimeter
40.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling	2' 2" X 4'	Opens into LIVING__DIN
Missing Wall	8' 2" X 8'	Opens into LIVING__DIN
Door	3' X 6' 8"	Opens into Exterior
Door	1' 8" X 6' 8"	Opens into CLOSET
Door	4' X 6' 8"	Opens into UTILITY_ROOM
Missing Wall	2' X 8'	Opens into ROOM3
Door	2' 2" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	8' 5" X 4'	Opens into LIVING__DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,825. Seal & paint baseboard - two coats	40.17 LF		0.00	2.24	0.44	18.00	108.42
3,826. Seal & paint base shoe or quarter round	40.17 LF		0.00	1.19	0.44	9.56	57.80




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,827. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls and ceiling</i>	401.35 SF		0.00	1.84	11.29	147.70	897.47
3,828. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,829. Mask the floor per square foot - plastic and tape - 4 mil	107.91 SF		0.00	0.35	0.54	7.56	45.87
3,830. Final cleaning - construction - Residential	107.91 SF		0.00	0.34	0.00	7.34	44.03
<b>Totals: Kitchen</b>					<b>13.17</b>	<b>199.30</b>	<b>1,208.90</b>



**Living / Dining Room**


**Height: 8'**

394.22 SF Walls	294.17 SF Ceiling
688.39 SF Walls & Ceiling	294.17 SF Floor
32.69 SY Flooring	60.08 LF Floor Perimeter
50.08 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 4" X 8'</b>	<b>Opens into ROOM2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 9" X 4'</b>	<b>Opens into ROOM2</b>
<b>Missing Wall</b>	<b>8' 2" X 8'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>8' 11" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>3' 9" X 8'</b>	<b>Opens into ROOM2</b>

**Subroom: Room3 (1)**

**Height: 8'**



49.33 SF Walls	4.33 SF Ceiling
53.67 SF Walls & Ceiling	4.33 SF Floor
0.48 SY Flooring	6.17 LF Floor Perimeter
6.17 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>5' 8" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>2' X 8'</b>	<b>Opens into KITCHEN</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,831. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
<i>Walls</i>							
3,832. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
<i>Walls</i>							
3,833. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
3,834. Base shoe	6.00 LF		0.00	1.41	0.30	1.70	10.46
3,835. Seal & paint baseboard - two coats	66.25 LF		0.00	2.24	0.73	29.68	178.81
3,836. Seal & paint base shoe or quarter round	66.25 LF		0.00	1.19	0.73	15.76	95.33
3,837. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
3,838. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
3,839. Blown-in insulation - 10" depth - R26	298.50 SF		0.00	1.12	22.50	66.86	423.68
<i>Ceiling</i>							
3,840. Seal/prime then paint the walls and ceiling twice (3 coats)	742.06 SF		0.00	1.84	20.88	273.08	1,659.35
<i>Walls and ceiling</i>							
3,841. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
3,842. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,843. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,844. Mask the floor per square foot - plastic and tape - 4 mil	298.50 SF		0.00	0.35	1.50	20.90	126.88
3,845. Final cleaning - construction - Residential	298.50 SF		0.00	0.34	0.00	20.30	121.79
Totals: Living / Dining Room					56.17	519.10	3,170.89
Total: 8224					<b>69.34</b>	<b>718.40</b>	<b>4,379.79</b>

8225



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

Height: 9'


201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling
- Door
- Door
- Missing Wall

- 6' 4" X 5'
- 1' 8" X 6' 8"
- 3' X 6' 8"
- 4' 5" X 9'

- Opens into LIVING\_ROOM
- Opens into PANTRY
- Opens into UTILITY\_ROOM
- Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,846. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
3,847. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
3,848. Paint the walls and ceiling - two coats	267.13 SF		0.00	1.36	5.91	72.66	441.87
<i>Walls and ceiling</i>							
3,849. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,850. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
3,851. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					7.24	107.78	653.87



### Entry

Height: 9'

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

- Missing Wall
- Missing Wall
- Door
- Door
- Door
- Missing Wall

- 1' 5" X 9'
- 4' 5" X 9'
- 3' X 6' 8"
- 2' 8" X 6' 8"
- 2' 10" X 6' 8"
- 4' 6" X 9'

- Opens into LIVING\_ROOM
- Opens into KITCHEN
- Opens into Exterior
- Opens into BATHROOM
- Opens into BEDROOM
- Opens into LIVING\_ROOM




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,852. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
3,853. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
3,854. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
<i>Walls and ceiling</i>							
3,855. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,856. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
3,857. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					<b>5.35</b>	<b>78.78</b>	<b>478.01</b>
<b>Total: 8225</b>					<b>12.59</b>	<b>186.56</b>	<b>1,131.88</b>

8314



### Bedroom 1

Height: 8'

373.33 SF Walls	133.90 SF Ceiling
507.23 SF Walls & Ceiling	133.90 SF Floor
14.88 SY Flooring	45.50 LF Floor Perimeter
52.50 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into BEDROOM_1_WA</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,858. 5/8" drywall - hung, taped, floated, ready for paint	227.23 SF		0.00	2.87	15.30	130.44	797.89
3,859. Seal/prime then paint the walls and ceiling twice (3 coats)	507.23 SF		0.00	1.84	14.27	186.66	1,134.23
3,860. Batt insulation - 6" - R19 - unfaced batt	133.90 SF		0.00	1.07	8.61	28.66	180.54
3,861. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
3,862. Baseboard - 4 1/4"	11.38 LF		0.00	4.14	2.31	9.42	58.84
3,863. Seal & paint baseboard - two coats	45.50 LF		0.00	2.24	0.50	20.38	122.80



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom 1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,864. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,865. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,866. Mask the walls per square foot - plastic and tape - 4 mil	373.33 SF		0.00	0.35	1.88	26.14	158.69
3,867. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
<b>Totals: Bedroom 1</b>					<b>56.59</b>	<b>497.70</b>	<b>3,042.72</b>
<b>Total: 8314</b>					<b>56.59</b>	<b>497.70</b>	<b>3,042.72</b>

**8315**



**Bathroom**

**Height: 9'**

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

- Door** 2' 8" X 6' 8" Opens into ENTRY
- Door** 2' 8" X 6' 8" Opens into WALKIN\_CLOS
- Missing Wall** 4' 11" X 9' Opens into BEDROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,868. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16
<i>Ceiling</i>							
3,869. Blown-in insulation - 10" depth - R26	81.97 SF		0.00	1.12	6.18	18.36	116.35
<i>Ceiling</i>							
3,870. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
3,871. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72
3,872. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
3,873. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,874. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,875. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					20.71	227.86	1,387.85
Total: 8315					<b>20.71</b>	<b>227.86</b>	<b>1,387.85</b>

### 8316



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Missing Wall</b>	<b>4' 11" X 9'</b>	<b>Opens into BEDROOM</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,876. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
3,877. 5/8" drywall - hung, taped, floated, ready for paint	2.00 SF		0.00	2.87	0.13	1.14	7.01
3,878. Blown-in insulation - 10" depth - R26	81.97 SF		0.00	1.12	6.18	18.36	116.35
3,879. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
3,880. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72
3,881. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
3,882. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,883. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
3,884. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					20.23	238.76	1,452.85
Total: 8316					<b>20.23</b>	<b>238.76</b>	<b>1,452.85</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

8320



**Entry**

**Height: 9'**

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,885. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
3,886. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
3,887. Seal & paint base shoe or quarter round	6.17 LF		0.00	1.19	0.07	1.46	8.87
3,888. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,889. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
3,890. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95

Totals: Entry 2.51      38.34      232.71



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,891. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Ceiling</i>							
3,892. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
3,893. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
3,894. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
3,895. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
<i>Walls and ceiling</i>							
3,896. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
3,897. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,898. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,899. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
3,900. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>43.22</b>	<b>691.38</b>	<b>4,191.41</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 8320

45.73

729.72

4,424.12

8322



### Bathroom

Height: 9'

310.89 SF Walls  
390.74 SF Walls & Ceiling  
8.87 SY Flooring  
38.00 LF Ceil. Perimeter


79.85 SF Ceiling  
79.85 SF Floor  
33.33 LF Floor Perimeter

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>							
				1' 8" X 6' 8"			Opens into LINEN_CLOSET
<b>Door</b>							
				3' X 6' 8"			Opens into LIVING_ROOM2
3,901. 5/8" drywall - hung, taped, floated, ready for paint	64.00 SF		0.00	2.87	4.31	36.74	224.73
<i>Ceiling</i>							
3,902. Blown-in insulation - 10" depth - R26	79.85 SF		0.00	1.12	6.02	17.88	113.33
<i>Ceiling</i>							
3,903. Paint - two coats	390.74 SF		0.00	1.36	8.64	106.28	646.33
3,904. Batt insulation - 6" - R19 - unfaced batt	44.00 SF		0.00	1.07	2.83	9.42	59.33
<i>Walls</i>							
3,905. Seal & paint baseboard - two coats	33.33 LF		0.00	2.24	0.37	14.94	89.97
3,906. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,907. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
3,908. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
<b>Totals: Bathroom</b>					23.03	205.44	1,255.54



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Entry**

**Height: 9'**

62.50 SF Walls  
82.01 SF Walls & Ceiling  
2.17 SY Flooring  
9.17 LF Ceil. Perimeter

19.51 SF Ceiling  
19.51 SF Floor  
6.17 LF Floor Perimeter

**Missing Wall**

**4' 5" X 9'**

**Opens into LIVING\_ROOM2**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

**Missing Wall**

**4' 5" X 9'**


**Opens into LIVING\_ROOM2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,909. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
3,910. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65
3,911. Seal & paint base shoe or quarter round	6.17 LF		0.00	1.19	0.07	1.46	8.87
3,912. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,913. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
3,914. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
<b>Totals: Entry</b>					2.51	38.34	232.71



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM2</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,915. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
<i>Kitchen fur down</i>							
3,916. Seal/prime then paint the walls twice (3 coats)	823.56 SF		0.00	1.84	23.18	303.08	1,841.61
3,917. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
3,918. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
3,919. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,920. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>26.85</b>	<b>426.22</b>	<b>2,584.10</b>
<b>Total: 8322</b>					<b>52.39</b>	<b>670.00</b>	<b>4,072.35</b>

8401



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom 1

**Height: 8'**

373.33 SF Walls  
507.23 SF Walls & Ceiling  
14.88 SY Flooring  
52.50 LF Ceil. Perimeter

133.90 SF Ceiling  
133.90 SF Floor  
45.50 LF Floor Perimeter

**Door** 4' X 6' 8" Opens into BEDROOM\_1\_WA  
**Door** 3' X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,921. 5/8" drywall - hung, taped, floated, ready for paint	82.00 SF		0.00	2.87	5.52	47.06	287.92
3,922. Blown-in insulation - 12" depth - R30	32.00 SF		0.00	1.27	2.80	8.12	51.56
3,923. Batt insulation - 4" - R13 - paper / foil faced	16.00 SF		0.00	1.07	1.16	3.42	21.70
3,924. Seal/prime then paint the walls and ceiling twice (3 coats)	507.23 SF		0.00	1.84	14.27	186.66	1,134.23
3,925. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
3,926. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
3,927. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,928. Paint door slab only - 2 coats (per side)	6.00 EA		0.00	53.15	4.47	63.78	387.15
3,929. Mask the walls per square foot - plastic and tape - 4 mil	373.33 SF		0.00	0.35	1.88	26.14	158.69
3,930. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63

Totals: Bedroom 1 31.01 402.54 2,446.38

Total: 8401 31.01 402.54 2,446.38

**8402**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 8'**

353.33 SF Walls	162.86 SF Ceiling
516.19 SF Walls & Ceiling	162.86 SF Floor
18.10 SY Flooring	45.17 LF Floor Perimeter
51.17 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BATH</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,931. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Walls</i>							
3,932. Paint - two coats	353.33 SF		0.00	1.36	7.81	96.10	584.44
3,933. Seal & paint baseboard - two coats	45.17 LF		0.00	2.24	0.50	20.24	121.92
3,934. Seal & paint base shoe or quarter round	45.17 LF		0.00	1.19	0.50	10.76	65.01
3,935. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,936. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,937. Mask the floor per square foot - plastic and tape - 4 mil	162.86 SF		0.00	0.35	0.82	11.40	69.22
3,938. Final cleaning - construction - Residential	162.86 SF		0.00	0.34	0.00	11.08	66.45
<b>Totals: Master Bedroom</b>					<b>10.87</b>	<b>199.48</b>	<b>1,207.70</b>



### Master Bath

**Height: 8'**

308.67 SF Walls	84.51 SF Ceiling
393.18 SF Walls & Ceiling	84.51 SF Floor
9.39 SY Flooring	37.67 LF Floor Perimeter
43.17 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into MASTER_WALK</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,939. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Master Bath**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Walls</i>							
3,940. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
<i>Walls</i>							
3,941. Seal/prime then paint the walls twice (3 coats)	308.67 SF		0.00	1.84	8.69	113.60	690.24
3,942. Seal & paint baseboard - two coats	37.67 LF		0.00	2.24	0.42	16.88	101.68
3,943. Seal & paint base shoe or quarter round	37.67 LF		0.00	1.19	0.42	8.96	54.21
3,944. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,945. Mask the floor per square foot - plastic and tape - 4 mil	84.51 SF		0.00	0.35	0.43	5.92	35.93
3,946. Final cleaning - construction - Residential	84.51 SF		0.00	0.34	0.00	5.74	34.47
<b>Totals: Master Bath</b>					<b>11.73</b>	<b>168.12</b>	<b>1,020.43</b>



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,947. 5/8" drywall - hung, taped, floated, ready for paint	34.00 SF		0.00	2.87	2.29	19.52	119.39
<i>Walls</i>							




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,948. Batt insulation - 6" - R19 - unfaced batt	34.00 SF		0.00	1.07	2.19	7.28	45.85
<i>Walls</i>							
3,949. Seal/prime then paint the walls and ceiling twice (3 coats)	875.58 SF		0.00	1.84	24.64	322.22	1,957.93
<i>Walls</i>							
3,950. Baseboard - 3 1/4"	17.00 LF		0.00	3.49	2.48	11.86	73.67
3,951. Base shoe	17.00 LF		0.00	1.41	0.85	4.80	29.62
3,952. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
3,953. Seal & paint base shoe or quarter round	63.08 LF		0.00	1.19	0.70	15.02	90.79
3,954. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
3,955. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
<i>Ceiling</i>							
3,956. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,957. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,958. Mask the floor per square foot - plastic and tape - 4 mil	376.68 SF		0.00	0.35	1.89	26.36	160.09
3,959. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
Totals: Living / Dining Room					41.21	514.52	3,128.24



### Kitchen

Height: 8'

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

2' 3" X 4'

Opens into KITCHEN

Missing Wall

14' 2 1/16" X 8'

Opens into LIVING\_\_DIN

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

1' 11" X 6' 8"

Opens into PANTRY

Door

3' X 6' 8"

Opens into Exterior

Missing Wall - Goes to Ceiling

7' 6" X 4'

Opens into KITCHEN




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,960. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Ceiling</i>							
3,961. Seal/prime then paint the walls and ceiling twice (3 coats)	525.18 SF		0.00	1.84	14.78	193.26	1,174.37
<i>Paint and blend (ceiling)</i>							
3,962. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
3,963. Seal & paint baseboard - two coats	54.92 LF		0.00	2.24	0.61	24.60	148.23
3,964. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,965. Seal & paint base shoe or quarter round	54.92 LF		0.00	1.19	0.61	13.08	79.04
3,966. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
3,967. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
<b>Totals: Kitchen</b>					17.56	289.34	1,753.54



### Bedroom 1

**Height: 8'**

373.33 SF Walls	133.90 SF Ceiling
507.23 SF Walls & Ceiling	133.90 SF Floor
14.88 SY Flooring	45.50 LF Floor Perimeter
52.50 LF Ceil. Perimeter	

**Door** 4' X 6' 8" **Opens into BEDROOM\_1\_WA**  
**Door** 3' X 6' 8" **Opens into LIVING\_\_DIN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,968. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
<i>Walls</i>							
3,969. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
<i>Walls</i>							
3,970. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
3,971. Paint - two coats	373.33 SF		0.00	1.36	8.25	101.54	617.52
<i>Walls</i>							




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom 1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,972. Seal & paint baseboard - two coats	45.50 LF		0.00	2.24	0.50	20.38	122.80
3,973. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
3,974. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,975. Mask the floor per square foot - plastic and tape - 4 mil	133.90 SF		0.00	0.35	0.67	9.38	56.92
3,976. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
<b>Totals: Bedroom 1</b>					<b>14.43</b>	<b>195.24</b>	<b>1,185.92</b>
<b>Total: 8402</b>					<b>95.80</b>	<b>1,366.70</b>	<b>8,295.83</b>

**8405**



**Walk-in Closet**

**Height: 9'**

159.22 SF Walls	23.92 SF Ceiling
183.15 SF Walls & Ceiling	23.92 SF Floor
2.66 SY Flooring	17.00 LF Floor Perimeter
19.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,977. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
<i>Ceiling</i>							
3,978. Blown-in insulation - 10" depth - R26	23.92 SF		0.00	1.12	1.80	5.36	33.95
<i>Ceiling</i>							
3,979. Seal/prime then paint the walls and ceiling twice (3 coats)	183.15 SF		0.00	1.84	5.15	67.40	409.55
3,980. Shelving - wire (vinyl coated) - Detach & reset	2.00 LF		0.00	9.66	0.00	3.86	23.18
3,981. Seal & paint baseboard - two coats	17.00 LF		0.00	2.24	0.19	7.62	45.89
3,982. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,983. Mask the floor per square foot - plastic and tape - 4 mil	23.92 SF		0.00	0.35	0.12	1.68	10.17




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Walk-in Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,984. Final cleaning - construction - Residential	23.92 SF		0.00	0.34	0.00	1.62	9.75
Totals: Walk-in Closet					8.80	105.86	643.98



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	


<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,985. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
3,986. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	79.85 SF		0.00	1.12	6.02	17.88	113.33
3,987. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	390.74 SF		0.00	1.84	11.00	143.80	873.76
3,988. Seal & paint baseboard - two coats	33.33 LF		0.00	2.24	0.37	14.94	89.97
3,989. Seal & paint base shoe or quarter round	33.33 LF		0.00	1.19	0.37	7.94	47.97
3,990. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
3,991. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
3,992. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
Totals: Bathroom					19.43	211.62	1,289.01



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS1</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
3,993. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	409.00 SF		0.00	2.87	27.54	234.76	1,436.13
3,994. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	136.10 SF		0.00	1.12	10.26	30.48	193.17
3,995. Seal/prime then paint the walls and ceiling twice (3 coats)	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
3,996. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	108.00 SF		0.00	1.07	6.95	23.12	145.63
3,997. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
3,998. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
3,999. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,000. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,001. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
4,002. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53

Totals: Bedroom 60.93    578.68    3,533.08


Total: 8405 **89.16    896.16    5,466.07**

**8406**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

373.11 SF Walls	128.44 SF Ceiling
501.56 SF Walls & Ceiling	128.44 SF Floor
14.27 SY Flooring	42.50 LF Floor Perimeter
45.33 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 10" X 6' 8"**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,003. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	40.00 SF		0.00	2.87	2.69	22.96	140.45
4,004. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	128.44 SF		0.00	1.12	9.68	28.78	182.31
4,005. Seal/prime then paint the walls and ceiling twice (3 coats)	501.56 SF		0.00	1.84	14.11	184.58	1,121.56
4,006. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	108.00 SF		0.00	1.07	6.95	23.12	145.63
4,007. Seal & paint baseboard - two coats	42.50 LF		0.00	2.24	0.47	19.04	114.71
4,008. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,009. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,010. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,011. Mask the floor per square foot - plastic and tape - 4 mil	128.44 SF		0.00	0.35	0.65	9.00	54.60
4,012. Final cleaning - construction - Residential	128.44 SF		0.00	0.34	0.00	8.74	52.41
<b>Totals: Bedroom</b>					<b>35.46</b>	<b>364.54</b>	<b>2,222.51</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**6' 4" X 5'**

**Opens into LIVING\_ROOM**

**Door**

**1' 8" X 6' 8"**

**Opens into PANTRY**

**Door**

**3' X 6' 8"**

**Opens into UTILITY\_ROOM**


**Missing Wall**

**4' 5" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,013. Paint the walls and ceiling - two coats	267.13 SF		0.00	1.36	5.91	72.66	441.87
4,014. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
4,015. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
4,016. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,017. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
4,018. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59

Totals: Kitchen 7.24      107.78      653.87



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

**Missing Wall**

**1' 5" X 9'**

**Opens into ENTRY**

**Missing Wall - Goes to Ceiling**

**6' 10" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 6" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,019. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
4,020. Paint - two coats	640.44 SF		0.00	1.36	14.16	174.20	1,059.36
4,021. Batt insulation - 6" - R19 - unfaced batt	108.00 SF		0.00	1.07	6.95	23.12	145.63
<i>Walls</i>							
4,022. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
4,023. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,024. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,025. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,026. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
4,027. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					24.03	337.62	2,049.70
Total: 8406					<b>66.73</b>	<b>809.94</b>	<b>4,926.08</b>

### 8407



#### Entry

Height: 9'

62.50 SF Walls	19.51 SF Ceiling
82.01 SF Walls & Ceiling	19.51 SF Floor
2.17 SY Flooring	6.17 LF Floor Perimeter
9.17 LF Ceil. Perimeter	

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

Door

3' X 6' 8"

Opens into Exterior

Missing Wall

4' 5" X 9'

Opens into LIVING\_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,028. Paint the walls and ceiling - two coats	82.01 SF		0.00	1.36	1.81	22.30	135.64
4,029. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,030. Seal & paint baseboard - two coats	6.17 LF		0.00	2.24	0.07	2.76	16.65



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,031. Seal & paint base shoe or quarter round	6.17 LF		0.00	1.19	0.07	1.46	8.87
4,032. Mask the floor per square foot - plastic and tape - 4 mil	19.51 SF		0.00	0.35	0.10	1.36	8.29
4,033. Final cleaning - construction - Residential	19.51 SF		0.00	0.34	0.00	1.32	7.95
Totals: Entry					2.51	38.34	232.71



### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	

**Door** 2' 10" X 6' 8" **Opens into MASTER\_BATHR**  
**Window** 4' X 4' **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,034. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	114.00 SF		0.00	2.87	7.68	65.44	400.30
4,035. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	177.43 SF		0.00	1.12	13.37	39.74	251.83
4,036. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Walls</i>	624.04 SF		0.00	1.84	17.56	229.64	1,395.43
4,037. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	54.00 SF		0.00	1.07	3.47	11.56	72.81
4,038. Baseboard - 3 1/4"	12.00 LF		0.00	3.49	1.75	8.38	52.01
4,039. Seal & paint baseboard - two coats	50.67 LF		0.00	2.24	0.56	22.70	136.76
4,040. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,041. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,042. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,043. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
4,044. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
Totals: Master Bedroom					46.19	470.26	2,867.78



### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

### Window

4' X 4'

Opens into Exterior

### Door

3' X 6' 8"

Opens into LIVING\_ROOM

### Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,045. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	192.00 SF		0.00	2.87	12.93	110.20	674.17
4,046. Blown-in insulation - 10" depth - R26 <i>Ceiling</i> <i>Walls</i>	136.10 SF		0.00	1.12	10.26	30.48	193.17
4,047. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	40.00 SF		0.00	1.07	2.57	8.56	53.93
4,048. Baseboard - 3 1/4"	13.00 LF		0.00	3.49	1.89	9.08	56.34
4,049. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
4,050. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i> <i>Ceiling</i>	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
4,051. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,052. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,053. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,054. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
4,055. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					43.83	448.64	2,735.76



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,056. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	216.00 SF		0.00	2.87	14.54	123.98	758.44
4,057. Batt insulation - 8" - R25 - unfaced batt <i>Ceiling</i>	80.00 SF		0.00	1.43	6.51	22.88	143.79
4,058. Paint - two coats <i>Ceiling</i> <i>Walls</i>	1,310.03 SF		0.00	1.36	28.97	356.32	2,166.93



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,059. Batt insulation - 6" - R19 - unfaced batt	56.00 SF		0.00	1.07	3.60	11.98	75.50
<i>Walls</i>							
4,060. Crown molding - 3 1/4"	22.00 LF		0.00	4.40	3.67	19.36	119.83
4,061. Paint crown molding - two coats	123.33 LF		0.00	2.24	1.86	55.26	333.38
4,062. Baseboard - 3 1/4"	14.00 LF		0.00	3.49	2.04	9.78	60.68
4,063. Base shoe	14.00 LF		0.00	1.41	0.70	3.94	24.38
4,064. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
4,065. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
4,066. Casing - 3 1/4"	23.00 LF		0.00	3.19	4.90	14.68	92.95
4,067. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
<i>Walls</i>							
4,068. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
4,069. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,070. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
4,071. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>72.37</b>	<b>813.08</b>	<b>4,950.77</b>
<b>Total: 8407</b>					<b>164.90</b>	<b>1,770.32</b>	<b>10,787.02</b>

**8408**



### Bathroom

**Height: 9'**

256.03 SF Walls	62.14 SF Ceiling
318.17 SF Walls & Ceiling	62.14 SF Floor
6.90 SY Flooring	26.98 LF Floor Perimeter
32.64 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" **Opens into ENTRY**

**Door** 3' X 6' 8" **Opens into WALKIN\_CLOS**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,072. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
4,073. Seal/prime then paint the walls and ceiling twice (3 coats)	318.17 SF		0.00	1.84	8.95	117.08	711.46
4,074. Seal & paint baseboard - two coats	26.98 LF		0.00	2.24	0.30	12.08	72.82
4,075. Seal & paint base shoe or quarter round	26.98 LF		0.00	1.19	0.30	6.42	38.83
4,076. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,077. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
4,078. Mask the floor per square foot - plastic and tape - 4 mil	62.14 SF		0.00	0.35	0.31	4.36	26.42
4,079. Final cleaning - construction - Residential	62.14 SF		0.00	0.34	0.00	4.22	25.35
<b>Totals: Bathroom</b>					<b>11.37</b>	<b>208.74</b>	<b>1,263.89</b>



### Walk-in Closet

**Height: 9'**

179.77 SF Walls	31.46 SF Ceiling
211.23 SF Walls & Ceiling	31.46 SF Floor
3.50 SY Flooring	19.20 LF Floor Perimeter
22.20 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,080. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
<i>Walls</i>							
4,081. Seal/prime then paint the walls twice (3 coats)	179.77 SF		0.00	1.84	5.06	66.16	402.00
4,082. Shelving - wire (vinyl coated) - Detach & reset	11.33 LF		0.00	9.66	0.00	21.90	131.35
4,083. Seal & paint baseboard - two coats	19.20 LF		0.00	2.24	0.21	8.60	51.82
4,084. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,085. Mask the floor per square foot - plastic and tape - 4 mil	31.46 SF		0.00	0.35	0.16	2.20	13.37
4,086. Final cleaning - construction - Residential	31.46 SF		0.00	0.34	0.00	2.14	12.84




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Walk-in Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Walk-in Closet					6.29	113.58	687.75



### Bedroom

Height: 9'

373.11 SF Walls	128.44 SF Ceiling
501.56 SF Walls & Ceiling	128.44 SF Floor
14.27 SY Flooring	42.50 LF Floor Perimeter
45.33 LF Ceil. Perimeter	

### Window

4' X 4'

Opens into Exterior

### Door

2' 10" X 6' 8"


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,087. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	18.00 SF		0.00	2.87	1.21	10.34	63.21
4,088. Blown-in insulation - 10" depth - R26 Ceiling	128.44 SF		0.00	1.12	9.68	28.78	182.31
4,089. Seal/prime then paint the walls twice (3 coats)	373.11 SF		0.00	1.84	10.50	137.30	834.32
4,090. Paint the ceiling - two coats	128.44 SF		0.00	1.36	2.84	34.94	212.46
4,091. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,092. Seal & paint baseboard - two coats	42.50 LF		0.00	2.24	0.47	19.04	114.71
4,093. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,094. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,095. Mask the floor per square foot - plastic and tape - 4 mil	128.44 SF		0.00	0.35	0.65	9.00	54.60
4,096. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
Totals: Bedroom					26.26	307.78	1,872.85



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**6' 4" X 5'**

**Opens into LIVING\_ROOM**

**Door**

**1' 8" X 6' 8"**

**Opens into PANTRY**

**Door**

**3' X 6' 8"**


**Opens into UTILITY\_ROOM**

**Missing Wall**

**4' 5" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,097. Paint the walls and ceiling - two coats	267.13 SF		0.00	1.36	5.91	72.66	441.87
4,098. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
4,099. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,100. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
4,101. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
4,102. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>7.69</b>	<b>116.92</b>	<b>709.17</b>



### Entry

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

**Missing Wall**

**1' 5" X 9'**

**Opens into LIVING\_ROOM**

**Missing Wall**

**4' 5" X 9'**

**Opens into KITCHEN**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**2' 10" X 6' 8"**

**Opens into BEDROOM**

**Missing Wall**

**4' 6" X 9'**

**Opens into LIVING\_ROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,103. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
4,104. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
4,105. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,106. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
4,107. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
4,108. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					5.80	87.92	533.31



### Living Room

Height: 9'

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

Missing Wall	1' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to Ceiling	6' 10" X 5'	Opens into KITCHEN
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	4' 6" X 9'	Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,109. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	108.00 SF		0.00	2.87	7.27	62.00	379.23
4,110. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	215.36 SF		0.00	1.12	16.23	48.24	305.67
4,111. Seal/prime then paint the walls and ceiling twice (3 coats)	640.44 SF		0.00	1.84	18.02	235.68	1,432.11
4,112. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
4,113. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
4,114. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,115. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,116. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
4,117. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					44.11	468.42	2,854.57
Total: 8408					<b>101.52</b>	<b>1,303.36</b>	<b>7,921.54</b>

### 8409



### Utility Room

**Height: 8'**

156.67 SF Walls	29.17 SF Ceiling
185.83 SF Walls & Ceiling	29.17 SF Floor
3.24 SY Flooring	19.17 LF Floor Perimeter
21.67 LF Ceil. Perimeter	


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,118. Paint - two coats	29.17 SF		0.00	1.36	0.65	7.94	48.26
4,119. Mask the walls per square foot - plastic and tape - 4 mil	156.67 SF		0.00	0.35	0.79	10.96	66.58
4,120. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
Totals: Utility Room					1.44	18.96	115.24
Total: 8409					<b>1.44</b>	<b>18.96</b>	<b>115.24</b>

### 8410



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

**Missing Wall  
Window**

**4' 11" X 9'  
4' X 4'**

**Opens into BATHROOM  
Opens into Exterior**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,121. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	217.00 SF		0.00	2.87	14.61	124.56	761.96
4,122. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	121.71 SF		0.00	1.12	9.17	27.26	172.75
4,123. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	458.96 SF		0.00	1.84	12.92	168.90	1,026.31
4,124. Ceiling fan - Detach & reset <i>Walls</i>	1.00 EA		0.00	181.11	0.00	36.22	217.33
4,125. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	35.00 SF		0.00	1.07	2.25	7.50	47.20
4,126. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
4,127. Seal & paint baseboard - two coats <i>Walls</i>	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,128. Detach & Reset Window blind - PVC - 2" - 7.1 to 14 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,129. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,130. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
4,131. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
<b>Totals: Bedroom</b>					<b>42.50</b>	<b>438.60</b>	<b>2,674.05</b>
<b>Total: 8410</b>					<b>42.50</b>	<b>438.60</b>	<b>2,674.05</b>

**8413**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**


**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,132. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
<i>Walls</i>							
4,133. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
4,134. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,135. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
4,136. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,137. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					6.19	89.06	540.57



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,138. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
<i>Walls</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,139. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
<i>Walls</i>							
4,140. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
4,141. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,142. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
4,143. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,144. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					5.76	77.30	469.48



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'


Opens into ENTRY2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,145. Paint the walls - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79
<i>Walls</i>							
4,146. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
4,147. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,148. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,149. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					9.95	145.18	881.02



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

**Missing Wall  
Window**

**4' 11" X 9'  
4' X 4'**

**Opens into BATHROOM  
Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,150. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	153.00 SF		0.00	2.87	10.30	87.82	537.23
4,151. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	121.71 SF		0.00	1.12	9.17	27.26	172.75
4,152. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Walls</i>	458.96 SF		0.00	1.84	12.92	168.90	1,026.31
4,153. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	43.00 SF		0.00	1.07	2.77	9.20	57.98
4,154. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
4,155. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,156. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
<b>Totals: Bedroom</b>					<b>37.19</b>	<b>326.72</b>	<b>1,997.53</b>
<b>Total: 8413</b>					<b>59.09</b>	<b>638.26</b>	<b>3,888.60</b>

**8414**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 8'**

353.33 SF Walls	162.86 SF Ceiling
516.19 SF Walls & Ceiling	162.86 SF Floor
18.10 SY Flooring	45.17 LF Floor Perimeter
51.17 LF Ceil. Perimeter	


<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BATH</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,157. 5/8" drywall - hung, taped, floated, ready for paint	110.00 SF		0.00	2.87	7.41	63.14	386.25
<i>Ceiling</i>							
4,158. Blown-in insulation - 10" depth - R26	162.86 SF		0.00	1.12	12.28	36.48	231.16
<i>Ceiling</i>							
4,159. Seal/prime then paint the walls and ceiling twice (3 coats)	516.19 SF		0.00	1.84	14.53	189.96	1,154.28
<i>Ceiling</i>							
<i>Walls</i>							
4,160. Batt insulation - 6" - R19 - unfaced batt	15.00 SF		0.00	1.07	0.96	3.22	20.23
<i>Walls</i>							
4,161. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
4,162. Seal & paint baseboard - two coats	45.17 LF		0.00	2.24	0.50	20.24	121.92
4,163. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,164. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,165. Mask the floor per square foot - plastic and tape - 4 mil	162.86 SF		0.00	0.35	0.82	11.40	69.22
4,166. Final cleaning - construction - Residential	162.86 SF		0.00	0.34	0.00	11.08	66.45
<b>Totals: Master Bedroom</b>					<b>37.85</b>	<b>369.72</b>	<b>2,256.03</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	


<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,167. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
4,168. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	12.00 SF		0.00	1.07	0.77	2.56	16.17
4,169. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	498.90 SF		0.00	1.84	14.04	183.60	1,115.62
4,170. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
4,171. Base shoe	6.00 LF		0.00	1.41	0.30	1.70	10.46
4,172. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
4,173. Seal & paint base shoe or quarter round	63.08 LF		0.00	1.19	0.70	15.02	90.79
4,174. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
4,175. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
4,176. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
<b>Totals: Living / Dining Room</b>					<b>22.75</b>	<b>289.30</b>	<b>1,758.55</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Kitchen**

**Height: 8'**

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **2' 3" X 4'**      **Opens into KITCHEN**
- Door**      **3' X 6' 8"**      **Opens into Exterior**
- Door**      **1' 11" X 6' 8"**      **Opens into PANTRY**
- Door**      **1' 10" X 6' 8"**      **Opens into CLOSET**
- Missing Wall**      **14' 2 1/16" X 8'**      **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling**      **7' 6" X 4'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,177. Paint the walls - two coats	367.67 SF		0.00	1.36	8.13	100.00	608.16
<i>Walls</i>							
4,178. Seal & paint baseboard - two coats	54.92 LF		0.00	2.24	0.61	24.60	148.23
4,179. Seal & paint base shoe or quarter round	54.92 LF		0.00	1.19	0.61	13.08	79.04
4,180. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,181. Mask the floor per square foot - plastic and tape - 4 mil	154.15 SF		0.00	0.35	0.77	10.80	65.52
4,182. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
<b>Totals: Kitchen</b>					<b>10.58</b>	<b>168.10</b>	<b>1,019.15</b>



**Bedroom 1**

**Height: 8'**

373.33 SF Walls	133.90 SF Ceiling
507.23 SF Walls & Ceiling	133.90 SF Floor
14.88 SY Flooring	45.50 LF Floor Perimeter
52.50 LF Ceil. Perimeter	

- Door**      **4' X 6' 8"**      **Opens into BEDROOM\_1\_WA**
- Door**      **3' X 6' 8"**      **Opens into LIVING\_\_DIN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,183. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Walls</i>							
4,184. Batt insulation - 6" - R19 - unfaced batt	40.00 SF		0.00	1.07	2.57	8.56	53.93
<i>Walls</i>							
4,185. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
4,186. Seal & paint baseboard - two coats	45.50 LF		0.00	2.24	0.50	20.38	122.80
4,187. Paint - two coats	373.33 SF		0.00	1.36	8.25	101.54	617.52
<i>Walls</i>							
4,188. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
Totals: Bedroom 1					14.88	166.72	1,015.32
Total: 8414					<b>86.06</b>	<b>993.84</b>	<b>6,049.05</b>

**8415**



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

Missing Wall - Goes to Floor

**5' 7" X 9'**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,189. Seal/prime then paint the ceiling twice (3 coats)	64.74 SF		0.00	1.84	1.82	23.82	144.76
4,190. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,191. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					2.15	32.76	198.70



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,192. Seal/prime then paint the ceiling twice (3 coats)	40.83 SF		0.00	1.84	1.15	15.02	91.30
4,193. Mask the ceiling per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,194. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					1.36	20.66	125.32



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,195. Seal/prime then paint the ceiling twice (3 coats)	154.68 SF		0.00	1.84	4.35	56.92	345.88
4,196. Mask the ceiling per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,197. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					5.13	78.26	474.73



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 8415

8.64

131.68

798.75

### 8416



### Bedroom

Height: 9'

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

Missing Wall

4' 11" X 9'

Opens into BATHROOM

Window

4' X 4'

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,198. Paint - two coats	458.96 SF		0.00	1.36	10.15	124.84	759.18
<i>Ceiling</i>							
4,199. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,200. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,201. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,202. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,203. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
4,204. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
<b>Totals: Bedroom</b>					<b>12.10</b>	<b>227.54</b>	<b>1,377.34</b>
<b>Total: 8416</b>					<b>12.10</b>	<b>227.54</b>	<b>1,377.34</b>

### 8419



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bedroom

**Height: 8'**

316.11 SF Walls	138.06 SF Ceiling
454.17 SF Walls & Ceiling	138.06 SF Floor
15.34 SY Flooring	40.42 LF Floor Perimeter
47.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,205. Paint the walls and ceiling - two coats	454.17 SF		0.00	1.36	10.04	123.54	751.25
<i>Ceiling</i>							
<i>Walls</i>							
4,206. Seal & paint baseboard - two coats	40.42 LF		0.00	2.24	0.45	18.10	109.09
4,207. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,208. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,209. Mask the floor per square foot - plastic and tape - 4 mil	138.06 SF		0.00	0.35	0.69	9.66	58.67
4,210. Final cleaning - construction - Residential	138.06 SF		0.00	0.34	0.00	9.38	56.32
<b>Totals: Bedroom</b>					12.09	192.78	1,168.84



### Utility Room

**Height: 8'**

94.89 SF Walls	13.13 SF Ceiling
108.02 SF Walls & Ceiling	13.13 SF Floor
1.46 SY Flooring	11.17 LF Floor Perimeter
15.33 LF Ceil. Perimeter	

<b>Door</b>	<b>4' 2" X 6' 8"</b>	<b>Opens into KITCHEN</b>
-------------	----------------------	---------------------------

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,211. 5/8" drywall - hung, taped, floated, ready for paint	60.00 SF		0.00	2.87	4.04	34.44	210.68
<i>Ceiling</i>							
4,212. Blown-in insulation - 10" depth - R26	13.13 SF		0.00	1.12	0.99	2.94	18.64




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
4,213. Paint - two coats	13.13 SF		0.00	1.36	0.29	3.58	21.73
<i>Ceiling</i>							
4,214. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,215. Mask the floor per square foot - plastic and tape - 4 mil	13.13 SF		0.00	0.35	0.07	0.92	5.59
4,216. Final cleaning - construction - Residential	13.13 SF		0.00	0.34	0.00	0.90	5.36
Totals: Utility Room					5.39	52.96	323.03
Total: 8419					17.48	245.74	1,491.87

8420



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into BEDROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,217. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
4,218. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93




### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

#### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,219. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
4,220. Final cleaning - construction - Residential	1.00 SF		0.00	0.34	0.00	0.06	0.40
<b>Totals: Living Room</b>					<b>15.56</b>	<b>116.42</b>	<b>714.06</b>
<b>Total: 8420</b>					<b>15.56</b>	<b>116.42</b>	<b>714.06</b>

#### 8421



#### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**


**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,221. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
4,222. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>4.82</b>	<b>63.74</b>	<b>387.28</b>



#### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,223. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
4,224. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
4,225. Install Cold air return cover	1.00 EA		0.00	20.28	0.00	4.06	24.34
4,226. Seal/prime then paint the walls twice (3 coats)	118.00 SF		0.00	1.84	3.32	43.42	263.86
4,227. Baseboard - 4 1/4"	3.00 LF		0.00	4.14	0.61	2.48	15.51
4,228. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,229. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,230. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
4,231. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
4,232. Base shoe	3.00 LF		0.00	1.41	0.15	0.84	5.22
4,233. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>5.45</b>	<b>98.86</b>	<b>598.65</b>



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY2**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,234. Paint the walls - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79
4,235. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>8.22</b>	<b>111.62</b>	<b>677.90</b>
<b>Total: 8421</b>					<b>18.49</b>	<b>274.22</b>	<b>1,663.83</b>

**8423**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'


Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,236. Paint - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
4,237. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,238. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,239. Seal & paint base shoe or quarter round	2.00 LF		0.00	1.19	0.02	0.48	2.88
4,240. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,241. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					7.82	116.84	708.91



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,242. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
4,243. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,244. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,245. Seal & paint base shoe or quarter round	2.00 LF		0.00	1.19	0.02	0.48	2.88
4,246. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,247. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					4.77	72.60	440.37



### Bedroom

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

### Missing Wall

**4' 11" X 9'**

**Opens into BATHROOM**

### Window

**4' X 4'**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,248. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
<i>Wall</i>							
4,249. Paint - two coats	337.25 SF		0.00	1.36	7.46	91.74	557.86
4,250. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,251. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,252. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,253. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
4,254. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
Totals: Bedroom					9.74	176.02	1,065.84



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,255. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	110.00 SF		0.00	2.87	7.41	63.14	386.25
4,256. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
4,257. Paint - two coats <i>Ceiling</i> <i>Walls</i>	526.35 SF		0.00	1.36	11.64	143.16	870.64
4,258. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	25.00 SF		0.00	1.07	1.61	5.36	33.72
4,259. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,260. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,261. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,262. Seal & paint base shoe or quarter round	2.00 LF		0.00	1.19	0.02	0.48	2.88
4,263. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,264. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>34.54</b>	<b>320.86</b>	<b>1,959.76</b>
<b>Total: 8423</b>					<b>56.87</b>	<b>686.32</b>	<b>4,174.88</b>

8424



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

2' 6" X 5'

Opens into KITCHEN

Missing Wall

12' 7" X 9'

Opens into LIVING\_\_DIN

Missing Wall

2' 4" X 9'

Opens into HALLWAY

Door

1' 6" X 6' 8"

Opens into PANTRY

Missing Wall - Goes to Ceiling

7' 7" X 5'


Opens into KITCHEN

Missing Wall - Goes to Ceiling

2' 6" X 5'

Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,265. Paint the walls and ceiling - two coats	472.34 SF		0.00	1.36	10.44	128.48	781.30
4,266. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
4,267. Seal & paint base shoe or quarter round	53.92 LF		0.00	1.19	0.60	12.84	77.60
4,268. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,269. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
4,270. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					12.66	190.04	1,152.78



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

2' 8" X 6' 8"

Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,271. Drywall patch / small repair, ready for paint walls	2.00 EA		0.00	89.02	0.67	35.60	214.31




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,272. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	375.72 SF		0.00	1.84	10.57	138.26	840.15
4,273. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
4,274. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,275. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,276. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
4,277. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
4,278. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					13.27	273.00	1,651.32

<b>Entry</b>		<b>Height: 9'</b>	
	124.25 SF Walls	28.58 SF Ceiling	
	152.83 SF Walls & Ceiling	28.58 SF Floor	
	3.18 SY Flooring	12.25 LF Floor Perimeter	
	18.25 LF Ceil. Perimeter		
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>	
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>	
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into LIVING__DIN</b>	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,279. Drywall patch / small repair, ready for paint <i>Walls</i>	1.00 EA		0.00	89.02	0.33	17.80	107.15
4,280. Paint - two coats	124.25 SF		0.00	1.36	2.75	33.80	205.53
4,281. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
4,282. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
4,283. Seal & paint base shoe or quarter round	12.25 LF		0.00	1.19	0.14	2.92	17.64
4,284. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,285. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
4,286. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					3.96	103.08	622.49



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall	12' 7" X 9'	Opens into KITCHEN
Missing Wall	4' 1" X 9'	Opens into ENTRY
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	1' 1" X 9'	Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,287. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	632.00 SF		0.00	2.87	42.56	362.76	2,219.16
4,288. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	289.60 SF		0.00	1.12	21.83	64.88	411.06
4,289. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
4,290. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
4,291. Seal/prime then paint the ceiling twice (3 coats)	289.60 SF		0.00	1.84	8.15	106.58	647.59
4,292. Paint the walls - two coats	414.58 SF		0.00	1.36	9.17	112.76	685.76
4,293. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
4,294. Ceiling fan without light	1.00 EA		0.00	234.41	8.79	46.88	290.08
4,295. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,296. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,297. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,298. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
4,299. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					106.29	871.36	5,334.34
Total: 8424					<b>136.18</b>	<b>1,437.48</b>	<b>8,760.93</b>

**8426**



### Bedroom

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

Missing Wall

4' 11" X 9'

Opens into BATHROOM

Window

4' X 4'


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,300. Paint - two coats	458.96 SF		0.00	1.36	10.15	124.84	759.18
4,301. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,302. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,303. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,304. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,305. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
4,306. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
Totals: Bedroom					12.10	227.54	1,377.34



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,307. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	32.00 SF		0.00	2.87	2.15	18.36	112.35
4,308. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
4,309. Seal/prime then paint the ceiling twice (3 coats)	64.74 SF		0.00	1.84	1.82	23.82	144.76
4,310. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
4,311. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,312. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,313. Seal & paint base shoe or quarter round	2.00 LF		0.00	1.19	0.02	0.48	2.88
4,314. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,315. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					16.22	164.38	1,002.61



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Entry**

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

- Missing Wall - Goes to Floor**
- Missing Wall**
- Door**
- Door**
- Door**

- 5' 7" X 9'**
- 4' 1" X 9'**
- 1' 10" X 6' 8"**
- 2' 8" X 6' 8"**
- 3' X 6' 8"**

- Opens into KITCHEN**
- Opens into LIVING\_ROOM**
- Opens into CLOSET**
- Opens into BATHROOM**
- Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,316. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
4,317. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,318. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,319. Seal & paint base shoe or quarter round	2.00 LF		0.00	1.19	0.02	0.48	2.88
4,320. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,321. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66

Totals: Entry 4.32      63.46      385.07



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**
- Window**
- Missing Wall**

- 5' 5" X 5'**
- 4' X 4'**
- 4' 1" X 9'**

- Opens into KITCHEN**
- Opens into Exterior**
- Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,322. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,323. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,324. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,325. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,326. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,327. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					13.84	217.24	1,317.37
Total: 8426					<b>46.48</b>	<b>672.62</b>	<b>4,082.39</b>

8427



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,328. 5/8" drywall - hung, taped, floated, ready for paint	64.00 SF		0.00	2.87	4.31	36.74	224.73
4,329. Blown-in insulation - 12" depth - R30	32.00 SF		0.00	1.27	2.80	8.12	51.56
4,330. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
4,331. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
4,332. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
4,333. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
4,334. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
4,335. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					15.37	194.12	1,180.14



**Entry**

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,336. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
4,337. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
4,338. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
4,339. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
4,340. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66

Totals: Entry

4.47 95.52 577.47



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,341. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
4,342. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
4,343. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
4,344. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
4,345. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>14.81</b>	<b>238.50</b>	<b>1,445.73</b>
<b>Total: 8427</b>					<b>34.65</b>	<b>528.14</b>	<b>3,203.34</b>

**8430**



**Bedroom**

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

**Missing Wall**

**4' 11" X 9'**

**Opens into BATHROOM**

**Window**

**4' X 4'**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,346. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	8.00 SF		0.00	2.87	0.54	4.60	28.10
4,347. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	8.00 SF		0.00	1.07	0.51	1.72	10.79
4,348. Seal/prime then paint the walls and ceiling twice (3 coats)	458.96 SF		0.00	1.84	12.92	168.90	1,026.31
4,349. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,350. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,351. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,352. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,353. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
Totals: Bedroom					15.92	241.70	1,466.03



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'


Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,354. Paint more than the ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
<i>Ceiling</i>							
4,355. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,356. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
4,357. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,358. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,359. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					7.65	113.70	689.94



**Closet**

**Height: 9'**

76.28 SF Walls	6.03 SF Ceiling
82.31 SF Walls & Ceiling	6.03 SF Floor
0.67 SY Flooring	8.00 LF Floor Perimeter
9.83 LF Ceil. Perimeter	

Door

1' 10" X 6' 8"

Opens into ENTRY




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,360. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	46.00 SF		0.00	2.87	3.10	26.40	161.52
4,361. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	6.03 SF		0.00	1.12	0.45	1.36	8.56
4,362. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Walls</i>	82.31 SF		0.00	1.84	2.32	30.30	184.07
4,363. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	40.00 SF		0.00	1.07	2.57	8.56	53.93
4,364. Baseboard - 3 1/4"	5.00 LF		0.00	3.49	0.73	3.50	21.68
4,365. Seal & paint baseboard - two coats <i>Walls</i>	8.00 LF		0.00	2.24	0.09	3.58	21.59
4,366. Shelving - wire (vinyl coated)	5.17 LF		0.00	10.99	1.99	11.36	70.17
4,367. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,368. Mask the floor per square foot - plastic and tape - 4 mil	6.03 SF		0.00	0.35	0.03	0.42	2.56
4,369. Final cleaning - construction - Residential	6.03 SF		0.00	0.34	0.00	0.42	2.47
<b>Totals: Closet</b>					11.74	95.04	581.86



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,370. Paint more than the ceiling - two coats <i>Ceiling</i>	158.83 SF		0.00	1.36	3.51	43.20	262.72
4,371. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,372. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
4,373. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,374. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,375. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					4.42	65.64	398.26



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Missing Wall</b>	<b>4' 11" X 9'</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,376. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	6.00 SF		0.00	2.87	0.40	3.44	21.06
4,377. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	6.00 SF		0.00	1.07	0.39	1.28	8.09
4,378. Seal/prime then paint the walls twice (3 coats) <i>Walls</i>	341.69 SF		0.00	1.84	9.61	125.74	764.06
4,379. Drywall Installer / Finisher - per hour	1.50 HR		0.00	100.00	0.00	30.00	180.00
4,380. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
4,381. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,382. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
4,383. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,384. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
4,385. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					12.72	258.00	1,560.80



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,386. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	170.00 SF		0.00	2.87	11.45	97.58	596.93
4,387. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
4,388. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
4,389. Ceiling fan - Detach & reset <i>Walls</i>	1.00 EA		0.00	181.11	0.00	36.22	217.33
4,390. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i> walls	16.00 SF		0.00	1.07	1.03	3.42	21.57
4,391. Baseboard - 3 1/4"	11.00 LF		0.00	3.49	1.60	7.68	47.67
4,392. Base shoe	11.00 LF		0.00	1.41	0.55	3.10	19.16



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,393. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,394. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
4,395. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,396. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,397. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,398. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					43.81	461.38	2,812.23
Total: 8430					<b>96.26</b>	<b>1,235.46</b>	<b>7,509.12</b>
Total: Building 8 Interiors					<b>2,037.84</b>	<b>24,841.22</b>	<b>151,084.79</b>

### Corridors/Breezways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,399. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	107,640. SF 00		0.00	2.87	7,247.94	61,785.36	377,960.10
4,400. Exterior - paint two coats <i>Estimated allowance</i>	53,820. SF 00		0.00	1.58	1,730.85	17,007.12	103,773.57
4,401. Electrician - per hour <i>Labor to detach and reset misc to prep for paint.</i>	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
4,402. Painter - per hour <i>Misc labor to prep for paint.</i>	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
4,403. Carpenter - General Frammer - per hour <i>Labor to install drywall nailers.</i>	60.00 HR		0.00	72.00	0.00	864.00	5,184.00
Totals: Corridors/Breezways					8,978.79	80,922.92	494,516.35

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,404. Clean with pressure/chemical spray	21,760. SF 00		0.00	0.43	21.87	1,871.36	11,250.03
4,405. Exterior - paint two coats	21,760. SF 00		0.00	1.58	699.80	6,876.16	41,956.76
4,406. Electrician - per hour	100.00 HR		0.00	95.03	0.00	1,900.60	11,403.60
<i>Labor to detach and reset misc to prep for paint. Includes time to service light post.</i>							
4,407. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
4,408. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
4,409. R&R Window screen, 1 - 9 SF	43.00 EA		4.74	36.30	135.48	352.94	2,253.14
4,410. R&R Gutter / downspout - aluminum - 7" to 8"	415.00 LF		0.63	17.54	547.20	1,508.12	9,595.87
<b>415 LF Gutters</b>							
4,411. R&R Light fixture - wall sconce - High grade	2.00 EA		10.49	155.78	24.12	66.52	423.18
4,412. R&R Overhead door & hardware - 9' x 7'	3.00 EA		82.04	934.67	196.67	610.02	3,856.82
4,413. R&R Clothes dryer vent cover	1.00 EA		4.72	41.86	0.69	9.32	56.59
4,414. Clean with pressure/chemical spray	336.00 SF		0.00	0.43	0.34	28.90	173.72
<b>Six (6) double doors.</b>							
4,415. R&R Soffit - vinyl	70.00 SF		0.38	5.81	15.27	86.66	535.23
4,416. R&R Bifold door set - full louvered - Double	4.00 EA		18.86	468.16	142.32	389.60	2,480.00
4,417. Paint full louvered door slab only - 2 coats (per side)	8.00 EA		0.00	74.43	6.03	119.08	720.55
Totals: Exteriors					1,934.01	16,206.64	99,173.87

### Garage/Storage

#### B08G05

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,418. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
4,419. Paint the surface area - two coats	860.00 SF		0.00	1.36	19.01	233.92	1,422.53
4,420. Detach & Reset Fluorescent - four tube - 4' - strip light	1.00 EA	73.82	0.00	0.00	0.00	14.76	88.58



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - B08G05

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: B08G05					19.68	254.42	1,546.22
Total: Garage/Storage					<b>19.68</b>	<b>254.42</b>	<b>1,546.22</b>

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,462. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR					AS INCURRED	
4,463. Telehandler/forklift and operator	160.00 HR					AS INCURRED	
4,464. Scaffolding	43,400. EA 00		0.00	0.50	872.34	4,340.00	26,912.34
4,465. Commercial Supervision / Project Management - per hour	536.00 HR		0.00	68.91	0.00	7,387.16	44,322.92
4,466. General Laborer - per hour	360.00 HR		0.00	37.61	0.00	2,707.92	16,247.52
4,467. Temporary toilet (per month)	12.00 MO					AS INCURRED	
4,468. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
4,469. Hand wash station	6.00 MO					AS INCURRED	
4,470. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
4,471. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
4,472. OSHA compliance safety monitor- per hour	HR					AS INCURRED	
4,473. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
4,474. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
4,475. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
4,476. Light bulb - Incand. standard bulb - 1000 hr - mat. only	18.00 EA		0.00	0.79	1.43	2.84	18.49
Totals: GENERAL CONDITIONS					933.77	14,671.66	88,963.71
Total: SAULET-BLDG-08-V5_23					<b>13,904.09</b>	<b>136,896.86</b>	<b>835,284.94</b>

### SAULET-BLDG-09-V5\_23


#### Building 9 Interiors

9101



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

135.78 SF Walls	40.83 SF Ceiling
176.61 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	13.83 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN2**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**3' X 6' 8"**


**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,477. 5/8" drywall - hung, taped, floated, ready for paint	108.72 SF		0.00	2.87	7.32	62.40	381.75
4,478. Batt insulation - 6" - R19 - unfaced batt	135.78 SF		0.00	1.07	8.73	29.06	183.07
4,479. Seal/prime then paint the walls twice (3 coats)	135.78 SF		0.00	1.84	3.82	49.96	303.62
4,480. Seal/prime then paint the walls and ceiling twice (3 coats)	176.61 SF		0.00	1.84	4.97	65.00	394.93
4,481. Seal & paint baseboard - two coats	13.83 LF		0.00	2.24	0.15	6.20	37.33
4,482. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,483. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
4,484. Light bulb - Incand. standard bulb - 1000 hr - mat. only	1.00 EA		0.00	0.79	0.08	0.16	1.03
4,485. Smoke detector	1.00 EA		0.00	60.60	2.82	12.12	75.54
4,486. Baseboard - 3 1/4"	13.83 LF		0.00	3.49	2.02	9.66	59.95
4,487. Casing - 2 1/4"	34.00 LF		0.00	2.23	3.96	15.16	94.94
4,488. Paint baseboard - two coats	13.83 LF		0.00	2.16	0.18	5.98	36.03
4,489. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,490. Clean concrete the floor	40.83 SF		0.00	0.39	0.04	3.18	19.14
4,491. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>38.53</b>	<b>296.62</b>	<b>1,818.23</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Closet

**Height: 9'**

76.28 SF Walls	6.03 SF Ceiling
82.31 SF Walls & Ceiling	6.03 SF Floor
0.67 SY Flooring	8.00 LF Floor Perimeter
9.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	1' 10" X 6' 8"			O&P	TOTAL
				REPLACE	TAX	Opens into ENTRY		
4,492. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18	
4,493. Baseboard - 3 1/4"	8.00 LF		0.00	3.49	1.17	5.58	34.67	
4,494. R&R Casing - 2 1/4"	17.00 LF		0.64	2.23	1.98	9.76	60.53	
4,495. Seal/prime then paint the walls and ceiling twice (3 coats)	82.31 SF		0.00	1.84	2.32	30.30	184.07	
4,496. Paint baseboard - two coats	8.00 LF		0.00	2.16	0.10	3.46	20.84	
4,497. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
4,498. Clean concrete the floor	6.03 SF		0.00	0.39	0.01	0.48	2.84	
4,499. Shelving - wire (vinyl coated)	7.75 LF		0.00	10.99	2.99	17.04	105.20	
Totals: Closet					10.11	84.94	519.64	



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	5' 5" X 5'			O&P	TOTAL
				REPLACE	TAX	Opens into LIVING_ROOM		
4,500. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93	
4,501. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14	
4,502. 5/8" drywall - hung, taped, floated, ready for paint	88.04 SF		0.00	2.87	5.93	50.54	309.14	
4,503. Batt insulation - 6" - R19 - unfaced batt	21.00 SF		0.00	1.07	1.35	4.50	28.32	
4,504. Baseboard - 3 1/4"	27.25 LF		0.00	3.49	3.97	19.02	118.09	



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,505. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,506. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
4,507. Clean floor	64.74 SF		0.00	0.54	0.07	7.00	42.03
4,508. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,509. Cabinetry - lower (base) units	9.34 LF		0.00	219.33	167.30	409.70	2,625.54
4,510. Install Countertop - post formed plastic laminate	9.34 LF		0.00	15.67	0.00	29.28	175.64
4,511. Cabinet refacing	35.84 SF		0.00	28.62	61.95	205.14	1,292.83
4,512. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
4,513. Install Sink - double	1.00 EA		0.00	124.58	0.00	24.92	149.50
4,514. Install Garbage disposer	1.00 EA		0.00	119.85	0.00	23.98	143.83
4,515. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
4,516. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
4,517. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
4,518. Light bulb - Incand. standard bulb - 1000 hr - mat. only	3.00 EA		0.00	0.79	0.24	0.48	3.09
4,519. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
4,520. Clean concrete the floor	64.74 SF		0.00	0.39	0.07	5.06	30.38
4,521. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
<b>Totals: Kitchen</b>					<b>260.01</b>	<b>1,064.52</b>	<b>6,647.03</b>



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN2

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,522. 5/8" drywall - hung, taped, floated, ready for paint	78.08 SF		0.00	2.87	5.26	44.82	274.17
4,523. Batt insulation - 6" - R19 - unfaced batt	60.00 SF		0.00	1.07	3.86	12.84	80.90
4,524. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
4,525. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,526. Baseboard - 3 1/4"	46.08 LF		0.00	3.49	6.72	32.16	199.70
4,527. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,528. Crown molding - 3 1/4"	20.33 LF		0.00	4.40	3.39	17.90	110.74
4,529. Paint crown molding - two coats	40.67 LF		0.00	2.24	0.61	18.22	109.93
4,530. Trim board - 1" x 2" - installed (pine)	46.08 LF		0.00	2.96	5.23	27.28	168.91
4,531. Seal & paint trim - two coats	40.67 LF		0.00	2.15	0.49	17.48	105.41
4,532. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
4,533. Casing - 2 1/4"	17.00 LF		0.00	2.23	1.98	7.58	47.47
4,534. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,535. Clean concrete the floor	154.68 SF		0.00	0.39	0.16	12.06	72.55
4,536. Detach & Reset Smoke detector	1.00 EA	49.24	0.00	0.00	0.00	9.84	59.08
<b>Totals: Living Room</b>					<b>43.93</b>	<b>472.50</b>	<b>2,879.08</b>



### Bedroom

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>					
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,537. 5/8" drywall - hung, taped, floated, ready for paint	49.33 SF		0.00	2.87	3.32	28.32	173.22
4,538. Baseboard - 3 1/4"	20.67 LF		0.00	3.49	3.01	14.42	89.57




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,539. Casing - 2 1/4"	34.00 LF		0.00	2.23	3.96	15.16	94.94
4,540. Seal/prime then paint the walls twice (3 coats)	362.22 SF		0.00	1.84	10.19	133.30	809.97
4,541. Detach & Reset Window blind - PVC - 1" - 7.1 to 14 SF	1.00 EA	34.54	0.00	0.00	0.00	6.90	41.44
4,542. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,543. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
4,544. Paint baseboard - two coats	41.33 LF		0.00	2.16	0.54	17.86	107.67
4,545. Clean concrete the floor	120.89 SF		0.00	0.39	0.12	9.44	56.71
4,546. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
Totals: Bedroom					22.05	255.38	1,554.37



### Walk-in Closet

Height: 9'


181.72 SF Walls	22.92 SF Ceiling
204.64 SF Walls & Ceiling	22.92 SF Floor
2.55 SY Flooring	19.50 LF Floor Perimeter
22.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,547. Casing - 2 1/4"	17.00 LF		0.00	2.23	1.98	7.58	47.47
4,548. 5/8" drywall - hung, taped, floated, ready for paint	39.00 SF		0.00	2.87	2.63	22.38	136.94
4,549. Seal/prime then paint the walls twice (3 coats)	181.72 SF		0.00	1.84	5.11	66.88	406.35
4,550. Detach & Reset Shelving - wire (vinyl coated)	16.25 LF	9.66	0.00	0.00	0.00	31.40	188.38
4,551. Baseboard - 3 1/4"	19.50 LF		0.00	3.49	2.84	13.62	84.52
4,552. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,553. Paint baseboard - two coats	19.50 LF		0.00	2.16	0.26	8.42	50.80
4,554. Clean concrete the floor	22.92 SF		0.00	0.39	0.02	1.78	10.74
4,555. Final cleaning - construction - Residential	22.92 SF		0.00	0.34	0.00	1.56	9.35
Totals: Walk-in Closet					13.30	162.76	989.86



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bathroom**

**Height: 9'**

355.33 SF Walls	81.15 SF Ceiling
436.49 SF Walls & Ceiling	81.15 SF Floor
9.02 SY Flooring	37.08 LF Floor Perimeter
46.33 LF Ceil. Perimeter	


<b>Door</b>	<b>3' 11" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,556. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
4,557. Batt insulation - 6" - R19 - unfaced batt	37.50 SF		0.00	1.07	2.41	8.02	50.56
4,558. 5/8" drywall - hung, taped, floated, ready for paint	111.25 SF		0.00	2.87	7.49	63.86	390.64
4,559. Vanity	5.00 LF		0.00	211.87	85.81	211.88	1,357.04
4,560. Install Vanity top - one sink - cultured marble	LF		0.00	24.86	0.00	0.00	0.00
4,561. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
4,562. Baseboard - 3 1/4"	18.54 LF		0.00	3.49	2.70	12.94	80.34
4,563. Casing - 2 1/4"	51.00 LF		0.00	2.23	5.95	22.74	142.42
4,564. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,565. Seal/prime then paint the walls twice (3 coats)	355.33 SF		0.00	1.84	10.00	130.76	794.57
4,566. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
4,567. Paint baseboard - two coats	37.08 LF		0.00	2.16	0.48	16.02	96.59
4,568. Toilet paper holder - Standard grade	1.00 EA		0.00	19.23	0.58	3.84	23.65
4,569. Clean concrete the floor	81.15 SF		0.00	0.39	0.08	6.34	38.07
4,570. Final cleaning - construction - Residential	81.15 SF		0.00	0.34	0.00	5.52	33.11
<b>Totals: Bathroom</b>					<b>117.52</b>	<b>588.20</b>	<b>3,646.68</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Utility Room

**Height: 9'**

119.39 SF Walls	14.88 SF Ceiling
134.26 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	12.25 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,571. Detach & Reset Washer/Washing Machine - Front-loading	1.00 EA	46.97	0.00	0.00	0.00	9.40	56.37
4,572. Dryer - Electric - Reset	1.00 EA		0.00	18.11	0.00	3.62	21.73
4,573. 5/8" drywall - hung, taped, floated, ready for paint	36.75 SF		0.00	2.87	2.47	21.10	129.04
4,574. Batt insulation - 6" - R19 - unfaced batt	15.75 SF		0.00	1.07	1.01	3.38	21.24
4,575. Baseboard - 3 1/4"	12.25 LF		0.00	3.49	1.78	8.56	53.09
4,576. Detach & Reset Bifold door set - Colonist - Double	1.00 EA	32.23	0.00	0.00	0.00	6.44	38.67
4,577. Seal/prime then paint the walls twice (3 coats)	119.39 SF		0.00	1.84	3.36	43.94	266.98
4,578. Paint baseboard - two coats	12.25 LF		0.00	2.16	0.16	5.30	31.92
4,579. Clean concrete the floor	14.88 SF		0.00	0.39	0.02	1.16	6.98
4,580. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
<b>Totals: Utility Room</b>					<b>8.80</b>	<b>103.92</b>	<b>632.10</b>
<b>Total: 9101</b>					<b>514.25</b>	<b>3,028.84</b>	<b>18,686.99</b>

9102



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 8'**

296.67 SF Walls	133.13 SF Ceiling
429.79 SF Walls & Ceiling	133.13 SF Floor
14.79 SY Flooring	37.67 LF Floor Perimeter
46.17 LF Ceil. Perimeter	

#### Window

4' X 4'

Opens into Exterior

#### Door

3' X 6' 8"

Opens into LIVING\_ROOM2

#### Door

2' 6" X 6' 8"

Opens into MASTER\_WALK

#### Door

3' X 6' 8"


Opens into MASTER\_BATHR

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,581. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
4,582. Batt insulation - 4" - R11-unfaced batt	20.00 SF		0.00	0.70	0.74	2.80	17.54
4,583. Baseboard - 4 1/4"	10.00 LF		0.00	4.14	2.03	8.28	51.71
4,584. Seal & paint baseboard - two coats	37.67 LF		0.00	2.24	0.42	16.88	101.68
4,585. Casing - 2 1/4"	16.00 LF		0.00	2.23	1.87	7.14	44.69
4,586. Seal/prime then paint the walls twice (3 coats)	296.67 SF		0.00	1.84	8.35	109.18	663.40
4,587. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,588. Final cleaning - construction - Commercial	133.13 SF		0.00	0.27	0.00	7.20	43.15
<b>Totals: Master Bedroom</b>					<b>15.22</b>	<b>172.10</b>	<b>1,047.71</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen / Dining

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__D2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__D2</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,589. Seal/prime then paint the walls twice (3 coats)	413.33 SF		0.00	1.84	11.63	152.10	924.26
4,590. Final cleaning - construction - Commercial	214.90 SF		0.00	0.27	0.00	11.60	69.62
<b>Totals: Kitchen / Dining</b>					<b>11.63</b>	<b>163.70</b>	<b>993.88</b>



### Living Room

**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDR2</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__D2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,591. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
4,592. Batt insulation - 4" - R11-unfaced batt	10.00 SF		0.00	0.70	0.37	1.40	8.77



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,593. Baseboard - 4 1/4"	5.00 LF		0.00	4.14	1.02	4.14	25.86
4,594. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
4,595. Casing - 2 1/4"	16.00 LF		0.00	2.23	1.87	7.14	44.69
4,596. Seal/prime then paint the walls twice (3 coats)	232.67 SF		0.00	1.84	6.55	85.62	520.28
4,597. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,598. Final cleaning - construction - Commercial	141.03 SF		0.00	0.27	0.00	7.62	45.70
<b>Totals: Living Room</b>					<b>11.27</b>	<b>134.02</b>	<b>815.35</b>
<b>Total: 9102</b>					<b>38.12</b>	<b>469.82</b>	<b>2,856.94</b>

### 9103



### Bathroom

Height: 9'

256.03 SF Walls	62.14 SF Ceiling
318.17 SF Walls & Ceiling	62.14 SF Floor
6.90 SY Flooring	26.98 LF Floor Perimeter
32.64 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8"

**Opens into ENTRY**

**Door** 3' X 6' 8"

**Opens into WALKIN\_CLOS**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,599. 5/8" drywall - hung, taped, floated, ready for paint	13.00 SF		0.00	2.87	0.88	7.46	45.65
4,600. Mirror - 1/4" plate glass	15.00 SF		0.00	16.85	17.79	50.56	321.10
4,601. Toilet	1.00 EA		0.00	488.88	26.78	97.78	613.44
4,602. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
4,603. Seal/prime then paint the walls twice (3 coats)	256.03 SF		0.00	1.84	7.20	94.22	572.52
4,604. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
4,605. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,606. Mask the walls per square foot - plastic and tape - 4 mil	256.03 SF		0.00	0.35	1.29	17.92	108.82
4,607. Final cleaning - construction - Residential	62.14 SF		0.00	0.34	0.00	4.22	25.35




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Bathroom					57.84	307.14	1,900.61



### Walk-in Closet

Height: 9'


179.77 SF Walls	31.46 SF Ceiling
211.23 SF Walls & Ceiling	31.46 SF Floor
3.50 SY Flooring	19.20 LF Floor Perimeter
22.20 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,608. 5/8" drywall - hung, taped, floated, ready for paint	38.39 SF		0.00	2.87	2.58	22.04	134.80
4,609. Interior door - Colonist - pre-hung unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
4,610. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
4,611. Paint the ceiling - two coats	31.46 SF		0.00	1.36	0.70	8.56	52.05
4,612. Seal/prime then paint the walls twice (3 coats)	179.77 SF		0.00	1.84	5.06	66.16	402.00
4,613. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
4,614. Baseboard - 4 1/4"	19.20 LF		0.00	4.14	3.90	15.90	99.29
4,615. Shelving - wire (vinyl coated) - Detach & reset	19.34 LF		0.00	9.66	0.00	37.36	224.18
4,616. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
4,617. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
4,618. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,619. Final cleaning - construction - Residential	31.46 SF		0.00	0.34	0.00	2.14	12.84
Totals: Walk-in Closet					36.54	247.76	1,522.98



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**
- Door**
- Door**
- Missing Wall**

- 6' 4" X 5'**
- 1' 8" X 6' 8"**
- 3' X 6' 8"**
- 4' 5" X 9'**


- Opens into LIVING\_ROOM**
- Opens into PANTRY**
- Opens into UTILITY\_ROOM**
- Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,620. 5/8" drywall - hung, taped, floated, ready for paint	26.00 SF		0.00	2.87	1.75	14.92	91.29
4,621. Batt insulation - 4" - R11-unfaced batt	26.00 SF		0.00	0.70	0.97	3.64	22.81
4,622. Detach & Reset Cabinetry - lower (base) units	4.00 LF	69.68	0.00	0.00	0.00	55.74	334.46
4,623. Detach & Reset Cabinetry - upper (wall) units	2.00 LF	59.59	0.00	0.00	0.00	23.84	143.02
4,624. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,625. Baseboard - 4 1/4"	7.00 LF		0.00	4.14	1.42	5.80	36.20
4,626. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
4,627. Seal/prime then paint the walls and ceiling twice (3 coats)	267.13 SF		0.00	1.84	7.52	98.30	597.34
4,628. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
4,629. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
4,630. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>12.53</b>	<b>238.40</b>	<b>1,442.84</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

**Missing Wall**

**1' 5" X 9'**

**Opens into ENTRY**

**Missing Wall - Goes to Ceiling**

**6' 10" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**


**Opens into Exterior**

**Missing Wall**

**4' 6" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,631. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
4,632. Baseboard - 4 1/4"	12.00 LF		0.00	4.14	2.44	9.94	62.06
4,633. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,634. Seal/prime then paint the walls and ceiling twice (3 coats)	640.44 SF		0.00	1.84	18.02	235.68	1,432.11
4,635. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,636. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,637. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
4,638. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
4,639. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>23.72</b>	<b>373.86</b>	<b>2,266.84</b>



### Bedroom

**Height: 9'**

373.11 SF Walls	128.44 SF Ceiling
501.56 SF Walls & Ceiling	128.44 SF Floor
14.27 SY Flooring	42.50 LF Floor Perimeter
45.33 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 10" X 6' 8"**

**Opens into ENTRY**




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,640. 5/8" drywall - hung, taped, floated, ready for paint	41.00 SF		0.00	2.87	2.76	23.54	143.97
4,641. Batt insulation - 4" - R11-unfaced batt	20.00 SF		0.00	0.70	0.74	2.80	17.54
4,642. Baseboard - 2 1/4"	42.50 LF		0.00	2.90	4.01	24.66	151.92
4,643. Interior door - Colonist - pre-hung unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
4,644. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
4,645. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
4,646. Seal/prime then paint the walls and ceiling twice (3 coats)	501.56 SF		0.00	1.84	14.11	184.58	1,121.56
4,647. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,648. Mask the walls per square foot - plastic and tape - 4 mil	373.11 SF		0.00	0.35	1.88	26.12	158.59
4,649. Final cleaning - construction - Residential	128.44 SF		0.00	0.34	0.00	8.74	52.41
<b>Totals: Bedroom</b>					<b>47.80</b>	<b>352.38</b>	<b>2,161.86</b>



**Entry**

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

- Missing Wall**                      **1' 5" X 9'**                      **Opens into LIVING\_ROOM**
- Missing Wall**                      **4' 5" X 9'**                      **Opens into KITCHEN**
- Door**                                      **3' X 6' 8"**                      **Opens into Exterior**
- Door**                                      **2' 8" X 6' 8"**                      **Opens into BATHROOM**
- Door**                                      **2' 10" X 6' 8"**                      **Opens into BEDROOM**
- Missing Wall**                      **4' 6" X 9'**                      **Opens into LIVING\_ROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,650. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	29.00 SF		0.00	2.87	1.95	16.64	101.82
4,651. 5/8" drywall - hung, taped, floated, ready for paint	19.00 SF		0.00	2.87	1.28	10.90	66.71



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
4,652. Seal/prime then paint the walls and ceiling twice (3 coats)	195.72 SF		0.00	1.84	5.51	72.02	437.65
4,653. Baseboard - 3 1/4"	14.17 LF		0.00	3.49	2.07	9.90	61.42
4,654. Casing - 2 1/4"	14.00 LF		0.00	2.23	1.63	6.24	39.09
4,655. Base shoe	14.17 LF		0.00	1.41	0.71	4.00	24.69
4,656. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
4,657. R&R Light fixture	1.00 EA		10.49	69.13	3.32	15.92	98.86
4,658. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
4,659. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,660. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
4,661. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,662. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					17.95	170.30	1,039.81
Total: 9103					<b>196.38</b>	<b>1,689.84</b>	<b>10,334.94</b>

### 9105



### Bathroom

Height: 9'

256.03 SF Walls	62.14 SF Ceiling
318.17 SF Walls & Ceiling	62.14 SF Floor
6.90 SY Flooring	26.98 LF Floor Perimeter
32.64 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>					
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,663. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
4,664. 5/8" drywall - hung, taped, floated, ready for paint	32.00 SF		0.00	2.87	2.15	18.36	112.35

*Ceiling*




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,665. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	62.14 SF		0.00	1.12	4.68	13.92	88.20
4,666. Seal/prime then paint the walls and ceiling twice (3 coats)	318.17 SF		0.00	1.84	8.95	117.08	711.46
4,667. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	6.00 SF		0.00	1.07	0.39	1.28	8.09
4,668. Baseboard - 3 1/4" <i>Wall</i>	3.00 LF		0.00	3.49	0.44	2.10	13.01
4,669. Seal & paint baseboard - two coats	26.98 LF		0.00	2.24	0.30	12.08	72.82
4,670. Seal & paint base shoe or quarter round	26.98 LF		0.00	1.19	0.30	6.42	38.83
4,671. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,672. Mask the floor per square foot - plastic and tape - 4 mil	62.14 SF		0.00	0.35	0.31	4.36	26.42
4,673. Final cleaning - construction - Residential	62.14 SF		0.00	0.34	0.00	4.22	25.35
<b>Totals: Bathroom</b>					<b>18.63</b>	<b>240.96</b>	<b>1,464.48</b>



### Walk-in Closet

**Height: 9'**

179.77 SF Walls	31.46 SF Ceiling
211.23 SF Walls & Ceiling	31.46 SF Floor
3.50 SY Flooring	19.20 LF Floor Perimeter
22.20 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,674. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	40.00 SF		0.00	2.87	2.69	22.96	140.45
4,675. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	31.46 SF		0.00	1.12	2.37	7.04	44.65
4,676. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	211.23 SF		0.00	1.84	5.94	77.74	472.34




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Walk-in Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,677. Shelving - wire (vinyl coated) - Detach & reset	11.33 LF		0.00	9.66	0.00	21.90	131.35
4,678. Seal & paint baseboard - two coats	19.20 LF		0.00	2.24	0.21	8.60	51.82
4,679. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,680. Mask the floor per square foot - plastic and tape - 4 mil	31.46 SF		0.00	0.35	0.16	2.20	13.37
4,681. Final cleaning - construction - Residential	31.46 SF		0.00	0.34	0.00	2.14	12.84
Totals: Walk-in Closet					11.83	151.72	922.13



### Kitchen

Height: 9'

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

6' 4" X 5'

Opens into LIVING\_ROOM

Door

1' 8" X 6' 8"

Opens into PANTRY

Door

3' X 6' 8"

Opens into UTILITY\_ROOM

Missing Wall

4' 5" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,682. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
<i>Ceiling</i>							
4,683. Blown-in insulation - 10" depth - R26	65.15 SF		0.00	1.12	4.91	14.60	92.48
<i>Ceiling</i>							
4,684. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,685. Seal/prime then paint the walls and ceiling twice (3 coats)	267.13 SF		0.00	1.84	7.52	98.30	597.34
4,686. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
4,687. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
4,688. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,689. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
Totals: Kitchen					15.72	169.72	1,033.94



### Entry

Height: 9'

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	


Missing Wall	1' 5" X 9'	Opens into LIVING_ROOM
Missing Wall	4' 5" X 9'	Opens into KITCHEN
Door	3' X 6' 8"	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	2' 10" X 6' 8"	Opens into BEDROOM
Missing Wall	4' 6" X 9'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,690. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,691. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
4,692. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
4,693. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
4,694. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,695. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
4,696. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					5.35	88.96	539.04



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

**Missing Wall**

**1' 5" X 9'**

**Opens into ENTRY**

**Missing Wall - Goes to Ceiling**

**6' 10" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 6" X 9'**

**Opens into ENTRY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,697. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall fur down</i>	3.00 SF		0.00	2.87	0.20	1.72	10.53
4,698. Paint the walls and ceiling - two coats	640.44 SF		0.00	1.36	14.16	174.20	1,059.36
4,699. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,700. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
4,701. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,702. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,703. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
4,704. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>16.95</b>	<b>298.42</b>	<b>1,807.45</b>
<b>Total: 9105</b>					<b>68.48</b>	<b>949.78</b>	<b>5,767.04</b>

9108



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Entry**

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

- Missing Wall - Goes to Floor**      **5' 7" X 9'**      **Opens into KITCHEN**
- Missing Wall**      **4' 1" X 9'**      **Opens into LIVING\_ROOM**
- Door**      **1' 10" X 6' 8"**      **Opens into CLOSET**
- Door**      **2' 8" X 6' 8"**      **Opens into BATHROOM**
- Door**      **3' X 6' 8"**      **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,705. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,706. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
4,707. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,708. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
4,709. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,710. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,711. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>4.42</b>	<b>75.82</b>	<b>459.29</b>



**Bedroom**

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

- Missing Wall**      **4' 11" X 9'**      **Opens into BATHROOM**
- Window**      **4' X 4'**      **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,712. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Wall</i>							
4,713. Batt insulation - 6" - R19 - unfaced batt	14.00 SF		0.00	1.07	0.90	3.00	18.88
<i>Wall</i>							
4,714. Baseboard - 3 1/4"	14.00 LF		0.00	3.49	2.04	9.78	60.68
4,715. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,716. Seal/prime then paint the walls twice (3 coats)	337.25 SF		0.00	1.84	9.49	124.10	754.13
<i>Wall</i>							
4,717. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
Totals: Bedroom					13.80	170.78	1,038.44



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,718. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
<i>Ceiling</i>							
4,719. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
4,720. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,721. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
4,722. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,723. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
4,724. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,725. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					16.19	177.06	1,078.61



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,726. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
<i>Wall</i>							
4,727. Batt insulation - 6" - R19 - unfaced batt	6.00 SF		0.00	1.07	0.39	1.28	8.09
<i>Wall</i>							
4,728. Baseboard - 3 1/4"	8.00 LF		0.00	3.49	1.17	5.58	34.67
4,729. Base shoe	8.00 LF		0.00	1.41	0.40	2.26	13.94
4,730. Seal/prime then paint the walls twice (3 coats)	371.67 SF		0.00	1.84	10.46	136.78	831.11
4,731. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,732. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,733. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,734. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,735. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					14.24	248.82	1,507.19

Total: 9108

48.65

672.48


4,083.53



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

9111



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into ENTRY
Door	2' 8" X 6' 8"	Opens into WALKIN_CLOS
Missing Wall	4' 11" X 9'	Opens into BEDROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,736. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
4,737. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
Wall							
4,738. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
Wall							
4,739. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
4,740. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72
4,741. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
4,742. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,743. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
4,744. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					15.29	259.78	1,573.87
Total: 9111					15.29	259.78	1,573.87

9113



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Master Bath

Height: 8'

308.67 SF Walls	84.51 SF Ceiling
393.18 SF Walls & Ceiling	84.51 SF Floor
9.39 SY Flooring	37.67 LF Floor Perimeter
43.17 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>					
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into MASTER_WALK</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,745. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
4,746. Batt insulation - 4" - R11-unfaced batt	12.00 SF		0.00	0.70	0.45	1.68	10.53
4,747. Baseboard - 4 1/4"	3.67 LF		0.00	4.14	0.74	3.04	18.97
4,748. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64
4,749. R&R Light bar - 2 lights	2.00 EA		25.16	73.13	4.80	39.32	240.70
4,750. Seal/prime then paint the walls and ceiling twice (3 coats)	393.18 SF		0.00	1.84	11.06	144.70	879.21
4,751. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,752. Seal & paint baseboard - two coats	37.67 LF		0.00	2.24	0.42	16.88	101.68
4,753. Mask the ceiling per square foot - plastic and tape - 4 mil	84.51 SF		0.00	0.35	0.43	5.92	35.93
4,754. Final cleaning - construction - Residential	84.51 SF		0.00	0.34	0.00	5.74	34.47
Totals: Master Bath					20.27	294.44	1,786.87



### Master Walk-in Closet

Height: 8'

236.67 SF Walls	46.13 SF Ceiling
282.79 SF Walls & Ceiling	46.13 SF Floor
5.13 SY Flooring	29.17 LF Floor Perimeter
31.67 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into MASTER_BATH</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,755. 5/8" drywall - hung, taped, floated, ready for paint	38.00 SF		0.00	2.87	2.56	21.82	133.44
4,756. Baseboard - 4 1/4"	24.82 LF		0.00	4.14	5.04	20.56	128.35




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Master Walk-in Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,757. Batt insulation - 4" - R11-unfaced batt	12.00 SF		0.00	0.70	0.45	1.68	10.53
4,758. Detach & Reset Shelving - wire (vinyl coated)	30.00 LF	9.66	0.00	0.00	0.00	57.96	347.76
4,759. Seal/prime then paint the walls and ceiling twice (3 coats)	282.79 SF		0.00	1.84	7.96	104.06	632.35
4,760. Seal & paint baseboard - two coats	29.17 LF		0.00	2.24	0.32	13.06	78.72
4,761. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
<b>Totals: Master Walk-in Closet</b>					<b>16.87</b>	<b>229.90</b>	<b>1,396.23</b>



**Living / Dining Room**

**Height: 8'**

498.90 SF Walls	376.68 SF Ceiling
875.58 SF Walls & Ceiling	376.68 SF Floor
41.85 SY Flooring	63.08 LF Floor Perimeter
82.75 LF Ceil. Perimeter	

<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALL_BATHROO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall</b>	<b>14' 6 1/16" X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,762. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
4,763. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
4,764. Casing - 2 1/4"	14.00 LF		0.00	2.23	1.63	6.24	39.09
4,765. Seal/prime then paint the walls and ceiling twice (3 coats)	875.58 SF		0.00	1.84	24.64	322.22	1,957.93
4,766. Seal & paint baseboard - two coats	63.08 LF		0.00	2.24	0.70	28.26	170.26
4,767. Paint door/window trim & jamb - 2 coats (per side)	4.00 EA		0.00	45.71	1.83	36.56	221.23




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,768. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
4,769. Mask the walls per square foot - plastic and tape - 4 mil	498.90 SF		0.00	0.35	2.51	34.92	212.05
4,770. Final cleaning - construction - Residential	376.68 SF		0.00	0.34	0.00	25.62	153.69
Totals: Living / Dining Room					34.42	481.02	2,920.58



### Kitchen

Height: 8'

367.67 SF Walls	157.51 SF Ceiling
525.18 SF Walls & Ceiling	154.15 SF Floor
17.13 SY Flooring	54.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

7' 6" X 4'

Opens into KITCHEN

Door

3' X 6' 8"

Opens into Exterior

Door

1' 11" X 6' 8"

Opens into PANTRY

Door

1' 10" X 6' 8"

Opens into CLOSET

Missing Wall

14' 2 1/16" X 8'

Opens into LIVING\_\_DI2

Missing Wall - Goes to Ceiling

2' 3" X 4'

Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,771. 5/8" drywall - hung, taped, floated, ready for paint	32.00 SF		0.00	2.87	2.15	18.36	112.35
4,772. Batt insulation - 4" - R11-unfaced batt	30.00 SF		0.00	0.70	1.12	4.20	26.32
4,773. R&R Cabinetry - lower (base) units	9.34 LF		9.45	219.33	167.30	427.36	2,731.46
4,774. Baseboard - 2 1/4"	28.00 LF		0.00	2.90	2.65	16.24	100.09
4,775. Base shoe	28.00 LF		0.00	1.41	1.41	7.90	48.79
4,776. R&R Countertop - post formed plastic laminate	9.34 LF		5.22	50.41	32.61	103.92	656.11
4,777. R&R Cabinet refacing	35.84 SF		3.78	28.62	61.95	232.24	1,455.41
4,778. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
4,779. Detach & Reset Built-in oven	1.00 EA	203.73	0.00	0.00	0.00	40.74	244.47
4,780. Detach & Reset Cooktop - electric	1.00 EA	149.91	0.00	0.00	0.00	29.98	179.89
4,781. Casing - 2 1/4"	14.00 LF		0.00	2.23	1.63	6.24	39.09




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,782. Seal/prime then paint the walls and ceiling twice (3 coats)	525.18 SF		0.00	1.84	14.78	193.26	1,174.37
4,783. Mask the walls per square foot - plastic and tape - 4 mil	367.67 SF		0.00	0.35	1.85	25.74	156.27
4,784. Final cleaning - construction - Residential	154.15 SF		0.00	0.34	0.00	10.48	62.89
Totals: Kitchen					287.45	1,140.44	7,130.19




### Pantry

Height: 8'

63.22 SF Walls	5.63 SF Ceiling
68.85 SF Walls & Ceiling	5.63 SF Floor
0.63 SY Flooring	7.58 LF Floor Perimeter
9.50 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,785. 5/8" drywall - hung, taped, floated, ready for paint	63.22 SF		0.00	2.87	4.26	36.28	221.98
4,786. Baseboard - 2 1/4"	7.58 LF		0.00	2.90	0.72	4.40	27.10
4,787. Seal/prime then paint the walls and ceiling twice (3 coats)	68.85 SF		0.00	1.84	1.94	25.34	153.96
4,788. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,789. Mask the walls per square foot - plastic and tape - 4 mil	63.22 SF		0.00	0.35	0.32	4.42	26.87
4,790. Final cleaning - construction - Residential	5.63 SF		0.00	0.34	0.00	0.38	2.29
Totals: Pantry					7.70	79.96	487.51



### Closet

Height: 8'

65.11 SF Walls	5.81 SF Ceiling
70.92 SF Walls & Ceiling	5.81 SF Floor
0.65 SY Flooring	7.83 LF Floor Perimeter
9.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Door	1' 10" X 6' 8"			Opens into KITCHEN			



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,791. 5/8" drywall - hung, taped, floated, ready for paint	65.11 SF		0.00	2.87	4.38	37.38	228.63
4,792. Baseboard - 2 1/4"	7.83 LF		0.00	2.90	0.74	4.54	27.99
4,793. Seal/prime then paint the walls and ceiling twice (3 coats)	70.92 SF		0.00	1.84	2.00	26.10	158.59
4,794. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,795. Mask the walls per square foot - plastic and tape - 4 mil	65.11 SF		0.00	0.35	0.33	4.56	27.68
4,796. Final cleaning - construction - Residential	5.81 SF		0.00	0.34	0.00	0.40	2.38
<b>Totals: Closet</b>					7.91	82.12	500.58



### Bedroom 1 Walk-In Closet

**Height: 8'**


154.67 SF Walls	29.60 SF Ceiling
184.27 SF Walls & Ceiling	29.60 SF Floor
3.29 SY Flooring	18.67 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	4' X 6' 8"	
								Opens into BEDROOM_1	
4,797. 5/8" drywall - hung, taped, floated, ready for paint	11.00 SF		0.00	2.87	0.74	6.32	38.63		
4,798. Baseboard - 4 1/4"	18.67 LF		0.00	4.14	3.79	15.46	96.54		
4,799. Detach & Reset Shelving - wire (vinyl coated)	21.00 LF	9.66	0.00	0.00	0.00	40.58	243.44		
4,800. Seal/prime then paint the walls and ceiling twice (3 coats)	184.27 SF		0.00	1.84	5.19	67.82	412.07		
4,801. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08		
4,802. Seal & paint baseboard - two coats	18.67 LF		0.00	2.24	0.21	8.36	50.39		
4,803. Mask the floor per square foot - plastic and tape - 4 mil	29.60 SF		0.00	0.35	0.15	2.08	12.59		
4,804. Final cleaning - construction - Residential	29.60 SF		0.00	0.34	0.00	2.02	12.08		
<b>Totals: Bedroom 1 Walk-In Closet</b>					10.62	153.40	930.82		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Bedroom 1

**Height: 8'**

373.33 SF Walls	133.90 SF Ceiling
507.23 SF Walls & Ceiling	133.90 SF Floor
14.88 SY Flooring	45.50 LF Floor Perimeter
52.50 LF Ceil. Perimeter	

**Door** 4' X 6' 8" Opens into BEDROOM\_1\_WA  
**Door** 3' X 6' 8" Opens into LIVING\_\_DI2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,805. 5/8" drywall - hung, taped, floated, ready for paint	9.00 SF		0.00	2.87	0.61	5.16	31.60
4,806. Batt insulation - 4" - R11-unfaced batt	373.33 SF		0.00	0.70	13.88	52.26	327.47
4,807. Baseboard - 4 1/4"	11.00 LF		0.00	4.14	2.23	9.10	56.87
4,808. Seal/prime then paint the walls and ceiling twice (3 coats)	507.23 SF		0.00	1.84	14.27	186.66	1,134.23
4,809. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,810. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
4,811. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
<b>Totals: Bedroom 1</b>					<b>31.99</b>	<b>282.18</b>	<b>1,725.19</b>



### Linen Closet

**Height: 8'**

47.33 SF Walls	3.21 SF Ceiling
50.54 SF Walls & Ceiling	3.21 SF Floor
0.36 SY Flooring	5.67 LF Floor Perimeter
7.17 LF Ceil. Perimeter	

**Door** 1' 6" X 6' 8" Opens into HALL\_BATHROO

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,812. 5/8" drywall - hung, taped, floated, ready for paint	17.00 SF		0.00	2.87	1.14	9.76	59.69
4,813. Baseboard - 4 1/4"	5.67 LF		0.00	4.14	1.15	4.70	29.32
4,814. Detach & Reset Shelving - wire (vinyl coated)	3.00 LF	9.66	0.00	0.00	0.00	5.80	34.78
4,815. Seal/prime then paint the walls twice (3 coats)	47.33 SF		0.00	1.84	1.33	17.42	105.84




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Linen Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,816. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,817. Final cleaning - construction - Residential	3.21 SF		0.00	0.34	0.00	0.22	1.31
Totals: Linen Closet					4.08	47.04	286.25



### Hall Bathroom

Height: 8'

240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,818. 5/8" drywall - hung, taped, floated, ready for paint	317.00 SF		0.00	2.87	21.35	181.96	1,113.10
4,819. Batt insulation - 10" - R30 - unfaced batt	11.00 SF		0.00	1.57	1.14	3.46	21.87
4,820. R&R Light bar - 3 lights	1.00 EA		25.16	75.99	2.69	20.24	124.08
4,821. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64
4,822. Vanity	3.50 LF		0.00	211.87	60.07	148.32	949.94
4,823. Baseboard - 2 1/4"	29.33 LF		0.00	2.90	2.77	17.02	104.85
4,824. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,825. Final cleaning - construction - Residential	57.36 SF		0.00	0.34	0.00	3.90	23.40
Totals: Hall Bathroom					89.58	445.18	2,760.49

<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DI2</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom 2**

**Height: 8'**


420.05 SF Walls  
571.57 SF Walls & Ceiling  
16.84 SY Flooring  
59.01 LF Ceil. Perimeter

151.52 SF Ceiling  
151.52 SF Floor  
56.01 LF Floor Perimeter

**Door** 3' X 6' 8" **Opens into LIVING \_\_DI2**  
**Window** 4' X 4" **Opens into Exterior**  
**Window** 4' X 4" **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
4,826. 5/8" drywall - hung, taped, floated, ready for paint	41.00 SF		0.00	2.87	2.76	23.54	143.97	
4,827. Baseboard - 4 1/4"	13.50 LF		0.00	4.14	2.74	11.18	69.81	
4,828. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
4,829. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08	
4,830. Seal/prime then paint the walls and ceiling twice (3 coats)	571.57 SF		0.00	1.84	16.08	210.34	1,278.11	
4,831. Seal & paint baseboard - two coats	56.01 LF		0.00	2.24	0.62	25.10	151.18	
4,832. Batt insulation - 10" - R30 - unfaced batt	12.00 SF		0.00	1.57	1.24	3.76	23.84	
4,833. Final cleaning - construction - Residential	151.52 SF		0.00	0.34	0.00	10.30	61.82	
<b>Totals: Bedroom 2</b>						24.44	304.12	1,849.12
<b>Total: 9113</b>						<b>535.33</b>	<b>3,539.80</b>	<b>21,773.83</b>

9115



**Bedroom**

**Height: 9'**

373.11 SF Walls  
501.56 SF Walls & Ceiling  
14.27 SY Flooring  
45.33 LF Ceil. Perimeter

128.44 SF Ceiling  
128.44 SF Floor  
42.50 LF Floor Perimeter

**Window** 4' X 4" **Opens into Exterior**  
**Door** 2' 10" X 6' 8" **Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,834. 5/8" - drywall per LF - up to 2' tall	8.00 LF		0.00	11.45	1.14	18.32	111.06
4,835. Batt insulation - 4" - R13 - paper / foil faced	16.00 SF		0.00	1.07	1.16	3.42	21.70
4,836. Baseboard - 4 1/4"	8.00 LF		0.00	4.14	1.62	6.62	41.36
4,837. Seal & paint baseboard - two coats	42.50 LF		0.00	2.24	0.47	19.04	114.71
4,838. Seal/prime then paint the walls twice (3 coats)	373.11 SF		0.00	1.84	10.50	137.30	834.32
4,839. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
4,840. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,841. Final cleaning - construction - Residential	128.44 SF		0.00	0.34	0.00	8.74	52.41
<b>Totals: Bedroom</b>					<b>15.80</b>	<b>216.86</b>	<b>1,316.99</b>



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,842. 5/8" - drywall per LF - up to 2' tall	15.00 LF		0.00	11.45	2.14	34.36	208.25
4,843. Batt insulation - 4" - R13 - paper / foil faced	30.00 SF		0.00	1.07	2.17	6.42	40.69
4,844. Baseboard - 4 1/4"	15.00 LF		0.00	4.14	3.05	12.42	77.57
4,845. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
4,846. Seal/prime then paint the walls and ceiling twice (3 coats)	640.44 SF		0.00	1.84	18.02	235.68	1,432.11
4,847. Install Outlet or switch cover	3.00 EA		0.00	2.20	0.00	1.32	7.92




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,848. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
4,849. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
4,850. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,851. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					26.89	365.28	2,218.55
Total: 9115					<b>42.69</b>	<b>582.14</b>	<b>3,535.54</b>

### 9120



#### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,852. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,853. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,854. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
4,855. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,856. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
4,857. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,858. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					4.42	75.82	459.29



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,859. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,860. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
4,861. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,862. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
4,863. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,864. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					7.19	114.74	695.66



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,865. Baseboard - 3 1/4"	23.00 LF		0.00	3.49	3.35	16.06	99.68
4,866. Base shoe	23.00 LF		0.00	1.41	1.16	6.48	40.07
4,867. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
4,868. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Wall</i>							
4,869. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
4,870. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,871. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,872. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,873. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,874. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,875. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>19.19</b>	<b>304.76</b>	<b>1,847.91</b>
<b>Total: 9120</b>					<b>30.80</b>	<b>495.32</b>	<b>3,002.86</b>

### 9201



### Bathroom

Height: 9'

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" **Opens into ENTRY**

**Door** 2' 8" X 6' 8" **Opens into WALKIN\_CLOS**

**Missing Wall** 4' 11" X 9' **Opens into BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,876. 5/8" drywall - hung, taped, floated, ready for paint	44.00 SF		0.00	2.87	2.96	25.26	154.50
<i>Wall</i>							
4,877. Batt insulation - 6" - R19 - unfaced batt	44.00 SF		0.00	1.07	2.83	9.42	59.33
<i>Wall</i>							
4,878. Baseboard - 3 1/4"	22.00 LF		0.00	3.49	3.21	15.36	95.35
4,879. Seal & paint baseboard - two coats	36.58 LF		0.00	2.24	0.40	16.38	98.72




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,880. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
4,881. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
4,882. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
4,883. Sink - single - Detach & reset	1.00 EA		0.00	160.49	0.05	32.10	192.64
4,884. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
4,885. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
4,886. Paint the walls - two coats	341.69 SF		0.00	1.36	7.55	92.94	565.19
<i>Wall</i>							
4,887. Seal & paint base shoe or quarter round	36.58 LF		0.00	1.19	0.40	8.70	52.63
4,888. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,889. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
4,890. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
Totals: Bathroom					196.59	756.76	4,737.11



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,891. 5/8" drywall - hung, taped, floated, ready for paint	83.00 SF		0.00	2.87	5.59	47.64	291.44
<i>Ceiling</i>							
4,892. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,893. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
4,894. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
<i>Ceiling</i>							
<i>Wall</i>							
4,895. Batt insulation - 6" - R19 - unfaced batt	51.00 SF		0.00	1.07	3.28	10.92	68.77
<i>Wall</i>							
4,896. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,897. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
4,898. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
4,899. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
4,900. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					20.65	162.42	995.15



### Closet

Height: 9'

76.28 SF Walls	6.03 SF Ceiling
82.31 SF Walls & Ceiling	6.03 SF Floor
0.67 SY Flooring	8.00 LF Floor Perimeter
9.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,901. 5/8" drywall - hung, taped, floated, ready for paint	34.00 SF		0.00	2.87	2.29	19.52	119.39
<i>Wall</i>							
4,902. Baseboard - 3 1/4"	8.00 LF		0.00	3.49	1.17	5.58	34.67
4,903. Seal/prime then paint the walls twice (3 coats)	76.28 SF		0.00	1.84	2.15	28.08	170.59
<i>Wall</i>							
4,904. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,905. Seal & paint baseboard - two coats	8.00 LF		0.00	2.24	0.09	3.58	21.59




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,906. Seal & paint base shoe or quarter round	8.00 LF		0.00	1.19	0.09	1.90	11.51
4,907. Final cleaning - construction - Residential	6.03 SF		0.00	0.34	0.00	0.42	2.47
Totals: Closet					6.25	68.22	415.53



### Utility Room

Height: 9'


145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,908. 5/8" drywall - hung, taped, floated, ready for paint	5.00 SF		0.00	2.87	0.34	2.88	17.57
<i>Wall</i>							
4,909. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
4,910. Seal & paint baseboard - two coats	16.17 LF		0.00	2.24	0.18	7.24	43.64
4,911. Seal/prime then paint the walls twice (3 coats)	145.50 SF		0.00	1.84	4.09	53.54	325.35
4,912. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,913. Mask the floor per square foot - plastic and tape - 4 mil	14.88 SF		0.00	0.35	0.07	1.04	6.32
4,914. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
Totals: Utility Room					5.58	76.96	467.28



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,915. 5/8" drywall - hung, taped, floated, ready for paint	112.00 SF		0.00	2.87	7.54	64.28	393.26
<i>Ceiling</i>							
4,916. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
<i>Ceiling</i>							
4,917. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
<i>Ceiling</i>							
4,918. Range - gas - Remove & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
4,919. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
4,920. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
4,921. Countertop - solid surface	35.50 SF		0.00	64.30	159.48	456.54	2,898.67
4,922. Cabinetry - lower (base) units	17.00 LF		0.00	219.33	304.51	745.72	4,778.84
4,923. Sink - single - Detach & reset	1.00 EA		0.00	160.49	0.05	32.10	192.64
4,924. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
4,925. Countertop subdeck - plywood	35.50 SF		0.00	3.70	6.21	26.28	163.84
4,926. Baseboard - 3 1/4"	27.25 LF		0.00	3.49	3.97	19.02	118.09
4,927. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
4,928. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
4,929. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
4,930. Base shoe	27.25 LF		0.00	1.41	1.37	7.68	47.47
4,931. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
4,932. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
4,933. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41

Totals: Kitchen

500.22 1,656.62 10,439.95

SAULET-RECON-V5\_23-B

5/31/2022

Page: 467



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,934. 5/8" drywall - hung, taped, floated, ready for paint	48.00 SF		0.00	2.87	3.23	27.56	168.55
<i>Ceiling</i>							
4,935. Blown-in insulation - 10" depth - R26	48.00 SF		0.00	1.12	3.62	10.76	68.14
<i>Ceiling</i>							
4,936. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
4,937. Baseboard - 3 1/4"	16.00 LF		0.00	3.49	2.33	11.16	69.33
4,938. Base shoe	16.00 LF		0.00	1.41	0.80	4.52	27.88
4,939. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
4,940. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
<i>Wall</i>							
4,941. Outlet or switch - Detach & reset	3.00 EA		0.00	18.23	0.00	10.94	65.63
4,942. Batt insulation - 6" - R19 - unfaced batt	32.00 SF		0.00	1.07	2.06	6.84	43.14
<i>Wall</i>							
4,943. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,944. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,945. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,946. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
4,947. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					29.56	386.74	2,350.03



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

Missing Wall

4' 11" X 9'

Opens into BATHROOM

Window

4' X 4'

Opens into Exterior


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,948. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	38.00 SF		0.00	2.87	2.56	21.82	133.44
4,949. Baseboard - 3 1/4"	19.00 LF		0.00	3.49	2.77	13.26	82.34
4,950. Seal & paint baseboard - two coats	39.25 LF		0.00	2.24	0.43	17.58	105.93
4,951. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	458.96 SF		0.00	1.84	12.92	168.90	1,026.31
4,952. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	38.00 SF		0.00	1.07	2.44	8.14	51.24
4,953. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,954. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
4,955. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
4,956. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
<b>Totals: Bedroom</b>					<b>22.64</b>	<b>278.60</b>	<b>1,694.16</b>
<b>Total: 9201</b>					<b>781.49</b>	<b>3,386.32</b>	<b>21,099.21</b>

9203



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Walk-in Closet

**Height: 9'**

179.77 SF Walls	31.46 SF Ceiling
211.23 SF Walls & Ceiling	31.46 SF Floor
3.50 SY Flooring	19.20 LF Floor Perimeter
22.20 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' X 6' 8"			Opens into BATHROOM			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
4,957. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03	
4,958. 5/8" drywall - hung, taped, floated, ready for paint	1.00 SF		0.00	2.87	0.07	0.58	3.52	
<i>Ceiling</i>								
4,959. Paint the walls and ceiling - two coats	211.23 SF		0.00	1.36	4.67	57.46	349.40	
4,960. Blown-in insulation - 10" depth - R26	31.46 SF		0.00	1.12	2.37	7.04	44.65	
<i>Ceiling</i>								
4,961. Shelving - wire (vinyl coated) - Detach & reset	11.33 LF		0.00	9.66	0.00	21.90	131.35	
4,962. Seal & paint baseboard - two coats	19.20 LF		0.00	2.24	0.21	8.60	51.82	
4,963. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
4,964. Mask the floor per square foot - plastic and tape - 4 mil	31.46 SF		0.00	0.35	0.16	2.20	13.37	
4,965. Final cleaning - construction - Residential	31.46 SF		0.00	0.34	0.00	2.14	12.84	
<b>Totals: Walk-in Closet</b>						7.94	119.24	723.29



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**6' 4" X 5'**

**Opens into LIVING\_ROOM**

**Door**

**1' 8" X 6' 8"**

**Opens into PANTRY**

**Door**

**3' X 6' 8"**

**Opens into UTILITY\_ROOM**

**Missing Wall**

**4' 5" X 9'**

**Opens into ENTRY**




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,966. 5/8" drywall - hung, taped, floated, ready for paint	27.00 SF		0.00	2.87	1.82	15.50	94.81
4,967. Blown-in insulation - 10" depth - R26	65.15 SF		0.00	1.12	4.91	14.60	92.48
4,968. Paint the walls and ceiling - two coats	267.13 SF		0.00	1.36	5.91	72.66	441.87
4,969. Batt insulation - 6" - R19 - unfaced batt	15.00 SF		0.00	1.07	0.96	3.22	20.23
4,970. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
4,971. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
4,972. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
4,973. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
4,974. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
Totals: Kitchen					14.47	142.14	867.11



### Entry

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

Missing Wall	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
Missing Wall	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
Door	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
Door	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
Door	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
Missing Wall	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,975. 5/8" drywall - hung, taped, floated, ready for paint	45.00 SF		0.00	2.87	3.03	25.84	158.02
<i>Ceiling</i>							
4,976. Blown-in insulation - 10" depth - R26	48.39 SF		0.00	1.12	3.65	10.84	68.69
<i>Ceiling</i>							




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,977. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
4,978. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
4,979. Batt insulation - 6" - R19 - unfaced batt	27.00 SF		0.00	1.07	1.74	5.78	36.41
4,980. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
4,981. Paint the walls and ceiling - two coats	195.72 SF		0.00	1.36	4.33	53.24	323.75
4,982. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
4,983. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
4,984. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
4,985. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
4,986. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					17.96	143.00	875.95



### Living Room

Height: 9'

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,987. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	52.00 SF		0.00	2.87	3.50	29.84	182.58
4,988. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	640.44 SF		0.00	1.84	18.02	235.68	1,432.11




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
4,989. Baseboard - 3 1/4"	13.00 LF		0.00	3.49	1.89	9.08	56.34
4,990. Base shoe	13.00 LF		0.00	1.41	0.65	3.66	22.64
4,991. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
4,992. Seal & paint base shoe or quarter round	54.58 LF		0.00	1.19	0.60	13.00	78.55
4,993. Outlet or switch - Detach & reset	1.00 EA		0.00	18.23	0.00	3.64	21.87
4,994. Vinyl plank flooring	215.36 SF		0.00	5.74	64.71	247.24	1,548.12
4,995. Floor preparation for resilient flooring	215.36 SF		0.00	0.71	2.16	30.58	185.65
4,996. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
4,997. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
4,998. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
4,999. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
Totals: Living Room					93.21	676.94	4,154.81
Total: 9203					<b>133.58</b>	<b>1,081.32</b>	<b>6,621.16</b>

### 9206



#### Kitchen

Height: 9'

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN2</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,000. Paint the walls and ceiling - two coats	522.56 SF		0.00	1.36	11.55	142.14	864.37
5,001. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
5,002. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
5,003. Sprinkler head/escutcheon - Detach & reset	3.00 EA		0.00	17.44	0.00	10.46	62.78
5,004. Mask the walls per square foot - plastic and tape - 4 mil	385.98 SF		0.00	0.35	1.94	27.02	164.05
5,005. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					13.49	219.18	1,328.53



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN2
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,006. Paint the walls and ceiling - two coats	1,039.83 SF		0.00	1.36	22.99	282.84	1,720.00
5,007. Mask the walls per square foot - plastic and tape - 4 mil	655.11 SF		0.00	0.35	3.29	45.86	278.44
5,008. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					26.28	354.86	2,155.40



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 9206

39.77

574.04

3,483.93

**9208**



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,009. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
5,010. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,011. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
5,012. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
5,013. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,014. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>7.65</b>	<b>113.70</b>	<b>689.94</b>



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,015. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	8.00 SF		0.00	2.87	0.54	4.60	28.10




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,016. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	8.00 SF		0.00	1.07	0.51	1.72	10.79
5,017. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
5,018. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
5,019. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
5,020. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,021. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,022. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
5,023. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>17.66</b>	<b>303.00</b>	<b>1,835.64</b>



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,024. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
5,025. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,026. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,027. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
5,028. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
5,029. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					4.42	65.64	398.26
Total: 9208					<b>29.73</b>	<b>482.34</b>	<b>2,923.84</b>

### 9213



#### Bedroom 1

Height: 8'

373.33 SF Walls	133.90 SF Ceiling
507.23 SF Walls & Ceiling	133.90 SF Floor
14.88 SY Flooring	45.50 LF Floor Perimeter
52.50 LF Ceil. Perimeter	

**Door** 4' X 6' 8"

Opens into BEDROOM\_1\_WA

**Door** 3' X 6' 8"

Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,030. 5/8" drywall - hung, taped, floated, ready for paint	177.00 SF		0.00	2.87	11.92	101.60	621.51
<i>Ceiling</i>							
5,031. Blown-in insulation - 10" depth - R26	133.90 SF		0.00	1.12	10.09	30.00	190.06
<i>Ceiling</i>							
5,032. Seal/prime then paint the walls and ceiling twice (3 coats)	507.23 SF		0.00	1.84	14.27	186.66	1,134.23
<i>Ceiling</i>							
5,033. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
<i>Wall</i>							
5,034. Batt insulation - 6" - R19 - unfaced batt	111.00 SF		0.00	1.07	7.14	23.76	149.67
<i>Wall</i>							
5,035. Baseboard - 3 1/4"	17.00 LF		0.00	3.49	2.48	11.86	73.67
5,036. Seal & paint baseboard - two coats	45.50 LF		0.00	2.24	0.50	20.38	122.80



## Camp Construction Services


15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,037. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,038. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,039. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,040. Mask the floor per square foot - plastic and tape - 4 mil	133.90 SF		0.00	0.35	0.67	9.38	56.92
5,041. Final cleaning - construction - Residential	133.90 SF		0.00	0.34	0.00	9.10	54.63
Totals: Bedroom 1					47.98	497.28	3,031.66

### Hall Bathroom

Height: 8'



240.22 SF Walls	57.36 SF Ceiling
297.58 SF Walls & Ceiling	57.36 SF Floor
6.37 SY Flooring	29.33 LF Floor Perimeter
33.50 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,042. 5/8" drywall - hung, taped, floated, ready for paint	34.00 SF		0.00	2.87	2.29	19.52	119.39
<i>Ceiling</i>							
5,043. Blown-in insulation - 10" depth - R26	57.36 SF		0.00	1.12	4.32	12.84	81.40
<i>Ceiling</i>							
5,044. Seal/prime then paint the walls and ceiling twice (3 coats)	297.58 SF		0.00	1.84	8.37	109.52	665.44
5,045. Batt insulation - 6" - R19 - unfaced batt	21.00 SF		0.00	1.07	1.35	4.50	28.32
5,046. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
5,047. Seal & paint baseboard - two coats	29.33 LF		0.00	2.24	0.32	13.14	79.16
5,048. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
5,049. Seal & paint base shoe or quarter round	29.33 LF		0.00	1.19	0.32	6.98	42.20
5,050. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Hall Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,051. Mask the floor per square foot - plastic and tape - 4 mil	57.36 SF		0.00	0.35	0.29	4.02	24.39
5,052. Final cleaning - construction - Residential	57.36 SF		0.00	0.34	0.00	3.90	23.40
Totals: Hall Bathroom					18.81	237.66	1,444.66
Total: 9213					<b>66.79</b>	<b>734.94</b>	<b>4,476.32</b>

**9214**



### Bathroom

**Height: 9'**

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	

**Door** 1' 5" X 6' 8" Opens into LINEN\_CLOSET  
**Door** 2' 8" X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,053. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	12.00 SF		0.00	2.87	0.81	6.88	42.13
5,054. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	53.06 SF		0.00	1.12	4.00	11.88	75.31
5,055. Paint the walls and ceiling - two coats <i>Ceiling</i>	319.83 SF		0.00	1.36	7.07	87.00	529.04
5,056. Batt insulation - 6" - R19 - unfaced batt	21.00 SF		0.00	1.07	1.35	4.50	28.32
5,057. Seal & paint baseboard - two coats	28.58 LF		0.00	2.24	0.32	12.80	77.14
5,058. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
5,059. Seal & paint base shoe or quarter round	28.58 LF		0.00	1.19	0.32	6.80	41.13
5,060. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,061. Mask the floor per square foot - plastic and tape - 4 mil	53.06 SF		0.00	0.35	0.27	3.72	22.56




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,062. Final cleaning - construction - Residential	53.06 SF		0.00	0.34	0.00	3.60	21.64
Totals: Bathroom					15.25	198.32	1,205.22
Total: 9214					<b>15.25</b>	<b>198.32</b>	<b>1,205.22</b>

9220



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into MAIN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM2

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,063. 5/8" drywall - hung, taped, floated, ready for paint	40.83 SF		0.00	2.87	2.75	23.44	143.37
5,064. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
5,065. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
5,066. Mask the ceiling per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
5,067. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					7.43	97.72	593.60



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM2

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,068. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
5,069. Seal/prime then paint the ceiling twice (3 coats)	64.74 SF		0.00	1.84	1.82	23.82	144.76
5,070. Mask the ceiling per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,071. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					2.15	42.94	259.73



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into MAIN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,072. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,073. Seal/prime then paint the ceiling twice (3 coats)	154.68 SF		0.00	1.84	4.35	56.92	345.88
5,074. Mask the ceiling per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
5,075. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					5.13	114.48	692.06



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


Total: 9220

14.71

255.14

1,545.39

### 9301



#### Kitchen

Height: 9'

218.17 SF Walls  
282.90 SF Walls & Ceiling  
7.19 SY Flooring  
27.42 LF Ceil. Perimeter

64.74 SF Ceiling  
64.74 SF Floor  
27.25 LF Floor Perimeter

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,076. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	126.00 SF		0.00	2.87	8.48	72.32	442.42
5,077. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
5,078. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
5,079. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,080. Hanging light fixture <i>Wall</i>	2.00 EA		0.00	81.74	6.53	32.70	202.71
5,081. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	49.00 SF		0.00	1.07	3.15	10.48	66.06
5,082. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01
5,083. Base shoe	3.00 LF		0.00	1.41	0.15	0.84	5.22
5,084. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
5,085. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
5,086. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
5,087. Range - gas - Remove & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
5,088. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
5,089. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,090. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					35.84	372.46	2,270.70



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,091. 5/8" drywall - hung, taped, floated, ready for paint	50.00 SF		0.00	2.87	3.37	28.70	175.57
<i>Ceiling</i>							
5,092. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							
5,093. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
5,094. Batt insulation - 6" - R19 - unfaced batt	36.00 SF		0.00	1.07	2.32	7.70	48.54
<i>Wall</i>							
5,095. Baseboard - 3 1/4"	6.00 LF		0.00	3.49	0.87	4.18	25.99
5,096. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
5,097. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
5,098. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,099. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
5,100. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					15.02	130.62	798.77



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,101. 5/8" drywall - hung, taped, floated, ready for paint	149.00 SF		0.00	2.87	10.03	85.52	523.18
<i>Ceiling</i>							
5,102. Blown-in insulation - 10" depth - R26	154.68 SF		0.00	1.12	11.66	34.64	219.54
<i>Ceiling</i>							
5,103. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
5,104. Batt insulation - 6" - R19 - unfaced batt	30.00 SF		0.00	1.07	1.93	6.42	40.45
<i>Wall under countertop.</i>							
5,105. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
5,106. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
5,107. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,108. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,109. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,110. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
5,111. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					41.20	426.32	2,599.25
<b>Total: 9301</b>					<b>92.06</b>	<b>929.40</b>	<b>5,668.72</b>

9303



### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling
- Door
- Door
- Missing Wall

- 6' 4" X 5'
- 1' 8" X 6' 8"
- 3' X 6' 8"
- 4' 5" X 9'


- Opens into LIVING\_ROOM
- Opens into PANTRY
- Opens into UTILITY\_ROOM
- Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,112. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	25.00 SF		0.00	2.87	1.68	14.36	87.79
5,113. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	267.13 SF		0.00	1.84	7.52	98.30	597.34
5,114. Baseboard - 4 1/4"	24.75 LF		0.00	4.14	5.03	20.50	128.00
5,115. Base shoe	24.75 LF		0.00	1.41	1.24	6.98	43.12
5,116. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
5,117. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
5,118. Floor preparation for resilient flooring	65.15 SF		0.00	0.71	0.66	9.26	56.18
5,119. Vinyl plank flooring	65.15 SF		0.00	5.74	19.58	74.80	468.34
5,120. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
5,121. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59
<b>Totals: Kitchen</b>					<b>36.58</b>	<b>250.18</b>	<b>1,537.46</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	


<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,122. 5/8" drywall - hung, taped, floated, ready for paint	50.00 SF		0.00	2.87	3.37	28.70	175.57
<i>Ceiling</i>							
5,123. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,124. Seal/prime then paint the walls and ceiling twice (3 coats)	195.72 SF		0.00	1.84	5.51	72.02	437.65
5,125. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
5,126. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
5,127. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,128. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
5,129. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
<b>Totals: Entry</b>					<b>13.22</b>	<b>140.08</b>	<b>853.75</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 10" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into ENTRY</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,130. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	14.00 SF		0.00	2.87	0.94	8.04	49.16
5,131. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	640.44 SF		0.00	1.84	18.02	235.68	1,432.11
5,132. Baseboard - 3 1/4"	7.00 LF		0.00	3.49	1.02	4.88	30.33
5,133. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
5,134. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,135. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,136. Mask the floor per square foot - plastic and tape - 4 mil	215.36 SF		0.00	0.35	1.08	15.08	91.54
5,137. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86
<b>Totals: Living Room</b>					<b>22.57</b>	<b>334.88</b>	<b>2,031.83</b>
<b>Total: 9303</b>					<b>72.37</b>	<b>725.14</b>	<b>4,423.04</b>

**9304**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Utility Room

Height: 9'

184.94 SF Walls	24.32 SF Ceiling
209.26 SF Walls & Ceiling	24.32 SF Floor
2.70 SY Flooring	19.75 LF Floor Perimeter
22.83 LF Ceil. Perimeter	

Door	3' 1" X 6' 8"			Opens into ROOM3				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	5,138. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37
	5,139. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
	5,140. Seal & paint baseboard - two coats	19.75 LF		0.00	2.24	0.22	8.84	53.30
	5,141. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
	5,142. Base shoe	19.75 LF		0.00	1.41	0.99	5.58	34.42
	5,143. Seal & paint base shoe or quarter round	19.75 LF		0.00	1.19	0.22	4.70	28.42
	5,144. Floor preparation for resilient flooring	24.32 SF		0.00	0.71	0.24	3.46	20.97
	5,145. Vinyl plank flooring	24.32 SF		0.00	5.74	7.31	27.92	174.83
	5,146. Mask the floor per square foot - plastic and tape - 4 mil	24.32 SF		0.00	0.35	0.12	1.70	10.33
	5,147. Final cleaning - construction - Residential	24.32 SF		0.00	0.34	0.00	1.66	9.93
Totals: Utility Room						9.56	79.64	487.33



### Master Walk-in Closet

Height: 9'

216.67 SF Walls	36.80 SF Ceiling
253.47 SF Walls & Ceiling	36.80 SF Floor
4.09 SY Flooring	23.17 LF Floor Perimeter
26.67 LF Ceil. Perimeter	

Door	3' 6" X 6' 8"			Opens into MASTER_BATHR				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	5,148. 5/8" drywall - hung, taped, floated, ready for paint	36.80 SF		0.00	2.87	2.48	21.12	129.22
	5,149. Seal/prime then paint the ceiling twice (3 coats)	36.80 SF		0.00	1.84	1.04	13.54	82.29




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Walk-in Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,150. Batt insulation - 8" - R25 - unfaced batt	36.80 SF		0.00	1.43	3.00	10.52	66.14
5,151. Paint the walls - two coats	216.67 SF		0.00	1.36	4.79	58.94	358.40
5,152. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
5,153. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,154. Shelving - wire (vinyl coated) - Detach & reset	23.17 LF		0.00	9.66	0.00	44.76	268.58
5,155. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
5,156. Remove Carpet	36.80 SF		0.34	0.00	0.00	2.50	15.01
5,157. Carpet	42.32 SF		0.00	3.67	11.44	31.06	197.81
<i>15 % waste added for Carpet.</i>							
5,158. Carpet pad	36.80 SF		0.00	0.63	1.81	4.64	29.63
5,159. Seal & paint baseboard - two coats	23.17 LF		0.00	2.24	0.26	10.38	62.54
5,160. Mask the floor per square foot - plastic and tape - 4 mil	36.80 SF		0.00	0.35	0.18	2.58	15.64
5,161. Final cleaning - construction - Residential	36.80 SF		0.00	0.34	0.00	2.50	15.01
Totals: Master Walk-in Closet					25.54	227.24	1,388.94



### Pantry

Height: 9'

68.78 SF Walls	5.06 SF Ceiling
73.83 SF Walls & Ceiling	5.06 SF Floor
0.56 SY Flooring	7.17 LF Floor Perimeter
9.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,162. Vinyl plank flooring	5.06 SF		0.00	5.74	1.52	5.80	36.36
5,163. Floor preparation for resilient flooring	5.06 SF		0.00	0.71	0.05	0.72	4.36
5,164. Base shoe	7.17 LF		0.00	1.41	0.36	2.02	12.49
5,165. Seal & paint baseboard - two coats	7.17 LF		0.00	2.24	0.08	3.22	19.36




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Pantry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,166. Seal & paint base shoe or quarter round	7.17 LF		0.00	1.19	0.08	1.70	10.31
5,167. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,168. Final cleaning - construction - Residential	5.06 SF		0.00	0.34	0.00	0.34	2.06
Totals: Pantry					2.55	22.94	140.25



### Room2

Height: 9'

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into ROOM3
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into BEDROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into ROOM3
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into ROOM3

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,169. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
5,170. Paint the walls and ceiling - two coats	1,397.90 SF		0.00	1.36	30.91	380.22	2,312.27
5,171. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
5,172. Detach & Reset Light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
5,173. Seal & paint base shoe or quarter round	115.25 LF		0.00	1.19	1.27	27.44	165.86
5,174. Baseboard - 3 1/4"	115.25 LF		0.00	3.49	16.79	80.44	499.45
5,175. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Room2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,176. Batt insulation - 6" - R19 - unfaced batt	36.00 SF		0.00	1.07	2.32	7.70	48.54
5,177. Toe kick - pre-finished wood - 1/2"	10.00 LF		0.00	9.57	4.29	19.14	119.13
5,178. Base shoe	115.25 LF		0.00	1.41	5.79	32.50	200.79
5,179. Floor preparation for resilient flooring	500.67 SF		0.00	0.71	5.03	71.10	431.61
5,180. Vinyl plank flooring	500.67 SF		0.00	5.74	150.45	574.78	3,599.08
5,181. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
5,182. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27
Totals: Room2					224.43	1,382.46	8,519.22
Total: 9304					<b>262.08</b>	<b>1,712.28</b>	<b>10,535.74</b>

### 9308



#### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,183. 5/8" drywall - hung, taped, floated, ready for paint	202.00 SF		0.00	2.87	13.60	115.94	709.28
5,184. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
5,185. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,186. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,187. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,188. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
5,189. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,190. Mask the walls per square foot - plastic and tape - 4 mil	118.00 SF		0.00	0.35	0.59	8.26	50.15
5,191. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					22.68	219.82	1,341.62



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,192. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
5,193. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,194. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,195. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
5,196. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
5,197. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,198. Mask the ceiling per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,199. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					10.97	131.28	798.77



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

371.67 SF Walls  
526.35 SF Walls & Ceiling  
17.19 SY Flooring  
40.67 LF Ceil. Perimeter

154.68 SF Ceiling  
154.68 SF Floor  
46.08 LF Floor Perimeter

**Missing Wall - Goes to Ceiling Window**  
**Missing Wall**

**5' 5" X 5'**  
**4' X 4'**  
**4' 1" X 9'**

**Opens into KITCHEN**  
**Opens into Exterior**  
**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
5,200. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33	
5,201. Light fixture	2.00 EA		0.00	69.13	6.63	27.66	172.55	
5,202. Paint the ceiling - two coats	154.68 SF		0.00	1.36	3.42	42.08	255.86	
5,203. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37	
5,204. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	1.00 EA	34.54	0.00	0.00	0.00	6.90	41.44	
5,205. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61	
5,206. Mask the ceiling per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74	
5,207. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11	
<b>Totals: Living Room</b>						12.25	173.12	1,051.01
<b>Total: 9308</b>						<b>45.90</b>	<b>524.22</b>	<b>3,191.40</b>

**9312**



**Bedroom 2**

**Height: 8'**

420.05 SF Walls  
571.57 SF Walls & Ceiling  
16.84 SY Flooring  
59.01 LF Ceil. Perimeter

151.52 SF Ceiling  
151.52 SF Floor  
56.01 LF Floor Perimeter

**Door**  
**Window**  
**Window**

**3' X 6' 8"**  
**4' X 4'**  
**4' X 4'**

**Opens into LIVING\_\_DIN**  
**Opens into Exterior**  
**Opens into Exterior**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom 2


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,208. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	116.00 SF		0.00	2.87	7.81	66.58	407.31
5,209. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	8.00 SF		0.00	1.07	0.51	1.72	10.79
5,210. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	151.52 SF		0.00	1.12	11.42	33.94	215.06
5,211. Paint more than the ceiling - two coats <i>Ceiling</i>	571.57 SF		0.00	1.36	12.64	155.46	945.44
5,212. Ceiling fan - Detach & reset <i>Wall</i>	1.00 EA		0.00	181.11	0.00	36.22	217.33
5,213. Baseboard - 3 1/4"	17.00 LF		0.00	3.49	2.48	11.86	73.67
5,214. Seal & paint baseboard - two coats	56.01 LF		0.00	2.24	0.62	25.10	151.18
5,215. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,216. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,217. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,218. Mask the floor per square foot - plastic and tape - 4 mil	151.52 SF		0.00	0.35	0.76	10.60	64.39
5,219. Final cleaning - construction - Residential	151.52 SF		0.00	0.34	0.00	10.30	61.82
Totals: Bedroom 2					37.15	420.10	2,557.83
Total: 9312					<b>37.15</b>	<b>420.10</b>	<b>2,557.83</b>

9316



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**3' X 6' 8"**

**Opens into LIVING\_ROOM**

**Door**

**2' 8" X 6' 8"**


**Opens into WALKIN\_CLOS1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,220. Paint the walls and ceiling - two coats <i>Wall</i>	502.33 SF		0.00	1.36	11.11	136.64	830.92
5,221. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,222. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,223. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
5,224. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,225. Mask the floor per square foot - plastic and tape - 4 mil	136.10 SF		0.00	0.35	0.68	9.52	57.84
5,226. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
<b>Totals: Bedroom</b>					13.15	242.10	1,465.78



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

Height: 9'

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,227. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	2.00 SF		0.00	2.87	0.13	1.14	7.01
5,228. Paint the walls and ceiling - two coats <i>Wall</i>	1,310.03 SF		0.00	1.36	28.97	356.32	2,166.93
5,229. Baseboard - 3 1/4"	2.00 LF		0.00	3.49	0.29	1.40	8.67
5,230. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
5,231. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
5,232. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
5,233. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,234. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,235. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
5,236. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					46.73	607.06	3,688.99



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Total: 9316

59.88

849.16

5,154.77

**9401**



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,237. 5/8" drywall - hung, taped, floated, ready for paint	28.00 SF		0.00	2.87	1.89	16.08	98.33
5,238. Batt insulation - 6" - R19 - unfaced batt	28.00 SF		0.00	1.07	1.80	6.00	37.76
5,239. Seal/prime then paint the walls twice (3 coats)	371.67 SF		0.00	1.84	10.46	136.78	831.11
5,240. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
5,241. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
5,242. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
5,243. Baseboard - 3 1/4"	46.08 LF		0.00	3.49	6.72	32.16	199.70
5,244. Base shoe	46.08 LF		0.00	1.41	2.32	13.00	80.29
5,245. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11

Totals: Living Room

24.75


256.90

1,566.06



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Entry**


**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

- Missing Wall - Goes to Floor**      **5' 7" X 9'**      **Opens into KITCHEN**
- Missing Wall**      **4' 1" X 9'**      **Opens into LIVING\_ROOM**
- Door**      **1' 10" X 6' 8"**      **Opens into CLOSET**
- Door**      **2' 8" X 6' 8"**      **Opens into BATHROOM**
- Door**      **3' X 6' 8"**      **Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,246. 5/8" drywall - hung, taped, floated, ready for paint	118.00 SF		0.00	2.87	7.95	67.74	414.35
5,247. Batt insulation - 6" - R19 - unfaced batt	118.00 SF		0.00	1.07	7.59	25.26	159.11
5,248. Seal/prime then paint the walls twice (3 coats)	118.00 SF		0.00	1.84	3.32	43.42	263.86
5,249. Paint the ceiling - two coats	40.83 SF		0.00	1.36	0.90	11.10	67.53
5,250. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
5,251. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
5,252. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
5,253. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66

Totals: Entry      20.21      160.82      985.08



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **5' 5" X 5'**      **Opens into LIVING\_ROOM**
- Missing Wall - Goes to Floor**      **5' 7" X 9'**      **Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,254. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
5,255. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
5,256. 5/8" drywall - hung, taped, floated, ready for paint	21.00 SF		0.00	2.87	1.41	12.06	73.74
5,257. Batt insulation - 6" - R19 - unfaced batt	21.00 SF		0.00	1.07	1.35	4.50	28.32
5,258. Baseboard - 3 1/4"	27.25 LF		0.00	3.49	3.97	19.02	118.09
5,259. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
5,260. Seal/prime then paint the walls twice (3 coats)	218.17 SF		0.00	1.84	6.14	80.28	487.85
5,261. Base shoe	27.25 LF		0.00	1.41	1.37	7.68	47.47
5,262. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
5,263. Clean floor	64.74 SF		0.00	0.54	0.07	7.00	42.03
5,264. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,265. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					15.24	217.84	1,322.26
Total: 9401					<b>60.20</b>	<b>635.56</b>	<b>3,873.40</b>


### 9405

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,266. Floor preparation for resilient flooring	582.59 SF		0.00	0.71	5.86	82.72	502.22
5,267. Vinyl plank flooring	582.59 SF		0.00	5.74	175.06	668.82	4,187.95
5,268. Final cleaning - construction - Residential	582.59 SF		0.00	0.34	0.00	39.62	237.70
Total: 9405					180.92	791.16	4,927.87



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Pantry

Height: 9'

66.89 SF Walls	4.69 SF Ceiling
71.58 SF Walls & Ceiling	4.69 SF Floor
0.52 SY Flooring	7.00 LF Floor Perimeter
8.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 8" X 6' 8"			Opens into KITCHEN			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
5,269. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16	
5,270. Baseboard - 4 1/4"	5.25 LF		0.00	4.14	1.07	4.34	27.15	
5,271. Base shoe	7.00 LF		0.00	1.41	0.35	1.98	12.20	
5,272. Seal/prime then paint the walls twice (3 coats)	66.89 SF		0.00	1.84	1.88	24.62	149.58	
5,273. Detach & Reset Shelving - wire (vinyl coated)	7.00 LF	9.66	0.00	0.00	0.00	13.52	81.14	
5,274. Final cleaning - construction - Residential	4.69 SF		0.00	0.34	0.00	0.32	1.91	
<b>Totals: Pantry</b>					4.24	52.82	321.14	



### Bathroom

Height: 9'

256.03 SF Walls	62.14 SF Ceiling
318.17 SF Walls & Ceiling	62.14 SF Floor
6.90 SY Flooring	26.98 LF Floor Perimeter
32.64 LF Ceil. Perimeter	

DESCRIPTION	QTY	2' 8" X 6' 8"			Opens into ENTRY			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
5,275. R&R Light bar - 3 lights	1.00 EA		25.16	75.99	2.69	20.24	124.08	
5,276. 5/8" drywall - hung, taped, floated, ready for paint	30.00 SF		0.00	2.87	2.02	17.22	105.34	
5,277. Detach & Reset Toilet	1.00 EA	259.99	0.00	0.00	0.65	52.00	312.64	
5,278. Baseboard - 4 1/4"	10.34 LF		0.00	4.14	2.10	8.56	53.47	
5,279. Base shoe	10.34 LF		0.00	1.41	0.52	2.92	18.02	
5,280. Casing - 2 1/4"	28.00 LF		0.00	2.23	3.26	12.48	78.18	
5,281. Paint casing - two coats	28.00 LF		0.00	2.18	0.42	12.20	73.66	




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,282. Seal/prime then paint the walls twice (3 coats)	256.03 SF		0.00	1.84	7.20	94.22	572.52
5,283. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,284. Mask the walls per square foot - plastic and tape - 4 mil	256.03 SF		0.00	0.35	1.29	17.92	108.82
5,285. Final cleaning - construction - Residential	62.14 SF		0.00	0.34	0.00	4.22	25.35
Totals: Bathroom					21.06	260.26	1,582.69



### Walk-in Closet

Height: 9'


179.77 SF Walls	31.46 SF Ceiling
211.23 SF Walls & Ceiling	31.46 SF Floor
3.50 SY Flooring	19.20 LF Floor Perimeter
22.20 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	3' X 6' 8" Opens into BATHROOM	
5,286. 5/8" drywall - hung, taped, floated, ready for paint	76.79 SF		0.00	2.87	5.17	44.08	269.64		
5,287. Baseboard - 4 1/4"	19.20 LF		0.00	4.14	3.90	15.90	99.29		
5,288. Detach & Reset Shelving - wire (vinyl coated)	18.58 LF	9.66	0.00	0.00	0.00	35.90	215.38		
5,289. Casing - 2 1/4"	14.00 LF		0.00	2.23	1.63	6.24	39.09		
5,290. Carpet	36.18 SF		0.00	3.67	9.78	26.56	169.12		
15 % waste added for Carpet.									
5,291. Carpet pad	31.46 SF		0.00	0.63	1.55	3.96	25.33		
5,292. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31		
5,293. Final cleaning - construction - Residential	31.46 SF		0.00	0.34	0.00	2.14	12.84		
Totals: Walk-in Closet					22.49	143.92	886.00		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Utility Room

**Height: 9'**

185.50 SF Walls	26.94 SF Ceiling
212.44 SF Walls & Ceiling	26.94 SF Floor
2.99 SY Flooring	19.83 LF Floor Perimeter
22.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' X 6' 8"			Opens into KITCHEN			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
5,294. 5/8" drywall - hung, taped, floated, ready for paint	39.67 SF		0.00	2.87	2.67	22.78	139.30	
5,295. Baseboard - 4 1/4"	19.83 LF		0.00	4.14	4.03	16.42	102.55	
5,296. Base shoe	19.83 LF		0.00	1.41	1.00	5.60	34.56	
5,297. Batt insulation - 4" - R11-unfaced batt	1.00 SF		0.00	0.70	0.04	0.14	0.88	
5,298. Paint the walls - two coats	185.50 SF		0.00	1.36	4.10	50.46	306.84	
5,299. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
5,300. Seal & paint baseboard - two coats	19.83 LF		0.00	2.24	0.22	8.88	53.52	
5,301. Seal & paint base shoe or quarter round	19.83 LF		0.00	1.19	0.22	4.72	28.54	
5,302. Final cleaning - construction - Residential	26.94 SF		0.00	0.34	0.00	1.84	11.00	
<b>Totals: Utility Room</b>						12.74	119.98	732.50



### Bedroom

**Height: 9'**

373.11 SF Walls	128.44 SF Ceiling
501.56 SF Walls & Ceiling	128.44 SF Floor
14.27 SY Flooring	42.50 LF Floor Perimeter
45.33 LF Ceil. Perimeter	

DESCRIPTION	QTY	4' X 4'			Opens into Exterior			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
5,303. 5/8" drywall - hung, taped, floated, ready for paint	18.00 SF		0.00	2.87	1.21	10.34	63.21	
5,304. Seal/prime then paint the walls twice (3 coats)	373.11 SF		0.00	1.84	10.50	137.30	834.32	
5,305. Baseboard - 4 1/4"	8.34 LF		0.00	4.14	1.69	6.90	43.12	




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,306. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
5,307. Carpet pad	128.44 SF		0.00	0.63	6.33	16.18	103.43
5,308. Carpet	147.71 SF		0.00	3.67	39.93	108.42	690.45
15 % waste added for Carpet.							
5,309. Seal & paint baseboard - two coats	42.50 LF		0.00	2.24	0.47	19.04	114.71
5,310. Final cleaning - construction - Residential	128.44 SF		0.00	0.34	0.00	8.74	52.41
Totals: Bedroom					60.13	310.40	1,922.57



### Kitchen

Height: 9'

201.97 SF Walls	65.15 SF Ceiling
267.13 SF Walls & Ceiling	65.15 SF Floor
7.24 SY Flooring	24.75 LF Floor Perimeter
23.08 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

6' 4" X 5'

Opens into LIVING\_ROOM2

Door

1' 8" X 6' 8"

Opens into PANTRY

Door

3' X 6' 8"

Opens into UTILITY\_ROOM

Missing Wall

4' 5" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,311. 5/8" drywall - hung, taped, floated, ready for paint Wall	6.00 SF		0.00	2.87	0.40	3.44	21.06
5,312. Seal/prime then paint the walls twice (3 coats)	201.97 SF		0.00	1.84	5.68	74.32	451.62
5,313. Baseboard - 2 1/4"	2.00 LF		0.00	2.90	0.19	1.16	7.15
5,314. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
5,315. Seal & paint baseboard - two coats	24.75 LF		0.00	2.24	0.27	11.08	66.79
5,316. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,317. Seal & paint base shoe or quarter round	24.75 LF		0.00	1.19	0.27	5.90	35.62
5,318. Mask the floor per square foot - plastic and tape - 4 mil	65.15 SF		0.00	0.35	0.33	4.56	27.69
5,319. Final cleaning - construction - Residential	65.15 SF		0.00	0.34	0.00	4.44	26.59




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					11.70	126.38	769.96



**Entry**

**Height: 9'**

147.33 SF Walls	48.39 SF Ceiling
195.72 SF Walls & Ceiling	48.39 SF Floor
5.38 SY Flooring	14.17 LF Floor Perimeter
22.67 LF Ceil. Perimeter	


<b>Missing Wall</b>	<b>1' 5" X 9'</b>	<b>Opens into LIVING_ROOM2</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Missing Wall</b>	<b>4' 6" X 9'</b>	<b>Opens into LIVING_ROOM2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,320. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
5,321. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
5,322. Seal & paint baseboard - two coats	14.17 LF		0.00	2.24	0.16	6.34	38.24
5,323. Paint the walls - two coats <i>Wall</i>	147.33 SF		0.00	1.36	3.26	40.08	243.71
5,324. Seal & paint base shoe or quarter round	14.17 LF		0.00	1.19	0.16	3.38	20.40
5,325. Base shoe	10.00 LF		0.00	1.41	0.50	2.82	17.42
5,326. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,327. Mask the floor per square foot - plastic and tape - 4 mil	48.39 SF		0.00	0.35	0.24	3.38	20.56
5,328. Final cleaning - construction - Residential	48.39 SF		0.00	0.34	0.00	3.30	19.75
Totals: Entry					7.59	86.90	528.96



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

425.08 SF Walls	215.36 SF Ceiling
640.44 SF Walls & Ceiling	215.36 SF Floor
23.93 SY Flooring	54.58 LF Floor Perimeter
47.75 LF Ceil. Perimeter	

**Missing Wall**

**1' 5" X 9'**

**Opens into ENTRY**

**Missing Wall - Goes to Ceiling**

**6' 10" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 6" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,329. 5/8" drywall - hung, taped, floated, ready for paint	321.00 SF		0.00	2.87	21.61	184.26	1,127.14
5,330. Batt insulation - 6" - R19 - unfaced batt	80.25 SF		0.00	1.07	5.16	17.18	108.21
5,331. Blown-in insulation - 10" depth - R26	240.75 SF		0.00	1.12	18.15	53.92	341.71
5,332. R&R Ceiling fan & light	1.00 EA		23.73	324.26	12.81	69.60	430.40
5,333. Crown molding - 3 1/4"	23.88 LF		0.00	4.40	3.98	21.02	130.07
5,334. Baseboard - 4 1/4"	26.00 LF		0.00	4.14	5.28	21.52	134.44
5,335. Base shoe	26.00 LF		0.00	1.41	1.31	7.34	45.31
5,336. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
5,337. Detach & Reset Track lighting - track only	1.00 LF	9.84	0.00	0.00	0.00	1.96	11.80
5,338. Seal/prime then paint the walls and ceiling twice (3 coats)	640.44 SF		0.00	1.84	18.02	235.68	1,432.11
5,339. Paint crown molding - one coat	47.75 LF		0.00	1.48	0.53	14.14	85.34
5,340. Seal & paint trim - two coats	54.58 LF		0.00	2.15	0.66	23.48	141.49
5,341. Seal & paint base shoe or quarter round	54.58 LF		0.00	1.19	0.60	13.00	78.55
5,342. Seal & paint baseboard - two coats	54.58 LF		0.00	2.24	0.60	24.46	147.32
5,343. Vinyl plank flooring	215.36 SF		0.00	5.74	64.71	247.24	1,548.12
5,344. Floor preparation for resilient flooring	215.36 SF		0.00	0.71	2.16	30.58	185.65
5,345. Mask the walls per square foot - plastic and tape - 4 mil	425.08 SF		0.00	0.35	2.14	29.76	180.68
5,346. Final cleaning - construction - Residential	215.36 SF		0.00	0.34	0.00	14.64	87.86




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living Room					157.72	1,013.26	6,237.12
Total: 9405					<b>478.59</b>	<b>2,905.08</b>	<b>17,908.81</b>

9420



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,347. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
5,348. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
5,349. Paint the walls - two coats	118.00 SF		0.00	1.36	2.61	32.10	195.19
5,350. Baseboard - 3 1/4"	11.17 LF		0.00	3.49	1.63	7.80	48.41
5,351. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
5,352. Clean floor	40.83 SF		0.00	0.54	0.04	4.42	26.51
5,353. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
5,354. Seal & paint base shoe or quarter round	11.17 LF		0.00	1.19	0.12	2.66	16.07
5,355. Mask the floor per square foot - plastic and tape - 4 mil	40.83 SF		0.00	0.35	0.21	2.86	17.36
5,356. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					7.15	91.36	555.15



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,357. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
5,358. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
5,359. Seal & paint base shoe or quarter round	27.25 LF		0.00	1.19	0.30	6.48	39.21
5,360. Clean floor	64.74 SF		0.00	0.54	0.07	7.00	42.03
5,361. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
5,362. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
5,363. 5/8" drywall - hung, taped, floated, ready for paint	13.00 SF		0.00	2.87	0.88	7.46	45.65
5,364. Baseboard - 3 1/4"	27.25 LF		0.00	3.49	3.97	19.02	118.09
5,365. Base shoe	27.25 LF		0.00	1.41	1.37	7.68	47.47
5,366. Batt insulation - 6" - R19 - unfaced batt	13.00 SF		0.00	1.07	0.84	2.78	17.53
5,367. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,368. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41

Totals: Kitchen

13.88

150.80

918.72



### Bedroom

**Height: 9'**

362.22 SF Walls	120.89 SF Ceiling
483.11 SF Walls & Ceiling	120.89 SF Floor
13.43 SY Flooring	41.33 LF Floor Perimeter
44.00 LF Ceil. Perimeter	

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Window**

**4' X 4'**

**Opens into Exterior**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,369. 5/8" drywall - hung, taped, floated, ready for paint	48.00 SF		0.00	2.87	3.23	27.56	168.55
5,370. Batt insulation - 6" - R19 - unfaced batt	48.00 SF		0.00	1.07	3.09	10.28	64.73
5,371. Window sill	3.00 LF		0.00	3.12	0.27	1.88	11.51
5,372. Seal & paint window sill	3.00 LF		0.00	3.82	0.07	2.30	13.83
5,373. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
5,374. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
5,375. Seal/prime then paint the walls and ceiling twice (3 coats)	483.11 SF		0.00	1.84	13.59	177.78	1,080.29
5,376. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,377. Carpet	139.02 SF		0.00	3.67	37.58	102.04	649.82
<i>15 % waste added for Carpet.</i>							
5,378. Carpet pad	120.89 SF		0.00	0.63	5.95	15.24	97.35
5,379. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,380. Mask the floor per square foot - plastic and tape - 4 mil	120.89 SF		0.00	0.35	0.61	8.46	51.38
5,381. Final cleaning - construction - Residential	120.89 SF		0.00	0.34	0.00	8.22	49.32
<b>Totals: Bedroom</b>					<b>65.76</b>	<b>414.56</b>	<b>2,552.88</b>



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,382. Paint the walls - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79
5,383. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,384. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
5,385. Detach & Reset Window blind - PVC - 2" - 14.1 to 20 SF	2.00 EA	34.54	0.00	0.00	0.00	13.82	82.90
5,386. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
5,387. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					10.42	175.18	1,061.52
Total: 9420					<b>97.21</b>	<b>831.90</b>	<b>5,088.27</b>
Total: Building 9 Interiors					<b>3,776.75</b>	<b>27,933.06</b>	<b>171,372.59</b>

### Corridors/Breezways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,388. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	57,040. SF 00		0.00	2.87	3,840.79	32,740.96	200,286.55
5,389. Exterior - paint two coats <i>Estimated allowance</i>	28,520. SF 00		0.00	1.58	917.20	9,012.32	54,991.12
5,390. Electrician - per hour <i>Labor to detach and reset misc to prep for paint.</i>	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
5,391. Painter - per hour <i>Misc labor to prep for paint.</i>	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
5,392. Carpenter - General Frammer - per hour <i>Labor to install drywall nailers.</i>	60.00 HR		0.00	72.00	0.00	864.00	5,184.00
Totals: Corridors/Breezways					4,757.99	43,883.72	268,060.35

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,393. Clean with pressure/chemical spray	38,440. SF 00		0.00	0.43	38.63	3,305.84	19,873.67
5,394. Exterior - paint two coats	38,440. SF 00		0.00	1.58	1,236.23	12,147.04	74,118.47



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,395. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
5,396. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
5,397. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
5,398. R&R Window screen, 1 - 9 SF	31.00 EA		4.74	36.30	97.67	254.44	1,624.35
5,399. R&R Gutter / downspout - aluminum - 7" to 8"	548.00 LF		0.63	17.54	722.57	1,991.42	12,671.15
<b>548 LF Gutters</b>							
5,400. R&R Light fixture - wall sconce - High grade	5.00 EA		10.49	155.78	60.30	166.28	1,057.93
5,401. R&R Clothes dryer vent cover	1.00 EA		4.72	41.86	0.69	9.32	56.59
5,402. Clean with pressure/chemical spray	68.00 SF		0.00	0.43	0.07	5.84	35.15
<b>One (1) double doors and one (1) window.</b>							
5,403. R&R Fascia - fiber cement - 8"	50.00 LF		0.42	8.92	13.07	93.40	573.47
5,404. Prime & paint exterior fascia - wood, 6" - 8" wide	50.00 LF		0.00	3.15	0.95	31.50	189.95
Totals: Exteriors					2,314.40	21,912.92	133,791.99

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,446. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR					AS INCURRED	
5,447. Telehandler/forklift and operator	160.00 HR					AS INCURRED	
5,448. Scaffold - per section (per month)	16.00 MO		0.00	112.88	0.00	361.22	2,167.30
5,449. Commercial Supervision / Project Management - per hour	465.00 HR		0.00	68.91	0.00	6,408.64	38,451.79
5,450. General Laborer - per hour	512.00 HR		0.00	37.61	0.00	3,851.26	23,107.58
5,451. Temporary toilet (per month)	12.00 MO					AS INCURRED	
5,452. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
5,453. Hand wash station	6.00 MO					AS INCURRED	
5,454. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,455. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
5,456. OSHA compliance safety monitor- per hour	HR					AS INCURRED	
5,457. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
5,458. Overhead safety monitor - per hour	HR					AS INCURRED	
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
5,459. Taxes, insurance, permits & fees (Bid Item)	1.00 EA					AS INCURRED	
5,460. Light bulb - Incand. standard bulb - 1000 hr - mat. only	57.00 EA		0.00	0.79	4.53	9.00	58.56
<b>Totals: GENERAL CONDITIONS</b>					<b>64.53</b>	<b>10,863.86</b>	<b>65,247.67</b>
<b>Total: SAULET-BLDG-09-V5_23</b>					<b>10,913.67</b>	<b>104,593.56</b>	<b>638,472.60</b>

### SAULET-BLDG-10-V5\_23

#### Building 10 Interiors

#### 10108



#### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,461. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
5,462. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
5,463. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
5,464. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>6.89</b>	<b>98.08</b>	<b>595.42</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bathroom**

**Height: 9'**


341.69 SF Walls  
423.67 SF Walls & Ceiling  
9.11 SY Flooring  
41.92 LF Ceil. Perimeter

81.97 SF Ceiling  
81.97 SF Floor  
36.58 LF Floor Perimeter

**Door** 2' 8" X 6' 8" **Opens into ENTRY**  
**Door** 2' 8" X 6' 8" **Opens into WALKIN\_CLOS**  
**Missing Wall** 4' 11" X 9' **Opens into BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,465. 5/8" drywall - hung, taped, floated, ready for paint	18.00 SF		0.00	2.87	1.21	10.34	63.21
<i>Ceiling</i>							
5,466. Blown-in insulation - 10" depth - R26	81.97 SF		0.00	1.12	6.18	18.36	116.35
<i>Ceiling</i>							
5,467. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
<i>Ceiling</i>							
<i>Wall</i>							
5,468. Batt insulation - 6" - R19 - unfaced batt	10.00 SF		0.00	1.07	0.64	2.14	13.48
<i>Wall</i>							
5,469. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
5,470. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
<b>Totals: Bathroom</b>					<b>20.36</b>	<b>198.08</b>	<b>1,208.72</b>
<b>Total: 10108</b>					<b>27.25</b>	<b>296.16</b>	<b>1,804.14</b>

**10111**



**Closet**

**Height: 9'**

198.76 SF Walls  
235.72 SF Walls & Ceiling  
4.11 SY Flooring  
24.06 LF Ceil. Perimeter

36.97 SF Ceiling  
36.97 SF Floor  
21.39 LF Floor Perimeter

**Door** 2' 8" X 6' 8" **Opens into BATHROOM**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,471. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,472. 5/8" drywall - hung, taped, floated, ready for paint	235.72 SF		0.00	2.87	15.87	135.30	827.69
5,473. Batt insulation - 6" - R19 - unfaced batt	198.76 SF		0.00	1.07	12.78	42.54	267.99
5,474. Blown-in insulation - 10" depth - R26	36.97 SF		0.00	1.12	2.79	8.28	52.48
5,475. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
5,476. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,477. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
5,478. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,479. Baseboard - 4 1/4"	21.39 LF		0.00	4.14	4.34	17.72	110.61
5,480. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
5,481. Shelving - wire (vinyl coated)	21.39 LF		0.00	10.99	8.26	47.02	290.36
5,482. Carpet	42.51 SF		0.00	3.67	11.49	31.20	198.70
<i>15 % waste added for Carpet.</i>							
5,483. Carpet pad	36.97 SF		0.00	0.63	1.82	4.66	29.77
5,484. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,485. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
5,486. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet					91.87	483.48	2,992.67



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY2</b>
<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,487. 5/8" drywall - hung, taped, floated, ready for paint	472.34 SF		0.00	2.87	31.81	271.12	1,658.55
5,488. Batt insulation - 6" - R19 - unfaced batt	356.25 SF		0.00	1.07	22.91	76.24	480.34
5,489. Blown-in insulation - 10" depth - R26	116.09 SF		0.00	1.12	8.75	26.00	164.77
5,490. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
5,491. Range - gas - Remove & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
5,492. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
5,493. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
5,494. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
5,495. Sink - double - Detach & reset	1.00 EA		0.00	171.64	0.07	34.32	206.03
5,496. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
5,497. P-trap assembly - Detach & reset	1.00 EA		0.00	63.96	0.00	12.80	76.76
5,498. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
5,499. Cabinetry - lower (base) units	17.00 LF		0.00	219.33	304.51	745.72	4,778.84
5,500. Cabinetry - upper (wall) units	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
5,501. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
5,502. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,503. Countertop - solid surface	30.00 SF		0.00	64.30	134.77	385.80	2,449.57
5,504. Countertop subdeck - plywood	30.00 SF		0.00	3.70	5.25	22.20	138.45
5,505. Baseboard - 4 1/4"	53.92 LF		0.00	4.14	10.95	44.64	278.82




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,506. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
5,507. Vinyl plank flooring	111.67 SF		0.00	5.74	33.56	128.20	802.75
5,508. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
5,509. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					688.87	2,480.76	15,573.37



### Bathroom

Height: 9'

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	

Door 2' 8" X 6' 8" Opens into CLOSET2

Door 2' 8" X 6' 8" Opens into HALLWAY2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,510. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,511. 5/8" drywall - hung, taped, floated, ready for paint	335.92 SF		0.00	2.87	22.62	192.82	1,179.53
5,512. Batt insulation - 6" - R19 - unfaced batt	271.97 SF		0.00	1.07	17.49	58.20	366.70
5,513. Blown-in insulation - 10" depth - R26	63.94 SF		0.00	1.12	4.82	14.32	90.75
5,514. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16
5,515. Fiberglass tub & shower combination	1.00 EA		0.00	1,109.55	56.90	221.92	1,388.37
5,516. Tub/shower faucet	1.00 EA		0.00	315.61	14.07	63.12	392.80
5,517. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
5,518. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
5,519. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,520. Exhaust fan	1.00 EA		0.00	197.85	5.11	39.58	242.54
5,521. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
5,522. Mirror - 1/4" plate glass	18.00 SF		0.00	16.85	21.35	60.66	385.31
5,523. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,524. Baseboard - 3 1/4"	28.84 LF		0.00	3.49	4.20	20.14	124.99
5,525. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,526. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
5,527. Seal & paint baseboard - two coats	28.84 LF		0.00	2.24	0.32	12.92	77.84
5,528. Vinyl plank flooring	63.94 SF		0.00	5.74	19.21	73.40	459.63
5,529. Sink - single	1.00 EA		0.00	274.65	15.92	54.94	345.51
5,530. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
5,531. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
5,532. Mask the floor per square foot - plastic and tape - 4 mil	63.94 SF		0.00	0.35	0.32	4.48	27.18
5,533. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
Totals: Bathroom					400.69	1,593.04	9,958.76



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

2' 8" X 6' 8"

Opens into HALLWAY2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,534. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,535. 5/8" drywall - hung, taped, floated, ready for paint	505.07 SF		0.00	2.87	34.01	289.92	1,773.48
5,536. Batt insulation - 6" - R19 - unfaced batt	375.72 SF		0.00	1.07	24.17	80.40	506.59
5,537. Blown-in insulation - 10" depth - R26	129.35 SF		0.00	1.12	9.75	28.98	183.60
5,538. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
5,539. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,540. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
5,541. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,542. Baseboard - 4 1/4"	42.83 LF		0.00	4.14	8.70	35.46	221.48
5,543. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
5,544. Carpet	148.75 SF		0.00	3.67	40.21	109.18	695.30
<i>15 % waste added for Carpet.</i>							
5,545. Carpet pad	129.35 SF		0.00	0.63	6.37	16.30	104.16
5,546. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,547. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
5,548. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					<b>162.68</b>	<b>868.42</b>	<b>5,373.10</b>

Entry	Height: 9'
124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	



DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,549. 5/8" drywall - hung, taped, floated, ready for paint	152.83 SF		0.00	2.87	10.29	87.72	536.63
5,550. Batt insulation - 6" - R19 - unfaced batt	124.25 SF		0.00	1.07	7.99	26.60	167.54
5,551. Blown-in insulation - 10" depth - R26	28.58 SF		0.00	1.12	2.15	6.40	40.56
5,552. Steel door, 3' x 7' - fire rated	1.00 EA		0.00	567.29	51.51	113.46	732.26
5,553. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,554. Baseboard - 4 1/4"	12.25 LF		0.00	4.14	2.49	10.14	63.35
5,555. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
5,556. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
5,557. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,558. Seal/prime then paint the walls and ceiling twice (3 coats)	152.83 SF		0.00	1.84	4.30	56.24	341.75
5,559. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
5,560. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
5,561. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
5,562. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					91.45	376.68	2,351.64



### Utility Room

Height: 9'


322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	Door	3' X 6' 8"	Opens into ENTRY
5,563. 5/8" drywall - hung, taped, floated, ready for paint	368.15 SF		0.00	2.87	24.79	211.32	1,292.70			
5,564. Batt insulation - 6" - R19 - unfaced batt	322.00 SF		0.00	1.07	20.71	68.90	434.15			
5,565. Blown-in insulation - 10" depth - R26	46.15 SF		0.00	1.12	3.48	10.34	65.51			
5,566. Seal/prime then paint the walls and ceiling twice (3 coats)	368.15 SF		0.00	1.84	10.36	135.48	823.24			
5,567. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37			
5,568. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45			
5,569. Baseboard - 3 1/4"	35.00 LF		0.00	3.49	5.10	24.44	151.69			
5,570. Seal & paint baseboard - two coats	35.00 LF		0.00	2.24	0.39	15.68	94.47			
5,571. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27			
5,572. Mask the floor per square foot - plastic and tape - 4 mil	46.15 SF		0.00	0.35	0.23	3.24	19.62			
5,573. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83			
Totals: Utility Room					68.38	503.00	3,086.30			



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Pantry

**Height: 9'**

63.50 SF Walls	4.17 SF Ceiling
67.67 SF Walls & Ceiling	4.17 SF Floor
0.46 SY Flooring	6.67 LF Floor Perimeter
8.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 6" X 6" 8"			Opens into KITCHEN			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
5,574. 5/8" drywall - hung, taped, floated, ready for paint	67.67 SF		0.00	2.87	4.56	38.84	237.61	
5,575. Batt insulation - 6" - R19 - unfaced batt	63.50 SF		0.00	1.07	4.08	13.60	85.63	
5,576. Blown-in insulation - 10" depth - R26	4.17 SF		0.00	1.12	0.31	0.94	5.92	
5,577. Seal/prime then paint the walls and ceiling twice (3 coats)	67.67 SF		0.00	1.84	1.90	24.90	151.31	
5,578. Baseboard - 3 1/4"	6.67 LF		0.00	3.49	0.97	4.66	28.91	
5,579. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27	
5,580. Seal & paint baseboard - two coats	6.67 LF		0.00	2.24	0.07	2.98	17.99	
5,581. Shelving - 12" - in place	6.67 LF		0.00	10.47	2.72	13.96	86.51	
5,582. Paint wood shelving, 12" - 24" width - 1 coat	6.67 LF		0.00	4.50	0.23	6.00	36.25	
5,583. Mask the floor per square foot - plastic and tape - 4 mil	4.17 SF		0.00	0.35	0.02	0.30	1.78	
5,584. Final cleaning - construction - Residential	4.17 SF		0.00	0.34	0.00	0.28	1.70	
<b>Totals: Pantry</b>					18.18	120.28	739.88	



### Hallway

**Height: 9'**

61.19 SF Walls	11.96 SF Ceiling
73.15 SF Walls & Ceiling	11.96 SF Floor
1.33 SY Flooring	5.42 LF Floor Perimeter
10.75 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Hallway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,585. 5/8" drywall - hung, taped, floated, ready for paint	73.15 SF		0.00	2.87	4.93	41.98	256.85
5,586. Batt insulation - 6" - R19 - unfaced batt	61.19 SF		0.00	1.07	3.94	13.10	82.51
5,587. Blown-in insulation - 10" depth - R26	11.96 SF		0.00	1.12	0.90	2.68	16.98
5,588. Seal/prime then paint the walls and ceiling twice (3 coats)	73.15 SF		0.00	1.84	2.06	26.92	163.58
5,589. Baseboard - 3 1/4"	5.42 LF		0.00	3.49	0.79	3.78	23.49
5,590. Seal & paint baseboard - two coats	5.42 LF		0.00	2.24	0.06	2.42	14.62
5,591. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,592. Mask the floor per square foot - plastic and tape - 4 mil	11.96 SF		0.00	0.35	0.06	0.84	5.09
5,593. Final cleaning - construction - Residential	11.96 SF		0.00	0.34	0.00	0.82	4.89
<b>Totals: Hallway</b>					<b>16.06</b>	<b>106.36</b>	<b>654.28</b>



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,594. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
5,595. 5/8" drywall - hung, taped, floated, ready for paint	704.18 SF		0.00	2.87	47.42	404.20	2,472.62
5,596. Batt insulation - 6" - R19 - unfaced batt	414.58 SF		0.00	1.07	26.67	88.72	558.99
5,597. Blown-in insulation - 10" depth - R26	289.60 SF		0.00	1.12	21.83	64.88	411.06



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,598. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
5,599. Vinyl plank flooring	289.60 SF		0.00	5.74	87.02	332.46	2,081.78
5,600. Baseboard - 3 1/4"	48.58 LF		0.00	3.49	7.08	33.90	210.52
5,601. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
5,602. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
5,603. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
5,604. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
5,605. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
5,606. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,607. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	18.80	0.00	7.52	45.12
5,608. Smoke detector	1.00 EA		0.00	60.60	2.82	12.12	75.54
5,609. French double doors - Exterior - pre-hung unit	1.00 EA		0.00	1,359.90	117.82	271.98	1,749.70
5,610. Window sill	6.00 LF		0.00	3.12	0.55	3.74	23.01
5,611. Seal & paint window sill	4.00 LF		0.00	3.82	0.10	3.06	18.44
5,612. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
5,613. Track lighting - track only	8.00 LF		0.00	21.78	4.32	34.84	213.40
5,614. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
5,615. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>359.36</b>	<b>1,739.88</b>	<b>10,798.59</b>
<b>Total: 10111</b>					<b>1,897.54</b>	<b>8,271.90</b>	<b>51,528.59</b>

10114



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 8'**


278.00 SF Walls  
388.63 SF Walls & Ceiling  
12.29 SY Flooring  
42.17 LF Ceil. Perimeter

110.63 SF Ceiling  
110.63 SF Floor  
35.67 LF Floor Perimeter

**Door** 4' X 6' 8" Opens into **BEDROOM\_CLOS**  
**Door** 2' 6" X 6' 8" Opens into **LIVING\_ROOM**  
**Window** 4' X 4' Opens into **Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,616. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
5,617. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	388.63 SF		0.00	1.84	10.94	143.02	869.04
5,618. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
5,619. Mask the floor per square foot - plastic and tape - 4 mil	110.63 SF		0.00	0.35	0.56	7.74	47.02
5,620. Final cleaning - construction - Residential	110.63 SF		0.00	0.34	0.00	7.52	45.13

Totals: Bedroom 14.14 174.04 1,058.39



**Bedroom Closet**

**Height: 8'**

88.00 SF Walls  
97.17 SF Walls & Ceiling  
1.02 SY Flooring  
14.33 LF Ceil. Perimeter

9.17 SF Ceiling  
9.17 SF Floor  
10.33 LF Floor Perimeter

**Door** 4' X 6' 8" Opens into **BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,621. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
5,622. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	97.17 SF		0.00	1.84	2.73	35.76	217.28




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,623. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97
5,624. Mask the floor per square foot - plastic and tape - 4 mil	9.17 SF		0.00	0.35	0.05	0.64	3.90
5,625. Final cleaning - construction - Residential	9.17 SF		0.00	0.34	0.00	0.62	3.74
Totals: Bedroom Closet					5.42	52.78	322.12
Total: 10114					<b>19.56</b>	<b>226.82</b>	<b>1,380.51</b>

### 10211



#### Closet

Height: 9'

198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,626. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,627. 5/8" drywall - hung, taped, floated, ready for paint	235.72 SF		0.00	2.87	15.87	135.30	827.69
5,628. Batt insulation - 6" - R19 - unfaced batt	198.76 SF		0.00	1.07	12.78	42.54	267.99
5,629. Blown-in insulation - 10" depth - R26	36.97 SF		0.00	1.12	2.79	8.28	52.48
5,630. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
5,631. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,632. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
5,633. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,634. Baseboard - 3 1/4"	21.39 LF		0.00	3.49	3.12	14.94	92.71
5,635. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
5,636. Shelving - wire (vinyl coated)	21.39 LF		0.00	10.99	8.26	47.02	290.36
5,637. Carpet	42.51 SF		0.00	3.67	11.49	31.20	198.70

15 % waste added for Carpet.




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,638. Carpet pad	36.97 SF		0.00	0.63	1.82	4.66	29.77
5,639. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,640. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
5,641. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
<b>Totals: Closet</b>					<b>91.39</b>	<b>491.32</b>	<b>3,039.28</b>



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**                      **2' 6" X 5'**                      **Opens into KITCHEN**
- Door**    **1' 6" X 6' 8"**                      **Opens into PANTRY**
- Missing Wall**    **2' 4" X 9'**                      **Opens into HALLWAY**
- Missing Wall**    **12' 7" X 9'**                      **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling**                      **7' 7" X 5'**                      **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling**                      **2' 6" X 5'**                      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,642. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
5,643. Trash compactor - Remove & reset	1.00 EA		0.00	101.95	0.00	20.40	122.35
5,644. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
5,645. Sink - double - Detach & reset	1.00 EA		0.00	171.64	0.07	34.32	206.03
5,646. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
5,647. P-trap assembly - Detach & reset	1.00 EA		0.00	63.96	0.00	12.80	76.76
5,648. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
5,649. Cabinetry - lower (base) units	17.00 LF		0.00	219.33	304.51	745.72	4,778.84
5,650. Cabinetry - upper (wall) units	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
5,651. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
5,652. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,653. Countertop - solid surface	30.00 SF		0.00	64.30	134.77	385.80	2,449.57




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,654. Countertop subdeck - plywood	30.00 SF		0.00	3.70	5.25	22.20	138.45
5,655. 5/8" drywall - hung, taped, floated, ready for paint	472.34 SF		0.00	2.87	31.81	271.12	1,658.55
5,656. Batt insulation - 6" - R19 - unfaced batt	356.25 SF		0.00	1.07	22.91	76.24	480.34
5,657. Blown-in insulation - 10" depth - R26	116.09 SF		0.00	1.12	8.75	26.00	164.77
5,658. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
5,659. Range - gas - Remove & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
5,660. Baseboard - 4 1/4"	53.92 LF		0.00	4.14	10.95	44.64	278.82
5,661. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
5,662. Vinyl plank flooring	111.67 SF		0.00	5.74	33.56	128.20	802.75
5,663. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
5,664. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					688.87	2,466.86	15,489.96



### Bathroom

Height: 9'

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8"

**Opens into CLOSET**

**Door** 2' 8" X 6' 8"

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,665. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,666. 5/8" drywall - hung, taped, floated, ready for paint	335.92 SF		0.00	2.87	22.62	192.82	1,179.53
5,667. Batt insulation - 6" - R19 - unfaced batt	271.97 SF		0.00	1.07	17.49	58.20	366.70
5,668. Blown-in insulation - 10" depth - R26	63.94 SF		0.00	1.12	4.82	14.32	90.75
5,669. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,670. Fiberglass tub & shower combination	1.00 EA		0.00	1,109.55	56.90	221.92	1,388.37
5,671. Tub/shower faucet	1.00 EA		0.00	315.61	14.07	63.12	392.80
5,672. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
5,673. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
5,674. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,675. Exhaust fan	1.00 EA		0.00	197.85	5.11	39.58	242.54
5,676. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
5,677. Mirror - 1/4" plate glass	18.00 SF		0.00	16.85	21.35	60.66	385.31
5,678. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
5,679. Baseboard - 4 1/4"	28.84 LF		0.00	4.14	5.86	23.88	149.14
5,680. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,681. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
5,682. Seal & paint baseboard - two coats	28.84 LF		0.00	2.24	0.32	12.92	77.84
5,683. Vinyl plank flooring	63.94 SF		0.00	5.74	19.21	73.40	459.63
5,684. Sink - single	1.00 EA		0.00	274.65	15.92	54.94	345.51
5,685. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
5,686. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
5,687. Mask the floor per square foot - plastic and tape - 4 mil	63.94 SF		0.00	0.35	0.32	4.48	27.18
5,688. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
<b>Totals: Bathroom</b>					<b>401.61</b>	<b>1,586.16</b>	<b>9,918.40</b>



### Bedroom

**Height: 9'**

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,689. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,690. 5/8" drywall - hung, taped, floated, ready for paint	505.07 SF		0.00	2.87	34.01	289.92	1,773.48
5,691. Batt insulation - 6" - R19 - unfaced batt	375.72 SF		0.00	1.07	24.17	80.40	506.59
5,692. Blown-in insulation - 10" depth - R26	129.35 SF		0.00	1.12	9.75	28.98	183.60
5,693. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
5,694. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,695. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
5,696. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,697. Baseboard - 4 1/4"	42.83 LF		0.00	4.14	8.70	35.46	221.48
5,698. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
5,699. Carpet	148.75 SF		0.00	3.67	40.21	109.18	695.30
<i>15 % waste added for Carpet.</i>							
5,700. Carpet pad	129.35 SF		0.00	0.63	6.37	16.30	104.16
5,701. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,702. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
5,703. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					<b>163.42</b>	<b>879.04</b>	<b>5,437.61</b>



<b>Entry</b>		<b>Height: 9'</b>
124.25 SF Walls	28.58 SF Ceiling	
152.83 SF Walls & Ceiling	28.58 SF Floor	
3.18 SY Flooring	12.25 LF Floor Perimeter	
18.25 LF Ceil. Perimeter		

- Door** 3' X 6' 8" **Opens into Exterior**
- Door** 3' X 6' 8" **Opens into UTILITY\_ROOM**
- Missing Wall** 4' 1" X 9' **Opens into LIVING\_\_DIN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,704. 5/8" drywall - hung, taped, floated, ready for paint	152.83 SF		0.00	2.87	10.29	87.72	536.63




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,705. Batt insulation - 6" - R19 - unfaced batt	124.25 SF		0.00	1.07	7.99	26.60	167.54
5,706. Blown-in insulation - 10" depth - R26	28.58 SF		0.00	1.12	2.15	6.40	40.56
5,707. Steel door, 3' x 7' - fire rated	1.00 EA		0.00	567.29	51.51	113.46	732.26
5,708. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,709. Baseboard - 4 1/4"	12.25 LF		0.00	4.14	2.49	10.14	63.35
5,710. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
5,711. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
5,712. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,713. Seal/prime then paint the walls and ceiling twice (3 coats)	152.83 SF		0.00	1.84	4.30	56.24	341.75
5,714. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
5,715. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
5,716. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
5,717. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
<b>Totals: Entry</b>					91.45	376.68	2,351.64



### Utility Room

**Height: 9'**

322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,718. 5/8" drywall - hung, taped, floated, ready for paint	368.15 SF		0.00	2.87	24.79	211.32	1,292.70
5,719. Batt insulation - 6" - R19 - unfaced batt	322.00 SF		0.00	1.07	20.71	68.90	434.15
5,720. Blown-in insulation - 10" depth - R26	46.15 SF		0.00	1.12	3.48	10.34	65.51
5,721. Seal/prime then paint the walls and ceiling twice (3 coats)	368.15 SF		0.00	1.84	10.36	135.48	823.24




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,722. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37
5,723. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
5,724. Baseboard - 4 1/4"	35.00 LF		0.00	4.14	7.11	28.98	180.99
5,725. Seal & paint baseboard - two coats	35.00 LF		0.00	2.24	0.39	15.68	94.47
5,726. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,727. Mask the floor per square foot - plastic and tape - 4 mil	46.15 SF		0.00	0.35	0.23	3.24	19.62
5,728. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83
Totals: Utility Room					70.39	507.54	3,115.60



### Pantry

Height: 9'

63.50 SF Walls	4.17 SF Ceiling
67.67 SF Walls & Ceiling	4.17 SF Floor
0.46 SY Flooring	6.67 LF Floor Perimeter
8.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,729. 5/8" drywall - hung, taped, floated, ready for paint	67.67 SF		0.00	2.87	4.56	38.84	237.61
5,730. Batt insulation - 6" - R19 - unfaced batt	63.50 SF		0.00	1.07	4.08	13.60	85.63
5,731. Blown-in insulation - 10" depth - R26	4.17 SF		0.00	1.12	0.31	0.94	5.92
5,732. Seal/prime then paint the walls and ceiling twice (3 coats)	67.67 SF		0.00	1.84	1.90	24.90	151.31
5,733. Baseboard - 4 1/4"	6.67 LF		0.00	4.14	1.35	5.52	34.48
5,734. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,735. Seal & paint baseboard - two coats	6.67 LF		0.00	2.24	0.07	2.98	17.99
5,736. Shelving - 12" - in place	6.67 LF		0.00	10.47	2.72	13.96	86.51
5,737. Paint wood shelving, 12"- 24" width - 1 coat	6.67 LF		0.00	4.50	0.23	6.00	36.25
5,738. Mask the floor per square foot - plastic and tape - 4 mil	4.17 SF		0.00	0.35	0.02	0.30	1.78




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Pantry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,739. Final cleaning - construction - Residential	4.17 SF		0.00	0.34	0.00	0.28	1.70
Totals: Pantry					18.56	121.14	745.45



### Hallway

Height: 9'

61.19 SF Walls	11.96 SF Ceiling
73.15 SF Walls & Ceiling	11.96 SF Floor
1.33 SY Flooring	5.42 LF Floor Perimeter
10.75 LF Ceil. Perimeter	

Missing Wall

1' 1" X 9'

Opens into LIVING\_\_DIN

Missing Wall

2' 4" X 9'

Opens into KITCHEN

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

2' 8" X 6' 8"


Opens into BEDROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,740. 5/8" drywall - hung, taped, floated, ready for paint	73.15 SF		0.00	2.87	4.93	41.98	256.85
5,741. Batt insulation - 6" - R19 - unfaced batt	61.19 SF		0.00	1.07	3.94	13.10	82.51
5,742. Blown-in insulation - 10" depth - R26	11.96 SF		0.00	1.12	0.90	2.68	16.98
5,743. Seal/prime then paint the walls and ceiling twice (3 coats)	73.15 SF		0.00	1.84	2.06	26.92	163.58
5,744. Baseboard - 4 1/4"	5.42 LF		0.00	4.14	1.10	4.48	28.02
5,745. Seal & paint baseboard - two coats	5.42 LF		0.00	2.24	0.06	2.42	14.62
5,746. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,747. Mask the floor per square foot - plastic and tape - 4 mil	11.96 SF		0.00	0.35	0.06	0.84	5.09
5,748. Final cleaning - construction - Residential	11.96 SF		0.00	0.34	0.00	0.82	4.89
Totals: Hallway					16.37	107.06	658.81



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,749. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
5,750. 5/8" drywall - hung, taped, floated, ready for paint	704.18 SF		0.00	2.87	47.42	404.20	2,472.62
5,751. Batt insulation - 6" - R19 - unfaced batt	414.58 SF		0.00	1.07	26.67	88.72	558.99
5,752. Blown-in insulation - 10" depth - R26	289.60 SF		0.00	1.12	21.83	64.88	411.06
5,753. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
5,754. Vinyl plank flooring	289.60 SF		0.00	5.74	87.02	332.46	2,081.78
5,755. Baseboard - 4 1/4"	48.58 LF		0.00	4.14	9.86	40.22	251.20
5,756. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
5,757. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
5,758. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
5,759. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
5,760. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
5,761. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,762. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	18.80	0.00	7.52	45.12
5,763. Smoke detector	1.00 EA		0.00	60.60	2.82	12.12	75.54
5,764. French double doors - Exterior - pre-hung unit	1.00 EA		0.00	1,359.90	117.82	271.98	1,749.70
5,765. Window sill	6.00 LF		0.00	3.12	0.55	3.74	23.01
5,766. Seal & paint window sill	4.00 LF		0.00	3.82	0.10	3.06	18.44



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267


### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,767. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
5,768. Track lighting - track only	8.00 LF		0.00	21.78	4.32	34.84	213.40
5,769. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
5,770. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					362.14	1,746.20	10,839.27
Total: 10211					<b>1,904.20</b>	<b>8,282.00</b>	<b>51,596.02</b>

### 10212

#### Kitchen

Height: 8'



293.44 SF Walls	107.91 SF Ceiling
401.35 SF Walls & Ceiling	107.91 SF Floor
11.99 SY Flooring	40.17 LF Floor Perimeter
40.42 LF Ceil. Perimeter	


Missing Wall - Goes to Ceiling	2' 2" X 4'	Opens into LIVING__DIN
Missing Wall	8' 2" X 8'	Opens into LIVING__DIN
Door	3' X 6' 8"	Opens into Exterior
Door	1' 8" X 6' 8"	Opens into CLOSET
Door	4' X 6' 8"	Opens into UTILITY_ROOM
Missing Wall	2' X 8'	Opens into ROOM3
Door	2' 2" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to Ceiling	8' 5" X 4'	Opens into LIVING__DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,771. Paint the walls - two coats	293.44 SF		0.00	1.36	6.49	79.82	485.39
5,772. Seal & paint baseboard - two coats	40.17 LF		0.00	2.24	0.44	18.00	108.42
5,773. Mask the floor per square foot - plastic and tape - 4 mil	107.91 SF		0.00	0.35	0.54	7.56	45.87
5,774. Final cleaning - construction - Residential	107.91 SF		0.00	0.34	0.00	7.34	44.03
Totals: Kitchen					7.47	112.72	683.71



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**


**Height: 8'**

394.22 SF Walls	294.17 SF Ceiling
688.39 SF Walls & Ceiling	294.17 SF Floor
32.69 SY Flooring	60.08 LF Floor Perimeter
50.08 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 4" X 8'</b>	<b>Opens into ROOM2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 9" X 4'</b>	<b>Opens into ROOM2</b>
<b>Missing Wall</b>	<b>8' 2" X 8'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>8' 11" X 4'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' 1" X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>3' 9" X 8'</b>	<b>Opens into ROOM2</b>

**Subroom: Room3 (1)**

**Height: 8'**



49.33 SF Walls	4.33 SF Ceiling
53.67 SF Walls & Ceiling	4.33 SF Floor
0.48 SY Flooring	6.17 LF Floor Perimeter
6.17 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>5' 8" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>2' X 8'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,775. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	8.00 SF		0.00	2.87	0.54	4.60	28.10
5,776. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	8.00 SF		0.00	1.07	0.51	1.72	10.79
5,777. Paint the walls - two coats <i>Wall</i>	443.56 SF		0.00	1.36	9.81	120.64	733.69
5,778. Baseboard - 4 1/4"	66.25 LF		0.00	4.14	13.45	54.86	342.59
5,779. Base shoe	4.00 LF		0.00	1.41	0.20	1.12	6.96
5,780. Seal & paint baseboard - two coats	66.25 LF		0.00	2.24	0.73	29.68	178.81




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,781. Seal & paint base shoe or quarter round	66.25 LF		0.00	1.19	0.73	15.76	95.33
5,782. Mask the floor per square foot - plastic and tape - 4 mil	298.50 SF		0.00	0.35	1.50	20.90	126.88
5,783. Final cleaning - construction - Residential	298.50 SF		0.00	0.34	0.00	20.30	121.79
Totals: Living / Dining Room					27.47	269.58	1,644.94



### Bathroom

**Height: 8'**

221.16 SF Walls	58.09 SF Ceiling
279.24 SF Walls & Ceiling	58.09 SF Floor
6.45 SY Flooring	26.78 LF Floor Perimeter
31.95 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,784. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11
5,785. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	10.00 SF		0.00	1.07	0.64	2.14	13.48
5,786. Baseboard - 4 1/4"	26.78 LF		0.00	4.14	5.44	22.18	138.49
5,787. Seal & paint baseboard - two coats	26.78 LF		0.00	2.24	0.30	12.00	72.29
5,788. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	279.24 SF		0.00	1.84	7.86	102.76	624.42
5,789. Mask the floor per square foot - plastic and tape - 4 mil	58.09 SF		0.00	0.35	0.29	4.06	24.68
5,790. Final cleaning - construction - Residential	58.09 SF		0.00	0.34	0.00	3.96	23.71
Totals: Bathroom					15.20	152.84	932.18



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Stairs**


**Height: 16' 9"**

321.69 SF Walls	39.00 SF Ceiling
360.69 SF Walls & Ceiling	66.86 SF Floor
7.43 SY Flooring	30.66 LF Floor Perimeter
26.00 LF Ceil. Perimeter	

Missing Wall

**3' X 16' 8 15/16"**

**Opens into Exterior**



**Subroom: Stairs (1)**

**Height: 8'**

78.67 SF Walls	10.25 SF Ceiling
88.92 SF Walls & Ceiling	10.25 SF Floor
1.14 SY Flooring	9.83 LF Floor Perimeter
9.83 LF Ceil. Perimeter	

Missing Wall

**3' X 8'**

**Opens into STAIRS**

Door

**3' X 6' 8"**

**Opens into GARAGE**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,791. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls (landing)</i>	28.00 SF		0.00	2.87	1.89	16.08	98.33
5,792. Baseboard - 4 1/4"	40.49 LF		0.00	4.14	8.22	33.52	209.37
5,793. Seal & paint baseboard - two coats	40.49 LF		0.00	2.24	0.45	18.14	109.29
5,794. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall Staircase</i>	449.61 SF		0.00	1.84	12.65	165.46	1,005.39
5,795. Mask the floor per square foot - plastic and tape - 4 mil	77.11 SF		0.00	0.35	0.39	5.40	32.78
5,796. Final cleaning - construction - Residential	77.11 SF		0.00	0.34	0.00	5.24	31.46
<b>Totals: Stairs</b>					23.60	243.84	1,486.62
<b>Total: 10212</b>					<b>73.74</b>	<b>778.98</b>	<b>4,747.45</b>

**10214**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 8'**

278.00 SF Walls  
388.63 SF Walls & Ceiling  
12.29 SY Flooring  
42.17 LF Ceil. Perimeter

110.63 SF Ceiling  
110.63 SF Floor  
35.67 LF Floor Perimeter


**Door** 4' X 6' 8" Opens into **BEDROOM\_CLOS**  
**Door** 2' 6" X 6' 8" Opens into **LIVING\_ROOM**  
**Window** 4' X 4' Opens into **Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,797. 5/8" drywall - hung, taped, floated, ready for paint	254.63 SF		0.00	2.87	17.15	146.16	894.10
<i>Ceiling</i>							
5,798. Blown-in insulation - 10" depth - R26	110.63 SF		0.00	1.12	8.34	24.78	157.03
<i>Ceiling</i>							
5,799. Seal/prime then paint the walls and ceiling twice (3 coats)	388.63 SF		0.00	1.84	10.94	143.02	869.04
5,800. Baseboard - 4 1/4"	35.67 LF		0.00	4.14	7.24	29.54	184.45
5,801. Seal & paint baseboard - two coats	35.67 LF		0.00	2.24	0.39	15.98	96.27
5,802. Mask the floor per square foot - plastic and tape - 4 mil	110.63 SF		0.00	0.35	0.56	7.74	47.02
5,803. Final cleaning - construction - Residential	110.63 SF		0.00	0.34	0.00	7.52	45.13
<b>Totals: Bedroom</b>					44.62	374.74	2,293.04



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen / Dining

**Height: 8'**

413.33 SF Walls	217.96 SF Ceiling
631.29 SF Walls & Ceiling	214.90 SF Floor
23.88 SY Flooring	58.56 LF Floor Perimeter
53.56 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into LIVING_ROOM</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>6' 11" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 7" X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,804. Paint the walls and ceiling - two coats	631.29 SF		0.00	1.36	13.96	171.72	1,044.23
5,805. Seal & paint baseboard - two coats	58.56 LF		0.00	2.24	0.65	26.24	158.06
5,806. Mask the floor per square foot - plastic and tape - 4 mil	214.90 SF		0.00	0.35	1.08	15.04	91.34
5,807. Final cleaning - construction - Residential	214.90 SF		0.00	0.34	0.00	14.62	87.69
<b>Totals: Kitchen / Dining</b>					<b>15.69</b>	<b>227.62</b>	<b>1,381.32</b>



### Bathroom

**Height: 8'**

287.00 SF Walls	65.56 SF Ceiling
352.56 SF Walls & Ceiling	65.56 SF Floor
7.28 SY Flooring	35.08 LF Floor Perimeter
39.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>
<b>Door</b>	<b>2' 5" X 6' 8"</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,808. Vinyl tile	65.56 SF		0.00	3.93	14.36	51.54	323.55
5,809. Baseboard - 4 1/4"	35.08 LF		0.00	4.14	7.12	29.04	181.39
5,810. Seal & paint baseboard - two coats	35.08 LF		0.00	2.24	0.39	15.72	94.69




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,811. Mask the floor per square foot - plastic and tape - 4 mil	65.56 SF		0.00	0.35	0.33	4.60	27.88
5,812. Final cleaning - construction - Residential	65.56 SF		0.00	0.34	0.00	4.46	26.75
Totals: Bathroom					22.20	105.36	654.26



### Living Room

Height: 8'

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,813. Vinyl plank flooring	141.03 SF		0.00	5.74	42.38	161.90	1,013.79
5,814. Baseboard - 4 1/4"	29.50 LF		0.00	4.14	5.99	24.42	152.54
5,815. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
5,816. Mask the floor per square foot - plastic and tape - 4 mil	141.03 SF		0.00	0.35	0.71	9.88	59.95
5,817. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
Totals: Living Room					49.41	219.02	1,363.46


Total: 10214 131.92 926.74 5,692.08

10301



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,818. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
<i>Ceiling</i>							
5,819. Blown-in insulation - 10" depth - R26	486.47 SF		0.00	1.12	36.67	108.98	690.50
<i>Ceiling</i>							
5,820. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
5,821. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
5,822. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>77.03</b>	<b>666.70</b>	<b>4,077.07</b>
<b>Total: 10301</b>					<b>77.03</b>	<b>666.70</b>	<b>4,077.07</b>

10311



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Closet

**Height: 9'**


198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

DESCRIPTION	QTY	2' 8" X 6' 8"		Opens into BATHROOM			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P	
5,823. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,824. 5/8" drywall - hung, taped, floated, ready for paint	235.72 SF		0.00	2.87	15.87	135.30	827.69
5,825. Batt insulation - 6" - R19 - unfaced batt	198.76 SF		0.00	1.07	12.78	42.54	267.99
5,826. Blown-in insulation - 10" depth - R26	36.97 SF		0.00	1.12	2.79	8.28	52.48
5,827. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
5,828. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,829. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
5,830. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,831. Baseboard - 4 1/4"	21.39 LF		0.00	4.14	4.34	17.72	110.61
5,832. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
5,833. Shelving - wire (vinyl coated)	21.39 LF		0.00	10.99	8.26	47.02	290.36
5,834. Carpet	42.51 SF		0.00	3.67	11.49	31.20	198.70
<i>15 % waste added for Carpet.</i>							
5,835. Carpet pad	36.97 SF		0.00	0.63	1.82	4.66	29.77
5,836. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,837. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71
5,838. R&R Light weight, gypsum concrete - 1 1/2" thick	36.97 SF		4.14	4.41	11.89	63.22	391.21
5,839. R&R Underlayment - 5/8" OSB	36.97 SF		0.83	2.21	4.83	22.48	139.70
5,840. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
<b>Totals: Closet</b>					<b>108.59</b>	<b>569.18</b>	<b>3,523.58</b>



### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY2**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DI2**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,841. 5/8" drywall - hung, taped, floated, ready for paint	472.34 SF		0.00	2.87	31.81	271.12	1,658.55
5,842. Batt insulation - 6" - R19 - unfaced batt	356.25 SF		0.00	1.07	22.91	76.24	480.34
5,843. Blown-in insulation - 10" depth - R26	116.09 SF		0.00	1.12	8.75	26.00	164.77
5,844. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
5,845. Range - gas - Remove & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
5,846. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
5,847. Garbage disposer - Detach & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
5,848. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
5,849. Sink - double - Detach & reset	1.00 EA		0.00	171.64	0.07	34.32	206.03
5,850. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
5,851. P-trap assembly - Detach & reset	1.00 EA		0.00	63.96	0.00	12.80	76.76
5,852. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
5,853. Cabinetry - lower (base) units	17.00 LF		0.00	219.33	304.51	745.72	4,778.84
5,854. Cabinetry - upper (wall) units	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
5,855. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
5,856. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,857. Countertop - solid surface	30.00 SF		0.00	64.30	134.77	385.80	2,449.57
5,858. Countertop subdeck - plywood	30.00 SF		0.00	3.70	5.25	22.20	138.45
5,859. Baseboard - 4 1/4"	53.92 LF		0.00	4.14	10.95	44.64	278.82




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,860. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
5,861. Vinyl plank flooring	111.67 SF		0.00	5.74	33.56	128.20	802.75
5,862. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
5,863. R&R Light weight, gypsum concrete - 1 1/2" thick	111.67 SF		4.14	4.41	35.91	190.96	1,181.64
5,864. R&R Underlayment - 5/8" OSB	111.67 SF		0.83	2.21	14.59	67.90	421.97
5,865. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					739.37	2,739.62	17,176.98



### Bathroom

Height: 9'

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Door				2' 8" X 6' 8"			Opens into CLOSET2
Door				2' 8" X 6' 8"			Opens into HALLWAY2
5,866. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,867. 5/8" drywall - hung, taped, floated, ready for paint	335.92 SF		0.00	2.87	22.62	192.82	1,179.53
5,868. Batt insulation - 6" - R19 - unfaced batt	271.97 SF		0.00	1.07	17.49	58.20	366.70
5,869. Blown-in insulation - 10" depth - R26	63.94 SF		0.00	1.12	4.82	14.32	90.75
5,870. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16
5,871. Fiberglass tub & shower combination	1.00 EA		0.00	1,109.55	56.90	221.92	1,388.37
5,872. Tub/shower faucet	1.00 EA		0.00	315.61	14.07	63.12	392.80
5,873. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
5,874. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
5,875. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,876. Bathroom ventilation fan - Detach & reset	1.00 EA		0.00	55.29	0.00	11.06	66.35




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,877. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
5,878. Mirror - 1/4" plate glass	18.00 SF		0.00	16.85	21.35	60.66	385.31
5,879. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
5,880. Baseboard - 4 1/4"	28.84 LF		0.00	4.14	5.86	23.88	149.14
5,881. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,882. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
5,883. Seal & paint baseboard - two coats	28.84 LF		0.00	2.24	0.32	12.92	77.84
5,884. Vinyl plank flooring	63.94 SF		0.00	5.74	19.21	73.40	459.63
5,885. Sink - single	1.00 EA		0.00	274.65	15.92	54.94	345.51
5,886. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
5,887. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
5,888. Mask the floor per square foot - plastic and tape - 4 mil	63.94 SF		0.00	0.35	0.32	4.48	27.18
5,889. R&R Light weight, gypsum concrete - 1 1/2" thick	63.94 SF		4.14	4.41	20.56	109.34	676.59
5,890. R&R Underlayment - 5/8" OSB	63.94 SF		0.83	2.21	8.35	38.88	241.61
5,891. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
<b>Totals: Bathroom</b>					<b>425.41</b>	<b>1,705.86</b>	<b>10,660.41</b>



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

### Window

4' X 4'

Opens into Exterior

### Door

2' 8" X 6' 8"

Opens into HALLWAY2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,892. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
5,893. 5/8" drywall - hung, taped, floated, ready for paint	505.07 SF		0.00	2.87	34.01	289.92	1,773.48
5,894. Batt insulation - 6" - R19 - unfaced batt	375.72 SF		0.00	1.07	24.17	80.40	506.59




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,895. Blown-in insulation - 10" depth - R26	129.35 SF		0.00	1.12	9.75	28.98	183.60
5,896. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
5,897. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
5,898. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
5,899. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,900. Baseboard - 4 1/4"	42.83 LF		0.00	4.14	8.70	35.46	221.48
5,901. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
5,902. Carpet	148.75 SF		0.00	3.67	40.21	109.18	695.30
15 % waste added for Carpet.							
5,903. Carpet pad	129.35 SF		0.00	0.63	6.37	16.30	104.16
5,904. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,905. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
5,906. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
5,907. R&R Light weight, gypsum concrete - 1 1/2" thick	129.35 SF		4.14	4.41	41.60	221.18	1,368.72
5,908. R&R Underlayment - 5/8" OSB	129.35 SF		0.83	2.21	16.90	78.66	488.78
5,909. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					<b>233.99</b>	<b>1,233.12</b>	<b>7,632.53</b>



### Entry

Height: 9'

124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into LIVING__DI2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,910. 5/8" drywall - hung, taped, floated, ready for paint	152.83 SF		0.00	2.87	10.29	87.72	536.63
5,911. Batt insulation - 6" - R19 - unfaced batt	124.25 SF		0.00	1.07	7.99	26.60	167.54
5,912. Blown-in insulation - 10" depth - R26	28.58 SF		0.00	1.12	2.15	6.40	40.56
5,913. Steel door, 3' x 7' - fire rated	1.00 EA		0.00	567.29	51.51	113.46	732.26
5,914. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,915. Baseboard - 4 1/4"	12.25 LF		0.00	4.14	2.49	10.14	63.35
5,916. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
5,917. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
5,918. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
5,919. Seal/prime then paint the walls and ceiling twice (3 coats)	152.83 SF		0.00	1.84	4.30	56.24	341.75
5,920. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
5,921. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
5,922. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
5,923. R&R Light weight, gypsum concrete - 1 1/2" thick	28.58 SF		4.14	4.41	9.19	48.86	302.41
5,924. R&R Underlayment - 5/8" OSB	28.58 SF		0.83	2.21	3.73	17.38	107.99
5,925. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					104.37	442.92	2,762.04



### Utility Room

Height: 9'

322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,926. 5/8" drywall - hung, taped, floated, ready for paint	368.15 SF		0.00	2.87	24.79	211.32	1,292.70
5,927. Batt insulation - 6" - R19 - unfaced batt	322.00 SF		0.00	1.07	20.71	68.90	434.15




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,928. Batt insulation - 10" - R30 - unfaced batt	46.15 SF		0.00	1.57	4.78	14.50	91.74
5,929. Seal/prime then paint the walls and ceiling twice (3 coats)	368.15 SF		0.00	1.84	10.36	135.48	823.24
5,930. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37
5,931. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
5,932. Baseboard - 4 1/4"	35.00 LF		0.00	4.14	7.11	28.98	180.99
5,933. Seal & paint baseboard - two coats	35.00 LF		0.00	2.24	0.39	15.68	94.47
5,934. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,935. Mask the floor per square foot - plastic and tape - 4 mil	46.15 SF		0.00	0.35	0.23	3.24	19.62
5,936. R&R Light weight, gypsum concrete - 1 1/2" thick	46.15 SF		4.14	4.41	14.84	78.92	488.34
5,937. R&R Underlayment - 5/8" OSB	46.15 SF		0.83	2.21	6.03	28.06	174.38
5,938. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83
Totals: Utility Room					92.56	618.68	3,804.55



### Pantry

Height: 9'

63.50 SF Walls	4.17 SF Ceiling
67.67 SF Walls & Ceiling	4.17 SF Floor
0.46 SY Flooring	6.67 LF Floor Perimeter
8.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,939. 5/8" drywall - hung, taped, floated, ready for paint	67.67 SF		0.00	2.87	4.56	38.84	237.61
5,940. Batt insulation - 6" - R19 - unfaced batt	63.50 SF		0.00	1.07	4.08	13.60	85.63
5,941. Blown-in insulation - 10" depth - R26	4.17 SF		0.00	1.12	0.31	0.94	5.92
5,942. Seal/prime then paint the walls and ceiling twice (3 coats)	67.67 SF		0.00	1.84	1.90	24.90	151.31
5,943. Baseboard - 4 1/4"	6.67 LF		0.00	4.14	1.35	5.52	34.48
5,944. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27

1' 6" X 6' 8"

Opens into KITCHEN




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Pantry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,945. Seal & paint baseboard - two coats	6.67 LF		0.00	2.24	0.07	2.98	17.99
5,946. Shelving - 12" - in place	6.67 LF		0.00	10.47	2.72	13.96	86.51
5,947. Seal & paint wood shelving, 12"- 24" width	6.67 LF		0.00	6.68	0.32	8.92	53.80
5,948. Mask the floor per square foot - plastic and tape - 4 mil	4.17 SF		0.00	0.35	0.02	0.30	1.78
5,949. R&R Light weight, gypsum concrete - 1 1/2" thick	4.17 SF		4.14	4.41	1.34	7.14	44.13
5,950. R&R Underlayment - 5/8" OSB	4.17 SF		0.83	2.21	0.54	2.54	15.76
5,951. Final cleaning - construction - Residential	4.17 SF		0.00	0.34	0.00	0.28	1.70
<b>Totals: Pantry</b>					<b>20.53</b>	<b>133.74</b>	<b>822.89</b>



### Hallway

**Height: 9'**

61.19 SF Walls	11.96 SF Ceiling
73.15 SF Walls & Ceiling	11.96 SF Floor
1.33 SY Flooring	5.42 LF Floor Perimeter
10.75 LF Ceil. Perimeter	

**Missing Wall**

**1' 1" X 9'**

**Opens into LIVING \_\_DI2**

**Missing Wall**

**2' 4" X 9'**

**Opens into KITCHEN**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**2' 8" X 6' 8"**

**Opens into BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,952. 5/8" drywall - hung, taped, floated, ready for paint	73.15 SF		0.00	2.87	4.93	41.98	256.85
5,953. Batt insulation - 6" - R19 - unfaced batt	61.19 SF		0.00	1.07	3.94	13.10	82.51
5,954. Blown-in insulation - 10" depth - R26	11.96 SF		0.00	1.12	0.90	2.68	16.98
5,955. Seal/prime then paint the walls and ceiling twice (3 coats)	73.15 SF		0.00	1.84	2.06	26.92	163.58
5,956. Baseboard - 4 1/4"	5.42 LF		0.00	4.14	1.10	4.48	28.02
5,957. Seal & paint baseboard - two coats	5.42 LF		0.00	2.24	0.06	2.42	14.62
5,958. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,959. Mask the floor per square foot - plastic and tape - 4 mil	11.96 SF		0.00	0.35	0.06	0.84	5.09




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Hallway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,960. R&R Light weight, gypsum concrete - 1 1/2" thick	11.96 SF		4.14	4.41	3.85	20.44	126.54
5,961. R&R Underlayment - 5/8" OSB	11.96 SF		0.83	2.21	1.56	7.26	45.18
5,962. Final cleaning - construction - Residential	11.96 SF		0.00	0.34	0.00	0.82	4.89
Totals: Hallway					21.78	134.76	830.53



### Living / Dining Room

Height: 9'

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

Missing Wall	12' 7" X 9'	Opens into KITCHEN
Missing Wall	4' 1" X 9'	Opens into ENTRY
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Missing Wall	1' 1" X 9'	Opens into HALLWAY2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,963. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
5,964. 5/8" drywall - hung, taped, floated, ready for paint	704.18 SF		0.00	2.87	47.42	404.20	2,472.62
5,965. Batt insulation - 6" - R19 - unfaced batt	414.58 SF		0.00	1.07	26.67	88.72	558.99
5,966. Batt insulation - 8" - R25 - unfaced batt	289.60 SF		0.00	1.43	23.58	82.82	520.53
5,967. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
5,968. Vinyl plank flooring	289.60 SF		0.00	5.74	87.02	332.46	2,081.78
5,969. Baseboard - 4 1/4"	48.58 LF		0.00	4.14	9.86	40.22	251.20
5,970. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
5,971. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
5,972. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
5,973. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,974. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
5,975. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
5,976. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	18.80	0.00	7.52	45.12
5,977. Smoke detector	1.00 EA		0.00	60.60	2.82	12.12	75.54
5,978. French double doors - Exterior - pre-hung unit	1.00 EA		0.00	1,359.90	117.82	271.98	1,749.70
5,979. Window sill	6.00 LF		0.00	3.12	0.55	3.74	23.01
5,980. Seal & paint window sill	4.00 LF		0.00	3.82	0.10	3.06	18.44
5,981. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
5,982. Track lighting - track only	8.00 LF		0.00	21.78	4.32	34.84	213.40
5,983. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
5,984. R&R Light weight, gypsum concrete - 1 1/2" thick	289.60 SF		4.14	4.41	93.14	495.20	3,064.42
5,985. R&R Underlayment - 5/8" OSB	289.60 SF		0.83	2.21	37.84	176.08	1,094.31
5,986. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>494.87</b>	<b>2,435.42</b>	<b>15,107.47</b>
<b>Total: 10311</b>					<b>2,241.47</b>	<b>10,013.30</b>	<b>62,320.98</b>

**10313**



**Bathroom**

**Height: 9'**

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

**Door** 1' 8" X 6' 8" Opens into LINEN\_CLOSET  
**Door** 3' X 6' 8" Opens into ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,987. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
5,988. Batt insulation - 6" - R19 - unfaced batt	20.00 SF		0.00	1.07	1.29	4.28	26.97




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bathroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,989. Seal/prime then paint the walls and ceiling twice (3 coats)	390.74 SF		0.00	1.84	11.00	143.80	873.76
5,990. Detach & Reset Light bar - 2 lights	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
5,991. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
5,992. Detach & Reset Bathroom ventilation fan w/light	1.00 EA	55.29	0.00	0.00	0.00	11.06	66.35
5,993. Clean floor	79.85 SF		0.00	0.54	0.08	8.62	51.82
5,994. Seal & paint baseboard - two coats	33.33 LF		0.00	2.24	0.37	14.94	89.97
5,995. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
5,996. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
5,997. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
<b>Totals: Bathroom</b>					<b>15.86</b>	<b>246.58</b>	<b>1,495.15</b>



**Room2**

**Height: 9'**

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into ROOM2</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into ROOM2</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into ROOM2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Room2**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5,998. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
5,999. Batt insulation - 6" - R19 - unfaced batt	12.00 SF		0.00	1.07	0.77	2.56	16.17
6,000. Seal/prime then paint the walls and ceiling twice (3 coats)	1,397.90 SF		0.00	1.84	39.34	514.42	3,125.90
6,001. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
6,002. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
6,003. Baseboard - 4 1/4"	115.25 LF		0.00	4.14	23.40	95.42	595.96
6,004. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,005. Mask the floor per square foot - plastic and tape - 4 mil	500.67 SF		0.00	0.35	2.52	35.04	212.79
6,006. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27
<b>Totals: Room2</b>					<b>69.02</b>	<b>794.50</b>	<b>4,836.23</b>
<b>Total: 10313</b>					<b>84.88</b>	<b>1,041.08</b>	<b>6,331.38</b>

**10404**



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DIN**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,007. Paint the walls - two coats	356.25 SF		0.00	1.36	7.88	96.90	589.28
6,008. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
6,009. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,010. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					9.04	136.48	827.85



### Bedroom

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

2' 8" X 6' 8"


Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,011. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	22.00 SF		0.00	2.87	1.48	12.62	77.24
6,012. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	18.00 SF		0.00	1.07	1.16	3.86	24.28
6,013. Baseboard - 4 1/4"	42.83 LF		0.00	4.14	8.70	35.46	221.48
6,014. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
6,015. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i> <i>Ceiling</i>	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
6,016. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	129.35 SF		0.00	1.12	9.75	28.98	183.60
6,017. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
6,018. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
Totals: Bedroom					36.42	303.82	1,859.35



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,019. Drywall patch / small repair, ready for paint <i>Wall</i>	1.00 EA		0.00	89.02	0.33	17.80	107.15
6,020. Paint the walls - two coats <i>Wall</i>	414.58 SF		0.00	1.36	9.17	112.76	685.76
6,021. Drywall Installer / Finisher - per hour	0.50 HR		0.00	100.00	0.00	10.00	60.00
6,022. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
6,023. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
6,024. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>10.95</b>	<b>200.30</b>	<b>1,212.80</b>
<b>Total: 10404</b>					<b>56.41</b>	<b>640.60</b>	<b>3,900.00</b>

**10405**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 8'**

345.33 SF Walls  
472.99 SF Walls & Ceiling  
14.18 SY Flooring  
47.67 LF Ceil. Perimeter

127.65 SF Ceiling  
127.65 SF Floor  
44.67 LF Floor Perimeter


**Door** 3' X 6' 8" Opens into LIVING\_\_DIN  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,025. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	88.00 SF		0.00	2.87	5.93	50.52	309.01
6,026. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	127.65 SF		0.00	1.12	9.62	28.60	181.19
6,027. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Wall</i>	472.99 SF		0.00	1.84	13.31	174.06	1,057.67
6,028. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	22.00 SF		0.00	1.07	1.42	4.70	29.66
6,029. Mask the floor per square foot - plastic and tape - 4 mil	127.65 SF		0.00	0.35	0.64	8.94	54.26
6,030. Final cleaning - construction - Residential	127.65 SF		0.00	0.34	0.00	8.68	52.08
<b>Totals: Bedroom</b>					30.92	275.50	1,683.87



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen / Dining

**Height: 8'**

366.78 SF Walls	146.51 SF Ceiling
513.29 SF Walls & Ceiling	144.57 SF Floor
16.06 SY Flooring	52.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 7" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>11' 7" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 10" X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 2" X 4'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,031. Paint the walls and ceiling - two coats	513.29 SF		0.00	1.36	11.35	139.62	849.04
6,032. Seal & paint baseboard - two coats	52.92 LF		0.00	2.24	0.58	23.70	142.82
6,033. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
6,034. Mask the floor per square foot - plastic and tape - 4 mil	144.57 SF		0.00	0.35	0.73	10.12	61.45
6,035. Final cleaning - construction - Residential	144.57 SF		0.00	0.34	0.00	9.84	58.99
<b>Totals: Kitchen / Dining</b>					<b>13.57</b>	<b>201.56</b>	<b>1,222.91</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining

**Height: 8'**

395.33 SF Walls	237.02 SF Ceiling
632.35 SF Walls & Ceiling	237.02 SF Floor
26.34 SY Flooring	50.67 LF Floor Perimeter
62.83 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 11" X 8'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY1</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 10" X 4'</b>	<b>Opens into KITCHEN__DI</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,036. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	42.00 SF		0.00	2.87	2.83	24.10	147.47
6,037. Blown-in insulation - 10" depth - R26	237.02 SF		0.00	1.12	17.87	53.10	336.43
6,038. Seal/prime then paint the walls and ceiling twice (3 coats)	632.35 SF		0.00	1.84	17.79	232.70	1,414.01
6,039. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,040. Crown molding - 3 1/4"	5.00 LF		0.00	4.40	0.83	4.40	27.23
6,041. Paint crown molding - two coats <i>Wall</i>	62.83 LF		0.00	2.24	0.95	28.14	169.83
6,042. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	9.00 SF		0.00	1.07	0.58	1.92	12.13
6,043. Mask the floor per square foot - plastic and tape - 4 mil	237.02 SF		0.00	0.35	1.19	16.60	100.75
6,044. Final cleaning - construction - Residential	237.02 SF		0.00	0.34	0.00	16.12	96.71
<b>Totals: Living / Dining</b>					<b>42.04</b>	<b>413.30</b>	<b>2,521.89</b>
<b>Total: 10405</b>					<b>86.53</b>	<b>890.36</b>	<b>5,428.67</b>

**10408**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

**Missing Wall**

**4' 11" X 9'**


**Opens into BATHROOM**

**Window**

**4' X 4'**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,045. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	50.00 SF		0.00	2.87	3.37	28.70	175.57
6,046. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	42.00 SF		0.00	1.07	2.70	8.98	56.62
6,047. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i> <i>Ceiling</i>	458.96 SF		0.00	1.84	12.92	168.90	1,026.31
6,048. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	121.71 SF		0.00	1.12	9.17	27.26	172.75
6,049. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,050. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
6,051. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
<b>Totals: Bedroom</b>					<b>28.77</b>	<b>286.86</b>	<b>1,749.97</b>



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,052. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
6,053. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
6,054. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
6,055. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					6.89	98.08	595.42



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,056. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	178.00 SF		0.00	2.87	11.99	102.18	625.03
6,057. Paint crown molding - two coats	40.67 LF		0.00	2.24	0.61	18.22	109.93
6,058. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
6,059. Crown molding - 3 1/4" <i>Wall</i>	11.00 LF		0.00	4.40	1.84	9.68	59.92
6,060. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	46.00 SF		0.00	1.07	2.96	9.84	62.02
6,061. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
6,062. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
6,063. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,064. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
6,065. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
Totals: Living Room					46.07	428.52	2,617.26
Total: 10408					<b>81.73</b>	<b>813.46</b>	<b>4,962.65</b>

### 10409



### Bedroom

Height: 8'

345.33 SF Walls	127.65 SF Ceiling
472.99 SF Walls & Ceiling	127.65 SF Floor
14.18 SY Flooring	44.67 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

Door

3' X 6' 8"

Opens into LIVING \_\_\_DIN

Window

4' X 4'

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,066. 5/8" drywall - hung, taped, floated, ready for paint	265.31 SF		0.00	2.87	17.86	152.28	931.58
<i>Ceiling</i>							
6,067. Blown-in insulation - 10" depth - R26	127.65 SF		0.00	1.12	9.62	28.60	181.19
<i>Ceiling</i>							
6,068. Seal/prime then paint the walls and ceiling twice (3 coats)	472.99 SF		0.00	1.84	13.31	174.06	1,057.67
6,069. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,070. Mask the floor per square foot - plastic and tape - 4 mil	127.65 SF		0.00	0.35	0.64	8.94	54.26
6,071. Final cleaning - construction - Residential	127.65 SF		0.00	0.34	0.00	8.68	52.08
Totals: Bedroom					41.43	408.78	2,494.11




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Kitchen / Dining

**Height: 8'**



366.78 SF Walls	146.51 SF Ceiling
513.29 SF Walls & Ceiling	144.57 SF Floor
16.06 SY Flooring	52.92 LF Floor Perimeter
41.50 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 7" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>11' 7" X 8'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 10" X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 2" X 4'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,072. 5/8" drywall - hung, taped, floated, ready for paint	293.03 SF		0.00	2.87	19.73	168.20	1,028.93
<i>Ceiling</i>							
6,073. Blown-in insulation - 10" depth - R26	146.51 SF		0.00	1.12	11.04	32.82	207.95
<i>Ceiling</i>							
6,074. Seal/prime then paint the walls and ceiling twice (3 coats)	513.29 SF		0.00	1.84	14.44	188.90	1,147.79
<i>Ceiling</i>							
6,075. Mask the floor per square foot - plastic and tape - 4 mil	144.57 SF		0.00	0.35	0.73	10.12	61.45
6,076. Final cleaning - construction - Residential	144.57 SF		0.00	0.34	0.00	9.84	58.99
<b>Totals: Kitchen / Dining</b>					<b>45.94</b>	<b>409.88</b>	<b>2,505.11</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining**

**Height: 8'**

395.33 SF Walls	237.02 SF Ceiling
632.35 SF Walls & Ceiling	237.02 SF Floor
26.34 SY Flooring	50.67 LF Floor Perimeter
62.83 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>11' 11" X 8'</b>	<b>Opens into KITCHEN__DI</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY1</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 10" X 4'</b>	<b>Opens into KITCHEN__DI</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,077. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	489.04 SF		0.00	2.87	32.93	280.70	1,717.17
6,078. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	237.02 SF		0.00	1.12	17.87	53.10	336.43
6,079. Seal/prime then paint the walls and ceiling twice (3 coats)	632.35 SF		0.00	1.84	17.79	232.70	1,414.01
6,080. Crown molding - 3 1/4"	62.83 LF		0.00	4.40	10.48	55.30	342.23
6,081. Paint crown molding - two coats	62.83 LF		0.00	2.24	0.95	28.14	169.83
6,082. Mask the floor per square foot - plastic and tape - 4 mil	237.02 SF		0.00	0.35	1.19	16.60	100.75
6,083. Final cleaning - construction - Residential	237.02 SF		0.00	0.34	0.00	16.12	96.71
<b>Totals: Living / Dining</b>					<b>81.21</b>	<b>682.66</b>	<b>4,177.13</b>
<b>Total: 10409</b>					<b>168.58</b>	<b>1,501.32</b>	<b>9,176.35</b>

**10411**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Closet

Height: 9'


198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

DESCRIPTION	QTY	2' 8" X 6' 8"		Opens into BATHROOM			TOTAL	
		RESET	REMOVE	REPLACE	TAX	O&P		
6,084. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05	
6,085. 5/8" drywall - hung, taped, floated, ready for paint	235.72 SF		0.00	2.87	15.87	135.30	827.69	
6,086. Batt insulation - 6" - R19 - unfaced batt	198.76 SF		0.00	1.07	12.78	42.54	267.99	
6,087. Blown-in insulation - 10" depth - R26	36.97 SF		0.00	1.12	2.79	8.28	52.48	
6,088. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09	
6,089. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97	
6,090. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54	
6,091. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62	
6,092. Baseboard - 4 1/4"	21.39 LF		0.00	4.14	4.34	17.72	110.61	
6,093. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73	
6,094. Shelving - wire (vinyl coated)	21.39 LF		0.00	10.99	8.26	47.02	290.36	
6,095. Carpet	42.51 SF		0.00	3.67	11.49	31.20	198.70	
<i>15 % waste added for Carpet.</i>								
6,096. Carpet pad	36.97 SF		0.00	0.63	1.82	4.66	29.77	
6,097. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27	
6,098. Mask the floor per square foot - plastic and tape - 4 mil	36.97 SF		0.00	0.35	0.19	2.58	15.71	
6,099. R&R Light weight, gypsum concrete - 1 1/2" thick	36.97 SF		4.14	4.41	11.89	63.22	391.21	
6,100. R&R Underlayment - 5/8" OSB	36.97 SF		0.83	2.21	4.83	22.48	139.70	
6,101. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09	
<b>Totals: Closet</b>						<b>108.59</b>	<b>569.18</b>	<b>3,523.58</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,102. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
6,103. Trash compactor - Remove & reset	1.00 EA		0.00	101.95	0.00	20.40	122.35
6,104. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
6,105. Sink - double - Detach & reset	1.00 EA		0.00	171.64	0.07	34.32	206.03
6,106. Install Sink faucet - Kitchen	1.00 EA		0.00	83.42	0.00	16.68	100.10
6,107. P-trap assembly - Detach & reset	1.00 EA		0.00	63.96	0.00	12.80	76.76
6,108. Detach & Reset Microwave oven - over range w/built-in hood	1.00 EA	118.90	0.00	0.00	0.00	23.78	142.68
6,109. Cabinetry - lower (base) units	17.00 LF		0.00	219.33	304.51	745.72	4,778.84
6,110. Cabinetry - upper (wall) units	10.00 LF		0.00	152.53	111.99	305.06	1,942.35
6,111. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
6,112. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,113. Countertop - solid surface	30.00 SF		0.00	64.30	134.77	385.80	2,449.57
6,114. Countertop subdeck - plywood	30.00 SF		0.00	3.70	5.25	22.20	138.45
6,115. 5/8" drywall - hung, taped, floated, ready for paint	472.34 SF		0.00	2.87	31.81	271.12	1,658.55
6,116. Batt insulation - 6" - R19 - unfaced batt	356.25 SF		0.00	1.07	22.91	76.24	480.34
6,117. Blown-in insulation - 10" depth - R26	116.09 SF		0.00	1.12	8.75	26.00	164.77
6,118. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22
6,119. Range - gas - Remove & reset	1.00 EA		0.00	171.46	0.00	34.30	205.76
6,120. Baseboard - 4 1/4"	53.92 LF		0.00	4.14	10.95	44.64	278.82




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,121. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
6,122. Vinyl plank flooring	111.67 SF		0.00	5.74	33.56	128.20	802.75
6,123. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
6,124. R&R Light weight, gypsum concrete - 1 1/2" thick	111.67 SF		4.14	4.41	35.91	190.96	1,181.64
6,125. R&R Underlayment - 5/8" OSB	111.67 SF		0.83	2.21	14.59	67.90	421.97
6,126. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
<b>Totals: Kitchen</b>					<b>739.37</b>	<b>2,725.72</b>	<b>17,093.57</b>



### Bathroom

**Height: 9'**

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	

**Door** **2' 8" X 6' 8"** **Opens into CLOSET2**  
**Door** **2' 8" X 6' 8"** **Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,127. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
6,128. 5/8" drywall - hung, taped, floated, ready for paint	335.92 SF		0.00	2.87	22.62	192.82	1,179.53
6,129. Batt insulation - 6" - R19 - unfaced batt	271.97 SF		0.00	1.07	17.49	58.20	366.70
6,130. Blown-in insulation - 10" depth - R26	63.94 SF		0.00	1.12	4.82	14.32	90.75
6,131. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16
6,132. Fiberglass tub & shower combination	1.00 EA		0.00	1,109.55	56.90	221.92	1,388.37
6,133. Tub/shower faucet	1.00 EA		0.00	315.61	14.07	63.12	392.80
6,134. Vanity	6.00 LF		0.00	211.87	102.97	254.24	1,628.43
6,135. Countertop - solid surface	13.50 SF		0.00	64.30	60.65	173.62	1,102.32
6,136. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,137. Exhaust fan	1.00 EA		0.00	197.85	5.11	39.58	242.54
6,138. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,139. Mirror - 1/4" plate glass	9.00 SF		0.00	16.85	10.67	30.34	192.66
6,140. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
6,141. Baseboard - 3 1/4"	28.84 LF		0.00	3.49	4.20	20.14	124.99
6,142. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
6,143. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
6,144. Seal & paint baseboard - two coats	28.84 LF		0.00	2.24	0.32	12.92	77.84
6,145. Vinyl plank flooring	63.94 SF		0.00	5.74	19.21	73.40	459.63
6,146. Sink - single	1.00 EA		0.00	274.65	15.92	54.94	345.51
6,147. P-trap assembly - ABS (plastic)	1.00 EA		0.00	65.04	0.69	13.00	78.73
6,148. Sink faucet - Bathroom	1.00 EA		0.00	216.39	13.36	43.28	273.03
6,149. Mask the floor per square foot - plastic and tape - 4 mil	63.94 SF		0.00	0.35	0.32	4.48	27.18
6,150. R&R Light weight, gypsum concrete - 1 1/2" thick	63.94 SF		4.14	4.41	20.56	109.34	676.59
6,151. R&R Underlayment - 5/8" OSB	63.94 SF		0.83	2.21	8.35	38.88	241.61
6,152. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
<b>Totals: Bathroom</b>					<b>418.92</b>	<b>1,710.94</b>	<b>10,684.31</b>



### Bedroom

**Height: 9'**

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,153. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
6,154. 5/8" drywall - hung, taped, floated, ready for paint	505.07 SF		0.00	2.87	34.01	289.92	1,773.48
6,155. Batt insulation - 6" - R19 - unfaced batt	375.72 SF		0.00	1.07	24.17	80.40	506.59
6,156. Blown-in insulation - 10" depth - R26	129.35 SF		0.00	1.12	9.75	28.98	183.60




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,157. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
6,158. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
6,159. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
6,160. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,161. Baseboard - 3 1/4"	42.83 LF		0.00	3.49	6.24	29.90	185.62
6,162. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
6,163. Carpet	148.75 SF		0.00	3.67	40.21	109.18	695.30
<i>15 % waste added for Carpet.</i>							
6,164. Carpet pad	129.35 SF		0.00	0.63	6.37	16.30	104.16
6,165. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
6,166. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
6,167. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
6,168. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
Totals: Bedroom					160.22	899.08	5,554.57



### Entry

Height: 9'

124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	

Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into UTILITY_ROOM
Missing Wall	4' 1" X 9'	Opens into LIVING__DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,169. 5/8" drywall - hung, taped, floated, ready for paint	152.83 SF		0.00	2.87	10.29	87.72	536.63
6,170. Batt insulation - 6" - R19 - unfaced batt	124.25 SF		0.00	1.07	7.99	26.60	167.54
6,171. Blown-in insulation - 10" depth - R26	28.58 SF		0.00	1.12	2.15	6.40	40.56




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,172. Steel door, 3' x 7' - fire rated	1.00 EA		0.00	567.29	51.51	113.46	732.26
6,173. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,174. Baseboard - 4 1/4"	12.25 LF		0.00	4.14	2.49	10.14	63.35
6,175. Seal & paint baseboard - two coats	12.25 LF		0.00	2.24	0.14	5.48	33.06
6,176. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,177. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,178. Seal/prime then paint the walls and ceiling twice (3 coats)	152.83 SF		0.00	1.84	4.30	56.24	341.75
6,179. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
6,180. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
6,181. Mask the floor per square foot - plastic and tape - 4 mil	28.58 SF		0.00	0.35	0.14	2.00	12.14
6,182. R&R Light weight, gypsum concrete - 1 1/2" thick	28.58 SF		4.14	4.41	9.19	48.86	302.41
6,183. R&R Underlayment - 5/8" OSB	28.58 SF		0.83	2.21	3.73	17.38	107.99
6,184. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
Totals: Entry					104.37	442.92	2,762.04



### Utility Room

Height: 9'

322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

Door	3' X 6' 8"	Opens into ENTRY					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,185. 5/8" drywall - hung, taped, floated, ready for paint	368.15 SF		0.00	2.87	24.79	211.32	1,292.70
6,186. Batt insulation - 6" - R19 - unfaced batt	322.00 SF		0.00	1.07	20.71	68.90	434.15
6,187. Blown-in insulation - 10" depth - R26	46.15 SF		0.00	1.12	3.48	10.34	65.51
6,188. Seal/prime then paint the walls and ceiling twice (3 coats)	368.15 SF		0.00	1.84	10.36	135.48	823.24
6,189. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,190. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
6,191. Baseboard - 4 1/4"	35.00 LF		0.00	4.14	7.11	28.98	180.99
6,192. Seal & paint baseboard - two coats	35.00 LF		0.00	2.24	0.39	15.68	94.47
6,193. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,194. Mask the floor per square foot - plastic and tape - 4 mil	46.15 SF		0.00	0.35	0.23	3.24	19.62
6,195. R&R Light weight, gypsum concrete - 1 1/2" thick	46.15 SF		4.14	4.41	14.84	78.92	488.34
6,196. R&R Underlayment - 5/8" OSB	46.15 SF		0.83	2.21	6.03	28.06	174.38
6,197. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83
Totals: Utility Room					91.26	614.52	3,778.32



### Pantry

Height: 9'

63.50 SF Walls	4.17 SF Ceiling
67.67 SF Walls & Ceiling	4.17 SF Floor
0.46 SY Flooring	6.67 LF Floor Perimeter
8.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,198. 5/8" drywall - hung, taped, floated, ready for paint	67.67 SF		0.00	2.87	4.56	38.84	237.61
6,199. Batt insulation - 6" - R19 - unfaced batt	63.50 SF		0.00	1.07	4.08	13.60	85.63
6,200. Blown-in insulation - 10" depth - R26	4.17 SF		0.00	1.12	0.31	0.94	5.92
6,201. Seal/prime then paint the walls and ceiling twice (3 coats)	67.67 SF		0.00	1.84	1.90	24.90	151.31
6,202. Baseboard - 4 1/4"	6.67 LF		0.00	4.14	1.35	5.52	34.48
6,203. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,204. Seal & paint baseboard - two coats	6.67 LF		0.00	2.24	0.07	2.98	17.99
6,205. Shelving - 12" - in place	6.67 LF		0.00	10.47	2.72	13.96	86.51
6,206. Seal & paint wood shelving, 12"- 24" width	6.67 LF		0.00	6.68	0.32	8.92	53.80
6,207. Mask the floor per square foot - plastic and tape - 4 mil	4.17 SF		0.00	0.35	0.02	0.30	1.78




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Pantry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,208. R&R Light weight, gypsum concrete - 1 1/2" thick	4.17 SF		4.14	4.41	1.34	7.14	44.13
6,209. R&R Underlayment - 5/8" OSB	4.17 SF		0.83	2.21	0.54	2.54	15.76
6,210. Final cleaning - construction - Residential	4.17 SF		0.00	0.34	0.00	0.28	1.70
Totals: Pantry					20.53	133.74	822.89



### Hallway

Height: 9'

61.19 SF Walls	11.96 SF Ceiling
73.15 SF Walls & Ceiling	11.96 SF Floor
1.33 SY Flooring	5.42 LF Floor Perimeter
10.75 LF Ceil. Perimeter	

Missing Wall

1' 1" X 9'

Opens into LIVING \_\_\_ DIN

Missing Wall

2' 4" X 9'

Opens into KITCHEN

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

2' 8" X 6' 8"

Opens into BEDROOM


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,211. 5/8" drywall - hung, taped, floated, ready for paint	73.15 SF		0.00	2.87	4.93	41.98	256.85
6,212. Batt insulation - 6" - R19 - unfaced batt	61.19 SF		0.00	1.07	3.94	13.10	82.51
6,213. Blown-in insulation - 10" depth - R26	11.96 SF		0.00	1.12	0.90	2.68	16.98
6,214. Seal/prime then paint the walls and ceiling twice (3 coats)	73.15 SF		0.00	1.84	2.06	26.92	163.58
6,215. Baseboard - 4 1/4"	5.42 LF		0.00	4.14	1.10	4.48	28.02
6,216. Seal & paint baseboard - two coats	5.42 LF		0.00	2.24	0.06	2.42	14.62
6,217. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,218. Mask the floor per square foot - plastic and tape - 4 mil	11.96 SF		0.00	0.35	0.06	0.84	5.09
6,219. R&R Light weight, gypsum concrete - 1 1/2" thick	11.96 SF		4.14	4.41	3.85	20.44	126.54
6,220. R&R Underlayment - 5/8" OSB	11.96 SF		0.83	2.21	1.56	7.26	45.18
6,221. Final cleaning - construction - Residential	11.96 SF		0.00	0.34	0.00	0.82	4.89

Totals: Hallway 21.78 134.76 830.53



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living / Dining Room**

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,222. Door lockset - exterior	1.00 EA		0.00	50.72	3.07	10.14	63.93
6,223. 5/8" drywall - hung, taped, floated, ready for paint	704.18 SF		0.00	2.87	47.42	404.20	2,472.62
6,224. Batt insulation - 6" - R19 - unfaced batt	414.58 SF		0.00	1.07	26.67	88.72	558.99
6,225. Blown-in insulation - 10" depth - R26	289.60 SF		0.00	1.12	21.83	64.88	411.06
6,226. Seal/prime then paint the walls and ceiling twice (3 coats)	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
6,227. Vinyl plank flooring	289.60 SF		0.00	5.74	87.02	332.46	2,081.78
6,228. Baseboard - 4 1/4"	48.58 LF		0.00	4.14	9.86	40.22	251.20
6,229. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
6,230. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
6,231. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
6,232. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
6,233. Seal & paint crown molding - two coats	52.58 LF		0.00	2.24	0.74	23.56	142.08
6,234. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
6,235. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	18.80	0.00	7.52	45.12
6,236. Smoke detector	1.00 EA		0.00	60.60	2.82	12.12	75.54
6,237. French double doors - Exterior - pre-hung unit	1.00 EA		0.00	1,359.90	117.82	271.98	1,749.70
6,238. Window sill	6.00 LF		0.00	3.12	0.55	3.74	23.01
6,239. Seal & paint window sill	4.00 LF		0.00	3.82	0.10	3.06	18.44



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,240. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
6,241. Track lighting - track only	8.00 LF		0.00	21.78	4.32	34.84	213.40
6,242. Mask the floor per square foot - plastic and tape - 4 mil	289.60 SF		0.00	0.35	1.46	20.28	123.10
6,243. R&R Light weight, gypsum concrete - 1 1/2" thick	289.60 SF		4.14	4.41	93.14	495.20	3,064.42
6,244. R&R Underlayment - 5/8" OSB	289.60 SF		0.83	2.21	37.84	176.08	1,094.31
6,245. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>493.07</b>	<b>2,417.48</b>	<b>14,997.95</b>
<b>Total: 10411</b>					<b>2,158.11</b>	<b>9,648.34</b>	<b>60,047.76</b>

### 10413



### Bathroom

Height: 9'

310.89 SF Walls	79.85 SF Ceiling
390.74 SF Walls & Ceiling	79.85 SF Floor
8.87 SY Flooring	33.33 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into LINEN_CLOSET</b>					
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING_ROOM</b>					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,246. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	54.00 SF		0.00	2.87	3.64	31.00	189.62
6,247. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	79.85 SF		0.00	1.12	6.02	17.88	113.33
6,248. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i> <i>Wall</i>	390.74 SF		0.00	1.84	11.00	143.80	873.76
6,249. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	24.00 SF		0.00	1.07	1.54	5.14	32.36



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,250. Mask the floor per square foot - plastic and tape - 4 mil	79.85 SF		0.00	0.35	0.40	5.60	33.95
6,251. Final cleaning - construction - Residential	79.85 SF		0.00	0.34	0.00	5.44	32.59
Totals: Bathroom					22.60	208.86	1,275.61



### Master Bedroom

Height: 9'

446.61 SF Walls	177.43 SF Ceiling
624.04 SF Walls & Ceiling	177.43 SF Floor
19.71 SY Flooring	50.67 LF Floor Perimeter
53.50 LF Ceil. Perimeter	


<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into MASTER_BATHR</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,252. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	282.00 SF		0.00	2.87	18.99	161.86	990.19
6,253. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	177.43 SF		0.00	1.12	13.37	39.74	251.83
6,254. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	624.04 SF		0.00	1.84	17.56	229.64	1,395.43
6,255. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,256. Mask the floor per square foot - plastic and tape - 4 mil	177.43 SF		0.00	0.35	0.89	12.42	75.41
6,257. Final cleaning - construction - Residential	177.43 SF		0.00	0.34	0.00	12.06	72.39
Totals: Master Bedroom					50.81	491.94	3,002.58



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM
Missing Wall	4' 5" X 9'	Opens into ENTRY
Missing Wall	4' 5" X 9'	Opens into ENTRY
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into BEDROOM
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Door	1' 10" X 6' 8"	Opens into PANTRY
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into LIVING_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into LIVING_ROOM

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,258. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	96.00 SF		0.00	2.87	6.46	55.10	337.08
6,259. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	486.47 SF		0.00	1.12	36.67	108.98	690.50
6,260. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
6,261. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,262. Track for track lighting - Detach & reset	8.00 LF		0.00	9.84	0.00	15.74	94.46
6,263. Mask the floor per square foot - plastic and tape - 4 mil	481.31 SF		0.00	0.35	2.42	33.70	204.58
6,264. Crown molding - 4 1/4"	22.00 LF		0.00	4.86	4.42	21.38	132.72
6,265. Paint crown molding, oversized - one coat	108.42 LF		0.00	1.58	1.31	34.26	206.87
6,266. Seal & paint trim - two coats	108.42 LF		0.00	2.15	1.31	46.62	281.03
6,267. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
6,268. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living Room					89.45	870.32	5,311.30
Total: 10413					<b>162.86</b>	<b>1,571.12</b>	<b>9,589.49</b>

### 10414



### Living Room

**Height: 8'**

232.67 SF Walls	141.03 SF Ceiling
373.69 SF Walls & Ceiling	141.03 SF Floor
15.67 SY Flooring	29.50 LF Floor Perimeter
39.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Missing Wall</b>	<b>15' X 8'</b>	<b>Opens into KITCHEN__DI</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,269. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
6,270. Batt insulation - 4" - R11-unfaced batt	6.00 SF		0.00	0.70	0.22	0.84	5.26
6,271. Casing - 2 1/4"	8.00 LF		0.00	2.23	0.93	3.56	22.33
6,272. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
6,273. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
6,274. Seal & paint baseboard - two coats	29.50 LF		0.00	2.24	0.33	13.22	79.63
6,275. Seal/prime then paint the walls twice (3 coats)	232.67 SF		0.00	1.84	6.55	85.62	520.28
6,276. Final cleaning - construction - Residential	141.03 SF		0.00	0.34	0.00	9.60	57.55
Totals: Living Room					10.11	130.38	792.44



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 8'**

296.67 SF Walls	133.13 SF Ceiling
429.79 SF Walls & Ceiling	133.13 SF Floor
14.79 SY Flooring	37.67 LF Floor Perimeter
46.17 LF Ceil. Perimeter	

#### Window

4' X 4'

Opens into Exterior

#### Door

3' X 6' 8"

Opens into LIVING\_ROOM

#### Door

2' 6" X 6' 8"

Opens into MASTER\_WALK

#### Door

3' X 6' 8"


Opens into MASTER\_BATHR

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,277. 5/8" drywall - hung, taped, floated, ready for paint	20.00 SF		0.00	2.87	1.35	11.48	70.23
6,278. Batt insulation - 4" - R11-unfaced batt	20.00 SF		0.00	0.70	0.74	2.80	17.54
6,279. Baseboard - 4 1/4"	12.00 LF		0.00	4.14	2.44	9.94	62.06
6,280. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
6,281. Seal & paint baseboard - two coats	37.67 LF		0.00	2.24	0.42	16.88	101.68
6,282. Seal/prime then paint the walls twice (3 coats)	296.67 SF		0.00	1.84	8.35	109.18	663.40
6,283. Final cleaning - construction - Residential	133.13 SF		0.00	0.34	0.00	9.06	54.32
Totals: Master Bedroom					13.76	168.48	1,024.54
Total: 10414					23.87	298.86	1,816.98
Total: Building 10 Interiors					9,195.68	45,867.74	284,400.12

### Garage/Storage

#### B10S3

**LxWxH 22' x 10' x 9'**



576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - B10S3

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,284. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
6,285. Paint the walls and ceiling - two coats	796.00 SF		0.00	1.36	17.60	216.52	1,316.68
6,286. Mask the walls per square foot - plastic and tape - 4 mil	576.00 SF		0.00	0.35	2.89	40.32	244.81
6,287. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B10S3					20.82	289.60	1,758.40




### B10G6

LxWxH 22' x 10' x 9'

576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,288. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
6,289. Paint the walls and ceiling - two coats	796.00 SF		0.00	1.36	17.60	216.52	1,316.68
6,290. Mask the walls per square foot - plastic and tape - 4 mil	576.00 SF		0.00	0.35	2.89	40.32	244.81
6,291. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B10G6					20.82	289.60	1,758.40



### B10G7

LxWxH 22' x 10' x 9'

576.00 SF Walls	220.00 SF Ceiling
796.00 SF Walls & Ceiling	220.00 SF Floor
24.44 SY Flooring	64.00 LF Floor Perimeter
198.00 SF Long Wall	90.00 SF Short Wall
64.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,292. R&R Fluorescent - four tube - 4' - strip light	1.00 EA		17.52	113.24	6.43	26.14	163.33



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - B10G7

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,293. 5/8" drywall - hung, taped, floated, ready for paint	120.00 SF		0.00	2.87	8.08	68.88	421.36
6,294. Paint the walls and ceiling - two coats	796.00 SF		0.00	1.36	17.60	216.52	1,316.68
6,295. Mask the walls per square foot - plastic and tape - 4 mil	576.00 SF		0.00	0.35	2.89	40.32	244.81
6,296. Final cleaning - construction - Residential	220.00 SF		0.00	0.34	0.00	14.96	89.76
Totals: B10G7					35.00	366.82	2,235.94
Total: Garage/Storage					<b>76.64</b>	<b>946.02</b>	<b>5,752.74</b>

### Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
***Ceiling***							
6,297. 5/8" drywall - hung, taped, heavy texture, ready for paint	24.00 SF		0.00	3.35	1.98	16.08	98.46
<i>Double Layer</i>							
6,298. Blown-in insulation - 14" depth - R38	12.00 SF		0.00	1.50	1.33	3.60	22.93
6,299. Paint the surface area - two coats	12.00 SF		0.00	1.35	0.25	3.24	19.69
<i>First Floor</i>							
6,300. Sprinkler head/escutcheon - Detach & reset	16.00 EA		0.00	17.44	0.00	55.80	334.84
<i>First Floor</i>							
6,301. Light fixture - Detach & reset	17.00 EA		0.00	50.85	0.00	172.90	1,037.35
<i>First Floor</i>							
6,302. Ceiling fan - Detach & reset	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
<i>First Floor</i>							
6,303. Exit sign - Detach & reset	6.00 EA		0.00	66.10	0.00	79.32	475.92
<i>First Floor</i>							
6,304. Heat/AC register - Mechanically attached - Detach & reset	16.00 EA		0.00	18.80	0.00	60.16	360.96
<i>First Floor</i>							
***Walls***							
6,305. 5/8" drywall - hung, taped, heavy texture, ready for paint	54.00 SF		0.00	3.35	4.45	36.18	221.53



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>First Floor</i>							
6,306. Batt insulation - 4" - R15 - paper / foil faced	27.00 SF		0.00	1.32	2.25	7.12	45.01
<i>First Floor</i>							
6,307. Paint the surface area - two coats	27.00 SF		0.00	1.35	0.57	7.30	44.32
<i>First Floor</i>							
6,308. Paint door or window opening - 1 coat (per side)	1.00 EA		0.00	30.60	0.32	6.12	37.04
<i>First Floor</i>							
6,309. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
<i>First Floor</i>							
***Ceiling***							
6,310. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
<i>First Floor</i>							
6,311. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
<i>First Floor</i>							
***Ceiling***							
6,312. 5/8" drywall - hung, taped, heavy texture, ready for paint	120.00 SF		0.00	3.35	9.89	80.40	492.29
<i>Second Floor</i>							
6,313. Blown-in insulation - 14" depth - R38	60.00 SF		0.00	1.50	6.63	18.00	114.63
<i>Second Floor</i>							
6,314. Paint the surface area - two coats	969.30 SF		0.00	1.36	21.43	263.66	1,603.34
<i>Second Floor</i>							
6,315. Sprinkler head/escutcheon - Detach & reset	17.00 EA		0.00	17.44	0.00	59.30	355.78
<i>Second Floor</i>							
6,316. Light fixture - Detach & reset	20.00 EA		0.00	50.85	0.00	203.40	1,220.40
<i>Second Floor</i>							
6,317. Ceiling fan - Detach & reset	4.00 EA		0.00	181.09	0.00	144.88	869.24
<i>Second Floor</i>							
6,318. Exit sign - Detach & reset	5.00 EA		0.00	66.10	0.00	66.10	396.60
<i>Second Floor</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,319. Heat/AC register - Mechanically attached - Detach & reset <i>Second Floor</i> ***Walls***	19.00 EA		0.00	18.80	0.00	71.44	428.64
6,320. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Second Floor</i>	424.00 SF		0.00	3.35	34.94	284.08	1,739.42
6,321. Batt insulation - 4" - R15 - paper / foil faced <i>Second Floor</i>	212.00 SF		0.00	1.32	17.68	55.96	353.48
6,322. Paint the surface area - two coats - 2 colors <i>Second Floor</i>	2,655.04 SF		0.00	1.72	56.03	913.34	5,536.04
6,323. Paint door or window opening - 1 coat (per side) <i>Second Floor</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
6,324. Light fixture - Detach & reset <i>Second Floor</i> ***Ceiling***	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,325. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Third Floor</i>	120.00 SF		0.00	3.35	9.89	80.40	492.29
6,326. Blown-in insulation - 14" depth - R38 <i>Third Floor</i>	60.00 SF		0.00	1.50	6.63	18.00	114.63
6,327. Paint the surface area - two coats <i>Third Floor</i>	484.65 SF		0.00	1.36	10.72	131.82	801.66
6,328. Sprinkler head/escutcheon - Detach & reset <i>Third Floor</i>	17.00 EA		0.00	17.44	0.00	59.30	355.78
6,329. Light fixture - Detach & reset <i>Third Floor</i>	18.00 EA		0.00	50.85	0.00	183.06	1,098.36
6,330. Ceiling fan - Detach & reset <i>Third Floor</i>	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
6,331. Exit sign - Detach & reset <i>Third Floor</i>	5.00 EA		0.00	66.10	0.00	66.10	396.60



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,332. Heat/AC register - Mechanically attached - Detach & reset <i>Third Floor</i>	19.00 EA		0.00	18.80	0.00	71.44	428.64
***Walls***							
6,333. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Third Floor</i>	514.00 SF		0.00	3.35	42.36	344.38	2,108.64
6,334. Batt insulation - 4" - R15 - paper / foil faced <i>Third Floor</i>	257.00 SF		0.00	1.32	21.44	67.84	428.52
6,335. Paint the surface area - two coats <i>Third Floor</i>	2,655.04 SF		0.00	1.36	58.70	722.18	4,391.73
6,336. Paint door or window opening - 1 coat (per side) <i>Third Floor</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
6,337. Light fixture - Detach & reset <i>Third Floor</i>	1.00 EA		0.00	50.85	0.00	10.18	61.03
***Ceiling***							
6,338. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Fourth Floor</i>	150.00 SF		0.00	3.35	12.36	100.50	615.36
6,339. Blown-in insulation - 14" depth - R38 <i>Fourth Floor</i>	75.00 SF		0.00	1.50	8.29	22.50	143.29
6,340. Paint the surface area - two coats <i>Fourth Floor</i>	484.65 SF		0.00	1.36	10.72	131.82	801.66
6,341. Sprinkler head/escutcheon - Detach & reset <i>Fourth Floor</i>	16.00 EA		0.00	17.44	0.00	55.80	334.84
6,342. Light fixture - Detach & reset <i>Fourth Floor</i>	20.00 EA		0.00	50.85	0.00	203.40	1,220.40
6,343. Ceiling fan without light <i>Fourth Floor</i>	6.00 EA		0.00	234.39	52.76	281.26	1,740.36
6,344. Exit sign - Detach & reset <i>Fourth Floor</i>	4.00 EA		0.00	66.10	0.00	52.88	317.28



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Corridor/Breezeway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,345. Heat/AC register - Mechanically attached - Detach & reset <i>Fourth Floor</i> ***Walls***	20.00 EA		0.00	18.80	0.00	75.20	451.20
6,346. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Fourth Floor</i>	90.00 SF		0.00	3.35	7.42	60.30	369.22
6,347. Batt insulation - 4" - R15 - paper / foil faced <i>Fourth Floor</i>	45.00 SF		0.00	1.32	3.75	11.88	75.03
6,348. Paint the surface area - two coats <i>Fourth Floor</i>	7,248.69 SF		0.00	1.36	160.27	1,971.64	11,990.13
6,349. Paint door or window opening - 1 coat (per side) <i>Fourth Floor</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
6,350. Light fixture - Detach & reset <i>Fourth Floor</i>	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,351. Carpenter - General Framer - per hour <i>Labor to install drywall nailers.</i>	40.00 HR		0.00	72.00	0.00	576.00	3,456.00
Totals: Corridor/Breezeway					564.02	8,354.84	50,692.78

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,352. Clean with pressure/chemical spray	39,000. SF 00		0.00	0.43	39.20	3,354.00	20,163.20
6,353. Exterior - paint two coats	39,000. SF 00		0.00	1.58	1,254.24	12,324.00	75,198.24
6,354. Electrician - per hour <i>Labor to detach and reset misc to prep for paint.</i>	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
6,355. Painter - per hour <i>Additional misc labor to prep for paint.</i>	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
6,356. Siding <i>Allowance</i>	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
6,357. R&R Window screen, 1 - 9 SF	43.00 EA		4.74	36.30	135.48	352.94	2,253.14



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,358. R&R Gutter / downspout - aluminum - 7" to 8"	100.00 LF		0.63	17.54	131.86	363.40	2,312.26
<i>100 LF Gutters</i>							
6,359. R&R Light fixture - wall sconce - High grade	10.00 EA		10.49	155.78	120.60	332.54	2,115.84
Totals: Exteriors					1,825.60	20,634.72	125,633.94

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,401. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR						AS INCURRED
6,402. Telehandler/forklift and operator	160.00 HR						AS INCURRED
6,403. Scaffolding	39,000. EA 00		0.00	0.50	783.90	3,900.00	24,183.90
6,404. Commercial Supervision / Project Management - per hour	174.00 HR		0.00	68.91	0.00	2,398.06	14,388.40
6,405. General Laborer - per hour	512.00 HR		0.00	37.61	0.00	3,851.26	23,107.58
6,406. Temporary toilet (per month)	12.00 MO						AS INCURRED
6,407. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
6,408. Hand wash station	6.00 MO						AS INCURRED
6,409. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
6,410. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
6,411. OSHA compliance safety monitor- per hour	HR						AS INCURRED
6,412. Caution tape	500.00 LF		0.00	0.09	0.50	9.00	54.50
6,413. Overhead safety monitor - per hour	HR						AS INCURRED
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
6,414. Taxes, insurance, permits & fees (Bid Item)	1.00 EA						AS INCURRED
6,415. Light bulb - Incand. standard bulb - 1000 hr - mat. only	138.00 EA		0.00	0.79	10.96	21.80	141.78
Totals: GENERAL CONDITIONS					854.86	10,404.86	63,284.10
Total: SAULET-BLDG-10-V5_23					<b>12,516.80</b>	<b>86,208.18</b>	<b>529,763.68</b>




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### SAULET-BLDG-11-V5\_23

#### Building 11 Interiors

#### 11101



#### Room2

Height: 9'

892.06 SF Walls	505.84 SF Ceiling
1,397.90 SF Walls & Ceiling	500.67 SF Floor
55.63 SY Flooring	115.25 LF Floor Perimeter
133.17 LF Ceil. Perimeter	

Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into ROOM3
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM1
Door	3' X 6' 8"	Opens into Exterior
Door	1' 10" X 6' 8"	Opens into PANTRY
Door	3' 1" X 6' 8"	Opens into UTILITY_ROOM
Missing Wall - Goes to neither Floor/Ceiling	3' X 5'	Opens into ROOM3
Missing Wall - Goes to neither Floor/Ceiling	10' 2" X 5'	Opens into ROOM3

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,416. 5/8" drywall - hung, taped, floated, ready for paint	10.00 SF		0.00	2.87	0.67	5.74	35.11
6,417. Seal/prime then paint the walls twice (3 coats)	892.06 SF		0.00	1.84	25.10	328.28	1,994.77
6,418. Baseboard - 4 1/4"	5.00 LF		0.00	4.14	1.02	4.14	25.86
6,419. Seal & paint baseboard - two coats	115.25 LF		0.00	2.24	1.27	51.64	311.07
6,420. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,421. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
6,422. Smoke detector - Detach & reset	2.00 EA		0.00	49.24	0.00	19.70	118.18
6,423. Cold air return cover - Detach & reset	1.00 EA		0.00	25.68	0.00	5.14	30.82
6,424. Heat/AC register - Mechanically attached - Detach & reset	3.00 EA		0.00	18.80	0.00	11.28	67.68
6,425. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
6,426. Paint the walls and ceiling - two coats	1,397.90 SF		0.00	1.36	30.91	380.22	2,312.27




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Room2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,427. Track for track lighting - Detach & reset	3.00 LF		0.00	9.84	0.00	5.90	35.42
6,428. In-wall / In-ceiling speaker - Detach & reset	3.00 EA		0.00	18.44	0.00	11.06	66.38
6,429. Casing - 2 1/4"	14.00 LF		0.00	2.23	1.63	6.24	39.09
6,430. Paint door/window trim & jamb - 2 coats (per side)	8.00 EA		0.00	45.71	3.65	73.14	442.47
6,431. Final cleaning - construction - Residential	500.67 SF		0.00	0.34	0.00	34.04	204.27
<b>Totals: Room2</b>					<b>64.25</b>	<b>979.60</b>	<b>5,941.86</b>
<b>Total: 11101</b>					<b>64.25</b>	<b>979.60</b>	<b>5,941.86</b>

### 11103



#### Living / Dining Room

Height: 8'

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,432. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	34.00 SF		0.00	2.87	2.29	19.52	119.39
6,433. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	34.00 SF		0.00	1.07	2.19	7.28	45.85
6,434. Seal/prime then paint the walls twice (3 coats) <i>Wall</i>	465.11 SF		0.00	1.84	13.09	171.16	1,040.05




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living / Dining Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,435. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,436. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,437. Baseboard - 4 1/4"	25.00 LF		0.00	4.14	5.08	20.70	129.28
6,438. Base shoe	25.00 LF		0.00	1.41	1.26	7.06	43.57
6,439. Seal & paint baseboard - two coats	62.17 LF		0.00	2.24	0.69	27.86	167.81
6,440. Seal & paint base shoe or quarter round	62.17 LF		0.00	1.19	0.69	14.80	89.47
6,441. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
<b>Totals: Living / Dining Room</b>					<b>29.85</b>	<b>308.68</b>	<b>1,881.82</b>



**Kitchen**

**Height: 8'**

230.00 SF Walls	80.06 SF Ceiling
310.06 SF Walls & Ceiling	80.06 SF Floor
8.90 SY Flooring	26.33 LF Floor Perimeter
40.83 LF Ceil. Perimeter	

<b>Door</b>	<b>4' 2" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 6" X 6' 8"</b>	<b>Opens into WORKSPACE___</b>
<b>Door</b>	<b>1' 9" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into LIVING___DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,442. Mask the floor per square foot - plastic and tape - 4 mil	80.06 SF		0.00	0.35	0.40	5.60	34.02
6,443. Paint the walls - two coats	230.00 SF		0.00	1.36	5.09	62.56	380.45
6,444. Seal & paint baseboard - two coats	26.33 LF		0.00	2.24	0.29	11.80	71.07
6,445. Final cleaning - construction - Residential	80.06 SF		0.00	0.34	0.00	5.44	32.66
<b>Totals: Kitchen</b>					<b>5.78</b>	<b>85.40</b>	<b>518.20</b>


<b>Total: 11103</b>					<b>35.63</b>	<b>394.08</b>	<b>2,400.02</b>
---------------------	--	--	--	--	--------------	---------------	-----------------

**11106**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,446. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	10.00 SF		0.00	2.87	0.67	5.74	35.11
6,447. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	10.00 SF		0.00	1.07	0.64	2.14	13.48
6,448. Baseboard - 4 1/4"	56.86 LF		0.00	4.14	11.54	47.08	294.02
6,449. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,450. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	522.56 SF		0.00	1.84	14.71	192.30	1,168.52
6,451. Base shoe	56.86 LF		0.00	1.41	2.86	16.04	99.07
6,452. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
6,453. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>31.68</b>	<b>311.36</b>	<b>1,899.77</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,454. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	26.00 SF		0.00	2.87	1.75	14.92	91.29
6,455. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	26.00 SF		0.00	1.07	1.67	5.56	35.05
6,456. Baseboard - 4 1/4"	68.42 LF		0.00	4.14	13.89	56.66	353.81
6,457. Base shoe	13.00 LF		0.00	1.41	0.65	3.66	22.64
6,458. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
6,459. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
6,460. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,461. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,462. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
6,463. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>53.30</b>	<b>558.04</b>	<b>3,401.54</b>
<b>Total: 11106</b>					<b>84.98</b>	<b>869.40</b>	<b>5,301.31</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

11108



**Closet**

**Height: 9'**


198.76 SF Walls	36.97 SF Ceiling
235.72 SF Walls & Ceiling	36.97 SF Floor
4.11 SY Flooring	21.39 LF Floor Perimeter
24.06 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"			Opens into BATHROOM				
	DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
	6,464. 5/8" drywall - hung, taped, floated, ready for paint	42.00 SF		0.00	2.87	2.83	24.10	147.47
	<i>Wall</i>							
	6,465. Seal/prime then paint the walls and ceiling twice (3 coats)	235.72 SF		0.00	1.84	6.63	86.74	527.09
	<i>Wall</i>							
	6,466. Baseboard - 4 1/4"	21.39 LF		0.00	4.14	4.34	17.72	110.61
	6,467. Seal & paint baseboard - two coats	21.39 LF		0.00	2.24	0.24	9.58	57.73
	6,468. Floor preparation for resilient flooring	36.97 SF		0.00	0.71	0.37	5.26	31.88
	6,469. Vinyl plank flooring	36.97 SF		0.00	5.74	11.11	42.44	265.76
	6,470. Base shoe	21.39 LF		0.00	1.41	1.08	6.04	37.28
	6,471. Seal & paint base shoe or quarter round	21.39 LF		0.00	1.19	0.24	5.10	30.79
	6,472. Final cleaning - construction - Residential	36.97 SF		0.00	0.34	0.00	2.52	15.09
Totals: Closet						26.84	199.50	1,223.70



### Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	


- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DI2**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
6,473. 5/8" drywall - hung, taped, floated, ready for paint	34.00 SF		0.00	2.87	2.29	19.52	119.39	
6,474. Seal/prime then paint the walls and ceiling twice (3 coats)	472.34 SF		0.00	1.84	13.29	173.82	1,056.22	
6,475. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54	
6,476. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46	
6,477. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04	
6,478. Floor preparation for resilient flooring	111.67 SF		0.00	0.71	1.12	15.86	96.27	
6,479. Vinyl plank flooring	111.67 SF		0.00	5.74	33.56	128.20	802.75	
6,480. Base shoe	53.92 LF		0.00	1.41	2.71	15.20	93.94	
6,481. Seal & paint base shoe or quarter round	53.92 LF		0.00	1.19	0.60	12.84	77.60	
6,482. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57	
<b>Totals: Kitchen</b>						<b>54.73</b>	<b>425.36</b>	<b>2,606.78</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bathroom

**Height: 9'**

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	


**Door** **2' 8" X 6' 8"** **Opens into CLOSET2**  
**Door** **2' 8" X 6' 8"** **Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,483. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	28.00 SF		0.00	2.87	1.89	16.08	98.33
6,484. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	28.00 SF		0.00	1.07	1.80	6.00	37.76
6,485. Baseboard - 4 1/4"	28.84 LF		0.00	4.14	5.86	23.88	149.14
6,486. Seal & paint baseboard - two coats	28.84 LF		0.00	2.24	0.32	12.92	77.84
6,487. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16
6,488. Floor preparation for resilient flooring	63.94 SF		0.00	0.71	0.64	9.08	55.12
6,489. Vinyl plank flooring	63.94 SF		0.00	5.74	19.21	73.40	459.63
6,490. Base shoe	28.84 LF		0.00	1.41	1.45	8.14	50.25
6,491. Seal & paint base shoe or quarter round	28.84 LF		0.00	1.19	0.32	6.86	41.50
6,492. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
6,493. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
6,494. Shelving - wire (vinyl coated)	24.67 LF		0.00	10.99	9.52	54.22	334.86
<b>Totals: Bathroom</b>					51.11	390.54	2,394.31



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

375.72 SF Walls  
505.07 SF Walls & Ceiling  
14.37 SY Flooring  
45.50 LF Ceil. Perimeter

129.35 SF Ceiling  
129.35 SF Floor  
42.83 LF Floor Perimeter

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**


**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,495. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	337.00 SF		0.00	2.87	22.69	193.44	1,183.32
6,496. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	78.00 SF		0.00	1.07	5.02	16.70	105.18
6,497. Paint the walls and ceiling - two coats <i>Wall</i>	505.07 SF		0.00	1.36	11.17	137.38	835.45
6,498. Baseboard - 3 1/4"	42.83 LF		0.00	3.49	6.24	29.90	185.62
6,499. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
6,500. Floor preparation for resilient flooring	129.35 SF		0.00	0.71	1.30	18.36	111.50
6,501. Vinyl plank flooring	129.35 SF		0.00	5.74	38.87	148.50	929.84
6,502. Base shoe	42.83 LF		0.00	1.41	2.15	12.08	74.62
6,503. Seal & paint base shoe or quarter round	42.83 LF		0.00	1.19	0.47	10.20	61.64
6,504. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
6,505. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
<b>Totals: Bedroom</b>					101.19	659.40	4,057.47



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

**Height: 9'**

124.25 SF Walls	28.58 SF Ceiling
152.83 SF Walls & Ceiling	28.58 SF Floor
3.18 SY Flooring	12.25 LF Floor Perimeter
18.25 LF Ceil. Perimeter	


<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into LIVING__DI2</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,506. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	84.00 SF		0.00	2.87	5.66	48.22	294.96
6,507. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	28.58 SF		0.00	1.12	2.15	6.40	40.56
6,508. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	152.83 SF		0.00	1.84	4.30	56.24	341.75
6,509. Baseboard - 4 1/4"	12.25 LF		0.00	4.14	2.49	10.14	63.35
6,510. Seal & paint baseboard - two coats <i>Wall</i>	12.25 LF		0.00	2.24	0.14	5.48	33.06
6,511. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	49.00 SF		0.00	1.07	3.15	10.48	66.06
6,512. Floor preparation for resilient flooring	28.58 SF		0.00	0.71	0.29	4.06	24.64
6,513. Vinyl plank flooring	28.58 SF		0.00	5.74	8.59	32.82	205.46
6,514. Base shoe	12.25 LF		0.00	1.41	0.62	3.46	21.35
6,515. Seal & paint base shoe or quarter round	12.25 LF		0.00	1.19	0.14	2.92	17.64
6,516. Final cleaning - construction - Residential	28.58 SF		0.00	0.34	0.00	1.94	11.66
<b>Totals: Entry</b>					<b>27.53</b>	<b>182.16</b>	<b>1,120.49</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Utility Room

**Height: 9'**

322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	3' X 6' 8"			Opens into ENTRY			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
6,517. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	180.00 SF		0.00	2.87	12.12	103.32	632.04	
6,518. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	368.15 SF		0.00	1.84	10.36	135.48	823.24	
6,519. Floor preparation for resilient flooring	46.15 SF		0.00	0.71	0.46	6.56	39.79	
6,520. Vinyl plank flooring	46.15 SF		0.00	5.74	13.87	52.98	331.75	
6,521. Base shoe	35.00 LF		0.00	1.41	1.76	9.88	60.99	
6,522. Seal & paint base shoe or quarter round	35.00 LF		0.00	1.19	0.39	8.34	50.38	
6,523. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83	
Totals: Utility Room						38.96	319.70	1,957.02



### Pantry

**Height: 9'**

63.50 SF Walls	4.17 SF Ceiling
67.67 SF Walls & Ceiling	4.17 SF Floor
0.46 SY Flooring	6.67 LF Floor Perimeter
8.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 6" X 6' 8"			Opens into KITCHEN			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
6,524. Floor preparation for resilient flooring	4.17 SF		0.00	0.71	0.04	0.60	3.60	
6,525. Vinyl plank flooring	4.17 SF		0.00	5.74	1.25	4.78	29.97	
6,526. Base shoe	6.67 LF		0.00	1.41	0.34	1.88	11.62	
6,527. Seal & paint base shoe or quarter round	6.67 LF		0.00	1.19	0.07	1.58	9.59	




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Pantry**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,528. Final cleaning - construction - Residential	4.17 SF		0.00	0.34	0.00	0.28	1.70
Totals: Pantry					1.70	9.12	56.48



**Hallway**

**Height: 9'**

61.19 SF Walls	11.96 SF Ceiling
73.15 SF Walls & Ceiling	11.96 SF Floor
1.33 SY Flooring	5.42 LF Floor Perimeter
10.75 LF Ceil. Perimeter	


<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,529. Floor preparation for resilient flooring	11.96 SF		0.00	0.71	0.12	1.70	10.31
6,530. Vinyl plank flooring	11.96 SF		0.00	5.74	3.59	13.74	85.98
6,531. Base shoe	5.42 LF		0.00	1.41	0.27	1.52	9.43
6,532. Seal & paint base shoe or quarter round	5.42 LF		0.00	1.19	0.06	1.30	7.81
6,533. Final cleaning - construction - Residential	11.96 SF		0.00	0.34	0.00	0.82	4.89
Totals: Hallway					4.04	19.08	118.42



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,534. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	704.18 SF		0.00	2.87	47.42	404.20	2,472.62
6,535. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i> <i>Ceiling</i>	414.58 SF		0.00	1.07	26.67	88.72	558.99
6,536. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	289.60 SF		0.00	1.12	21.83	64.88	411.06
6,537. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls and ceiling</i>	704.18 SF		0.00	1.84	19.82	259.14	1,574.65
6,538. Baseboard - 3 1/4"	48.58 LF		0.00	3.49	7.08	33.90	210.52
6,539. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
6,540. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
6,541. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
6,542. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
6,543. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
6,544. Vinyl plank flooring	289.60 SF		0.00	5.74	87.02	332.46	2,081.78
6,545. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,546. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,547. Window trim set (casing & stop)	30.00 LF		0.00	5.51	7.51	33.06	205.87




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,548. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
6,549. Light fixture	2.00 EA		0.00	69.13	6.63	27.66	172.55
6,550. Floor preparation for resilient flooring	289.60 SF		0.00	0.71	2.91	41.12	249.65
6,551. Trim board - 1" x 2" - installed (pine)	52.58 LF		0.00	2.96	5.97	31.12	192.73
6,552. Seal & paint trim - two coats	52.58 LF		0.00	2.15	0.63	22.62	136.30
6,553. Window stool & apron	7.00 LF		0.00	8.09	2.68	11.32	70.63
6,554. Seal & paint window stool and apron	7.00 LF		0.00	5.93	0.25	8.30	50.06
6,555. Window sill	7.00 LF		0.00	3.12	0.64	4.36	26.84
6,556. Seal & paint window sill	7.00 LF		0.00	3.82	0.17	5.34	32.25
6,557. In-wall / In-ceiling speaker - Detach & reset	1.00 EA		0.00	18.44	0.00	3.68	22.12
6,558. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>255.33</b>	<b>1,539.06</b>	<b>9,489.73</b>
<b>Total: 11108</b>					<b>561.43</b>	<b>3,743.92</b>	<b>23,024.40</b>

### 11109



#### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"

Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,559. 5/8" drywall - hung, taped, floated, ready for paint Wall	58.00 SF		0.00	2.87	3.91	33.30	203.67




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,560. Baseboard - 4 1/4"	11.17 LF		0.00	4.14	2.27	9.24	57.75
6,561. Batt insulation - 6" - R19 - unfaced batt	45.00 SF		0.00	1.07	2.89	9.64	60.68
<i>Wall</i>							
<i>Ceiling</i>							
6,562. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							
6,563. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
<i>Ceiling</i>							
6,564. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
<i>Wall</i>							
6,565. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					16.74	127.56	782.03



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,566. 5/8" drywall - hung, taped, floated, ready for paint	76.00 SF		0.00	2.87	5.12	43.62	266.86
6,567. Blown-in insulation - 10" depth - R26	64.74 SF		0.00	1.12	4.88	14.50	91.89
6,568. Seal/prime then paint the walls and ceiling twice (3 coats)	282.90 SF		0.00	1.84	7.96	104.10	632.60
6,569. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
6,570. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
6,571. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Kitchen**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Kitchen					17.96	197.14	1,200.83



**Utility Room**

**Height: 9'**

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,572. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	123.00 SF		0.00	2.87	8.28	70.60	431.89
6,573. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	160.38 SF		0.00	1.84	4.51	59.02	358.63
6,574. Baseboard - 4 1/4"	16.17 LF		0.00	4.14	3.28	13.38	83.60
6,575. Seal & paint baseboard - two coats	16.17 LF		0.00	2.24	0.18	7.24	43.64
6,576. Batt insulation - 6" - R19 - unfaced batt	123.00 SF		0.00	1.07	7.91	26.32	165.84
6,577. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
Totals: Utility Room					24.16	177.58	1,089.68



**Bathroom**

**Height: 9'**

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Missing Wall</b>	<b>4' 11" X 9'</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,578. 5/8" drywall - hung, taped, floated, ready for paint <i>Above tile surround</i>	20.00 SF		0.00	2.87	1.35	11.48	70.23
6,579. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	20.00 SF		0.00	1.07	1.29	4.28	26.97
6,580. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	423.67 SF		0.00	1.84	11.92	155.92	947.39
6,581. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
<b>Totals: Bathroom</b>					14.56	177.26	1,078.04



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,582. 5/8" drywall - hung, taped, floated, ready for paint	60.00 SF		0.00	2.87	4.04	34.44	210.68
6,583. Batt insulation - 6" - R19 - unfaced batt	60.00 SF		0.00	1.07	3.86	12.84	80.90
6,584. Seal/prime then paint the walls and ceiling twice (3 coats)	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
6,585. Baseboard - 4 1/4"	46.08 LF		0.00	4.14	9.35	38.16	238.28
6,586. Base shoe	7.00 LF		0.00	1.41	0.35	1.98	12.20
6,587. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
6,588. Seal & paint base shoe or quarter round	46.08 LF		0.00	1.19	0.51	10.96	66.31
6,589. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					33.43	323.24	1,972.84




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Total: 11109 106.85 1,002.78 6,123.42

**11110**



**Bedroom**

**Height: 9'**

375.72 SF Walls 129.35 SF Ceiling  
 505.07 SF Walls & Ceiling 129.35 SF Floor  
 14.37 SY Flooring 42.83 LF Floor Perimeter  
 45.50 LF Ceil. Perimeter

**Window**

**4' X 4'**


**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,590. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	35.00 SF		0.00	2.87	2.36	20.10	122.91
6,591. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	22.00 SF		0.00	1.07	1.42	4.70	29.66
6,592. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Wall</i>	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
6,593. Baseboard - 4 1/4"	42.83 LF		0.00	4.14	8.70	35.46	221.48
6,594. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
6,595. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					27.16	274.10	1,671.82



**Utility Room**

**Height: 9'**

322.00 SF Walls 46.15 SF Ceiling  
 368.15 SF Walls & Ceiling 46.15 SF Floor  
 5.13 SY Flooring 35.00 LF Floor Perimeter  
 38.00 LF Ceil. Perimeter

**Door**

**3' X 6' 8"**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,596. 5/8" drywall - hung, taped, floated, ready for paint	32.00 SF		0.00	2.87	2.15	18.36	112.35




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,597. Seal/prime then paint the walls and ceiling twice (3 coats)	368.15 SF		0.00	1.84	10.36	135.48	823.24
6,598. Batt insulation - 6" - R19 - unfaced batt	32.00 SF		0.00	1.07	2.06	6.84	43.14
6,599. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83
Totals: Utility Room					14.57	163.82	997.56



### Kitchen

Height: 9'

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	


Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN
Door	1' 6" X 6' 8"	Opens into PANTRY
Missing Wall	2' 4" X 9'	Opens into HALLWAY
Missing Wall	12' 7" X 9'	Opens into LIVING__DIN
Missing Wall - Goes to Ceiling	7' 7" X 5'	Opens into KITCHEN
Missing Wall - Goes to Ceiling	2' 6" X 5'	Opens into KITCHEN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,600. Paint the walls - two coats	356.25 SF		0.00	1.36	7.88	96.90	589.28
6,601. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
6,602. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
6,603. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
Totals: Kitchen					9.04	136.48	827.85



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,604. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	80.00 SF		0.00	2.87	5.39	45.92	280.91
6,605. Paint the walls - two coats <i>Wall</i>	414.58 SF		0.00	1.36	9.17	112.76	685.76
6,606. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	80.00 SF		0.00	1.07	5.15	17.12	107.87
6,607. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,608. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,609. Baseboard - 3 1/4"	48.58 LF		0.00	3.49	7.08	33.90	210.52
6,610. Base shoe	48.58 LF		0.00	1.41	2.44	13.70	84.64
6,611. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
6,612. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
6,613. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>34.87</b>	<b>297.90</b>	<b>1,822.33</b>
<b>Total: 11110</b>					<b>85.64</b>	<b>872.30</b>	<b>5,319.56</b>

11111



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'


Opens into Exterior

Missing Wall

4' 1" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,614. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
6,615. R&R Batt insulation - 4" - R11-unfaced batt	8.00 SF		0.30	0.70	0.30	1.60	9.90
6,616. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
6,617. Seal/prime then paint the walls twice (3 coats)	371.67 SF		0.00	1.84	10.46	136.78	831.11
6,618. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
6,619. Baseboard - 4 1/4"	3.50 LF		0.00	4.14	0.71	2.90	18.10
6,620. Paint baseboard - two coats	46.08 LF		0.00	2.16	0.60	19.90	120.03
6,621. Casing - 2 1/4"	8.00 LF		0.00	2.23	0.93	3.56	22.33
6,622. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
6,623. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					26.09	345.06	2,096.49



### Bedroom

Height: 9'

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

Missing Wall

4' 11" X 9'

Opens into BATHROOM

Window

4' X 4'

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,624. Seal/prime then paint the walls twice (3 coats)	337.25 SF		0.00	1.84	9.49	124.10	754.13
6,625. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
Totals: Bedroom					9.49	132.38	803.79
Total: 11111					<b>35.58</b>	<b>477.44</b>	<b>2,900.28</b>

### 11112




#### Utility Room

Height: 9'

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,626. 5/8" drywall - hung, taped, floated, ready for paint	33.00 SF		0.00	2.87	2.22	18.94	115.87
<i>Walls</i>							
6,627. Paint the walls and ceiling - two coats	160.38 SF		0.00	1.36	3.55	43.62	265.29
6,628. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
Totals: Utility Room					5.77	63.58	387.24



#### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,629. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	97.00 SF		0.00	2.87	6.53	55.68	340.60
6,630. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
6,631. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
6,632. Detach & Reset Hanging light fixture	2.00 EA	50.85	0.00	0.00	0.00	20.34	122.04
6,633. Detach & Reset Light fixture <i>Walls</i>	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
6,634. Batt insulation - 6" - R19 - unfaced batt	4.00 SF		0.00	1.07	0.26	0.86	5.40
6,635. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					17.93	182.90	1,115.31



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN2**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,636. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	28.00 SF		0.00	2.87	1.89	16.08	98.33
6,637. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	3.00 SF		0.00	1.07	0.19	0.64	4.04
6,638. Baseboard - 3 1/4"	3.00 LF		0.00	3.49	0.44	2.10	13.01



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Entry

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,639. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
<i>Ceiling</i>							
6,640. Blown-in insulation - 10" depth - R26	40.83 SF		0.00	1.12	3.08	9.14	57.95
<i>Ceiling</i>							
6,641. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
6,642. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
<b>Totals: Entry</b>					<b>9.23</b>	<b>78.94</b>	<b>482.85</b>



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN2**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY2**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,643. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
6,644. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
6,645. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74
6,646. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
6,647. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
<b>Totals: Living Room</b>					<b>13.84</b>	<b>203.42</b>	<b>1,234.47</b>
<b>Total: 11112</b>					<b>46.77</b>	<b>528.84</b>	<b>3,219.87</b>

**11116**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,648. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
6,649. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,650. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
6,651. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>9.83</b>	<b>148.82</b>	<b>902.72</b>



### Bedroom 1

**Height: 9'**

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,652. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	30.00 SF		0.00	2.87	2.02	17.22	105.34
6,653. Batt insulation - 6" - R19 - unfaced batt	24.00 SF		0.00	1.07	1.54	5.14	32.36



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bedroom 1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Walls</i>							
6,654. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
<i>Walls</i>							
6,655. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
<b>Totals: Bedroom 1</b>					18.42	226.26	1,375.92



**Living / Dining Room**

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,656. 5/8" drywall - hung, taped, floated, ready for paint	71.00 SF		0.00	2.87	4.78	40.76	249.31
<i>Walls</i>							
6,657. Batt insulation - 6" - R19 - unfaced batt	71.00 SF		0.00	1.07	4.57	15.20	95.74
<i>Walls</i>							
6,658. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
<i>Walls</i>							
6,659. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living / Dining Room					38.61	464.78	2,827.22
Total: 11116					<b>66.86</b>	<b>839.86</b>	<b>5,105.86</b>

### 11120



### Bedroom

**Height: 8'**

316.11 SF Walls	138.06 SF Ceiling
454.17 SF Walls & Ceiling	138.06 SF Floor
15.34 SY Flooring	40.42 LF Floor Perimeter
47.00 LF Ceil. Perimeter	

<b>Door</b>	<b>3' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,660. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	138.06 SF		0.00	2.87	9.30	79.24	484.77
6,661. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	138.06 SF		0.00	1.12	10.41	30.92	195.96
6,662. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	454.17 SF		0.00	1.84	12.78	167.14	1,015.59
6,663. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,664. In-wall / In-ceiling speaker - Detach & reset	1.00 EA		0.00	18.44	0.00	3.68	22.12
6,665. Final cleaning - construction - Residential	138.06 SF		0.00	0.34	0.00	9.38	56.32
Totals: Bedroom					32.49	326.58	1,992.09



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 8'**

465.11 SF Walls	277.94 SF Ceiling
743.06 SF Walls & Ceiling	276.89 SF Floor
30.77 SY Flooring	62.17 LF Floor Perimeter
74.00 LF Ceil. Perimeter	


<b>Missing Wall - Goes to Floor</b>	<b>6' 1" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into STUDY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 11" X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>2' 10" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' X 4'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,666. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	22.00 SF		0.00	2.87	1.48	12.62	77.24
6,667. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	22.00 SF		0.00	1.07	1.42	4.70	29.66
6,668. Baseboard - 4 1/4"	11.00 LF		0.00	4.14	2.23	9.10	56.87
6,669. Seal & paint baseboard - two coats	62.17 LF		0.00	2.24	0.69	27.86	167.81
6,670. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	743.06 SF		0.00	1.84	20.91	273.44	1,661.58
6,671. Final cleaning - construction - Residential	276.89 SF		0.00	0.34	0.00	18.82	112.96
<b>Totals: Living / Dining Room</b>					<b>26.73</b>	<b>346.54</b>	<b>2,106.12</b>



**Camp Construction Services**


15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Pantry**

**Height: 8'**

Door	1' 9" X 6' 8"		Opens into PANTRY1				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,672. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	16.00 SF		0.00	2.87	1.08	9.18	56.18
6,673. Seal/prime then paint the surface area twice (3 coats) <i>Walls</i>	50.00 SF		0.00	1.84	1.41	18.40	111.81
6,674. Final cleaning - construction - Residential	50.00 SF		0.00	0.34	0.00	3.40	20.40
<b>Totals: Pantry</b>					2.49	30.98	188.39



**Kitchen**

**Height: 8'**

230.00 SF Walls	80.06 SF Ceiling
310.06 SF Walls & Ceiling	80.06 SF Floor
8.90 SY Flooring	26.33 LF Floor Perimeter
40.83 LF Ceil. Perimeter	

Door	4' 2" X 6' 8"		Opens into UTILITY_ROOM				
Door	2' 6" X 6' 8"		Opens into ROOM4				
Door	1' 9" X 6' 8"		Opens into PANTRY1				
Missing Wall - Goes to Floor	6' 1" X 6' 8"		Opens into LIVING__DIN				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,675. Paint the walls - two coats	230.00 SF		0.00	1.36	5.09	62.56	380.45
6,676. Seal & paint baseboard - two coats	26.33 LF		0.00	2.24	0.29	11.80	71.07
6,677. Mask the floor per square foot - plastic and tape - 4 mil	80.06 SF		0.00	0.35	0.40	5.60	34.02



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,678. Final cleaning - construction - Residential	80.06 SF		0.00	0.34	0.00	5.44	32.66
Totals: Kitchen					5.78	85.40	518.20
Total: 11120					<b>67.49</b>	<b>789.50</b>	<b>4,804.80</b>

### 11203

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,679. 5/8" drywall - hung, taped, floated, ready for paint	30.00 SF		0.00	2.87	2.02	17.22	105.34
6,680. Batt insulation - 6" - R19 - unfaced batt	30.00 SF		0.00	1.07	1.93	6.42	40.45
6,681. Paint the walls - two coats	609.00 SF		0.00	1.36	13.46	165.64	1,007.34
6,682. Baseboard - 3 1/4"	26.00 LF		0.00	3.49	3.79	18.14	112.67
6,683. Seal & paint baseboard - two coats	67.67 LF		0.00	2.24	0.75	30.32	182.65
6,684. Final cleaning - construction - Residential	242.44 SF		0.00	0.34	0.00	16.48	98.91
Totals: Work Space					21.95	254.22	1,547.36


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,685. Drywall patch / small repair, ready for paint <i>Walls</i>	1.00 EA		0.00	89.02	0.33	17.80	107.15
6,686. Paint the walls - two coats	518.47 SF		0.00	1.36	11.46	141.02	857.60
6,687. Drywall Installer / Finisher - per hour	1.00 HR		0.00	100.00	0.00	20.00	120.00
6,688. Final cleaning - construction - Residential	309.91 SF		0.00	0.34	0.00	21.08	126.45
Totals: Living Room					11.79	199.90	1,211.20
Total: 11203					<b>33.74</b>	<b>454.12</b>	<b>2,758.56</b>

### 11204



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

511.36 SF Walls	364.58 SF Ceiling
875.94 SF Walls & Ceiling	364.58 SF Floor
40.51 SY Flooring	59.92 LF Floor Perimeter
70.25 LF Ceil. Perimeter	

Missing Wall	12' 5" X 9'	Opens into STAIRWAY
Missing Wall	4' X 9'	Opens into STAIRWAY
Door	1' 10" X 6' 8"	Opens into HALL_CLOSET
Door	3' X 6' 8"	Opens into UTILITY_ROOM
Door	3' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	4' X 6' 8"	Opens into Exterior
Missing Wall	2' 6" X 9'	Opens into KITCHEN2
Missing Wall - Goes to Ceiling	7' 6" X 5'	Opens into KITCHEN2
Door	3' X 6' 8"	Opens into BEDROOM
Door	3' X 6' 8"	Opens into BATHROOM
Missing Wall	4' X 9'	Opens into STAIRWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,689. 5/8" drywall - hung, taped, floated, ready for paint	52.00 SF		0.00	2.87	3.50	29.84	182.58
6,690. Batt insulation - 6" - R19 - unfaced batt	52.00 SF		0.00	1.07	3.34	11.12	70.10
6,691. Paint the walls - two coats	511.36 SF		0.00	1.36	11.31	139.10	845.86
6,692. Baseboard - 3 1/4"	59.92 LF		0.00	3.49	8.73	41.82	259.67
6,693. Seal & paint baseboard - two coats	59.92 LF		0.00	2.24	0.66	26.84	161.72
6,694. Window sill	12.00 LF		0.00	3.12	1.10	7.48	46.02
6,695. Seal & paint window sill	12.00 LF		0.00	3.82	0.29	9.16	55.29
6,696. Floor preparation for resilient flooring	364.58 SF		0.00	0.71	3.66	51.78	314.29
6,697. Vinyl plank flooring	364.58 SF		0.00	5.74	109.55	418.54	2,620.78
<i>Entry</i>							
6,698. Final cleaning - construction - Residential	364.58 SF		0.00	0.34	0.00	24.80	148.76


Totals: Living / Dining Room

142.14 760.48 4,705.07



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




**Work Space**

**Height: 9'**

875.50 SF Walls	371.04 SF Ceiling
1,246.54 SF Walls & Ceiling	371.04 SF Floor
41.23 SY Flooring	97.50 LF Floor Perimeter
103.50 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LANDING</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,699. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
6,700. Batt insulation - 6" - R19 - unfaced batt	36.00 SF		0.00	1.07	2.32	7.70	48.54
6,701. Seal/prime then paint the walls twice (3 coats)	875.50 SF		0.00	1.84	24.64	322.18	1,957.74
6,702. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,703. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,704. Baseboard - 3 1/4"	97.50 LF		0.00	3.49	14.21	68.06	422.55
6,705. Seal & paint baseboard - two coats	97.50 LF		0.00	2.24	1.08	43.68	263.16
6,706. Final cleaning - construction - Residential	371.04 SF		0.00	0.34	0.00	25.24	151.39
<b>Totals: Work Space</b>					49.23	509.00	3,103.22



**Kitchen**

**Height: 9'**

290.56 SF Walls	104.06 SF Ceiling
394.61 SF Walls & Ceiling	103.44 SF Floor
11.49 SY Flooring	41.33 LF Floor Perimeter
32.33 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>2' 6" X 9'</b>	<b>Opens into LIVING__DI2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' X 5'</b>	<b>Opens into KITCHEN2</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' X 5'</b>	<b>Opens into LIVING__DI2</b>
<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,707. Vinyl plank flooring	103.44 SF		0.00	5.74	31.08	118.76	743.59
6,708. Floor preparation for resilient flooring	103.44 SF		0.00	0.71	1.04	14.68	89.16
6,709. Final cleaning - construction - Residential	103.44 SF		0.00	0.34	0.00	7.04	42.21
Totals: Kitchen					32.12	140.48	874.96
Total: 11204					<b>223.49</b>	<b>1,409.96</b>	<b>8,683.25</b>

### 11209



### Living Room

Height: 9'

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into KITCHEN

Window

4' X 4'

Opens into Exterior

Missing Wall

4' 1" X 9'


Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,710. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
6,711. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
6,712. Paint crown molding - two coats	40.67 LF		0.00	2.24	0.61	18.22	109.93
6,713. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
6,714. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					12.71	217.26	1,316.32



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Entry

Height: 9'

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into KITCHEN

Missing Wall

4' 1" X 9'

Opens into LIVING\_ROOM

Door

1' 10" X 6' 8"

Opens into CLOSET

Door

2' 8" X 6' 8"


Opens into BATHROOM

Door

3' X 6' 8"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,715. Paint the walls and ceiling - two coats	158.83 SF		0.00	1.36	3.51	43.20	262.72
6,716. Seal & paint baseboard - two coats	11.17 LF		0.00	2.24	0.12	5.00	30.14
6,717. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
6,718. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
6,719. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					4.09	70.30	425.86



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,720. 5/8" drywall - hung, taped, floated, ready for paint	40.00 SF		0.00	2.87	2.69	22.96	140.45
6,721. Batt insulation - 8" - R25 - unfaced batt	40.00 SF		0.00	1.43	3.26	11.44	71.90
6,722. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
6,723. Install Hanging light fixture	1.00 EA		0.00	49.24	0.00	9.84	59.08




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,724. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
6,725. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
6,726. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					12.51	147.96	900.35



### Utility Room

Height: 9'

126.61 SF Walls	14.88 SF Ceiling
141.49 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	13.33 LF Floor Perimeter
16.17 LF Ceil. Perimeter	


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,727. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
6,728. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,729. Shelving - wire (vinyl coated)	3.00 LF		0.00	10.99	1.16	6.60	40.73
6,730. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37
6,731. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
6,732. Seal/prime then paint the walls and ceiling twice (3 coats)	141.49 SF		0.00	1.84	3.98	52.06	316.38
6,733. Paint baseboard - one coat	13.33 LF		0.00	1.43	0.12	3.82	23.00
6,734. Seal & paint base shoe or quarter round	13.33 LF		0.00	1.19	0.15	3.18	19.19
6,735. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
6,736. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
Totals: Utility Room					6.28	122.06	738.46
Total: 11209					35.59	557.58	3,380.99

11213



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,737. Paint the walls and ceiling - two coats	282.90 SF		0.00	1.36	6.26	76.94	467.94
6,738. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
6,739. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
6,740. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					6.89	98.08	595.42



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,741. Baseboard - 4 1/4"	46.08 LF		0.00	4.14	9.35	38.16	238.28
6,742. Base shoe	7.00 LF		0.00	1.41	0.35	1.98	12.20
6,743. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37
6,744. Paint base shoe or quarter round - 1 coat	7.00 LF		0.00	0.80	0.06	1.12	6.78
6,745. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,746. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Living Room**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,747. Paint the walls and ceiling - two coats	526.35 SF		0.00	1.36	11.64	143.16	870.64
6,748. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
Totals: Living Room					26.47	237.06	1,448.82
Total: 11213					<b>33.36</b>	<b>335.14</b>	<b>2,044.24</b>

**11216**



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,749. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
6,750. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,751. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
6,752. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					9.83	148.82	902.72





## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,758. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	11.00 SF		0.00	2.87	0.74	6.32	38.63
6,759. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	11.00 SF		0.00	1.07	0.71	2.36	14.84
6,760. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
6,761. Drywall Installer / Finisher - per hour	2.00 HR		0.00	100.00	0.00	40.00	240.00
6,762. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>30.71</b>	<b>457.50</b>	<b>2,775.64</b>
<b>Total: 11216</b>					<b>56.45</b>	<b>856.54</b>	<b>5,195.47</b>

**11218**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Work Space

**Height: 9'**

875.50 SF Walls	371.04 SF Ceiling
1,246.54 SF Walls & Ceiling	371.04 SF Floor
41.23 SY Flooring	97.50 LF Floor Perimeter
103.50 LF Ceil. Perimeter	


<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LANDING</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,763. R&R Hat channel, 16" OC	185.52 SF		0.63	1.53	7.09	80.16	487.98
6,764. 5/8" drywall - hung, taped, floated, ready for paint	1,071.44 SF		0.00	2.87	72.14	615.00	3,762.17
6,765. Batt insulation - 4" - R11- unfaced batt	656.63 SF		0.00	0.70	24.42	91.92	575.98
6,766. Seal/prime then paint the walls and ceiling twice (3 coats)	1,246.54 SF		0.00	1.84	35.08	458.72	2,787.43
6,767. Baseboard - 4 1/4"	97.50 LF		0.00	4.14	19.79	80.74	504.18
6,768. Seal & paint baseboard - two coats	97.50 LF		0.00	2.24	1.08	43.68	263.16
6,769. Light fixture - Detach & reset	5.00 EA		0.00	50.85	0.00	50.86	305.11
6,770. Sprinkler head/escutcheon - Detach & reset	4.00 EA		0.00	17.44	0.00	13.96	83.72
6,771. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
6,772. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
6,773. Seal & paint window sill	3.50 LF		0.00	3.82	0.08	2.68	16.13
6,774. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	34.54	0.00	6.90	41.44
6,775. Casing - 3 1/4"	LF		0.00	3.19	0.00	0.00	0.00
6,776. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
6,777. Thermostat - Detach & reset	1.00 EA		0.00	62.84	0.00	12.56	75.40
6,778. Clean and deodorize carpet	371.04 SF		0.00	0.57	0.00	42.30	253.79
6,779. Final cleaning - construction - Residential	371.04 SF		0.00	0.34	0.00	25.24	151.39
<b>Totals: Work Space</b>					<b>162.05</b>	<b>1,552.82</b>	<b>9,478.85</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

**Height: 9'**

348.33 SF Walls	130.28 SF Ceiling
478.61 SF Walls & Ceiling	130.28 SF Floor
14.48 SY Flooring	38.67 LF Floor Perimeter
45.67 LF Ceil. Perimeter	


<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into BEDROOM_WALK</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,780. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
6,781. 5/8" drywall - hung, taped, floated, ready for paint	408.94 SF		0.00	2.87	27.54	234.74	1,435.94
6,782. Batt insulation - 4" - R11-unfaced batt	93.00 SF		0.00	0.70	3.46	13.02	81.58
6,783. Seal/prime then paint the walls and ceiling twice (3 coats)	478.61 SF		0.00	1.84	13.47	176.12	1,070.23
6,784. Baseboard - 4 1/4"	29.00 LF		0.00	4.14	5.89	24.02	149.97
6,785. Seal & paint baseboard - two coats	38.67 LF		0.00	2.24	0.43	17.32	104.37
6,786. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
6,787. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
6,788. Casing - 3 1/4"	LF		0.00	3.19	0.00	0.00	0.00
6,789. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
6,790. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
6,791. Carpet - Standard grade	149.82 SF		0.00	2.82	27.70	84.50	534.69
15 % waste added for Carpet - Standard grade.							
6,792. Carpet pad	130.28 SF		0.00	0.63	6.42	16.42	104.92
6,793. Final cleaning - construction - Residential	130.28 SF		0.00	0.34	0.00	8.86	53.16
<b>Totals: Bedroom</b>					<b>101.58</b>	<b>689.22</b>	<b>4,236.81</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

290.56 SF Walls	104.06 SF Ceiling
394.61 SF Walls & Ceiling	103.44 SF Floor
11.49 SY Flooring	41.33 LF Floor Perimeter
32.33 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>2' 6" X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' X 5'</b>	<b>Opens into LIVING__DIN</b>
<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,794. 5/8" drywall - hung, taped, floated, ready for paint	170.28 SF		0.00	2.87	11.47	97.74	597.91
6,795. Batt insulation - 4" - R11-unfaced batt	145.28 SF		0.00	0.70	5.40	20.34	127.44
6,796. Baseboard - 2 1/4"	145.28 LF		0.00	2.90	13.72	84.26	519.29
6,797. Base shoe	41.33 LF		0.00	1.41	2.08	11.66	72.02
6,798. Seal/prime then paint the walls and ceiling twice (3 coats)	394.61 SF		0.00	1.84	11.10	145.22	882.40
6,799. Seal & paint baseboard - two coats	41.33 LF		0.00	2.24	0.46	18.52	111.56
6,800. Seal & paint base shoe or quarter round	41.33 LF		0.00	1.19	0.46	9.84	59.48
6,801. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
6,802. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
6,803. Window sill	3.50 LF		0.00	3.12	0.32	2.18	13.42
6,804. Seal & paint window sill	3.50 LF		0.00	3.82	0.08	2.68	16.13
6,805. R&R Cabinetry - lower (base) units - Standard grade	7.33 LF		9.45	159.48	87.21	247.66	1,573.13
6,806. R&R Cabinet refacing	27.00 SF		3.78	28.62	46.67	174.96	1,096.43
6,807. Countertop - Granite or Marble	14.68 SF		0.00	64.59	40.76	189.64	1,178.58
6,808. Floor preparation for resilient flooring	103.44 SF		0.00	0.71	1.04	14.68	89.16
6,809. Vinyl plank flooring	103.44 SF		0.00	5.74	31.08	118.76	743.59
6,810. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,811. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
6,812. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	34.54	0.00	6.90	41.44




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,813. Final cleaning - construction - Residential	103.44 SF		0.00	0.34	0.00	7.04	42.21
Totals: Kitchen					259.84	1,204.78	7,488.29



### Utility Room

**Height: 9'**

205.00 SF Walls	38.50 SF Ceiling
243.50 SF Walls & Ceiling	38.50 SF Floor
4.28 SY Flooring	22.00 LF Floor Perimeter
25.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	3' X 6' 8"		Opens into LIVING ___ DIN		TOTAL
				REPLACE	TAX	O&P	TOTAL	
6,814. 5/8" drywall - hung, taped, floated, ready for paint	81.50 SF		0.00	2.87	5.49	46.78	286.18	
6,815. Baseboard - 4 1/4"	5.75 LF		0.00	4.14	1.17	4.76	29.74	
6,816. Seal & paint baseboard - two coats	22.00 LF		0.00	2.24	0.24	9.86	59.38	
6,817. Base shoe	22.00 LF		0.00	1.41	1.11	6.20	38.33	
6,818. Seal & paint base shoe or quarter round	22.00 LF		0.00	1.19	0.24	5.24	31.66	
6,819. Casing - 3 1/4"	LF		0.00	3.19	0.00	0.00	0.00	
6,820. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31	
6,821. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92	
6,822. R&R Light fixture	1.00 EA		10.49	69.13	3.32	15.92	98.86	
6,823. Final cleaning - construction - Residential	38.50 SF		0.00	0.34	0.00	2.62	15.71	
Totals: Utility Room					12.03	104.00	636.09	




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Stairway

**Height: 9'**




111.75 SF Walls	49.67 SF Ceiling
161.42 SF Walls & Ceiling	49.67 SF Floor
5.52 SY Flooring	12.42 LF Floor Perimeter
12.42 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 5" X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>4' X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>4' X 9'</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,824. Carpet	57.12 SF		0.00	3.67	15.44	41.92	266.99
15 % waste added for Carpet.							
6,825. Carpet pad	49.67 SF		0.00	0.63	2.45	6.26	40.00
6,826. Step charge for "waterfall" carpet installation	18.00 EA		0.00	12.17	0.81	43.82	263.69
6,827. 5/8" drywall - hung, taped, floated, ready for paint	52.00 SF		0.00	2.87	3.50	29.84	182.58
6,828. Seal/prime then paint the walls and ceiling twice (3 coats)	161.42 SF		0.00	1.84	4.54	59.40	360.95
6,829. Handrail - wall mounted - Detach & reset	20.00 LF		0.00	6.42	0.00	25.68	154.08
6,830. Paint handrail - wall mounted	20.00 LF		0.00	1.65	0.32	6.60	39.92
6,831. Final cleaning - construction - Residential	49.67 SF		0.00	0.34	0.00	3.38	20.27
<b>Totals: Stairway</b>					<b>27.06</b>	<b>216.90</b>	<b>1,328.48</b>

### Landing

**Height: 9'**



89.50 SF Walls	14.72 SF Ceiling
104.22 SF Walls & Ceiling	14.72 SF Floor
1.64 SY Flooring	9.17 LF Floor Perimeter
12.17 LF Ceil. Perimeter	

<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into WORK_SPACE</b>
-------------	-------------------	------------------------------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Landing

#### Subroom: Stairs (1)

Height: 17' 5"



346.56 SF Walls	46.67 SF Ceiling
393.23 SF Walls & Ceiling	82.10 SF Floor
9.12 SY Flooring	33.70 LF Floor Perimeter
28.00 LF Ceil. Perimeter	

#### Missing Wall

3' 4" X 17' 4 9/16"


Opens into LANDING

#### Missing Wall

3' 4" X 17' 4 9/16"

Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,832. 5/8" drywall - hung, taped, floated, ready for paint	124.00 SF		0.00	2.87	8.35	71.18	435.41
6,833. Seal/prime then paint the walls and ceiling twice (3 coats)	497.45 SF		0.00	1.84	14.00	183.06	1,112.37
6,834. Baseboard - 4 1/4"	13.33 LF		0.00	4.14	2.71	11.04	68.94
6,835. Seal & paint baseboard - two coats	42.87 LF		0.00	2.24	0.47	19.20	115.70
6,836. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,837. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
6,838. Carpet	111.35 SF		0.00	3.67	30.10	81.74	520.49
15 % waste added for Carpet.							
6,839. Carpet pad	24.00 SF		0.00	0.63	1.18	3.02	19.32
6,840. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
6,841. Final cleaning - construction - Residential	96.82 SF		0.00	0.34	0.00	6.58	39.50
<b>Totals: Landing</b>					57.27	398.62	2,448.99



#### Master Walk-In Closet

Height: 9'

232.94 SF Walls	48.50 SF Ceiling
281.44 SF Walls & Ceiling	48.50 SF Floor
5.39 SY Flooring	25.08 LF Floor Perimeter
28.17 LF Ceil. Perimeter	

#### Door

3' 1" X 6' 8"

Opens into MASTER\_BATHR

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Walk-In Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,842. 5/8" drywall - hung, taped, floated, ready for paint	125.00 SF		0.00	2.87	8.42	71.76	438.93
6,843. Baseboard - 4 1/4"	8.50 LF		0.00	4.14	1.73	7.04	43.96
6,844. Seal & paint baseboard - two coats	25.08 LF		0.00	2.24	0.28	11.24	67.70
6,845. Shelving - wire (vinyl coated)	14.00 LF		0.00	10.99	5.40	30.78	190.04
6,846. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
6,847. Mask the floor per square foot - plastic and tape - 4 mil	48.50 SF		0.00	0.35	0.24	3.40	20.62
6,848. Seal/prime then paint the walls and ceiling twice (3 coats)	281.44 SF		0.00	1.84	7.92	103.58	629.35
6,849. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
6,850. Final cleaning - construction - Residential	48.50 SF		0.00	0.34	0.00	3.30	19.79
<b>Totals: Master Walk-In Closet</b>					<b>24.53</b>	<b>245.34</b>	<b>1,496.39</b>



### Bathroom

Height: 9'

257.50 SF Walls	52.96 SF Ceiling
310.46 SF Walls & Ceiling	52.96 SF Floor
5.88 SY Flooring	27.83 LF Floor Perimeter
30.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,851. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
6,852. Floor preparation for resilient flooring	52.96 SF		0.00	0.71	0.53	7.52	45.65
6,853. Vinyl plank flooring	52.96 SF		0.00	5.74	15.91	60.80	380.70
6,854. Baseboard - 4 1/4"	20.87 LF		0.00	4.14	4.24	17.28	107.92
6,855. Seal & paint baseboard - two coats	27.83 LF		0.00	2.24	0.31	12.46	75.11
6,856. Base shoe	20.87 LF		0.00	1.41	1.05	5.88	36.36
6,857. Seal & paint base shoe or quarter round	27.83 LF		0.00	1.19	0.31	6.62	40.05
6,858. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,859. Final cleaning - construction - Residential	52.96 SF		0.00	0.34	0.00	3.60	21.61
Totals: Bathroom					24.37	193.58	1,185.96



### Master Bathroom

Height: 9'

245.22 SF Walls	61.33 SF Ceiling
306.56 SF Walls & Ceiling	61.33 SF Floor
6.81 SY Flooring	25.00 LF Floor Perimeter
33.67 LF Ceil. Perimeter	


Door	3' 1" X 6' 8"	Opens into MASTER_WALK
Door	2' 7" X 6' 8"	Opens into LINEN_CLOSET
Door	3' X 6' 8"	Opens into MASTER_BEDRO

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,860. Vinyl - metal transition strip	3.00 LF		0.00	3.02	0.39	1.82	11.27
6,861. Final cleaning - construction - Residential	61.33 SF		0.00	0.34	0.00	4.18	25.03
Totals: Master Bathroom					0.39	6.00	36.30



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

511.36 SF Walls	364.58 SF Ceiling
875.94 SF Walls & Ceiling	364.58 SF Floor
40.51 SY Flooring	59.92 LF Floor Perimeter
70.25 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 5" X 9'</b>	<b>Opens into STAIRWAY</b>
<b>Missing Wall</b>	<b>4' X 9'</b>	<b>Opens into STAIRWAY</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into HALL_CLOSET</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>2' 6" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Missing Wall</b>	<b>4' X 9'</b>	<b>Opens into STAIRWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,862. 5/8" drywall - hung, taped, floated, ready for paint	875.94 SF		0.00	2.87	58.98	502.80	3,075.73
6,863. Batt insulation - 4" - R11-unfaced batt	93.00 SF		0.00	0.70	3.46	13.02	81.58
6,864. Seal/prime then paint the walls and ceiling twice (3 coats)	875.94 SF		0.00	1.84	24.65	322.34	1,958.72
6,865. Crown molding - 4 1/4"	70.25 LF		0.00	4.86	14.12	68.28	423.82
6,866. Paint crown molding, oversized - one coat	70.25 LF		0.00	1.58	0.85	22.20	134.05
6,867. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
6,868. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
6,869. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
6,870. Window stool & apron	7.00 LF		0.00	8.09	2.68	11.32	70.63
6,871. Seal & paint window stool and apron	7.00 LF		0.00	5.93	0.25	8.30	50.06
6,872. Trim board - 1" x 2" - installed (pine)	70.25 LF		0.00	2.96	7.98	41.58	257.50
6,873. Seal & paint trim - two coats	70.25 LF		0.00	2.15	0.85	30.20	182.09
6,874. Floor preparation for resilient flooring	364.58 SF		0.00	0.71	3.66	51.78	314.29




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,875. Vinyl plank flooring	364.58 SF		0.00	5.74	109.55	418.54	2,620.78
6,876. Window blind - horizontal or vertical - Detach & reset	1.00 EA		0.00	34.54	0.00	6.90	41.44
6,877. Light weight, gypsum concrete - 1 1/2" thick	60.00 SF		0.00	4.41	19.30	52.92	336.82
6,878. Baseboard - 4 1/4"	59.92 LF		0.00	4.14	12.16	49.62	309.85
6,879. Seal & paint baseboard - two coats	59.92 LF		0.00	2.24	0.66	26.84	161.72
6,880. Base shoe	59.92 LF		0.00	1.41	3.01	16.90	104.40
6,881. Seal & paint base shoe or quarter round	59.92 LF		0.00	1.19	0.66	14.26	86.22
6,882. Casing - 3 1/4"	LF		0.00	3.19	0.00	0.00	0.00
6,883. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
6,884. Final cleaning - construction - Residential	364.58 SF		0.00	0.34	0.00	24.80	148.76
Totals: Living / Dining Room					277.00	1,792.04	11,029.20
Total: 11218					<b>946.12</b>	<b>6,403.30</b>	<b>39,365.36</b>

11220



### Bathroom

Height: 9'

274.89 SF Walls	62.22 SF Ceiling
337.11 SF Walls & Ceiling	62.22 SF Floor
6.91 SY Flooring	29.33 LF Floor Perimeter
34.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,885. Paint the walls and ceiling - two coats	337.11 SF		0.00	1.36	7.45	91.70	557.62
6,886. Final cleaning - construction - Residential	62.22 SF		0.00	0.34	0.00	4.24	25.39
Totals: Bathroom					7.45	95.94	583.01

Door

3' X 6' 8"

Opens into HALLWAY

Door


1' 8" X 6' 8"

Opens into LINEN\_CLOSET



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Hallway**


**Height: 9'**

76.25 SF Walls	16.97 SF Ceiling
93.22 SF Walls & Ceiling	16.97 SF Floor
1.89 SY Flooring	6.92 LF Floor Perimeter
12.92 LF Ceil. Perimeter	

- Door** **3' X 6' 8"** **Opens into BATHROOM1**
- Missing Wall** **3' 11" X 9'** **Opens into LIVING\_ROOM**
- Door** **3' X 6' 8"** **Opens into BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,887. 5/8" drywall - hung, taped, floated, ready for paint	13.83 SF		0.00	2.87	0.93	7.94	48.56
6,888. Batt insulation - 6" - R19 - unfaced batt	13.83 SF		0.00	1.07	0.89	2.96	18.65
6,889. Seal/prime then paint the walls and ceiling twice (3 coats)	93.22 SF		0.00	1.84	2.62	34.30	208.44
6,890. Final cleaning - construction - Residential	16.97 SF		0.00	0.34	0.00	1.16	6.93
<b>Totals: Hallway</b>					<b>4.44</b>	<b>46.36</b>	<b>282.58</b>
<b>Total: 11220</b>					<b>11.89</b>	<b>142.30</b>	<b>865.59</b>

**11301**



**Linen Closet**

**Height: 9'**

68.39 SF Walls	4.83 SF Ceiling
73.22 SF Walls & Ceiling	4.83 SF Floor
0.54 SY Flooring	7.17 LF Floor Perimeter
8.83 LF Ceil. Perimeter	

- Door** **1' 8" X 6' 8"** **Opens into BATHROOM1**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,891. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
6,892. Batt insulation - 4" - R11 - unfaced batt	16.00 SF		0.00	0.70	0.59	2.24	14.03
6,893. Seal/prime then paint the walls twice (3 coats)	68.39 SF		0.00	1.84	1.92	25.16	152.92
6,894. Baseboard - 4 1/4"	21.00 LF		0.00	4.14	4.26	17.38	108.58




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Linen Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,895. Seal & paint baseboard - two coats	7.17 LF		0.00	2.24	0.08	3.22	19.36
6,896. Base shoe	21.00 LF		0.00	1.41	1.06	5.92	36.59
6,897. Seal & paint base shoe or quarter round	7.17 LF		0.00	1.19	0.08	1.70	10.31
6,898. Final cleaning - construction - Residential	4.83 SF		0.00	0.34	0.00	0.32	1.96
<b>Totals: Linen Closet</b>					<b>9.07</b>	<b>65.12</b>	<b>399.93</b>
<b>Total: 11301</b>					<b>9.07</b>	<b>65.12</b>	<b>399.93</b>

**11304**



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	


<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,899. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
6,900. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,901. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
6,902. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>9.83</b>	<b>148.82</b>	<b>902.72</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom 1

**Height: 9'**

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" Opens into WALKIN\_CLOS  
**Door** 3' X 6' 8" Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,903. 5/8" drywall - hung, taped, floated, ready for paint	12.00 SF		0.00	2.87	0.81	6.88	42.13
<i>Ceiling</i>							
6,904. Blown-in insulation - 10" depth - R26	139.97 SF		0.00	1.12	10.55	31.36	198.68
<i>Ceiling</i>							
6,905. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
<i>Ceiling</i>							
6,906. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
<b>Totals: Bedroom 1</b>					26.22	242.14	1,479.03



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

**Door** 2' 8" X 6' 8" Opens into UTILITY\_ROOM  
**Door** 2' 4" X 6' 8" Opens into CLOSET  
**Door** 2' 8" X 6' 8" Opens into BATHROOM  
**Door** 3' X 6' 8" Opens into BEDROOM\_1  
**Missing Wall - Goes to Floor** 10' 3" X 6' 8" Opens into KITCHEN  
**Door** 4' X 6' 8" Opens into Exterior  
**Window** 4' X 4' Opens into Exterior  
**Window** 4' X 4' Opens into Exterior  
**Door** 2' 8" X 6' 8" Opens into MASTER\_BEDRO  
**Door** 3' X 6' 8" Opens into Exterior




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,907. Paint the walls - two coats	655.11 SF		0.00	1.36	14.48	178.20	1,083.63
6,908. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					14.48	204.36	1,240.59
Total: 11304					<b>50.53</b>	<b>595.32</b>	<b>3,622.34</b>

11306



### Kitchen

Height: 9'

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	


<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,909. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
6,910. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,911. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
6,912. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					9.83	148.82	902.72



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

Height: 9'

450.94 SF Walls  
612.61 SF Walls & Ceiling  
17.96 SY Flooring  
55.83 LF Ceil. Perimeter

161.67 SF Ceiling  
161.67 SF Floor  
50.50 LF Floor Perimeter

**Door** 2' 8" X 6' 8" Opens into BATHROOM1  
**Door** 2' 8" X 6' 8" Opens into LIVING\_\_DIN  
**Window** 4' X 4' Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,913. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	16.00 SF		0.00	2.87	1.08	9.18	56.18
6,914. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	16.00 SF		0.00	1.07	1.03	3.42	21.57
6,915. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	612.61 SF		0.00	1.84	17.24	225.44	1,369.88
6,916. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
6,917. Clean and deodorize carpet	161.67 SF		0.00	0.57	0.00	18.44	110.59
<b>Totals: Master Bedroom</b>					19.35	267.48	1,624.19



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,918. Baseboard - 4 1/4"	68.42 LF		0.00	4.14	13.89	56.66	353.81
6,919. Base shoe	27.00 LF		0.00	1.41	1.36	7.62	47.05
6,920. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
6,921. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
6,922. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	14.00 SF		0.00	2.87	0.94	8.04	49.16
6,923. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	14.00 SF		0.00	1.07	0.90	3.00	18.88
6,924. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Paint and blend (walls)</i>	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
6,925. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
6,926. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
6,927. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>52.43</b>	<b>552.56</b>	<b>3,367.65</b>
<b>Total: 11306</b>					<b>81.61</b>	<b>968.86</b>	<b>5,894.56</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

11307



**Utility Room**

**Height: 9'**

145.50 SF Walls	14.88 SF Ceiling
160.38 SF Walls & Ceiling	14.88 SF Floor
1.65 SY Flooring	16.17 LF Floor Perimeter
16.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,928. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
6,929. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37
6,930. 5/8" drywall - hung, taped, floated, ready for paint	34.00 SF		0.00	2.87	2.29	19.52	119.39
6,931. Batt insulation - 4" - R11-unfaced batt	16.00 SF		0.00	0.70	0.59	2.24	14.03
6,932. Seal/prime then paint the walls twice (3 coats)	145.50 SF		0.00	1.84	4.09	53.54	325.35
6,933. Shelving - wire (vinyl coated) - Detach & reset	3.00 LF		0.00	9.66	0.00	5.80	34.78
6,934. Baseboard - 4 1/4"	11.00 LF		0.00	4.14	2.23	9.10	56.87
6,935. Seal & paint baseboard - two coats	16.17 LF		0.00	2.24	0.18	7.24	43.64
6,936. Base shoe	11.00 LF		0.00	1.41	0.55	3.10	19.16
6,937. Seal & paint base shoe or quarter round	16.17 LF		0.00	1.19	0.18	3.84	23.26
6,938. Final cleaning - construction - Residential	14.88 SF		0.00	0.34	0.00	1.02	6.08
<b>Totals: Utility Room</b>					<b>10.11</b>	<b>122.04</b>	<b>742.38</b>



**Bathroom**

**Height: 9'**

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Missing Wall</b>	<b>4' 11" X 9'</b>	<b>Opens into BEDROOM</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Bathroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,939. 5/8" drywall - hung, taped, floated, ready for paint	18.00 SF		0.00	2.87	1.21	10.34	63.21
6,940. Batt insulation - 10" - R30 - unfaced batt	18.00 SF		0.00	1.57	1.86	5.66	35.78
6,941. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
6,942. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
6,943. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
6,944. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
6,945. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
<b>Totals: Bathroom</b>					<b>18.09</b>	<b>201.92</b>	<b>1,229.47</b>
<b>Total: 11307</b>					<b>28.20</b>	<b>323.96</b>	<b>1,971.85</b>

**11310**



**Kitchen**

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	


- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Door**      **1' 6" X 6' 8"**      **Opens into PANTRY**
- Missing Wall**      **2' 4" X 9'**      **Opens into HALLWAY**
- Missing Wall**      **12' 7" X 9'**      **Opens into LIVING\_\_DI2**
- Missing Wall - Goes to Ceiling**      **2' 6" X 5'**      **Opens into KITCHEN**
- Missing Wall - Goes to Ceiling**      **7' 7" X 5'**      **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,946. Seal/prime then paint the walls twice (3 coats)	356.25 SF		0.00	1.84	10.02	131.10	796.62
<b>Totals: Kitchen</b>					<b>10.02</b>	<b>131.10</b>	<b>796.62</b>



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

375.72 SF Walls  
505.07 SF Walls & Ceiling  
14.37 SY Flooring  
45.50 LF Ceil. Perimeter

129.35 SF Ceiling  
129.35 SF Floor  
42.83 LF Floor Perimeter

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**2' 8" X 6' 8"**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,947. Drywall patch / small repair, ready for paint	1.00 EA		0.00	89.02	0.33	17.80	107.15
6,948. Mask the floor per square foot - plastic and tape - 4 mil	129.35 SF		0.00	0.35	0.65	9.06	54.98
6,949. Seal/prime then paint the walls and ceiling twice (3 coats)	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
6,950. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
6,951. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					<b>28.00</b>	<b>286.38</b>	<b>1,746.24</b>



**Living / Dining Room**

**Height: 9'**

414.58 SF Walls  
704.18 SF Walls & Ceiling  
32.18 SY Flooring  
52.58 LF Ceil. Perimeter

289.60 SF Ceiling  
289.60 SF Floor  
48.58 LF Floor Perimeter

**Missing Wall**

**12' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**4' X 6' 8"**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**1' 1" X 9'**

**Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,952. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
6,953. Batt insulation - 4" - R11-unfaced batt	6.00 SF		0.00	0.70	0.22	0.84	5.26
6,954. Seal/prime then paint the walls twice (3 coats)	414.58 SF		0.00	1.84	11.67	152.56	927.06




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,955. Baseboard - 4 1/4"	22.00 LF		0.00	4.14	4.47	18.22	113.77
6,956. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
6,957. Base shoe	22.00 LF		0.00	1.41	1.11	6.20	38.33
6,958. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
6,959. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					18.95	234.28	1,424.67
Total: 11310					<b>56.97</b>	<b>651.76</b>	<b>3,967.53</b>

### 11316



#### Kitchen

Height: 9'

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,960. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
6,961. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,962. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
6,963. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					9.83	148.82	902.72



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>2' 4" X 6' 8"</b>	<b>Opens into CLOSET</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM_1</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into MASTER_BEDRO</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,964. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	48.00 SF		0.00	2.87	3.23	27.56	168.55
6,965. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	40.00 SF		0.00	1.07	2.57	8.56	53.93
6,966. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
6,967. Baseboard - 4 1/4"	68.42 LF		0.00	4.14	13.89	56.66	353.81
6,968. Base shoe	18.00 LF		0.00	1.41	0.90	5.08	31.36
6,969. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
6,970. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
6,971. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					<b>51.37</b>	<b>553.62</b>	<b>3,372.96</b>
<b>Total: 11316</b>					<b>61.20</b>	<b>702.44</b>	<b>4,275.68</b>

11318



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY2</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,972. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	54.00 SF		0.00	2.87	3.64	31.00	189.62
6,973. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	30.00 SF		0.00	1.07	1.93	6.42	40.45
6,974. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	522.56 SF		0.00	1.84	14.71	192.30	1,168.52
6,975. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	136.58 SF		0.00	1.12	10.30	30.60	193.87
6,976. Floor preparation for resilient flooring	133.00 SF		0.00	0.71	1.34	18.88	114.65
6,977. Vinyl floor covering (sheet goods) 15 % waste added for Vinyl floor covering (sheet goods).	152.95 SF		0.00	3.35	26.75	102.48	641.61
6,978. Base shoe	56.86 LF		0.00	1.41	2.86	16.04	99.07
6,979. Hanging light fixture	2.00 EA		0.00	81.74	6.53	32.70	202.71
6,980. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
6,981. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
6,982. Dishwasher - Detach & reset	1.00 EA		0.00	250.12	0.00	50.02	300.14
6,983. Range - electric - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,984. Refrigerator - Remove & reset	1.00 EA		0.00	48.27	0.00	9.66	57.93
6,985. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					69.32	545.40	3,341.59



### Bathroom

Height: 9'

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

**Door** 3' 3" X 6' 8" Opens into ROOM3

**Door** 2' 8" X 6' 8" Opens into MASTER\_BEDRO

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,986. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
6,987. Batt insulation - 4" - R11-unfaced batt	15.00 SF		0.00	0.70	0.56	2.10	13.16
6,988. Paint the walls and ceiling - two coats	360.31 SF		0.00	1.36	7.97	98.00	595.99
6,989. Seal & paint baseboard - two coats	31.08 LF		0.00	2.24	0.34	13.92	83.88
6,990. Seal & paint base shoe or quarter round	31.08 LF		0.00	1.19	0.34	7.40	44.73
6,991. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
6,992. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
Totals: Bathroom					15.69	184.70	1,123.96



### Room2

Height: 9'

222.83 SF Walls	44.86 SF Ceiling
267.69 SF Walls & Ceiling	44.86 SF Floor
4.98 SY Flooring	23.92 LF Floor Perimeter
27.17 LF Ceil. Perimeter	

**Door** 3' 3" X 6' 8" Opens into BATHROOM1

SAULET-RECON-V5\_23-B

5/31/2022

Page: 644




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Room2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
6,993. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
6,994. 5/8" drywall - hung, taped, floated, ready for paint	267.69 SF		0.00	2.87	18.02	153.66	939.95
6,995. Paint the walls and ceiling - two coats	267.69 SF		0.00	1.36	5.92	72.82	442.80
6,996. Batt insulation - 6" - R19 - unfaced batt	222.83 SF		0.00	1.07	14.33	47.68	300.44
6,997. Blown-in insulation - 10" depth - R26	44.86 SF		0.00	1.12	3.38	10.04	63.66
6,998. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
6,999. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
7,000. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
7,001. Light fixture	1.00 EA		0.00	69.13	3.32	13.82	86.27
7,002. Carpet	51.59 SF		0.00	3.67	13.95	37.86	241.15
<i>15 % waste added for Carpet.</i>							
7,003. Carpet pad	44.86 SF		0.00	0.63	2.21	5.66	36.13
7,004. Final cleaning - construction - Residential	44.86 SF		0.00	0.34	0.00	3.06	18.31
Totals: Room2					86.01	436.74	2,706.40



### Utility Room

Height: 9'

216.22 SF Walls	40.89 SF Ceiling
257.11 SF Walls & Ceiling	40.89 SF Floor
4.54 SY Flooring	23.33 LF Floor Perimeter
26.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,005. 5/8" drywall - hung, taped, floated, ready for paint	257.11 SF		0.00	2.87	17.31	147.58	902.80
7,006. Seal/prime then paint the walls and ceiling twice (3 coats)	257.11 SF		0.00	1.84	7.23	94.62	574.93
7,007. Baseboard - 4 1/4"	23.33 LF		0.00	4.14	4.74	19.32	120.65
7,008. Seal & paint baseboard - two coats	23.33 LF		0.00	2.24	0.26	10.46	62.98
7,009. Base shoe	23.33 LF		0.00	1.41	1.17	6.58	40.65

2' 8" X 6' 8"

Opens into LIVING\_\_DIN




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,010. Seal & paint base shoe or quarter round	23.33 LF		0.00	1.19	0.26	5.56	33.58
7,011. Floor preparation for resilient flooring	40.89 SF		0.00	0.71	0.41	5.80	35.24
7,012. Vinyl plank flooring	40.89 SF		0.00	5.74	12.29	46.94	293.94
7,013. Light fixture - Standard grade	1.00 EA		0.00	53.27	1.72	10.66	65.65
7,014. Water heater - Detach & reset	1.00 EA		0.00	581.39	0.00	116.28	697.67
7,015. Interior door - Colonist - pre-hung unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
7,016. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
7,017. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
7,018. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
7,019. Final cleaning - construction - Residential	40.89 SF		0.00	0.34	0.00	2.78	16.68
Totals: Utility Room					69.69	548.52	3,360.64



### Bathroom

Height: 9'

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	

**Door** 1' 5" X 6' 8"

Opens into LINEN\_CLOSET

**Door** 2' 8" X 6' 8"

Opens into LIVING\_\_DIN

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,020. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
7,021. Floor preparation for resilient flooring	53.06 SF		0.00	0.71	0.53	7.54	45.74
7,022. Vinyl plank flooring	53.06 SF		0.00	5.74	15.94	60.92	381.42
7,023. Baseboard - 4 1/4"	28.58 LF		0.00	4.14	5.80	23.66	147.78
7,024. Seal & paint baseboard - two coats	28.58 LF		0.00	2.24	0.32	12.80	77.14
7,025. Base shoe	28.58 LF		0.00	1.41	1.44	8.06	49.80
7,026. Seal & paint base shoe or quarter round	28.58 LF		0.00	1.19	0.32	6.80	41.13




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,027. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
Totals: Bathroom					25.91	190.06	1,166.26



### Closet

Height: 9'

71.44 SF Walls	5.67 SF Ceiling
77.11 SF Walls & Ceiling	5.67 SF Floor
0.63 SY Flooring	7.33 LF Floor Perimeter
9.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<b>Door</b>							
<b>2' 4" X 6' 8"</b>							
<b>Opens into LIVING__DIN</b>							
7,028. 5/8" drywall - hung, taped, floated, ready for paint	77.11 SF		0.00	2.87	5.19	44.26	270.76
7,029. Baseboard - 4 1/4"	7.33 LF		0.00	4.14	1.49	6.08	37.92
7,030. Seal & paint baseboard - two coats	7.33 LF		0.00	2.24	0.08	3.28	19.78
7,031. Base shoe	7.33 LF		0.00	1.41	0.37	2.06	12.77
7,032. Seal & paint base shoe or quarter round	7.33 LF		0.00	1.19	0.08	1.74	10.54
7,033. Floor preparation for resilient flooring	5.67 SF		0.00	0.71	0.06	0.80	4.89
7,034. Vinyl plank flooring	5.67 SF		0.00	5.74	1.70	6.52	40.77
7,035. Interior door - Reset - slab only	1.00 EA		0.00	13.73	0.00	2.74	16.47
7,036. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
7,037. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
7,038. Seal/prime then paint the walls and ceiling twice (3 coats)	77.11 SF		0.00	1.84	2.17	28.38	172.43
7,039. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
Totals: Closet					35.14	176.30	1,092.96



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Master Bedroom

**Height: 9'**

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,040. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
7,041. 5/8" drywall - hung, taped, floated, ready for paint	612.61 SF		0.00	2.87	41.25	351.64	2,151.08
7,042. Paint the walls and ceiling - two coats	612.61 SF		0.00	1.36	13.54	166.64	1,013.33
7,043. Batt insulation - 6" - R19 - unfaced batt	450.94 SF		0.00	1.07	29.00	96.50	608.01
7,044. Blown-in insulation - 10" depth - R26	161.67 SF		0.00	1.12	12.19	36.22	229.48
7,045. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
7,046. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	53.15	0.75	10.64	64.54
7,047. Seal & paint casing - two coats	20.00 LF		0.00	2.26	0.26	9.04	54.50
7,048. Baseboard - 4 1/4"	50.50 LF		0.00	4.14	10.25	41.82	261.14
7,049. Seal & paint baseboard - two coats	50.50 LF		0.00	2.24	0.56	22.62	136.30
7,050. Carpet	185.92 SF		0.00	3.67	50.26	136.46	869.05
<i>15 % waste added for Carpet.</i>							
7,051. Carpet pad	161.67 SF		0.00	0.63	7.96	20.38	130.19
7,052. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
7,053. Detach & Reset Ceiling fan & light	1.00 EA	181.11	0.00	0.00	0.00	36.22	217.33
7,054. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
7,055. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
7,056. Seal & paint window sill	3.50 LF		0.00	3.82	0.08	2.68	16.13
7,057. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
7,058. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Master Bedroom					190.65	1,021.08	6,316.91



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,059. R&R Hat channel, 16" OC	384.72 SF		0.63	1.53	14.69	166.20	1,011.88
7,060. Framing material allowance for repairs	1.00 EA		0.00	125.00	5.15	25.00	155.15
7,061. 5/8" drywall - hung, taped, floated, ready for paint	1,039.83 SF		0.00	2.87	70.02	596.86	3,651.19
7,062. Paint the walls and ceiling - two coats	1,039.83 SF		0.00	1.36	22.99	282.84	1,720.00
7,063. Batt insulation - 6" - R19 - unfaced batt	113.00 SF		0.00	1.07	7.27	24.18	152.36
7,064. Blown-in insulation - 10" depth - R26	384.72 SF		0.00	1.12	29.00	86.18	546.07
7,065. Baseboard - 3 1/4"	68.42 LF		0.00	3.49	9.97	47.76	296.52
7,066. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
7,067. Base shoe	68.42 LF		0.00	1.41	3.44	19.30	119.21
7,068. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
7,069. Crown molding - 4 1/4"	99.00 LF		0.00	4.86	19.90	96.22	597.26



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,070. Paint crown molding, oversized - one coat	99.00 LF		0.00	1.58	1.19	31.28	188.89
7,071. Trim board - 1" x 2" - installed (pine)	99.00 LF		0.00	2.96	11.24	58.60	362.88
7,072. Seal & paint trim - two coats	99.00 LF		0.00	2.15	1.19	42.58	256.62
7,073. R&R Light weight, gypsum concrete - 1 1/2" thick	60.00 SF		4.14	4.41	19.30	102.60	634.90
7,074. Casing - 2 1/4"	21.00 LF		0.00	2.23	2.45	9.36	58.64
7,075. Paint casing - one coat	21.00 LF		0.00	1.44	0.21	6.04	36.49
7,076. Light fixture - Standard grade	1.00 EA		0.00	53.27	1.72	10.66	65.65
7,077. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
7,078. Floor preparation for resilient flooring	384.72 SF		0.00	0.71	3.87	54.64	331.66
7,079. Vinyl plank flooring	384.72 SF		0.00	5.74	115.61	441.66	2,765.56
7,080. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					340.73	2,178.54	13,411.95
Total: 11318					<b>833.14</b>	<b>5,281.34</b>	<b>32,520.67</b>

**11401**



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

823.56 SF Walls	486.47 SF Ceiling
1,310.03 SF Walls & Ceiling	481.31 SF Floor
53.48 SY Flooring	108.42 LF Floor Perimeter
123.33 LF Ceil. Perimeter	

<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Missing Wall</b>	<b>4' 5" X 9'</b>	<b>Opens into ENTRY</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BATHROOM1</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into BEDROOM</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>3' 1" X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>1' 10" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>10' 2" X 5'</b>	<b>Opens into LIVING_ROOM</b>
<b>Missing Wall - Goes to neither Floor/Ceiling</b>	<b>3' X 5'</b>	<b>Opens into LIVING_ROOM</b>


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,081. 5/8" drywall - hung, taped, floated, ready for paint	36.00 SF		0.00	2.87	2.42	20.66	126.40
7,082. Batt insulation - 6" - R19 - unfaced batt	36.00 SF		0.00	1.07	2.32	7.70	48.54
7,083. Baseboard - 4 1/4"	108.42 LF		0.00	4.14	22.01	89.78	560.65
7,084. Base shoe	18.00 LF		0.00	1.41	0.90	5.08	31.36
7,085. Seal & paint baseboard - two coats	108.42 LF		0.00	2.24	1.20	48.58	292.64
7,086. Seal & paint base shoe or quarter round	108.42 LF		0.00	1.19	1.20	25.80	156.02
7,087. Seal/prime then paint the walls and ceiling twice (3 coats)	1,310.03 SF		0.00	1.84	36.86	482.10	2,929.42
7,088. Final cleaning - construction - Residential	481.31 SF		0.00	0.34	0.00	32.74	196.39
<b>Totals: Living Room</b>					<b>66.91</b>	<b>712.44</b>	<b>4,341.42</b>
<b>Total: 11401</b>					<b>66.91</b>	<b>712.44</b>	<b>4,341.42</b>

**11402**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,089. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
7,090. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
7,091. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
7,092. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>9.83</b>	<b>148.82</b>	<b>902.72</b>



### Bedroom 1

**Height: 9'**

388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into WALKIN_CLOS</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,093. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	30.00 SF		0.00	2.87	2.02	17.22	105.34
7,094. Blown-in insulation - 10" depth - R26	139.97 SF		0.00	1.12	10.55	31.36	198.68



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Ceiling</i>							
7,095. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
7,096. Seal/prime then paint the walls and ceiling twice (3 coats)	528.19 SF		0.00	1.84	14.86	194.38	1,181.11
<i>Ceiling</i>							
7,097. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
Totals: Bedroom 1					27.43	288.70	1,759.57



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,098. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
<i>Walls</i>							
7,099. Batt insulation - 6" - R19 - unfaced batt	8.00 SF		0.00	1.07	0.51	1.72	10.79
<i>Walls</i>							
7,100. Seal/prime then paint the walls and ceiling twice (3 coats)	1,039.83 SF		0.00	1.84	29.26	382.66	2,325.21
<i>Walls</i>							
7,101. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Living / Dining Room					30.31	415.14	2,521.06
Total: 11402					<b>67.57</b>	<b>852.66</b>	<b>5,183.35</b>

### 11403



#### Bedroom

Height: 9'

366.22 SF Walls	136.10 SF Ceiling
502.33 SF Walls & Ceiling	136.10 SF Floor
15.12 SY Flooring	41.00 LF Floor Perimeter
46.67 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

3' X 6' 8"

Opens into ROOM2

Door

2' 8" X 6' 8"

Opens into WALKIN\_CLOS1


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,102. 5/8" drywall - hung, taped, floated, ready for paint	8.00 SF		0.00	2.87	0.54	4.60	28.10
7,103. Batt insulation - 6" - R19 - unfaced batt	5.00 SF		0.00	1.07	0.32	1.08	6.75
7,104. Batt insulation - 8" - R25 - unfaced batt	3.00 SF		0.00	1.43	0.24	0.86	5.39
7,105. Seal/prime then paint the walls and ceiling twice (3 coats)	502.33 SF		0.00	1.84	14.14	184.86	1,123.29
7,106. Baseboard - 3 1/4"	41.00 LF		0.00	3.49	5.97	28.62	177.68
7,107. Seal & paint baseboard - two coats	41.00 LF		0.00	2.24	0.45	18.36	110.65
7,108. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
7,109. Clean and deodorize carpet	136.10 SF		0.00	0.57	0.00	15.52	93.10
7,110. Final cleaning - construction - Residential	136.10 SF		0.00	0.34	0.00	9.26	55.53
Totals: Bedroom					22.57	281.44	1,711.10
Total: 11403					<b>22.57</b>	<b>281.44</b>	<b>1,711.10</b>

### 11404



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	


<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,111. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	71.00 SF		0.00	2.87	4.78	40.76	249.31
7,112. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	136.58 SF		0.00	1.12	10.30	30.60	193.87
7,113. Detach & Reset Light fixture	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
7,114. Paint the walls and ceiling - two coats <i>Ceiling</i> <i>Walls</i>	522.56 SF		0.00	1.36	11.55	142.14	864.37
7,115. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	21.00 SF		0.00	1.07	1.35	4.50	28.32
7,116. Baseboard - 3 1/4"	10.00 LF		0.00	3.49	1.46	6.98	43.34
7,117. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
7,118. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>30.07</b>	<b>269.68</b>	<b>1,647.98</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Utility Room

**Height: 9'**

216.22 SF Walls	40.89 SF Ceiling
257.11 SF Walls & Ceiling	40.89 SF Floor
4.54 SY Flooring	23.33 LF Floor Perimeter
26.00 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,119. Paint the walls and ceiling - two coats	257.11 SF		0.00	1.36	5.68	69.94	425.29
7,120. Final cleaning - construction - Residential	40.89 SF		0.00	0.34	0.00	2.78	16.68
Totals: Utility Room					5.68	72.72	441.97



### Master Bedroom

**Height: 9'**

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,121. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	61.00 SF		0.00	2.87	4.11	35.02	214.20
7,122. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	61.00 SF		0.00	1.07	3.92	13.06	82.25
7,123. Baseboard - 4 1/4"	50.50 LF		0.00	4.14	10.25	41.82	261.14
7,124. Seal & paint baseboard - two coats	50.50 LF		0.00	2.24	0.56	22.62	136.30
7,125. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	612.61 SF		0.00	1.84	17.24	225.44	1,369.88
7,126. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Master Bedroom**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Master Bedroom					36.08	348.96	2,129.74



**Living / Dining Room**

**Height: 9'**

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,127. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	30.00 SF		0.00	2.87	2.02	17.22	105.34
7,128. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	30.00 SF		0.00	1.07	1.93	6.42	40.45
7,129. Paint the walls - two coats <i>Walls</i>	655.11 SF		0.00	1.36	14.48	178.20	1,083.63
7,130. Baseboard - 4 1/4"	68.42 LF		0.00	4.14	13.89	56.66	353.81
7,131. Base shoe	15.00 LF		0.00	1.41	0.75	4.24	26.14
7,132. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
7,133. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
7,134. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					34.59	335.84	2,049.47




**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Total: 11404

**106.42      1,027.20      6,269.16**

**11406**



**Kitchen**

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

<b>Door</b>	<b>1' 8" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall - Goes to Floor</b>	<b>10' 3" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>1/4" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 4 5/8" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>3' 1 3/4" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,135. Paint the walls - two coats	385.98 SF		0.00	1.36	8.53	104.98	638.44
7,136. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
7,137. Mask the floor per square foot - plastic and tape - 4 mil	133.00 SF		0.00	0.35	0.67	9.32	56.54
7,138. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
<b>Totals: Kitchen</b>					<b>9.83</b>	<b>148.82</b>	<b>902.72</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,139. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	60.00 SF		0.00	2.87	4.04	34.44	210.68
7,140. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	60.00 SF		0.00	1.07	3.86	12.84	80.90
7,141. Paint the walls - two coats <i>Walls</i>	655.11 SF		0.00	1.36	14.48	178.20	1,083.63
7,142. Baseboard - 3 1/4"	15.00 LF		0.00	3.49	2.19	10.48	65.02
7,143. Base shoe	15.00 LF		0.00	1.41	0.75	4.24	26.14
7,144. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68
7,145. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
7,146. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
<b>Totals: Living / Dining Room</b>					26.84	313.30	1,906.47
<b>Total: 11406</b>					<b>36.67</b>	<b>462.12</b>	<b>2,809.19</b>

11407



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Bedroom**

**Height: 9'**

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

**Missing Wall**

**4' 11" X 9'**

**Opens into BATHROOM**

**Window**

**4' X 4'**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,147. 5/8" drywall - hung, taped, floated, ready for paint	54.00 SF		0.00	2.87	3.64	31.00	189.62
7,148. Batt insulation - 10" - R30 - unfaced batt	54.00 SF		0.00	1.57	5.59	16.96	107.33
7,149. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
7,150. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
7,151. Mask the floor per square foot - plastic and tape - 4 mil	121.71 SF		0.00	0.35	0.61	8.52	51.73
7,152. Seal/prime then paint the walls and ceiling twice (3 coats)	458.96 SF		0.00	1.84	12.92	168.90	1,026.31
7,153. Clean and deodorize carpet	121.71 SF		0.00	0.57	0.00	13.88	83.25
7,154. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66

Totals: Bedroom 35.57    315.88    1,930.75



**Bathroom**

**Height: 9'**

341.69 SF Walls	81.97 SF Ceiling
423.67 SF Walls & Ceiling	81.97 SF Floor
9.11 SY Flooring	36.58 LF Floor Perimeter
41.92 LF Ceil. Perimeter	

**Door**

**2' 8" X 6' 8"**

**Opens into ENTRY**

**Door**

**2' 8" X 6' 8"**

**Opens into WALKIN\_CLOS**

**Missing Wall**

**4' 11" X 9'**

**Opens into BEDROOM**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,155. 5/8" drywall - hung, taped, floated, ready for paint	32.00 SF		0.00	2.87	2.15	18.36	112.35
7,156. Batt insulation - 10" - R30 - unfaced batt	32.00 SF		0.00	1.57	3.31	10.04	63.59



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,157. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
7,158. Light bar - 3 lights	1.00 EA		0.00	75.99	2.69	15.20	93.88
7,159. Mask the floor per square foot - plastic and tape - 4 mil	81.97 SF		0.00	0.35	0.41	5.74	34.84
7,160. Seal/prime then paint the walls and ceiling twice (3 coats)	423.67 SF		0.00	1.84	11.92	155.92	947.39
7,161. Paint door/window trim & jamb - 2 coats (per side)	3.00 EA		0.00	45.71	1.37	27.42	165.92
7,162. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
7,163. Final cleaning - construction - Residential	81.97 SF		0.00	0.34	0.00	5.58	33.45
<b>Totals: Bathroom</b>					<b>22.39</b>	<b>252.50</b>	<b>1,537.42</b>
<b>Total: 11407</b>					<b>57.96</b>	<b>568.38</b>	<b>3,468.17</b>

11408

Kitchen		Height: 9'
369.50 SF Walls	146.76 SF Ceiling	
516.26 SF Walls & Ceiling	142.34 SF Floor	
15.82 SY Flooring	53.83 LF Floor Perimeter	
34.83 LF Ceil. Perimeter		
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into UTILITY_ROOM</b>
<b>Door</b>	<b>3' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Missing Wall</b>	<b>17' X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,164. Baseboard - 3 1/4"	53.83 LF		0.00	3.49	7.84	37.58	233.29
7,165. Seal & paint baseboard - two coats	53.83 LF		0.00	2.24	0.59	24.12	145.29
7,166. 5/8" drywall - hung, taped, floated, ready for paint	53.83 SF		0.00	2.87	3.63	30.90	189.02




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,167. Batt insulation - 6" - R19 - unfaced batt	107.67 SF		0.00	1.07	6.93	23.04	145.18
7,168. Paint the walls - two coats	369.50 SF		0.00	1.36	8.17	100.50	611.19
7,169. Final cleaning - construction - Residential	142.34 SF		0.00	0.34	0.00	9.68	58.08
Totals: Kitchen					27.16	225.82	1,382.05



### Bathroom


Height: 9'

271.97 SF Walls	63.94 SF Ceiling
335.92 SF Walls & Ceiling	63.94 SF Floor
7.10 SY Flooring	28.84 LF Floor Perimeter
34.17 LF Ceil. Perimeter	

**Door** **2' 8" X 6' 8"** **Opens into CLOSET**

**Door** **2' 8" X 6' 8"** **Opens into HALLWAY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,170. 5/8" drywall - hung, taped, floated, ready for paint	16.00 SF		0.00	2.87	1.08	9.18	56.18
7,171. Seal/prime then paint the walls and ceiling twice (3 coats)	335.92 SF		0.00	1.84	9.45	123.62	751.16
7,172. Final cleaning - construction - Residential	63.94 SF		0.00	0.34	0.00	4.34	26.08
Totals: Bathroom					10.53	137.14	833.42



### Utility Room

Height: 9'

322.00 SF Walls	46.15 SF Ceiling
368.15 SF Walls & Ceiling	46.15 SF Floor
5.13 SY Flooring	35.00 LF Floor Perimeter
38.00 LF Ceil. Perimeter	

**Door** **3' X 6' 8"** **Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,173. Wood door frame & trim (for a 2" x 4" wall)	20.00 LF		0.00	12.46	14.43	49.84	313.47




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,174. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
7,175. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
7,176. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
7,177. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
7,178. Final cleaning - construction - Residential	46.15 SF		0.00	0.34	0.00	3.14	18.83
Totals: Utility Room					39.92	154.68	967.98



### Room1

Height: 9'

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

Window

4' X 4'

Opens into Exterior

Door

2' 8" X 6' 8"


Opens into HALLWAY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,179. 5/8" drywall - hung, taped, floated, ready for paint	32.00 SF		0.00	2.87	2.15	18.36	112.35
7,180. Paint the ceiling - two coats	129.35 SF		0.00	1.36	2.86	35.18	213.96
7,181. Batt insulation - 8" - R25 - unfaced batt	32.00 SF		0.00	1.43	2.60	9.16	57.52
7,182. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
Totals: Room1					7.61	71.50	436.61



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

**Missing Wall**

**17' X 9'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Door**

**4' X 6' 8"**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**1' 1" X 9'**

**Opens into HALLWAY**


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,183. 5/8" drywall - hung, taped, floated, ready for paint	289.60 SF		0.00	2.87	19.50	166.24	1,016.89
7,184. Paint the ceiling - two coats	289.60 SF		0.00	1.36	6.40	78.78	479.04
7,185. Detach & Reset In-wall / In-ceiling speaker	2.00 EA	18.44	0.00	0.00	0.00	7.38	44.26
7,186. Smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
7,187. R&R Light bar - 8 lights	1.00 EA		35.94	118.65	5.33	30.92	190.84
7,188. Crown molding - 3 1/4"	52.58 LF		0.00	4.40	8.77	46.28	286.40
7,189. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
7,190. Baseboard - 3 1/4"	48.58 LF		0.00	3.49	7.08	33.90	210.52
7,191. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12
7,192. Batt insulation - 8" - R25 - unfaced batt	289.60 SF		0.00	1.43	23.58	82.82	520.53
7,193. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
<b>Totals: Living / Dining Room</b>					<b>71.99</b>	<b>521.18</b>	<b>3,198.97</b>
<b>Total: 11408</b>					<b>157.21</b>	<b>1,110.32</b>	<b>6,819.03</b>

**11410**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Kitchen

**Height: 9'**

356.25 SF Walls	116.09 SF Ceiling
472.34 SF Walls & Ceiling	111.67 SF Floor
12.41 SY Flooring	53.92 LF Floor Perimeter
28.92 LF Ceil. Perimeter	

<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into LIVING__DIN</b>
<b>Missing Wall</b>	<b>2' 4" X 9'</b>	<b>Opens into HALLWAY</b>
<b>Door</b>	<b>1' 6" X 6' 8"</b>	<b>Opens into PANTRY</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>7' 7" X 5'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall - Goes to Ceiling</b>	<b>2' 6" X 5'</b>	<b>Opens into KITCHEN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,194. Paint the walls - two coats	356.25 SF		0.00	1.36	7.88	96.90	589.28
7,195. Seal & paint baseboard - two coats	53.92 LF		0.00	2.24	0.60	24.16	145.54
7,196. Mask the floor per square foot - plastic and tape - 4 mil	111.67 SF		0.00	0.35	0.56	7.82	47.46
7,197. Final cleaning - construction - Residential	111.67 SF		0.00	0.34	0.00	7.60	45.57
<b>Totals: Kitchen</b>					<b>9.04</b>	<b>136.48</b>	<b>827.85</b>



### Bedroom

**Height: 9'**

375.72 SF Walls	129.35 SF Ceiling
505.07 SF Walls & Ceiling	129.35 SF Floor
14.37 SY Flooring	42.83 LF Floor Perimeter
45.50 LF Ceil. Perimeter	

<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,198. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	84.00 SF		0.00	2.87	5.66	48.22	294.96
7,199. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	84.00 SF		0.00	1.07	5.40	17.98	113.26



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,200. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Walls</i>	505.07 SF		0.00	1.84	14.21	185.86	1,129.40
7,201. Baseboard - 4 1/4"	42.83 LF		0.00	4.14	8.70	35.46	221.48
7,202. Seal & paint baseboard - two coats	42.83 LF		0.00	2.24	0.47	19.18	115.59
7,203. Final cleaning - construction - Residential	129.35 SF		0.00	0.34	0.00	8.80	52.78
<b>Totals: Bedroom</b>					34.44	315.50	1,927.47



### Living / Dining Room

**Height: 9'**

414.58 SF Walls	289.60 SF Ceiling
704.18 SF Walls & Ceiling	289.60 SF Floor
32.18 SY Flooring	48.58 LF Floor Perimeter
52.58 LF Ceil. Perimeter	

<b>Missing Wall</b>	<b>12' 7" X 9'</b>	<b>Opens into KITCHEN</b>
<b>Missing Wall</b>	<b>4' 1" X 9'</b>	<b>Opens into ENTRY</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Door</b>	<b>4' X 6' 8"</b>	<b>Opens into Exterior</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>
<b>Missing Wall</b>	<b>1' 1" X 9'</b>	<b>Opens into HALLWAY</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,204. Crown molding - 3 1/4"	5.00 LF		0.00	4.40	0.83	4.40	27.23
7,205. Paint crown molding - two coats	52.58 LF		0.00	2.24	0.79	23.56	142.13
7,206. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls</i>	63.00 SF		0.00	2.87	4.24	36.16	221.21
7,207. Batt insulation - 6" - R19 - unfaced batt <i>Walls</i>	63.00 SF		0.00	1.07	4.05	13.48	84.94
7,208. Baseboard - 4 1/4"	48.58 LF		0.00	4.14	9.86	40.22	251.20
7,209. Base shoe	18.00 LF		0.00	1.41	0.90	5.08	31.36
7,210. Seal & paint baseboard - two coats	48.58 LF		0.00	2.24	0.54	21.76	131.12




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,211. Seal & paint base shoe or quarter round	48.58 LF		0.00	1.19	0.54	11.56	69.91
7,212. Casing - 3 1/4"	20.00 LF		0.00	3.19	4.26	12.76	80.82
7,213. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
7,214. Paint the walls - two coats	414.58 SF		0.00	1.36	9.17	112.76	685.76
<i>Walls</i>							
7,215. Final cleaning - construction - Residential	289.60 SF		0.00	0.34	0.00	19.70	118.16
Totals: Living / Dining Room					35.48	310.16	1,896.46
Total: 11410					<b>78.96</b>	<b>762.14</b>	<b>4,651.78</b>

### 11411



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,216. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
7,217. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
7,218. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
7,219. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					5.45	80.48	488.35



**Camp Construction Services**

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



**Living Room**

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,220. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	206.00 SF		0.00	2.87	13.87	118.24	723.33
7,221. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
7,222. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
7,223. Crown molding - 3 1/4"	39.00 LF		0.00	4.40	6.51	34.32	212.43
7,224. Paint crown molding - two coats	40.67 LF		0.00	2.24	0.61	18.22	109.93
7,225. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11

Totals: Living Room 47.46    409.64    2,505.33

Total: 11411 **52.91    490.12    2,993.68**

**11412**



**Kitchen**

**Height: 9'**

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into LIVING\_ROOM**

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,226. Paint the walls - two coats	218.17 SF		0.00	1.36	4.82	59.34	360.87
7,227. Seal & paint baseboard - two coats	27.25 LF		0.00	2.24	0.30	12.20	73.54
7,228. Mask the floor per square foot - plastic and tape - 4 mil	64.74 SF		0.00	0.35	0.33	4.54	27.53
7,229. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
<b>Totals: Kitchen</b>					<b>5.45</b>	<b>80.48</b>	<b>488.35</b>



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall**

**4' 1" X 9'**


**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,230. 5/8" drywall - hung, taped, floated, ready for paint <i>Ceiling</i>	304.00 SF		0.00	2.87	20.47	174.50	1,067.45
7,231. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	154.68 SF		0.00	1.12	11.66	34.64	219.54
7,232. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	526.35 SF		0.00	1.84	14.81	193.70	1,176.99
7,233. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
7,234. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11
<b>Totals: Living Room</b>					<b>59.75</b>	<b>478.22</b>	<b>2,929.02</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Bedroom

Height: 9'

337.25 SF Walls	121.71 SF Ceiling
458.96 SF Walls & Ceiling	121.71 SF Floor
13.52 SY Flooring	39.25 LF Floor Perimeter
39.25 LF Ceil. Perimeter	

Missing Wall

4' 11" X 9'

Opens into BATHROOM

Window

4' X 4'


Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,235. 5/8" drywall - hung, taped, floated, ready for paint	60.00 SF		0.00	2.87	4.04	34.44	210.68
<i>Ceiling</i>							
7,236. Blown-in insulation - 10" depth - R26	121.71 SF		0.00	1.12	9.17	27.26	172.75
<i>Ceiling</i>							
7,237. Paint the ceiling - two coats	121.71 SF		0.00	1.36	2.69	33.10	201.32
<i>Ceiling</i>							
7,238. Ceiling fan - Detach & reset	1.00 EA		0.00	181.11	0.00	36.22	217.33
7,239. Final cleaning - construction - Residential	121.71 SF		0.00	0.34	0.00	8.28	49.66
Totals: Bedroom					15.90	139.30	851.74

Total: 11412

81.10 698.00 4,269.11

11414



### Kitchen

Height: 9'

218.17 SF Walls	64.74 SF Ceiling
282.90 SF Walls & Ceiling	64.74 SF Floor
7.19 SY Flooring	27.25 LF Floor Perimeter
27.42 LF Ceil. Perimeter	

Missing Wall - Goes to Ceiling

5' 5" X 5'

Opens into LIVING\_ROOM

Missing Wall - Goes to Floor

5' 7" X 9'

Opens into ENTRY

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,240. 5/8" drywall - hung, taped, floated, ready for paint	100.00 SF		0.00	2.87	6.73	57.40	351.13
<i>Double layer (ceiling)</i>							




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,241. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	64.74 SF		0.00	1.12	4.88	14.50	91.89
7,242. Paint the ceiling - two coats <i>Ceiling</i>	64.74 SF		0.00	1.36	1.43	17.62	107.10
7,243. Final cleaning - construction - Residential	64.74 SF		0.00	0.34	0.00	4.40	26.41
Totals: Kitchen					13.04	93.92	576.53



### Entry

**Height: 9'**

118.00 SF Walls	40.83 SF Ceiling
158.83 SF Walls & Ceiling	40.83 SF Floor
4.54 SY Flooring	11.17 LF Floor Perimeter
24.25 LF Ceil. Perimeter	

**Missing Wall - Goes to Floor**

**5' 7" X 9'**

**Opens into KITCHEN**

**Missing Wall**

**4' 1" X 9'**

**Opens into LIVING\_ROOM**

**Door**

**1' 10" X 6' 8"**

**Opens into CLOSET**

**Door**

**2' 8" X 6' 8"**

**Opens into BATHROOM**

**Door**

**3' X 6' 8"**

**Opens into Exterior**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,244. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	36.00 SF		0.00	2.87	2.42	20.66	126.40
7,245. Seal/prime then paint the walls and ceiling twice (3 coats)	158.83 SF		0.00	1.84	4.47	58.46	355.18
7,246. Final cleaning - construction - Residential	40.83 SF		0.00	0.34	0.00	2.78	16.66
Totals: Entry					6.89	81.90	498.24



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living Room

**Height: 9'**

371.67 SF Walls	154.68 SF Ceiling
526.35 SF Walls & Ceiling	154.68 SF Floor
17.19 SY Flooring	46.08 LF Floor Perimeter
40.67 LF Ceil. Perimeter	

**Missing Wall - Goes to Ceiling**

**5' 5" X 5'**

**Opens into KITCHEN**

**Window**

**4' X 4'**

**Opens into Exterior**


**Missing Wall**

**4' 1" X 9'**

**Opens into ENTRY**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
7,247. Paint the walls - two coats	371.67 SF		0.00	1.36	8.22	101.10	614.79	
7,248. Seal & paint baseboard - two coats	46.08 LF		0.00	2.24	0.51	20.64	124.37	
7,249. Mask the floor per square foot - plastic and tape - 4 mil	154.68 SF		0.00	0.35	0.78	10.82	65.74	
7,250. Final cleaning - construction - Residential	154.68 SF		0.00	0.34	0.00	10.52	63.11	
Totals: Living Room						9.51	143.08	868.01
Total: 11414						<b>29.44</b>	<b>318.90</b>	<b>1,942.78</b>

**11418**



### Kitchen

**Height: 9'**

385.98 SF Walls	136.58 SF Ceiling
522.56 SF Walls & Ceiling	133.00 SF Floor
14.78 SY Flooring	56.86 LF Floor Perimeter
47.67 LF Ceil. Perimeter	

**Door**

**1' 8" X 6' 8"**

**Opens into PANTRY**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Window**

**4' X 4'**

**Opens into Exterior**

**Missing Wall - Goes to Floor**

**10' 3" X 6' 8"**

**Opens into LIVING\_\_DIN**

**Missing Wall - Goes to Ceiling**

**1/4" X 5'**

**Opens into KITCHEN**

**Missing Wall - Goes to Ceiling**

**7' 4 5/8" X 5'**

**Opens into KITCHEN**

**Missing Wall - Goes to Ceiling**

**3' 1 3/4" X 5'**

**Opens into KITCHEN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,251. 5/8" drywall - hung, taped, floated, ready for paint <i>Double layer (ceiling)</i>	365.00 SF		0.00	2.87	24.58	209.52	1,281.65
7,252. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	136.58 SF		0.00	1.12	10.30	30.60	193.87
7,253. Seal/prime then paint the walls and ceiling twice (3 coats) <i>Ceiling</i>	522.56 SF		0.00	1.84	14.71	192.30	1,168.52
7,254. Detach & Reset Light fixture <i>Wall</i>	1.00 EA	50.85	0.00	0.00	0.00	10.18	61.03
7,255. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	45.00 SF		0.00	1.07	2.89	9.64	60.68
7,256. Baseboard - 4 1/4"	12.00 LF		0.00	4.14	2.44	9.94	62.06
7,257. Base shoe	12.00 LF		0.00	1.41	0.60	3.38	20.90
7,258. Seal & paint baseboard - two coats	56.86 LF		0.00	2.24	0.63	25.48	153.48
7,259. Seal & paint base shoe or quarter round	56.86 LF		0.00	1.19	0.63	13.54	81.83
7,260. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
7,261. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
7,262. Window blind - PVC - 1" - 7.1 to 14 SF	1.00 EA		0.00	62.34	2.00	12.46	76.80
7,263. Final cleaning - construction - Residential	133.00 SF		0.00	0.34	0.00	9.04	54.26
Totals: Kitchen					60.24	535.90	3,275.44



### Bathroom

Height: 9'

293.56 SF Walls	66.75 SF Ceiling
360.31 SF Walls & Ceiling	66.75 SF Floor
7.42 SY Flooring	31.08 LF Floor Perimeter
37.00 LF Ceil. Perimeter	

Door 3' 3" X 6' 8"

Opens into ROOM2

Door 2' 8" X 6' 8"

Opens into MASTER\_BEDRO

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,264. 5/8" drywall - hung, taped, floated, ready for paint	6.00 SF		0.00	2.87	0.40	3.44	21.06
7,265. Batt insulation - 6" - R19 - unfaced batt	6.00 SF		0.00	1.07	0.39	1.28	8.09
7,266. Paint the walls - two coats	293.56 SF		0.00	1.36	6.49	79.84	485.57
7,267. Vinyl plank flooring	66.75 SF		0.00	5.74	20.06	76.64	479.85
7,268. Floor preparation for resilient flooring	66.75 SF		0.00	0.71	0.67	9.48	57.54
7,269. Final cleaning - construction - Residential	66.75 SF		0.00	0.34	0.00	4.54	27.24
<b>Totals: Bathroom</b>					<b>28.01</b>	<b>175.22</b>	<b>1,079.35</b>



### Utility Room

**Height: 9'**

216.22 SF Walls	40.89 SF Ceiling
257.11 SF Walls & Ceiling	40.89 SF Floor
4.54 SY Flooring	23.33 LF Floor Perimeter
26.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into LIVING__DIN					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,270. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
7,271. Washer/Washing machine - Remove & reset	1.00 EA		0.00	46.97	0.00	9.40	56.37
7,272. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
7,273. 5/8" drywall - hung, taped, floated, ready for paint	257.11 SF		0.00	2.87	17.31	147.58	902.80
7,274. Paint the walls and ceiling - two coats	257.11 SF		0.00	1.36	5.68	69.94	425.29
7,275. Vinyl plank flooring	40.89 SF		0.00	5.74	12.29	46.94	293.94
7,276. Baseboard - 3 1/4"	23.33 LF		0.00	3.49	3.40	16.28	101.10
7,277. Seal & paint baseboard - two coats	23.33 LF		0.00	2.24	0.26	10.46	62.98
7,278. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
7,279. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
7,280. Paint casing - two coats	20.00 LF		0.00	2.18	0.30	8.72	52.62
7,281. Floor preparation for resilient flooring	40.89 SF		0.00	0.71	0.41	5.80	35.24




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,282. Light fixture - Standard grade	1.00 EA		0.00	53.27	1.72	10.66	65.65
7,283. Shelving - wire (vinyl coated)	10.00 LF		0.00	10.99	3.86	21.98	135.74
7,284. Casing - 2 1/4"	16.00 LF		0.00	2.23	1.87	7.14	44.69
7,285. Paint casing - one coat	16.00 LF		0.00	1.44	0.16	4.60	27.80
7,286. Final cleaning - construction - Residential	40.89 SF		0.00	0.34	0.00	2.78	16.68
Totals: Utility Room					71.84	452.94	2,789.42



### Bathroom

Height: 9'

266.78 SF Walls	53.06 SF Ceiling
319.83 SF Walls & Ceiling	53.06 SF Floor
5.90 SY Flooring	28.58 LF Floor Perimeter
32.67 LF Ceil. Perimeter	


<b>Door</b>	<b>1' 5" X 6' 8"</b>	<b>Opens into LINEN_CLOSE2</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,287. Toilet - Detach & reset	1.00 EA		0.00	259.99	0.65	52.00	312.64
7,288. Baseboard - 4 1/4"	16.00 LF		0.00	4.14	3.25	13.24	82.73
7,289. Seal & paint baseboard - two coats	28.58 LF		0.00	2.24	0.32	12.80	77.14
7,290. Base shoe	16.00 LF		0.00	1.41	0.80	4.52	27.88
7,291. Seal & paint base shoe or quarter round	28.58 LF		0.00	1.19	0.32	6.80	41.13
7,292. Final cleaning - construction - Commercial	53.06 SF		0.00	0.27	0.00	2.86	17.19
Totals: Bathroom					5.34	92.22	558.71



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267




### Linen Closet

**Height: 9'**

47.56 SF Walls	2.44 SF Ceiling
50.00 SF Walls & Ceiling	2.44 SF Floor
0.27 SY Flooring	4.92 LF Floor Perimeter
6.33 LF Ceil. Perimeter	

DESCRIPTION	QTY	1' 5" X 6' 8"			Opens into BATHROOM			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
7,293. 5/8" drywall - hung, taped, floated, ready for paint	14.00 SF		0.00	2.87	0.94	8.04	49.16	
7,294. Seal/prime then paint the walls and ceiling twice (3 coats)	50.00 SF		0.00	1.84	1.41	18.40	111.81	
7,295. Baseboard - 3 1/4"	4.92 LF		0.00	3.49	0.72	3.44	21.33	
7,296. Seal & paint baseboard - two coats	4.92 LF		0.00	2.24	0.05	2.20	13.27	
7,297. Final cleaning - construction - Residential	2.44 SF		0.00	0.34	0.00	0.16	0.99	
Totals: Linen Closet						3.12	32.24	196.56



### Walk-in Closet

**Height: 9'**

181.72 SF Walls	27.01 SF Ceiling
208.74 SF Walls & Ceiling	27.01 SF Floor
3.00 SY Flooring	19.50 LF Floor Perimeter
22.17 LF Ceil. Perimeter	

DESCRIPTION	QTY	2' 8" X 6' 8"			Opens into BEDROOM_1			TOTAL
		RESET	REMOVE	REPLACE	TAX	O&P		
7,298. 5/8" drywall - hung, taped, floated, ready for paint	44.00 SF		0.00	2.87	2.96	25.26	154.50	
<i>Wall</i>								
7,299. Seal/prime then paint the walls and ceiling twice (3 coats)	208.74 SF		0.00	1.84	5.87	76.82	466.77	
<i>Wall</i>								
7,300. Baseboard - 4 1/4"	11.00 LF		0.00	4.14	2.23	9.10	56.87	
7,301. Seal & paint baseboard - two coats	19.50 LF		0.00	2.24	0.22	8.74	52.64	
7,302. Carpet - Standard grade	31.07 SF		0.00	2.82	5.75	17.52	110.89	
15 % waste added for Carpet - Standard grade.								



**Camp Construction Services**


15139 South Post Oak  
Houston, TX 77053  
713.413.2267

**CONTINUED - Walk-in Closet**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,303. Carpet pad	27.01 SF		0.00	0.63	1.33	3.40	21.75
7,304. Shelving - wire (vinyl coated)	24.67 LF		0.00	10.99	9.52	54.22	334.86
7,305. Sprinkler head/escutcheon - Detach & reset	1.00 EA		0.00	17.44	0.00	3.48	20.92
7,306. Paint door/window trim & jamb - Large - 2 coats (per side)	1.00 EA		0.00	53.78	0.54	10.76	65.08
7,307. Final cleaning - construction - Residential	27.01 SF		0.00	0.34	0.00	1.84	11.02
<b>Totals: Walk-in Closet</b>					<b>28.42</b>	<b>211.14</b>	<b>1,295.30</b>

**Closet**

**Height: 9'**




71.44 SF Walls	5.67 SF Ceiling
77.11 SF Walls & Ceiling	5.67 SF Floor
0.63 SY Flooring	7.33 LF Floor Perimeter
9.67 LF Ceil. Perimeter	

**Door** **2' 4" X 6' 8"** **Opens into LIVING\_\_DIN**

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,308. Carpet - Standard grade 15 % waste added for Carpet - Standard grade.	6.52 SF		0.00	2.82	1.21	3.68	23.28
7,309. Carpet pad	5.67 SF		0.00	0.63	0.28	0.72	4.57
7,310. Casing - 3 1/4"	LF		0.00	3.19	0.00	0.00	0.00
7,311. Paint casing - one coat	16.00 LF		0.00	1.44	0.16	4.60	27.80
<b>Totals: Closet</b>					<b>1.65</b>	<b>9.00</b>	<b>55.65</b>

**Bedroom 1**

**Height: 9'**



388.22 SF Walls	139.97 SF Ceiling
528.19 SF Walls & Ceiling	139.97 SF Floor
15.55 SY Flooring	41.67 LF Floor Perimeter
47.33 LF Ceil. Perimeter	

**Door** **2' 8" X 6' 8"** **Opens into WALKIN\_CLOS**  
**Door** **3' X 6' 8"** **Opens into LIVING\_\_DIN**



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Bedroom 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,312. 5/8" drywall - hung, taped, floated, ready for paint <i>Wall</i>	95.00 SF		0.00	2.87	6.40	54.54	333.59
7,313. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	95.00 SF		0.00	1.07	6.11	20.34	128.10
7,314. Paint the walls and ceiling - two coats <i>Wall</i>	528.19 SF		0.00	1.36	11.68	143.66	873.68
7,315. Baseboard - 3 1/4"	12.50 LF		0.00	3.49	1.82	8.72	54.17
7,316. Seal & paint baseboard - two coats	41.67 LF		0.00	2.24	0.46	18.66	112.46
7,317. Window stool & apron	3.50 LF		0.00	8.09	1.34	5.66	35.32
7,318. Seal & paint window stool and apron	3.50 LF		0.00	5.93	0.12	4.16	25.04
7,319. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
7,320. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	45.71	0.91	18.28	110.61
7,321. Final cleaning - construction - Residential	139.97 SF		0.00	0.34	0.00	9.52	57.11
7,322. Clean and deodorize carpet	139.97 SF		0.00	0.57	0.00	15.96	95.74
Totals: Bedroom 1					41.65	364.36	2,227.75



### Master Bedroom

Height: 9'

450.94 SF Walls	161.67 SF Ceiling
612.61 SF Walls & Ceiling	161.67 SF Floor
17.96 SY Flooring	50.50 LF Floor Perimeter
55.83 LF Ceil. Perimeter	

<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into BATHROOM3</b>
<b>Door</b>	<b>2' 8" X 6' 8"</b>	<b>Opens into LIVING__DIN</b>
<b>Window</b>	<b>4' X 4'</b>	<b>Opens into Exterior</b>

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,323. Door knob - interior	1.00 EA		0.00	41.58	2.15	8.32	52.05
7,324. 5/8" drywall - hung, taped, floated, ready for paint <i>Walls and ceiling</i>	612.61 SF		0.00	2.87	41.25	351.64	2,151.08



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Master Bedroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,325. Batt insulation - 6" - R19 - unfaced batt <i>Wall</i>	450.94 SF		0.00	1.07	29.00	96.50	608.01
7,326. Blown-in insulation - 10" depth - R26 <i>Ceiling</i>	161.67 SF		0.00	1.12	12.19	36.22	229.48
7,327. Paint the walls and ceiling - two coats <i>Walls and ceiling</i>	612.61 SF		0.00	1.36	13.54	166.64	1,013.33
7,328. Baseboard - 3 1/4"	50.50 LF		0.00	3.49	7.36	35.26	218.87
7,329. Seal & paint baseboard - two coats	50.50 LF		0.00	2.24	0.56	22.62	136.30
7,330. Ceiling fan & light	1.00 EA		0.00	324.26	12.81	64.86	401.93
7,331. In-wall / In-ceiling speaker	1.00 EA		0.00	237.59	18.09	47.52	303.20
7,332. Interior door unit	1.00 EA		0.00	269.19	20.94	53.84	343.97
7,333. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	53.15	1.49	21.26	129.05
7,334. Seal & paint casing - two coats	20.00 LF		0.00	2.26	0.26	9.04	54.50
7,335. Shelving - 12" - in place	12.00 LF		0.00	10.47	4.90	25.12	155.66
7,336. Seal & paint wood shelving, 12"- 24" width	12.00 LF		0.00	6.68	0.58	16.04	96.78
7,337. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	18.80	0.00	3.76	22.56
7,338. Detach & Reset Sprinkler head only	1.00 EA	17.44	0.00	0.00	0.00	3.48	20.92
7,339. Window sill	3.00 LF		0.00	3.12	0.27	1.88	11.51
7,340. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
7,341. Window trim set (casing & stop)	20.00 LF		0.00	5.51	5.00	22.04	137.24
7,342. Carpet - Standard grade 15 % waste added for Carpet - Standard grade.	185.92 SF		0.00	2.82	34.38	104.86	663.53
7,343. Carpet pad	161.67 SF		0.00	0.63	7.96	20.38	130.19
7,344. Final cleaning - construction - Residential	161.67 SF		0.00	0.34	0.00	11.00	65.97
<b>Totals: Master Bedroom</b>					213.19	1,131.42	7,001.44



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267



### Living / Dining Room

Height: 9'

655.11 SF Walls	384.72 SF Ceiling
1,039.83 SF Walls & Ceiling	384.72 SF Floor
42.75 SY Flooring	68.42 LF Floor Perimeter
99.00 LF Ceil. Perimeter	

Door	2' 8" X 6' 8"	Opens into UTILITY_ROOM
Door	2' 4" X 6' 8"	Opens into CLOSET2
Door	2' 8" X 6' 8"	Opens into BATHROOM
Door	3' X 6' 8"	Opens into BEDROOM_1
Missing Wall - Goes to Floor	10' 3" X 6' 8"	Opens into KITCHEN
Door	4' X 6' 8"	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Window	4' X 4'	Opens into Exterior
Door	2' 8" X 6' 8"	Opens into MASTER_BEDRO
Door	3' X 6' 8"	Opens into Exterior

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,345. R&R Exterior door - metal - insulated - flush or panel style	1.00 EA		26.95	333.93	24.38	72.18	457.44
7,346. 5/8" drywall - hung, taped, floated, ready for paint	1,039.83 SF		0.00	2.87	70.02	596.86	3,651.19
<i>Wall</i>							
7,347. Batt insulation - 6" - R19 - unfaced batt	127.00 SF		0.00	1.07	8.17	27.18	171.24
<i>Wall</i>							
7,348. Paint the walls and ceiling - two coats	1,039.83 SF		0.00	1.36	22.99	282.84	1,720.00
<i>Wall</i>							
7,349. Light fixture	5.00 EA		0.00	69.13	16.58	69.14	431.37
<i>Double layer (ceiling)</i>							
7,350. Blown-in insulation - 10" depth - R26	384.72 SF		0.00	1.12	29.00	86.18	546.07
<i>Ceiling</i>							
7,351. Finish wood shelving, 12"- 24" width - 1 coat urethane	68.42 LF		0.00	4.61	3.16	63.08	381.66
<i>Ceiling</i>							
7,352. Baseboard - 3 1/4"	60.00 LF		0.00	3.49	8.74	41.88	260.02
7,353. Base shoe	60.00 LF		0.00	1.41	3.02	16.92	104.54
7,354. Seal & paint baseboard - two coats	68.42 LF		0.00	2.24	0.76	30.66	184.68




## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Living / Dining Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,355. Seal & paint base shoe or quarter round	68.42 LF		0.00	1.19	0.76	16.28	98.46
7,356. Paint door slab only - 2 coats (per side)	4.00 EA		0.00	53.15	2.98	42.52	258.10
7,357. Paint door/window trim & jamb - 2 coats (per side)	4.00 EA		0.00	45.71	1.83	36.56	221.23
7,358. Door lockset - exterior	2.00 EA		0.00	50.72	6.14	20.28	127.86
7,359. R&R Exterior double door - alder - paneled	1.00 EA		34.31	1,839.90	166.06	374.84	2,415.11
7,360. Crown molding - 4 1/4"	99.00 LF		0.00	4.86	19.90	96.22	597.26
7,361. Trim board - 1" x 2" - installed (pine)	99.00 LF		0.00	2.96	11.24	58.60	362.88
7,362. Paint crown molding, oversized - one coat	99.00 LF		0.00	1.58	1.19	31.28	188.89
7,363. Seal & paint trim - two coats	99.00 LF		0.00	2.15	1.19	42.58	256.62
7,364. Carpet - Standard grade	442.43 SF		0.00	2.82	81.81	249.54	1,579.00
15 % waste added for Carpet - Standard grade.							
7,365. Carpet pad	384.72 SF		0.00	0.63	18.95	48.48	309.80
7,366. Final cleaning - construction - Residential	384.72 SF		0.00	0.34	0.00	26.16	156.96
Totals: Living / Dining Room					498.87	2,330.26	14,480.38
Total: 11418					<b>952.33</b>	<b>5,334.70</b>	<b>32,960.00</b>

### 11421



#### Utility Room

Height: 8'

156.67 SF Walls	29.17 SF Ceiling
185.83 SF Walls & Ceiling	29.17 SF Floor
3.24 SY Flooring	19.17 LF Floor Perimeter
21.67 LF Ceil. Perimeter	

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,367. Washer/Washing machine - Reset	1.00 EA		0.00	23.49	0.00	4.70	28.19
7,368. Dryer - Remove & reset	1.00 EA		0.00	36.21	0.00	7.24	43.45
7,369. 5/8" drywall - hung, taped, floated, ready for paint	32.00 SF		0.00	2.87	2.15	18.36	112.35



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Utility Room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,370. Seal/prime then paint the walls and ceiling twice (3 coats)	185.83 SF		0.00	1.84	5.23	68.38	415.54
7,371. Baseboard - 4 1/4"	6.00 LF		0.00	4.14	1.22	4.96	31.02
7,372. Seal & paint baseboard - two coats	19.17 LF		0.00	2.24	0.21	8.58	51.73
7,373. Quarter round - 3/4"	6.00 LF		0.00	1.65	0.45	1.98	12.33
7,374. Seal & paint base shoe or quarter round	19.17 LF		0.00	1.19	0.21	4.56	27.58
7,375. Light fixture - Detach & reset	1.00 EA		0.00	50.85	0.00	10.18	61.03
7,376. Shelving - wire (vinyl coated)	6.00 LF		0.00	10.99	2.32	13.18	81.44
7,377. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	45.71	0.46	9.14	55.31
Totals: Utility Room					12.25	151.26	919.97
Total: 11421					<b>12.25</b>	<b>151.26</b>	<b>919.97</b>
Total: Building 11 Interiors					<b>5,339.14</b>	<b>42,015.14</b>	<b>257,426.14</b>

### Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
***Ceiling***							
7,378. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>First Floor - Left Hallway</i>	320.00 SF		0.00	3.35	26.37	214.40	1,312.77
7,379. Blown-in insulation - 14" depth - R38 <i>First Floor - Left Hallway</i>	160.00 SF		0.00	1.50	17.69	48.00	305.69
7,380. Paint the surface area - two coats <i>First Floor - Left Hallway</i>	1,107.82 SF		0.00	1.35	23.38	299.12	1,818.06
7,381. Sprinkler head/escutcheon - Detach & reset <i>First Floor - Left Hallway</i>	14.00 EA		0.00	17.44	0.00	48.84	293.00
7,382. Light fixture - Detach & reset <i>First Floor - Left Hallway</i>	15.00 EA		0.00	50.85	0.00	152.56	915.31
7,383. Ceiling fan - Detach & reset <i>First Floor - Left Hallway</i>	4.00 EA		0.00	181.09	0.00	144.88	869.24
7,384. Exit sign - Detach & reset	3.00 EA		0.00	66.10	0.00	39.66	237.96



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>First Floor - Left Hallway</i>							
7,385. Heat/AC register - Mechanically attached - Detach & reset	7.00 EA		0.00	18.80	0.00	26.32	157.92
<i>First Floor - Left Hallway</i>							
***Walls***							
7,386. 5/8" drywall - hung, taped, heavy texture, ready for paint	450.00 SF		0.00	3.35	37.08	301.50	1,846.08
<i>First Floor - Left Hallway</i>							
7,387. Batt insulation - 4" - R15 - paper / foil faced	225.00 SF		0.00	1.32	18.77	59.40	375.17
<i>First Floor - Left Hallway</i>							
7,388. Paint the surface area - two coats - 2 colors	2,892.97 SF		0.00	1.72	61.06	995.18	6,032.15
<i>First Floor - Left Hallway</i>							
7,389. Trim board - 1" x 2" - installed (pine)	8.00 LF		0.00	2.99	0.93	4.78	29.63
<i>Line item for chair railing in the hallway</i>							
<i>First Floor - Left Hallway</i>							
7,390. Trim board - 1" x 8" - installed (pine)	8.00 LF		0.00	6.15	3.22	9.84	62.26
<i>Line item for baseboard</i>							
<i>First Floor - Left Hallway</i>							
7,391. 2" x 4" lumber (.667 BF per LF)	18.00 LF		0.00	2.99	1.90	10.76	66.48
<i>Line item to cover 2x4 trim where removed with walls.</i>							
<i>First Floor - Left Hallway</i>							
7,392. Paint trim - one coat	34.00 LF		0.00	1.43	0.27	9.72	58.61
<i>Line item to paint chair rail, base board, and 2x4 trim.</i>							
<i>First Floor - Left Hallway</i>							
7,393. Paint door or window opening - 1 coat (per side)	2.00 EA		0.00	30.60	0.63	12.24	74.07
<i>First Floor - Left Hallway</i>							
7,394. Light fixture - Detach & reset	6.00 EA		0.00	50.85	0.00	61.02	366.12
<i>Line item to detach and reset wall sconce emergency lights.</i>							
<i>First Floor - Left Hallway</i>							
7,395. Commercial smoke detector - Detach & reset	4.00 EA		0.00	49.24	0.00	39.40	236.36
<i>First Floor - Left Hallway</i>							
***Ceiling***							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,396. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>First Floor - Central Hallway</i>	320.00 SF		0.00	3.35	26.37	214.40	1,312.77
7,397. Blown-in insulation - 14" depth - R38 <i>First Floor - Central Hallway</i>	260.00 SF		0.00	1.50	28.74	78.00	496.74
7,398. Paint the surface area - two coats <i>First Floor - Central Hallway</i>	846.35 SF		0.00	1.36	18.71	230.20	1,399.95
7,399. Sprinkler head/escutcheon - Detach & reset <i>First Floor - Central Hallway</i>	12.00 EA		0.00	17.44	0.00	41.86	251.14
7,400. Light fixture - Detach & reset <i>First Floor - Central Hallway</i>	10.00 EA		0.00	50.85	0.00	101.70	610.20
7,401. Ceiling fan - Detach & reset <i>First Floor - Central Hallway</i>	2.00 EA		0.00	181.09	0.00	72.44	434.62
7,402. Exit sign - Detach & reset <i>First Floor - Central Hallway</i>	4.00 EA		0.00	66.10	0.00	52.88	317.28
7,403. Heat/AC register - Mechanically attached - Detach & reset <i>First Floor - Central Hallway</i>	8.00 EA		0.00	18.80	0.00	30.08	180.48
***Walls***							
7,404. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>First Floor - Central Hallway</i>	250.00 SF		0.00	3.35	20.60	167.50	1,025.60
7,405. Batt insulation - 4" - R15 - paper / foil faced <i>First Floor - Central Hallway</i>	125.00 SF		0.00	1.32	10.43	33.00	208.43
7,406. Paint the surface area - two coats <i>First Floor - Central Hallway</i>	2,507.19 SF		0.00	1.36	55.43	681.96	4,147.17
7,407. Light fixture - Detach & reset <i>Line item to detach and reset wall sconce emergency lights.</i> <i>First Floor - Central Hallway</i>	11.00 EA		0.00	50.85	0.00	111.88	671.23
7,408. Commercial smoke detector - Detach & reset <i>First Floor - Central Hallway</i>	5.00 EA		0.00	49.24	0.00	49.24	295.44



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
***Ceiling***							
7,409. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>First Floor - Right Hallway</i>	150.00 SF		0.00	3.35	12.36	100.50	615.36
7,410. Blown-in insulation - 14" depth - R38 <i>First Floor - Right Hallway</i>	75.00 SF		0.00	1.50	8.29	22.50	143.29
7,411. Paint the surface area - two coats <i>First Floor - Right Hallway</i>	1,087.88 SF		0.00	1.36	24.05	295.90	1,799.47
7,412. Sprinkler head/escutcheon - Detach & reset <i>First Floor - Right Hallway</i>	16.00 EA		0.00	17.44	0.00	55.80	334.84
7,413. Light fixture - Detach & reset <i>First Floor - Right Hallway</i>	15.00 EA		0.00	50.85	0.00	152.56	915.31
7,414. Ceiling fan - Detach & reset <i>First Floor - Right Hallway</i>	4.00 EA		0.00	181.09	0.00	144.88	869.24
7,415. Exit sign - Detach & reset <i>First Floor - Right Hallway</i>	3.00 EA		0.00	66.10	0.00	39.66	237.96
7,416. Heat/AC register - Mechanically attached - Detach & reset <i>First Floor - Right Hallway</i>	9.00 EA		0.00	18.80	0.00	33.84	203.04
7,417. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>First Floor - Courtyard Left</i>	323.13 SF		0.00	3.35	26.63	216.50	1,325.62
7,418. Paint the surface area - two coats <i>First Floor - Courtyard Left</i>	323.13 SF		0.00	1.36	7.14	87.90	534.50
***Ceiling***							
7,419. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>First Floor - Courtyard Right</i>	64.00 SF		0.00	3.35	5.27	42.88	262.55
7,420. Additional cost for high wall or ceiling - over 14' to 20' <i>First Floor - Courtyard Right</i>	311.25 SF		0.00	0.83	0.00	51.66	310.00
7,421. Blown-in insulation - 14" depth - R38	32.00 SF		0.00	1.50	3.54	9.60	61.14



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>First Floor - Courtyard Right</i>							
7,422. Paint the surface area - two coats	311.25 SF		0.00	1.36	6.88	84.66	514.84
<i>First Floor - Courtyard Right</i>							
7,423. Additional cost for high wall or ceiling - Over 14'	311.25 SF		0.00	0.14	0.00	8.72	52.30
<i>First Floor - Courtyard Right</i>							
***Ceiling***							
7,424. 5/8" drywall - hung, taped, heavy texture, ready for paint	80.00 SF		0.00	3.35	6.59	53.60	328.19
<i>Double Layer</i>							
<i>First Floor - Left Entry</i>							
7,425. Blown-in insulation - 14" depth - R38	40.00 SF		0.00	1.50	4.42	12.00	76.42
<i>First Floor - Left Entry</i>							
7,426. Paint the surface area - two coats	166.46 SF		0.00	1.36	3.68	45.28	275.35
<i>First Floor - Left Entry</i>							
7,427. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
<i>First Floor - Left Entry</i>							
7,428. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
<i>First Floor - Left Entry</i>							
***Ceiling***							
7,429. 5/8" drywall - hung, taped, heavy texture, ready for paint	362.08 SF		0.00	3.35	29.84	242.60	1,485.41
<i>Double Layer</i>							
<i>First Floor - Right Entry</i>							
7,430. Blown-in insulation - 14" depth - R38	181.04 SF		0.00	1.50	20.01	54.32	345.89
<i>First Floor - Right Entry</i>							
7,431. Paint the surface area - two coats	181.04 SF		0.00	1.36	4.00	49.24	299.45
<i>First Floor - Right Entry</i>							
7,432. Sprinkler head/escutcheon - Detach & reset	2.00 EA		0.00	17.44	0.00	6.98	41.86
<i>First Floor - Right Entry</i>							
7,433. Light fixture - Detach & reset	2.00 EA		0.00	50.85	0.00	20.34	122.04
<i>First Floor - Right Entry</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
***Ceiling***							
7,434. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>Second Floor - Left Hallway</i>	585.00 SF		0.00	3.35	48.21	391.96	2,399.92
7,435. Blown-in insulation - 14" depth - R38 <i>Second Floor - Left Hallway</i>	292.50 SF		0.00	1.50	32.34	87.76	558.85
7,436. Paint the surface area - two coats <i>Second Floor - Left Hallway</i>	1,106.40 SF		0.00	1.35	23.35	298.72	1,815.71
7,437. Sprinkler head/escutcheon - Detach & reset <i>Second Floor - Left Hallway</i>	13.00 EA		0.00	17.44	0.00	45.34	272.06
7,438. Light fixture - Detach & reset <i>Second Floor - Left Hallway</i>	17.00 EA		0.00	50.85	0.00	172.90	1,037.35
7,439. Ceiling fan - Detach & reset <i>Second Floor - Left Hallway</i>	4.00 EA		0.00	181.09	0.00	144.88	869.24
7,440. Exit sign - Detach & reset <i>Second Floor - Left Hallway</i>	2.00 EA		0.00	66.10	0.00	26.44	158.64
7,441. Heat/AC register - Mechanically attached - Detach & reset <i>Second Floor - Left Hallway</i>	12.00 EA		0.00	18.80	0.00	45.12	270.72
***Walls***							
7,442. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Second Floor - Left Hallway</i>	369.00 SF		0.00	3.35	30.41	247.24	1,513.80
7,443. Batt insulation - 4" - R15 - paper / foil faced <i>Second Floor - Left Hallway</i>	184.50 SF		0.00	1.32	15.39	48.70	307.63
7,444. Paint the surface area - two coats - 2 colors <i>Second Floor - Left Hallway</i>	2,970.97 SF		0.00	1.72	62.70	1,022.02	6,194.79
7,445. Trim board - 1" x 2" - installed (pine) <i>Line item for chair railing in the hallway.</i> <i>Second Floor - Left Hallway</i>	8.00 LF		0.00	2.99	0.93	4.78	29.63
7,446. Trim board - 1" x 8" - installed (pine)	8.00 LF		0.00	6.15	3.22	9.84	62.26



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Line item for baseboard.</i>							
<i>Second Floor - Left Hallway</i>							
7,447. 2" x 4" lumber (.667 BF per LF)	18.00 LF		0.00	2.99	1.90	10.76	66.48
<i>Line item to cover 2x4 trim where removed with walls.</i>							
<i>Second Floor - Left Hallway</i>							
7,448. Paint trim - one coat	396.67 LF		0.00	1.43	3.19	113.44	683.87
<i>Line item to paint chair rail, base board, and 2x4 trim.</i>							
<i>Second Floor - Left Hallway</i>							
7,449. Light fixture - Detach & reset	6.00 EA		0.00	50.85	0.00	61.02	366.12
<i>Line item to detach and reset wall sconce emergency lights.</i>							
<i>Second Floor - Left Hallway</i>							
7,450. Commercial smoke detector - Detach & reset	3.00 EA		0.00	49.24	0.00	29.54	177.26
<i>Second Floor - Left Hallway</i>							
***Ceiling***							
7,451. 5/8" drywall - hung, taped, heavy texture, ready for paint	677.08 SF		0.00	3.35	55.80	453.64	2,777.66
<i>Double Layer</i>							
<i>Second Floor - Central Hallway</i>							
7,452. Paint the surface area - two coats	846.35 SF		0.00	1.35	17.86	228.52	1,388.95
<i>Second Floor - Central Hallway</i>							
7,453. Sprinkler head/escutcheon - Detach & reset	8.00 EA		0.00	17.44	0.00	27.90	167.42
<i>Second Floor - Central Hallway</i>							
7,454. Light fixture - Detach & reset	8.00 EA		0.00	50.85	0.00	81.36	488.16
<i>Second Floor - Central Hallway</i>							
7,455. Ceiling fan - Detach & reset	4.00 EA		0.00	181.09	0.00	144.88	869.24
<i>Second Floor - Central Hallway</i>							
7,456. Exit sign - Detach & reset	4.00 EA		0.00	66.10	0.00	52.88	317.28
<i>Second Floor - Central Hallway</i>							
7,457. Heat/AC register - Mechanically attached - Detach & reset	8.00 EA		0.00	18.80	0.00	30.08	180.48
<i>Second Floor - Central Hallway</i>							
***Walls***							
7,458. 5/8" drywall - hung, taped, heavy texture, ready for paint	2,507.20 SF		0.00	3.35	206.62	1,679.82	10,285.56



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Second Floor - Central Hallway</i>							
7,459. Batt insulation - 4" - R15 - paper / foil faced	1,253.60 SF		0.00	1.32	104.57	330.96	2,090.28
<i>Second Floor - Central Hallway</i>							
7,460. Paint the surface area - two coats - 2 colors	2,507.19 SF		0.00	1.72	52.91	862.48	5,227.76
<i>Second Floor - Central Hallway</i>							
7,461. Trim board - 1" x 2" - installed (pine)	130.00 LF		0.00	2.99	15.16	77.74	481.60
<i>Line item for chair railing in the hallway.</i>							
<i>Second Floor - Central Hallway</i>							
7,462. Trim board - 1" x 8" - installed (pine)	130.00 LF		0.00	6.15	52.26	159.90	1,011.66
<i>Line item for baseboard.</i>							
<i>Second Floor - Central Hallway</i>							
7,463. 2" x 4" lumber (.667 BF per LF)	40.00 LF		0.00	2.99	4.22	23.92	147.74
<i>Line item to cover 2x4 trim where removed with walls.</i>							
<i>Second Floor - Central Hallway</i>							
7,464. Paint trim - one coat	300.00 LF		0.00	1.43	2.41	85.80	517.21
<i>Line item to paint chair rail, base board, and 2x4 trim.</i>							
<i>Second Floor - Central Hallway</i>							
7,465. Paint door or window opening - 1 coat (per side)	10.00 EA		0.00	30.60	3.17	61.20	370.37
<i>Second Floor - Central Hallway</i>							
7,466. Light fixture - Detach & reset	11.00 EA		0.00	50.85	0.00	111.88	671.23
<i>Line item to detach and reset wall sconce emergency lights.</i>							
<i>Second Floor - Central Hallway</i>							
7,467. Commercial smoke detector - Detach & reset	4.00 EA		0.00	49.24	0.00	39.40	236.36
<i>Second Floor - Central Hallway</i>							
<i>***Ceiling***</i>							
7,468. 5/8" drywall - hung, taped, heavy texture, ready for paint	64.00 SF		0.00	3.35	5.27	42.88	262.55
<i>Double Layer</i>							
<i>Second Floor - Right Hallway</i>							
7,469. Blown-in insulation - 14" depth - R38	32.00 SF		0.00	1.50	3.54	9.60	61.14
<i>Second Floor - Right Hallway</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,470. Paint the surface area - two coats <i>Second Floor - Right Hallway</i>	1,077.06 SF		0.00	1.35	22.73	290.80	1,767.56
7,471. Sprinkler head/escutcheon - Detach & reset <i>Second Floor - Right Hallway</i>	13.00 EA		0.00	17.44	0.00	45.34	272.06
7,472. Light fixture - Detach & reset <i>Second Floor - Right Hallway</i>	18.00 EA		0.00	50.85	0.00	183.06	1,098.36
7,473. Ceiling fan - Detach & reset <i>Second Floor - Right Hallway</i>	4.00 EA		0.00	181.09	0.00	144.88	869.24
7,474. Exit sign - Detach & reset <i>Second Floor - Right Hallway</i>	3.00 EA		0.00	66.10	0.00	39.66	237.96
7,475. Heat/AC register - Mechanically attached - Detach & reset <i>Second Floor - Right Hallway</i> ***Walls***	11.00 EA		0.00	18.80	0.00	41.36	248.16
7,476. Paint the surface area - two coats - 2 colors <i>Second Floor - Right Hallway</i>	3,366.50 SF		0.00	1.72	71.05	1,158.08	7,019.51
7,477. Light fixture - Detach & reset <i>Line item to detach and reset wall sconce emergency lights.</i> <i>Second Floor - Right Hallway</i>	5.00 EA		0.00	50.85	0.00	50.86	305.11
7,478. Commercial smoke detector - Detach & reset <i>Second Floor - Right Hallway</i> ***Ceiling***	2.00 EA		0.00	49.24	0.00	19.70	118.18
7,479. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>Third Floor - Left Hallway</i>	1,770.24 SF		0.00	3.35	145.89	1,186.06	7,262.25
7,480. Blown-in insulation - 14" depth - R38 <i>Third Floor - Left Hallway</i>	885.12 SF		0.00	1.50	97.85	265.54	1,691.07
7,481. Paint the surface area - two coats <i>Third Floor - Left Hallway</i>	1,106.40 SF		0.00	1.35	23.35	298.72	1,815.71
7,482. Sprinkler head/escutcheon - Detach & reset	13.00 EA		0.00	17.44	0.00	45.34	272.06



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Third Floor - Left Hallway</i>							
7,483. Light fixture - Detach & reset	13.00 EA		0.00	50.85	0.00	132.22	793.27
<i>Third Floor - Left Hallway</i>							
7,484. Ceiling fan - Detach & reset	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
<i>Third Floor - Left Hallway</i>							
7,485. Exit sign - Detach & reset	2.00 EA		0.00	66.10	0.00	26.44	158.64
<i>Third Floor - Left Hallway</i>							
7,486. Heat/AC register - Mechanically attached - Detach & reset	8.00 EA		0.00	18.80	0.00	30.08	180.48
<i>Third Floor - Left Hallway</i>							
***Walls***							
7,487. 5/8" drywall - hung, taped, heavy texture, ready for paint	2,970.98 SF		0.00	3.35	244.84	1,990.56	12,188.18
<i>Third Floor - Left Hallway</i>							
7,488. Batt insulation - 4" - R15 - paper / foil faced	1,485.49 SF		0.00	1.32	123.91	392.18	2,476.94
<i>Third Floor - Left Hallway</i>							
7,489. Paint the surface area - two coats - 2 colors	2,970.97 SF		0.00	1.72	62.70	1,022.02	6,194.79
<i>Third Floor - Left Hallway</i>							
7,490. Trim board - 1" x 2" - installed (pine)	163.33 LF		0.00	2.99	19.04	97.68	605.08
<i>Line item for chair railing in the hallway.</i>							
<i>Third Floor - Left Hallway</i>							
7,491. 2" x 4" lumber (.667 BF per LF)	70.00 LF		0.00	2.99	7.39	41.86	258.55
<i>Line item to cover 2x4 trim where removed with walls.</i>							
<i>Third Floor - Left Hallway</i>							
7,492. Paint trim - one coat	396.67 LF		0.00	1.43	3.19	113.44	683.87
<i>Line item to paint chair rail, base board, and 2x4 trim.</i>							
<i>Third Floor - Left Hallway</i>							
7,493. Paint door or window opening - 1 coat (per side)	1.00 EA		0.00	30.60	0.32	6.12	37.04
<i>Third Floor - Left Hallway</i>							
7,494. Light fixture - Detach & reset	4.00 EA		0.00	50.85	0.00	40.68	244.08
<i>Line item to detach and reset wall sconce emergency lights.</i>							
<i>Third Floor - Left Hallway</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,495. Commercial smoke detector - Detach & reset <i>Third Floor - Left Hallway</i> ***Ceiling***	2.00 EA		0.00	49.24	0.00	19.70	118.18
7,496. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>Third Floor - Central Hallway</i>	256.00 SF		0.00	3.35	21.10	171.52	1,050.22
7,497. Blown-in insulation - 14" depth - R38 <i>Third Floor - Central Hallway</i>	128.00 SF		0.00	1.50	14.15	38.40	244.55
7,498. Paint the surface area - two coats <i>Third Floor - Central Hallway</i>	846.35 SF		0.00	1.35	17.86	228.52	1,388.95
7,499. Sprinkler head/escutcheon - Detach & reset <i>Third Floor - Central Hallway</i>	14.00 EA		0.00	17.44	0.00	48.84	293.00
7,500. Light fixture - Detach & reset <i>Third Floor - Central Hallway</i>	4.00 EA		0.00	50.85	0.00	40.68	244.08
7,501. Ceiling fan - Detach & reset <i>Third Floor - Central Hallway</i>	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
7,502. Exit sign - Detach & reset <i>Third Floor - Central Hallway</i>	1.00 EA		0.00	66.10	0.00	13.22	79.32
7,503. Heat/AC register - Mechanically attached - Detach & reset <i>Third Floor - Central Hallway</i> ***Walls***	4.00 EA		0.00	18.80	0.00	15.04	90.24
7,504. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Third Floor - Central Hallway</i>	2,340.00 SF		0.00	3.35	192.84	1,567.80	9,599.64
7,505. Batt insulation - 4" - R15 - paper / foil faced <i>Third Floor - Central Hallway</i>	1,504.32 SF		0.00	1.32	125.48	397.14	2,508.32
7,506. Paint the surface area - two coats - 2 colors <i>Third Floor - Central Hallway</i>	2,507.19 SF		0.00	1.72	52.91	862.48	5,227.76
7,507. Trim board - 1" x 2" - installed (pine) <i>Line item for chair railing in the hallway.</i>	130.00 LF		0.00	2.99	15.16	77.74	481.60



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Third Floor - Central Hallway</i>							
7,508. Trim board - 1" x 8" - installed (pine)	130.00 LF		0.00	6.15	52.26	159.90	1,011.66
<i>Line item for baseboard.</i>							
<i>Third Floor - Central Hallway</i>							
7,509. 2" x 4" lumber (.667 BF per LF)	40.00 LF		0.00	2.99	4.22	23.92	147.74
<i>Line item to cover 2x4 trim where removed with walls.</i>							
<i>Third Floor - Central Hallway</i>							
7,510. Paint trim - one coat	300.00 LF		0.00	1.43	2.41	85.80	517.21
<i>Line item to paint chair rail, base board, and 2x4 trim.</i>							
<i>Third Floor - Central Hallway</i>							
7,511. Paint door or window opening - 1 coat (per side)	1.00 EA		0.00	30.60	0.32	6.12	37.04
<i>Third Floor - Central Hallway</i>							
7,512. Light fixture - Detach & reset	5.00 EA		0.00	50.85	0.00	50.86	305.11
<i>Line item to detach and reset wall sconce emergency lights.</i>							
<i>Third Floor - Central Hallway</i>							
7,513. Commercial smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
<i>Third Floor - Central Hallway</i>							
***Ceiling***							
7,514. 5/8" drywall - hung, taped, heavy texture, ready for paint	128.00 SF		0.00	3.35	10.55	85.76	525.11
<i>Double Layer</i>							
<i>Third Floor - Right Hallway</i>							
7,515. Blown-in insulation - 14" depth - R38	64.00 SF		0.00	1.50	7.08	19.20	122.28
<i>Third Floor - Right Hallway</i>							
7,516. Paint the surface area - two coats	1,077.06 SF		0.00	1.35	22.73	290.80	1,767.56
<i>Third Floor - Right Hallway</i>							
7,517. Sprinkler head/escutcheon - Detach & reset	12.00 EA		0.00	17.44	0.00	41.86	251.14
<i>Third Floor - Right Hallway</i>							
7,518. Light fixture - Detach & reset	11.00 EA		0.00	50.85	0.00	111.88	671.23
<i>Third Floor - Right Hallway</i>							
7,519. Ceiling fan - Detach & reset	4.00 EA		0.00	181.09	0.00	144.88	869.24
<i>Third Floor - Right Hallway</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,520. Exit sign - Detach & reset <i>Third Floor - Right Hallway</i>	3.00 EA		0.00	66.10	0.00	39.66	237.96
7,521. Heat/AC register - Mechanically attached - Detach & reset <i>Third Floor - Right Hallway</i> ***Walls***	12.00 EA		0.00	18.80	0.00	45.12	270.72
7,522. Paint the surface area - two coats - 2 colors <i>Third Floor - Right Hallway</i>	3,366.50 SF		0.00	1.72	71.05	1,158.08	7,019.51
7,523. Light fixture - Detach & reset <i>Line item to detach and reset wall sconce emergency lights.</i> <i>Third Floor - Right Hallway</i>	5.00 EA		0.00	50.85	0.00	50.86	305.11
7,524. Commercial smoke detector - Detach & reset <i>Third Floor - Right Hallway</i> ***Ceiling***	2.00 EA		0.00	49.24	0.00	19.70	118.18
7,525. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Double Layer</i> <i>Fourth Floor - Left Hallway</i>	4,425.62 SF		0.00	3.35	364.72	2,965.16	18,155.71
7,526. Blown-in insulation - 14" depth - R38 <i>Fourth Floor - Left Hallway</i>	1,106.40 SF		0.00	1.50	122.31	331.92	2,113.83
7,527. Paint the surface area - two coats <i>Fourth Floor - Left Hallway</i>	1,106.40 SF		0.00	1.35	23.35	298.72	1,815.71
7,528. Sprinkler head/escutcheon - Detach & reset <i>Fourth Floor - Left Hallway</i>	12.00 EA		0.00	17.44	0.00	41.86	251.14
7,529. Light fixture - Detach & reset <i>Fourth Floor - Left Hallway</i>	15.00 EA		0.00	50.85	0.00	152.56	915.31
7,530. Ceiling fan - Detach & reset <i>Fourth Floor - Left Hallway</i>	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
7,531. Exit sign - Detach & reset <i>Fourth Floor - Left Hallway</i>	1.00 EA		0.00	66.10	0.00	13.22	79.32
7,532. Remove Special Doors - Ceiling access <i>Fourth Floor - Left Hallway</i>	1.00 EA		11.79	0.00	0.00	2.36	14.15



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,533. Install Special Doors - Ceiling access <i>Fourth Floor - Left Hallway</i>	1.00 EA		0.00	46.22	0.00	9.24	55.46
7,534. Heat/AC register - Mechanically attached - Detach & reset <i>Fourth Floor - Left Hallway</i> ***Walls***	10.00 EA		0.00	18.80	0.00	37.60	225.60
7,535. 5/8" drywall - hung, taped, heavy texture, ready for paint <i>Fourth Floor - Left Hallway</i>	3,543.84 SF		0.00	3.35	292.05	2,374.38	14,538.29
7,536. Batt insulation - 4" - R15 - paper / foil faced <i>Fourth Floor - Left Hallway</i>	1,771.92 SF		0.00	1.32	147.80	467.78	2,954.51
7,537. Paint the surface area - two coats - 2 colors <i>Fourth Floor - Left Hallway</i>	2,953.19 SF		0.00	1.72	62.33	1,015.90	6,157.72
7,538. Trim board - 1" x 2" - installed (pine) <i>Line item for chair railing in the hallway.</i> <i>Fourth Floor - Left Hallway</i>	162.00 LF		0.00	2.99	18.89	96.88	600.15
7,539. Trim board - 1" x 8" - installed (pine) <i>Line item for baseboard.</i> <i>Fourth Floor - Left Hallway</i>	162.00 LF		0.00	6.15	65.12	199.26	1,260.68
7,540. 2" x 4" lumber (.667 BF per LF) <i>Line item to cover 2x4 trim where removed with walls.</i> <i>Fourth Floor - Left Hallway</i>	110.00 LF		0.00	2.99	11.61	65.78	406.29
7,541. Paint trim - one coat <i>Line item to paint chair rail, base board, and 2x4 trim.</i> <i>Fourth Floor - Left Hallway</i>	434.00 LF		0.00	1.43	3.49	124.12	748.23
7,542. Paint door or window opening - 1 coat (per side) <i>Fourth Floor - Left Hallway</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
7,543. Light fixture - Detach & reset <i>Line item to detach and reset wall sconce emergency lights.</i> <i>Fourth Floor - Left Hallway</i>	2.00 EA		0.00	50.85	0.00	20.34	122.04
7,544. Commercial smoke detector - Detach & reset	2.00 EA		0.00	49.24	0.00	19.70	118.18



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Fourth Floor - Left Hallway</i>							
***Ceiling***							
7,545. 5/8" drywall - hung, taped, heavy texture, ready for paint	256.00 SF		0.00	3.35	21.10	171.52	1,050.22
<i>Double Layer</i>							
<i>Fourth Floor - Central Hallway</i>							
7,546. Blown-in insulation - 14" depth - R38	128.00 SF		0.00	1.50	14.15	38.40	244.55
<i>Fourth Floor - Central Hallway</i>							
7,547. Paint the surface area - two coats	846.35 SF		0.00	1.35	17.86	228.52	1,388.95
<i>Fourth Floor - Central Hallway</i>							
7,548. Sprinkler head/escutcheon - Detach & reset	14.00 EA		0.00	17.44	0.00	48.84	293.00
<i>Fourth Floor - Central Hallway</i>							
7,549. Light fixture - Detach & reset	15.00 EA		0.00	50.85	0.00	152.56	915.31
<i>Fourth Floor - Central Hallway</i>							
7,550. Ceiling fan - Detach & reset	5.00 EA		0.00	181.09	0.00	181.10	1,086.55
<i>Fourth Floor - Central Hallway</i>							
7,551. Exit sign - Detach & reset	1.00 EA		0.00	66.10	0.00	13.22	79.32
<i>Fourth Floor - Central Hallway</i>							
7,552. Remove Special Doors - Ceiling access	1.00 EA		11.79	0.00	0.00	2.36	14.15
<i>Fourth Floor - Central Hallway</i>							
7,553. Install Special Doors - Ceiling access	1.00 EA		0.00	46.22	0.00	9.24	55.46
<i>Fourth Floor - Central Hallway</i>							
7,554. Heat/AC register - Mechanically attached - Detach & reset	4.00 EA		0.00	18.80	0.00	15.04	90.24
<i>Fourth Floor - Central Hallway</i>							
***Walls***							
7,555. 5/8" drywall - hung, taped, heavy texture, ready for paint	2,340.00 SF		0.00	3.35	192.84	1,567.80	9,599.64
<i>Fourth Floor - Central Hallway</i>							
7,556. Batt insulation - 4" - R15 - paper / foil faced	1,504.32 SF		0.00	1.32	125.48	397.14	2,508.32
<i>Fourth Floor - Central Hallway</i>							
7,557. Paint the surface area - two coats - 2 colors	2,507.19 SF		0.00	1.72	52.91	862.48	5,227.76



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Fourth Floor - Central Hallway</i>							
7,558. Trim board - 1" x 2" - installed (pine)	130.00 LF		0.00	2.99	15.16	77.74	481.60
<i>Line item for chair railing in the hallway.</i>							
<i>Fourth Floor - Central Hallway</i>							
7,559. Trim board - 1" x 8" - installed (pine)	130.00 LF		0.00	6.15	52.26	159.90	1,011.66
<i>Line item for baseboard.</i>							
<i>Fourth Floor - Central Hallway</i>							
7,560. 2" x 4" lumber (.667 BF per LF)	40.00 LF		0.00	2.99	4.22	23.92	147.74
<i>Line item to cover 2x4 trim where removed with walls.</i>							
<i>Fourth Floor - Central Hallway</i>							
7,561. Paint trim - one coat	300.00 LF		0.00	1.43	2.41	85.80	517.21
<i>Line item to paint chair rail, base board, and 2x4 trim.</i>							
<i>Fourth Floor - Central Hallway</i>							
7,562. Paint door or window opening - 1 coat (per side)	1.00 EA		0.00	30.60	0.32	6.12	37.04
<i>Fourth Floor - Central Hallway</i>							
7,563. Light fixture - Detach & reset	5.00 EA		0.00	50.85	0.00	50.86	305.11
<i>Line item to detach and reset wall sconce emergency lights.</i>							
<i>Fourth Floor - Central Hallway</i>							
7,564. Commercial smoke detector - Detach & reset	1.00 EA		0.00	49.24	0.00	9.84	59.08
<i>Fourth Floor - Central Hallway</i>							
***Ceiling***							
7,565. 5/8" drywall - hung, taped, heavy texture, ready for paint	845.00 SF		0.00	3.35	69.64	566.16	3,466.55
<i>Double Layer</i>							
<i>Fourth Floor - Right Hallway</i>							
7,566. Blown-in insulation - 14" depth - R38	422.50 SF		0.00	1.50	46.71	126.76	807.22
<i>Fourth Floor - Right Hallway</i>							
7,567. Paint the surface area - two coats	1,077.06 SF		0.00	1.35	22.73	290.80	1,767.56
<i>Fourth Floor - Right Hallway</i>							
7,568. Sprinkler head/escutcheon - Detach & reset	12.00 EA		0.00	17.44	0.00	41.86	251.14
<i>Fourth Floor - Right Hallway</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Breezeways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,569. Light fixture - Detach & reset <i>Fourth Floor - Right Hallway</i>	11.00 EA		0.00	50.85	0.00	111.88	671.23
7,570. Ceiling fan - Detach & reset <i>Fourth Floor - Right Hallway</i>	4.00 EA		0.00	181.09	0.00	144.88	869.24
7,571. Exit sign - Detach & reset <i>Fourth Floor - Right Hallway</i>	3.00 EA		0.00	66.10	0.00	39.66	237.96
7,572. Remove Special Doors - Ceiling access <i>Fourth Floor - Right Hallway</i>	1.00 EA		11.79	0.00	0.00	2.36	14.15
7,573. Install Special Doors - Ceiling access <i>Fourth Floor - Right Hallway</i>	1.00 EA		0.00	46.22	0.00	9.24	55.46
7,574. Heat/AC register - Mechanically attached - Detach & reset <i>Fourth Floor - Right Hallway</i>	12.00 EA		0.00	18.80	0.00	45.12	270.72
***Walls***							
7,575. Paint the surface area - two coats - 2 colors <i>Fourth Floor - Right Hallway</i>	3,366.50 SF		0.00	1.72	71.05	1,158.08	7,019.51
7,576. Paint door or window opening - 1 coat (per side) <i>Fourth Floor - Right Hallway</i>	1.00 EA		0.00	30.60	0.32	6.12	37.04
7,577. Light fixture - Detach & reset <i>Line item to detach and reset wall sconce emergency lights.</i> <i>Fourth Floor - Right Hallway</i>	6.00 EA		0.00	50.85	0.00	61.02	366.12
7,578. Commercial smoke detector - Detach & reset <i>Fourth Floor - Right Hallway</i>	2.00 EA		0.00	49.24	0.00	19.70	118.18
7,579. Carpenter - General Framer - per hour <i>Labor to install drywall nailers.</i>	40.00 HR		0.00	72.00	0.00	576.00	3,456.00
Totals: Breezeways					4,513.24	43,043.54	262,772.77

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,580. Clean with pressure/chemical spray	39,000. SF 00		0.00	0.43	39.20	3,354.00	20,163.20
7,581. Exterior - paint two coats	39,000. SF 00		0.00	1.58	1,254.24	12,324.00	75,198.24
7,582. Electrician - per hour	80.00 HR		0.00	95.03	0.00	1,520.48	9,122.88
<i>Labor to detach and reset misc to prep for paint.</i>							
7,583. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
7,584. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance</i>							
7,585. R&R Window screen, 1 - 9 SF	81.00 EA		4.74	36.30	255.20	664.84	4,244.28
7,586. Reglaze window, 1 - 9 sf	1.00 EA		0.00	78.39	3.98	15.68	98.05
7,587. R&R Gutter / downspout - aluminum - 7" to 8"	160.00 LF		0.63	17.54	210.97	581.44	3,699.61
<b>160 LF Downspout.</b>							
7,588. R&R Light fixture - wall sconce - High grade	1.00 EA		10.49	155.78	12.06	33.26	211.59
7,589. R&R Clothes dryer vent cover	3.00 EA		4.72	41.86	2.07	27.96	169.77
7,590. R&R Bifold door set - full louvered - Double	3.00 EA		18.86	468.16	106.74	292.22	1,860.02
7,591. Paint full louvered door slab only - 2 coats (per side)	6.00 EA		0.00	74.43	4.52	89.32	540.42
Totals: Exteriors					2,033.20	21,290.56	129,776.44

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,633. Crane and operator - 14 ton capacity - 65' extension boom	160.00 HR						AS INCURRED
7,634. Telehandler/forklift and operator	160.00 HR						AS INCURRED
7,635. Scaffold - per section (per month)	16.00 MO		0.00	112.88	0.00	361.22	2,167.30
7,636. Commercial Supervision / Project Management - per hour	248.00 HR		0.00	68.91	0.00	3,417.94	20,507.62
7,637. General Laborer - per hour	360.00 HR		0.00	37.61	0.00	2,707.92	16,247.52
7,638. Temporary toilet (per month)	12.00 MO						AS INCURRED
7,639. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,640. Hand wash station	6.00 MO						AS INCURRED
7,641. Job-site cargo/storage container - 40' long - per month	2.00 MO		0.00	115.84	0.00	46.34	278.02
7,642. Delivery charge (Bid Item)	2.00 EA		0.00	150.00	0.00	60.00	360.00
7,643. OSHA compliance safety monitor- per hour	HR		0.00	65.00	0.00	0.00	0.00
7,644. Caution tape	500.00 LF						AS INCURRED
7,645. Overhead safety monitor - per hour	HR						AS INCURRED
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
7,646. Taxes, insurance, permits & fees (Bid Item)	1.00 EA						AS INCURRED
7,647. Light bulb - Incand. standard bulb - 1000 hr - mat. only	93.00 EA		0.00	0.79	7.38	14.70	95.55
Totals: GENERAL CONDITIONS					66.88	6,726.52	40,425.93
Total: SAULET-BLDG-11-V5_23					<b>11,952.46</b>	<b>113,075.76</b>	<b>690,401.28</b>

### SAULET-OFFICE-V5\_23

#### Corridors/Hallways

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,648. R&R 5/8" drywall - hung, taped, floated, ready for paint <i>Allowance 10%</i>	1,131.60 SF		0.53	2.87	76.20	769.50	4,693.14
7,649. Seal/prime then paint the surface area twice (3 coats) <i>Estimated allowance</i>	11,316.00 SF		0.00	1.84	318.43	4,164.28	25,304.15
7,650. Electrician - per hour <i>Labor to detach and reset misc to prep for paint.</i>	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
7,651. Painter - per hour <i>Misc labor to prep for paint.</i>	24.00 HR		0.00	105.46	0.00	506.20	3,037.24
Totals: Corridors/Hallways					394.63	6,200.22	37,595.97

#### Interiors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
-------------	-----	-------	--------	---------	-----	-----	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Interiors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,652. Paint the surface area - two coats	4,500.00 SF		0.00	1.36	99.50	1,224.00	7,443.50
7,653. Mask the surface area per square foot - plastic and tape - 4 mil	4,500.00 SF		0.00	0.35	22.61	315.00	1,912.61
7,654. Paint baseboard - two coats	250.00 LF		0.00	2.16	3.27	108.00	651.27
7,655. Paint door/window trim & jamb - 2 coats (per side)	30.00 EA		0.00	45.71	13.69	274.26	1,659.25
7,656. Final cleaning - construction - Residential	4,500.00 SF		0.00	0.34	0.00	306.00	1,836.00
Totals: Interiors					139.07	2,227.26	13,502.63

### Exteriors

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,657. Clean with pressure/chemical spray	10,560. SF 00		0.00	0.43	10.61	908.16	5,459.57
7,658. Exterior - paint two coats	10,560. SF 00		0.00	1.58	339.61	3,336.96	20,361.37
7,659. R&R Metal lath & stucco	20.00 SF		0.95	7.58	2.41	34.12	207.13
<b>Stucco Repairs.</b>							
7,660. Seal & paint stucco	76.00 SF		0.00	2.03	1.91	30.86	187.05
7,661. Electrician - per hour	40.00 HR		0.00	95.03	0.00	760.24	4,561.44
<i>Labor to detach and reset misc to prep for paint.</i>							
7,662. Painter - per hour	80.00 HR		0.00	105.46	0.00	1,687.36	10,124.16
<i>Additional misc labor to prep for paint.</i>							
7,663. Siding	1.00 EA		0.00	3,500.00	144.22	700.00	4,344.22
<i>Allowance.</i>							
7,664. R&R Shutters - wood - louvered or paneled - Large	2.00 EA		7.86	358.97	52.66	146.72	933.04
7,665. Seal & paint window shutters - per set	2.00 EA		0.00	46.58	1.09	18.64	112.89
Totals: Exteriors					552.51	7,623.06	46,290.87

### Exterior Lighting

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,695. R&R Exterior post light fixture - High grade	12.00 EA		47.46	2,369.57	177.28	5,800.86	34,982.50



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - Exterior Lighting

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
<i>Exterior light post on property.</i>							
Totals: Exterior Lighting					177.28	5,800.86	34,982.50

### Fencing

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,696. R&R Ornamental iron fencing - 6' high	250.00 LF		6.29	51.24	551.75	2,876.50	17,810.75
7,697. R&R Electric gate opener	4.00 EA		62.90	1,863.59	560.86	1,541.20	9,808.02
7,698. Prime & paint ornamental fence - per SF	3,000.00 SF		0.00	4.45	262.31	2,670.00	16,282.31
Totals: Fencing					1,374.92	7,087.70	43,901.08

### Parking Garages

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,699. General Laborer - per hour	64.00 HR		0.00	45.00	0.00	576.00	3,456.00
<i>Labor to check and tighten parking deck cabling.</i>							
7,700. R&R Light fixture - High grade	4.00 EA		10.49	100.24	20.50	88.60	552.02
<i>Two (2) in building 5 parking garage. Two (2) in building 9 parking garage.</i>							
Totals: Parking Garages					20.50	664.60	4,008.02

### GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,701. Crane and operator - 14 ton capacity - 65' extension boom	80.00 HR						AS INCURRED
7,702. Telehandler/forklift and operator	160.00 HR						AS INCURRED
7,703. Scaffolding	10,560.00 SF		0.00	0.50	212.26	1,056.00	6,548.26
7,704. Commercial Supervision / Project Management - per hour	100.00 HR		0.00	68.91	0.00	1,378.20	8,269.20
7,705. General Laborer - per hour	320.00 HR		0.00	37.61	0.00	2,407.04	14,442.24
<i>Four (4) laborers at eight (8) hours x fourteen (14) weeks.</i>							



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### CONTINUED - GENERAL CONDITIONS

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
7,706. Temporary toilet (per month)	12.00 MO						AS INCURRED
7,707. Temporary power usage (per month) - Commercial	3.00 MO		0.00	197.34	59.50	118.40	769.92
7,708. Hand wash station	6.00 MO						AS INCURRED
7,709. Job-site cargo/storage container - 40' long - per month	1.00 MO		0.00	115.84	0.00	23.16	139.00
7,710. Delivery charge (Bid Item)	1.00 EA		0.00	150.00	0.00	30.00	180.00
7,711. OSHA compliance safety monitor- per hour	HR						AS INCURRED
7,712. Caution tape	125.00 LF		0.00	0.09	0.13	2.26	13.64
7,713. Overhead safety monitor - per hour	HR						AS INCURRED
<i>Safety monitor to keep residents out of overhead work zones during roof and exterior repairs.</i>							
7,714. Taxes, insurance, permits & fees (Bid Item)	1.00 EA						AS INCURRED
<b>Totals: GENERAL CONDITIONS</b>					<b>271.89</b>	<b>5,015.06</b>	<b>30,362.26</b>
<b>Total: SAULET-OFFICE-V5_23</b>					<b>2,930.80</b>	<b>34,618.76</b>	<b>210,643.33</b>
<b>Line Item Totals: SAULET-B01-OFFICE-V5_23</b>					<b>99,437.06</b>	<b>983,822.60</b>	<b>6,002,351.49</b>



## Camp Construction Services

---

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Grand Total Areas:

786,614. 96	SF Walls	257,613. 51	SF Ceiling	1,044,228. 47	SF Walls and Ceiling
256,995. 47	SF Floor	28,555.05	SY Flooring	91,817.75	LF Floor Perimeter
1,782.00	SF Long Wall	810.00	SF Short Wall	102,625. 71	LF Ceil. Perimeter
252,940. 87	Floor Area	276,599. 53	Total Area	798,665. 91	Interior Wall Area
351,644. 49	Exterior Wall Area	39,046.77	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		



## Camp Construction Services

---

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Summary for Building

Line Item Total	4,919,091.83
Overhead	491,911.30
Profit	491,911.30
Material Sales Tax	99,437.06
	<hr/>
<b>Replacement Cost Value</b>	<b>\$6,002,351.49</b>
<b>Net Claim</b>	<b>\$6,002,351.49</b>
	<hr/> <hr/>

---



**Camp Construction Services**

15139 South Post Oak  
 Houston, TX 77053  
 713.413.2267

**Recap of Taxes, Overhead and Profit**

	<b>Overhead (10%)</b>	<b>Profit (10%)</b>	<b>Material Sales Tax (10.05%)</b>	<b>Manuf. Home Tax (10.05%)</b>	<b>Cleaning Mat'l Tax (0%)</b>	<b>Fabric Cleaning Tax (0%)</b>	<b>Storage Tax (0%)</b>	<b>Local Food Tax (5.6%)</b>
<b>Line Items</b>	491,911.30	491,911.30	99,437.06	0.00	0.00	0.00	0.00	0.00
<b>Total</b>	<b>491,911.30</b>	<b>491,911.30</b>	<b>99,437.06</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Recap by Room

Estimate: SAULET-B01-OFFICE-V5\_23

Area: SAULET-BLDG-01-V5\_23

Area: Building 1 Interiors

Area: 1108

Kitchen	840.21	0.02%
Living / Dining Room	1,891.33	0.04%
Bedroom	1,399.59	0.03%
Closet	573.92	0.01%

---

Area Subtotal: 1108	4,705.05	0.10%
---------------------	----------	-------

Area: 1109

Kitchen	840.21	0.02%
Living / Dining Room	1,891.33	0.04%
Bedroom	1,399.59	0.03%
Closet	573.92	0.01%

---

Area Subtotal: 1109	4,705.05	0.10%
---------------------	----------	-------

Area: 1110

Kitchen	490.45	0.01%
Living Room	1,344.39	0.03%

---

Area Subtotal: 1110	1,834.84	0.04%
---------------------	----------	-------

Area: 1111

Entry	1,533.86	0.03%
Kitchen	1,209.76	0.02%
Living Room	1,667.90	0.03%

---

Area Subtotal: 1111	4,411.52	0.09%
---------------------	----------	-------

Area: 1112

Kitchen	947.57	0.02%
Living / Dining Room	2,198.47	0.04%

---

Area Subtotal: 1112	3,146.04	0.06%
---------------------	----------	-------

Area: 1113

Kitchen	7,071.41	0.14%
Hall Bathroom	666.42	0.01%

SAULET-RECON-V5\_23-B

5/31/2022

Page: 707



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Living / Dining Room</b>	<b>2,343.07</b>	<b>0.05%</b>
<hr/>		
<b>Area Subtotal: 1113</b>	<b>10,080.90</b>	<b>0.20%</b>
<hr/>		
<b>Area: 1119</b>		
<b>Kitchen</b>	<b>929.82</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>2,721.54</b>	<b>0.06%</b>
<b>Bathroom</b>	<b>723.35</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 1119</b>	<b>4,374.71</b>	<b>0.09%</b>
<hr/>		
<b>Area: 1202</b>		
<b>Bathroom</b>	<b>830.46</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 1202</b>	<b>830.46</b>	<b>0.02%</b>
<hr/>		
<b>Area: 1207</b>		
<b>Living / Dining Room</b>	<b>788.67</b>	<b>0.02%</b>
<b>Bathroom</b>	<b>723.35</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 1207</b>	<b>1,512.02</b>	<b>0.03%</b>
<hr/>		
<b>Area: 1208</b>		
<b>Kitchen</b>	<b>1,295.87</b>	<b>0.03%</b>
<b>Living / Dining Room</b>	<b>1,357.74</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 1208</b>	<b>2,653.61</b>	<b>0.05%</b>
<hr/>		
<b>Area: 1209</b>		
<b>Living / Dining Room</b>	<b>1,278.20</b>	<b>0.03%</b>
<b>Closet</b>	<b>684.66</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 1209</b>	<b>1,962.86</b>	<b>0.04%</b>
<hr/>		
<b>Area: 1211</b>		
<b>Entry</b>	<b>592.05</b>	<b>0.01%</b>
<b>Kitchen</b>	<b>1,180.61</b>	<b>0.02%</b>
<b>Bathroom</b>	<b>1,222.92</b>	<b>0.02%</b>
<b>Living Room</b>	<b>4,509.32</b>	<b>0.09%</b>
<hr/>		
<b>Area Subtotal: 1211</b>	<b>7,504.90</b>	<b>0.15%</b>
<hr/>		
<b>Area: 1213</b>		
<b>Bedroom 2</b>	<b>672.28</b>	<b>0.01%</b>
<b>Kitchen</b>	<b>1,419.20</b>	<b>0.03%</b>
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 1213</b>	<b>2,091.48</b>	<b>0.04%</b>
<b>Area: 1214</b>		
<b>Kitchen</b>	<b>776.46</b>	<b>0.02%</b>
<b>Living Room</b>	<b>1,399.00</b>	<b>0.03%</b>
<b>Area Subtotal: 1214</b>	<b>2,175.46</b>	<b>0.04%</b>
<b>Area: 1219</b>		
<b>Master Bedroom</b>	<b>1,226.84</b>	<b>0.02%</b>
<b>Area Subtotal: 1219</b>	<b>1,226.84</b>	<b>0.02%</b>
<b>Area: 1301</b>		
<b>Living Room/Kitchen</b>	<b>2,476.96</b>	<b>0.05%</b>
<b>Area Subtotal: 1301</b>	<b>2,476.96</b>	<b>0.05%</b>
<b>Area: 1308</b>		
<b>Kitchen</b>	<b>1,088.27</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>1,357.74</b>	<b>0.03%</b>
<b>Area Subtotal: 1308</b>	<b>2,446.01</b>	<b>0.05%</b>
<b>Area: 1310</b>		
<b>Bedroom</b>	<b>1,308.28</b>	<b>0.03%</b>
<b>Area Subtotal: 1310</b>	<b>1,308.28</b>	<b>0.03%</b>
<b>Area: 1311</b>		
<b>Entry</b>	<b>925.96</b>	<b>0.02%</b>
<b>Kitchen</b>	<b>7,214.65</b>	<b>0.15%</b>
<b>Bedroom</b>	<b>509.30</b>	<b>0.01%</b>
<b>Walk-in Closet</b>	<b>96.54</b>	
<b>Bathroom</b>	<b>2,596.86</b>	<b>0.05%</b>
<b>Living Room</b>	<b>1,993.06</b>	<b>0.04%</b>
<b>Area Subtotal: 1311</b>	<b>13,336.37</b>	<b>0.27%</b>
<b>Area: 1312</b>		
<b>Master Walk-in Closet</b>	<b>417.29</b>	<b>0.01%</b>
<b>Bedroom 1 Walk-In Closet</b>	<b>274.03</b>	<b>0.01%</b>
<b>Kitchen</b>	<b>1,419.20</b>	<b>0.03%</b>
<b>Area Subtotal: 1312</b>	<b>2,110.52</b>	<b>0.04%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 1316

Kitchen	463.69	0.01%
Living Room	1,336.65	0.03%

### Area: 1317

Kitchen	1,199.71	0.02%
Living / Dining Room	2,640.51	0.05%
Bathroom	723.35	0.01%

---

<b>Area Subtotal: 1317</b>	<b>4,563.57</b>	<b>0.09%</b>
----------------------------	-----------------	--------------

---

<b>Area Subtotal: 1316</b>	<b>6,363.91</b>	<b>0.13%</b>
----------------------------	-----------------	--------------

### Area: 1319

Bedroom 1	2,559.14	0.05%
Kitchen	929.82	0.02%
Living / Dining Room	2,636.76	0.05%
Bathroom	723.35	0.01%

---

<b>Area Subtotal: 1319</b>	<b>6,849.07</b>	<b>0.14%</b>
----------------------------	-----------------	--------------

### Area: 1409

Bedroom	1,037.24	0.02%
Closet	460.78	0.01%

---

<b>Area Subtotal: 1409</b>	<b>1,498.02</b>	<b>0.03%</b>
----------------------------	-----------------	--------------

### Area: 1410

Bedroom	1,268.86	0.03%
---------	----------	-------

---

<b>Area Subtotal: 1410</b>	<b>1,268.86</b>	<b>0.03%</b>
----------------------------	-----------------	--------------

### Area: 1412

Bedroom 1	1,183.09	0.02%
Master Bedroom	998.33	0.02%
Living / Dining Room	2,255.21	0.05%

---

<b>Area Subtotal: 1412</b>	<b>4,436.63</b>	<b>0.09%</b>
----------------------------	-----------------	--------------

### Area: 1413

Master Bath	763.69	0.02%
-------------	--------	-------

---

<b>Area Subtotal: 1413</b>	<b>763.69</b>	<b>0.02%</b>
----------------------------	---------------	--------------

<b>Area Subtotal: Building 1 Interiors</b>	<b>96,074.06</b>	<b>1.95%</b>
--	------------------	--------------

Gym/Clubhouse	6,044.11	0.12%
---------------	----------	-------

Corridors/Hallways	97,135.62	1.97%
--------------------	-----------	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Exteriors	125,377.28	2.55%
GENERAL CONDITIONS	59,935.63	1.22%
<hr/>		
Area Subtotal: SAULET-BLDG-01-V5_23	384,566.70	7.82%
Area: SAULET-BLDG-02-V5_23		
Area: Building 2 Interiors		
Area: Main Level		
Area: 2102		
Kitchen	929.82	0.02%
Living / Dining Room	4,089.66	0.08%
Utility Room	191.25	
Area: 2103		
Bedroom	917.20	0.02%
Kitchen	535.90	0.01%
Living / Dining Room	1,432.29	0.03%
<hr/>		
Area Subtotal: 2103	2,885.39	0.06%
<hr/>		
Area Subtotal: 2102	8,096.12	0.16%
Area: 2107		
Kitchen	1,534.71	0.03%
Living / Dining Room	2,439.18	0.05%
Area: 2108		
Kitchen	1,401.81	0.03%
<hr/>		
Area Subtotal: 2108	1,401.81	0.03%
<hr/>		
Area Subtotal: 2107	5,375.70	0.11%
Area: 2111		
Kitchen	1,129.26	0.02%
Living Room	1,793.23	0.04%
Entry	830.48	0.02%
Area: 2112		
Living / Dining Room	1,583.96	0.03%
Kitchen	905.89	0.02%
Hall Bathroom	720.25	0.01%
<hr/>		
Area Subtotal: 2112	3,210.10	0.07%
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 2111</b>	<b>6,963.07</b>	<b>0.14%</b>
<b>Area: 2115</b>		
<b>Bathroom</b>	<b>828.70</b>	<b>0.02%</b>
<b>Area Subtotal: 2115</b>	<b>828.70</b>	<b>0.02%</b>
<b>Area Subtotal: Main Level</b>	<b>21,263.59</b>	<b>0.43%</b>
<b>Area: 2106</b>		
<b>Living Room</b>	<b>558.06</b>	<b>0.01%</b>
<b>Entry</b>	<b>694.47</b>	<b>0.01%</b>
<b>Area Subtotal: 2106</b>	<b>1,252.53</b>	<b>0.03%</b>
<b>Area: 2202</b>		
<b>Kitchen</b>	<b>277.52</b>	<b>0.01%</b>
<b>Living / Dining Room</b>	<b>788.67</b>	<b>0.02%</b>
<b>Area Subtotal: 2202</b>	<b>1,066.19</b>	<b>0.02%</b>
<b>Area: 2209</b>		
<b>Living / Dining Room</b>	<b>1,788.70</b>	<b>0.04%</b>
<b>Area Subtotal: 2209</b>	<b>1,788.70</b>	<b>0.04%</b>
<b>Area: 2211</b>		
<b>Kitchen</b>	<b>650.02</b>	<b>0.01%</b>
<b>Entry</b>	<b>408.37</b>	<b>0.01%</b>
<b>Area Subtotal: 2211</b>	<b>1,058.39</b>	<b>0.02%</b>
<b>Area: 2213</b>		
<b>Living / Dining Room</b>	<b>2,327.30</b>	<b>0.05%</b>
<b>Kitchen</b>	<b>1,072.69</b>	<b>0.02%</b>
<b>Area Subtotal: 2213</b>	<b>3,399.99</b>	<b>0.07%</b>
<b>Area: 2307</b>		
<b>Master Bedroom</b>	<b>1,443.29</b>	<b>0.03%</b>
<b>Area Subtotal: 2307</b>	<b>1,443.29</b>	<b>0.03%</b>
<b>Area: 2308</b>		
<b>Kitchen</b>	<b>2,276.15</b>	<b>0.05%</b>
<b>Living / Dining Room</b>	<b>1,357.74</b>	<b>0.03%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 2308</b>	<b>3,633.89</b>	<b>0.07%</b>
<b>Area: 2310</b>		
<b>Kitchen</b>	<b>536.16</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,895.12</b>	<b>0.04%</b>
<b>Area Subtotal: 2310</b>	<b>2,431.28</b>	<b>0.05%</b>
<b>Area: 2311</b>		
<b>Kitchen</b>	<b>132.72</b>	
<b>Living Room</b>	<b>1,391.14</b>	<b>0.03%</b>
<b>Entry</b>	<b>773.09</b>	<b>0.02%</b>
<b>Area Subtotal: 2311</b>	<b>2,296.95</b>	<b>0.05%</b>
<b>Area: 2312</b>		
<b>Bedroom 1</b>	<b>1,617.65</b>	<b>0.03%</b>
<b>Hall Bathroom</b>	<b>669.47</b>	<b>0.01%</b>
<b>Area Subtotal: 2312</b>	<b>2,287.12</b>	<b>0.05%</b>
<b>Area: 2313</b>		
<b>Living / Dining Room</b>	<b>1,882.46</b>	<b>0.04%</b>
<b>Hall Bathroom</b>	<b>703.03</b>	<b>0.01%</b>
<b>Area Subtotal: 2313</b>	<b>2,585.49</b>	<b>0.05%</b>
<b>Area: 2410</b>		
<b>Kitchen</b>	<b>490.45</b>	<b>0.01%</b>
<b>Living Room</b>	<b>2,308.63</b>	<b>0.05%</b>
<b>Area Subtotal: 2410</b>	<b>2,799.08</b>	<b>0.06%</b>
<b>Area: 2412</b>		
<b>Bedroom 1</b>	<b>3,015.54</b>	<b>0.06%</b>
<b>Bedroom 2</b>	<b>1,824.92</b>	<b>0.04%</b>
<b>Area Subtotal: 2412</b>	<b>4,840.46</b>	<b>0.10%</b>
<b>Area Subtotal: Building 2 Interiors</b>	<b>52,146.95</b>	<b>1.06%</b>
<b>Corridors/Hallways</b>	<b>96,561.25</b>	<b>1.96%</b>
<b>Exteriors</b>	<b>115,171.84</b>	<b>2.34%</b>
<b>GENERAL CONDITIONS</b>	<b>55,536.53</b>	<b>1.13%</b>
<b>Area Subtotal: SAULET-BLDG-02-V5_23</b>	<b>319,416.57</b>	<b>6.49%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: SAULET-BLDG-03-V5\_23

#### Area: Building 3 Interiors

##### Area: 3103

Living / Dining Room	1,579.72	0.03%
Walk-in Closet	807.78	0.02%
Bedroom	1,618.64	0.03%
Kitchen	202.55	
Bathroom	1,355.26	0.03%
<hr/>		
Area Subtotal: 3103	5,563.95	0.11%

##### Area: 3107

Master Bedroom	331.42	0.01%
<hr/>		
Area Subtotal: 3107	331.42	0.01%

##### Area: 3109

Bedroom	4,738.95	0.10%
Kitchen	9,790.44	0.20%
Pantry	390.08	0.01%
Closet	2,515.57	0.05%
Bathroom	7,660.08	0.16%
Entry	2,167.26	0.04%
Utility Room	1,139.20	0.02%
Living / Dining Room	5,645.27	0.11%
<hr/>		
Area Subtotal: 3109	34,046.85	0.69%

##### Area: 3112

Entry	494.55	0.01%
Bedroom	931.57	0.02%
Bathroom	1,235.47	0.03%
<hr/>		
Area Subtotal: 3112	2,661.59	0.05%

##### Area: 3113

Kitchen	2,096.26	0.04%
Living Room	2,244.23	0.05%
Entry	1,193.15	0.02%
Closet	356.22	0.01%
Bedroom	1,570.02	0.03%
Bathroom	2,486.31	0.05%
Utility Room	465.78	0.01%
<hr/>		
Area Subtotal: 3113	10,411.97	0.21%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 3119

Living / Dining Room	988.89	0.02%
<hr/>		
Area Subtotal: 3119	988.89	0.02%

### Area: 3203

Master Walk-in Closet	660.74	0.01%
Utility Room	610.07	0.01%
Bathroom	325.89	0.01%
Living Room	9,823.66	0.20%
Entry	275.34	0.01%
<hr/>		
Area Subtotal: 3203	11,695.70	0.24%

### Area: 3205

Kitchen	1,511.51	0.03%
Bathroom	345.73	0.01%
Bedroom 1	1,555.72	0.03%
Living / Dining Room	1,227.52	0.02%
<hr/>		
Area Subtotal: 3205	4,640.48	0.09%

### Area: 3208

Kitchen	1,624.06	0.03%
<hr/>		
Area Subtotal: 3208	1,624.06	0.03%

### Area: 3209

Closet	667.76	0.01%
Bedroom	1,477.94	0.03%
Bathroom	824.31	0.02%
Kitchen	1,756.97	0.04%
Living / Dining Room	2,343.93	0.05%
<hr/>		
Area Subtotal: 3209	7,070.91	0.14%

### Area: 3210

Kitchen	701.73	0.01%
Living Room	2,422.55	0.05%
Entry	1,146.19	0.02%
<hr/>		
Area Subtotal: 3210	4,270.47	0.09%

### Area: 3213

Kitchen	5,939.99	0.12%
Living Room	1,241.17	0.03%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Entry	1,001.83	0.02%
Bedroom	1,416.50	0.03%
Bathroom	1,289.05	0.03%
<hr/>		
Area Subtotal: 3213	10,888.54	0.22%
Area: 3215		
Kitchen	1,323.18	0.03%
Bathroom	753.41	0.02%
<hr/>		
Area Subtotal: 3215	2,076.59	0.04%
Area: 3218		
Kitchen	777.74	0.02%
<hr/>		
Area Subtotal: 3218	777.74	0.02%
Area: 3219		
Bedroom	1,112.89	0.02%
Living / Dining Room	2,462.65	0.05%
Kitchen	1,005.05	0.02%
<hr/>		
Area Subtotal: 3219	4,580.59	0.09%
Area: 3303		
Bathroom	801.30	0.02%
Living Room	2,352.19	0.05%
<hr/>		
Area Subtotal: 3303	3,153.49	0.06%
Area: 3305		
Bathroom	210.89	
Living / Dining Room	3,209.60	0.07%
<hr/>		
Area Subtotal: 3305	3,420.49	0.07%
Area: 3306		
Kitchen	613.52	0.01%
Living Room	1,400.26	0.03%
Bedroom	2,353.46	0.05%
<hr/>		
Area Subtotal: 3306	4,367.24	0.09%
Area: 3310		
Kitchen	3,066.28	0.06%
Living Room	5,485.74	0.11%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Entry	931.34	0.02%
Bedroom	592.40	0.01%
Bathroom	473.10	0.01%
Utility Room	143.70	
<hr/>		
Area Subtotal: 3310	10,692.56	0.22%
<b>Area: 3313</b>		
Kitchen	2,672.00	0.05%
Living Room	1,017.21	0.02%
Entry	756.98	0.02%
<hr/>		
Area Subtotal: 3313	4,446.19	0.09%
<b>Area: 3317</b>		
Utility Room	103.45	
<hr/>		
Area Subtotal: 3317	103.45	0.00%
<b>Area: 3409</b>		
Bedroom	1,808.29	0.04%
<hr/>		
Area Subtotal: 3409	1,808.29	0.04%
<b>Area: 3411</b>		
Living Room	736.78	0.01%
Bedroom	1,982.75	0.04%
<hr/>		
Area Subtotal: 3411	2,719.53	0.06%
<hr/>		
Area Subtotal: Building 3 Interiors	132,340.99	2.69%
Corridors/Hallways	92,837.09	1.89%
Exteriors	99,340.01	2.02%
GENERAL CONDITIONS	53,755.08	1.09%
<hr/>		
Area Subtotal: SAULET-BLDG-03-V5_23	378,273.17	7.69%
<b>Area: SAULET-BLDG-04-V5_23</b>		
<b>Area: Building 4 Interiors</b>		
<b>Area: 4101</b>		
Bedroom	4,855.51	0.10%
Bathroom	7,562.39	0.15%
Walk-in Closet	1,941.20	0.04%
Utility Room	523.88	0.01%
Kitchen	4,850.10	0.10%
SAULET-RECON-V5_23-B	5/31/2022	Page: 717



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Entry	821.07	0.02%
Living Room	1,876.88	0.04%
<hr/>		
<b>Area Subtotal: 4101</b>	<b>22,431.03</b>	<b>0.46%</b>
<b>Area: 4106</b>		
Kitchen	773.75	0.02%
Entry	461.91	0.01%
Living / Dining Room	862.53	0.02%
<hr/>		
<b>Area Subtotal: 4106</b>	<b>2,098.19</b>	<b>0.04%</b>
<b>Area: 4107</b>		
Living / Dining Room	1,881.43	0.04%
Kitchen	697.52	0.01%
<hr/>		
<b>Area Subtotal: 4107</b>	<b>2,578.95</b>	<b>0.05%</b>
<b>Area: 4110</b>		
Living Room	6,031.09	0.12%
Entry	184.52	
<hr/>		
<b>Area Subtotal: 4110</b>	<b>6,215.61</b>	<b>0.13%</b>
<b>Area: 4209</b>		
Bathroom	954.76	0.02%
<hr/>		
<b>Area Subtotal: 4209</b>	<b>954.76</b>	<b>0.02%</b>
<b>Area: 4301</b>		
Pantry	111.43	
Kitchen	648.54	0.01%
<hr/>		
<b>Area Subtotal: 4301</b>	<b>759.97</b>	<b>0.02%</b>
<b>Area: 4308</b>		
Bedroom	857.82	0.02%
Living / Dining Room	869.89	0.02%
Kitchen	427.02	0.01%
<hr/>		
<b>Area Subtotal: 4308</b>	<b>2,154.73</b>	<b>0.04%</b>
<b>Area: 4309</b>		
Living Room	4,171.24	0.08%
<hr/>		
<b>Area Subtotal: 4309</b>	<b>4,171.24</b>	<b>0.08%</b>
SAULET-RECON-V5_23-B	5/31/2022	Page: 718



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area: 4310</b>		
Living Room	4,036.51	0.08%
Entry	184.52	
<hr/>		
<b>Area Subtotal: 4310</b>	<b>4,221.03</b>	<b>0.09%</b>
<b>Area: 4312</b>		
Living Room	3,726.95	0.08%
Entry	184.52	
<hr/>		
<b>Area Subtotal: 4312</b>	<b>3,911.47</b>	<b>0.08%</b>
<b>Area: 4402</b>		
Kitchen	352.27	0.01%
Entry	248.56	0.01%
Living Room	974.50	0.02%
<hr/>		
<b>Area Subtotal: 4402</b>	<b>1,575.33</b>	<b>0.03%</b>
<b>Area: 4403</b>		
Living Room	1,793.86	0.04%
<hr/>		
<b>Area Subtotal: 4403</b>	<b>1,793.86</b>	<b>0.04%</b>
<b>Area: 4406</b>		
Bedroom	1,600.40	0.03%
<hr/>		
<b>Area Subtotal: 4406</b>	<b>1,600.40</b>	<b>0.03%</b>
<b>Area: 4407</b>		
Master Bedroom	684.53	0.01%
<hr/>		
<b>Area Subtotal: 4407</b>	<b>684.53</b>	<b>0.01%</b>
<b>Area: 4410</b>		
Master Bedroom	2,535.75	0.05%
Bedroom	1,931.39	0.04%
Living Room	4,278.87	0.09%
Entry	157.99	
<hr/>		
<b>Area Subtotal: 4410</b>	<b>8,904.00</b>	<b>0.18%</b>
<b>Area: 4411</b>		
Master Bedroom	1,158.25	0.02%
Living Room	1,339.01	0.03%
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 4411</b>	<b>2,497.26</b>	<b>0.05%</b>
<b>Area: 4412</b>		
Master Bedroom	2,088.17	0.04%
Bedroom	2,878.53	0.06%
Bathroom	2,464.10	0.05%
Living Room	7,057.19	0.14%
Entry	310.36	0.01%
<b>Area Subtotal: 4412</b>	<b>14,798.35</b>	<b>0.30%</b>
<b>Area: Garage/Storage</b>		
B04G1	1,997.24	0.04%
B451	611.33	0.01%
B452	1,472.20	0.03%
B04G3	1,359.62	0.03%
B04G4	1,630.27	0.03%
<b>Area Subtotal: Garage/Storage</b>	<b>7,070.66</b>	<b>0.14%</b>
<b>Area Subtotal: Building 4 Interiors</b>		
Corridors/Hallways	58,473.25	1.19%
Exteriors	81,363.72	1.65%
GENERAL CONDITIONS	68,417.59	1.39%
<b>Area Subtotal: SAULET-BLDG-04-V5_23</b>	<b>296,675.93</b>	<b>6.03%</b>
<b>Area: SAULET-BLDG-05-V5_23</b>		
<b>Area: Building 5 Interiors</b>		
<b>Area: 5101</b>		
Master Bedroom	1,171.60	0.02%
<b>Area Subtotal: 5101</b>	<b>1,171.60</b>	<b>0.02%</b>
<b>Area: 5102</b>		
Bedroom	868.42	0.02%
Bathroom	993.61	0.02%
<b>Area Subtotal: 5102</b>	<b>1,862.03</b>	<b>0.04%</b>
<b>Area: 5110</b>		
Master Bedroom	689.93	0.01%
Master Bathroom	703.45	0.01%
Living Room	289.11	0.01%
Kitchen / Dining	517.82	0.01%
SAULET-RECON-V5_23-B	5/31/2022	Page: 720



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 5110</b>	<b>2,200.31</b>	<b>0.04%</b>
<b>Area: 5210</b>		
Master Bathroom	153.80	
Living Room	895.24	0.02%
Kitchen / Dining	1,709.51	0.03%
<b>Area Subtotal: 5210</b>	<b>2,758.55</b>	<b>0.06%</b>
<b>Area: 5301</b>		
Living Room	753.00	0.02%
Kitchen / Dining	911.28	0.02%
<b>Area Subtotal: 5301</b>	<b>1,664.28</b>	<b>0.03%</b>
<b>Area: 5302</b>		
Bathroom	186.00	
<b>Area Subtotal: 5302</b>	<b>186.00</b>	<b>0.00%</b>
<b>Area: 5303</b>		
Kitchen	232.64	
Living / Dining Room	658.21	0.01%
<b>Area Subtotal: 5303</b>	<b>890.85</b>	<b>0.02%</b>
<b>Area: 5304</b>		
Living Room	847.37	0.02%
Kitchen / Dining	930.68	0.02%
<b>Area Subtotal: 5304</b>	<b>1,778.05</b>	<b>0.04%</b>
<b>Area: 5309</b>		
Kitchen	997.48	0.02%
Bedroom 1	1,699.43	0.03%
Master Bedroom	668.61	0.01%
Living / Dining Room	2,327.42	0.05%
<b>Area Subtotal: 5309</b>	<b>5,692.94</b>	<b>0.12%</b>
<b>Area: 5311</b>		
Kitchen / Dining	724.22	0.01%
Bathroom	412.61	0.01%
<b>Area Subtotal: 5311</b>	<b>1,136.83</b>	<b>0.02%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 5312

Kitchen / Dining	444.72	0.01%
Bathroom	435.56	0.01%
Living Room	289.11	0.01%

---

<b>Area Subtotal: 5312</b>	<b>1,169.39</b>	<b>0.02%</b>
----------------------------	-----------------	--------------

### Area: 5403

Utility Room	23.92	
--------------	-------	--

---

<b>Area Subtotal: 5403</b>	<b>23.92</b>	<b>0.00%</b>
----------------------------	--------------	--------------

### Area: 5404

Bedroom 1	597.05	0.01%
Master Bedroom	1,762.31	0.04%
Kitchen	957.03	0.02%
Living / Dining Room	2,880.79	0.06%

---

<b>Area Subtotal: 5404</b>	<b>6,197.18</b>	<b>0.13%</b>
----------------------------	-----------------	--------------

### Area: 5405

Bathroom	1,201.37	0.02%
Living / Dining Room	900.05	0.02%

---

<b>Area Subtotal: 5405</b>	<b>2,101.42</b>	<b>0.04%</b>
----------------------------	-----------------	--------------

### Area: 5406

Bedroom	664.80	0.01%
Living / Dining Room	403.46	0.01%

---

<b>Area Subtotal: 5406</b>	<b>1,068.26</b>	<b>0.02%</b>
----------------------------	-----------------	--------------

### Area: 5408

Bathroom	2,821.61	0.06%
Entry Hall	329.12	0.01%
Kitchen	240.72	
Living / Dining Room	900.05	0.02%

---

<b>Area Subtotal: 5408</b>	<b>4,291.50</b>	<b>0.09%</b>
----------------------------	-----------------	--------------

### Area: 5409

Master Bedroom	1,562.97	0.03%
Kitchen	904.72	0.02%
Living / Dining Room	1,663.51	0.03%
Bathroom	903.08	0.02%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 5409</b>	<b>5,034.28</b>	<b>0.10%</b>
<b>Area: 5410</b>		
Living Room	943.10	0.02%
Kitchen / Dining	1,002.70	0.02%
<b>Area Subtotal: 5410</b>	<b>1,945.80</b>	<b>0.04%</b>
<b>Area: 5412</b>		
Kitchen / Dining	838.27	0.02%
Living Room	645.74	0.01%
<b>Area Subtotal: 5412</b>	<b>1,484.01</b>	<b>0.03%</b>
<b>Area Subtotal: Building 5 Interiors</b>	<b>42,657.20</b>	<b>0.87%</b>
Corridors/Breezways	319,582.72	6.50%
Exteriors	97,263.26	1.98%
GENERAL CONDITIONS	23,741.78	0.48%
<b>Area Subtotal: SAULET-BLDG-05-V5_23</b>	<b>483,244.96</b>	<b>9.82%</b>
<b>Area: SAULET-BLDG-06-V5_23</b>		
<b>Area: Building 6 Interiors</b>		
<b>Area: 6101</b>		
Entry	308.31	0.01%
Kitchen	411.13	0.01%
Living Room	1,379.32	0.03%
<b>Area Subtotal: 6101</b>	<b>2,098.76</b>	<b>0.04%</b>
<b>Area: 6103</b>		
Bedroom	2,334.74	0.05%
<b>Area Subtotal: 6103</b>	<b>2,334.74</b>	<b>0.05%</b>
<b>Area: 6107</b>		
Kitchen	1,156.41	0.02%
Living / Dining Room	1,913.69	0.04%
<b>Area Subtotal: 6107</b>	<b>3,070.10</b>	<b>0.06%</b>
<b>Area: 6108</b>		
Bedroom	1,980.59	0.04%
Kitchen / Dining	757.93	0.02%
SAULET-RECON-V5_23-B	5/31/2022	Page: 723



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Utility Room	750.89	0.02%
Living / Dining	1,146.00	0.02%
<hr/>		
<b>Area Subtotal: 6108</b>	<b>4,635.41</b>	<b>0.09%</b>
<b>Area: 6112</b>		
Walk-in Closet	507.35	0.01%
Master Linen Closet	291.44	0.01%
Bathroom	4,637.78	0.09%
Utility Room	650.94	0.01%
Linen Closet	256.11	0.01%
Bedroom	1,441.31	0.03%
Master Walk-in Closet	631.26	0.01%
Master Bedroom	1,497.08	0.03%
Master Bathroom	4,211.20	0.09%
Living Room/kitchen	8,446.06	0.17%
<hr/>		
<b>Area Subtotal: 6112</b>	<b>22,570.53</b>	<b>0.46%</b>
<b>Area: 6203</b>		
Entry	217.06	
Living Room	2,112.91	0.04%
<b>Area: 6210</b>		
Bathroom	1,236.77	0.03%
Master Bedroom	1,352.63	0.03%
Room2	2,740.22	0.06%
<hr/>		
<b>Area Subtotal: 6210</b>	<b>5,329.62</b>	<b>0.11%</b>
<hr/>		
<b>Area Subtotal: 6203</b>	<b>7,659.59</b>	<b>0.16%</b>
<b>Area: 6301</b>		
Kitchen	1,018.58	0.02%
Entry	393.88	0.01%
Living Room	1,414.39	0.03%
<hr/>		
<b>Area Subtotal: 6301</b>	<b>2,826.85</b>	<b>0.06%</b>
<b>Area: 6310</b>		
Bedroom	1,265.62	0.03%
Master Bedroom	1,434.43	0.03%
<hr/>		
<b>Area Subtotal: 6310</b>	<b>2,700.05</b>	<b>0.05%</b>
<b>Area: 6312</b>		
Bedroom	3,373.40	0.07%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Master Bedroom</b>	<b>3,781.37</b>	<b>0.08%</b>
<b>Room2</b>	<b>7,741.99</b>	<b>0.16%</b>
<hr/>		
<b>Area Subtotal: 6312</b>	<b>14,896.76</b>	<b>0.30%</b>
<hr/>		
<b>Area: 6401</b>		
<b>Entry</b>	<b>393.88</b>	<b>0.01%</b>
<b>Kitchen</b>	<b>921.42</b>	<b>0.02%</b>
<b>Living Room</b>	<b>894.68</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 6401</b>	<b>2,209.98</b>	<b>0.04%</b>
<hr/>		
<b>Area: 6403</b>		
<b>Room2</b>	<b>2,288.39</b>	<b>0.05%</b>
<hr/>		
<b>Area Subtotal: 6403</b>	<b>2,288.39</b>	<b>0.05%</b>
<hr/>		
<b>Area: 6404</b>		
<b>Entry</b>	<b>157.99</b>	
<b>Living Room</b>	<b>8,614.89</b>	<b>0.18%</b>
<hr/>		
<b>Area Subtotal: 6404</b>	<b>8,772.88</b>	<b>0.18%</b>
<hr/>		
<b>Area: 6407</b>		
<b>Bedroom 1</b>	<b>2,267.28</b>	<b>0.05%</b>
<b>Kitchen</b>	<b>956.66</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>3,230.31</b>	<b>0.07%</b>
<hr/>		
<b>Area Subtotal: 6407</b>	<b>6,454.25</b>	<b>0.13%</b>
<hr/>		
<b>Area: 6408</b>		
<b>Bedroom</b>	<b>255.98</b>	<b>0.01%</b>
<b>Bedroom</b>	<b>2,629.24</b>	<b>0.05%</b>
<b>Study</b>	<b>2,231.00</b>	<b>0.05%</b>
<b>Walk-in Closet</b>	<b>276.96</b>	<b>0.01%</b>
<b>Study Closet 1</b>	<b>46.04</b>	
<b>Bathroom</b>	<b>1,123.20</b>	<b>0.02%</b>
<b>Study Closet 2</b>	<b>45.09</b>	
<b>Kitchen / Dining</b>	<b>900.74</b>	<b>0.02%</b>
<b>Living / Dining</b>	<b>1,349.32</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 6408</b>	<b>8,857.57</b>	<b>0.18%</b>
<hr/>		
<b>Area: 6410</b>		
<b>Master Bedroom</b>	<b>1,426.23</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 6410</b>	<b>1,426.23</b>	<b>0.03%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 6411

Master Bathroom	1,393.81	0.03%
<hr/>		
Area Subtotal: 6411	1,393.81	0.03%

### Area: 6412

Bedroom	2,247.60	0.05%
Master Bedroom	2,781.75	0.06%
Room2	8,899.43	0.18%
<hr/>		
Area Subtotal: 6412	13,928.78	0.28%
<hr/>		
Area Subtotal: Building 6 Interiors	108,124.68	2.20%
Corridors/Breezways	276,661.04	5.62%
Exteriors	77,261.66	1.57%
GENERAL CONDITIONS	39,325.72	0.80%
<hr/>		
Area Subtotal: SAULET-BLDG-06-V5_23	501,373.10	10.19%

### Area: SAULET-BLDG-07-V5\_23

#### Area: Building 7 Interiors

### Area: 7102

Bathroom	961.37	0.02%
<hr/>		
Area Subtotal: 7102	961.37	0.02%

### Area: 7104

Kitchen	854.42	0.02%
Hallway	172.85	
Living / Dining Room	1,309.83	0.03%
<hr/>		
Area Subtotal: 7104	2,337.10	0.05%

### Area: 7105

Entry	105.45	
Living Room	3,013.70	0.06%
<hr/>		
Area Subtotal: 7105	3,119.15	0.06%

### Area: 7109

Living Room	2,255.03	0.05%
<hr/>		
Area Subtotal: 7109	2,255.03	0.05%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 7114

Bedroom Closet	417.67	0.01%
Bathroom	1,072.04	0.02%
Bedroom	1,280.38	0.03%

---

<b>Area Subtotal: 7114</b>	<b>2,770.09</b>	<b>0.06%</b>
----------------------------	-----------------	--------------

### Area: 7203

Kitchen	984.29	0.02%
Living / Dining Room	2,523.41	0.05%

---

<b>Area Subtotal: 7203</b>	<b>3,507.70</b>	<b>0.07%</b>
----------------------------	-----------------	--------------

### Area: 7206

Kitchen / Dining	2,684.71	0.05%
Living Room	571.24	0.01%

---

<b>Area Subtotal: 7206</b>	<b>3,255.95</b>	<b>0.07%</b>
----------------------------	-----------------	--------------

### Area: 7211

Living / Dining Room	1,861.55	0.04%
----------------------	----------	-------

---

<b>Area Subtotal: 7211</b>	<b>1,861.55</b>	<b>0.04%</b>
----------------------------	-----------------	--------------

### Area: 7213

Room2	2,495.01	0.05%
-------	----------	-------

---

<b>Area Subtotal: 7213</b>	<b>2,495.01</b>	<b>0.05%</b>
----------------------------	-----------------	--------------

### Area: 7304

Entry	432.17	0.01%
Living / Dining Room	862.53	0.02%

---

<b>Area Subtotal: 7304</b>	<b>1,294.70</b>	<b>0.03%</b>
----------------------------	-----------------	--------------

### Area: 7306

Living Room	4,062.10	0.08%
-------------	----------	-------

---

<b>Area Subtotal: 7306</b>	<b>4,062.10</b>	<b>0.08%</b>
----------------------------	-----------------	--------------

### Area: 7313

Bathroom	1,247.64	0.03%
Living Room/Dining/Kitchen	2,594.68	0.05%

---

<b>Area Subtotal: 7313</b>	<b>3,842.32</b>	<b>0.08%</b>
----------------------------	-----------------	--------------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 7402

Bedroom	1,158.67	0.02%
Living Room	2,665.62	0.05%

---

Area Subtotal: 7402	3,824.29	0.08%
---------------------	----------	-------

### Area: 7403

Bedroom	1,389.33	0.03%
---------	----------	-------

---

Area Subtotal: 7403	1,389.33	0.03%
---------------------	----------	-------

### Area: 7405

Utility Room	674.79	0.01%
Bedroom	1,719.44	0.03%
Living Room	4,109.54	0.08%

---

Area Subtotal: 7405	6,503.77	0.13%
---------------------	----------	-------

### Area: 7406

Master Walk-in Closet	515.11	0.01%
Bedroom	1,075.64	0.02%
Bathroom	464.18	0.01%
Kitchen / Dining	1,038.21	0.02%
Living Room	678.42	0.01%

---

Area Subtotal: 7406	3,771.56	0.08%
---------------------	----------	-------

### Area: 7407

Entry	157.06	
Kitchen	523.44	0.01%
Living Room	928.98	0.02%

---

Area Subtotal: 7407	1,609.48	0.03%
---------------------	----------	-------

### Area: 7408

Bathroom	1,115.09	0.02%
----------	----------	-------

### Area: 7409

Bedroom	990.36	0.02%
---------	--------	-------

---

Area Subtotal: 7409	990.36	0.02%
---------------------	--------	-------

---

Area Subtotal: 7408	2,105.45	0.04%
---------------------	----------	-------

### Area: 7411

Living / Dining Room	2,320.37	0.05%
----------------------	----------	-------



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 7411</b>	<b>2,320.37</b>	<b>0.05%</b>
<b>Area: 7412</b>		
<b>Kitchen</b>	<b>234.93</b>	
<b>Entry</b>	<b>58.59</b>	
<b>Living / Dining Room</b>	<b>2,190.76</b>	<b>0.04%</b>
<b>Area Subtotal: 7412</b>	<b>2,484.28</b>	<b>0.05%</b>
<b>Area: 7413</b>		
<b>Bathroom</b>	<b>854.92</b>	<b>0.02%</b>
<b>Area Subtotal: 7413</b>	<b>854.92</b>	<b>0.02%</b>
<b>Area Subtotal: Building 7 Interiors</b>	<b>56,625.52</b>	<b>1.15%</b>
<b>Corridor/Breezeway</b>	<b>34,832.71</b>	<b>0.71%</b>
<b>Exteriors</b>	<b>64,614.84</b>	<b>1.31%</b>
<b>Area: Garage/Storage</b>		
<b>B07G1</b>	<b>1,358.96</b>	<b>0.03%</b>
<b>Area Subtotal: Garage/Storage</b>	<b>1,358.96</b>	<b>0.03%</b>
<b>GENERAL CONDITIONS</b>	<b>21,154.48</b>	<b>0.43%</b>
<b>Area Subtotal: SAULET-BLDG-07-V5_23</b>	<b>178,586.51</b>	<b>3.63%</b>
<b>Area: SAULET-BLDG-08-V5_23</b>		
<b>Area: Building 8 Interiors</b>		
<b>Area: Main Level</b>		
<b>Master Walk-in Closet</b>	<b>1,110.38</b>	<b>0.02%</b>
<b>Bathroom</b>	<b>1,353.15</b>	<b>0.03%</b>
<b>Bedroom</b>	<b>1,075.50</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>2,685.37</b>	<b>0.05%</b>
<b>Area Subtotal: Main Level</b>	<b>6,224.40</b>	<b>0.13%</b>
<b>Area: 8111</b>		
<b>Kitchen</b>	<b>487.40</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,692.48</b>	<b>0.03%</b>
<b>Entry</b>	<b>357.43</b>	<b>0.01%</b>
<b>Area Subtotal: 8111</b>	<b>2,537.31</b>	<b>0.05%</b>
<b>Area: 8113</b>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Kitchen</b>	<b>457.90</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,083.98</b>	<b>0.02%</b>
<b>Bedroom</b>	<b>960.66</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 8113</b>	<b>2,502.54</b>	<b>0.05%</b>
<b>Area: 8115</b>		
<b>Kitchen</b>	<b>484.48</b>	<b>0.01%</b>
<b>Living Room</b>	<b>989.32</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 8115</b>	<b>1,473.80</b>	<b>0.03%</b>
<b>Area: 8126</b>		
<b>Kitchen</b>	<b>1,246.80</b>	<b>0.03%</b>
<b>Entry</b>	<b>652.82</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,835.02</b>	<b>0.04%</b>
<hr/>		
<b>Area Subtotal: 8126</b>	<b>3,734.64</b>	<b>0.08%</b>
<b>Area: 8128</b>		
<b>Bathroom</b>	<b>1,092.48</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 8128</b>	<b>1,092.48</b>	<b>0.02%</b>
<b>Area: 8129</b>		
<b>Bathroom</b>	<b>1,609.72</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 8129</b>	<b>1,609.72</b>	<b>0.03%</b>
<b>Area: 8202</b>		
<b>Master Bath</b>	<b>1,162.67</b>	<b>0.02%</b>
<b>Master Bedroom</b>	<b>1,328.33</b>	<b>0.03%</b>
<b>Living / Dining Room</b>	<b>1,752.55</b>	<b>0.04%</b>
<b>Kitchen</b>	<b>1,035.04</b>	<b>0.02%</b>
<b>Hall Bathroom</b>	<b>700.76</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 8202</b>	<b>5,979.35</b>	<b>0.12%</b>
<b>Area: 8203</b>		
<b>Kitchen</b>	<b>884.19</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>704.73</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 8203</b>	<b>1,588.92</b>	<b>0.03%</b>
<b>Area: 8204</b>		
<b>Kitchen</b>	<b>779.09</b>	<b>0.02%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Entry	773.53	0.02%
Living Room	1,026.34	0.02%
<hr/>		
Area Subtotal: 8204	2,578.96	0.05%
Area: 8210		
Kitchen	573.73	0.01%
Entry	333.34	0.01%
Living Room	1,427.95	0.03%
<hr/>		
Area Subtotal: 8210	2,335.02	0.05%
Area: 8212		
Living / Dining Room	1,436.87	0.03%
Kitchen	852.94	0.02%
<hr/>		
Area Subtotal: 8212	2,289.81	0.05%
Area: 8213		
Utility Room	562.72	0.01%
Bathroom	1,506.30	0.03%
<hr/>		
Area Subtotal: 8213	2,069.02	0.04%
Area: 8222		
Living / Dining Room	873.63	0.02%
<hr/>		
Area Subtotal: 8222	873.63	0.02%
Area: 8224		
Kitchen	996.43	0.02%
Living / Dining Room	2,595.62	0.05%
<hr/>		
Area Subtotal: 8224	3,592.05	0.07%
Area: 8225		
Kitchen	538.85	0.01%
Entry	393.88	0.01%
<hr/>		
Area Subtotal: 8225	932.73	0.02%
Area: 8314		
Bedroom 1	2,488.43	0.05%
<hr/>		
Area Subtotal: 8314	2,488.43	0.05%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area: 8315</b>		
Bathroom	1,139.28	0.02%
<hr/>		
Area Subtotal: 8315	1,139.28	0.02%
<b>Area: 8316</b>		
Bathroom	1,193.86	0.02%
<hr/>		
Area Subtotal: 8316	1,193.86	0.02%
<b>Area: 8320</b>		
Entry	191.86	
Living Room	3,456.81	0.07%
<hr/>		
Area Subtotal: 8320	3,648.67	0.07%
<b>Area: 8322</b>		
Bathroom	1,027.07	0.02%
Entry	191.86	
Living Room	2,131.03	0.04%
<hr/>		
Area Subtotal: 8322	3,349.96	0.07%
<b>Area: 8401</b>		
Bedroom 1	2,012.83	0.04%
<hr/>		
Area Subtotal: 8401	2,012.83	0.04%
<b>Area: 8402</b>		
Master Bedroom	997.35	0.02%
Master Bath	840.58	0.02%
Living / Dining Room	2,572.51	0.05%
Kitchen	1,446.64	0.03%
Bedroom 1	976.25	0.02%
<hr/>		
Area Subtotal: 8402	6,833.33	0.14%
<b>Area: 8405</b>		
Walk-in Closet	529.32	0.01%
Bathroom	1,057.96	0.02%
Bedroom	2,893.47	0.06%
<hr/>		
Area Subtotal: 8405	4,480.75	0.09%
<b>Area: 8406</b>		
Bedroom	1,822.51	0.04%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Kitchen</b>	<b>538.85</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,688.05</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 8406</b>	<b>4,049.41</b>	<b>0.08%</b>
<b>Area: 8407</b>		
<b>Entry</b>	<b>191.86</b>	
<b>Master Bedroom</b>	<b>2,351.33</b>	<b>0.05%</b>
<b>Bedroom</b>	<b>2,243.29</b>	<b>0.05%</b>
<b>Living Room</b>	<b>4,065.32</b>	<b>0.08%</b>
<hr/>		
<b>Area Subtotal: 8407</b>	<b>8,851.80</b>	<b>0.18%</b>
<b>Area: 8408</b>		
<b>Bathroom</b>	<b>1,043.78</b>	<b>0.02%</b>
<b>Walk-in Closet</b>	<b>567.88</b>	<b>0.01%</b>
<b>Bedroom</b>	<b>1,538.81</b>	<b>0.03%</b>
<b>Kitchen</b>	<b>584.56</b>	<b>0.01%</b>
<b>Entry</b>	<b>439.59</b>	<b>0.01%</b>
<b>Living Room</b>	<b>2,342.04</b>	<b>0.05%</b>
<hr/>		
<b>Area Subtotal: 8408</b>	<b>6,516.66</b>	<b>0.13%</b>
<b>Area: 8409</b>		
<b>Utility Room</b>	<b>94.84</b>	
<hr/>		
<b>Area Subtotal: 8409</b>	<b>94.84</b>	<b>0.00%</b>
<b>Area: 8410</b>		
<b>Bedroom</b>	<b>2,192.95</b>	<b>0.04%</b>
<hr/>		
<b>Area Subtotal: 8410</b>	<b>2,192.95</b>	<b>0.04%</b>
<b>Area: 8413</b>		
<b>Kitchen</b>	<b>445.32</b>	<b>0.01%</b>
<b>Entry</b>	<b>386.42</b>	<b>0.01%</b>
<b>Living Room</b>	<b>725.89</b>	<b>0.01%</b>
<b>Bedroom</b>	<b>1,633.62</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 8413</b>	<b>3,191.25</b>	<b>0.06%</b>
<b>Area: 8414</b>		
<b>Master Bedroom</b>	<b>1,848.46</b>	<b>0.04%</b>
<b>Living / Dining Room</b>	<b>1,446.50</b>	<b>0.03%</b>
<b>Kitchen</b>	<b>840.47</b>	<b>0.02%</b>
<b>Bedroom 1</b>	<b>833.72</b>	<b>0.02%</b>
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 8414</b>	<b>4,969.15</b>	<b>0.10%</b>
<b>Area: 8415</b>		
<b>Kitchen</b>	<b>163.79</b>	
<b>Entry</b>	<b>103.30</b>	
<b>Living Room</b>	<b>391.34</b>	<b>0.01%</b>
<b>Area Subtotal: 8415</b>	<b>658.43</b>	<b>0.01%</b>
<b>Area: 8416</b>		
<b>Bedroom</b>	<b>1,137.70</b>	<b>0.02%</b>
<b>Area Subtotal: 8416</b>	<b>1,137.70</b>	<b>0.02%</b>
<b>Area: 8419</b>		
<b>Bedroom</b>	<b>963.97</b>	<b>0.02%</b>
<b>Utility Room</b>	<b>264.68</b>	<b>0.01%</b>
<b>Area Subtotal: 8419</b>	<b>1,228.65</b>	<b>0.02%</b>
<b>Area: 8420</b>		
<b>Living Room</b>	<b>582.08</b>	<b>0.01%</b>
<b>Area Subtotal: 8420</b>	<b>582.08</b>	<b>0.01%</b>
<b>Area: 8421</b>		
<b>Kitchen</b>	<b>318.72</b>	<b>0.01%</b>
<b>Entry</b>	<b>494.34</b>	<b>0.01%</b>
<b>Living Room</b>	<b>558.06</b>	<b>0.01%</b>
<b>Area Subtotal: 8421</b>	<b>1,371.12</b>	<b>0.03%</b>
<b>Area: 8423</b>		
<b>Kitchen</b>	<b>584.25</b>	<b>0.01%</b>
<b>Entry</b>	<b>363.00</b>	<b>0.01%</b>
<b>Bedroom</b>	<b>880.08</b>	<b>0.02%</b>
<b>Living Room</b>	<b>1,604.36</b>	<b>0.03%</b>
<b>Area Subtotal: 8423</b>	<b>3,431.69</b>	<b>0.07%</b>
<b>Area: 8424</b>		
<b>Kitchen</b>	<b>950.08</b>	<b>0.02%</b>
<b>Bedroom</b>	<b>1,365.05</b>	<b>0.03%</b>
<b>Entry</b>	<b>515.45</b>	<b>0.01%</b>
<b>Living / Dining Room</b>	<b>4,356.69</b>	<b>0.09%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 8424</b>	<b>7,187.27</b>	<b>0.15%</b>
<b>Area: 8426</b>		
Bedroom	1,137.70	0.02%
Kitchen	822.01	0.02%
Entry	317.29	0.01%
Living Room	1,086.29	0.02%
<b>Area Subtotal: 8426</b>	<b>3,363.29</b>	<b>0.07%</b>
<b>Area: 8427</b>		
Kitchen	970.65	0.02%
Entry	477.48	0.01%
Living Room	1,192.42	0.02%
<b>Area Subtotal: 8427</b>	<b>2,640.55</b>	<b>0.05%</b>
<b>Area: 8430</b>		
Bedroom	1,208.41	0.02%
Kitchen	568.59	0.01%
Closet	475.08	0.01%
Entry	328.20	0.01%
Bathroom	1,290.08	0.03%
Living Room	2,307.04	0.05%
<b>Area Subtotal: 8430</b>	<b>6,177.40</b>	<b>0.13%</b>
<b>Area Subtotal: Building 8 Interiors</b>	<b>124,205.73</b>	<b>2.52%</b>
Corridors/Breezways	404,614.64	8.23%
Exteriors	81,033.22	1.65%
<b>Area: Garage/Storage</b>		
B08G05	1,272.12	0.03%
<b>Area Subtotal: Garage/Storage</b>	<b>1,272.12</b>	<b>0.03%</b>
<b>GENERAL CONDITIONS</b>	<b>73,358.28</b>	<b>1.49%</b>
<b>Area Subtotal: SAULET-BLDG-08-V5_23</b>	<b>684,483.99</b>	<b>13.91%</b>
<b>Area: SAULET-BLDG-09-V5_23</b>		
<b>Area: Building 9 Interiors</b>		
<b>Area: 9101</b>		
Entry	1,483.08	0.03%
Closet	424.59	0.01%
SAULET-RECON-V5_23-B	5/31/2022	Page: 735



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Kitchen</b>	<b>5,322.50</b>	<b>0.11%</b>
<b>Living Room</b>	<b>2,362.65</b>	<b>0.05%</b>
<b>Bedroom</b>	<b>1,276.94</b>	<b>0.03%</b>
<b>Walk-in Closet</b>	<b>813.80</b>	<b>0.02%</b>
<b>Bathroom</b>	<b>2,940.96</b>	<b>0.06%</b>
<b>Utility Room</b>	<b>519.38</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 9101</b>	<b>15,143.90</b>	<b>0.31%</b>
<b>Area: 9102</b>		
<b>Master Bedroom</b>	<b>860.39</b>	<b>0.02%</b>
<b>Kitchen / Dining</b>	<b>818.55</b>	<b>0.02%</b>
<b>Living Room</b>	<b>670.06</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 9102</b>	<b>2,349.00</b>	<b>0.05%</b>
<b>Area: 9103</b>		
<b>Bathroom</b>	<b>1,535.63</b>	<b>0.03%</b>
<b>Walk-in Closet</b>	<b>1,238.68</b>	<b>0.03%</b>
<b>Kitchen</b>	<b>1,191.91</b>	<b>0.02%</b>
<b>Living Room</b>	<b>1,869.26</b>	<b>0.04%</b>
<b>Bedroom</b>	<b>1,761.68</b>	<b>0.04%</b>
<b>Entry</b>	<b>851.56</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 9103</b>	<b>8,448.72</b>	<b>0.17%</b>
<b>Area: 9105</b>		
<b>Bathroom</b>	<b>1,204.89</b>	<b>0.02%</b>
<b>Walk-in Closet</b>	<b>758.58</b>	<b>0.02%</b>
<b>Kitchen</b>	<b>848.50</b>	<b>0.02%</b>
<b>Entry</b>	<b>444.73</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,492.08</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 9105</b>	<b>4,748.78</b>	<b>0.10%</b>
<b>Area: 9108</b>		
<b>Entry</b>	<b>379.05</b>	<b>0.01%</b>
<b>Bedroom</b>	<b>853.86</b>	<b>0.02%</b>
<b>Kitchen</b>	<b>885.36</b>	<b>0.02%</b>
<b>Living Room</b>	<b>1,244.13</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 9108</b>	<b>3,362.40</b>	<b>0.07%</b>
<b>Area: 9111</b>		
<b>Bathroom</b>	<b>1,298.80</b>	<b>0.03%</b>
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 9111</b>	<b>1,298.80</b>	<b>0.03%</b>
<b>Area: 9113</b>		
Master Bath	1,472.16	0.03%
Master Walk-in Closet	1,149.46	0.02%
Living / Dining Room	2,405.14	0.05%
Kitchen	5,702.30	0.12%
Pantry	399.85	0.01%
Closet	410.55	0.01%
Bedroom 1 Walk-In Closet	766.80	0.02%
Bedroom 1	1,411.02	0.03%
Linen Closet	235.13	
Hall Bathroom	2,225.73	0.05%
Bedroom 2	1,520.56	0.03%
<b>Area Subtotal: 9113</b>	<b>17,698.70</b>	<b>0.36%</b>
<b>Area: 9115</b>		
Bedroom	1,084.33	0.02%
Living Room	1,826.38	0.04%
<b>Area Subtotal: 9115</b>	<b>2,910.71</b>	<b>0.06%</b>
<b>Area: 9120</b>		
Entry	379.05	0.01%
Kitchen	573.73	0.01%
Living Room	1,523.96	0.03%
<b>Area Subtotal: 9120</b>	<b>2,476.74</b>	<b>0.05%</b>
<b>Area: 9201</b>		
Bathroom	3,783.76	0.08%
Entry	812.08	0.02%
Closet	341.06	0.01%
Utility Room	384.74	0.01%
Kitchen	8,283.11	0.17%
Living Room	1,933.73	0.04%
Bedroom	1,392.92	0.03%
<b>Area Subtotal: 9201</b>	<b>16,931.40</b>	<b>0.34%</b>
<b>Area: 9203</b>		
Walk-in Closet	596.11	0.01%
Kitchen	710.50	0.01%
Entry	714.99	0.01%
Living Room	3,384.66	0.07%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 9203</b>	<b>5,406.26</b>	<b>0.11%</b>
<b>Area: 9206</b>		
<b>Kitchen</b>	<b>1,095.86</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>1,774.26</b>	<b>0.04%</b>
<b>Area Subtotal: 9206</b>	<b>2,870.12</b>	<b>0.06%</b>
<b>Area: 9208</b>		
<b>Kitchen</b>	<b>568.59</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,514.98</b>	<b>0.03%</b>
<b>Entry</b>	<b>328.20</b>	<b>0.01%</b>
<b>Area Subtotal: 9208</b>	<b>2,411.77</b>	<b>0.05%</b>
<b>Area: 9213</b>		
<b>Bedroom 1</b>	<b>2,486.40</b>	<b>0.05%</b>
<b>Hall Bathroom</b>	<b>1,188.19</b>	<b>0.02%</b>
<b>Area Subtotal: 9213</b>	<b>3,674.59</b>	<b>0.07%</b>
<b>Area: 9214</b>		
<b>Bathroom</b>	<b>991.65</b>	<b>0.02%</b>
<b>Area Subtotal: 9214</b>	<b>991.65</b>	<b>0.02%</b>
<b>Area: 9220</b>		
<b>Entry</b>	<b>488.45</b>	<b>0.01%</b>
<b>Kitchen</b>	<b>214.64</b>	
<b>Living Room</b>	<b>572.45</b>	<b>0.01%</b>
<b>Area Subtotal: 9220</b>	<b>1,275.54</b>	<b>0.03%</b>
<b>Area: 9301</b>		
<b>Kitchen</b>	<b>1,862.40</b>	<b>0.04%</b>
<b>Entry</b>	<b>653.13</b>	<b>0.01%</b>
<b>Living Room</b>	<b>2,131.73</b>	<b>0.04%</b>
<b>Area Subtotal: 9301</b>	<b>4,647.26</b>	<b>0.09%</b>
<b>Area: 9303</b>		
<b>Kitchen</b>	<b>1,250.70</b>	<b>0.03%</b>
<b>Entry</b>	<b>700.45</b>	<b>0.01%</b>
<b>Living Room</b>	<b>1,674.38</b>	<b>0.03%</b>
<b>Area Subtotal: 9303</b>	<b>3,625.53</b>	<b>0.07%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Area: 9304

Utility Room	398.13	0.01%
Master Walk-in Closet	1,136.16	0.02%
Pantry	114.76	
Room2	6,912.33	0.14%

---

<b>Area Subtotal: 9304</b>	<b>8,561.38</b>	<b>0.17%</b>
----------------------------	-----------------	--------------

### Area: 9308

Entry	1,099.12	0.02%
Kitchen	656.52	0.01%
Living Room	865.64	0.02%

---

<b>Area Subtotal: 9308</b>	<b>2,621.28</b>	<b>0.05%</b>
----------------------------	-----------------	--------------

### Area: 9312

Bedroom 2	2,100.58	0.04%
-----------	----------	-------

---

<b>Area Subtotal: 9312</b>	<b>2,100.58</b>	<b>0.04%</b>
----------------------------	-----------------	--------------

### Area: 9316

Bedroom	1,210.53	0.02%
Living Room	3,035.20	0.06%

---

<b>Area Subtotal: 9316</b>	<b>4,245.73</b>	<b>0.09%</b>
----------------------------	-----------------	--------------

### Area: 9401

Living Room	1,284.41	0.03%
Entry	804.05	0.02%
Kitchen	1,089.18	0.02%

---

<b>Area Subtotal: 9401</b>	<b>3,177.64</b>	<b>0.06%</b>
----------------------------	-----------------	--------------

### Area: 9405

Pantry	3,955.79	0.08%
Bathroom	264.08	0.01%
Walk-in Closet	1,301.37	0.03%
Walk-in Closet	719.59	0.01%
Utility Room	599.78	0.01%
Bedroom	1,552.04	0.03%
Kitchen	631.88	0.01%
Entry	434.47	0.01%
Living Room	5,066.14	0.10%

---

<b>Area Subtotal: 9405</b>	<b>14,525.14</b>	<b>0.30%</b>
----------------------------	------------------	--------------

### Area: 9420



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Entry	456.64	0.01%
Kitchen	754.04	0.02%
Bedroom	2,072.56	0.04%
Living Room	875.92	0.02%
<hr/>		
<b>Area Subtotal: 9420</b>	<b>4,159.16</b>	<b>0.08%</b>
<hr/>		
<b>Area Subtotal: Building 9 Interiors</b>	<b>139,662.78</b>	<b>2.84%</b>
Corridors/Breezways	219,418.64	4.46%
Exteriors	109,564.67	2.23%
GENERAL CONDITIONS	54,319.28	1.10%
<hr/>		
<b>Area Subtotal: SAULET-BLDG-09-V5_23</b>	<b>522,965.37</b>	<b>10.63%</b>
<b>Area: SAULET-BLDG-10-V5_23</b>		
<b>Area: Building 10 Interiors</b>		
<b>Area: 10108</b>		
Kitchen	490.45	0.01%
Bathroom	990.28	0.02%
<hr/>		
<b>Area Subtotal: 10108</b>	<b>1,480.73</b>	<b>0.03%</b>
<b>Area: 10111</b>		
Closet	2,417.32	0.05%
Kitchen	12,403.74	0.25%
Bathroom	7,965.03	0.16%
Bedroom	4,342.00	0.09%
Entry	1,883.51	0.04%
Utility Room	2,514.92	0.05%
Pantry	601.42	0.01%
Hallway	531.86	0.01%
Living / Dining Room	8,699.35	0.18%
<hr/>		
<b>Area Subtotal: 10111</b>	<b>41,359.15</b>	<b>0.84%</b>
<b>Area: 10114</b>		
Bedroom	870.21	0.02%
Bedroom Closet	263.92	0.01%
<hr/>		
<b>Area Subtotal: 10114</b>	<b>1,134.13</b>	<b>0.02%</b>
<b>Area: 10211</b>		
Closet	2,456.57	0.05%
Kitchen	12,334.23	0.25%
Bathroom	7,930.63	0.16%
<hr/>		
<b>SAULET-RECON-V5_23-B</b>	<b>5/31/2022</b>	<b>Page: 740</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Bedroom	4,395.15	0.09%
Entry	1,883.51	0.04%
Utility Room	2,537.67	0.05%
Pantry	605.75	0.01%
Hallway	535.38	0.01%
Living / Dining Room	8,730.93	0.18%
<hr/>		
<b>Area Subtotal: 10211</b>	<b>41,409.82</b>	<b>0.84%</b>
<hr/>		
<b>Area: 10212</b>		
Kitchen	563.52	0.01%
Living / Dining Room	1,347.89	0.03%
Bathroom	764.14	0.02%
Stairs	1,219.18	0.02%
<hr/>		
<b>Area Subtotal: 10212</b>	<b>3,894.73</b>	<b>0.08%</b>
<hr/>		
<b>Area: 10214</b>		
Bedroom	1,873.68	0.04%
Kitchen / Dining	1,138.01	0.02%
Bathroom	526.70	0.01%
Living Room	1,095.03	0.02%
<hr/>		
<b>Area Subtotal: 10214</b>	<b>4,633.42</b>	<b>0.09%</b>
<hr/>		
<b>Area: 10301</b>		
Living Room	3,333.34	0.07%
<hr/>		
<b>Area Subtotal: 10301</b>	<b>3,333.34</b>	<b>0.07%</b>
<hr/>		
<b>Area: 10311</b>		
Closet	2,845.81	0.06%
Kitchen	13,697.99	0.28%
Bathroom	8,529.14	0.17%
Bedroom	6,165.42	0.13%
Entry	2,214.75	0.05%
Utility Room	3,093.31	0.06%
Pantry	668.62	0.01%
Hallway	673.99	0.01%
Living / Dining Room	12,177.18	0.25%
<hr/>		
<b>Area Subtotal: 10311</b>	<b>50,066.21</b>	<b>1.02%</b>
<hr/>		
<b>Area: 10313</b>		
Bathroom	1,232.71	0.03%
Room2	3,972.71	0.08%
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 10313</b>	<b>5,205.42</b>	<b>0.11%</b>
<b>Area: 10404</b>		
Kitchen	682.33	0.01%
Bedroom	1,519.11	0.03%
Living / Dining Room	1,001.55	0.02%
<b>Area Subtotal: 10404</b>	<b>3,202.99</b>	<b>0.07%</b>
<b>Area: 10405</b>		
Bedroom	1,377.45	0.03%
Kitchen / Dining	1,007.78	0.02%
Living / Dining	2,066.55	0.04%
<b>Area Subtotal: 10405</b>	<b>4,451.78</b>	<b>0.09%</b>
<b>Area: 10408</b>		
Bedroom	1,434.34	0.03%
Kitchen	490.45	0.01%
Living Room	2,142.67	0.04%
<b>Area Subtotal: 10408</b>	<b>4,067.46</b>	<b>0.08%</b>
<b>Area: 10409</b>		
Bedroom	2,043.90	0.04%
Kitchen / Dining	2,049.29	0.04%
Living / Dining	3,413.26	0.07%
<b>Area Subtotal: 10409</b>	<b>7,506.45</b>	<b>0.15%</b>
<b>Area: 10411</b>		
Closet	2,845.81	0.06%
Kitchen	13,628.48	0.28%
Bathroom	8,554.45	0.17%
Bedroom	4,495.27	0.09%
Entry	2,214.75	0.05%
Utility Room	3,072.54	0.06%
Pantry	668.62	0.01%
Hallway	673.99	0.01%
Living / Dining Room	12,087.40	0.25%
<b>Area Subtotal: 10411</b>	<b>48,241.31</b>	<b>0.98%</b>
<b>Area: 10413</b>		
Bathroom	1,044.15	0.02%
Master Bedroom	2,459.83	0.05%
Living Room	4,351.53	0.09%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 10413</b>	<b>7,855.51</b>	<b>0.16%</b>
<b>Area: 10414</b>		
<b>Living Room</b>	<b>651.95</b>	<b>0.01%</b>
<b>Master Bedroom</b>	<b>842.30</b>	<b>0.02%</b>
<b>Area Subtotal: 10414</b>	<b>1,494.25</b>	<b>0.03%</b>
<b>Area Subtotal: Building 10 Interiors</b>	<b>229,336.70</b>	<b>4.66%</b>
<b>Area: Garage/Storage</b>		
<b>B10S3</b>	<b>1,447.98</b>	<b>0.03%</b>
<b>B10G6</b>	<b>1,447.98</b>	<b>0.03%</b>
<b>B10G7</b>	<b>1,834.12</b>	<b>0.04%</b>
<b>Area Subtotal: Garage/Storage</b>	<b>4,730.08</b>	<b>0.10%</b>
<b>Corridor/Breezeway</b>	<b>41,773.92</b>	<b>0.85%</b>
<b>Exteriors</b>	<b>103,173.62</b>	<b>2.10%</b>
<b>GENERAL CONDITIONS</b>	<b>52,024.38</b>	<b>1.06%</b>
<b>Area Subtotal: SAULET-BLDG-10-V5_23</b>	<b>431,038.70</b>	<b>8.76%</b>
<b>Area: SAULET-BLDG-11-V5_23</b>		
<b>Area: Building 11 Interiors</b>		
<b>Area: 11101</b>		
<b>Room2</b>	<b>4,898.01</b>	<b>0.10%</b>
<b>Area Subtotal: 11101</b>	<b>4,898.01</b>	<b>0.10%</b>
<b>Area: 11103</b>		
<b>Living / Dining Room</b>	<b>1,543.29</b>	<b>0.03%</b>
<b>Kitchen</b>	<b>427.02</b>	<b>0.01%</b>
<b>Area Subtotal: 11103</b>	<b>1,970.31</b>	<b>0.04%</b>
<b>Area: 11106</b>		
<b>Kitchen</b>	<b>1,556.73</b>	<b>0.03%</b>
<b>Living / Dining Room</b>	<b>2,790.20</b>	<b>0.06%</b>
<b>Area Subtotal: 11106</b>	<b>4,346.93</b>	<b>0.09%</b>
<b>Area: 11108</b>		
<b>Closet</b>	<b>997.36</b>	<b>0.02%</b>
<b>SAULET-RECON-V5_23-B</b>	<b>5/31/2022</b>	<b>Page: 743</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

Kitchen	2,126.69	0.04%
Bathroom	1,952.66	0.04%
Bedroom	3,296.88	0.07%
Entry	910.80	0.02%
Utility Room	1,598.36	0.03%
Pantry	45.66	
Hallway	95.30	
Living / Dining Room	7,695.34	0.16%
<hr/>		
<b>Area Subtotal: 11108</b>	<b>18,719.05</b>	<b>0.38%</b>
<b>Area: 11109</b>		
Entry	637.73	0.01%
Kitchen	985.73	0.02%
Utility Room	887.94	0.02%
Bathroom	886.22	0.02%
Living Room	1,616.17	0.03%
<hr/>		
<b>Area Subtotal: 11109</b>	<b>5,013.79</b>	<b>0.10%</b>
<b>Area: 11110</b>		
Bedroom	1,370.56	0.03%
Utility Room	819.17	0.02%
Kitchen	682.33	0.01%
Living / Dining Room	1,489.56	0.03%
<hr/>		
<b>Area Subtotal: 11110</b>	<b>4,361.62</b>	<b>0.09%</b>
<b>Area: 11111</b>		
Living Room	1,725.34	0.04%
Bedroom	661.92	0.01%
<hr/>		
<b>Area Subtotal: 11111</b>	<b>2,387.26</b>	<b>0.05%</b>
<b>Area: 11112</b>		
Utility Room	317.89	0.01%
Kitchen	914.48	0.02%
Entry	394.68	0.01%
Living Room	1,017.21	0.02%
<hr/>		
<b>Area Subtotal: 11112</b>	<b>2,644.26</b>	<b>0.05%</b>
<b>Area: 11116</b>		
Kitchen	744.07	0.02%
Bedroom 1	1,131.24	0.02%
Living / Dining Room	2,323.83	0.05%
<hr/>		



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Area Subtotal: 11116</b>	<b>4,199.14</b>	<b>0.09%</b>
<b>Area: 11120</b>		
Bedroom	1,633.02	0.03%
Living / Dining Room	1,732.85	0.04%
Pantry	154.92	
Kitchen	427.02	0.01%
<b>Area Subtotal: 11120</b>	<b>3,947.81</b>	<b>0.08%</b>
<b>Area: 11203</b>		
Work Space	1,271.19	0.03%
Living Room	999.51	0.02%
<b>Area Subtotal: 11203</b>	<b>2,270.70</b>	<b>0.05%</b>
<b>Area: 11204</b>		
Living / Dining Room	3,802.45	0.08%
Work Space	2,544.99	0.05%
Kitchen	702.36	0.01%
<b>Area Subtotal: 11204</b>	<b>7,049.80</b>	<b>0.14%</b>
<b>Area: 11209</b>		
Living Room	1,086.35	0.02%
Entry	351.47	0.01%
Kitchen	739.88	0.02%
Utility Room	610.12	0.01%
<b>Area Subtotal: 11209</b>	<b>2,787.82</b>	<b>0.06%</b>
<b>Area: 11213</b>		
Kitchen	490.45	0.01%
Living Room	1,185.29	0.02%
<b>Area Subtotal: 11213</b>	<b>1,675.74</b>	<b>0.03%</b>
<b>Area: 11216</b>		
Kitchen	744.07	0.02%
Bedroom 1	1,250.98	0.03%
Living / Dining Room	2,287.43	0.05%
<b>Area Subtotal: 11216</b>	<b>4,282.48</b>	<b>0.09%</b>
<b>Area: 11218</b>		
Work Space	7,763.98	0.16%
<b>SAULET-RECON-V5_23-B</b>	<b>5/31/2022</b>	<b>Page: 745</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Bedroom</b>	<b>3,446.01</b>	<b>0.07%</b>
<b>Kitchen</b>	<b>6,023.67</b>	<b>0.12%</b>
<b>Utility Room</b>	<b>520.06</b>	<b>0.01%</b>
<b>Stairway</b>	<b>1,084.52</b>	<b>0.02%</b>
<b>Landing</b>	<b>1,993.10</b>	<b>0.04%</b>
<b>Master Walk-In Closet</b>	<b>1,226.52</b>	<b>0.02%</b>
<b>Bathroom</b>	<b>968.01</b>	<b>0.02%</b>
<b>Master Bathroom</b>	<b>29.91</b>	
<b>Living / Dining Room</b>	<b>8,960.16</b>	<b>0.18%</b>
<hr/>		
<b>Area Subtotal: 11218</b>	<b>32,015.94</b>	<b>0.65%</b>
<hr/>		
<b>Area: 11220</b>		
<b>Bathroom</b>	<b>479.62</b>	<b>0.01%</b>
<b>Hallway</b>	<b>231.78</b>	
<hr/>		
<b>Area Subtotal: 11220</b>	<b>711.40</b>	<b>0.01%</b>
<hr/>		
<b>Area: 11301</b>		
<b>Linen Closet</b>	<b>325.74</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 11301</b>	<b>325.74</b>	<b>0.01%</b>
<hr/>		
<b>Area: 11304</b>		
<b>Kitchen</b>	<b>744.07</b>	<b>0.02%</b>
<b>Bedroom 1</b>	<b>1,210.67</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>1,021.75</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 11304</b>	<b>2,976.49</b>	<b>0.06%</b>
<hr/>		
<b>Area: 11306</b>		
<b>Kitchen</b>	<b>744.07</b>	<b>0.02%</b>
<b>Master Bedroom</b>	<b>1,337.36</b>	<b>0.03%</b>
<b>Living / Dining Room</b>	<b>2,762.66</b>	<b>0.06%</b>
<hr/>		
<b>Area Subtotal: 11306</b>	<b>4,844.09</b>	<b>0.10%</b>
<hr/>		
<b>Area: 11307</b>		
<b>Utility Room</b>	<b>610.23</b>	<b>0.01%</b>
<b>Bathroom</b>	<b>1,009.46</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 11307</b>	<b>1,619.69</b>	<b>0.03%</b>
<hr/>		
<b>Area: 11310</b>		
<b>Kitchen</b>	<b>655.50</b>	<b>0.01%</b>
<b>Bedroom</b>	<b>1,431.86</b>	<b>0.03%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Living / Dining Room</b>	<b>1,171.44</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 11310</b>	<b>3,258.80</b>	<b>0.07%</b>
<hr/>		
<b>Area: 11316</b>		
<b>Kitchen</b>	<b>744.07</b>	<b>0.02%</b>
<b>Living / Dining Room</b>	<b>2,767.97</b>	<b>0.06%</b>
<hr/>		
<b>Area Subtotal: 11316</b>	<b>3,512.04</b>	<b>0.07%</b>
<hr/>		
<b>Area: 11318</b>		
<b>Kitchen</b>	<b>2,726.87</b>	<b>0.06%</b>
<b>Bathroom</b>	<b>923.57</b>	<b>0.02%</b>
<b>Room2</b>	<b>2,183.65</b>	<b>0.04%</b>
<b>Utility Room</b>	<b>2,742.43</b>	<b>0.06%</b>
<b>Bathroom</b>	<b>950.29</b>	<b>0.02%</b>
<b>Closet</b>	<b>881.52</b>	<b>0.02%</b>
<b>Master Bedroom</b>	<b>5,105.18</b>	<b>0.10%</b>
<b>Living / Dining Room</b>	<b>10,892.68</b>	<b>0.22%</b>
<hr/>		
<b>Area Subtotal: 11318</b>	<b>26,406.19</b>	<b>0.54%</b>
<hr/>		
<b>Area: 11401</b>		
<b>Living Room</b>	<b>3,562.07</b>	<b>0.07%</b>
<hr/>		
<b>Area Subtotal: 11401</b>	<b>3,562.07</b>	<b>0.07%</b>
<hr/>		
<b>Area: 11402</b>		
<b>Kitchen</b>	<b>744.07</b>	<b>0.02%</b>
<b>Bedroom 1</b>	<b>1,443.44</b>	<b>0.03%</b>
<b>Living / Dining Room</b>	<b>2,075.61</b>	<b>0.04%</b>
<hr/>		
<b>Area Subtotal: 11402</b>	<b>4,263.12</b>	<b>0.09%</b>
<hr/>		
<b>Area: 11403</b>		
<b>Bedroom</b>	<b>1,407.09</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 11403</b>	<b>1,407.09</b>	<b>0.03%</b>
<hr/>		
<b>Area: 11404</b>		
<b>Kitchen</b>	<b>1,348.23</b>	<b>0.03%</b>
<b>Utility Room</b>	<b>363.57</b>	<b>0.01%</b>
<b>Master Bedroom</b>	<b>1,744.70</b>	<b>0.04%</b>
<b>Living / Dining Room</b>	<b>1,679.04</b>	<b>0.03%</b>
<hr/>		
<b>Area Subtotal: 11404</b>		<b>0.10%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

		5,135.54	
<b>Area: 11406</b>			
<b>Kitchen</b>		744.07	0.02%
<b>Living / Dining Room</b>		1,566.33	0.03%
<hr/>			
<b>Area Subtotal: 11406</b>		2,310.40	0.05%
<b>Area: 11407</b>			
<b>Bedroom</b>		1,579.30	0.03%
<b>Bathroom</b>		1,262.53	0.03%
<hr/>			
<b>Area Subtotal: 11407</b>		2,841.83	0.06%
<b>Area: 11408</b>			
<b>Kitchen</b>		1,129.07	0.02%
<b>Bathroom</b>		685.75	0.01%
<b>Utility Room</b>		773.38	0.02%
<b>Room1</b>		357.50	0.01%
<b>Living / Dining Room</b>		2,605.80	0.05%
<hr/>			
<b>Area Subtotal: 11408</b>		5,551.50	0.11%
<b>Area: 11410</b>			
<b>Kitchen</b>		682.33	0.01%
<b>Bedroom</b>		1,577.53	0.03%
<b>Living / Dining Room</b>		1,550.82	0.03%
<hr/>			
<b>Area Subtotal: 11410</b>		3,810.68	0.08%
<b>Area: 11411</b>			
<b>Kitchen</b>		402.42	0.01%
<b>Living Room</b>		2,048.23	0.04%
<hr/>			
<b>Area Subtotal: 11411</b>		2,450.65	0.05%
<b>Area: 11412</b>			
<b>Kitchen</b>		402.42	0.01%
<b>Living Room</b>		2,391.05	0.05%
<b>Bedroom</b>		696.54	0.01%
<hr/>			
<b>Area Subtotal: 11412</b>		3,490.01	0.07%
<b>Area: 11414</b>			
<b>Kitchen</b>		469.57	0.01%
<b>Entry</b>		409.45	0.01%



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Living Room</b>	<b>715.42</b>	<b>0.01%</b>
<hr/>		
<b>Area Subtotal: 11414</b>	<b>1,594.44</b>	<b>0.03%</b>
<hr/>		
<b>Area: 11418</b>		
<b>Kitchen</b>	<b>2,679.30</b>	<b>0.05%</b>
<b>Bathroom</b>	<b>876.12</b>	<b>0.02%</b>
<b>Utility Room</b>	<b>2,264.64</b>	<b>0.05%</b>
<b>Bathroom</b>	<b>461.15</b>	<b>0.01%</b>
<b>Linen Closet</b>	<b>161.20</b>	
<b>Walk-in Closet</b>	<b>1,055.74</b>	<b>0.02%</b>
<b>Closet</b>	<b>45.00</b>	
<b>Bedroom 1</b>	<b>1,821.74</b>	<b>0.04%</b>
<b>Master Bedroom</b>	<b>5,656.83</b>	<b>0.11%</b>
<b>Living / Dining Room</b>	<b>11,651.25</b>	<b>0.24%</b>
<hr/>		
<b>Area Subtotal: 11418</b>	<b>26,672.97</b>	<b>0.54%</b>
<hr/>		
<b>Area: 11421</b>		
<b>Utility Room</b>	<b>756.46</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: 11421</b>	<b>756.46</b>	<b>0.02%</b>
<hr/>		
<b>Area Subtotal: Building 11 Interiors</b>	<b>210,071.86</b>	<b>4.27%</b>
<b>Breezeways</b>	<b>215,215.99</b>	<b>4.38%</b>
<b>Exteriors</b>	<b>106,452.68</b>	<b>2.16%</b>
<b>GENERAL CONDITIONS</b>	<b>33,632.53</b>	<b>0.68%</b>
<hr/>		
<b>Area Subtotal: SAULET-BLDG-11-V5_23</b>	<b>565,373.06</b>	<b>11.49%</b>
<hr/>		
<b>Area: SAULET-OFFICE-V5_23</b>		
<b>Corridors/Hallways</b>	<b>31,001.12</b>	<b>0.63%</b>
<b>Interiors</b>	<b>11,136.30</b>	<b>0.23%</b>
<b>Exteriors</b>	<b>38,115.30</b>	<b>0.77%</b>
<b>Exterior Lighting</b>	<b>29,004.36</b>	<b>0.59%</b>
<b>Fencing</b>	<b>35,438.46</b>	<b>0.72%</b>
<b>Parking Garages</b>	<b>3,322.92</b>	<b>0.07%</b>
<b>GENERAL CONDITIONS</b>	<b>25,075.31</b>	<b>0.51%</b>
<hr/>		
<b>Area Subtotal: SAULET-OFFICE-V5_23</b>	<b>173,093.77</b>	<b>3.52%</b>
<hr/>		
<b>Subtotal of Areas</b>	<b>4,919,091.83</b>	<b>100.00%</b>
<hr/>		
<b>Total</b>	<b>4,919,091.83</b>	<b>100.00%</b>



## Camp Construction Services

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

### Recap by Category

O&P Items	Total	%
APPLIANCES	9,915.78	0.17%
CABINETS	101,366.10	1.69%
CLEANING	202,414.72	3.37%
CONCRETE & ASPHALT	6,330.25	0.11%
CONTENT MANIPULATION	2,664.32	0.04%
GENERAL DEMOLITION	18,590.43	0.31%
DOORS	30,185.09	0.50%
DRYWALL	1,195,417.62	19.92%
ELECTRICAL	128,519.36	2.14%
ELECTRICAL - SPECIAL SYSTEMS	1,378.72	0.02%
MISC. EQUIPMENT - COMMERCIAL	288.80	0.00%
FLOOR COVERING - CARPET	13,977.86	0.23%
FLOOR COVERING - VINYL	60,021.40	1.00%
PERMITS AND FEES	3,450.00	0.06%
FINISH CARPENTRY / TRIMWORK	58,885.39	0.98%
FINISH HARDWARE	1,988.45	0.03%
FIRE PROTECTION SYSTEMS	5,889.50	0.10%
FRAMING & ROUGH CARPENTRY	37,156.74	0.62%
HEAT, VENT & AIR CONDITIONING	8,604.54	0.14%
INSULATION	75,590.39	1.26%
LABOR ONLY	406,272.01	6.77%
LIGHT FIXTURES	115,529.03	1.92%
MIRRORS & SHOWER DOORS	1,871.61	0.03%
METAL STRUCTURES & COMPONENTS	6,616.20	0.11%
ORNAMENTAL IRON	20,264.36	0.34%
PLUMBING	27,819.89	0.46%
PANELING & WOOD WALL FINISHES	444.31	0.01%
PAINTING	2,097,837.95	34.95%
SCAFFOLDING	146,145.04	2.43%
SIDING	46,666.61	0.78%
SOFFIT, FASCIA, & GUTTER	58,105.80	0.97%
SPECIALTY ITEMS	1,081.57	0.02%
STUCCO & EXTERIOR PLASTER	151.60	0.00%
TOILET & BATH ACCESSORIES	768.34	0.01%
TEMPORARY REPAIRS	6,184.11	0.10%
WINDOW REGLAZING & REPAIR	15,934.14	0.27%
WINDOW TREATMENT	4,435.97	0.07%
WINDOWS - VINYL	327.83	0.01%
<b>O&amp;P Items Subtotal</b>	<b>4,919,091.83</b>	<b>81.95%</b>



## Camp Construction Services

---

15139 South Post Oak  
Houston, TX 77053  
713.413.2267

<b>Overhead</b>	<b>491,911.30</b>	<b>8.20%</b>
<b>Profit</b>	<b>491,911.30</b>	<b>8.20%</b>
<b>Material Sales Tax</b>	<b>99,437.06</b>	<b>1.66%</b>
<hr/>	<hr/>	<hr/>
<b>Total</b>	<b>6,002,351.49</b>	<b>100.00%</b>

# AIA<sup>®</sup> Document A101<sup>®</sup> – 2017 Exhibit A

## Insurance and Bonds

This Insurance and Bonds Exhibit is part of the Agreement, between the Owner and the Contractor, dated the Twenty-seventh day of June in the year Two Thousand Twenty-two  
*(In words, indicate day, month and year.)*

for the following **PROJECT:**  
*(Name and location or address)*

The Saulet  
1420 Annunciation Street  
New Orleans, LA 70130

**THE OWNER:**  
*(Name, legal status and address)*

Saulet Apts LLC  
780 Third Ave 25<sup>th</sup> Fl  
New York, N.Y. 10017

**THE CONTRACTOR:**  
*(Name, legal status and address)*

Camp Roofing LTD dba Camp Construction Services  
15139 South Post Oak Road  
Houston, Texas 77053

### TABLE OF ARTICLES

- A.1 GENERAL
- A.2 OWNER'S INSURANCE
- A.3 CONTRACTOR'S INSURANCE AND BONDS
- A.4 SPECIAL TERMS AND CONDITIONS

#### ARTICLE A.1 GENERAL

The Owner and Contractor shall purchase and maintain insurance, and provide bonds, as set forth in this Exhibit. As used in this Exhibit, the term General Conditions refers to AIA Document A201<sup>TM</sup>-2017, General Conditions of the Contract for Construction.

#### ARTICLE A.2 OWNER'S INSURANCE

##### § A.2.1 General

Prior to commencement of the Work, the Owner shall secure the insurance, and provide evidence of the coverage, required under this Article A.2 and, upon the Contractor's request, provide a copy of the property insurance policy or policies required by Section

#### ADDITIONS AND DELETIONS:

The author of this document has added information needed for its completion. The author may also have revised the text of the original AIA standard form. An *Additions and Deletions Report* that notes added information as well as revisions to the standard form text is available from the author and should be reviewed. A vertical line in the left margin of this document indicates where the author has added necessary information and where the author has added to or deleted from the original AIA text.

This document has important legal consequences. Consultation with an attorney is encouraged with respect to its completion or modification.

This document is intended to be used in conjunction with AIA Document A201<sup>®</sup>-2017, General Conditions of the Contract for Construction. Article 11 of A201<sup>®</sup>-2017 contains additional insurance provisions.

A.2.3. The copy of the policy or policies provided shall contain all applicable conditions, definitions, exclusions, and endorsements.

### § A.2.2 Liability Insurance

The Owner shall be responsible for purchasing and maintaining the Owner's usual general liability insurance.

### § A.2.3 Required Property Insurance

§ A.2.3.1 Unless this obligation is placed on the Contractor pursuant to Section A.3.3.2.1, the Owner shall purchase and maintain, from an insurance company or insurance companies lawfully authorized to issue insurance in the jurisdiction where the Project is located, property insurance written on a builder's risk "all-risks" completed value or equivalent policy form and sufficient to cover the total value of the entire Project on a replacement cost basis. The Owner's property insurance coverage shall be no less than the amount of the initial Contract Sum, plus the value of subsequent Modifications and labor performed and materials or equipment supplied by others. The property insurance shall be maintained until Substantial Completion and thereafter as provided in Section A.2.3.1.3, unless otherwise provided in the Contract Documents or otherwise agreed in writing by the parties to this Agreement. This insurance shall include the interests of the Owner, Contractor, Subcontractors, and Sub-subcontractors in the Project as insureds. This insurance shall include the interests of mortgagees as loss payees.

§ A.2.3.1.1 **Causes of Loss.** The insurance required by this Section A.2.3.1 shall provide coverage for direct physical loss or damage, and shall not exclude the risks of fire, explosion, theft, vandalism, malicious mischief, collapse, earthquake, flood, or windstorm. The insurance shall also provide coverage for ensuing loss or resulting damage from error, omission, or deficiency in construction methods, design, specifications, workmanship, or materials. Sub-limits, if any, are as follows:

*(Indicate below the cause of loss and any applicable sub-limit.)*

**Causes of Loss**

**Sub-Limit**

§ A.2.3.1.2 **Specific Required Coverages.** The insurance required by this Section A.2.3.1 shall provide coverage for loss or damage to falsework and other temporary structures, and to building systems from testing and startup. The insurance shall also cover debris removal, including demolition occasioned by enforcement of any applicable legal requirements, and reasonable compensation for the Architect's and Contractor's services and expenses required as a result of such insured loss, including claim preparation expenses. Sub-limits, if any, are as follows:

*(Indicate below type of coverage and any applicable sub-limit for specific required coverages.)*

**Coverage**

**Sub-Limit**

§ A.2.3.1.3 Unless the parties agree otherwise, upon Substantial Completion, the Owner shall continue the insurance required by Section A.2.3.1 or, if necessary, replace the insurance policy required under Section A.2.3.1 with property insurance written for the total value of the Project that shall remain in effect until expiration of the period for correction of the Work set forth in Section 12.2.2 of the General Conditions.

§ A.2.3.1.4 **Deductibles and Self-Insured Retentions.** If the insurance required by this Section A.2.3 is subject to deductibles or self-insured retentions, the Owner shall be responsible for all loss not covered because of such deductibles or retentions.

§ A.2.3.2 **Occupancy or Use Prior to Substantial Completion.** The Owner's occupancy or use of any completed or partially completed portion of the Work prior to Substantial Completion shall not commence until the insurance company or companies providing the insurance under Section A.2.3.1 have consented in writing to the continuance of coverage. The Owner and the Contractor shall take no action with respect to partial occupancy or use that would cause cancellation, lapse, or reduction of insurance, unless they agree otherwise in writing.

### § A.2.3.3 Insurance for Existing Structures

If the Work involves remodeling an existing structure or constructing an addition to an existing structure, the Owner shall purchase and maintain, until the expiration of the period for correction of Work as set forth in Section 12.2.2 of

Init.

/

the General Conditions, "all-risks" property insurance, on a replacement cost basis, protecting the existing structure against direct physical loss or damage from the causes of loss identified in Section A.2.3.1, notwithstanding the undertaking of the Work. The Owner shall be responsible for all co-insurance penalties.

**§ A.2.4 Optional Extended Property Insurance.**

The Owner shall purchase and maintain the insurance selected and described below.

*(Select the types of insurance the Owner is required to purchase and maintain by placing an X in the box(es) next to the description(s) of selected insurance. For each type of insurance selected, indicate applicable limits of coverage or other conditions in the fill point below the selected item.)*

- § A.2.4.1 Loss of Use, Business Interruption, and Delay in Completion Insurance**, to reimburse the Owner for loss of use of the Owner's property, or the inability to conduct normal operations due to a covered cause of loss.
- § A.2.4.2 Ordinance or Law Insurance**, for the reasonable and necessary costs to satisfy the minimum requirements of the enforcement of any law or ordinance regulating the demolition, construction, repair, replacement or use of the Project.
- § A.2.4.3 Expediting Cost Insurance**, for the reasonable and necessary costs for the temporary repair of damage to insured property, and to expedite the permanent repair or replacement of the damaged property.
- § A.2.4.4 Extra Expense Insurance**, to provide reimbursement of the reasonable and necessary excess costs incurred during the period of restoration or repair of the damaged property that are over and above the total costs that would normally have been incurred during the same period of time had no loss or damage occurred.
- § A.2.4.5 Civil Authority Insurance**, for losses or costs arising from an order of a civil authority prohibiting access to the Project, provided such order is the direct result of physical damage covered under the required property insurance.
- § A.2.4.6 Ingress/Egress Insurance**, for loss due to the necessary interruption of the insured's business due to physical prevention of ingress to, or egress from, the Project as a direct result of physical damage.
- § A.2.4.7 Soft Costs Insurance**, to reimburse the Owner for costs due to the delay of completion of the Work, arising out of physical loss or damage covered by the required property insurance: including construction loan fees; leasing and marketing expenses; additional fees, including those of architects, engineers, consultants, attorneys and accountants, needed for the completion of the construction, repairs, or reconstruction; and carrying costs such as property taxes, building permits, additional interest on loans, realty taxes, and insurance premiums over and above normal expenses.

**§ A.2.5 Other Optional Insurance.**

The Owner shall purchase and maintain the insurance selected below.

*(Select the types of insurance the Owner is required to purchase and maintain by placing an X in the box(es) next to the description(s) of selected insurance.)*

**§ A.2.5.1 Cyber Security Insurance** for loss to the Owner due to data security and privacy breach, including costs of investigating a potential or actual breach of confidential or private information.  
*(Indicate applicable limits of coverage or other conditions in the fill point below.)*

**§ A.2.5.2 Other Insurance**  
*(List below any other insurance coverage to be provided by the Owner and any applicable limits.)*

**Coverage**

**Limits**

**ARTICLE A.3 CONTRACTOR'S INSURANCE AND BONDS****§ A.3.1 General**

**§ A.3.1.1 Certificates of Insurance.** The Contractor shall provide certificates of insurance acceptable to the Owner evidencing compliance with the requirements in this Article A.3 at the following times: (1) prior to commencement of the Work; (2) upon renewal or replacement of each required policy of insurance; and (3) upon the Owner's written request. An additional certificate evidencing continuation of commercial liability coverage, including coverage for completed operations, shall be submitted with the final Application for Payment and thereafter upon renewal or replacement of such coverage until the expiration of the periods required by Section A.3.2.1 and Section A.3.3.1. The certificates will show the Owner as an additional insured on the Contractor's Commercial General Liability and excess or umbrella liability policy or policies.

**§ A.3.1.2 Deductibles and Self-Insured Retentions.** The Contractor shall disclose to the Owner any deductible or self-insured retentions applicable to any insurance required to be provided by the Contractor.

**§ A.3.1.3 Additional Insured Obligations.** To the fullest extent permitted by law, the Contractor shall cause the commercial general liability coverage to include (1) the Owner, the Architect, and the Architect's consultants as additional insureds for claims caused in whole or in part by the Contractor's negligent acts or omissions during the Contractor's operations; and (2) the Owner as an additional insured for claims caused in whole or in part by the Contractor's negligent acts or omissions for which loss occurs during completed operations. The additional insured coverage shall be primary and non-contributory to any of the Owner's general liability insurance policies and shall apply to both ongoing and completed operations. To the extent commercially available, the additional insured coverage shall be no less than that provided by Insurance Services Office, Inc. (ISO) forms CG 20 10 07 04, CG 20 37 07 04, and, with respect to the Architect and the Architect's consultants, CG 20 32 07 04.

**§ A.3.2 Contractor's Required Insurance Coverage**

**§ A.3.2.1** The Contractor shall purchase and maintain the following types and limits of insurance from an insurance company or insurance companies lawfully authorized to issue insurance in the jurisdiction where the Project is located. The Contractor shall maintain the required insurance until the expiration of the period for correction of Work as set forth in Section 12.2.2 of the General Conditions, unless a different duration is stated below:

*(If the Contractor is required to maintain insurance for a duration other than the expiration of the period for correction of Work, state the duration.)*

**§ A.3.2.2 Commercial General Liability**

**§ A.3.2.2.1** Commercial General Liability insurance for the Project written on an occurrence form with policy limits of not less than One million dollars (\$ 1,000,000 ) each occurrence, Two million dollars (\$ 2,000,000 ) general aggregate, and Two million dollars (\$ 2,000,000 ) aggregate for products-completed operations hazard, providing coverage for claims including

Init.

- .1 damages because of bodily injury, sickness or disease, including occupational sickness or disease, and death of any person;
- .2 personal injury and advertising injury;
- .3 damages because of physical damage to or destruction of tangible property.
- .4 bodily injury or property damage arising out of completed operations; and
- .5 the Contractor's indemnity obligations under Section 3.18 of the General Conditions.

**§ A.3.2.2** The Contractor's Commercial General Liability policy under this Section A.3.2.2 shall not contain an exclusion or restriction of coverage for the following:

- .1 Claims by one insured against another insured, if the exclusion or restriction is based solely on the fact that the claimant is an insured, and there would otherwise be coverage for the claim.
- .2 Claims for property damage to the Contractor's Work arising out of the products-completed operations hazard where the damaged Work or the Work out of which the damage arises was performed by a Subcontractor.
- .3 Claims for bodily injury other than to employees of the insured.
- .4 Claims for indemnity under Section 3.18 of the General Conditions arising out of injury to employees of the insured.
- .5 Claims or loss excluded under a prior work endorsement or other similar exclusionary language.
- .6 Claims or loss due to physical damage under a prior injury endorsement or similar exclusionary language.
- .7 Claims related to residential, multi-family, or other habitational projects, if the Work is to be performed on such a project.
- .8 Claims related to roofing, if the Work involves roofing.
- .9 Claims related to exterior insulation finish systems (EIFS), synthetic stucco or similar exterior coatings or surfaces, if the Work involves such coatings or surfaces.

*(Paragraph deleted)*

- .10 Claims related to explosion, collapse and underground hazards, where the Work involves such hazards.

**§ A.3.2.3** Automobile Liability covering vehicles owned, and non-owned vehicles used, by the Contractor, with policy limits of not less than One million dollars (\$ 1,000,000 ) per accident, for bodily injury, death of any person, and property damage arising out of the ownership, maintenance and use of those motor vehicles along with any other statutorily required automobile coverage.

**§ A.3.2.4** The Contractor may achieve the required limits and coverage for Commercial General Liability and Automobile Liability through a combination of primary and excess or umbrella liability insurance, provided such primary and excess or umbrella insurance policies result in the same or greater coverage as the coverages required under Section A.3.2.2 and A.3.2.3, and in no event shall any excess or umbrella liability insurance provide narrower coverage than the primary policy. The excess policy shall not require the exhaustion of the underlying limits only through the actual payment by the underlying insurers.

**§ A.3.2.5** Workers' Compensation at statutory limits.

**§ A.3.2.6** Employers' Liability with policy limits not less than One million dollars (\$ 1,000,000 ) each accident, One million dollars (\$ 1,000,000 ) each employee, and One million dollars (\$ 1,000,000 ) policy limit.

*(Paragraphs deleted)*

**§**

**§ A.3.2.9** If the Work involves the transport, dissemination, use, or release of pollutants, the Contractor shall procure Pollution Liability insurance, with policy limits of not less than One million dollars (\$ 1,000,000 ) per claim and Two million dollars (\$ 2,000,000 ) in the aggregate.

§ **A.3.2.10** Coverage under Sections A.3.2.8 and A.3.2.9 may be procured through a Combined Professional Liability and Pollution Liability insurance policy, with combined policy limits of not less than (\$ ) per claim and (\$ ) in the aggregate.

*(Paragraphs deleted)*

§

§ **A.3.3 Contractor's Other Insurance Coverage**

§ **A.3.3.1** Insurance selected and described in this Section A.3.3 shall be purchased from an insurance company or insurance companies lawfully authorized to issue insurance in the jurisdiction where the Project is located. The Contractor shall maintain the required insurance until the expiration of the period for correction of Work as set forth in Section 12.2.2 of the General Conditions, unless a different duration is stated below:

*(If the Contractor is required to maintain any of the types of insurance selected below for a duration other than the expiration of the period for correction of Work, state the duration.)*

§ **A.3.3.2** The Contractor shall purchase and maintain the following types and limits of insurance in accordance with Section A.3.3.1.

*(Select the types of insurance the Contractor is required to purchase and maintain by placing an X in the box(es) next to the description(s) of selected insurance. Where policy limits are provided, include the policy limit in the appropriate fill point.)*

*(Paragraphs deleted)*

§ **A.3.3.2.6 Other Insurance**

*(List below any other insurance coverage to be provided by the Contractor and any applicable limits.)*

Coverage	Limits
Excess liability	10,000,000

§ **A.3.4 Performance Bond and Payment Bond**

The Contractor shall provide surety bonds, from a company or companies lawfully authorized to issue surety bonds in the jurisdiction where the Project is located, as follows:

*(Specify type and penal sum of bonds.)*


Type	Penal Sum (\$0.00)
Payment Bond	None
Performance Bond	None

Payment and Performance Bonds shall be AIA Document A312™, Payment Bond and Performance Bond, or contain provisions identical to AIA Document A312™, current as of the date of this Agreement.

**ARTICLE A.4 SPECIAL TERMS AND CONDITIONS**

Special terms and conditions that modify this Insurance and Bonds Exhibit, if any, are as follows:

None



OWNER (Signature)

Jeremy Rieder President and Chief Executive Officer

(Printed name and title)

DocuSigned by:



7/17/2022 | 10:15 CDT

CONTRACTOR (Signature)

Camp Roofing, Ltd.  
By: Camp GP, LLC, its general partner  
By: Jeff Blevins President

(Printed name and title)

# Additions and Deletions Report for AIA® Document A101® – 2017 Exhibit A

This Additions and Deletions Report, as defined on page 1 of the associated document, reproduces below all text the author has added to the standard form AIA document in order to complete it, as well as any text the author may have added to or deleted from the original AIA text. Added text is shown underlined. Deleted text is indicated with a horizontal line through the original AIA text.

Note: This Additions and Deletions Report is provided for information purposes only and is not incorporated into or constitute any part of the associated AIA document. This Additions and Deletions Report and its associated document were generated simultaneously by AIA software at 11:07:15 CT on 06/27/2022.

## PAGE 1

This Insurance and Bonds Exhibit is part of the Agreement, between the Owner and the Contractor, dated the Twenty-seventh day of June in the year Two Thousand Twenty-two

...

The Saulet  
1420 Annunciation Street  
New Orleans, LA 70130

...

Saulet Apts LLC  
780 Third Ave 25<sup>th</sup> Fl  
New York, N.Y. 10017

...

Camp Roofing LTD dba Camp Construction Services  
15139 South Post Oak Road  
Houston, Texas 77053

## PAGE 4

§ A.3.2.2.1 Commercial General Liability insurance for the Project written on an occurrence form with policy limits of not less than One million dollars (\$ 1,000,000 ) each occurrence, Two million dollars (\$ 2,000,000 ) general aggregate, and Two million dollars (\$ 2,000,000 ) aggregate for products-completed operations hazard, providing coverage for claims including

## PAGE 5

- .3 damages because of physical damage to or destruction of tangible ~~property, including the loss of use of such property;~~ property.

...

- ~~.10~~ Claims related to earth subsidence or movement, where the Work involves such hazards.

~~.11~~

- .10 Claims related to explosion, collapse and underground hazards, where the Work involves such hazards.

§ A.3.2.3 Automobile Liability covering vehicles owned, and non-owned vehicles used, by the Contractor, with policy limits of not less than One million dollars (\$ 1,000,000 ) per accident, for bodily injury, death of any person, and

property damage arising out of the ownership, maintenance and use of those motor vehicles along with any other statutorily required automobile coverage.

...

~~§ A.3.2.6~~ Employers' Liability with policy limits not less than One million dollars (\$ 1,000,000 ) each accident, One million dollars (\$ 1,000,000 ) each employee, and One million dollars (\$ 1,000,000 ) policy limit.

~~§ A.3.2.7~~ Jones Act, and the Longshore & Harbor Workers' Compensation Act, as required, if the Work involves hazards arising from work on or near navigable waterways, including vessels and docks

~~§ A.3.2.8~~ If the Contractor is required to furnish professional services as part of the Work, the Contractor shall procure Professional Liability insurance covering performance of the professional services, with policy limits of not less than (\$ ) per claim and (\$ ) in the aggregate.

§

~~§ A.3.2.9~~ If the Work involves the transport, dissemination, use, or release of pollutants, the Contractor shall procure Pollution Liability insurance, with policy limits of not less than One million dollars (\$ 1,000,000 ) per claim and Two million dollars (\$ 2,000,000 ) in the aggregate.

PAGE 6

~~§ A.3.2.11~~ Insurance for maritime liability risks associated with the operation of a vessel, if the Work requires such activities, with policy limits of not less than (\$ ) per claim and (\$ ) in the aggregate.

~~§ A.3.2.12~~ Insurance for the use or operation of manned or unmanned aircraft, if the Work requires such activities, with policy limits of not less than (\$ ) per claim and (\$ ) in the aggregate.

§

...

[ ]

[ ]

[ ] ~~§ A.3.3.2.1~~ Property insurance of the same type and scope satisfying the requirements identified in Section A.2.3, which, if selected in this section A.3.3.2.1, relieves the Owner of the responsibility to purchase and maintain such insurance except insurance required by Section A.2.3.1.3 and Section A.2.3.3. The Contractor shall comply with all obligations of the Owner under Section A.2.3 except to the extent provided below. The Contractor shall disclose to the Owner the amount of any deductible, and the Owner shall be responsible for losses within the deductible. Upon request, the Contractor shall provide the Owner with a copy of the property insurance policy or policies required. The Owner shall adjust and settle the loss with the insurer and be the trustee of the proceeds of the property insurance in accordance with Article 11 of the General Conditions unless otherwise set forth below:

*(Where the Contractor's obligation to provide property insurance differs from the Owner's obligations as described under Section A.2.3, indicate such differences in the space below. Additionally, if a party other than the Owner will be responsible for adjusting and settling a loss with the insurer and acting as the trustee of the proceeds of property insurance in accordance with Article 11 of the General Conditions, indicate the responsible party below.)*

- ~~§ A.3.3.2.2 Railroad Protective Liability Insurance~~, with policy limits of not less than ~~(\$ )~~ per claim and ~~(\$ )~~ in the aggregate, for Work within fifty (50) feet of railroad property.
- ~~§ A.3.3.2.3 Asbestos Abatement Liability Insurance~~, with policy limits of not less than ~~(\$ )~~ per claim and ~~(\$ )~~ in the aggregate, for liability arising from the encapsulation, removal, handling, storage, transportation, and disposal of asbestos-containing materials.
- ~~§ A.3.3.2.4 Insurance for physical damage to property while it is in storage and in transit to the construction site on an "all-risks" completed value form.~~
- ~~§ A.3.3.2.5 Property insurance on an "all-risks" completed value form, covering property owned by the Contractor and used on the Project, including scaffolding and other equipment.~~
- ~~§ A.3.3.2.6 Other Insurance~~

...

<u>Excess liability</u>	<u>10,000,000</u>
-------------------------	-------------------

...

Payment Bond	<u>None</u>
Performance Bond	<u>None</u>

PAGE 7

None

OWNER (Signature)

Jeremy Rieder President and Chief Executive Officer  
*(Printed name and title)*

DocuSigned by:

7/17/2022 | 10:15 CDT

CONTRACTOR (Signature)

Camp Roofing, Ltd.  
By: Camp GP, LLC, its general partner  
By: Jeff Blevins President  
*(Printed name and title)*



# AIA® Document A201® – 2017

## General Conditions of the Contract for Construction

**for the following PROJECT:**

*(Name and location or address)*

The Saulet  
1420 Annunciation Street  
New Orleans, LA 70130

**THE OWNER:**

*(Name, legal status and address)*

Saulet Apts LLC  
780 Third Ave 25<sup>th</sup> Fl  
New York, N.Y. 10017

**THE ARCHITECT:**

*(Name, legal status and address)*

N/A

**TABLE OF ARTICLES**

- 1 GENERAL PROVISIONS
- 2 OWNER
- 3 CONTRACTOR
- 4 ARCHITECT
- 5 SUBCONTRACTORS
- 6 CONSTRUCTION BY OWNER OR BY SEPARATE CONTRACTORS
- 7 CHANGES IN THE WORK
- 8 TIME
- 9 PAYMENTS AND COMPLETION
- 10 PROTECTION OF PERSONS AND PROPERTY
- 11 INSURANCE AND BONDS
- 12 UNCOVERING AND CORRECTION OF WORK
- 13 MISCELLANEOUS PROVISIONS

**ADDITIONS AND DELETIONS:**

The author of this document has added information needed for its completion. The author may also have revised the text of the original AIA standard form. An *Additions and Deletions Report* that notes added information as well as revisions to the standard form text is available from the author and should be reviewed. A vertical line in the left margin of this document indicates where the author has added necessary information and where the author has added to or deleted from the original AIA text.

This document has important legal consequences. Consultation with an attorney is encouraged with respect to its completion or modification.

For guidance in modifying this document to include supplementary conditions, see AIA Document A503™, Guide for Supplementary Conditions.

Init.

/

14 TERMINATION OR SUSPENSION OF THE CONTRACT

15 CLAIMS AND DISPUTES



Init.

/

**INDEX**

(Topics and numbers in bold are Section headings.)

**Acceptance of Nonconforming Work**9.6.6, 9.9.3, **12.3**

Acceptance of Work

9.6.6, 9.8.2, 9.9.3, 9.10.1, 9.10.3, **12.3****Access to Work****3.16**, 6.2.1, 12.1

Accident Prevention

10

Acts and Omissions

3.2, 3.3.2, 3.12.8, 3.18, 4.2.3, 8.3.1, 9.5.1, 10.2.5,

10.2.8, 13.3.2, 14.1, 15.1.2, 15.2

Addenda

1.1.1

Additional Costs, Claims for

3.7.4, 3.7.5, 10.3.2, 15.1.5

**Additional Inspections and Testing**9.4.2, 9.8.3, 12.2.1, **13.4****Additional Time, Claims for**3.2.4, 3.7.4, 3.7.5, 3.10.2, 8.3.2, **15.1.6****Administration of the Contract**3.1.3, **4.2**, 9.4, 9.5

Advertisement or Invitation to Bid

1.1.1

Aesthetic Effect

4.2.13

**Allowances****3.8****Applications for Payment**4.2.5, 7.3.9, 9.2, **9.3**, 9.4, 9.5.1, 9.5.4, 9.6.3, 9.7, 9.10

Approvals

2.1.1, 2.3.1, 2.5, 3.1.3, 3.10.2, 3.12.8, 3.12.9,

3.12.10.1, 4.2.7, 9.3.2, 13.4.1

**Arbitration**8.3.1, 15.3.2, **15.4****ARCHITECT****4****Architect**, Definition of**4.1.1**

Architect, Extent of Authority

2.5, 3.12.7, 4.1.2, 4.2, 5.2, 6.3, 7.1.2, 7.3.4, 7.4, 9.2,  
9.3.1, 9.4, 9.5, 9.6.3, 9.8, 9.10.1, 9.10.3, 12.1, 12.2.1,  
13.4.1, 13.4.2, 14.2.2, 14.2.4, 15.1.4, 15.2.1

Architect, Limitations of Authority and Responsibility

2.1.1, 3.12.4, 3.12.8, 3.12.10, 4.1.2, 4.2.1, 4.2.2, 4.2.3,  
4.2.6, 4.2.7, 4.2.10, 4.2.12, 4.2.13, 5.2.1, 7.4, 9.4.2,  
9.5.4, 9.6.4, 15.1.4, 15.2

Architect's Additional Services and Expenses

2.5, 12.2.1, 13.4.2, 13.4.3, 14.2.4

Architect's Administration of the Contract

3.1.3, 3.7.4, 15.2, 9.4.1, 9.5

Architect's Approvals

2.5, 3.1.3, 3.5, 3.10.2, 4.2.7

Architect's Authority to Reject Work

3.5, 4.2.6, 12.1.2, 12.2.1

Architect's Copyright

1.1.7, 1.5

Architect's Decisions

3.7.4, 4.2.6, 4.2.7, 4.2.11, 4.2.12, 4.2.13, 4.2.14, 6.3,  
7.3.4, 7.3.9, 8.1.3, 8.3.1, 9.2, 9.4.1, 9.5, 9.8.4, 9.9.1,  
13.4.2, 15.2

Architect's Inspections

3.7.4, 4.2.2, 4.2.9, 9.4.2, 9.8.3, 9.9.2, 9.10.1, 13.4

Architect's Instructions

3.2.4, 3.3.1, 4.2.6, 4.2.7, 13.4.2

Architect's Interpretations

4.2.11, 4.2.12

Architect's Project Representative

4.2.10

Architect's Relationship with Contractor

1.1.2, 1.5, 2.3.3, 3.1.3, 3.2.2, 3.2.3, 3.2.4, 3.3.1, 3.4.2,  
3.5, 3.7.4, 3.7.5, 3.9.2, 3.9.3, 3.10, 3.11, 3.12, 3.16,  
3.18, 4.1.2, 4.2, 5.2, 6.2.2, 7, 8.3.1, 9.2, 9.3, 9.4, 9.5,  
9.7, 9.8, 9.9, 10.2.6, 10.3, 11.3, 12, 13.3.2, 13.4, 15.2

Architect's Relationship with Subcontractors

1.1.2, 4.2.3, 4.2.4, 4.2.6, 9.6.3, 9.6.4, 11.3

Architect's Representations

9.4.2, 9.5.1, 9.10.1

Architect's Site Visits

3.7.4, 4.2.2, 4.2.9, 9.4.2, 9.5.1, 9.9.2, 9.10.1, 13.4

Asbestos

10.3.1

Attorneys' Fees

3.18.1, 9.6.8, 9.10.2, 10.3.3

Award of Separate Contracts

6.1.1, 6.1.2

**Award of Subcontracts and Other Contracts for Portions of the Work****5.2****Basic Definitions****1.1**

Bidding Requirements

1.1.1

Binding Dispute Resolution

8.3.1, 9.7, 11.5, 13.1, 15.1.2, 15.1.3, 15.2.1, 15.2.5,  
15.2.6.1, 15.3.1, 15.3.2, 15.3.3, 15.4.1

Bonds, Lien

7.3.4.4, 9.6.8, 9.10.2, 9.10.3

**Bonds, Performance, and Payment**7.3.4.4, 9.6.7, 9.10.3, **11.1.2**, 11.1.3, **11.5****Building Information Models Use and Reliance****1.8**

Building Permit

3.7.1

**Capitalization****1.3**

Certificate of Substantial Completion

9.8.3, 9.8.4, 9.8.5

Init.

/

**Certificates for Payment**

4.2.1, 4.2.5, 4.2.9, 9.3.3, **9.4**, 9.5, 9.6.1, 9.6.6, 9.7,  
9.10.1, 9.10.3, 14.1.1.3, 14.2.4, 15.1.4

Certificates of Inspection, Testing or Approval  
13.4.4

Certificates of Insurance  
9.10.2

**Change Orders**

1.1.1, 3.4.2, 3.7.4, 3.8.2.3, 3.11, 3.12.8, 4.2.8, 5.2.3,  
7.1.2, 7.1.3, **7.2**, 7.3.2, 7.3.7, 7.3.9, 7.3.10, 8.3.1,  
9.3.1.1, 9.10.3, 10.3.2, 11.2, 11.5, 12.1.2

**Change Orders**, Definition of

**7.2.1****CHANGES IN THE WORK**

2.2.2, 3.11, 4.2.8, 7, 7.2.1, 7.3.1, 7.4, 8.3.1, 9.3.1.1,  
11.5

**Claims**, Definition of

**15.1.1**

Claims, Notice of  
1.6.2, 15.1.3

**CLAIMS AND DISPUTES**

3.2.4, 6.1.1, 6.3, 7.3.9, 9.3.3, 9.10.4, 10.3.3, **15**, 15.4  
Claims and Timely Assertion of Claims  
15.4.1

**Claims for Additional Cost**

3.2.4, 3.3.1, 3.7.4, 7.3.9, 9.5.2, 10.2.5, 10.3.2, **15.1.5**

**Claims for Additional Time**

3.2.4, 3.3.1, 3.7.4, 6.1.1, 8.3.2, 9.5.2, 10.3.2, **15.1.6**

**Concealed or Unknown Conditions, Claims for 3.7.4**

Claims for Damages  
3.2.4, 3.18, 8.3.3, 9.5.1, 9.6.7, 10.2.5, 10.3.3, 11.3,  
11.3.2, 14.2.4, 15.1.7

Claims Subject to Arbitration  
15.4.1

**Cleaning Up**

**3.15**, 6.3

Commencement of the Work, Conditions Relating to  
2.2.1, 3.2.2, 3.4.1, 3.7.1, 3.10.1, 3.12.6, 5.2.1, 5.2.3,  
6.2.2, 8.1.2, 8.2.2, 8.3.1, 11.1, 11.2, **15.1.5**

**Commencement of the Work**, Definition of **8.1.2****Communications**

3.9.1, **4.2.4**

Completion, Conditions Relating to  
3.4.1, 3.11, 3.15, 4.2.2, 4.2.9, 8.2, 9.4.2, 9.8, 9.9.1,  
9.10, 12.2, 14.1.2, 15.1.2

**COMPLETION, PAYMENTS AND 9**

Completion, Substantial  
3.10.1, 4.2.9, 8.1.1, 8.1.3, 8.2.3, 9.4.2, 9.8, 9.9.1,  
9.10.3, 12.2, 15.1.2  
Compliance with Laws  
2.3.2, 3.2.3, 3.6, 3.7, 3.12.10, 3.13, 9.6.4, 10.2.2, 13.1,  
13.3, 13.4.1, 13.4.2, 13.5, 14.1.1, 14.2.1.3, 15.2.8,  
15.4.2, 15.4.3

**Concealed or Unknown Conditions**

3.7.4, 4.2.8, 8.3.1, 10.3

**Conditions of the Contract**

1.1.1, 6.1.1, 6.1.4

**Consent, Written**

3.4.2, 3.14.2, 4.1.2, 9.8.5, 9.9.1, 9.10.2, 9.10.3, 13.2,  
15.4.4.2

**Consolidation or Joinder****15.4.4****CONSTRUCTION BY OWNER OR BY SEPARATE CONTRACTORS**

1.1.4, **6**

**Construction Change Directive**, Definition of **7.3.1****Construction Change Directives**

1.1.1, 3.4.2, 3.11, 3.12.8, 4.2.8, 7.1.1, 7.1.2, 7.1.3, **7.3**,  
9.3.1.1

Construction Schedules, Contractor's

3.10, 3.11, 3.12.1, 3.12.2, 6.1.3, 15.1.6.2

**Contingent Assignment of Subcontracts**

**5.4**, 14.2.2.2

**Continuing Contract Performance****15.1.4**

**Contract**, Definition of

**1.1.2****CONTRACT, TERMINATION OR SUSPENSION OF THE**

5.4.1.1, 5.4.2, 11.5, **14**

Contract Administration

3.1.3, 4, 9.4, 9.5

Contract Award and Execution, Conditions Relating to

3.7.1, 3.10, 5.2, 6.1

Contract Documents, Copies Furnished and Use of  
1.5.2, 2.3.6, 5.3

**Contract Documents**, Definition of

**1.1.1****Contract Sum**

2.2.2, 2.2.4, 3.7.4, 3.7.5, 3.8, 3.10.2, 5.2.3, 7.3, 7.4,  
**9.1**, 9.2, 9.4.2, 9.5.1.4, 9.6.7, 9.7, 10.3.2, 11.5, 12.1.2,  
12.3, 14.2.4, 14.3.2, 15.1.4.2, **15.1.5**, **15.2.5**

**Contract Sum**, Definition of

**9.1**

Contract Time

1.1.4, 2.2.1, 2.2.2, 3.7.4, 3.7.5, 3.10.2, 5.2.3, 6.1.5,  
7.2.1.3, 7.3.1, 7.3.5, 7.3.6, 7, 7.3.10, 7.4, 8.1.1,  
8.2.1, 8.2.3, 8.3.1, 9.5.1, 9.7, 10.3.2, 12.1.1, 12.1.2,  
14.3.2, 15.1.4.2, 15.1.6.1, 15.2.5

**Contract Time**, Definition of

**8.1.1****CONTRACTOR****3**

Contractor, Definition of

**3.1**, **6.1.2****Contractor's Construction and Submittal Schedules**

**3.10**, 3.12.1, 3.12.2, 4.2.3, 6.1.3, 15.1.6.2

Init.

/

**Contractor's Employees**

2.2.4, 3.3.2, 3.4.3, 3.8.1, 3.9, 3.18.2, 4.2.3, 4.2.6, 10.2, 10.3, 11.3, 14.1, 14.2.1.1

**Contractor's Liability Insurance****11.1****Contractor's Relationship with Separate Contractors and Owner's Forces**

3.12.5, 3.14.2, 4.2.4, 6, 11.3, 12.2.4

**Contractor's Relationship with Subcontractors**

1.2.2, 2.2.4, 3.3.2, 3.18.1, 3.18.2, 4.2.4, 5, 9.6.2, 9.6.7, 9.10.2, 11.2, 11.3, 11.4

**Contractor's Relationship with the Architect**

1.1.2, 1.5, 2.3.3, 3.1.3, 3.2.2, 3.2.3, 3.2.4, 3.3.1, 3.4.2, 3.5.1, 3.7.4, 3.10, 3.11, 3.12, 3.16, 3.18, 4.2, 5.2, 6.2.2, 7, 8.3.1, 9.2, 9.3, 9.4, 9.5, 9.7, 9.8, 9.9, 10.2.6, 10.3, 11.3, 12, 13.4, 15.1.3, 15.2.1

**Contractor's Representations**

3.2.1, 3.2.2, 3.5, 3.12.6, 6.2.2, 8.2.1, 9.3.3, 9.8.2

**Contractor's Responsibility for Those Performing the Work**

3.3.2, 3.18, 5.3, 6.1.3, 6.2, 9.5.1, 10.2.8

**Contractor's Review of Contract Documents**

3.2

**Contractor's Right to Stop the Work**

2.2.2, 9.7

**Contractor's Right to Terminate the Contract**

14.1

**Contractor's Submittals**

3.10, 3.11, 3.12, 4.2.7, 5.2.1, 5.2.3, 9.2, 9.3, 9.8.2, 9.8.3, 9.9.1, 9.10.2, 9.10.3

**Contractor's Superintendent**

3.9, 10.2.6

**Contractor's Supervision and Construction****Procedures**

1.2.2, 3.3, 3.4, 3.12.10, 4.2.2, 4.2.7, 6.1.3, 6.2.4, 7.1.3, 7.3.4, 7.3.6, 8.2, 10, 12, 14, 15.1.4

**Coordination and Correlation**

1.2, 3.2.1, 3.3.1, 3.10, 3.12.6, 6.1.3, 6.2.1

**Copies Furnished of Drawings and Specifications**

1.5, 2.3.6, 3.11

**Copyrights**1.5, **3.17****Correction of Work**2.5, 3.7.3, 9.4.2, 9.8.2, 9.8.3, 9.9.1, 12.1.2, **12.2**, 12.3, 15.1.3.1, 15.1.3.2, 15.2.1**Correlation and Intent of the Contract Documents****1.2****Cost, Definition of****7.3.4****Costs**

2.5, 3.2.4, 3.7.3, 3.8.2, 3.15.2, 5.4.2, 6.1.1, 6.2.3, 7.3.3.3, 7.3.4, 7.3.8, 7.3.9, 9.10.2, 10.3.2, 10.3.6, 11.2, 12.1.2, 12.2.1, 12.2.4, 13.4, 14

**Cutting and Patching****3.14**, 6.2.5**Damage to Construction of Owner or Separate Contractors**

3.14.2, 6.2.4, 10.2.1.2, 10.2.5, 10.4, 12.2.4

**Damage to the Work**

3.14.2, 9.9.1, 10.2.1.2, 10.2.5, 10.4, 12.2.4

**Damages, Claims for**

3.2.4, 3.18, 6.1.1, 8.3.3, 9.5.1, 9.6.7, 10.3.3, 11.3.2, 11.3, 14.2.4, 15.1.7

**Damages for Delay**

6.2.3, 8.3.3, 9.5.1.6, 9.7, 10.3.2, 14.3.2

**Date of Commencement of the Work, Definition of****8.1.2****Date of Substantial Completion, Definition of****8.1.3****Day, Definition of****8.1.4****Decisions of the Architect**

3.7.4, 4.2.6, 4.2.7, 4.2.11, 4.2.12, 4.2.13, 6.3, 7.3.4, 7.3.9, 8.1.3, 8.3.1, 9.2, 9.4, 9.5.1, 9.8.4, 9.9.1, 13.4.2, 14.2.2, 14.2.4, 15.1, 15.2

**Decisions to Withhold Certification**9.4.1, **9.5**, 9.7, 14.1.1.3**Defective or Nonconforming Work, Acceptance, Rejection and Correction of**

2.5, 3.5, 4.2.6, 6.2.3, 9.5.1, 9.5.3, 9.6.6, 9.8.2, 9.9.3, 9.10.4, 12.2.1

**Definitions**

1.1, 2.1.1, 3.1.1, 3.5, 3.12.1, 3.12.2, 3.12.3, 4.1.1, 5.1, 6.1.2, 7.2.1, 7.3.1, 8.1, 9.1, 9.8.1, 15.1.1

**Delays and Extensions of Time****3.2**, **3.7.4**, 5.2.3, 7.2.1, 7.3.1, **7.4**, **8.3**, 9.5.1, **9.7**, 10.3.2, **10.4**, 14.3.2, **15.1.6**, 15.2.5**Digital Data Use and Transmission****1.7****Disputes**

6.3, 7.3.9, 15.1, 15.2

**Documents and Samples at the Site****3.11****Drawings, Definition of****1.1.5**

Drawings and Specifications, Use and Ownership of 3.11

**Effective Date of Insurance**

8.2.2

**Emergencies****10.4**, 14.1.1.2, **15.1.5****Employees, Contractor's**

3.3.2, 3.4.3, 3.8.1, 3.9, 3.18.2, 4.2.3, 4.2.6, 10.2, 10.3.3, 11.3, 14.1, 14.2.1.1

**Equipment, Labor, or Materials**

1.1.3, 1.1.6, 3.4, 3.5, 3.8.2, 3.8.3, 3.12, 3.13, 3.15.1, 4.2.6, 4.2.7, 5.2.1, 6.2.1, 7.3.4, 9.3.2, 9.3.3, 9.5.1.3, 9.10.2, 10.2.1, 10.2.4, 14.2.1.1, 14.2.1.2

**Execution and Progress of the Work**

1.1.3, 1.2.1, 1.2.2, 2.3.4, 2.3.6, 3.1, 3.3.1, 3.4.1, 3.7.1, 3.10.1, 3.12, 3.14, 4.2, 6.2.2, 7.1.3, 7.3.6, 8.2, 9.5.1, 9.9.1, 10.2, 10.3, 12.1, 12.2, 14.2, 14.3.1, 15.1.4

Extensions of Time  
3.2.4, 3.7.4, 5.2.3, 7.2.1, 7.3, 7.4, 9.5.1, 9.7, 10.3.2,  
10.4, 14.3, 15.1.6, **15.2.5**

**Failure of Payment**

9.5.1.3, **9.7**, 9.10.2, 13.5, 14.1.1.3, 14.2.1.2

Faulty Work

(See Defective or Nonconforming Work)

**Final Completion and Final Payment**

4.2.1, 4.2.9, 9.8.2, **9.10**, 12.3, 14.2.4, 14.4.3

Financial Arrangements, Owner's

2.2.1, 13.2.2, 14.1.1.4

**GENERAL PROVISIONS**

**1**

**Governing Law**

**13.1**

Guarantees (See Warranty)

**Hazardous Materials and Substances**

10.2.4, **10.3**

Identification of Subcontractors and Suppliers

5.2.1

**Indemnification**

3.17, **3.18**, 9.6.8, 9.10.2, 10.3.3, 11.3

**Information and Services Required of the Owner**

2.1.2, **2.2**, 2.3, 3.2.2, 3.12.10.1, 6.1.3, 6.1.4, 6.2.5,

9.6.1, 9.9.2, 9.10.3, 10.3.3, 11.2, 13.4.1, 13.4.2,

14.1.1.4, 14.1.4, 15.1.4

**Initial Decision**

**15.2**

**Initial Decision Maker, Definition of**

1.1.8

Initial Decision Maker, Decisions

14.2.4, 15.1.4.2, 15.2.1, 15.2.2, 15.2.3, 15.2.4, 15.2.5

Initial Decision Maker, Extent of Authority

14.2.4, 15.1.4.2, 15.2.1, 15.2.2, 15.2.3, 15.2.4, 15.2.5

**Injury or Damage to Person or Property**

**10.2.8**, 10.4

Inspections

3.1.3, 3.3.3, 3.7.1, 4.2.2, 4.2.6, 4.2.9, 9.4.2, 9.8.3,

9.9.2, 9.10.1, 12.2.1, 13.4

Instructions to Bidders

1.1.1

Instructions to the Contractor

3.2.4, 3.3.1, 3.8.1, 5.2.1, 7, 8.2.2, 12, 13.4.2

**Instruments of Service, Definition of**

**1.1.7**

Insurance

6.1.1, 7.3.4, 8.2.2, 9.3.2, 9.8.4, 9.9.1, 9.10.2, 10.2.5, **11**

Insurance, Notice of Cancellation or Expiration

11.1.4, 11.2.3

**Insurance, Contractor's Liability**

**11.1**

Insurance, Effective Date of

8.2.2, 14.4.2

**Insurance, Owner's Liability**

**11.2**

**Insurance, Property**

**10.2.5**, 11.2, 11.4, 11.5

Insurance, Stored Materials

9.3.2

**INSURANCE AND BONDS**

**11**

Insurance Companies, Consent to Partial Occupancy

9.9.1

Insured loss, Adjustment and Settlement of

11.5

Intent of the Contract Documents

1.2.1, 4.2.7, 4.2.12, 4.2.13

**Interest**

**13.5**

**Interpretation**

1.1.8, 1.2.3, **1.4**, 4.1.1, 5.1, 6.1.2, 15.1.1

Interpretations, Written

4.2.11, 4.2.12

Judgment on Final Award

15.4.2

**Labor and Materials, Equipment**

1.1.3, 1.1.6, **3.4**, 3.5, 3.8.2, 3.8.3, 3.12, 3.13, 3.15.1,

5.2.1, 6.2.1, 7.3.4, 9.3.2, 9.3.3, 9.5.1.3, 9.10.2, 10.2.1,

10.2.4, 14.2.1.1, 14.2.1.2

Labor Disputes

8.3.1

Laws and Regulations

1.5, 2.3.2, 3.2.3, 3.2.4, 3.6, 3.7, 3.12.10, 3.13, 9.6.4,

9.9.1, 10.2.2, 13.1, 13.3.1, 13.4.2, 13.5, 14, 15.2.8,

15.4

Liens

2.1.2, 9.3.1, 9.3.3, 9.6.8, 9.10.2, 9.10.4, 15.2.8

Limitations, Statutes of

12.2.5, 15.1.2, 15.4.1.1

Limitations of Liability

3.2.2, 3.5, 3.12.10, 3.12.10.1, 3.17, 3.18.1, 4.2.6,

4.2.7, 6.2.2, 9.4.2, 9.6.4, 9.6.7, 9.6.8, 10.2.5, 10.3.3,

11.3, 12.2.5, 13.3.1

Limitations of Time

2.1.2, 2.2, 2.5, 3.2.2, 3.10, 3.11, 3.12.5, 3.15.1, 4.2.7,

5.2, 5.3, 5.4.1, 6.2.4, 7.3, 7.4, 8.2, 9.2, 9.3.1, 9.3.3,

9.4.1, 9.5, 9.6, 9.7, 9.8, 9.9, 9.10, 12.2, 13.4, 14, 15,

15.1.2, 15.1.3, 15.1.5

**Materials, Hazardous**

**10.2.4**, **10.3**

Materials, Labor, Equipment and

1.1.3, 1.1.6, 3.4.1, 3.5, 3.8.2, 3.8.3, 3.12, 3.13, 3.15.1,

5.2.1, 6.2.1, 7.3.4, 9.3.2, 9.3.3, 9.5.1.3, 9.10.2,

10.2.1.2, 10.2.4, 14.2.1.1, 14.2.1.2

Means, Methods, Techniques, Sequences and

Procedures of Construction

3.3.1, 3.12.10, 4.2.2, 4.2.7, 9.4.2

Mechanic's Lien

2.1.2, 9.3.1, 9.3.3, 9.6.8, 9.10.2, 9.10.4, 15.2.8

**Mediation**

8.3.1, 15.1.3.2, 15.2.1, 15.2.5, 15.2.6, **15.3**, 15.4.1,

15.4.1.1

**Minor Changes in the Work**

1.1.1, 3.4.2, 3.12.8, 4.2.8, 7.1, **7.4**

Init.

/

**MISCELLANEOUS PROVISIONS****13****Modifications, Definition of****1.1.1**

## Modifications to the Contract

1.1.1, 1.1.2, 2.5, 3.11, 4.1.2, 4.2.1, 5.2.3, 7, 8.3.1, 9.7, 10.3.2

**Mutual Responsibility****6.2****Nonconforming Work, Acceptance of**9.6.6, 9.9.3, **12.3**Nonconforming Work, Rejection and Correction of  
2.4, 2.5, 3.5, 4.2.6, 6.2.4, 9.5.1, 9.8.2, 9.9.3, 9.10.4, 12.2**Notice****1.6**, 1.6.1, 1.6.2, 2.1.2, 2.2.2., 2.2.3, 2.2.4, 2.5, 3.2.4, 3.3.1, 3.7.4, 3.7.5, 3.9.2, 3.12.9, 3.12.10, 5.2.1, 7.4, 8.2.2, 9.6.8, 9.7, 9.10.1, 10.2.8, 10.3.2, 11.5, 12.2.2.1, 13.4.1, 13.4.2, 14.1, 14.2.2, 14.4.2, 15.1.3, 15.1.5, 15.1.6, 15.4.1

## Notice of Cancellation or Expiration of Insurance

11.1.4, 11.2.3

**Notice of Claims**1.6.2, 2.1.2, 3.7.4, 9.6.8, 10.2.8, **15.1.3**, 15.1.5, 15.1.6, 15.2.8, 15.3.2, 15.4.1

## Notice of Testing and Inspections

13.4.1, 13.4.2

## Observations, Contractor's

3.2, 3.7.4

## Occupancy

2.3.1, 9.6.6, 9.8

## Orders, Written

1.1.1, 2.4, 3.9.2, 7, 8.2.2, 11.5, 12.1, 12.2.2.1, 13.4.2, 14.3.1

**OWNER****2****Owner, Definition of****2.1.1****Owner, Evidence of Financial Arrangements****2.2**, 13.2.2, 14.1.1.4**Owner, Information and Services Required of the**2.1.2, **2.2**, 2.3, 3.2.2, 3.12.10, 6.1.3, 6.1.4, 6.2.5, 9.3.2, 9.6.1, 9.6.4, 9.9.2, 9.10.3, 10.3.3, 11.2, 13.4.1, 13.4.2, 14.1.1.4, 14.1.4, 15.1.4

## Owner's Authority

1.5, 2.1.1, 2.3.32.4, 2.5, 3.4.2, 3.8.1, 3.12.10, 3.14.2, 4.1.2, 4.2.4, 4.2.9, 5.2.1, 5.2.4, 5.4.1, 6.1, 6.3, 7.2.1, 7.3.1, 8.2.2, 8.3.1, 9.3.2, 9.5.1, 9.6.4, 9.9.1, 9.10.2, 10.3.2, 11.4, 11.5, 12.2.2, 12.3, 13.2.2, 14.3, 14.4, 15.2.7

**Owner's Insurance****11.2**

## Owner's Relationship with Subcontractors

1.1.2, 5.2, 5.3, 5.4, 9.6.4, 9.10.2, 14.2.2

**Owner's Right to Carry Out the Work****2.5**, 14.2.2**Owner's Right to Clean Up****6.3****Owner's Right to Perform Construction and to Award Separate Contracts****6.1****Owner's Right to Stop the Work****2.4**

## Owner's Right to Suspend the Work

14.3

## Owner's Right to Terminate the Contract

14.2, 14.4

**Ownership and Use of Drawings, Specifications and Other Instruments of Service**1.1.1, 1.1.6, 1.1.7, **1.5**, 2.3.6, 3.2.2, 3.11, 3.17, 4.2.12, 5.3**Partial Occupancy or Use**9.6.6, **9.9****Patching, Cutting and****3.14**, 6.2.5

## Patents

3.17

**Payment, Applications for**4.2.5, 7.3.9, 9.2, **9.3**, 9.4, 9.5, 9.6.3, 9.7, 9.8.5, 9.10.1, 14.2.3, 14.2.4, 14.4.3**Payment, Certificates for**4.2.5, 4.2.9, 9.3.3, **9.4**, 9.5, 9.6.1, 9.6.6, 9.7, 9.10.1, 9.10.3, 14.1.1.3, 14.2.4**Payment, Failure of**9.5.1.3, **9.7**, 9.10.2, 13.5, 14.1.1.3, 14.2.1.2

## Payment, Final

4.2.1, 4.2.9, **9.10**, 12.3, 14.2.4, 14.4.3**Payment Bond, Performance Bond and**7.3.4.4, 9.6.7, 9.10.3, **11.1.2****Payments, Progress**9.3, **9.6**, 9.8.5, 9.10.3, 14.2.3, 15.1.4**PAYMENTS AND COMPLETION****9**

## Payments to Subcontractors

5.4.2, 9.5.1.3, 9.6.2, 9.6.3, 9.6.4, 9.6.7, 14.2.1.2

## PCB

10.3.1

**Performance Bond and Payment Bond**7.3.4.4, 9.6.7, 9.10.3, **11.1.2****Permits, Fees, Notices and Compliance with Laws**2.3.1, **3.7**, 3.13, 7.3.4.4, 10.2.2**PERSONS AND PROPERTY, PROTECTION OF****10**

## Polychlorinated Biphenyl

10.3.1

**Product Data, Definition of****3.12.2****Product Data and Samples, Shop Drawings**3.11, **3.12**, 4.2.7**Progress and Completion**4.2.2, **8.2**, 9.8, 9.9.1, 14.1.4, 15.1.4**Progress Payments**9.3, **9.6**, 9.8.5, 9.10.3, 14.2.3, 15.1.4

Init.

/

**Project, Definition of****1.1.4**

Project Representatives

4.2.10

**Property Insurance**10.2.5, **11.2****Proposal Requirements**

1.1.1

**PROTECTION OF PERSONS AND PROPERTY  
10**

Regulations and Laws

1.5, 2.3.2, 3.2.3, 3.6, 3.7, 3.12.10, 3.13, 9.6.4, 9.9.1,  
10.2.2, 13.1, 13.3, 13.4.1, 13.4.2, 13.5, 14, 15.2.8, 15.4

Rejection of Work

4.2.6, 12.2.1

Releases and Waivers of Liens

9.3.1, 9.10.2

Representations

3.2.1, 3.5, 3.12.6, 8.2.1, 9.3.3, 9.4.2, 9.5.1, 9.10.1

Representatives

2.1.1, 3.1.1, 3.9, 4.1.1, 4.2.10, 13.2.1

Responsibility for Those Performing the Work

3.3.2, 3.18, 4.2.2, 4.2.3, 5.3, 6.1.3, 6.2, 6.3, 9.5.1, 10

Retainage

9.3.1, 9.6.2, 9.8.5, 9.9.1, 9.10.2, 9.10.3

**Review of Contract Documents and Field****Conditions by Contractor****3.2**, 3.12.7, 6.1.3Review of Contractor's Submittals by Owner and  
Architect

3.10.1, 3.10.2, 3.11, 3.12, 4.2, 5.2, 6.1.3, 9.2, 9.8.2

Review of Shop Drawings, Product Data and Samples  
by Contractor

3.12

**Rights and Remedies**1.1.2, 2.4, 2.5, 3.5, 3.7.4, 3.15.2, 4.2.6, 5.3, 5.4, 6.1,  
6.3, 7.3.1, 8.3, 9.5.1, 9.7, 10.2.5, 10.3, 12.2.1, 12.2.2,  
12.2.4, **13.3**, 14, 15.4**Royalties, Patents and Copyrights****3.17**

Rules and Notices for Arbitration

15.4.1

**Safety of Persons and Property****10.2**, 10.4**Safety Precautions and Programs**3.3.1, 4.2.2, 4.2.7, 5.3, **10.1**, 10.2, 10.4**Samples**, Definition of**3.12.3****Samples, Shop Drawings, Product Data and**3.11, **3.12**, 4.2.7**Samples at the Site, Documents and****3.11****Schedule of Values****9.2**, 9.3.1

Schedules, Construction

3.10, 3.12.1, 3.12.2, 6.1.3, 15.1.6.2

Separate Contracts and Contractors

1.1.4, 3.12.5, 3.14.2, 4.2.4, 4.2.7, 6, 8.3.1, 12.1.2

**Separate Contractors**, Definition of**6.1.1****Shop Drawings**, Definition of**3.12.1****Shop Drawings, Product Data and Samples**3.11, **3.12**, 4.2.7**Site, Use of****3.13**, 6.1.1, 6.2.1

Site Inspections

3.2.2, 3.3.3, 3.7.1, 3.7.4, 4.2, 9.9.2, 9.4.2, 9.10.1, 13.4

Site Visits, Architect's

3.7.4, 4.2.2, 4.2.9, 9.4.2, 9.5.1, 9.9.2, 9.10.1, 13.4

Special Inspections and Testing

4.2.6, 12.2.1, 13.4

**Specifications**, Definition of**1.1.6****Specifications**1.1.1, **1.1.6**, 1.2.2, 1.5, 3.12.10, 3.17, 4.2.14

Statute of Limitations

15.1.2, 15.4.1.1

Stopping the Work

2.2.2, 2.4, 9.7, 10.3, 14.1

Stored Materials

6.2.1, 9.3.2, 10.2.1.2, 10.2.4

**Subcontractor**, Definition of**5.1.1****SUBCONTRACTORS****5**

Subcontractors, Work by

1.2.2, 3.3.2, 3.12.1, 3.18, 4.2.3, 5.2.3, 5.3, 5.4, 9.3.1.2,  
9.6.7**Subcontractual Relations****5.3**, 5.4, 9.3.1.2, 9.6, 9.10, 10.2.1, 14.1, 14.2.1

Submittals

3.10, 3.11, 3.12, 4.2.7, 5.2.1, 5.2.3, 7.3.4, 9.2, 9.3, 9.8,  
9.9.1, 9.10.2, 9.10.3

Submittal Schedule

3.10.2, 3.12.5, 4.2.7

**Subrogation, Waivers of**6.1.1, **11.3****Substances, Hazardous****10.3****Substantial Completion**4.2.9, 8.1.1, 8.1.3, 8.2.3, 9.4.2, **9.8**, 9.9.1, 9.10.3, 12.2,  
15.1.2**Substantial Completion**, Definition of**9.8.1**

Substitution of Subcontractors

5.2.3, 5.2.4

Substitution of Architect

2.3.3

Substitutions of Materials

3.4.2, 3.5, 7.3.8

**Sub-subcontractor**, Definition of**5.1.2**

Init.

/

**Subsurface Conditions**

3.7.4

**Successors and Assigns****13.2****Superintendent**

3.9, 10.2.6

**Supervision and Construction Procedures**1.2.2, **3.3**, 3.4, 3.12.10, 4.2.2, 4.2.7, 6.1.3, 6.2.4, 7.1.3, 7.3.4, 8.2, 8.3.1, 9.4.2, 10, 12, 14, 15.1.4**Suppliers**

1.5, 3.12.1, 4.2.4, 4.2.6, 5.2.1, 9.3, 9.4.2, 9.5.4, 9.6, 9.10.5, 14.2.1

**Surety**

5.4.1.2, 9.6.8, 9.8.5, 9.10.2, 9.10.3, 11.1.2, 14.2.2, 15.2.7

**Surety, Consent of**

9.8.5, 9.10.2, 9.10.3

**Surveys**

1.1.7, 2.3.4

**Suspension by the Owner for Convenience****14.3****Suspension of the Work**

3.7.5, 5.4.2, 14.3

**Suspension or Termination of the Contract**

5.4.1.1, 14

**Taxes**

3.6, 3.8.2.1, 7.3.4.4

**Termination by the Contractor**

14.1, 15.1.7

**Termination by the Owner for Cause**5.4.1.1, **14.2**, 15.1.7**Termination by the Owner for Convenience****14.4****Termination of the Architect**

2.3.3

**Termination of the Contractor Employment**

14.2.2

**TERMINATION OR SUSPENSION OF THE CONTRACT****14****Tests and Inspections**3.1.3, 3.3.3, 3.7.1, 4.2.2, 4.2.6, 4.2.9, 9.4.2, 9.8.3, 9.9.2, 9.10.1, 10.3.2, 12.2.1, **13.4****TIME****8****Time, Delays and Extensions of**3.2.4, 3.7.4, 5.2.3, 7.2.1, 7.3.1, 7.4, **8.3**, 9.5.1, 9.7, 10.3.2, 10.4, 14.3.2, 15.1.6, 15.2.5**Time Limits**

2.1.2, 2.2, 2.5, 3.2.2, 3.10, 3.11, 3.12.5, 3.15.1, 4.2, 5.2, 5.3, 5.4, 6.2.4, 7.3, 7.4, 8.2, 9.2, 9.3.1, 9.3.3, 9.4.1, 9.5, 9.6, 9.7, 9.8, 9.9, 9.10, 12.2, 13.4, 14, 15.1.2, 15.1.3, 15.4

**Time Limits on Claims**

3.7.4, 10.2.8, 15.1.2, 15.1.3

**Title to Work**

9.3.2, 9.3.3

**UNCOVERING AND CORRECTION OF WORK****12****Uncovering of Work****12.1****Unforeseen Conditions, Concealed or Unknown**

3.7.4, 8.3.1, 10.3

**Unit Prices**

7.3.3.2, 9.1.2

**Use of Documents**

1.1.1, 1.5, 2.3.6, 3.12.6, 5.3

**Use of Site****3.13**, 6.1.1, 6.2.1**Values, Schedule of****9.2**, 9.3.1**Waiver of Claims by the Architect**

13.3.2

**Waiver of Claims by the Contractor**9.10.5, 13.3.2, **15.1.7****Waiver of Claims by the Owner**9.9.3, 9.10.3, 9.10.4, 12.2.2.1, 13.3.2, 14.2.4, **15.1.7****Waiver of Consequential Damages**

14.2.4, 15.1.7

**Waiver of Liens**

9.3, 9.10.2, 9.10.4

**Waivers of Subrogation**6.1.1, **11.3****Warranty****3.5**, 4.2.9, 9.3.3, 9.8.4, 9.9.1, 9.10.2, 9.10.4, 12.2.2, 15.1.2**Weather Delays**

8.3, 15.1.6.2

**Work, Definition of****1.1.3****Written Consent**

1.5.2, 3.4.2, 3.7.4, 3.12.8, 3.14.2, 4.1.2, 9.3.2, 9.10.3, 13.2, 13.3.2, 15.4.4.2

**Written Interpretations**

4.2.11, 4.2.12

**Written Orders**

1.1.1, 2.4, 3.9, 7, 8.2.2, 12.1, 12.2, 13.4.2, 14.3.1

## ARTICLE 1 GENERAL PROVISIONS

### § 1.1 Basic Definitions

#### § 1.1.1 The Contract Documents

The Contract Documents are enumerated in the Agreement between the Owner and Contractor (hereinafter the Agreement) and consist of the Agreement, Conditions of the Contract (General, Supplementary and other Conditions), Drawings, Specifications, Addenda issued prior to execution of the Contract, other documents listed in the Agreement, and Modifications issued after execution of the Contract. A Modification is (1) a written amendment to the Contract signed by both parties, (2) a Change Order, (3) a Construction Change Directive, or (4) a written order for a minor change in the Work issued by the Architect. Unless specifically enumerated in the Agreement, the Contract Documents do not include the advertisement or invitation to bid, Instructions to Bidders, sample forms, other information furnished by the Owner in anticipation of receiving bids or proposals, the Contractor's bid or proposal, or portions of Addenda relating to bidding or proposal requirements.

#### § 1.1.2 The Contract

The Contract Documents form the Contract for Construction. The Contract represents the entire and integrated agreement between the parties hereto and supersedes prior negotiations, representations, or agreements, either written or oral. The Contract may be amended or modified only by a Modification. The Contract Documents shall not be construed to create a contractual relationship of any kind (1) between the Contractor and the Architect or the Architect's consultants, (2) between the Owner and a Subcontractor or a Sub-subcontractor, (3) between the Owner and the Architect or the Architect's consultants, or (4) between any persons or entities other than the Owner and the Contractor. The Architect shall, however, be entitled to performance and enforcement of obligations under the Contract intended to facilitate performance of the Architect's duties.

#### § 1.1.3 The Work

The term "Work" means the construction and services required by the Contract Documents, whether completed or partially completed, and includes all other labor, materials, equipment, and services provided or to be provided by the Contractor to fulfill the Contractor's obligations. The Work may constitute the whole or a part of the Project.

#### § 1.1.4 The Project

The Project is the total construction of which the Work performed under the Contract Documents may be the whole or a part and which may include construction by the Owner and by Separate Contractors.

#### § 1.1.5 The Drawings

The Drawings are the graphic and pictorial portions of the Contract Documents showing the design, location and dimensions of the Work, generally including plans, elevations, sections, details, schedules, and diagrams.

#### § 1.1.6 The Specifications

The Specifications are that portion of the Contract Documents consisting of the written requirements for materials, equipment, systems, standards and workmanship for the Work, and performance of related services.

#### § 1.1.7 Instruments of Service

Instruments of Service are representations, in any medium of expression now known or later developed, of the tangible and intangible creative work performed by the Architect and the Architect's consultants under their respective professional services agreements. Instruments of Service may include, without limitation, studies, surveys, models, sketches, drawings, specifications, and other similar materials.

#### § 1.1.8 Initial Decision Maker

The Initial Decision Maker is the person identified in the Agreement to render initial decisions on Claims in accordance with Section 15.2. The Initial Decision Maker shall not show partiality to the Owner or Contractor and shall not be liable for results of interpretations or decisions rendered in good faith.

### § 1.2 Correlation and Intent of the Contract Documents

§ 1.2.1 The intent of the Contract Documents is to include all items necessary for the proper execution and completion of the Work by the Contractor. The Contract Documents are complementary, and what is required by one shall be as binding as if required by all; performance by the Contractor shall be required only to the extent consistent with the Contract Documents and reasonably inferable from them as being necessary to produce the indicated results.

§ 1.2.1.1 The invalidity of any provision of the Contract Documents shall not invalidate the Contract or its remaining provisions. If it is determined that any provision of the Contract Documents violates any law, or is otherwise invalid or unenforceable, then that provision shall be revised to the extent necessary to make that provision legal and enforceable. In such case the Contract Documents shall be construed, to the fullest extent permitted by law, to give effect to the parties' intentions and purposes in executing the Contract.

§ 1.2.2 Organization of the Specifications into divisions, sections and articles, and arrangement of Drawings shall not control the Contractor in dividing the Work among Subcontractors or in establishing the extent of Work to be performed by any trade.

§ 1.2.3 Unless otherwise stated in the Contract Documents, words that have well-known technical or construction industry meanings are used in the Contract Documents in accordance with such recognized meanings.

### § 1.3 Capitalization

Terms capitalized in these General Conditions include those that are (1) specifically defined, (2) the titles of numbered articles, or (3) the titles of other documents published by the American Institute of Architects.

### § 1.4 Interpretation

In the interest of brevity the Contract Documents frequently omit modifying words such as "all" and "any" and articles such as "the" and "an," but the fact that a modifier or an article is absent from one statement and appears in another is not intended to affect the interpretation of either statement.

### § 1.5 Ownership and Use of Drawings, Specifications, and Other Instruments of Service

§ 1.5.1 The Architect and the Architect's consultants shall be deemed the authors and owners of their respective Instruments of Service, including the Drawings and Specifications, and retain all common law, statutory, and other reserved rights in their Instruments of Service, including copyrights. The Contractor, Subcontractors, Sub-subcontractors, and suppliers shall not own or claim a copyright in the Instruments of Service. Submittal or distribution to meet official regulatory requirements or for other purposes in connection with the Project is not to be construed as publication in derogation of the Architect's or Architect's consultants' reserved rights.

§ 1.5.2 The Contractor, Subcontractors, Sub-subcontractors, and suppliers are authorized to use and reproduce the Instruments of Service provided to them, subject to any protocols established pursuant to Sections 1.7 and 1.8, solely and exclusively for execution of the Work. All copies made under this authorization shall bear the copyright notice, if any, shown on the Instruments of Service. The Contractor, Subcontractors, Sub-subcontractors, and suppliers may not use the Instruments of Service on other projects or for additions to the Project outside the scope of the Work without the specific written consent of the Owner, Architect, and the Architect's consultants.

### § 1.6 Notice

§ 1.6.1 Except as otherwise provided in Section 1.6.2, where the Contract Documents require one party to notify or give notice to the other party, such notice shall be provided in writing to the designated representative of the party to whom the notice is addressed and shall be deemed to have been duly served if delivered in person, by mail, by courier, or by electronic transmission if a method for electronic transmission is set forth in the Agreement.

§ 1.6.2 Notice of Claims as provided in Section 15.1.3 shall be provided in writing and shall be deemed to have been duly served only if delivered to the designated representative of the party to whom the notice is addressed by certified or registered mail, or by courier providing proof of delivery.

### § 1.7 Digital Data Use and Transmission

The parties shall agree upon protocols governing the transmission and use of Instruments of Service or any other information or documentation in digital form. The parties will use AIA Document E203™–2013, Building Information Modeling and Digital Data Exhibit, to establish the protocols for the development, use, transmission, and exchange of digital data.

### § 1.8 Building Information Models Use and Reliance

Any use of, or reliance on, all or a portion of a building information model without agreement to protocols governing the use of, and reliance on, the information contained in the model and without having those protocols set forth in AIA Document E203™–2013, Building Information Modeling and Digital Data Exhibit, and the requisite AIA Document

G202™–2013, Project Building Information Modeling Protocol Form, shall be at the using or relying party's sole risk and without liability to the other party and its contractors or consultants, the authors of, or contributors to, the building information model, and each of their agents and employees.

## **ARTICLE 2 OWNER**

### **§ 2.1 General**

**§ 2.1.1** The Owner is the person or entity identified as such in the Agreement and is referred to throughout the Contract Documents as if singular in number. The Owner shall designate in writing a representative who shall have express authority to bind the Owner with respect to all matters requiring the Owner's approval or authorization. Except as otherwise provided in Section 4.2.1, the Architect does not have such authority. The term "Owner" means the Owner or the Owner's authorized representative.

**§ 2.1.2** The Owner shall furnish to the Contractor, within fifteen days after receipt of a written request, information necessary and relevant for the Contractor to evaluate, give notice of, or enforce mechanic's lien rights. Such information shall include a correct statement of the record legal title to the property on which the Project is located, usually referred to as the site, and the Owner's interest therein.

### **§ 2.2 Evidence of the Owner's Financial Arrangements**

**§ 2.2.1** Prior to commencement of the Work and upon written request by the Contractor, the Owner shall furnish to the Contractor reasonable evidence that the Owner has made financial arrangements to fulfill the Owner's obligations under the Contract. The Contractor shall have no obligation to commence the Work until the Owner provides such evidence. If commencement of the Work is delayed under this Section 2.2.1, the Contract Time shall be extended appropriately.

**§ 2.2.2** Following commencement of the Work and upon written request by the Contractor, the Owner shall furnish to the Contractor reasonable evidence that the Owner has made financial arrangements to fulfill the Owner's obligations under the Contract only if (1) the Owner fails to make payments to the Contractor as the Contract Documents require; (2) the Contractor identifies in writing a reasonable concern regarding the Owner's ability to make payment when due; or (3) a change in the Work materially changes the Contract Sum. If the Owner fails to provide such evidence, as required, within fourteen days of the Contractor's request, the Contractor may immediately stop the Work and, in that event, shall notify the Owner that the Work has stopped. However, if the request is made because a change in the Work materially changes the Contract Sum under (3) above, the Contractor may immediately stop only that portion of the Work affected by the change until reasonable evidence is provided. If the Work is stopped under this Section 2.2.2, the Contract Time shall be extended appropriately and the Contract Sum shall be increased by the amount of the Contractor's reasonable costs of shutdown, delay and start-up, plus interest as provided in the Contract Documents.

**§ 2.2.3** After the Owner furnishes evidence of financial arrangements under this Section 2.2, the Owner shall not materially vary such financial arrangements without prior notice to the Contractor.

**§ 2.2.4** Where the Owner has designated information furnished under this Section 2.2 as "confidential," the Contractor shall keep the information confidential and shall not disclose it to any other person. However, the Contractor may disclose "confidential" information, after seven (7) days' notice to the Owner, where disclosure is required by law, including a subpoena or other form of compulsory legal process issued by a court or governmental entity, or by court or arbitrator(s) order. The Contractor may also disclose "confidential" information to its employees, consultants, sureties, Subcontractors and their employees, Sub-subcontractors, and others who need to know the content of such information solely and exclusively for the Project and who agree to maintain the confidentiality of such information.

### **§ 2.3 Information and Services Required of the Owner**

**§ 2.3.1** Except for permits and fees that are the responsibility of the Contractor under the Contract Documents, including those required under Section 3.7.1, the Owner shall secure and pay for necessary approvals, easements, assessments and charges required for construction, use or occupancy of permanent structures or for permanent changes in existing facilities.

**§ 2.3.2** The Owner shall retain an architect lawfully licensed to practice architecture, or an entity lawfully practicing architecture, in the jurisdiction where the Project is located. That person or entity is identified as the Architect in the Agreement and is referred to throughout the Contract Documents as if singular in number.

§ 2.3.3 If the employment of the Architect terminates, the Owner shall employ a successor to whom the Contractor has no reasonable objection and whose status under the Contract Documents shall be that of the Architect.

§ 2.3.4 The Owner shall furnish surveys describing physical characteristics, legal limitations and utility locations for the site of the Project, and a legal description of the site. The Contractor shall be entitled to rely on the accuracy of information furnished by the Owner but shall exercise proper precautions relating to the safe performance of the Work.

§ 2.3.5 The Owner shall furnish information or services required of the Owner by the Contract Documents with reasonable promptness. The Owner shall also furnish any other information or services under the Owner's control and relevant to the Contractor's performance of the Work with reasonable promptness after receiving the Contractor's written request for such information or services.

§ 2.3.6 Unless otherwise provided in the Contract Documents, the Owner shall furnish to the Contractor one copy of the Contract Documents for purposes of making reproductions pursuant to Section 1.5.2.

#### § 2.4 Owner's Right to Stop the Work

If the Contractor fails to correct Work that is not in accordance with the requirements of the Contract Documents as required by Section 12.2 or repeatedly fails to carry out Work in accordance with the Contract Documents, the Owner may issue a written order to the Contractor to stop the Work, or any portion thereof, until the cause for such order has been eliminated; however, the right of the Owner to stop the Work shall not give rise to a duty on the part of the Owner to exercise this right for the benefit of the Contractor or any other person or entity, except to the extent required by Section 6.1.3.

#### § 2.5 Owner's Right to Carry Out the Work

If the Contractor defaults or neglects to carry out the Work in accordance with the Contract Documents and fails within a ten-day period after receipt of notice from the Owner to commence and continue correction of such default or neglect with diligence and promptness, the Owner may, without prejudice to other remedies the Owner may have, correct such default or neglect. Such action by the Owner and amounts charged to the Contractor are both subject to prior approval of the Architect and the Architect may, pursuant to Section 9.5.1, withhold or nullify a Certificate for Payment in whole or in part, to the extent reasonably necessary to reimburse the Owner for the reasonable cost of correcting such deficiencies, including Owner's expenses and compensation for the Architect's additional services made necessary by such default, neglect, or failure. If current and future payments are not sufficient to cover such amounts, the Contractor shall pay the difference to the Owner. If the Contractor disagrees with the actions of the Owner or the Architect, or the amounts claimed as costs to the Owner, the Contractor may file a Claim pursuant to Article 15.

### ARTICLE 3 CONTRACTOR

#### § 3.1 General

§ 3.1.1 The Contractor is the person or entity identified as such in the Agreement and is referred to throughout the Contract Documents as if singular in number. The Contractor shall be lawfully licensed, if required in the jurisdiction where the Project is located. The Contractor shall designate in writing a representative who shall have express authority to bind the Contractor with respect to all matters under this Contract. The term "Contractor" means the Contractor or the Contractor's authorized representative.

§ 3.1.2 The Contractor shall perform the Work in accordance with the Contract Documents.

§ 3.1.3 The Contractor shall not be relieved of its obligations to perform the Work in accordance with the Contract Documents either by activities or duties of the Architect in the Architect's administration of the Contract, or by tests, inspections or approvals required or performed by persons or entities other than the Contractor.

#### § 3.2 Review of Contract Documents and Field Conditions by Contractor

§ 3.2.1 Execution of the Contract by the Contractor is a representation that the Contractor has visited the site, become generally familiar with local conditions under which the Work is to be performed, and correlated personal observations with requirements of the Contract Documents.

§ 3.2.2 Because the Contract Documents are complementary, the Contractor shall, before starting each portion of the Work, carefully study and compare the various Contract Documents relative to that portion of the Work, as well as the information furnished by the Owner pursuant to Section 2.3.4, shall take field measurements of any existing conditions related to that portion of the Work, and shall observe any conditions at the site affecting it. These obligations are for the purpose of facilitating coordination and construction by the Contractor and are not for the purpose of discovering errors, omissions, or inconsistencies in the Contract Documents; however, the Contractor shall promptly report to the Architect any errors, inconsistencies or omissions discovered by or made known to the Contractor as a request for information in such form as the Architect may require. It is recognized that the Contractor's review is made in the Contractor's capacity as a contractor and not as a licensed design professional, unless otherwise specifically provided in the Contract Documents.

§ 3.2.3 The Contractor is not required to ascertain that the Contract Documents are in accordance with applicable laws, statutes, ordinances, codes, rules and regulations, or lawful orders of public authorities, but the Contractor shall promptly report to the Architect any nonconformity discovered by or made known to the Contractor as a request for information in such form as the Architect may require.

§ 3.2.4 If the Contractor believes that additional cost or time is involved because of clarifications or instructions the Architect issues in response to the Contractor's notices or requests for information pursuant to Sections 3.2.2 or 3.2.3, the Contractor shall submit Claims as provided in Article 15. If the Contractor fails to perform the obligations of Sections 3.2.2 or 3.2.3, the Contractor shall pay such costs and damages to the Owner, subject to Section 15.1.7, as would have been avoided if the Contractor had performed such obligations. If the Contractor performs those obligations, the Contractor shall not be liable to the Owner or Architect for damages resulting from errors, inconsistencies or omissions in the Contract Documents, for differences between field measurements or conditions and the Contract Documents, or for nonconformities of the Contract Documents to applicable laws, statutes, ordinances, codes, rules and regulations, and lawful orders of public authorities.

### § 3.3 Supervision and Construction Procedures

§ 3.3.1 The Contractor shall supervise and direct the Work, using the Contractor's best skill and attention. The Contractor shall be solely responsible for, and have control over, construction means, methods, techniques, sequences, and procedures, and for coordinating all portions of the Work under the Contract. If the Contract Documents give specific instructions concerning construction means, methods, techniques, sequences, or procedures, the Contractor shall evaluate the jobsite safety thereof and shall be solely responsible for the jobsite safety of such means, methods, techniques, sequences, or procedures. If the Contractor determines that such means, methods, techniques, sequences or procedures may not be safe, the Contractor shall give timely notice to the Owner and Architect, and shall propose alternative means, methods, techniques, sequences, or procedures. The Architect shall evaluate the proposed alternative solely for conformance with the design intent for the completed construction. Unless the Architect objects to the Contractor's proposed alternative, the Contractor shall perform the Work using its alternative means, methods, techniques, sequences, or procedures.

§ 3.3.2 The Contractor shall be responsible to the Owner for acts and omissions of the Contractor's employees, Subcontractors and their agents and employees, and other persons or entities performing portions of the Work for, or on behalf of, the Contractor or any of its Subcontractors.

§ 3.3.3 The Contractor shall be responsible for inspection of portions of Work already performed to determine that such portions are in proper condition to receive subsequent Work.

### § 3.4 Labor and Materials

§ 3.4.1 Unless otherwise provided in the Contract Documents, the Contractor shall provide and pay for labor, materials, equipment, tools, construction equipment and machinery, water, heat, utilities, transportation, and other facilities and services necessary for proper execution and completion of the Work, whether temporary or permanent and whether or not incorporated or to be incorporated in the Work.

§ 3.4.2 Except in the case of minor changes in the Work approved by the Architect in accordance with Section 3.12.8 or ordered by the Architect in accordance with Section 7.4, the Contractor may make substitutions only with the consent of the Owner, after evaluation by the Architect and in accordance with a Change Order or Construction Change Directive.

§ 3.4.3 The Contractor shall enforce strict discipline and good order among the Contractor's employees and other persons carrying out the Work. The Contractor shall not permit employment of unfit persons or persons not properly skilled in tasks assigned to them.

### § 3.5 Warranty

§ 3.5.1 The Contractor warrants to the Owner and Architect that materials and equipment furnished under the Contract will be of good quality and new unless the Contract Documents require or permit otherwise. The Contractor further warrants that the Work will conform to the requirements of the Contract Documents and will be free from defects, except for those inherent in the quality of the Work the Contract Documents require or permit. Work, materials, or equipment not conforming to these requirements may be considered defective. The Contractor's warranty excludes remedy for damage or defect caused by abuse, alterations to the Work not executed by the Contractor, improper or insufficient maintenance, improper operation, or normal wear and tear and normal usage. If required by the Architect, the Contractor shall furnish satisfactory evidence as to the kind and quality of materials and equipment.

§ 3.5.2 All material, equipment, or other special warranties required by the Contract Documents shall be issued in the name of the Owner, or shall be transferable to the Owner, and shall commence in accordance with Section 9.8.4.

### § 3.6 Taxes

The Contractor shall pay sales, consumer, use and similar taxes for the Work provided by the Contractor that are legally enacted when bids are received or negotiations concluded, whether or not yet effective or merely scheduled to go into effect.

### § 3.7 Permits, Fees, Notices and Compliance with Laws

§ 3.7.1 Unless otherwise provided in the Contract Documents, the Contractor shall secure and pay for the building permit as well as for other permits, fees, licenses, and inspections by government agencies necessary for proper execution and completion of the Work that are customarily secured after execution of the Contract and legally required at the time bids are received or negotiations concluded.

§ 3.7.2 The Contractor shall comply with and give notices required by applicable laws, statutes, ordinances, codes, rules and regulations, and lawful orders of public authorities applicable to performance of the Work.

§ 3.7.3 If the Contractor performs Work knowing it to be contrary to applicable laws, statutes, ordinances, codes, rules and regulations, or lawful orders of public authorities, the Contractor shall assume appropriate responsibility for such Work and shall bear the costs attributable to correction.

### § 3.7.4 Concealed or Unknown Conditions

If the Contractor encounters conditions at the site that are (1) subsurface or otherwise concealed physical conditions that differ materially from those indicated in the Contract Documents or (2) unknown physical conditions of an unusual nature that differ materially from those ordinarily found to exist and generally recognized as inherent in construction activities of the character provided for in the Contract Documents, the Contractor shall promptly provide notice to the Owner and the Architect before conditions are disturbed and in no event later than 14 days after first observance of the conditions. The Architect will promptly investigate such conditions and, if the Architect determines that they differ materially and cause an increase or decrease in the Contractor's cost of, or time required for, performance of any part of the Work, will recommend that an equitable adjustment be made in the Contract Sum or Contract Time, or both. If the Architect determines that the conditions at the site are not materially different from those indicated in the Contract Documents and that no change in the terms of the Contract is justified, the Architect shall promptly notify the Owner and Contractor, stating the reasons. If either party disputes the Architect's determination or recommendation, that party may submit a Claim as provided in Article 15.

§ 3.7.5 If, in the course of the Work, the Contractor encounters human remains or recognizes the existence of burial markers, archaeological sites or wetlands not indicated in the Contract Documents, the Contractor shall immediately suspend any operations that would affect them and shall notify the Owner and Architect. Upon receipt of such notice, the Owner shall promptly take any action necessary to obtain governmental authorization required to resume the operations. The Contractor shall continue to suspend such operations until otherwise instructed by the Owner but shall continue with all other operations that do not affect those remains or features. Requests for adjustments in the Contract Sum and Contract Time arising from the existence of such remains or features may be made as provided in Article 15.

**§ 3.8 Allowances**

**§ 3.8.1** The Contractor shall include in the Contract Sum all allowances stated in the Contract Documents. Items covered by allowances shall be supplied for such amounts and by such persons or entities as the Owner may direct, but the Contractor shall not be required to employ persons or entities to whom the Contractor has reasonable objection.

**§ 3.8.2** Unless otherwise provided in the Contract Documents,

- .1 allowances shall cover the cost to the Contractor of materials and equipment delivered at the site and all required taxes, less applicable trade discounts;
- .2 Contractor's costs for unloading and handling at the site, labor, installation costs, overhead, profit, and other expenses contemplated for stated allowance amounts shall be included in the Contract Sum but not in the allowances; and
- .3 whenever costs are more than or less than allowances, the Contract Sum shall be adjusted accordingly by Change Order. The amount of the Change Order shall reflect (1) the difference between actual costs and the allowances under Section 3.8.2.1 and (2) changes in Contractor's costs under Section 3.8.2.2.

**§ 3.8.3** Materials and equipment under an allowance shall be selected by the Owner with reasonable promptness.

**§ 3.9 Superintendent**

**§ 3.9.1** The Contractor shall employ a competent superintendent and necessary assistants who shall be in attendance at the Project site during performance of the Work. The superintendent shall represent the Contractor, and communications given to the superintendent shall be as binding as if given to the Contractor.

**§ 3.9.2** The Contractor, as soon as practicable after award of the Contract, shall notify the Owner and Architect of the name and qualifications of a proposed superintendent. Within 14 days of receipt of the information, the Architect may notify the Contractor, stating whether the Owner or the Architect (1) has reasonable objection to the proposed superintendent or (2) requires additional time for review. Failure of the Architect to provide notice within the 14-day period shall constitute notice of no reasonable objection.

**§ 3.9.3** The Contractor shall not employ a proposed superintendent to whom the Owner or Architect has made reasonable and timely objection. The Contractor shall not change the superintendent without the Owner's consent, which shall not unreasonably be withheld or delayed.

**§ 3.10 Contractor's Construction and Submittal Schedules**

**§ 3.10.1** The Contractor, promptly after being awarded the Contract, shall submit for the Owner's and Architect's information a Contractor's construction schedule for the Work. The schedule shall contain detail appropriate for the Project, including (1) the date of commencement of the Work, interim schedule milestone dates, and the date of Substantial Completion; (2) an apportionment of the Work by construction activity; and (3) the time required for completion of each portion of the Work. The schedule shall provide for the orderly progression of the Work to completion and shall not exceed time limits current under the Contract Documents. The schedule shall be revised at appropriate intervals as required by the conditions of the Work and Project.

**§ 3.10.2** The Contractor, promptly after being awarded the Contract and thereafter as necessary to maintain a current submittal schedule, shall submit a submittal schedule for the Architect's approval. The Architect's approval shall not be unreasonably delayed or withheld. The submittal schedule shall (1) be coordinated with the Contractor's construction schedule, and (2) allow the Architect reasonable time to review submittals. If the Contractor fails to submit a submittal schedule, or fails to provide submittals in accordance with the approved submittal schedule, the Contractor shall not be entitled to any increase in Contract Sum or extension of Contract Time based on the time required for review of submittals.

**§ 3.10.3** The Contractor shall perform the Work in general accordance with the most recent schedules submitted to the Owner and Architect.

**§ 3.11 Documents and Samples at the Site**

The Contractor shall make available, at the Project site, the Contract Documents, including Change Orders, Construction Change Directives, and other Modifications, in good order and marked currently to indicate field changes and selections made during construction, and the approved Shop Drawings, Product Data, Samples, and similar required submittals. These shall be in electronic form or paper copy, available to the Architect and Owner, and

Init.

/

delivered to the Architect for submittal to the Owner upon completion of the Work as a record of the Work as constructed.

**§ 3.12 Shop Drawings, Product Data and Samples**

**§ 3.12.1** Shop Drawings are drawings, diagrams, schedules, and other data specially prepared for the Work by the Contractor or a Subcontractor, Sub-subcontractor, manufacturer, supplier, or distributor to illustrate some portion of the Work.

**§ 3.12.2** Product Data are illustrations, standard schedules, performance charts, instructions, brochures, diagrams, and other information furnished by the Contractor to illustrate materials or equipment for some portion of the Work.

**§ 3.12.3** Samples are physical examples that illustrate materials, equipment, or workmanship, and establish standards by which the Work will be judged.

**§ 3.12.4** Shop Drawings, Product Data, Samples, and similar submittals are not Contract Documents. Their purpose is to demonstrate how the Contractor proposes to conform to the information given and the design concept expressed in the Contract Documents for those portions of the Work for which the Contract Documents require submittals. Review by the Architect is subject to the limitations of Section 4.2.7. Informational submittals upon which the Architect is not expected to take responsive action may be so identified in the Contract Documents. Submittals that are not required by the Contract Documents may be returned by the Architect without action.

**§ 3.12.5** The Contractor shall review for compliance with the Contract Documents, approve, and submit to the Architect, Shop Drawings, Product Data, Samples, and similar submittals required by the Contract Documents, in accordance with the submittal schedule approved by the Architect or, in the absence of an approved submittal schedule, with reasonable promptness and in such sequence as to cause no delay in the Work or in the activities of the Owner or of Separate Contractors.

**§ 3.12.6** By submitting Shop Drawings, Product Data, Samples, and similar submittals, the Contractor represents to the Owner and Architect that the Contractor has (1) reviewed and approved them, (2) determined and verified materials, field measurements and field construction criteria related thereto, or will do so, and (3) checked and coordinated the information contained within such submittals with the requirements of the Work and of the Contract Documents.

**§ 3.12.7** The Contractor shall perform no portion of the Work for which the Contract Documents require submittal and review of Shop Drawings, Product Data, Samples, or similar submittals, until the respective submittal has been approved by the Architect.

**§ 3.12.8** The Work shall be in accordance with approved submittals except that the Contractor shall not be relieved of responsibility for deviations from the requirements of the Contract Documents by the Architect's approval of Shop Drawings, Product Data, Samples, or similar submittals, unless the Contractor has specifically notified the Architect of such deviation at the time of submittal and (1) the Architect has given written approval to the specific deviation as a minor change in the Work, or (2) a Change Order or Construction Change Directive has been issued authorizing the deviation. The Contractor shall not be relieved of responsibility for errors or omissions in Shop Drawings, Product Data, Samples, or similar submittals, by the Architect's approval thereof.

**§ 3.12.9** The Contractor shall direct specific attention, in writing or on resubmitted Shop Drawings, Product Data, Samples, or similar submittals, to revisions other than those requested by the Architect on previous submittals. In the absence of such notice, the Architect's approval of a resubmission shall not apply to such revisions.

**§ 3.12.10** The Contractor shall not be required to provide professional services that constitute the practice of architecture or engineering unless such services are specifically required by the Contract Documents for a portion of the Work or unless the Contractor needs to provide such services in order to carry out the Contractor's responsibilities for construction means, methods, techniques, sequences, and procedures. The Contractor shall not be required to provide professional services in violation of applicable law.

**§ 3.12.10.1** If professional design services or certifications by a design professional related to systems, materials, or equipment are specifically required of the Contractor by the Contract Documents, the Owner and the Architect will

Init.

/

specify all performance and design criteria that such services must satisfy. The Contractor shall be entitled to rely upon the adequacy and accuracy of the performance and design criteria provided in the Contract Documents. The Contractor shall cause such services or certifications to be provided by an appropriately licensed design professional, whose signature and seal shall appear on all drawings, calculations, specifications, certifications, Shop Drawings, and other submittals prepared by such professional. Shop Drawings, and other submittals related to the Work, designed or certified by such professional, if prepared by others, shall bear such professional's written approval when submitted to the Architect. The Owner and the Architect shall be entitled to rely upon the adequacy and accuracy of the services, certifications, and approvals performed or provided by such design professionals, provided the Owner and Architect have specified to the Contractor the performance and design criteria that such services must satisfy. Pursuant to this Section 3.12.10, the Architect will review and approve or take other appropriate action on submittals only for the limited purpose of checking for conformance with information given and the design concept expressed in the Contract Documents.

**§ 3.12.10.2** If the Contract Documents require the Contractor's design professional to certify that the Work has been performed in accordance with the design criteria, the Contractor shall furnish such certifications to the Architect at the time and in the form specified by the Architect.

**§ 3.13 Use of Site**

The Contractor shall confine operations at the site to areas permitted by applicable laws, statutes, ordinances, codes, rules and regulations, lawful orders of public authorities, and the Contract Documents and shall not unreasonably encumber the site with materials or equipment.

**§ 3.14 Cutting and Patching**

**§ 3.14.1** The Contractor shall be responsible for cutting, fitting, or patching required to complete the Work or to make its parts fit together properly. All areas requiring cutting, fitting, or patching shall be restored to the condition existing prior to the cutting, fitting, or patching, unless otherwise required by the Contract Documents.

**§ 3.14.2** The Contractor shall not damage or endanger a portion of the Work or fully or partially completed construction of the Owner or Separate Contractors by cutting, patching, or otherwise altering such construction, or by excavation. The Contractor shall not cut or otherwise alter construction by the Owner or a Separate Contractor except with written consent of the Owner and of the Separate Contractor. Consent shall not be unreasonably withheld. The Contractor shall not unreasonably withhold, from the Owner or a Separate Contractor, its consent to cutting or otherwise altering the Work.

**§ 3.15 Cleaning Up**

**§ 3.15.1** The Contractor shall keep the premises and surrounding area free from accumulation of waste materials and rubbish caused by operations under the Contract. At completion of the Work, the Contractor shall remove waste materials, rubbish, the Contractor's tools, construction equipment, machinery, and surplus materials from and about the Project.

**§ 3.15.2** If the Contractor fails to clean up as provided in the Contract Documents, the Owner may do so and the Owner shall be entitled to reimbursement from the Contractor.

**§ 3.16 Access to Work**

The Contractor shall provide the Owner and Architect with access to the Work in preparation and progress wherever located.

**§ 3.17 Royalties, Patents and Copyrights**

The Contractor shall pay all royalties and license fees. The Contractor shall defend suits or claims for infringement of copyrights and patent rights and shall hold the Owner and Architect harmless from loss on account thereof, but shall not be responsible for defense or loss when a particular design, process, or product of a particular manufacturer or manufacturers is required by the Contract Documents, or where the copyright violations are contained in Drawings, Specifications, or other documents prepared by the Owner or Architect. However, if an infringement of a copyright or patent is discovered by, or made known to, the Contractor, the Contractor shall be responsible for the loss unless the information is promptly furnished to the Architect.

**§ 3.18 Indemnification**

**§ 3.18.1** To the fullest extent permitted by law, the Contractor shall indemnify and hold harmless the Owner, Architect, Architect's consultants, and agents and employees of any of them from and against claims, damages, losses, and expenses, including but not limited to attorneys' fees, arising out of or resulting from performance of the Work, provided that such claim, damage, loss, or expense is attributable to bodily injury, sickness, disease or death, or to injury to or destruction of tangible property (other than the Work itself), but only to the extent caused by the negligent acts or omissions of the Contractor, a Subcontractor, anyone directly or indirectly employed by them, or anyone for whose acts they may be liable, regardless of whether or not such claim, damage, loss, or expense is caused in part by a party indemnified hereunder. Such obligation shall not be construed to negate, abridge, or reduce other rights or obligations of indemnity that would otherwise exist as to a party or person described in this Section 3.18.

**§ 3.18.2** In claims against any person or entity indemnified under this Section 3.18 by an employee of the Contractor, a Subcontractor, anyone directly or indirectly employed by them, or anyone for whose acts they may be liable, the indemnification obligation under Section 3.18.1 shall not be limited by a limitation on amount or type of damages, compensation, or benefits payable by or for the Contractor or a Subcontractor under workers' compensation acts, disability benefit acts, or other employee benefit acts.

**ARTICLE 4 ARCHITECT****§ 4.1 General**

**§ 4.1.1** The Architect is the person or entity retained by the Owner pursuant to Section 2.3.2 and identified as such in the Agreement.

**§ 4.1.2** Duties, responsibilities, and limitations of authority of the Architect as set forth in the Contract Documents shall not be restricted, modified, or extended without written consent of the Owner, Contractor, and Architect. Consent shall not be unreasonably withheld.

**§ 4.2 Administration of the Contract**

**§ 4.2.1** The Architect will provide administration of the Contract as described in the Contract Documents and will be an Owner's representative during construction until the date the Architect issues the final Certificate for Payment. The Architect will have authority to act on behalf of the Owner only to the extent provided in the Contract Documents.

**§ 4.2.2** The Architect will visit the site at intervals appropriate to the stage of construction, or as otherwise agreed with the Owner, to become generally familiar with the progress and quality of the portion of the Work completed, and to determine in general if the Work observed is being performed in a manner indicating that the Work, when fully completed, will be in accordance with the Contract Documents. However, the Architect will not be required to make exhaustive or continuous on-site inspections to check the quality or quantity of the Work. The Architect will not have control over, charge of, or responsibility for the construction means, methods, techniques, sequences or procedures, or for the safety precautions and programs in connection with the Work, since these are solely the Contractor's rights and responsibilities under the Contract Documents.

**§ 4.2.3** On the basis of the site visits, the Architect will keep the Owner reasonably informed about the progress and quality of the portion of the Work completed, and promptly report to the Owner (1) known deviations from the Contract Documents, (2) known deviations from the most recent construction schedule submitted by the Contractor, and (3) defects and deficiencies observed in the Work. The Architect will not be responsible for the Contractor's failure to perform the Work in accordance with the requirements of the Contract Documents. The Architect will not have control over or charge of, and will not be responsible for acts or omissions of, the Contractor, Subcontractors, or their agents or employees, or any other persons or entities performing portions of the Work.

**§ 4.2.4 Communications**

The Owner and Contractor shall include the Architect in all communications that relate to or affect the Architect's services or professional responsibilities. The Owner shall promptly notify the Architect of the substance of any direct communications between the Owner and the Contractor otherwise relating to the Project. Communications by and with the Architect's consultants shall be through the Architect. Communications by and with Subcontractors and suppliers shall be through the Contractor. Communications by and with Separate Contractors shall be through the Owner. The Contract Documents may specify other communication protocols.

Init.

/

§ 4.2.5 Based on the Architect's evaluations of the Contractor's Applications for Payment, the Architect will review and certify the amounts due the Contractor and will issue Certificates for Payment in such amounts.

§ 4.2.6 The Architect has authority to reject Work that does not conform to the Contract Documents. Whenever the Architect considers it necessary or advisable, the Architect will have authority to require inspection or testing of the Work in accordance with Sections 13.4.2 and 13.4.3, whether or not the Work is fabricated, installed or completed. However, neither this authority of the Architect nor a decision made in good faith either to exercise or not to exercise such authority shall give rise to a duty or responsibility of the Architect to the Contractor, Subcontractors, suppliers, their agents or employees, or other persons or entities performing portions of the Work.

§ 4.2.7 The Architect will review and approve, or take other appropriate action upon, the Contractor's submittals such as Shop Drawings, Product Data, and Samples, but only for the limited purpose of checking for conformance with information given and the design concept expressed in the Contract Documents. The Architect's action will be taken in accordance with the submittal schedule approved by the Architect or, in the absence of an approved submittal schedule, with reasonable promptness while allowing sufficient time in the Architect's professional judgment to permit adequate review. Review of such submittals is not conducted for the purpose of determining the accuracy and completeness of other details such as dimensions and quantities, or for substantiating instructions for installation or performance of equipment or systems, all of which remain the responsibility of the Contractor as required by the Contract Documents. The Architect's review of the Contractor's submittals shall not relieve the Contractor of the obligations under Sections 3.3, 3.5, and 3.12. The Architect's review shall not constitute approval of safety precautions or of any construction means, methods, techniques, sequences, or procedures. The Architect's approval of a specific item shall not indicate approval of an assembly of which the item is a component.

§ 4.2.8 The Architect will prepare Change Orders and Construction Change Directives, and may order minor changes in the Work as provided in Section 7.4. The Architect will investigate and make determinations and recommendations regarding concealed and unknown conditions as provided in Section 3.7.4.

§ 4.2.9 The Architect will conduct inspections to determine the date or dates of Substantial Completion and the date of final completion; issue Certificates of Substantial Completion pursuant to Section 9.8; receive and forward to the Owner, for the Owner's review and records, written warranties and related documents required by the Contract and assembled by the Contractor pursuant to Section 9.10; and issue a final Certificate for Payment pursuant to Section 9.10.

§ 4.2.10 If the Owner and Architect agree, the Architect will provide one or more Project representatives to assist in carrying out the Architect's responsibilities at the site. The Owner shall notify the Contractor of any change in the duties, responsibilities and limitations of authority of the Project representatives.

§ 4.2.11 The Architect will interpret and decide matters concerning performance under, and requirements of, the Contract Documents on written request of either the Owner or Contractor. The Architect's response to such requests will be made in writing within any time limits agreed upon or otherwise with reasonable promptness.

§ 4.2.12 Interpretations and decisions of the Architect will be consistent with the intent of, and reasonably inferable from, the Contract Documents and will be in writing or in the form of drawings. When making such interpretations and decisions, the Architect will endeavor to secure faithful performance by both Owner and Contractor, will not show partiality to either, and will not be liable for results of interpretations or decisions rendered in good faith.

§ 4.2.13 The Architect's decisions on matters relating to aesthetic effect will be final if consistent with the intent expressed in the Contract Documents.

§ 4.2.14 The Architect will review and respond to requests for information about the Contract Documents. The Architect's response to such requests will be made in writing within any time limits agreed upon or otherwise with reasonable promptness. If appropriate, the Architect will prepare and issue supplemental Drawings and Specifications in response to the requests for information.

## ARTICLE 5 SUBCONTRACTORS

### § 5.1 Definitions

§ 5.1.1 A Subcontractor is a person or entity who has a direct contract with the Contractor to perform a portion of the Work at the site. The term "Subcontractor" is referred to throughout the Contract Documents as if singular in number and means a Subcontractor or an authorized representative of the Subcontractor. The term "Subcontractor" does not include a Separate Contractor or the subcontractors of a Separate Contractor.

§ 5.1.2 A Sub-subcontractor is a person or entity who has a direct or indirect contract with a Subcontractor to perform a portion of the Work at the site. The term "Sub-subcontractor" is referred to throughout the Contract Documents as if singular in number and means a Sub-subcontractor or an authorized representative of the Sub-subcontractor.

### § 5.2 Award of Subcontracts and Other Contracts for Portions of the Work

§ 5.2.1 Unless otherwise stated in the Contract Documents, the Contractor, as soon as practicable after award of the Contract, shall notify the Owner and Architect of the persons or entities proposed for each principal portion of the Work, including those who are to furnish materials or equipment fabricated to a special design. Within 14 days of receipt of the information, the Architect may notify the Contractor whether the Owner or the Architect (1) has reasonable objection to any such proposed person or entity or (2) requires additional time for review. Failure of the Architect to provide notice within the 14-day period shall constitute notice of no reasonable objection.

§ 5.2.2 The Contractor shall not contract with a proposed person or entity to whom the Owner or Architect has made reasonable and timely objection. The Contractor shall not be required to contract with anyone to whom the Contractor has made reasonable objection.

§ 5.2.3 If the Owner or Architect has reasonable objection to a person or entity proposed by the Contractor, the Contractor shall propose another to whom the Owner or Architect has no reasonable objection. If the proposed but rejected Subcontractor was reasonably capable of performing the Work, the Contract Sum and Contract Time shall be increased or decreased by the difference, if any, occasioned by such change, and an appropriate Change Order shall be issued before commencement of the substitute Subcontractor's Work. However, no increase in the Contract Sum or Contract Time shall be allowed for such change unless the Contractor has acted promptly and responsively in submitting names as required.

§ 5.2.4 The Contractor shall not substitute a Subcontractor, person, or entity for one previously selected if the Owner or Architect makes reasonable objection to such substitution.

### § 5.3 Subcontractual Relations

By appropriate written agreement, the Contractor shall require each Subcontractor, to the extent of the Work to be performed by the Subcontractor, to be bound to the Contractor by terms of the Contract Documents, and to assume toward the Contractor all the obligations and responsibilities, including the responsibility for safety of the Subcontractor's Work that the Contractor, by these Contract Documents, assumes toward the Owner and Architect. Each subcontract agreement shall preserve and protect the rights of the Owner and Architect under the Contract Documents with respect to the Work to be performed by the Subcontractor so that subcontracting thereof will not prejudice such rights, and shall allow to the Subcontractor, unless specifically provided otherwise in the subcontract agreement, the benefit of all rights, remedies, and redress against the Contractor that the Contractor, by the Contract Documents, has against the Owner. Where appropriate, the Contractor shall require each Subcontractor to enter into similar agreements with Sub-subcontractors. The Contractor shall make available to each proposed Subcontractor, prior to the execution of the subcontract agreement, copies of the Contract Documents to which the Subcontractor will be bound, and, upon written request of the Subcontractor, identify to the Subcontractor terms and conditions of the proposed subcontract agreement that may be at variance with the Contract Documents. Subcontractors will similarly make copies of applicable portions of such documents available to their respective proposed Sub-subcontractors.

### § 5.4 Contingent Assignment of Subcontracts

§ 5.4.1 Each subcontract agreement for a portion of the Work is assigned by the Contractor to the Owner, provided that

- .1 assignment is effective only after termination of the Contract by the Owner for cause pursuant to Section 14.2 and only for those subcontract agreements that the Owner accepts by notifying the Subcontractor and Contractor; and
- .2 assignment is subject to the prior rights of the surety, if any, obligated under bond relating to the Contract.

When the Owner accepts the assignment of a subcontract agreement, the Owner assumes the Contractor's rights and obligations under the subcontract.

§ 5.4.2 Upon such assignment, if the Work has been suspended for more than 30 days, the Subcontractor's compensation shall be equitably adjusted for increases in cost resulting from the suspension.

§ 5.4.3 Upon assignment to the Owner under this Section 5.4, the Owner may further assign the subcontract to a successor contractor or other entity. If the Owner assigns the subcontract to a successor contractor or other entity, the Owner shall nevertheless remain legally responsible for all of the successor contractor's obligations under the subcontract.

## **ARTICLE 6 CONSTRUCTION BY OWNER OR BY SEPARATE CONTRACTORS**

### **§ 6.1 Owner's Right to Perform Construction and to Award Separate Contracts**

§ 6.1.1 The term "Separate Contractor(s)" shall mean other contractors retained by the Owner under separate agreements. The Owner reserves the right to perform construction or operations related to the Project with the Owner's own forces, and with Separate Contractors retained under Conditions of the Contract substantially similar to those of this Contract, including those provisions of the Conditions of the Contract related to insurance and waiver of subrogation.

§ 6.1.2 When separate contracts are awarded for different portions of the Project or other construction or operations on the site, the term "Contractor" in the Contract Documents in each case shall mean the Contractor who executes each separate Owner-Contractor Agreement.

§ 6.1.3 The Owner shall provide for coordination of the activities of the Owner's own forces and of each Separate Contractor with the Work of the Contractor, who shall cooperate with them. The Contractor shall participate with any Separate Contractors and the Owner in reviewing their construction schedules. The Contractor shall make any revisions to its construction schedule deemed necessary after a joint review and mutual agreement. The construction schedules shall then constitute the schedules to be used by the Contractor, Separate Contractors, and the Owner until subsequently revised.

§ 6.1.4 Unless otherwise provided in the Contract Documents, when the Owner performs construction or operations related to the Project with the Owner's own forces or with Separate Contractors, the Owner or its Separate Contractors shall have the same obligations and rights that the Contractor has under the Conditions of the Contract, including, without excluding others, those stated in Article 3, this Article 6, and Articles 10, 11, and 12.

### **§ 6.2 Mutual Responsibility**

§ 6.2.1 The Contractor shall afford the Owner and Separate Contractors reasonable opportunity for introduction and storage of their materials and equipment and performance of their activities, and shall connect and coordinate the Contractor's construction and operations with theirs as required by the Contract Documents.

§ 6.2.2 If part of the Contractor's Work depends for proper execution or results upon construction or operations by the Owner or a Separate Contractor, the Contractor shall, prior to proceeding with that portion of the Work, promptly notify the Architect of apparent discrepancies or defects in the construction or operations by the Owner or Separate Contractor that would render it unsuitable for proper execution and results of the Contractor's Work. Failure of the Contractor to notify the Architect of apparent discrepancies or defects prior to proceeding with the Work shall constitute an acknowledgment that the Owner's or Separate Contractor's completed or partially completed construction is fit and proper to receive the Contractor's Work. The Contractor shall not be responsible for discrepancies or defects in the construction or operations by the Owner or Separate Contractor that are not apparent.

§ 6.2.3 The Contractor shall reimburse the Owner for costs the Owner incurs that are payable to a Separate Contractor because of the Contractor's delays, improperly timed activities or defective construction. The Owner shall be responsible to the Contractor for costs the Contractor incurs because of a Separate Contractor's delays, improperly timed activities, damage to the Work or defective construction.

§ 6.2.4 The Contractor shall promptly remedy damage that the Contractor wrongfully causes to completed or partially completed construction or to property of the Owner or Separate Contractor as provided in Section 10.2.5.

Init.

/

§ 6.2.5 The Owner and each Separate Contractor shall have the same responsibilities for cutting and patching as are described for the Contractor in Section 3.14.

### § 6.3 Owner's Right to Clean Up

If a dispute arises among the Contractor, Separate Contractors, and the Owner as to the responsibility under their respective contracts for maintaining the premises and surrounding area free from waste materials and rubbish, the Owner may clean up and the Architect will allocate the cost among those responsible.

## ARTICLE 7 CHANGES IN THE WORK

### § 7.1 General

§ 7.1.1 Changes in the Work may be accomplished after execution of the Contract, and without invalidating the Contract, by Change Order, Construction Change Directive or order for a minor change in the Work, subject to the limitations stated in this Article 7 and elsewhere in the Contract Documents.

§ 7.1.2 A Change Order shall be based upon agreement among the Owner, Contractor, and Architect. A Construction Change Directive requires agreement by the Owner and Architect and may or may not be agreed to by the Contractor. An order for a minor change in the Work may be issued by the Architect alone.

§ 7.1.3 Changes in the Work shall be performed under applicable provisions of the Contract Documents. The Contractor shall proceed promptly with changes in the Work, unless otherwise provided in the Change Order, Construction Change Directive, or order for a minor change in the Work.

### § 7.2 Change Orders

§ 7.2.1 A Change Order is a written instrument prepared by the Architect and signed by the Owner, Contractor, and Architect stating their agreement upon all of the following:

- .1 The change in the Work;
- .2 The amount of the adjustment, if any, in the Contract Sum; and
- .3 The extent of the adjustment, if any, in the Contract Time.

### § 7.3 Construction Change Directives

§ 7.3.1 A Construction Change Directive is a written order prepared by the Architect and signed by the Owner and Architect, directing a change in the Work prior to agreement on adjustment, if any, in the Contract Sum or Contract Time, or both. The Owner may by Construction Change Directive, without invalidating the Contract, order changes in the Work within the general scope of the Contract consisting of additions, deletions, or other revisions, the Contract Sum and Contract Time being adjusted accordingly.

§ 7.3.2 A Construction Change Directive shall be used in the absence of total agreement on the terms of a Change Order.

§ 7.3.3 If the Construction Change Directive provides for an adjustment to the Contract Sum, the adjustment shall be based on one of the following methods:

- .1 Mutual acceptance of a lump sum properly itemized and supported by sufficient substantiating data to permit evaluation;
- .2 Unit prices stated in the Contract Documents or subsequently agreed upon;
- .3 Cost to be determined in a manner agreed upon by the parties and a mutually acceptable fixed or percentage fee; or
- .4 As provided in Section 7.3.4.

§ 7.3.4 If the Contractor does not respond promptly or disagrees with the method for adjustment in the Contract Sum, the Architect shall determine the adjustment on the basis of reasonable expenditures and savings of those performing the Work attributable to the change, including, in case of an increase in the Contract Sum, an amount for overhead and profit as set forth in the Agreement, or if no such amount is set forth in the Agreement, a reasonable amount. In such case, and also under Section 7.3.3.3, the Contractor shall keep and present, in such form as the Architect may prescribe, an itemized accounting together with appropriate supporting data. Unless otherwise provided in the Contract Documents, costs for the purposes of this Section 7.3.4 shall be limited to the following:

- .1 Costs of labor, including applicable payroll taxes, fringe benefits required by agreement or custom, workers' compensation insurance, and other employee costs approved by the Architect;
- .2 Costs of materials, supplies, and equipment, including cost of transportation, whether incorporated or consumed;
- .3 Rental costs of machinery and equipment, exclusive of hand tools, whether rented from the Contractor or others;
- .4 Costs of premiums for all bonds and insurance, permit fees, and sales, use, or similar taxes, directly related to the change; and
- .5 Costs of supervision and field office personnel directly attributable to the change.

§ 7.3.5 If the Contractor disagrees with the adjustment in the Contract Time, the Contractor may make a Claim in accordance with applicable provisions of Article 15.

§ 7.3.6 Upon receipt of a Construction Change Directive, the Contractor shall promptly proceed with the change in the Work involved and advise the Architect of the Contractor's agreement or disagreement with the method, if any, provided in the Construction Change Directive for determining the proposed adjustment in the Contract Sum or Contract Time.

§ 7.3.7 A Construction Change Directive signed by the Contractor indicates the Contractor's agreement therewith, including adjustment in Contract Sum and Contract Time or the method for determining them. Such agreement shall be effective immediately and shall be recorded as a Change Order.

§ 7.3.8 The amount of credit to be allowed by the Contractor to the Owner for a deletion or change that results in a net decrease in the Contract Sum shall be actual net cost as confirmed by the Architect. When both additions and credits covering related Work or substitutions are involved in a change, the allowance for overhead and profit shall be figured on the basis of net increase, if any, with respect to that change.

§ 7.3.9 Pending final determination of the total cost of a Construction Change Directive to the Owner, the Contractor may request payment for Work completed under the Construction Change Directive in Applications for Payment. The Architect will make an interim determination for purposes of monthly certification for payment for those costs and certify for payment the amount that the Architect determines, in the Architect's professional judgment, to be reasonably justified. The Architect's interim determination of cost shall adjust the Contract Sum on the same basis as a Change Order, subject to the right of either party to disagree and assert a Claim in accordance with Article 15.

§ 7.3.10 When the Owner and Contractor agree with a determination made by the Architect concerning the adjustments in the Contract Sum and Contract Time, or otherwise reach agreement upon the adjustments, such agreement shall be effective immediately and the Architect will prepare a Change Order. Change Orders may be issued for all or any part of a Construction Change Directive.

#### § 7.4 Minor Changes in the Work

The Architect may order minor changes in the Work that are consistent with the intent of the Contract Documents and do not involve an adjustment in the Contract Sum or an extension of the Contract Time. The Architect's order for minor changes shall be in writing. If the Contractor believes that the proposed minor change in the Work will affect the Contract Sum or Contract Time, the Contractor shall notify the Architect and shall not proceed to implement the change in the Work. If the Contractor performs the Work set forth in the Architect's order for a minor change without prior notice to the Architect that such change will affect the Contract Sum or Contract Time, the Contractor waives any adjustment to the Contract Sum or extension of the Contract Time.

### ARTICLE 8 TIME

#### § 8.1 Definitions

§ 8.1.1 Unless otherwise provided, Contract Time is the period of time, including authorized adjustments, allotted in the Contract Documents for Substantial Completion of the Work.

§ 8.1.2 The date of commencement of the Work is the date established in the Agreement.

§ 8.1.3 The date of Substantial Completion is the date certified by the Architect in accordance with Section 9.8.

§ 8.1.4 The term "day" as used in the Contract Documents shall mean calendar day unless otherwise specifically defined.

## § 8.2 Progress and Completion

§ 8.2.1 Time limits stated in the Contract Documents are of the essence of the Contract. By executing the Agreement, the Contractor confirms that the Contract Time is a reasonable period for performing the Work.

§ 8.2.2 The Contractor shall not knowingly, except by agreement or instruction of the Owner in writing, commence the Work prior to the effective date of insurance required to be furnished by the Contractor and Owner.

§ 8.2.3 The Contractor shall proceed expeditiously with adequate forces and shall achieve Substantial Completion within the Contract Time.

## § 8.3 Delays and Extensions of Time

§ 8.3.1 If the Contractor is delayed at any time in the commencement or progress of the Work by (1) an act or neglect of the Owner or Architect, of an employee of either, or of a Separate Contractor; (2) by changes ordered in the Work; (3) by labor disputes, fire, unusual delay in deliveries, unavoidable casualties, adverse weather conditions documented in accordance with Section 15.1.6.2, or other causes beyond the Contractor's control; (4) by delay authorized by the Owner pending mediation and binding dispute resolution; or (5) by other causes that the Contractor asserts, and the Architect determines, justify delay, then the Contract Time shall be extended for such reasonable time as the Architect may determine.

§ 8.3.2 Claims relating to time shall be made in accordance with applicable provisions of Article 15.

§ 8.3.3 This Section 8.3 does not preclude recovery of damages for delay by either party under other provisions of the Contract Documents.

## ARTICLE 9 PAYMENTS AND COMPLETION

### § 9.1 Contract Sum

§ 9.1.1 The Contract Sum is stated in the Agreement and, including authorized adjustments, is the total amount payable by the Owner to the Contractor for performance of the Work under the Contract Documents.

§ 9.1.2 If unit prices are stated in the Contract Documents or subsequently agreed upon, and if quantities originally contemplated are materially changed so that application of such unit prices to the actual quantities causes substantial inequity to the Owner or Contractor, the applicable unit prices shall be equitably adjusted.

### § 9.2 Schedule of Values

Where the Contract is based on a stipulated sum or Guaranteed Maximum Price, the Contractor shall submit a schedule of values to the Architect before the first Application for Payment, allocating the entire Contract Sum to the various portions of the Work. The schedule of values shall be prepared in the form, and supported by the data to substantiate its accuracy, required by the Architect. This schedule, unless objected to by the Architect, shall be used as a basis for reviewing the Contractor's Applications for Payment. Any changes to the schedule of values shall be submitted to the Architect and supported by such data to substantiate its accuracy as the Architect may require, and unless objected to by the Architect, shall be used as a basis for reviewing the Contractor's subsequent Applications for Payment.

### § 9.3 Applications for Payment

§ 9.3.1 At least ten days before the date established for each progress payment, the Contractor shall submit to the Architect an itemized Application for Payment prepared in accordance with the schedule of values, if required under Section 9.2, for completed portions of the Work. The application shall be notarized, if required, and supported by all data substantiating the Contractor's right to payment that the Owner or Architect require, such as copies of requisitions, and releases and waivers of liens from Subcontractors and suppliers, and shall reflect retainage if provided for in the Contract Documents.

§ 9.3.1.1 As provided in Section 7.3.9, such applications may include requests for payment on account of changes in the Work that have been properly authorized by Construction Change Directives, or by interim determinations of the Architect, but not yet included in Change Orders.

Init.

§ 9.3.1.2 Applications for Payment shall not include requests for payment for portions of the Work for which the Contractor does not intend to pay a Subcontractor or supplier, unless such Work has been performed by others whom the Contractor intends to pay.

§ 9.3.2 Unless otherwise provided in the Contract Documents, payments shall be made on account of materials and equipment delivered and suitably stored at the site for subsequent incorporation in the Work. If approved in advance by the Owner, payment may similarly be made for materials and equipment suitably stored off the site at a location agreed upon in writing. Payment for materials and equipment stored on or off the site shall be conditioned upon compliance by the Contractor with procedures satisfactory to the Owner to establish the Owner's title to such materials and equipment or otherwise protect the Owner's interest, and shall include the costs of applicable insurance, storage, and transportation to the site, for such materials and equipment stored off the site.

§ 9.3.3 The Contractor warrants that title to all Work covered by an Application for Payment will pass to the Owner no later than the time of payment. The Contractor further warrants that upon submittal of an Application for Payment all Work for which Certificates for Payment have been previously issued and payments received from the Owner shall, to the best of the Contractor's knowledge, information, and belief, be free and clear of liens, claims, security interests, or encumbrances, in favor of the Contractor, Subcontractors, suppliers, or other persons or entities that provided labor, materials, and equipment relating to the Work.

#### § 9.4 Certificates for Payment

§ 9.4.1 The Architect will, within seven days after receipt of the Contractor's Application for Payment, either (1) issue to the Owner a Certificate for Payment in the full amount of the Application for Payment, with a copy to the Contractor; or (2) issue to the Owner a Certificate for Payment for such amount as the Architect determines is properly due, and notify the Contractor and Owner of the Architect's reasons for withholding certification in part as provided in Section 9.5.1; or (3) withhold certification of the entire Application for Payment, and notify the Contractor and Owner of the Architect's reason for withholding certification in whole as provided in Section 9.5.1.

§ 9.4.2 The issuance of a Certificate for Payment will constitute a representation by the Architect to the Owner, based on the Architect's evaluation of the Work and the data in the Application for Payment, that, to the best of the Architect's knowledge, information, and belief, the Work has progressed to the point indicated, the quality of the Work is in accordance with the Contract Documents, and that the Contractor is entitled to payment in the amount certified. The foregoing representations are subject to an evaluation of the Work for conformance with the Contract Documents upon Substantial Completion, to results of subsequent tests and inspections, to correction of minor deviations from the Contract Documents prior to completion, and to specific qualifications expressed by the Architect. However, the issuance of a Certificate for Payment will not be a representation that the Architect has (1) made exhaustive or continuous on-site inspections to check the quality or quantity of the Work; (2) reviewed construction means, methods, techniques, sequences, or procedures; (3) reviewed copies of requisitions received from Subcontractors and suppliers and other data requested by the Owner to substantiate the Contractor's right to payment; or (4) made examination to ascertain how or for what purpose the Contractor has used money previously paid on account of the Contract Sum.

#### § 9.5 Decisions to Withhold Certification

§ 9.5.1 The Architect may withhold a Certificate for Payment in whole or in part, to the extent reasonably necessary to protect the Owner, if in the Architect's opinion the representations to the Owner required by Section 9.4.2 cannot be made. If the Architect is unable to certify payment in the amount of the Application, the Architect will notify the Contractor and Owner as provided in Section 9.4.1. If the Contractor and Architect cannot agree on a revised amount, the Architect will promptly issue a Certificate for Payment for the amount for which the Architect is able to make such representations to the Owner. The Architect may also withhold a Certificate for Payment or, because of subsequently discovered evidence, may nullify the whole or a part of a Certificate for Payment previously issued, to such extent as may be necessary in the Architect's opinion to protect the Owner from loss for which the Contractor is responsible, including loss resulting from acts and omissions described in Section 3.3.2, because of

- .1 defective Work not remedied;
- .2 third party claims filed or reasonable evidence indicating probable filing of such claims, unless security acceptable to the Owner is provided by the Contractor;
- .3 failure of the Contractor to make payments properly to Subcontractors or suppliers for labor, materials or equipment;

Init.

- .4 reasonable evidence that the Work cannot be completed for the unpaid balance of the Contract Sum;
- .5 damage to the Owner or a Separate Contractor;
- .6 reasonable evidence that the Work will not be completed within the Contract Time, and that the unpaid balance would not be adequate to cover actual or liquidated damages for the anticipated delay; or
- .7 repeated failure to carry out the Work in accordance with the Contract Documents.

§ 9.5.2 When either party disputes the Architect's decision regarding a Certificate for Payment under Section 9.5.1, in whole or in part, that party may submit a Claim in accordance with Article 15.

§ 9.5.3 When the reasons for withholding certification are removed, certification will be made for amounts previously withheld.

§ 9.5.4 If the Architect withholds certification for payment under Section 9.5.1.3, the Owner may, at its sole option, issue joint checks to the Contractor and to any Subcontractor or supplier to whom the Contractor failed to make payment for Work properly performed or material or equipment suitably delivered. If the Owner makes payments by joint check, the Owner shall notify the Architect and the Contractor shall reflect such payment on its next Application for Payment.

## § 9.6 Progress Payments

§ 9.6.1 After the Architect has issued a Certificate for Payment, the Owner shall make payment in the manner and within the time provided in the Contract Documents, and shall so notify the Architect.

§ 9.6.2 The Contractor shall pay each Subcontractor, no later than seven days after receipt of payment from the Owner, the amount to which the Subcontractor is entitled, reflecting percentages actually retained from payments to the Contractor on account of the Subcontractor's portion of the Work. The Contractor shall, by appropriate agreement with each Subcontractor, require each Subcontractor to make payments to Sub-subcontractors in a similar manner.

§ 9.6.3 The Architect will, on request, furnish to a Subcontractor, if practicable, information regarding percentages of completion or amounts applied for by the Contractor and action taken thereon by the Architect and Owner on account of portions of the Work done by such Subcontractor.

§ 9.6.4 The Owner has the right to request written evidence from the Contractor that the Contractor has properly paid Subcontractors and suppliers amounts paid by the Owner to the Contractor for subcontracted Work. If the Contractor fails to furnish such evidence within seven days, the Owner shall have the right to contact Subcontractors and suppliers to ascertain whether they have been properly paid. Neither the Owner nor Architect shall have an obligation to pay, or to see to the payment of money to, a Subcontractor or supplier, except as may otherwise be required by law.

§ 9.6.5 The Contractor's payments to suppliers shall be treated in a manner similar to that provided in Sections 9.6.2, 9.6.3 and 9.6.4.

§ 9.6.6 A Certificate for Payment, a progress payment, or partial or entire use or occupancy of the Project by the Owner shall not constitute acceptance of Work not in accordance with the Contract Documents.

§ 9.6.7 Unless the Contractor provides the Owner with a payment bond in the full penal sum of the Contract Sum, payments received by the Contractor for Work properly performed by Subcontractors or provided by suppliers shall be held by the Contractor for those Subcontractors or suppliers who performed Work or furnished materials, or both, under contract with the Contractor for which payment was made by the Owner. Nothing contained herein shall require money to be placed in a separate account and not commingled with money of the Contractor, create any fiduciary liability or tort liability on the part of the Contractor for breach of trust, or entitle any person or entity to an award of punitive damages against the Contractor for breach of the requirements of this provision.

§ 9.6.8 Provided the Owner has fulfilled its payment obligations under the Contract Documents, the Contractor shall defend and indemnify the Owner from all loss, liability, damage or expense, including reasonable attorney's fees and litigation expenses, arising out of any lien claim or other claim for payment by any Subcontractor or supplier of any tier. Upon receipt of notice of a lien claim or other claim for payment, the Owner shall notify the Contractor. If approved by the applicable court, when required, the Contractor may substitute a surety bond for the property against which the lien or other claim for payment has been asserted.

Init.

/

**§ 9.7 Failure of Payment**

If the Architect does not issue a Certificate for Payment, through no fault of the Contractor, within seven days after receipt of the Contractor's Application for Payment, or if the Owner does not pay the Contractor within seven days after the date established in the Contract Documents, the amount certified by the Architect or awarded by binding dispute resolution, then the Contractor may, upon seven additional days' notice to the Owner and Architect, stop the Work until payment of the amount owing has been received. The Contract Time shall be extended appropriately and the Contract Sum shall be increased by the amount of the Contractor's reasonable costs of shutdown, delay and start-up, plus interest as provided for in the Contract Documents.

**§ 9.8 Substantial Completion**

**§ 9.8.1** Substantial Completion is the stage in the progress of the Work when the Work or designated portion thereof is sufficiently complete in accordance with the Contract Documents so that the Owner can occupy or utilize the Work for its intended use.

**§ 9.8.2** When the Contractor considers that the Work, or a portion thereof which the Owner agrees to accept separately, is substantially complete, the Contractor shall prepare and submit to the Architect a comprehensive list of items to be completed or corrected prior to final payment. Failure to include an item on such list does not alter the responsibility of the Contractor to complete all Work in accordance with the Contract Documents.

**§ 9.8.3** Upon receipt of the Contractor's list, the Architect will make an inspection to determine whether the Work or designated portion thereof is substantially complete. If the Architect's inspection discloses any item, whether or not included on the Contractor's list, which is not sufficiently complete in accordance with the Contract Documents so that the Owner can occupy or utilize the Work or designated portion thereof for its intended use, the Contractor shall, before issuance of the Certificate of Substantial Completion, complete or correct such item upon notification by the Architect. In such case, the Contractor shall then submit a request for another inspection by the Architect to determine Substantial Completion.

**§ 9.8.4** When the Work or designated portion thereof is substantially complete, the Architect will prepare a Certificate of Substantial Completion that shall establish the date of Substantial Completion; establish responsibilities of the Owner and Contractor for security, maintenance, heat, utilities, damage to the Work and insurance; and fix the time within which the Contractor shall finish all items on the list accompanying the Certificate. Warranties required by the Contract Documents shall commence on the date of Substantial Completion of the Work or designated portion thereof unless otherwise provided in the Certificate of Substantial Completion.

**§ 9.8.5** The Certificate of Substantial Completion shall be submitted to the Owner and Contractor for their written acceptance of responsibilities assigned to them in the Certificate. Upon such acceptance, and consent of surety if any, the Owner shall make payment of retainage applying to the Work or designated portion thereof. Such payment shall be adjusted for Work that is incomplete or not in accordance with the requirements of the Contract Documents.

**§ 9.9 Partial Occupancy or Use**

**§ 9.9.1** The Owner may occupy or use any completed or partially completed portion of the Work at any stage when such portion is designated by separate agreement with the Contractor, provided such occupancy or use is consented to by the insurer and authorized by public authorities having jurisdiction over the Project. Such partial occupancy or use may commence whether or not the portion is substantially complete, provided the Owner and Contractor have accepted in writing the responsibilities assigned to each of them for payments, retainage, if any, security, maintenance, heat, utilities, damage to the Work and insurance, and have agreed in writing concerning the period for correction of the Work and commencement of warranties required by the Contract Documents. When the Contractor considers a portion substantially complete, the Contractor shall prepare and submit a list to the Architect as provided under Section 9.8.2. Consent of the Contractor to partial occupancy or use shall not be unreasonably withheld. The stage of the progress of the Work shall be determined by written agreement between the Owner and Contractor or, if no agreement is reached, by decision of the Architect.

**§ 9.9.2** Immediately prior to such partial occupancy or use, the Owner, Contractor, and Architect shall jointly inspect the area to be occupied or portion of the Work to be used in order to determine and record the condition of the Work.

§ 9.9.3 Unless otherwise agreed upon, partial occupancy or use of a portion or portions of the Work shall not constitute acceptance of Work not complying with the requirements of the Contract Documents.

#### § 9.10 Final Completion and Final Payment

§ 9.10.1 Upon receipt of the Contractor's notice that the Work is ready for final inspection and acceptance and upon receipt of a final Application for Payment, the Architect will promptly make such inspection. When the Architect finds the Work acceptable under the Contract Documents and the Contract fully performed, the Architect will promptly issue a final Certificate for Payment stating that to the best of the Architect's knowledge, information and belief, and on the basis of the Architect's on-site visits and inspections, the Work has been completed in accordance with the Contract Documents and that the entire balance found to be due the Contractor and noted in the final Certificate is due and payable. The Architect's final Certificate for Payment will constitute a further representation that conditions listed in Section 9.10.2 as precedent to the Contractor's being entitled to final payment have been fulfilled.

§ 9.10.2 Neither final payment nor any remaining retained percentage shall become due until the Contractor submits to the Architect (1) an affidavit that payrolls, bills for materials and equipment, and other indebtedness connected with the Work for which the Owner or the Owner's property might be responsible or encumbered (less amounts withheld by Owner) have been paid or otherwise satisfied, (2) a certificate evidencing that insurance required by the Contract Documents to remain in force after final payment is currently in effect, (3) a written statement that the Contractor knows of no reason that the insurance will not be renewable to cover the period required by the Contract Documents, (4) consent of surety, if any, to final payment, (5) documentation of any special warranties, such as manufacturers' warranties or specific Subcontractor warranties, and (6) if required by the Owner, other data establishing payment or satisfaction of obligations, such as receipts and releases and waivers of liens, claims, security interests, or encumbrances arising out of the Contract, to the extent and in such form as may be designated by the Owner. If a Subcontractor refuses to furnish a release or waiver required by the Owner, the Contractor may furnish a bond satisfactory to the Owner to indemnify the Owner against such lien, claim, security interest, or encumbrance. If a lien, claim, security interest, or encumbrance remains unsatisfied after payments are made, the Contractor shall refund to the Owner all money that the Owner may be compelled to pay in discharging the lien, claim, security interest, or encumbrance, including all costs and reasonable attorneys' fees.

§ 9.10.3 If, after Substantial Completion of the Work, final completion thereof is materially delayed through no fault of the Contractor or by issuance of Change Orders affecting final completion, and the Architect so confirms, the Owner shall, upon application by the Contractor and certification by the Architect, and without terminating the Contract, make payment of the balance due for that portion of the Work fully completed, corrected, and accepted. If the remaining balance for Work not fully completed or corrected is less than retainage stipulated in the Contract Documents, and if bonds have been furnished, the written consent of the surety to payment of the balance due for that portion of the Work fully completed and accepted shall be submitted by the Contractor to the Architect prior to certification of such payment. Such payment shall be made under terms and conditions governing final payment, except that it shall not constitute a waiver of Claims.

§ 9.10.4 The making of final payment shall constitute a waiver of Claims by the Owner except those arising from

- .1 liens, Claims, security interests, or encumbrances arising out of the Contract and unsettled;
- .2 failure of the Work to comply with the requirements of the Contract Documents;
- .3 terms of special warranties required by the Contract Documents; or
- .4 audits performed by the Owner, if permitted by the Contract Documents, after final payment.

§ 9.10.5 Acceptance of final payment by the Contractor, a Subcontractor, or a supplier, shall constitute a waiver of claims by that payee except those previously made in writing and identified by that payee as unsettled at the time of final Application for Payment.

### ARTICLE 10 PROTECTION OF PERSONS AND PROPERTY

#### § 10.1 Safety Precautions and Programs

The Contractor shall be responsible for initiating, maintaining, and supervising all safety precautions and programs in connection with the performance of the Contract.

#### § 10.2 Safety of Persons and Property

§ 10.2.1 The Contractor shall take reasonable precautions for safety of, and shall provide reasonable protection to prevent damage, injury, or loss to

Init.

- .1 employees on the Work and other persons who may be affected thereby;
- .2 the Work and materials and equipment to be incorporated therein, whether in storage on or off the site, under care, custody, or control of the Contractor, a Subcontractor, or a Sub-subcontractor; and
- .3 other property at the site or adjacent thereto, such as trees, shrubs, lawns, walks, pavements, roadways, structures, and utilities not designated for removal, relocation, or replacement in the course of construction.

§ 10.2.2 The Contractor shall comply with, and give notices required by applicable laws, statutes, ordinances, codes, rules and regulations, and lawful orders of public authorities, bearing on safety of persons or property or their protection from damage, injury, or loss.

§ 10.2.3 The Contractor shall implement, erect, and maintain, as required by existing conditions and performance of the Contract, reasonable safeguards for safety and protection, including posting danger signs and other warnings against hazards; promulgating safety regulations; and notifying the owners and users of adjacent sites and utilities of the safeguards.

§ 10.2.4 When use or storage of explosives or other hazardous materials or equipment, or unusual methods are necessary for execution of the Work, the Contractor shall exercise utmost care and carry on such activities under supervision of properly qualified personnel.

§ 10.2.5 The Contractor shall promptly remedy damage and loss (other than damage or loss insured under property insurance required by the Contract Documents) to property referred to in Sections 10.2.1.2 and 10.2.1.3 caused in whole or in part by the Contractor, a Subcontractor, a Sub-subcontractor, or anyone directly or indirectly employed by any of them, or by anyone for whose acts they may be liable and for which the Contractor is responsible under Sections 10.2.1.2 and 10.2.1.3. The Contractor may make a Claim for the cost to remedy the damage or loss to the extent such damage or loss is attributable to acts or omissions of the Owner or Architect or anyone directly or indirectly employed by either of them, or by anyone for whose acts either of them may be liable, and not attributable to the fault or negligence of the Contractor. The foregoing obligations of the Contractor are in addition to the Contractor's obligations under Section 3.18.

§ 10.2.6 The Contractor shall designate a responsible member of the Contractor's organization at the site whose duty shall be the prevention of accidents. This person shall be the Contractor's superintendent unless otherwise designated by the Contractor in writing to the Owner and Architect.

§ 10.2.7 The Contractor shall not permit any part of the construction or site to be loaded so as to cause damage or create an unsafe condition.

#### § 10.2.8 Injury or Damage to Person or Property

If either party suffers injury or damage to person or property because of an act or omission of the other party, or of others for whose acts such party is legally responsible, notice of the injury or damage, whether or not insured, shall be given to the other party within a reasonable time not exceeding 21 days after discovery. The notice shall provide sufficient detail to enable the other party to investigate the matter.

#### § 10.3 Hazardous Materials and Substances

§ 10.3.1 The Contractor is responsible for compliance with any requirements included in the Contract Documents regarding hazardous materials or substances. If the Contractor encounters a hazardous material or substance not addressed in the Contract Documents and if reasonable precautions will be inadequate to prevent foreseeable bodily injury or death to persons resulting from a material or substance, including but not limited to asbestos or polychlorinated biphenyl (PCB), encountered on the site by the Contractor, the Contractor shall, upon recognizing the condition, immediately stop Work in the affected area and notify the Owner and Architect of the condition.

§ 10.3.2 Upon receipt of the Contractor's notice, the Owner shall obtain the services of a licensed laboratory to verify the presence or absence of the material or substance reported by the Contractor and, in the event such material or substance is found to be present, to cause it to be rendered harmless. Unless otherwise required by the Contract Documents, the Owner shall furnish in writing to the Contractor and Architect the names and qualifications of persons or entities who are to perform tests verifying the presence or absence of the material or substance or who are to perform the task of removal or safe containment of the material or substance. The Contractor and the Architect will

promptly reply to the Owner in writing stating whether or not either has reasonable objection to the persons or entities proposed by the Owner. If either the Contractor or Architect has an objection to a person or entity proposed by the Owner, the Owner shall propose another to whom the Contractor and the Architect have no reasonable objection. When the material or substance has been rendered harmless, Work in the affected area shall resume upon written agreement of the Owner and Contractor. By Change Order, the Contract Time shall be extended appropriately and the Contract Sum shall be increased by the amount of the Contractor's reasonable additional costs of shutdown, delay, and start-up.

**§ 10.3.3** To the fullest extent permitted by law, the Owner shall indemnify and hold harmless the Contractor, Subcontractors, Architect, Architect's consultants, and agents and employees of any of them from and against claims, damages, losses, and expenses, including but not limited to attorneys' fees, arising out of or resulting from performance of the Work in the affected area if in fact the material or substance presents the risk of bodily injury or death as described in Section 10.3.1 and has not been rendered harmless, provided that such claim, damage, loss, or expense is attributable to bodily injury, sickness, disease or death, or to injury to or destruction of tangible property (other than the Work itself), except to the extent that such damage, loss, or expense is due to the fault or negligence of the party seeking indemnity.

**§ 10.3.4** The Owner shall not be responsible under this Section 10.3 for hazardous materials or substances the Contractor brings to the site unless such materials or substances are required by the Contract Documents. The Owner shall be responsible for hazardous materials or substances required by the Contract Documents, except to the extent of the Contractor's fault or negligence in the use and handling of such materials or substances.

**§ 10.3.5** The Contractor shall reimburse the Owner for the cost and expense the Owner incurs (1) for remediation of hazardous materials or substances the Contractor brings to the site and negligently handles, or (2) where the Contractor fails to perform its obligations under Section 10.3.1, except to the extent that the cost and expense are due to the Owner's fault or negligence.

**§ 10.3.6** If, without negligence on the part of the Contractor, the Contractor is held liable by a government agency for the cost of remediation of a hazardous material or substance solely by reason of performing Work as required by the Contract Documents, the Owner shall reimburse the Contractor for all cost and expense thereby incurred.

#### **§ 10.4 Emergencies**

In an emergency affecting safety of persons or property, the Contractor shall act, at the Contractor's discretion, to prevent threatened damage, injury, or loss. Additional compensation or extension of time claimed by the Contractor on account of an emergency shall be determined as provided in Article 15 and Article 7.

### **ARTICLE 11 INSURANCE AND BONDS**

#### **§ 11.1 Contractor's Insurance and Bonds**

**§ 11.1.1** The Contractor shall purchase and maintain insurance of the types and limits of liability, containing the endorsements, and subject to the terms and conditions, as described in the Agreement or elsewhere in the Contract Documents. The Contractor shall purchase and maintain the required insurance from an insurance company or insurance companies lawfully authorized to issue insurance in the jurisdiction where the Project is located. The Owner, Architect, and Architect's consultants shall be named as additional insureds under the Contractor's commercial general liability policy or as otherwise described in the Contract Documents.

**§ 11.1.2** The Contractor shall provide surety bonds of the types, for such penal sums, and subject to such terms and conditions as required by the Contract Documents. The Contractor shall purchase and maintain the required bonds from a company or companies lawfully authorized to issue surety bonds in the jurisdiction where the Project is located.

**§ 11.1.3** Upon the request of any person or entity appearing to be a potential beneficiary of bonds covering payment of obligations arising under the Contract, the Contractor shall promptly furnish a copy of the bonds or shall authorize a copy to be furnished.

**§ 11.1.4 Notice of Cancellation or Expiration of Contractor's Required Insurance.** Within three (3) business days of the date the Contractor becomes aware of an impending or actual cancellation or expiration of any insurance required by the Contract Documents, the Contractor shall provide notice to the Owner of such impending or actual cancellation or expiration. Upon receipt of notice from the Contractor, the Owner shall, unless the lapse in coverage arises from an act

or omission of the Owner, have the right to stop the Work until the lapse in coverage has been cured by the procurement of replacement coverage by the Contractor. The furnishing of notice by the Contractor shall not relieve the Contractor of any contractual obligation to provide any required coverage.

### § 11.2 Owner's Insurance

§ 11.2.1 The Owner shall purchase and maintain insurance of the types and limits of liability, containing the endorsements, and subject to the terms and conditions, as described in the Agreement or elsewhere in the Contract Documents. The Owner shall purchase and maintain the required insurance from an insurance company or insurance companies lawfully authorized to issue insurance in the jurisdiction where the Project is located.

§ 11.2.2 **Failure to Purchase Required Property Insurance.** If the Owner fails to purchase and maintain the required property insurance, with all of the coverages and in the amounts described in the Agreement or elsewhere in the Contract Documents, the Owner shall inform the Contractor in writing prior to commencement of the Work. Upon receipt of notice from the Owner, the Contractor may delay commencement of the Work and may obtain insurance that will protect the interests of the Contractor, Subcontractors, and Sub-Subcontractors in the Work. When the failure to provide coverage has been cured or resolved, the Contract Sum and Contract Time shall be equitably adjusted. In the event the Owner fails to procure coverage, the Owner waives all rights against the Contractor, Subcontractors, and Sub-subcontractors to the extent the loss to the Owner would have been covered by the insurance to have been procured by the Owner. The cost of the insurance shall be charged to the Owner by a Change Order. If the Owner does not provide written notice, and the Contractor is damaged by the failure or neglect of the Owner to purchase or maintain the required insurance, the Owner shall reimburse the Contractor for all reasonable costs and damages attributable thereto.

§ 11.2.3 **Notice of Cancellation or Expiration of Owner's Required Property Insurance.** Within three (3) business days of the date the Owner becomes aware of an impending or actual cancellation or expiration of any property insurance required by the Contract Documents, the Owner shall provide notice to the Contractor of such impending or actual cancellation or expiration. Unless the lapse in coverage arises from an act or omission of the Contractor: (1) the Contractor, upon receipt of notice from the Owner, shall have the right to stop the Work until the lapse in coverage has been cured by the procurement of replacement coverage by either the Owner or the Contractor; (2) the Contract Time and Contract Sum shall be equitably adjusted; and (3) the Owner waives all rights against the Contractor, Subcontractors, and Sub-subcontractors to the extent any loss to the Owner would have been covered by the insurance had it not expired or been cancelled. If the Contractor purchases replacement coverage, the cost of the insurance shall be charged to the Owner by an appropriate Change Order. The furnishing of notice by the Owner shall not relieve the Owner of any contractual obligation to provide required insurance.

### § 11.3 Waivers of Subrogation

§ 11.3.1 The Owner and Contractor waive all rights against (1) each other and any of their subcontractors, sub-subcontractors, agents, and employees, each of the other; (2) the Architect and Architect's consultants; and (3) Separate Contractors, if any, and any of their subcontractors, sub-subcontractors, agents, and employees, for damages caused by fire, or other causes of loss, to the extent those losses are covered by property insurance required by the Agreement or other property insurance applicable to the Project, except such rights as they have to proceeds of such insurance. The Owner or Contractor, as appropriate, shall require similar written waivers in favor of the individuals and entities identified above from the Architect, Architect's consultants, Separate Contractors, subcontractors, and sub-subcontractors. The policies of insurance purchased and maintained by each person or entity agreeing to waive claims pursuant to this section 11.3.1 shall not prohibit this waiver of subrogation. This waiver of subrogation shall be effective as to a person or entity (1) even though that person or entity would otherwise have a duty of indemnification, contractual or otherwise, (2) even though that person or entity did not pay the insurance premium directly or indirectly, or (3) whether or not the person or entity had an insurable interest in the damaged property.

§ 11.3.2 If during the Project construction period the Owner insures properties, real or personal or both, at or adjacent to the site by property insurance under policies separate from those insuring the Project, or if after final payment property insurance is to be provided on the completed Project through a policy or policies other than those insuring the Project during the construction period, to the extent permissible by such policies, the Owner waives all rights in accordance with the terms of Section 11.3.1 for damages caused by fire or other causes of loss covered by this separate property insurance.

### § 11.4 Loss of Use, Business Interruption, and Delay in Completion Insurance

Init.

/

The Owner, at the Owner's option, may purchase and maintain insurance that will protect the Owner against loss of use of the Owner's property, or the inability to conduct normal operations, due to fire or other causes of loss. The Owner waives all rights of action against the Contractor and Architect for loss of use of the Owner's property, due to fire or other hazards however caused.

### **§11.5 Adjustment and Settlement of Insured Loss**

**§ 11.5.1** A loss insured under the property insurance required by the Agreement shall be adjusted by the Owner as fiduciary and made payable to the Owner as fiduciary for the insureds, as their interests may appear, subject to requirements of any applicable mortgagee clause and of Section 11.5.2. The Owner shall pay the Architect and Contractor their just shares of insurance proceeds received by the Owner, and by appropriate agreements the Architect and Contractor shall make payments to their consultants and Subcontractors in similar manner.

**§ 11.5.2** Prior to settlement of an insured loss, the Owner shall notify the Contractor of the terms of the proposed settlement as well as the proposed allocation of the insurance proceeds. The Contractor shall have 14 days from receipt of notice to object to the proposed settlement or allocation of the proceeds. If the Contractor does not object, the Owner shall settle the loss and the Contractor shall be bound by the settlement and allocation. Upon receipt, the Owner shall deposit the insurance proceeds in a separate account and make the appropriate distributions. Thereafter, if no other agreement is made or the Owner does not terminate the Contract for convenience, the Owner and Contractor shall execute a Change Order for reconstruction of the damaged or destroyed Work in the amount allocated for that purpose. If the Contractor timely objects to either the terms of the proposed settlement or the allocation of the proceeds, the Owner may proceed to settle the insured loss, and any dispute between the Owner and Contractor arising out of the settlement or allocation of the proceeds shall be resolved pursuant to Article 15. Pending resolution of any dispute, the Owner may issue a Construction Change Directive for the reconstruction of the damaged or destroyed Work.

## **ARTICLE 12 UNCOVERING AND CORRECTION OF WORK**

### **§ 12.1 Uncovering of Work**

**§ 12.1.1** If a portion of the Work is covered contrary to the Architect's request or to requirements specifically expressed in the Contract Documents, it must, if requested in writing by the Architect, be uncovered for the Architect's examination and be replaced at the Contractor's expense without change in the Contract Time.

**§ 12.1.2** If a portion of the Work has been covered that the Architect has not specifically requested to examine prior to its being covered, the Architect may request to see such Work and it shall be uncovered by the Contractor. If such Work is in accordance with the Contract Documents, the Contractor shall be entitled to an equitable adjustment to the Contract Sum and Contract Time as may be appropriate. If such Work is not in accordance with the Contract Documents, the costs of uncovering the Work, and the cost of correction, shall be at the Contractor's expense.

### **§ 12.2 Correction of Work**

#### **§ 12.2.1 Before Substantial Completion**

The Contractor shall promptly correct Work rejected by the Architect or failing to conform to the requirements of the Contract Documents, discovered before Substantial Completion and whether or not fabricated, installed or completed. Costs of correcting such rejected Work, including additional testing and inspections, the cost of uncovering and replacement, and compensation for the Architect's services and expenses made necessary thereby, shall be at the Contractor's expense.

#### **§ 12.2.2 After Substantial Completion**

**§ 12.2.2.1** In addition to the Contractor's obligations under Section 3.5, if, within one year after the date of Substantial Completion of the Work or designated portion thereof or after the date for commencement of warranties established under Section 9.9.1, or by terms of any applicable special warranty required by the Contract Documents, any of the Work is found to be not in accordance with the requirements of the Contract Documents, the Contractor shall correct it promptly after receipt of notice from the Owner to do so, unless the Owner has previously given the Contractor a written acceptance of such condition. The Owner shall give such notice promptly after discovery of the condition. During the one-year period for correction of Work, if the Owner fails to notify the Contractor and give the Contractor an opportunity to make the correction, the Owner waives the rights to require correction by the Contractor and to make a claim for breach of warranty. If the Contractor fails to correct nonconforming Work within a reasonable time during that period after receipt of notice from the Owner or Architect, the Owner may correct it in accordance with Section 2.5.

Init.

§ 12.2.2.2 The one-year period for correction of Work shall be extended with respect to portions of Work first performed after Substantial Completion by the period of time between Substantial Completion and the actual completion of that portion of the Work.

§ 12.2.2.3 The one-year period for correction of Work shall not be extended by corrective Work performed by the Contractor pursuant to this Section 12.2.

§ 12.2.3 The Contractor shall remove from the site portions of the Work that are not in accordance with the requirements of the Contract Documents and are neither corrected by the Contractor nor accepted by the Owner.

§ 12.2.4 The Contractor shall bear the cost of correcting destroyed or damaged construction of the Owner or Separate Contractors, whether completed or partially completed, caused by the Contractor's correction or removal of Work that is not in accordance with the requirements of the Contract Documents.

§ 12.2.5 Nothing contained in this Section 12.2 shall be construed to establish a period of limitation with respect to other obligations the Contractor has under the Contract Documents. Establishment of the one-year period for correction of Work as described in Section 12.2.2 relates only to the specific obligation of the Contractor to correct the Work, and has no relationship to the time within which the obligation to comply with the Contract Documents may be sought to be enforced, nor to the time within which proceedings may be commenced to establish the Contractor's liability with respect to the Contractor's obligations other than specifically to correct the Work.

### § 12.3 Acceptance of Nonconforming Work

If the Owner prefers to accept Work that is not in accordance with the requirements of the Contract Documents, the Owner may do so instead of requiring its removal and correction, in which case the Contract Sum will be reduced as appropriate and equitable. Such adjustment shall be effected whether or not final payment has been made.

## ARTICLE 13 MISCELLANEOUS PROVISIONS

### § 13.1 Governing Law

The Contract shall be governed by the law of the place where the Project is located, excluding that jurisdiction's choice of law rules. If the parties have selected arbitration as the method of binding dispute resolution, the Federal Arbitration Act shall govern Section 15.4.

### § 13.2 Successors and Assigns

§ 13.2.1 The Owner and Contractor respectively bind themselves, their partners, successors, assigns, and legal representatives to covenants, agreements, and obligations contained in the Contract Documents. Except as provided in Section 13.2.2, neither party to the Contract shall assign the Contract as a whole without written consent of the other. If either party attempts to make an assignment without such consent, that party shall nevertheless remain legally responsible for all obligations under the Contract.

§ 13.2.2 The Owner may, without consent of the Contractor, assign the Contract to a lender providing construction financing for the Project, if the lender assumes the Owner's rights and obligations under the Contract Documents. The Contractor shall execute all consents reasonably required to facilitate the assignment.

### § 13.3 Rights and Remedies

§ 13.3.1 Duties and obligations imposed by the Contract Documents and rights and remedies available thereunder shall be in addition to and not a limitation of duties, obligations, rights, and remedies otherwise imposed or available by law.

§ 13.3.2 No action or failure to act by the Owner, Architect, or Contractor shall constitute a waiver of a right or duty afforded them under the Contract, nor shall such action or failure to act constitute approval of or acquiescence in a breach thereunder, except as may be specifically agreed upon in writing.

### § 13.4 Tests and Inspections

§ 13.4.1 Tests, inspections, and approvals of portions of the Work shall be made as required by the Contract Documents and by applicable laws, statutes, ordinances, codes, rules, and regulations or lawful orders of public authorities. Unless otherwise provided, the Contractor shall make arrangements for such tests, inspections, and

Init.

/

approvals with an independent testing laboratory or entity acceptable to the Owner, or with the appropriate public authority, and shall bear all related costs of tests, inspections, and approvals. The Contractor shall give the Architect timely notice of when and where tests and inspections are to be made so that the Architect may be present for such procedures. The Owner shall bear costs of tests, inspections, or approvals that do not become requirements until after bids are received or negotiations concluded. The Owner shall directly arrange and pay for tests, inspections, or approvals where building codes or applicable laws or regulations so require.

§ 13.4.2 If the Architect, Owner, or public authorities having jurisdiction determine that portions of the Work require additional testing, inspection, or approval not included under Section 13.4.1, the Architect will, upon written authorization from the Owner, instruct the Contractor to make arrangements for such additional testing, inspection, or approval, by an entity acceptable to the Owner, and the Contractor shall give timely notice to the Architect of when and where tests and inspections are to be made so that the Architect may be present for such procedures. Such costs, except as provided in Section 13.4.3, shall be at the Owner's expense.

§ 13.4.3 If procedures for testing, inspection, or approval under Sections 13.4.1 and 13.4.2 reveal failure of the portions of the Work to comply with requirements established by the Contract Documents, all costs made necessary by such failure, including those of repeated procedures and compensation for the Architect's services and expenses, shall be at the Contractor's expense.

§ 13.4.4 Required certificates of testing, inspection, or approval shall, unless otherwise required by the Contract Documents, be secured by the Contractor and promptly delivered to the Architect.

§ 13.4.5 If the Architect is to observe tests, inspections, or approvals required by the Contract Documents, the Architect will do so promptly and, where practicable, at the normal place of testing.

§ 13.4.6 Tests or inspections conducted pursuant to the Contract Documents shall be made promptly to avoid unreasonable delay in the Work.

### § 13.5 Interest

Payments due and unpaid under the Contract Documents shall bear interest from the date payment is due at the rate the parties agree upon in writing or, in the absence thereof, at the legal rate prevailing from time to time at the place where the Project is located.

## ARTICLE 14 TERMINATION OR SUSPENSION OF THE CONTRACT

### § 14.1 Termination by the Contractor

§ 14.1.1 The Contractor may terminate the Contract if the Work is stopped for a period of 30 consecutive days through no act or fault of the Contractor, a Subcontractor, a Sub-subcontractor, their agents or employees, or any other persons or entities performing portions of the Work, for any of the following reasons:

- .1 Issuance of an order of a court or other public authority having jurisdiction that requires all Work to be stopped;
- .2 An act of government, such as a declaration of national emergency, that requires all Work to be stopped;
- .3 Because the Architect has not issued a Certificate for Payment and has not notified the Contractor of the reason for withholding certification as provided in Section 9.4.1, or because the Owner has not made payment on a Certificate for Payment within the time stated in the Contract Documents; or
- .4 The Owner has failed to furnish to the Contractor reasonable evidence as required by Section 2.2.

§ 14.1.2 The Contractor may terminate the Contract if, through no act or fault of the Contractor, a Subcontractor, a Sub-subcontractor, their agents or employees, or any other persons or entities performing portions of the Work, repeated suspensions, delays, or interruptions of the entire Work by the Owner as described in Section 14.3, constitute in the aggregate more than 100 percent of the total number of days scheduled for completion, or 120 days in any 365-day period, whichever is less.

§ 14.1.3 If one of the reasons described in Section 14.1.1 or 14.1.2 exists, the Contractor may, upon seven days' notice to the Owner and Architect, terminate the Contract and recover from the Owner payment for Work executed, as well as reasonable overhead and profit on Work not executed, and costs incurred by reason of such termination.

§ 14.1.4 If the Work is stopped for a period of 60 consecutive days through no act or fault of the Contractor, a Subcontractor, a Sub-subcontractor, or their agents or employees or any other persons or entities performing portions of the Work because the Owner has repeatedly failed to fulfill the Owner's obligations under the Contract Documents with respect to matters important to the progress of the Work, the Contractor may, upon seven additional days' notice to the Owner and the Architect, terminate the Contract and recover from the Owner as provided in Section 14.1.3.

## § 14.2 Termination by the Owner for Cause

§ 14.2.1 The Owner may terminate the Contract if the Contractor

- .1 repeatedly refuses or fails to supply enough properly skilled workers or proper materials;
- .2 fails to make payment to Subcontractors or suppliers in accordance with the respective agreements between the Contractor and the Subcontractors or suppliers;
- .3 repeatedly disregards applicable laws, statutes, ordinances, codes, rules and regulations, or lawful orders of a public authority; or
- .4 otherwise is guilty of substantial breach of a provision of the Contract Documents.

§ 14.2.2 When any of the reasons described in Section 14.2.1 exist, and upon certification by the Architect that sufficient cause exists to justify such action, the Owner may, without prejudice to any other rights or remedies of the Owner and after giving the Contractor and the Contractor's surety, if any, seven days' notice, terminate employment of the Contractor and may, subject to any prior rights of the surety:

- .1 Exclude the Contractor from the site and take possession of all materials, equipment, tools, and construction equipment and machinery thereon owned by the Contractor;
- .2 Accept assignment of subcontracts pursuant to Section 5.4; and
- .3 Finish the Work by whatever reasonable method the Owner may deem expedient. Upon written request of the Contractor, the Owner shall furnish to the Contractor a detailed accounting of the costs incurred by the Owner in finishing the Work.

§ 14.2.3 When the Owner terminates the Contract for one of the reasons stated in Section 14.2.1, the Contractor shall not be entitled to receive further payment until the Work is finished.

§ 14.2.4 If the unpaid balance of the Contract Sum exceeds costs of finishing the Work, including compensation for the Architect's services and expenses made necessary thereby, and other damages incurred by the Owner and not expressly waived, such excess shall be paid to the Contractor. If such costs and damages exceed the unpaid balance, the Contractor shall pay the difference to the Owner. The amount to be paid to the Contractor or Owner, as the case may be, shall be certified by the Initial Decision Maker, upon application, and this obligation for payment shall survive termination of the Contract.

## § 14.3 Suspension by the Owner for Convenience

§ 14.3.1 The Owner may, without cause, order the Contractor in writing to suspend, delay or interrupt the Work, in whole or in part for such period of time as the Owner may determine.

§ 14.3.2 The Contract Sum and Contract Time shall be adjusted for increases in the cost and time caused by suspension, delay, or interruption under Section 14.3.1. Adjustment of the Contract Sum shall include profit. No adjustment shall be made to the extent

- .1 that performance is, was, or would have been, so suspended, delayed, or interrupted, by another cause for which the Contractor is responsible; or
- .2 that an equitable adjustment is made or denied under another provision of the Contract.

## § 14.4 Termination by the Owner for Convenience

§ 14.4.1 The Owner may, at any time, terminate the Contract for the Owner's convenience and without cause.

§ 14.4.2 Upon receipt of notice from the Owner of such termination for the Owner's convenience, the Contractor shall

- .1 cease operations as directed by the Owner in the notice;
- .2 take actions necessary, or that the Owner may direct, for the protection and preservation of the Work; and
- .3 except for Work directed to be performed prior to the effective date of termination stated in the notice, terminate all existing subcontracts and purchase orders and enter into no further subcontracts and purchase orders.

§ 14.4.3 In case of such termination for the Owner's convenience, the Owner shall pay the Contractor for Work properly executed; costs incurred by reason of the termination, including costs attributable to termination of Subcontracts; and the termination fee, if any, set forth in the Agreement.

## ARTICLE 15 CLAIMS AND DISPUTES

### § 15.1 Claims

#### § 15.1.1 Definition

A Claim is a demand or assertion by one of the parties seeking, as a matter of right, payment of money, a change in the Contract Time, or other relief with respect to the terms of the Contract. The term "Claim" also includes other disputes and matters in question between the Owner and Contractor arising out of or relating to the Contract. The responsibility to substantiate Claims shall rest with the party making the Claim. This Section 15.1.1 does not require the Owner to file a Claim in order to impose liquidated damages in accordance with the Contract Documents.

#### § 15.1.2 Time Limits on Claims

The Owner and Contractor shall commence all Claims and causes of action against the other and arising out of or related to the Contract, whether in contract, tort, breach of warranty or otherwise, in accordance with the requirements of the binding dispute resolution method selected in the Agreement and within the period specified by applicable law, but in any case not more than 10 years after the date of Substantial Completion of the Work. The Owner and Contractor waive all Claims and causes of action not commenced in accordance with this Section 15.1.2.

#### § 15.1.3 Notice of Claims

§ 15.1.3.1 Claims by either the Owner or Contractor, where the condition giving rise to the Claim is first discovered prior to expiration of the period for correction of the Work set forth in Section 12.2.2, shall be initiated by notice to the other party and to the Initial Decision Maker with a copy sent to the Architect, if the Architect is not serving as the Initial Decision Maker. Claims by either party under this Section 15.1.3.1 shall be initiated within 21 days after occurrence of the event giving rise to such Claim or within 21 days after the claimant first recognizes the condition giving rise to the Claim, whichever is later.

§ 15.1.3.2 Claims by either the Owner or Contractor, where the condition giving rise to the Claim is first discovered after expiration of the period for correction of the Work set forth in Section 12.2.2, shall be initiated by notice to the other party. In such event, no decision by the Initial Decision Maker is required.

#### § 15.1.4 Continuing Contract Performance

§ 15.1.4.1 Pending final resolution of a Claim, except as otherwise agreed in writing or as provided in Section 9.7 and Article 14, the Contractor shall proceed diligently with performance of the Contract and the Owner shall continue to make payments in accordance with the Contract Documents.

§ 15.1.4.2 The Contract Sum and Contract Time shall be adjusted in accordance with the Initial Decision Maker's decision, subject to the right of either party to proceed in accordance with this Article 15. The Architect will issue Certificates for Payment in accordance with the decision of the Initial Decision Maker.

#### § 15.1.5 Claims for Additional Cost

If the Contractor wishes to make a Claim for an increase in the Contract Sum, notice as provided in Section 15.1.3 shall be given before proceeding to execute the portion of the Work that is the subject of the Claim. Prior notice is not required for Claims relating to an emergency endangering life or property arising under Section 10.4.

#### § 15.1.6 Claims for Additional Time

§ 15.1.6.1 If the Contractor wishes to make a Claim for an increase in the Contract Time, notice as provided in Section 15.1.3 shall be given. The Contractor's Claim shall include an estimate of cost and of probable effect of delay on progress of the Work. In the case of a continuing delay, only one Claim is necessary.

§ 15.1.6.2 If adverse weather conditions are the basis for a Claim for additional time, such Claim shall be documented by data substantiating that weather conditions were abnormal for the period of time, could not have been reasonably anticipated, and had an adverse effect on the scheduled construction.

**§ 15.1.7 Waiver of Claims for Consequential Damages**

The Contractor and Owner waive Claims against each other for consequential damages arising out of or relating to this Contract. This mutual waiver includes

- .1 damages incurred by the Owner for rental expenses, for losses of use, income, profit, financing, business and reputation, and for loss of management or employee productivity or of the services of such persons; and
- .2 damages incurred by the Contractor for principal office expenses including the compensation of personnel stationed there, for losses of financing, business and reputation, and for loss of profit, except anticipated profit arising directly from the Work.

This mutual waiver is applicable, without limitation, to all consequential damages due to either party's termination in accordance with Article 14. Nothing contained in this Section 15.1.7 shall be deemed to preclude assessment of liquidated damages, when applicable, in accordance with the requirements of the Contract Documents.

**§ 15.2 Initial Decision**

**§ 15.2.1** Claims, excluding those where the condition giving rise to the Claim is first discovered after expiration of the period for correction of the Work set forth in Section 12.2.2 or arising under Sections 10.3, 10.4, and 11.5, shall be referred to the Initial Decision Maker for initial decision. The Architect will serve as the Initial Decision Maker, unless otherwise indicated in the Agreement. Except for those Claims excluded by this Section 15.2.1, an initial decision shall be required as a condition precedent to mediation of any Claim. If an initial decision has not been rendered within 30 days after the Claim has been referred to the Initial Decision Maker, the party asserting the Claim may demand mediation and binding dispute resolution without a decision having been rendered. Unless the Initial Decision Maker and all affected parties agree, the Initial Decision Maker will not decide disputes between the Contractor and persons or entities other than the Owner.

**§ 15.2.2** The Initial Decision Maker will review Claims and within ten days of the receipt of a Claim take one or more of the following actions: (1) request additional supporting data from the claimant or a response with supporting data from the other party, (2) reject the Claim in whole or in part, (3) approve the Claim, (4) suggest a compromise, or (5) advise the parties that the Initial Decision Maker is unable to resolve the Claim if the Initial Decision Maker lacks sufficient information to evaluate the merits of the Claim or if the Initial Decision Maker concludes that, in the Initial Decision Maker's sole discretion, it would be inappropriate for the Initial Decision Maker to resolve the Claim.

**§ 15.2.3** In evaluating Claims, the Initial Decision Maker may, but shall not be obligated to, consult with or seek information from either party or from persons with special knowledge or expertise who may assist the Initial Decision Maker in rendering a decision. The Initial Decision Maker may request the Owner to authorize retention of such persons at the Owner's expense.

**§ 15.2.4** If the Initial Decision Maker requests a party to provide a response to a Claim or to furnish additional supporting data, such party shall respond, within ten days after receipt of the request, and shall either (1) provide a response on the requested supporting data, (2) advise the Initial Decision Maker when the response or supporting data will be furnished, or (3) advise the Initial Decision Maker that no supporting data will be furnished. Upon receipt of the response or supporting data, if any, the Initial Decision Maker will either reject or approve the Claim in whole or in part.

**§ 15.2.5** The Initial Decision Maker will render an initial decision approving or rejecting the Claim, or indicating that the Initial Decision Maker is unable to resolve the Claim. This initial decision shall (1) be in writing; (2) state the reasons therefor; and (3) notify the parties and the Architect, if the Architect is not serving as the Initial Decision Maker, of any change in the Contract Sum or Contract Time or both. The initial decision shall be final and binding on the parties but subject to mediation and, if the parties fail to resolve their dispute through mediation, to binding dispute resolution.

**§ 15.2.6** Either party may file for mediation of an initial decision at any time, subject to the terms of Section 15.2.6.1.

**§ 15.2.6.1** Either party may, within 30 days from the date of receipt of an initial decision, demand in writing that the other party file for mediation. If such a demand is made and the party receiving the demand fails to file for mediation within 30 days after receipt thereof, then both parties waive their rights to mediate or pursue binding dispute resolution proceedings with respect to the initial decision.

Init.

/

§ 15.2.7 In the event of a Claim against the Contractor, the Owner may, but is not obligated to, notify the surety, if any, of the nature and amount of the Claim. If the Claim relates to a possibility of a Contractor's default, the Owner may, but is not obligated to, notify the surety and request the surety's assistance in resolving the controversy.

§ 15.2.8 If a Claim relates to or is the subject of a mechanic's lien, the party asserting such Claim may proceed in accordance with applicable law to comply with the lien notice or filing deadlines.

### § 15.3 Mediation

§ 15.3.1 Claims, disputes, or other matters in controversy arising out of or related to the Contract, except those waived as provided for in Sections 9.10.4, 9.10.5, and 15.1.7, shall be subject to mediation as a condition precedent to binding dispute resolution.

§ 15.3.2 The parties shall endeavor to resolve their Claims by mediation which, unless the parties mutually agree otherwise, shall be administered by the American Arbitration Association in accordance with its Construction Industry Mediation Procedures in effect on the date of the Agreement. A request for mediation shall be made in writing, delivered to the other party to the Contract, and filed with the person or entity administering the mediation. The request may be made concurrently with the filing of binding dispute resolution proceedings but, in such event, mediation shall proceed in advance of binding dispute resolution proceedings, which shall be stayed pending mediation for a period of 60 days from the date of filing, unless stayed for a longer period by agreement of the parties or court order. If an arbitration is stayed pursuant to this Section 15.3.2, the parties may nonetheless proceed to the selection of the arbitrator(s) and agree upon a schedule for later proceedings.

§ 15.3.3 Either party may, within 30 days from the date that mediation has been concluded without resolution of the dispute or 60 days after mediation has been demanded without resolution of the dispute, demand in writing that the other party file for binding dispute resolution. If such a demand is made and the party receiving the demand fails to file for binding dispute resolution within 60 days after receipt thereof, then both parties waive their rights to binding dispute resolution proceedings with respect to the initial decision.

§ 15.3.4 The parties shall share the mediator's fee and any filing fees equally. The mediation shall be held in the place where the Project is located, unless another location is mutually agreed upon. Agreements reached in mediation shall be enforceable as settlement agreements in any court having jurisdiction thereof.

### § 15.4 Arbitration

§ 15.4.1 If the parties have selected arbitration as the method for binding dispute resolution in the Agreement, any Claim subject to, but not resolved by, mediation shall be subject to arbitration which, unless the parties mutually agree otherwise, shall be administered by the American Arbitration Association in accordance with its Construction Industry Arbitration Rules in effect on the date of the Agreement. The Arbitration shall be conducted in the place where the Project is located, unless another location is mutually agreed upon. A demand for arbitration shall be made in writing, delivered to the other party to the Contract, and filed with the person or entity administering the arbitration. The party filing a notice of demand for arbitration must assert in the demand all Claims then known to that party on which arbitration is permitted to be demanded.

§ 15.4.1.1 A demand for arbitration shall be made no earlier than concurrently with the filing of a request for mediation, but in no event shall it be made after the date when the institution of legal or equitable proceedings based on the Claim would be barred by the applicable statute of limitations. For statute of limitations purposes, receipt of a written demand for arbitration by the person or entity administering the arbitration shall constitute the institution of legal or equitable proceedings based on the Claim.

§ 15.4.2 The award rendered by the arbitrator or arbitrators shall be final, and judgment may be entered upon it in accordance with applicable law in any court having jurisdiction thereof.


§ 15.4.3 The foregoing agreement to arbitrate and other agreements to arbitrate with an additional person or entity duly consented to by parties to the Agreement, shall be specifically enforceable under applicable law in any court having jurisdiction thereof.

§ 15.4.4 Consolidation or Joinder

§ 15.4.4.1 Subject to the rules of the American Arbitration Association or other applicable arbitration rules, either party may consolidate an arbitration conducted under this Agreement with any other arbitration to which it is a party provided that (1) the arbitration agreement governing the other arbitration permits consolidation, (2) the arbitrations to be consolidated substantially involve common questions of law or fact, and (3) the arbitrations employ materially similar procedural rules and methods for selecting arbitrator(s).

§ 15.4.4.2 Subject to the rules of the American Arbitration Association or other applicable arbitration rules, either party may include by joinder persons or entities substantially involved in a common question of law or fact whose presence is required if complete relief is to be accorded in arbitration, provided that the party sought to be joined consents in writing to such joinder. Consent to arbitration involving an additional person or entity shall not constitute consent to arbitration of any claim, dispute or other matter in question not described in the written consent.

§ 15.4.4.3 The Owner and Contractor grant to any person or entity made a party to an arbitration conducted under this Section 15.4, whether by joinder or consolidation, the same rights of joinder and consolidation as those of the Owner and Contractor under this Agreement.

  
\_\_\_\_\_  
OWNER (Signature)  
  
Jeremy Rieder President and Chief Executive  
Officer  
\_\_\_\_\_  
(Printed name and title)

DocuSigned by:  
  
7/17/2022 | 10:15 CDT  
A58F71725F5842D...  
\_\_\_\_\_  
CONTRACTOR (Signature)  
  
Camp Roofing, Ltd.  
By: Camp GP, LLC, its general partner  
By: Jeff Blevins President  
\_\_\_\_\_  
(Printed name and title)

# Additions and Deletions Report for AIA® Document A201® – 2017

This Additions and Deletions Report, as defined on page 1 of the associated document, reproduces below all text the author has added to the standard form AIA document in order to complete it, as well as any text the author may have added to or deleted from the original AIA text. Added text is shown underlined. Deleted text is indicated with a horizontal line through the original AIA text.

Note: This Additions and Deletions Report is provided for information purposes only and is not incorporated into or constitute any part of the associated AIA document. This Additions and Deletions Report and its associated document were generated simultaneously by AIA software at 11:07:40 CT on 06/27/2022.

## PAGE 1

The Saulet  
1420 Annunciation Street  
New Orleans, LA 70130

...

*(Name, legal status and address)*

Saulet Apts LLC  
780 Third Ave 25<sup>th</sup> Fl  
New York, N.Y. 10017

...

N/A  
PAGE 40

OWNER (Signature)

Jeremy Rieder President and Chief Executive Officer  
*(Printed name and title)*

DocuSigned by:

Jeff Blevins

A58F71725F5842D...

7/17/2022 | 10:15 CDT

CONTRACTOR (Signature)

Camp Roofing, Ltd.  
By: Camp GP, LLC, its general partner  
By: Jeff Blevins President  
*(Printed name and title)*

## **Certification of Document's Authenticity**

**AIA® Document D401™ – 2003**

I, \_\_\_\_\_, hereby certify, to the best of my knowledge, information and belief, that I created the attached final document simultaneously with its associated Additions and Deletions Report and this certification at 11:07:40 CT on 06/27/2022 under Order No. 2114259654 from AIA Contract Documents software and that in preparing the attached final document I made no changes to the original text of AIA® Document A201™ – 2017, General Conditions of the Contract for Construction, as published by the AIA in its software, other than those additions and deletions shown in the associated Additions and Deletions Report.

DocuSigned by:

*Diane Suits*

78EB496EC0D04FC...

(Signed)

Executive Administrative Assistant

(Title)

7/17/2022 | 12:37 CDT

(Dated)