# HISTORIC DISTRICT LANDMARKS COMMISSION

## **CERTIFICATE OF REVIEW**

#### **WORK REVIEWED:**

- 1. Repair/replace existing slate roof with slate, to match existing, as shown on drawing attached, approved 9/6/2022.
- 2. Repair/replace plywood decking, sheathing, and felt paper, as needed.


  Overall pitch and height of roof to match existing.
- 3. Remove damaged gutters and downspouts and install half round or k-style gutters and downspouts, as needed.
- 4. All repair/replace shall match existing in material, exposure, dimension, size, operation, configuration, and type.
- 5. Contact the HDLC at (504)658-7051 for final inspection.



### NOT VALID UNLESS POSTED ON SITE

By posting this notice, the owner of the property certifies that they understand all work described above, and acknowledge that they are legally responsible for ensuring that all work performed has been approved prior to execution and is completed in accordance with reviws obtained. ••• For questions regarding this review or to schedule a final inspection call the number below •••

THIS FORM MUST REMAIN POSTED UNTIL WORK IS CERTIFIED AS COMPLIANT BY HDLC STAFF 1300 Perdido Street, Room 7W03 • New Orleans • LA • 70112 • (504) 658-7040 • www.nola.gov/hdlc SOLO EL TRABAJO DESCRITO ANTERIORMENTE PUEDE REALIZARSE LEGALMENTE EN ESTE EDIFICIO



#### Reroof

- 1. Remove existing slate roofing matierials, maintaing all vee caps, vents and accessories
- 2. Remove rear metal exhaust cap
- 3. Repair any decking
- 4. Apply Peel & Stick moisture barrier
- 5. Apply new Spanish Slate roof tile system
- 6. New Gutters, Downspouts and flashing to matchexisting.
- 7. New Lighting protection system to match existing



2541 Bayou Road New Orleans, LA 70117

**REVISIONS** 

**A-1**