

## FIRE

**Structure Type:** 1-Enclosed building  
**Number of Residential Living Units:** 1  
**Number of Buildings Involved:**  
**Area of Fire Origin:** 24-Cooking area, kitchen  
**Heat Source:** 00-Heat source: other  
**Item First Ignited:** 99-Multiple items first ignited  
**Type of Material First Ignited:**  
**Fire Spread Confined to Object of Origin:** Y-Yes  
**Cause of Ignition:** 2-Unintentional  
**Factors Contributing to Ignition:** 53-Equipment unattended  
**Human Factors Contributing to Ignition:** 3-Unattended or unsupervised person  
**Fire Suppression Factors:** None  
**Equipment Involved in Ignition:** 124-Stove, heating  
**Power Source of Equipment:** Undetermined  
**Portability of Equipment:** 2-Stationary  
**Mobile Property Involved in Ignition:** 1-Not involved in ignition, but burned  
**Type of Mobile Property:**  
**Make of Mobile Property:**  
**Model of Mobile Property:**  
**Year of Mobile Property:**  
**License Plate Number of Mobile Property:**  
**VIN Number of Mobile Property:**

## STRUCTURE

**Building Status:** 2-In normal use  
**Story of Fire Origin:** 1  
**Main Floor Length In Feet (est):**  
**Main Floor Width In Feet (est):**  
**Main Floor Total Square Feet (est):** 2000  
**Fire Spread:** 1-Confined to object of origin  
**Item Contributing Most to Flame Spread:**  
**Type of Material Contributing Most to Flame Spread:**  
**Presence of Detectors:** 1-Present  
**Detector Type:** 1-Smoke  
**Detector Power Supply:** 4-Hardwire with battery backup  
**Detector Operation:** 2-Detector operated  
**Presence of AES:** N-None Present

## ARSON

**Arson Case Status:**  
**Arson Availability of Material First Ignited:**  
**Arson Suspected Factor:**  
**Arson Group Involvement:**  
**Arson Extent of Fire Involvement:**  
**Arson Property Ownership:**

NEW ORLEANS FIRE DEPARTMENT

Unit	Dispatch	Arrival	Clear	Apparatus Action	Type
					<b>Personnel Rank Or Grade</b>
PAUL STEELE					CAPT
JEFFREY SMITH					FF
TIMOTHY THOMPSON					FF
Joshua Cooper					FF

## APPARATUS

Unit	Dispatch	Arrival	Clear	Apparatus Action	Type
C503	14:32:17	14:42:16	15:49:52	81-Incident command	92-Chief officer car
<b>Personnel Rank Or Grade</b>					
JON BIALAS				DC	
C505	14:32:17	15:02:58	15:13:00	81S-Safety	92-Chief officer car
<b>Personnel Rank Or Grade</b>					
VICTOR LACAVA				DC	
E21	14:32:17	14:37:27	15:47:38	11-Extinguishment by fire service personnel	11-Engine
<b>Personnel Rank Or Grade</b>					
MICHAEL FLOT				CAPT	
ARNOLD COLLINS JR				OPER	
TONY WATKINS				PFF	
E27	14:32:17	14:38:34	15:47:18	11-Extinguishment by fire service personnel	11-Engine
<b>Personnel Rank Or Grade</b>					
JERRY MAGEE				CAPT	
DWAYNE JACKSON				OPER	
William Briggs				FF	
E35	14:32:17	14:58:03	15:18:00	10-Fire control or extinguishment, other	11-Engine
<b>Personnel Rank Or Grade</b>					
JOHN GALLAGHER III				CAPT	
RICHARD JENSEN JR				OPER	
JASON AFFOLDER				FF	
L11	14:32:17	14:39:39	15:47:54	12-Salvage & overhaul	12-Truck or aerial
<b>Personnel Rank Or Grade</b>					
MICHAEL SCIORTINO JR				CAPT	
LEONCE ARNOLD				OPER	
GAVIN MURRAY				FF	
PSE1	15:07:36	15:30:41	15:50:12		00-Other apparatus/resource
R07	14:32:17	14:39:20	15:17:50	20-Search & rescue, other	71-Rescue unit
<b>Personnel Rank Or Grade</b>					
BRANDON KRSAK				Captain	
JERMAINE PERRY				OPER	
GRANT RODRIGUEZ				FF	
BIANCA JONES				FF	
S07	14:32:17	14:39:08	15:47:24	20-Search & rescue, other	11-Engine
<b>Personnel Rank Or Grade</b>					



## NOFD FIRE REPORT

## BASIC

**Incident Number:** 01003-22  
**PSAP Date Time:** 01/06/2022 14:31:29  
**Alarm Date Time:** 01/06/2022 14:32:02  
**Arrival Date Time:** 01/06/2022 14:37:27  
**Controlled Date Time:** 01/06/2022 14:50:08  
**Last Unit Cleared Date Time:** 01/06/2022 15:50:12  
**Incident Status:** Reviewed  
**Platoon:** A  
**Incident Type:** 111-Building fire  
**Aid Given or Received:** None  
**Type of Alarm:**  
**Primary Action Taken:** 11-Extinguishment by fire service personnel  
**Casualties:**  
**Suppression Apparatus:** 8  
**Suppression Personnel:** 22  
**Property Losses(est):** \$60000  
**Content Losses(est):** \$25000  
**Property Pre-Incident Value(est):** \$260000  
**Contents Pre-Incident Value(est):** \$  
**Detector Effectiveness:** 1-Detector alerted occupants, occupants responded  
**Property Use:** 419-1 family dwelling  
**Incident Location Type:** 1-Street address  
**Address:** 2455 AUBRY  
**Incident Zone Number:** 3002-03

## SITUATION

**Initial CAD Code:** DWELL  
**Incident Delay:** NONE

## PERSON INVOLVED

Person or Entity Involved Type	Person/Owner Involved Person Involved First Name	Person Involved Last Name
5101001-Owner	Hanah	Joffary

## AUTHORITY

Officer in Charge - Signature: FLOT, MICHAEL  
 Member Making Report - Signature: FLOT, MICHAEL

## NARRATIVES

Unit	Apparatus Narrative
C503	Arrived on scene, assumed fixed command, and provided dispatch with an initial size up. Ensured resources were adequate and monitored incident progress. Once incident was deemed under control, I transferred command to Company Officer on first arriving unit.
C505	C505 was safety at this incident.
E21	First On scene. 1 story house with heavy smoke showing. We forced entry to rear of house where we found heavy fire. in Kitchen hallway area. heavy fire and water damage to immediate area. Upon investigation we found laundry baskets on counter near and on stove top, which cause the clothes hamper to ignite. classed as unintentional, Fire was extinguished and electrical service was disconnected
E27	Engine 27 arrived on scene and began interior fire fighting with the other crews on scene. Engine 27 checked the attic, assisted with pet search and overhaul at this residential fire. The captain of Engine 27 assisted the captain of Engine 21 with taking pictures of the incident also.
E35	Made initial entry into the CHARLIE side of the building and found a small fire in the kitchen area. E35 FF extinguished the fire with E21 pre connect. We then searched for extension on fire and performed a primary search for reported missing cats.
L11	L11 entered on the Charlie side and made way into the attic to check for extension. We then set up the fan and ventilated. We continued to pull ceiling and walls for overhaul.
PSE1	
R07	Rescue 7 assisted in search for two missing cats and for extension of fire.
S07	Made entry from C side, began search for missing cats. Located one cat in room on A/B corner. E35 FF located a cat carrier and I assisted him in getting the cat into it. Continued searching for other cat with no luck.  Opened windows to vent.  Assisted in picking up hose.

## Attachments