


HISTORIC DISTRICT LANDMARKS COMMISSION CERTIFICATE OF APPROPRIATENESS

WORK APPROVED:

1. Repair/replace existing soffit at overhang with 5/4" wood, beaded tongue and groove boards or beaded plywood. Beads must run perpendicular to front wall of building. If beaded plywood is used, joints must be concealed at edge of bead.
2. remove damaged gutters and install half-round or k-style gutters and downspouts, as needed. Downspouts are not to be located on the front elevation of the building.
3. Repair/replace existing wood trim, including fascia, with wood, to match existing. Hardie trim is not allowed. Reinstall existing crown moulding to match existing.
4. Selective replacement of soffit framing only. No other framing work under this permit.
5. All repair/replace shall match existing in material, exposure, dimension, size, operation, configuration, and type, unless otherwise specified.
6. For final, please contact the HDLC inspector, Daniel Syal, at Daniel.Syal@nola.gov or call the mainline (504) 658-7051.



NOT VALID UNLESS POSTED ON SITE

By posting this notice, the owner of the property certifies that they understand all work described above, and acknowledge that they are legally responsible for ensuring that all work performed has been approved prior to execution and is completed in accordance with approvals obtained. *** For questions regarding this approval or to schedule a final inspection call the number below ***

THIS FORM MUST REMAIN POSTED UNTIL WORK IS CERTIFIED AS COMPLIANT BY HDLC STAFF

1300 Perdido Street, Room 7W03 • New Orleans • LA • 70112 • (504) 658-7040 • www.nola.gov/hdlc

SOLO EL TRABAJO DESCRITO ANTERIORMENTE PUEDE REALIZARSE LEGALMENTE EN ESTE EDIFICIO

2720 Annunciation St,
2720 Annunciation St,
22-28826-HDLC

10/28/2022

OWNER: CHARLES J MEAGHER

APPLICANT: TOPHER RIETH

ISSUED BY: WENDY CARGILE