

LaToya Cantrell
MAYOR

CITY OF NEW ORLEANS

Bryan D. Block
EXECUTIVE DIRECTOR

6320 St Robertson St. Demolition Request Inspection Results

- An exterior visual inspection of the structure took place on July 1, 2022.

Building description:

- The vacant raised residential building appeared to be in very poor condition.
- The structure had a pier and beam foundation, wood framed superstructure with wood weatherboards.
- The roof is covered with architectural asphalt shingles that appeared to be in fair condition.

Exterior:

- The building is essentially a pile of debris under a very mature tree which has fallen directly on top.
- There is a small front porch on the front left side which may be salvageable.
- There is a small entry room which looks to be an infilled porch at the front right side which may be salvageable.
- The remaining walls and roof have been destroyed and/or displaced by the tree and would need to be removed prior to rebuilding on the site.

Interior:

- The interior of the building was not accessible.

Overall, the building has been essentially destroyed by the fallen tree. The façade and front porch and entry may be salvageable. The rest of the building should be removed from the site and is only being held in place by the fallen tree.

HDLC Inspector Alex Nassar

