



John Bel Edwards
GOVERNOR

Office of State Fire Marshal

8181 Independence Blvd. Baton Rouge, LA 70806
(225) 925-4911 (800) 256-5452 Fax (225) 925-4241



Daniel H. Wallis
FIRE MARSHAL

Inspection Report

Report # PR-22-035305-1, Project # AR-22-016095

Deficient/Cautionary Codes cited.

Location Information		
Inspection Type	Plan Review Inspection	Inspection Date 10/6/2022 11:07:11 AM
Structure ID	No. of Buildings 1	Facility Code
Capacity	Year Built	Construction Type III-A / III(211)
Building/Trade Name GRAVIER STREET MASSAGE, LLC		Address 940 GRAVIER STREET, NEW ORLEANS, LA 70112

Owner Information			
Owner Type	Name	Contact Phone	Contact Email
Owner	HUI LIU	(725) 666-3668	GRAVIERMESAGE@GMAIL.COM
Address 940 GRAVIER STREET, NEW ORLEANS, LA 70112			

Tenant Information			
Name	Suite Number	Floor Number	Square Footage
HUI LIU		1,	2138

Occupancy Details	
Occupancy Type	Details
Business	

Deficient and Cautionary Items		
Description	Code Status	Correction Date
ADA/ABA 606.3 Height. Lavatories and sinks shall be installed with the front of the higher of the rim or counter surface 34 inches (865 mm) maximum above the finish floor or ground. AT TIME OF INSPECTION SINKS WERE ABOVE 34 INCHES MAX	DEFICIENT	11/7/2022
LRS 40:1731-(Effective 10/01/11) Provide access for persons with disabilities in accordance with the ADA-ABA Accessibility Guidelines, July 23, 2004 (also known as the 2010 Standards). This does not include a review for compliance with the Federal Americans with Disabilities (Civil Rights) Act of 1990. Compliance with state regulations and requirements does not guarantee compliance with federal law. NOTE: As per ADA-ABA 2004, Section F103, Office of State Fire Marshal appeal determinations are not valid for facilities that are designed, constructed, altered, or operated with federal funds, or leased by a federal agency. The authority having jurisdiction over such appeals is the administrator of the General Services Administration (GSA). Particular deficiencies and paragraph references are noted as follows:	DEFICIENT	11/7/2022
NFPA 101:32.2.9.1. SHALL PROVIDE EMERGENCY LIGHTING. AT TIME OF INSPECTION NO EMERGENCY LIGHTING WAS FOUND.	DEFICIENT	11/7/2022

Comments
FINAL INSPECTION CONDUCTED ON THIS DATE FOR NEW MASSAGE FACILITY AT THIS LOCATION LSC: BUSINESS IBC: BUSINESS GROUP B
PLEASE SEE LISTED DEFICIENCIES NOTED AT TIME OF INSPECTION
ACCEPTABLE FOR 30 DAY TEMPORARY OCCUPANCY

Inspector Information



John Bel Edwards
GOVERNOR

Office of State Fire Marshal

8181 Independence Blvd. Baton Rouge, LA 70806
(225) 925-4911 (800) 256-5452 Fax (225) 925-4241





Daniel H. Wallis
FIRE MARSHAL

Inspection Report

Report # PR-22-035305-1, Project # AR-22-016095

Deficient/Cautionary Codes cited.

Name: Brandon Richardson	Badge Number: 612	Inspector Signature: 
--------------------------	-------------------	--

Person to whom requirements were explained		
Name: MICHAEL LAROSE	Title: VP	Signature: 

For questions regarding the contents of this report, please call: (504) 568 8506

R. S. 40: 1621 Whoever fails to comply with any order issued by the Fire Marshal or his authorized representative under any provision of Part III, Chapter 7, Title 40 of the Louisiana Revised Statutes of 1950, R.S. 40:1569 excepted, shall be fined not more than five hundred dollars or imprisoned, for more than six months or both. Each day's violation of an order constitutes a separate offense and may be punished as such at the discretion of court.