



EXISTING CONDITIONS AND DEMOLITION ROOF PLAN






















MAIN ROOF CLASSROOM BUILDING (AT MECHANICAL EQUIPMENT PLATFORM)











20



5 CONDUIT PENETRATION AT EAST GYMNASIUM PARTITION



10 MECHANICAL EQUIPMENT ROOM DOOR HEAD










MAIN ROOF CLASSROOM BUILDING (EAST END LOOKING NORTH)

SHEET Sheet	DATE	R E V I S I O N S		11111111111111111111111111111111111111	ARCHDIOCESE OF NEW ORLEANS	
7 7 7	AUGUST 12, 2022				ST. STEPHENS GOOD SHEPHERD SCHOOL	DUPLANIEK & MERIC, ARCHIECIS, L.L.C.
	HCD, MJT				ROOF REPLACEMENT AND REPAIRS	4764 PARIS AVENUE NEW ORLEANS. LA 70122
	CHECKED BY		2203-K-1	DATENOT TO A COLL	1025 NAPOLEON AVENUE	
0 F 6	НСD				NEW ORLEANS, LOUISIANA 70115	




SHIELD.






n $\overline{\bigcirc}$ č 1 නේ Ż \square SS SS ŏ S S S S PHER S 000 EME S EP 2 \$ O 4 🔊 X ----- $\boldsymbol{\omega}$ 0 N N Δ


SCALE: 3/32"=1'-0"



TYPICAL ROOF DETAILS - GYMNASIUM AND ADDITION







SCALE AS NOTED

